SR Technics

CAPABILITIES AND FIXED PRICES CATALOGUE



ENGINE PARTS REPAIR SERVICES

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

valid until December 31, 2026

© SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AB	27	FLANGE FACE PLASMA SPRAY REPAIR		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AC	28	FLANGE SNAP DIAMETER PLASMA SPRAY REPAIR		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AF	31	INNER DIAMETER SPACER BORE PLASMA SPRAY REPAIR		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AI	34	PLASME COATE 6TH STAGE LPT AIRSEAL FRONT SNAP MATING DIAMETER		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AN	41	MARK HIGHPOINT AXIAL RUNOUT		565	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package E	4	REPAIR NO. 4 BEARING RETAINING PLATE HOLES		1000	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package R	17	SHAFT BALANCE (BY WAX APPLICATION) REPAIR		1465	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package S	18	SURFACE DAMAGE BLEND REPAIR		1510	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package S	32	SHOTPEEN AFTER BLEND REPAIR		1510	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package U	20	REAR COUPLING PILOT DIAMETER PLASMA SPRAY REPAIR		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package V	21	FRONT COUPLING PILOT DIAMETER PLASMA SPRAY REPAIR		4725	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package W	22	NICKEL PLATE REPAIR NO. 4 BEARING RETAINING PLATE MATING DIAMETER		4470	SR Technics Switzerland
1275	51A377-01; 52A519-01		34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package X	23	MACHINE REPAIR FRONT SPACER SURFACE		990	SR Technics Switzerland
1275	51A377-01; 52A519-01	EASA;FAA;CAAC;ANAC;CAA UK	34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		1800	SR Technics Switzerland
1275	51A377-01; 52A519-01	EASA;FAA;CAAC;ANAC;CAA UK	34	35	72-53-80	LPT - FRONT COMPRESSOR DRIVE TURBINE (LPT) SHAFT - 100"	Package AA	26	NICKEL PLATE REPAIR FOR 7TH STAGE LPT AIRSEAL SHOULDER		4470	SR Technics Switzerland
1288	57T251; HAD20836	EASA;FAA;CAAC;ANAC										
1288	57T251; HAD20836	EASA;FAA;CAAC;ANAC	5	21	75-41-01	PROBE-THERMOCOUPLE	Package B		CHECK AND REPAIR		1070	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AD	ESEE.000961-ED1	CRACK WELDING IN EGT PROBE BOSS OEM WELD JOINT		2570	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AE	47	NICKEL PLATE REPAIR THE FIT BETWEEN CARBON SEAL HOUSING AND REWORK OF CARBON SEAL HOUSING NOT IN		12485	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AF	52	FRONT OUTER FLANGE INNER LUG WEAR PLASMA COAT REPAIR		3615	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AG	55	FRONT OUTER FLANGE WELD JOINT WELD REPAIR		3145	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AH	33	PLASMA SPRAY REPAIR THE FRONT OUTER FLANGE FACE		3925	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AI	41	EGT PROBE BUSHING REPAIR		1040	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AJ	38	NO.4 JOURNAL BUSHING REPAIR		7305	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AK	45	WELD REPAIR STRUT TO OUTER CASE FILLET RADIUS CRACKS		3290	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AL	49	NO. 4 BEARING HOUSING REAR SURFACE CRACKS WELD REPAIR		1820	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AM	51	STRUT OUTER STAND-UP TRAILING EDGE CRACK WELD REPAIR		5420	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AN	43	STRUT TRAILING EDGE CRACK WELD REPAIR		6770	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package B	INSP	PREREQUISIT FOR REPAIR ACC.MPG CRACKED		845	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package C	2	HELICAL COIL INSERT REPAIR THERMOCOUPLE THREADED BOSS HOLES		3770	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package E	4	HELICAL COIL INSERT REPAIR NO. 3 BEARING OIL VENT TUBE BOSS HOLE		2855	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package F	5	HELICAL COIL INSERT NO. 4 BEARING COVER RETAINING HOLES		4075	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package G	6	REPLACE GROUND HANDLING BUSHINGS		6345	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package H	7	REPLACE MOUNT BUSHINGS		6345	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package I	8	REPLACE REAR FLANGE NUT PLATES		4075	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package M	12	REPLACE NO. 4 BEARING CARBON SEAL HOUSING		11165	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package N	13	PLASMA SPRAY REPAIR THE REAR OUTER FLANGE SNAP DIAMETER		5705	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package O	14	NICKEL PLATE REPAIR THE OUTER FRONT FLANGE SNAP DIAMETER		6315	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package P	15	OUTER FRONT FLANGE BOLTHOLE RADIAL EXTENSION		1490	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package R	17	WELD REPAIR INNER CASE AND SUPPORT STRUCTURE CRACKS		5415	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package U	20	CHROMIUM PLATE NO. 4 BEARING SHOULDER		4765	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package V	21	CHROMIUM PLATE NO. 4 BEARING JOURNAL		6775	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package W	39	STRUT INNER STAND-UP TRAILING EDGE CRACK REPAIR		5630	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package X	23	SURFACE DAMAGE BLEND REPAIR		4555	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P468-02		47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package Z	25	DRILL PURGE AND DRAIN HOLES IN EXHAUST CASE OUTER WALL AT STRUT LOCATION		2355	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P	EASA;FAA;CAAC;ANAC	47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		3820	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P	EASA;FAA;CAAC;ANAC	47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AA	60	STRUT SURFACE DAMAGE AND CRACK WELD REPAIR		2115	SR Technics Switzerland
1313	50P460-01; 50P468-01; 50P	EASA;FAA;CAAC;ANAC;CAA UK	47	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 100"	Package AC	28	STRUT DENT AND CRACK REPAIR		7975	SR Technics Switzerland
1456	50L664		20	28	72-52-17	STAGE 1 HPT AIR SEALING RING	Package SB01	FAA-2011-25-09	AD FAA-2011-25-09		545	SR Technics Switzerland
1456	50L664		20	28	72-52-17	STAGE 1 HPT AIR SEALING RING	Package SB02	FAA-2012-18-03	AD FAA-2012-18-03		545	SR Technics Switzerland
1456	50L664	EASA;FAA;CAAC;ANAC;CAA UK	20	28	72-52-17	STAGE 1 HPT AIR SEALING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		915	SR Technics Switzerland
1711	70R650	EASA;FAA;CAAC;ANAC	13	28	72-61-25	PW4 COUPLING, GEARBOX (STARTER DRIVE)	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1045	SR Technics Switzerland
1715	583887		29	28	72-34-34	INTERMEDIATE CASE - NO. 3 TOWER SHAFT BEARING RETAINING NUT	Package B	1	SURFACE DAMAGE BLEND REPAIR		1625	SR Technics Switzerland
1715	583887		29	28	72-34-34	INTERMEDIATE CASE - NO. 3 TOWER SHAFT BEARING RETAINING NUT	Package C	2	SILVER PLATE REPAIR		1470	SR Technics Switzerland
1715	583887	EASA;FAA;CAAC;ANAC	29	28	72-34-34	INTERMEDIATE CASE - NO. 3 TOWER SHAFT BEARING RETAINING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364-01		28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package F	5	AXIAL AND RADIAL CRACK WELD REPAIR		3080	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364-01		28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package G	6	COMBUSTION CHAMBER GUIDE TAB WELD REPAIR		3325	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364-01		28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package H	7	GUIDE SEAL REPLACEMENT REPAIR		3415	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364	EASA;FAA;CAAC;ANAC	28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package A	CLN/INSP	CLEANING AND INSPECTION		460	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364	EASA;FAA;CAAC;ANAC	28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package B	1	HARDFACE COAT REPAIR		2225	SR Technics Switzerland
1753	50K035; 50K192-01; 50K364	EASA;FAA;CAAC;ANAC	28	28	72-51-09	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (LOWE	Package E	4	REPLACE COMBUSTION CHAMBER GUIDE (END TAB) SEAL		1545	SR Technics Switzerland
1777	51U615	EASA;FAA;CAAC;ANAC	17	21	71-21-16	FWD ENGINE MOUNT - BOLT - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		300	SR Technics Switzerland
1778	51U616	EASA;FAA;CAAC;ANAC;CAA UK	18	21	71-22-16	REAR ENGINE MOUNT - BOLT - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION	PN55T532 FOR SHOP VISIT ONLY	300	SR Technics Switzerland
1880	50N587		30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package B	1	SURFACE DAMAGE BLEND REPAIR		1225	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1880	50N587		30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package C	2	MATING FACE PLASMA SPRAY REPAIR		4440	SR Technics Switzerland
1880	50N587		30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package D	3	MATING DIAMETER PLASMA SPRAY REPAIR		4190	SR Technics Switzerland
1880	50N587		30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package E	4	SHOTPEEN REPAIR		920	SR Technics Switzerland
1880	50N587		30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package SB00	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1070	SR Technics Switzerland
1880	50N587	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-53-61	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT DISK - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		1380	SR Technics Switzerland
2086	50G010; 50G011; 50G013; 5	EASA;FAA;CAAC;ANAC										
2086	50G010; 50G011; 50G013; 5	EASA;FAA;CAAC;ANAC	23	28	72-62-04	ANGLE GEARBOX - ANGLE GEARBOX BEARINGS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	690	SR Technics Switzerland
2120	70R147; 70R591; 70R986; 7	EASA;FAA;CAAC;ANAC										
2120	70R147; 70R591; 70R986; 7	EASA;FAA;CAAC;ANAC	29	28	72-61-68	MAIN GEARBOX - GEARBOX LUG	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	440	SR Technics Switzerland
2120	70R147; 70R591; 70R986; 7	EASA;FAA;CAAC;ANAC	29	28	72-61-68	MAIN GEARBOX - GEARBOX LUG	Package B	1	CHROMIUM PLATE LUG		1270	SR Technics Switzerland
2120	70R147; 70R591; 70R986; 7	EASA;FAA;CAAC;ANAC	29	28	72-61-68	MAIN GEARBOX - GEARBOX LUG	Package D	1	NICKEL & CHROMIUM PLATE LUG		1575	SR Technics Switzerland
2120	70R147; 70R591; 70R986; 7	EASA;FAA;CAAC;ANAC	29	28	72-61-68	MAIN GEARBOX - GEARBOX LUG	Package SB00	PW4ENG 72-538	MGB-INCORPORATE OF LUG WITH THREADED HOLE		370	SR Technics Switzerland
2140	23504-001; 23744-000; HAD	EASA;FAA;CAAC;ANAC	6	21	73-21-57	EEC THERMOCOUPLE PROBE (Tt3)	Package C	TEST	PRE TEST		375	SR Technics Switzerland
2140	23504-001; 23744-000; HAD	EASA;FAA;CAAC;ANAC	6	21	73-21-57	EEC THERMOCOUPLE PROBE (Tt3)	Package C	TEST	TEST		375	SR Technics Switzerland
2140	23504-001; 23744-000; HAD	EASA;FAA;CAAC;ANAC	6	21	73-21-57	EEC THERMOCOUPLE PROBE (Tt3)	Package D		OVERHAUL		920	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package A	INSP-04	CLEANING AND INSPECTION		1890	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AD	29	CORROSION SURFACE DAMAGE REPAIR (FLANGE)		1235	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AD	29	CORROSION SURFACE DAMAGE REPAIR (STEEL SHAFT)		1235	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AF	31	INNER DIAMETER SPACER BORE PLASMA SPRAY REPAIR		4580	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AH	33	REAR COUPLING PILOT DIAMETER PLASMA COAT REPAIR		4215	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AI	36	PLASMA COAT REPAIR THE 6TH STAGE AIRSEAL LAND SNAP DIAMETER		4340	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AJ	55	COOLING HOLES MACHINING		7200	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AK	58	SPACER OUTER DIAMETER MACHINING		6730	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AL	37	FRONT COUPLING PILOT DIAMETER PLASMA COAT REPAIR		4215	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AN	41	MARK HIGHPOINT AXIAL RUNOUT		545	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package C	2	SURFACE DAMAGE BLEND REPAIR		1465	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package D	3	RESTORE CORROSION PROTECTIVE COATING (STEEL SHAFT)		3655	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package E	4	REPAIR NO. 4 BEARING RETAINING PLATE HOLES		965	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package F	5	NICKEL PLATE REPAIR NO. 4 BEARING RETAINING PLATE SEAL LAND		4340	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package G	6	NICKEL PLATE REPAIR REAR COUPLING PILOT DIAMETER		4340	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package H	7	NICKEL PLATE REPAIR FRONT COUPLING PILOT DIAMETER		4340	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package I	8	NICKEL PLATE REPAIR NO. 4 BEARING RETAINING PLATE MATING DIAMETER		4340	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package J	9	FRONT SPACER SURFACE MACHINE REPAIR		955	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package K	10	CHROME PLATE REPAIR FOR NO. 4 BEARING JOURNAL		5145	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package L	11	TIEBOLD HOLES BUSHING REPAIR		9605	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package M	12	CHROME PLATE REPAIR FOR 6TH STAGE LPT AIRSEAL SHOULDER		5145	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package N	13	FLANGE FACE PLASMA SPRAY REPAIR		4580	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package O	14	FLANGE SNAP DIAMETER PLASMA SPRAY REPAIR		4580	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package P	15	LOCAL TOUCH- UP REPAIR PROTECTIVE COATING (STEEL SHAFT)		2620	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package Q	16	SHAFT BALANCE (BY WAX APPLICATION) REPAIR		1700	SR Technics Switzerland
2382	50A077		49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package SB00	A72-328	EDDY CURRENT INSPECTION		320	SR Technics Switzerland
2382	50A077	EASA;FAA;CAAC;ANAC;CAA UK	49	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package A	CLN/INSP	CLEANING AND INSPECTION		1890	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AG	36	CLEVIS BOSS (PIN HOLE) BUSHING (STANDARD) REPLACEMENT REPAIR		3210	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AH	37	EGT PROBE BUSHING REPAIR		2555	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AI	39	STRUT INNER STAND-UP TRAILING EDGE CRACK REPAIR		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AJ	42	RIVERT HOLE WELD REAPIR ON NO. 4 BEARING HOUSING HEAT SHIELD MOUNTING FALNGE		4715	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AK	43	STRUT INNER STAND-UP TRAILING EDGE CRACK REPAIR		7045	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AL	49	NO. 4 BEARING HOUSING REAR SURFACE CRACKS WELD REPAIR		1905	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AM	50	NO. 4 BEARING HEAT SHIELD BRACKET WORN AND/OR ELONGATED RIVET HOLES WELD REPAIR		2840	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AN	51	STRUT OUTER STAND-UP TRAILING EDGE CRACK WELD REPAIR		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AP	61	TOP LIGHTENING SLOT CRACK FLANGE R AND S		3485	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package B	1	STRUT DENT AND CRACK REPAIR		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package C	2	HELICAL COIL INSERT REPAIR THERMOCOUPLE THREADED BOSS HOLES		3920	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package D	3	HELICAL COIL INSERT REPAIR INTERNAL NO. 4 BEARING OIL TUBE BOSS THREADED HOLES		3645	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package E	4	HELICAL COIL INSERT REPAIR NO. 3 BEARING OIL VENT TUBE BOSS HOLE		2970	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package F	5	REPLACE THE HELICAL COIL INSERTS ON THE NO. 4 BEARING COVER RETAINING HOLES		4235	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package G	6	REPLACE GROUND HANDLING BUSHINGS		6595	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package H	7	REPLACE MOUNT BUSHINGS		6595	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package I	8	REPLACE REAR FLANGE NUT PLATES		4250	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package J	9	REPLACE TURBINE EXHAUST CASE BOSS (NO. 4 BEARING OIL PRESSURE AND/OR SCAVENGE TUBE)		1030	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package K	10	REPLACE OIL PRESSURE AND/OR OIL SCAVENGE TUBE BOSS BUSHING		775	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package L	57	CRACKS IN STRUT TO CASE ORIGINAL EQUIPMENT MANUFACTURER \ IN ASSEMBLED CONDITION		12540	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package M	12	REPLACE NO. 4 BEARING CARBON SEAL HOUSING		11345	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package N	13	PLASMA SPRAY REPAIR THE REAR OUTER FLANGE SNAP DIAMETER		6250	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package O	14	NICKEL PLATE REPAIR THE OUTER FRONT FLANGE SNAP DIAMETER		6250	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package P	15	OUTER FRONT FLANGE BOLTHOLE RADIAL EXTENTION		1715	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package Q	16	PLASMA SPRAY REPAIR REAR INTERMEDIATE FLANGE SNAP DIAMETER		5925	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package R	17	WELD REPAIR INNER CASE AND SUPPORT STRUCTURE CRACKS		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package S	18	PATCH REPAIR INNER CASE AND SUPPORT STRUCTURE		6595	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package SB00	PW4ENG 79-76	REROUTING OF THE BEARING NO. 4 OIL TUBES		7695	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package SB01	24	REPLACE STRUTS		2195	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package SB02	11	REPLACE NO. 4 BEARING SHIELD AND HEAT SHIELD ASSEMBLY		1905	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package SB03	47	WELD REPAIR STRUT TO OUTER CASE FILLET RADIUS CRACKS	REWORK OF CARBON SEAL HOUSING NOT IN	12320	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package T	19	WELD REPAIR, LIGHTENING SLOT CRACKS (FLANGES R AND S)		8275	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package U	20	CHROMIUM PLATE NO. 4 BEARING SHOULDER		5490	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package V	21	BEARING SHOULDER CHROMIUM PLATE REPAIR		7040	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package W	58	OUTER CASE WALL INNER CENTER BODY, STRUT BODY STRUT INNER AND OUTER STAND-UPS WELD REPAIR		2135	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package X	23	SURFACE DAMAGE BLEND REPAIR		4725	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package Y	53	STRUT OUTER STAND-UP TRAILING EDGE CRACK WELD REPAIR		4725	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200-01; 50P416-001; 50P417-001; 50P418-001; 50		54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package Z	25	DRILL PURGE AND DRAIN HOLES IN EXHAUST CASE OUTER WALL AT STRUT LOCATIONS		2485	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		3630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AA	26	WELD REPAIR THE NO. 4 BEARING HEAT SHIELD BRACKET CRACKS		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AB	27	WELD REPAIR RIVET HOLE DAMAGE NO. 4 BEARING HEATSHIELD		1115	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AC	57	CRACKS IN STRUT TO CASE ORIGINAL EQUIPMENT MANUFACTURER WELD BEAD WELD REPAIR		3855	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AD	45	WELD REPAIR STRUT TO OUTER CASE FILLET RADIUS CRACKS		7975	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AE	30	PLASMA SPRAY REPAIR THE FRONT OUTER FLANGE FACE		5630	SR Technics Switzerland
2553	50P027; 50P174-01; 50P200	EASA;FAA;CAAC;ANAC	54	35	72-54-01	TURBINE EXHAUST CASE - TURBINE EXHAUST CASE ASSEMBLY - 94"	Package AF	38	NO.4 JOURNAL BUSHING REPAIR		7305	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC										
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package A	CLN/INSP	CLEANING AND INSPECTION	PN51H149 53H934 FOR SHOP VISIT ONLY	700	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1325	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package C	2	REPLACE NUT PLATES		1555	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2755	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		360	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package L	11	APPLY PWA 578 PAINT		1095	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package M	12	RING SEGMENT SLOT WELD REPAIR		1900	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package SB00	PW4ENG 72-432	SYNCHRONIZING RING - MODIFICATION OF PIN ATTACHMENT		1325	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package SB01	PW4ENG 72-474	SYNCHRONIZING RING - PAINT REMOVAL FROM ID		375	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package SB02	PW4ENG 72-527	SYNCHRONIZING RING STG 5 AND 6 - INCORPORATION OF LOCATING PIN		825	SR Technics Switzerland
2709	50S728; 50S730; 51H148; 5	EASA;FAA;CAAC;ANAC	36	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package SB03	PW4ENG 72-837	SYNCHRONIZING RING STG 5 AND 6 REPL		1825	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC										
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package A	CLN/INSP	CLEANING AND INSPECTION	PN54H780-01 50H794 54H795-01 54H902-01	650	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1325	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package C	2	REPLACE NUT PLATES		1970	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2755	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		360	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package L	11	APPLY PWA 578 PAINT		1095	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package SB00	PW4ENG 72-432	SYNCHRONIZING RING - MODIFICATION OF PIN ATTACHMENT		1325	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package SB01	PW4ENG 72-474	SYNCHRONIZING RING - PAINT REMOVAL FROM ID		375	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package SB02	PW4ENG 72-527	SYNCHRONIZING RING STG 5 AND 6 - INCORPORATION OF LOCATING PIN		825	SR Technics Switzerland
2710	50H794; 50H795; 53H932; 5	EASA;FAA;CAAC;ANAC	34	28	72-35-52	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC SYNCHRONIZING	Package SB03	PW4ENG 72-114	REPLACEMENT OR MODIFICATION FOR IMPROVED HPC ARM ASSEMBLY		1825	SR Technics Switzerland
2730	221-0262-501; 221-0262-503		24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package D	2	BEARING REPLACEMENT	ITEM 330	1815	SR Technics Switzerland
2730	221-0262-501; 221-0262-503		24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package E	3	BLEND REPAIR FOR MINOR DAMAGES		1380	SR Technics Switzerland
2730	221-0262-501; 221-0262-503		24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package SB01	APW4MD11 A71-86	AFT ENGINE MOUNT LINK - INSP/REPL	AD 94-13-07	1045	SR Technics Switzerland
2730	221-0262-501; 221-0262-503		24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package SB01	APW4NAC 71-138	AFT ENGINE MOUNT LINK - INSP/REPL		1045	SR Technics Switzerland
2730	221-0262-501; 221-0262-50	EASA;FAA;CAAC;ANAC	24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1150	SR Technics Switzerland
2730	221-0262-501; 221-0262-50	EASA;FAA;CAAC;ANAC	24	21	71-20-05	AFT ENGINE MOUNT - LINK ASSY - 94"	Package C	2	BEARING REPLACEMENT	ITEM 320	1815	SR Technics Switzerland
2839	50D205; 50D613; 52D338; 5	EASA;FAA;CAAC;ANAC										
2839	50D205; 50D613; 52D338; 5	EASA;FAA;CAAC;ANAC	28	28	72-33-16	FAN CASE - BLEED VALVE CAM FOLLOWER DAMPER ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		230	SR Technics Switzerland
2839	50D205; 50D613; 52D338; 5	EASA;FAA;CAAC;ANAC	28	28	72-33-16	FAN CASE - BLEED VALVE CAM FOLLOWER DAMPER ASSEMBLY	Package B	1	REPLACE THE DAMPER ROLLER		340	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package H	01.Jan	REPLACE STUDS	ASSEMBLED	2665	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB00	JFC131-2-73-8	INCORPORATION OF IMPROVED PRESSURE SWITCH	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB02	JFC131-2-73-16	REPLACE PREFORMED PACKINGS BLACK TO BROWN	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB03	JFC131-2-73-17	REPLACEMENT OF ALL INCORRECT MATERIAL PACKINGS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB04	JFC131-2-73-18	ADD EPOXY TO RESOLVER COVER SCREWS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB05	JFC131-2-73-20	REPLACEMENT OF THE SEGMENT GEAR	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB06	JFC131-2-73-21	RESOLVER PROCUREMENT OF RESOLVER WITH ADHESIVE PREAPPLIED	IN CONJUNCTION WITH PACKAGE MEDIUM C	1940	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB07	JFC131-2-73-22	TORQUE MOTOR NOZZLE INSPECTION	IN CONJUNCTION WITH PACKAGE MEDIUM C	210	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB08	JFC131-2-73-5	INCORPORATION OF NEW METERING VALVE, SLEEVE AND PISTON	IN CONJUNCTION WITH PACKAGE MEDIUM C	170	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB09	JFC131-2-73-11	REPLACEMENT OF THE SPUR GEAR AND SEGMENT GEAR	IN CONJUNCTION WITH PACKAGE MEDIUM C	320	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB10	JFC131-2-73-A24	ADD SPRING TO METERING VALVE(MV) AND MODIFY CONTROL ORIFI	IN CONJUNCTION WITH PACKAGE MEDIUM C	680	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB11	JFC131-2-73-10	ADDS A WASHERLESS GUIDE SHAFT FOR THE PRESSURE REGULATING	IN CONJUNCTION WITH PACKAGE MEDIUM C	680	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB12	JFC131-2-73-2	REPLACEMENT OF THE SEGMENT GEAR	IN CONJUNCTION WITH PACKAGE MEDIUM C	170	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB13	JFC131-2-73-3	ELIMINATION OF ADJUSTMENT SCREW SHIMS AND PIN		170	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB14	JFC131-2-73-4	ADDITIONAL CABLE STRAPS AND ADDED INSULATION SLEEVING FOR	ELECTRICAL WIRING	170	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB15	JFC131-2-73-12	INCORPORATE NEW START-RUN SOLENOID	IN CONJUNCTION WITH PACKAGE MEDIUM C	170	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB18	JFC131-2-12/H	NEW START/RUN SOLENOID	IN CONJUNCTION WITH PACKAGE MEDIUM C	170	SR Technics Switzerland
2869	801000-1; 801000-2; 801000-3; 801000-4		30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package SB19	SIR JFC131-2:00	FMU - ORIFICE SELECTION INFORMATION	IN CONJUNCTION WITH PACKAGE MEDIUM C	170	SR Technics Switzerland
2869	801000-1; 801000-2; 80100(	EASA;FAA;CAAC;ANAC;CAA UK	30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	2825	SR Technics Switzerland
2869	801000-1; 801000-2; 80100(	EASA;FAA;CAAC;ANAC;CAA UK	30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE MEDIUM	1600	SR Technics Switzerland
2869	801000-1; 801000-2; 80100(	EASA;FAA;CAAC;ANAC;CAA UK	30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. E	EXAMPLE: GEAR SEGMENT OR RESOLVER REP	7005	SR Technics Switzerland
2869	801000-1; 801000-2; 80100(	EASA;FAA;CAAC;ANAC;CAA UK	30	21	73-21-64	FUEL METRING UNIT - JFC131-2	Package G		OVERHAUL	DISASSEMBLY,CLEANING, INSPECTION, ASSEI	10100	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB02	PW4ENG 72-662	INCORP. OF ADDITIONAL PLATFORM AND AIRFOIL COOLING WHICH	REQUIRES A NEW FIRST STAGE HPT COOLING D	5520	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB03	PW4ENG 72-730	INSPECTION AND MODIFICATION OF THE VANE CAVITIES		3850	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB04	PW4ENG 72-795	INTRODUCTION OF THE ADVANTAGE PERFORMANCE UPGRADE CONFIGURATION TO IMPROVE HPT PERFORMANCE		2060	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB05	PW4ENG 72-572	CONVERS.OF PW4152-58 TO-3		310	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package Y		24 OUTER FLANGE REAR FACE PLASMA COAT REPAIR		6775	SR Technics Switzerland
3200	50K120; 50K136-001; 50K136-01; 50K137-001; 50K137-01; 50K178-001; 50		17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package Z		25 BLEND REPAIR		595	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package A	CLN/INSP	CLEANING AND INSPECTION		900	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package B		1 FRONT FLANGE FACE PLASMA SPRAY REPAIR		6500	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package D		3 PLASMA SPRAY INNER COMBUSTION CHAMBER DIAMETER		6500	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package E		4 FRONT DIAMETER PLASMA SPRAY REPAIR		6500	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package F		5 LOCATING PIN REPLACEMENT		925	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package G		6 WELD REPAIR THE PS4 TUBE HOLE		5370	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package H		7 OUTER FLANGE BOLTHOLE CRACKS WELD REPAIR		5420	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package I		8 OUTER FLANGE FRONT FACE WELD REPAIR		5370	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package J		9 FUNCTIONAL AIRFLOW (CHECK) REPAIR		1650	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package N		13 REPLACE THE CLINCH NUTS		770	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package O		14 PLASMA COAT REPAIR THE BRUSH SEAL SUPPORT DIAMETER		2505	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package P		15 INNER FLANGE BOLT HOLE CRACKS WELD REPAIR		4550	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package R		17 OUTER FLANGE FRONT FACE PLASMA SPRAY REPAIR		5370	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB00	PW4ENG 72-466	REPLACEMENT OF WITH BLADES THAT HAVE CERAMIC THERMAL BARI	FLOW TEST ONLY	1775	SR Technics Switzerland
3200	50K120; 50K136-001; 50K13	EASA;FAA;CAAC;ANAC	17	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY-S	Package SB01	PW4ENG 72-514	MODIFICATION OF TO IMPROVE COMPRESSOR SURGE MARGIN AND WEAR RESISTACE		2435	SR Technics Switzerland
3202	286T3501-40; 286T3502-04(	EASA;FAA;ANAC										
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC										
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC	5	21	20-XX-XX	PW4000 ENGINE HARNESS	Package B		PRE-TEST		640	SR Technics Switzerland
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC	5	21	20-XX-XX	PW4000 ENGINE HARNESS	Package C		REPAIR LIGHT		2040	SR Technics Switzerland
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC	5	21	20-XX-XX	PW4000 ENGINE HARNESS	Package D		REPAIR MEDIUM		2930	SR Technics Switzerland
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC	5	21	20-XX-XX	PW4000 ENGINE HARNESS	Package E		REPAIR HEAVY		4755	SR Technics Switzerland
3202	286T3501-40; 286T3502-04(	EASA;FAA;CAAC;ANAC	5	21	20-XX-XX	PW4000 ENGINE HARNESS	Package F		DISASSEMBLY		265	SR Technics Switzerland
3463	221-0261-501; 221-0261-503		23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package B		1 BUSHING REPLACEMENT		2095	SR Technics Switzerland
3463	221-0261-501; 221-0261-503		23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package C		1 INSTALLATION OF OVERSIZE BUSHING		4630	SR Technics Switzerland
3463	221-0261-501; 221-0261-503		23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package D		1 WORK DISTANCE BUSHING		1145	SR Technics Switzerland
3463	221-0261-501; 221-0261-503		23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package E		3 BLEND REPAIR		1020	SR Technics Switzerland
3463	221-0261-501; 221-0261-50	EASA;FAA;CAAC;ANAC	23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1130	SR Technics Switzerland
3463	221-0261-501; 221-0261-50	EASA;FAA;CAAC;ANAC	23	21	71-20-05	AFT ENGINE MOUNT - BEAM ASSY - 94"	Package B		1 ORIGINAL BUSHING REPLACEMENT		2095	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;ANAC										
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC										
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package A		FUNCTIONAL TEST		915	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package B		1 MOISTER REMOVAL		720	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package C		2 CONNECTOR PIN REPAIR		720	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package D		3 REPLACEMENT OF DAMAGED		720	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package G		OVERHAUL		1000	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package SB00	PW4ENG 72-755	RCC MODIFICATION (BOEING)		1075	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package SB01	PW4ENG 72-756	RCC MODIFICATION (AIRBUS, SYMMETRIC)		1075	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package SB02	PW4ENG 72-757	RCC MODIFICATION (MD-11)		1075	SR Technics Switzerland
3606	51D415; 51D418; 51D429; 5	EASA;FAA;CAAC;ANAC	11	21	73-21-56	PW4 EEC PROGRAMMING PLUG	Package SB03	PW4G-100-73-23	EEC PROGRAMMING PLUG - PROVIDE ADDITIONAL 20°C SHUNT CONFIGURATION		770	SR Technics Switzerland
3610	53T732; 53T733; 53T734		4	21	73-21-37	S C U PROGRAMMING PLUG	Package C		2 CONNECTOR PIN REPAIR		45	SR Technics Switzerland
3610	53T732; 53T733; 53T734		4	21	73-21-37	S C U PROGRAMMING PLUG	Package D		3 REPLACEMENT OF DAMAGED OR CORRODED CONTACT ON ELECTRICAL ASSEMBLY		115	SR Technics Switzerland
3610	53T732; 53T733; 53T734	EASA;FAA;CAAC;ANAC	4	21	73-21-37	S C U PROGRAMMING PLUG	Package A	CLN/INSP	BENCH TEST		590	SR Technics Switzerland
3610	53T732; 53T733; 53T734	EASA;FAA;CAAC;ANAC	4	21	73-21-37	S C U PROGRAMMING PLUG	Package A	CLN/INSP	CLEANING & INSPECTION		590	SR Technics Switzerland
3610	53T732; 53T733; 53T734	EASA;FAA;CAAC;ANAC	4	21	73-21-37	S C U PROGRAMMING PLUG	Package B		1 MOISTER REMOVAL		55	SR Technics Switzerland
7872	22953-002		6	21	30-21-05	ANTI-ICING THERMOCOUPLE PROBE PW 51U565	Package B	TESTING	TESTING AND FAULT ISOLATION		280	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
7872	22953-002		6	21	30-21-05	ANTI-ICING THERMOCOUPLE PROBE PW 51U565	Package C	1	STUD THREAD REPAIR		65	SR Technics Switzerland
7872	22953-002		6	21	30-21-05	ANTI-ICING THERMOCOUPLE PROBE PW 51U565	Package D	2	MOISTURE REMOVAL		605	SR Technics Switzerland
7872	22953-002	EASA;FAA;CAAC;ANAC	6	21	30-21-05	ANTI-ICING THERMOCOUPLE PROBE PW 51U565	Package A	CLN/INSP	CLEANING & INSPECTION		105	SR Technics Switzerland
7934	50L433-01; 50L509-01	EASA;FAA;CAAC;ANAC	27	28	72-52-99	HIGH PRESSURE TURBINE (HPT) - MISCELLANEOUS PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
7934	50L433-01; 50L509-01	EASA;FAA;CAAC;ANAC	27	28	72-52-99	HIGH PRESSURE TURBINE (HPT) - MISCELLANEOUS PARTS	Package B	1	STRAIGHTEN THE SHAFT - BORESCOPE PLUG		450	SR Technics Switzerland
8009	50P258-01		29	28	72-54-86	TURBINE EXHAUST CASE - NO. 4 BEARING (HOUSING) HEAT SHIELD A	Package B	1	PATCH REPAIR ISOLATION		605	SR Technics Switzerland
8009	50P258-01	EASA;FAA;CAAC;ANAC	29	28	72-54-86	TURBINE EXHAUST CASE - NO. 4 BEARING (HOUSING) HEAT SHIELD A	Package A	CLN/INSP	CLEANING AND INSPECTION		240	SR Technics Switzerland
9030	52H696-01; 52H890-01; 52H	EASA;FAA;CAAC;ANAC										
9030	52H696-01; 52H890-01; 52H	EASA;FAA;CAAC;ANAC	5	28	72-35-58	PW4 HPC SHROUD SEGMENT ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		170	SR Technics Switzerland
9030	52H696-01; 52H890-01; 52H	EASA;FAA;CAAC;ANAC	5	28	72-35-58	PW4 HPC SHROUD SEGMENT ASSEMBLY	Package SB00	PW4G-100-72-121	REPLACE 11STG. HPC SHROUD SET		230	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package B	1	72-35-06 / STRAIGHTEN STAGE 5 HPC DISK KNIFE-EDGE SEAL - STAGE 5 HPC DISK		3500	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package D	3	72-35-07 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		3725	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package E	4	72-35-06 / SHOTPEEN BLADE SLOTS - STAGE 5 HPC DISK		1590	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package F	4	72-35-08 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		1300	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package G	5	72-35-06 / RESTORE ANTIGALLING COMPOUND IN DISK BLADE SLOTS		2115	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package H	7	72-35-07 / BLEND REPAIR TANGENTIAL SLOT RIM RAILS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		1115	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package I	8	72-35-08 / RESTORE KNIFE-EDGE SEAL PLASMA COAT - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		8440	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package J	9	72-35-05 / PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING JOURNAL		3770	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package K	10	72-35-07 / RESTORE ANTIGALLING COATING TO AXIAL BLADE SLOTS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		2775	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package L	11	72-35-07 / SURFACE DAMAGE BLEND REPAIR - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		2165	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package M	12	72-35-07 / REPLACE 9TH STAGE HPC DRUM ROTOR (FRONT) DISK TUBE ASSEMBLY - HPC DRUM ROTOR (FRONT) DISI		3355	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package N	11	72-35-05 / BLEND REPAIR ANTI-TORQUE LUGS		1115	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package O	14	72-35-08 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING JOURNAL - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		5290	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package P	15	72-35-08 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING SEAL SPACER JOURNAL - HPC DRUM ROTOR (REAR) DI		5290	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package Q	16	72-35-08 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING FRONT SEAL JOURNAL - HPC DRUM ROTOR (REAR) DIS		5290	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package R	17	72-35-08 / NICKEL PLATE HPC REAR HUB NO. 3 BEARING SEAL SEAT SHOULDER - HPC DRUM ROTOR (REAR) DISK A		5420	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package S	18	72-35-07 / REPLACE ANTI-VORTEX TUBES		1850	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB01	PW4ENG 72-745 /	6TH STG DOVETAIL LUG FPI (IN COMBINATION WITH PACKAGE A)		1625	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB02	PW4ENG 72-515	5TH STG - MODIFICATION OF TO REMOVE THE BALANCE FLANGE		2405	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB03	PW4ENG 72-796	FPI OF THE 13TH, 14TH, AND 15TH STAGE BLADE LOADING AND LOCKING SLOTS FOR CRACKS		785	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB04	PW4ENG 72-653	MODIFICATION OF THE FRONT KNIFE EDGE SEAL TO IMPROVE DURABILITY		5235	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB05	PW4ENG 72-816	INTRODUCTION OF NEW SHOOT PEEN SPECIFICATION TO IMPROVE R	ADMINISTRATIVE PROCESS ONLY	455	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB06	PW4ENG 72-799	REPETITIVE INSPECTION OF ANTI-VORTEX TUBE (AVT) SHELF SLOTS FOR CRACKS		675	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB07	PW4ENG A72-722	BORESKOPE INSPECTION OF THE 6TH TO 7TH STAGE SPACER AREA FOR CRACKS		625	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB08	PW4ENG A72-833	EDDY CURRENT AND ULTRASONIC INSPECTION OF THE 10TH STAGE D	PART B, AD 2016-08-09	4215	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB09	PW$ENG 72-845	REIDENTIFY DRUM ROTOR ASSEMBLY		680	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package SB10	PW4ENG 72-772	VISUAL INSPECTION OF ON BLADE ROOT & DISK LUG	PART 001	625	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package T	7	72-35-06 / KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR		3930	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package U	9	72-35-07 /RESTORE KNIFE-EDGE SEAL PLASMA COAT		4780	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package V	6	72-35-06 / BLEND REPAIR KNIFE-EDGE SEALS - STAGE 5 HPC DISK		915	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package W	8	72-35-06 / BLEND REPAIR SURFACE DAMAGE - STAGE 5 HPC DISK		1485	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package X	8	72-35-07 / BLEND REPAIR KNIFE-EDGE SEALS - STAGE 5 HPC DISK		915	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 53H973-001; 53H973-01; 54H668; 57H678-001;		62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package Y	24	72-35-08 / STRAIGHTEN KNIFE-EDGE SEAL THAT HAS NO COATING - HPC DRUM ROTOR (REAR)DISK ASSEMBLY		840	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package A	CLN/INSP	CLEANING AND INSPECTION		3630	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AB	27	BLEND REPAIR SPLINE SURFACE DAMAGE		900	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AF	15	72-35-06 / KNIFE EDGE THICK COATING		3175	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AH	33	72-35-08 / CHROMIUM PLATE THE PILOT DIAMETER FRONT JOURNAL		5510	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AI	34	72-35-08 / REAR HUB TURBINE PILOT DIAMETER REAR JOURNAL CHROMIUM PLATE REPAIR - HPC DRUM ROTOR (RE		5510	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AJ	17	72-35-06 / KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR		3930	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AM	39	72-35-07/ KNIFE-EDGE SEAL THICK PLASMA COAT REPAIR		3375	SR Technics Switzerland
11470	51H778; 51H878; 52H578; 5	EASA;FAA;CAAC;ANAC	62	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -94"	Package AN	5	72-35-08 REAR DRUM BLEND SURFACE		1385	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AE	15	72-35-10 / BLEND REPAIR DAMAGED KNIFE-EDGE SEALS- DRUM ROTOR (REAR) DISK ASSEMBLY		915	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AF	17	72-35-09 / BLEND REPAIR SPLINE SURFACE DAMAGE		900	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AG	15	72-35-06 / KNIFE EDGE THICK COATING		3175	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AN	39	72-35-07 / KNIFE EDGE THICK COATING		3710	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package B	3	72-35-07 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		3725	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package C	4	72-35-06 / SHOTPEEN BLADE SLOTS - STAGE 5 HPC DISK		1590	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package D	4	72-35-10 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		1290	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package E	5	72-35-06 / RESTORE ANTIGALLING COMPOUND IN DISK BLADE SLOTS		2115	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package F	5	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING JOURNAL		5290	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package G	6	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING SEAL SPACER JOURNAL		5290	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package H	6	72-35-10 / RESTORE KNIFE-EDGE SEAL PLASMA COAT (VENDOR APPLICATION)		8450	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package I	7	72-35-06/KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR	STAGE 5 HPC DISK	3930	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package J	8	72-35-06 / BLEND REPAIR SURFACE DAMAGE - STAGE 5 HPC DISK		1485	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package K	9	72-35-05 / PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING JOURNAL		3770	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package L	9	72-35-07 / RESTORE KNIFE-EDGE SEAL PLASMA COAT (VENDOR APPLICATION)		4780	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package M	10	72-35-07 / RESTORE ANTIGALLING COATING TO AXIAL BLADE SLOTS (STAGE 6, 7 AND 8)		2775	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package N	11	72-35-07 / SURFACE DAMAGE BLEND REPAIR - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		2165	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package O	11	72-35-05 / BLEND REPAIR ANTI-TORQUE LUGS		1115	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package P	1	72-35-06 / STRAIGHTEN STAGE 5 HPC DISK KNIFE-EDGE SEAL - STAGE 5 HPC DISK		3500	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package Q	5	72-35-10 / BLEND REPAIR TANGENTIAL SLOT RIM RAILS - DRUM ROTOR (REAR) DISK ASSEMBLY		895	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package R	6	72-35-06 / BLEND REPAIR KNIFE-EDGE SEALS - STAGE 5 HPC DISK		915	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package S	18	72-35-07 / REPLACE ANTI-VORTEX TUBES - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		1850	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB02	PW4G-100-72-186	72-35-10 / FPI HPC REAR DRUM BLADE LOCKING SLOTS	AD FAA-2012-18-17	590	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB05	PW4G-100-72-240	REPLACEMENT OF, AND INTRODUCTION OF A NEW SHOT PEEN SPECIFICATION		390	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB06	PW4G-100-72-226	REPETITIVE INSPECTION OF ANTI-VORTEX TUBE (AVT) SHELF SLOTS FC AD FAA-2010-24-14		675	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB07	PW4G-100-72-255	EDDY CURRENT AND ULTRASONIC INSPECTION OF THE 10TH STAGE D PART B, AD FAA 2016-08-09		4215	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB08	PW4G-100-72-232	BSI OF ANTI VOTEX TUBE SHELF SLOTS		495	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB10	PW4G-100-72-239	INTRODUCTION OF, TO IMPROVE FRONT COMPRESSOR DURABILITY		1530	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package SB15	PW4G-100-72-260	HPC, NEW DRUM ROTOR DISK ASSY		485	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package T	7	72-35-07 / BLEND REPAIR TANGENTIAL SLOT RIM RAILS - DRUM ROTOR (FRONT) DISK ASSEMBLY		1115	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package U	7	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO.3 BEARING FRONT SEAL JOURNAL - TURBINE DRIVE SHAFT		5290	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package V	8	72-35-07 / BLEND REPAIR KNIFE-EDGE SEALS - DRUM ROTOR (FRONT) DISK ASSEMBLY		915	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package W	12	72-35-10 / PLASMA SPRAY BRUSH SEAL LAND - DRUM ROTOR (REAR) DISK ASSEMBLY		4745	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package X	13	72-35-10 / BLEND LOCK SCREW DAMAGE IN BLADE SLOTS - DRUM ROTOR (REAR) DISK ASSEMBLY		2980	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 58H678; 59H078		54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package Z	14	72-35-09 / BLEND REPAIR SURFACE DAMAGE - TURBINE DRIVE SHAFT		1155	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 5	EASA;FAA;CAAC;ANAC	54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package A	CLN/INSP	CLEANING AND INSPECTION		3630	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 5	EASA;FAA;CAAC;ANAC	54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AA	26	72-35-09 / REAR HUB TURBINE PILOT DIAMETER FRONT JOURNAL CHROMIUM PLATE REPAIR		5515	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 5	EASA;FAA;CAAC;ANAC	54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AB	27	72-35-09 / REAR HUB TURBINE PILOT DIAMETER REAR JOURNAL CHROMIUM PLATE OR COAT REPAIR		5515	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 5	EASA;FAA;CAAC;ANAC	54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AC	14	72-35-10 / BLEND REPAIR SURFACE DAMAGE - DRUM ROTOR (REAR) DISK ASSEMBLY		1555	SR Technics Switzerland
11471	50S192; 52A520; 55H878; 5	EASA;FAA;CAAC;ANAC	54	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR STG 5 - 15 -100"	Package AD	15	72-35-09 / BLEND REPAIR KNIFE-EDGE SEALS - TURBINE DRIVE SHAFT		915	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AH	15	72-35-06 / KNIFE EDGE THICK COATING		3500	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AJ	INSP/CHK-03	FLUORESCENT PENETRANT TEST AND ELECTROSTATIC APPLICATION STG. 13-15		425	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AK	17	72-35-09 / BLEND REPAIR SPLINE SURFACE DAMAGE		900	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AL	17	72-35-06 / KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR		5285	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AN	39	72-35-07 / KNIFE-EDGE SEAL THICK PLASMA COAT REPAIR		4165	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package B	1	72-35-06 / STRAIGHTEN STAGE 5 HPC DISK KNIFE-EDGE SEAL		4000	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package D	3	72-35-07 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		3725	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package E	4	72-35-06 / SHOTPEEN BLADE SLOTS - STAGE 5 HPC DISK		1590	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package F	4	72-35-10 / SHOTPEEN BLADE SLOTS - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		1290	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package G	5	72-35-06 / RESTORE ANTIGALLING COMPOUND IN DISK BLADE SLOTS		2115	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package H	5	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING JOURNAL - HPC TURBINE DRIVE SHAFT		5290	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package I	5	72-35-10 / BLEND REPAIR TANGENTIAL SLOT RIM RAILS - HPC DRUM ROTOR DISK (REAR HUB) ASSEMBLY		895	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package J	6	72-35-06 / BLEND REPAIR KNIFE-EDGE SEALS - STAGE 5 HPC DISK		915	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package K	6	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING SEAL SPACER JOURNAL - HPC TURBINE DRIVE SHAFT		5290	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package L	6	72-35-10 / RESTORE KNIFE-EDGE SEAL PLASMA COAT - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		8450	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package M	7	72-35-06 / KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR- STAGE 5 HPC DISK		3930	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package N	7	72-35-07 / BLEND REPAIR TANGENTIAL SLOT RIM RAILS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		1115	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package O	7	72-35-09 / CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING FRONT SEAL JOURNAL - HPC TURBINE DRIVE SHAFT		5290	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package P	8	72-35-07 / BLEND REPAIR KNIFE-EDGE SEALS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		915	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package R	8	72-35-06 / BLEND REPAIR SURFACE DAMAGE - STAGE 5HPC		1485	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package S	9	72-35-07 / RESTORE KNIFE-EDGE SEAL PLASMA COAT - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		4780	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB01	PW4ENG 72-745	6TH STG DOVETAIL LUG FPI (IN COMBINATION WITH PACKAGE A)	PART 001	955	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB03	PW4ENG 72-515	5TH STG - MODIFICATION OF TO REMOVE THE BALANCE FLANGE		2645	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB04	PW4ENG 72-796	FPI OF THE 13TH, 14TH, AND 15TH STAGE BLADE LOADING AND LOCKI	AD FAA-2012-18-17	1025	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB05	PW4ENG 72-816	INTRODUCTION OF NEW SHOOT PEEN SPECIFICATION TO IMPROVE R	ADMINISTRATIVE PROCESS ONLY	150	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB06	PW4ENG 72-799	REPETITIVE INSPECTION OF ANTI-VORTEX TUBE (AVT) SHELF SLOTS FC	AD FAA-2010-24-14	675	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB07	PW4ENG A72-722	BORESKOPE INSPECTION OF THE 6TH TO 7TH STAGE SPACER AREA FO	AD FAA-2002-12-15	625	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB08	PW4ENG A72-833	EDDY CURRENT AND ULTRASONIC INSPECTION OF THE 10TH STAGE D	PART B, AD FAA-2016-08-09	4215	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB09	PW4ENG 72-845	REIDENTIFY DRUM ROTOR ASSEMBLY		680	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package SB10	PW4ENG 72-772	VISUAL INSPECTION OF ON BLADE ROOT & DISK LUG	PART 001	625	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package T	9	72-35-05 / PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING JOURNAL		3770	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package U	10	72-35-07 / RESTORE ANTIGALLING COATING TO AXIAL BLADE SLOTS - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		2775	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package V	11	72-35-07 / SURFACE DAMAGE BLEND REPAIR - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		2165	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package W	12	72-35-07 / REPLACE 9TH STAGE HPC DRUM ROTOR (FRONT) DISK TUBE ASSEMBLY - HPC DRUM ROTOR (FRONT) DISI		3355	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package X	12	72-35-10 / PLASMA SPRAY BRUSH SEAL LAND - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		4745	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package Y	13	72-35-10 / BLEND LOCK SCREW DAMAGE IN BLADE SLOTS - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		2980	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 56H378-002; 57H478; 57H478-002; 58H575; 58		58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package Z	14	72-35-09 / BLEND REPAIR SURFACE DAMAGE - HPC TURBINE DRIVE SHAFT		1155	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		3815	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AA	14	72-35-10 / SURFACE DAMAGE BLEND REPAIR - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		1555	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AB	15	72-35-09 / BLEND REPAIR KNIFE-EDGE SEALS - HPC TURBINE DRIVE SHAFT		915	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AC	15	72-35-10 / BLEND REPAIR DAMAGED KNIFE EDGE SEALS - HPC DRUM ROTOR (REAR) DISK ASSEMBLY		915	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AD	18	72-35-07 / REPLACE ANTI-VORTEX TUBES - HPC DRUM ROTOR (FRONT) DISK ASSEMBLY		1850	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AE	26	72-35-09 / REAR HUB TURBINE PILOT DIAMETER REAR JOURNAL CHROMIUM PLATE REPAIR		5510	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AF	27	72-35-09 / REAR HUB TURBINE PILOT DIAMETER REAR JOURNAL CHROMIUM PLATE - SHAFT, HPC DRIVE, TURBINE		5515	SR Technics Switzerland
11474	50S225; 55H778; 56H378; 5	EASA;FAA;CAAC;ANAC	58	35	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - DRUM DISK ASSY STG 13 - 94"	Package AG	11	72-35-05 / BLEND REPAIR ANTI - TORQUE LUGS - HPC FRONT HUB		1115	SR Technics Switzerland
14014	50S749; 58H596		24	28	72-35-69	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB00	PW4ENG 72-756	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	AIRBUS	13475	SR Technics Switzerland
14014	50S749; 58H596		24	28	72-35-69	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB00	PW4ENG 72-757	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	MD11	13475	SR Technics Switzerland
14014	50S749; 58H596		24	28	72-35-69	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB01	PW4ENG 72-845	INTRO OF NEW HPC FRONT DRUM		13125	SR Technics Switzerland
14014	50S749; 58H596	EASA;FAA;CAAC;ANAC	24	28	72-35-69	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package B	ASSEMBLY02	MACHINE STAGE 5 - 15 OUTER AIR SEAL SET		13475	SR Technics Switzerland
14014	50S749; 58H596	EASA;FAA;CAAC;ANAC	24	28	72-35-69	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB00	PW4ENG 72-755	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	BOEING	13475	SR Technics Switzerland
14082	54T661; 55T409	EASA;FAA;CAAC;ANAC	26	21	71-21-11	FWD ENGINE MOUNT - BEARING - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		350	SR Technics Switzerland
14082	54T661; 55T409	EASA;FAA;CAAC;ANAC	26	21	71-21-11	FWD ENGINE MOUNT - BEARING - 100"	Package B	1	PWA 474 ANTIGALLING COMPOUND REPLACEMENT REPAIR		405	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package Q	16	WELD REPAIR VANE ANTI- ROTATION SLOTS (STAGE 4)		3725	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package R	17	WELD REPAIR VANE ANTI- ROTATION SLOTS (STAGE 5)		3725	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package S	18	WELD REPAIR VANE ANTI- ROTATION SLOTS (STAGE 6)		5400	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB00	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		6510	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB01	PW4ENG 72-578	MODIFY THE FRONT ID RAIL ANTI- ROTATION SLOTS		2715	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB02	PW4ENG 72-579	MODIFY THE LPT VANE CLUSTER ASSEMBLY ANTI- ROTATION SLOTS AND ADD STRESS RELIEF SLOTS (STAGES 3 - 6)		20180	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB03	SI 20F-09	DIMENSIONAL INSPECTION		715	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB04	72-069925	PHIII - LOW PRESS TURBINE MODIFICATION		2360	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB05	72-216055	PHIII- LOW PRESS TURBINE MODIFICATION	4 STG MODIFICATION	2360	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB06	72-216055	PHIII- LOW PRESS TURBINE MODIFICATION	COMPLETE MODIFICATION	6405	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package T	19	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 3)		13980	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package T	20	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 4)		13980	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package T	21	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 5)		13980	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package T	22	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 6)		13980	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package U	75	CRACK BLEND REPAIR STG 3-6 ANTIROT. SLOTS		645	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package V	76	CRACK BLEND REPAIR STG 3-6 STRESS RELIEF. SLOTS		645	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package X	23	REPAIR FRONT INNER RAIL CRACKS BY STOP DRILLING		8055	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package Y	54	WELD BUILD-UP THE WORN OUTER AIRSEAL RETENTION SLOT (STAGES 3THROUGH 6) REPAIR		6180	SR Technics Switzerland
14160	50N248; 50N248-001; 50N248-002; 50N248-003; 50N248-004; 50N248-00		37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package Z	25	REPLACE LPT BORESCOPE BOSS		890	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package A	CLN/INSP	CLEANING AND INSPECTION	INCLUDE AD FAA-2012-14-09	4655	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AA	26	REPLACE RIVETED- ON ANGLED BRACKET		675	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AB	27	REPLACE FRONT FLANGE BRACKET		1690	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AC	28	MACHINE REPAIR VANE ANTI- ROTATION SLOTS TO REMOVE CRACKS		6510	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AD	29	STAGE 3 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		20955	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AD	30	STAGE 4 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		20955	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AD	31	STAGE 5 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		20955	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AD	32	STAGE 6 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		20955	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AH	33	STAGE 3 VANE HOOK INNER DIAMETER PLASMA COAT REPAIR		14165	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AJ	38	REAR FLANGE BRACKET REPLACEMENT REPAIR		505	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AK	47	STG.3 VANE HOOK CRACK WELD REPAIR		5650	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AL	56	WELD REPAIR AFT RETENTION LIP WEAR (STAGES 3 - 6)		12485	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AM	60	WELD REPAIR FRONT VANE HOOK GROOVE WEAR (STAGES 3 - 6)		6985	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AN	62	WORN TRANSITION DUCT RETENTION GROOVE WELD BUILD- UP REPAIR		7115	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package B	1	REPLACE FRONT FLANGE LOCATING PIN		960	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package C	2	REPLACE REAR FLANGE LOCATING PIN		1245	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package D	70	REPAIR REAR FLANGE THREADS WITH HELICAL COIL INSERTS		670	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package E	4	REPAIR THREADED BOSS HOLES WITH HELICAL COIL INSERTS		1340	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package F	5	SURFACE DAMAGE BLEND REPAIR		1910	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package G	6	STAGE 2 HPT SEAL MATING SURFACE PLASMA COAT REPAIR		4365	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package H	7	PLASMA SPRAY REPAIR FRONT FLANGE FACE (WITH FLANGE BRACKET)		3760	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package H	36	PLASMA SPRAY REPAIR FRONT FLANGE FACE (WITH FLANGE BRACKET)		3760	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package I	8	PLASMA SPRAY REPAIR FRONT FLANGE SNAP DIAMETER		3820	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package J	9	PLASMA SPRAY REPAIR REAR FLANGE SNAP DIAMETER		3550	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package K	10	REAR FLANGE FACE (WITHOUT BRACKET) PLASMA SPRAY REPAIR		3730	SR Technics Switzerland
14160	50N248; 50N248-001; 50N2	EASA;FAA;CAAC;ANAC	37	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package P	15	WELD REPAIR VANE ANTI- ROTATION SLOTS (STAGE 3)		3725	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package I	8	REAR SNAP DIAMETER PLASMA SPRAY REPAIR		4115	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package J	9	FRONT SNAP DIAMETER PLASMA SPRAY REPAIR		4115	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package K	10	REAR FLANGE FACE PLASMA SPRAY REPAIR		4705	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package L	11	SHOTPEEN REPAIR		1015	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package N	12	MACHINE REPAIR UNDERSIZED REAR SNAP INNER DIAMETER		815	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package SB00	PW4G-100-72-105	MODIFICATION OF, ENLARGING THE COOLING AIR HOLE AREA		1950	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package SB01	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1145	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package SB02	PW4ENG 72-657	ENLARGING OF THE COOLING AIR HOLE AREA		1690	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 51N304; 51N404; 51N404-001; 51N604		40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package SB04	PW4ENG 72-658	INTRODUCTION OF A NEW SPARE PART DISK FOR ENGINES PRIOR TO SB PW4ENG 72-634		265	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package B	1	SURFACE DAMAGE BLEND REPAIR		1205	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package C	2	MACHINE REPAIR FRONT FACE		955	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package D	3	REAR FLANGE FACE PLASMA SPRAY REPAIR		3320	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package F	5	PLASMA SPRAY REPAIR REAR SNAP DIAMETER		3960	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC;CAA UK	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		2250	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC;CAA UK	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package E	4	FRONT FLANGE FACE PLASMA SPRAY REPAIR		5220	SR Technics Switzerland
15023	50N024; 50N724; 50N924; 5	EASA;FAA;CAAC;ANAC;CAA UK	40	28	72-53-14	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT DISK ASSEMBLY	Package G	6	PLASMA SPRAY REPAIR FRONT SNAP DIAMETER		3960	SR Technics Switzerland
15167	221-0264-503	EASA;FAA;CAAC;ANAC	6	21	71-20-05	PW4 AFT ENGINE MOUNT PIN ITEM 1-300	Package A	CLN/INSP	CLEANING AND INSPECTION		125	SR Technics Switzerland
18858	50P255-01; 50P347; 50P348	EASA;FAA;CAAC;ANAC										
18858	50P255-01; 50P347; 50P348	EASA;FAA;CAAC;ANAC	15	28	72-54-35	TURBINE EXHAUST CASE - NO. 4 BEARING SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		360	SR Technics Switzerland
18858	50P255-01; 50P347; 50P348	EASA;FAA;CAAC;ANAC	15	28	72-54-35	TURBINE EXHAUST CASE - NO. 4 BEARING SHIELD	Package B	2	DAMAGED FOIL MATERIAL SPOT WELD REPAIR		305	SR Technics Switzerland
18887	80876-20-5; 80876-20-6	EASA;FAA;CAAC;ANAC										
18887	80876-20-5; 80876-20-6	EASA;FAA;CAAC;ANAC	6	21	71-20-05	AFT MOUNT MD-11 PIN & BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
18888	221-0251-509; 221-0251-51	EASA;FAA;CAAC;ANAC										
18888	221-0251-509; 221-0251-51	EASA;FAA;CAAC;ANAC	6	21	71-20-04	PW4 FWD MOUNT MD-11 BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package E	4	SEATING SHOULDER PLASMA SPRAY REPAIR		2505	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package F	5	COUPLING PILOT DIAMETER PLASMA SPRAY REPAIR		5620	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package G	6	REAR COUPLING SNAP DIAMETER REPAIR		4440	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package H	7	NO. 1 BEARING JOURNAL PLASMA SPRAY REPAIR		2705	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package I	8	NO. 1 SEAL PLATE DIAMETER PLASMA SPRAY REPAIR		2820	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package J	9	REAR OUTER SNAP DIAMETER PLASMA SPRAY REPAIR		2900	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package K	10	OUTER FRONT SNAP DIAMETER PLASMA SPRAY REPAIR		2995	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package P	15	ANTI-TORQUE SLOT REPAIR		2195	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package Q	16	MACHINE OFF DAMAGED COUNTERWEIGHT BALANCE FLANGE TANG REPAIR		3350	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 52B021; 53B021		44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package SB00	AD 2005-25-09	FPI AND ECI LIFE-LIMITED PART, LPC FRONT HUB	IN CONJUNCTION WITH PACKAGE A	605	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 5	EASA;FAA;CAAC;ANAC	44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package A	CLN/INSP	CLEANING AND INSPECTION		8500	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 5	EASA;FAA;CAAC;ANAC	44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package AA	26	BEARING SEAL SEAT FACE PLASMA SPRAY REPAIR		4035	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 5	EASA;FAA;CAAC;ANAC	44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package B	1	BLEND REPAIR FRONT COMPRESSOR HUB ASSEMBLY		2315	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 5	EASA;FAA;CAAC;ANAC;CAA UK	44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package C	2	HUB BLADE SLOT ANTIGALLANT AND SHOTPEEN TREATMENT		3745	SR Technics Switzerland
19044	50B221; 50B321; 51B321; 5	EASA;FAA;CAAC;ANAC;CAA UK	44	28	72-31-07	LOW PRESSURE COMPRESSOR (LPC) - FRONT COMPRESSOR HUB ASSE	Package D	3	REPLACE LOOSE OR DAMAGED NUTS		1605	SR Technics Switzerland
19124	50K128		7	28	72-51-01	STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package AC	28	ANTI-ROTATION LOCK BOLT HOLE WELD REPAIR		1645	SR Technics Switzerland
19124	50K128		7	28	72-51-01	STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	11	FRONT INNER DIAMETER PLASMA SPRAY REPAIR		5395	SR Technics Switzerland
19124	50K128		7	28	72-51-01	STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	12	VANE RETAINING SLOTS WELD REPAIR		5395	SR Technics Switzerland
19124	50K128		7	28	72-51-01	STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	15	ANTI-ROTATION LOCK LUG CRACK WELD REPAIR		5395	SR Technics Switzerland
19124	50K128	EASA;FAA;CAAC;ANAC	7	28	72-51-01	STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		995	SR Technics Switzerland
19125	50K044		2	28	72-51-01	SEAL - HPT SUPPORT	Package E	4	REAR INNER SEAL FACE PLASMA COAT REPAIR		3530	SR Technics Switzerland
19125	50K044	EASA;FAA;CAAC;ANAC	2	28	72-51-01	SEAL - HPT SUPPORT	Package A	CLN/INSP	CLEANING & INSPECTION		995	SR Technics Switzerland
20803	50L171; 50L471; 50L671; 50	EASA;FAA;CAAC;ANAC										
20803	50L171; 50L471; 50L671; 50	EASA;FAA;CAAC;ANAC	5	28	72-00-52	PW4 TURBINE ROTOR-ASSEMBLY, 1.ST STAGE	Package A	CLN/INSP	CLEANING & INSPECTION		555	SR Technics Switzerland
20803	50L171; 50L471; 50L671; 50	EASA;FAA;CAAC;ANAC	5	28	72-00-52	PW4 TURBINE ROTOR-ASSEMBLY, 1.ST STAGE	Package B	INSP-02	INSPECTION/CHECK	PW 4168	785	SR Technics Switzerland
20803	50L171; 50L471; 50L671; 50	EASA;FAA;CAAC;ANAC	5	28	72-00-52	PW4 TURBINE ROTOR-ASSEMBLY, 1.ST STAGE	Package C	INSP-03	INSPECTION/CHECK	PW 40XX, PW 41XX, PW 44XX	785	SR Technics Switzerland
20806	50L172; 50L472; 50L572; 50	EASA;FAA;CAAC;ANAC										
20806	50L172; 50L472; 50L572; 50	EASA;FAA;CAAC;ANAC	17	28	72-00-52	ENGINE GENERAL - COMMON PARTS - HIGH PRESSURE TURBINE - ASS	Package A	CLN/INSP	CLEANING AND INSPECTION		2205	SR Technics Switzerland
20806	50L172; 50L472; 50L572; 50	EASA;FAA;CAAC;ANAC	17	28	72-00-52	ENGINE GENERAL - COMMON PARTS - HIGH PRESSURE TURBINE - ASS	Package A	INSP-02	VISUAL INSPECTION	PW4168	2205	SR Technics Switzerland
20806	50L172; 50L472; 50L572; 50	EASA;FAA;CAAC;ANAC	17	28	72-00-52	ENGINE GENERAL - COMMON PARTS - HIGH PRESSURE TURBINE - ASS	Package A	INSP-03	VISUAL INSPECTION	PW40XX,PW41XX,PW44XX	2205	SR Technics Switzerland
20874	70R019; 70R020; 70R022; 7(	EASA;FAA;CAAC;ANAC										
20874	70R019; 70R020; 70R022; 7(	EASA;FAA;CAAC;ANAC	24	28	72-09-50	ENGINE GENERAL - COMMON PARTS - ENGINE BEARINGS	Package A	CLN/INSP	CLEANING AND INSPECTION		370	SR Technics Switzerland
20874	70R019; 70R020; 70R022; 7(	EASA;FAA;CAAC;ANAC	24	28	72-09-50	ENGINE GENERAL - COMMON PARTS - ENGINE BEARINGS	Package SB00	PW4G-100-72-115	REPL. OR MODIFICATION OF TO INCORPORATE A TIGHTER FIT AND AN ANTI-ROTATIONAL PIN		1045	SR Technics Switzerland
20874	70R019; 70R020; 70R022; 7(	EASA;FAA;CAAC;ANAC	24	28	72-09-50	ENGINE GENERAL - COMMON PARTS - ENGINE BEARINGS	Package SB01	PW4ENG 72-664	DEOILER IDLER BRG WITH ANTI-ROT FEATURES		910	SR Technics Switzerland
20874	70R019; 70R020; 70R022; 7(	EASA;FAA;CAAC;ANAC;CAA UK										
20953	53T848-01		4	28	7X-XX_XX	PW4TRAP TO EEC	Package SB00	MAN-PW4G-100-2-	INSPECT.& CLEANING OF CONDENSATION TRAP	MAN-PW4G-100-2-00	480	SR Technics Switzerland
20953	53T848-01	EASA;FAA;CAAC;ANAC	4	28	7X-XX_XX	PW4TRAP TO EEC	Package A	CLN/INSP	CLEANING & INSPECTION		85	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package C	2	REPLACE DUCT		910	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package D	3	PLASMA SPRAY REAR OUTER SURFACE		2315	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package H	7	SUPPORT FLANGE AND SLOT WELD BUILD- UP REPAIR		5355	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package I	8	SUPPORT FLANGE (FRONT FACE) WEAR AREA PLASMA SPRAY REPAIR		3710	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package K	10	RIVET HOLE PLUG WELD REPAIR		2115	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package L	11	RIVET HOLES WELD ATTACHMENT REPAIR		3330	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package N	13	SUPPORT FLANGE PATCH WELD REPAIR		1885	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package O	14	CRACK WELD REPAIR		5615	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package SB00	PW4ENG 72-513	REPL. OF WITH A DUCT ASSEMBLY THAT HAS NEW DUCT SEGEMENTS AND LPT SEALING RING WITH HARDCOATING		1460	SR Technics Switzerland
21176	50N265; 50N537		22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package SB01	PW4G-100-72-41	MODIFICATION OF THE DUCT ASSEMBLY THAT WILL ADD HARD COAT TO THE NEW DETAIL PARTS		1460	SR Technics Switzerland
21176	50N265; 50N537	EASA;FAA;CAAC;ANAC	22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package A	CLN/INSP	CLEANING AND INSPECTION		790	SR Technics Switzerland
21176	50N265; 50N537	EASA;FAA;CAAC;ANAC;CAA UK	22	28	72-53-20	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING S	Package B	1	REPLACE NUT PLATES		575	SR Technics Switzerland
21752	400970-11; 400970-13; 400!	EASA;FAA;CAAC;ANAC										
21752	400970-11; 400970-13; 400!	EASA;FAA;CAAC;ANAC	11	21	29.10.2001	HYDRAULIC HOSE	Package A	CLN/INSP	CLEANING AND INSPECTION		880	SR Technics Switzerland
21752	400970-11; 400970-13; 400!	EASA;FAA;CAAC;ANAC	11	21	29.10.2001	HYDRAULIC HOSE	Package A	CLN/INSP	PRE TEST		880	SR Technics Switzerland
21752	400970-11; 400970-13; 400!	EASA;FAA;CAAC;ANAC	11	21	29.10.2001	HYDRAULIC HOSE	Package G		OVERHAUL		1555	SR Technics Switzerland
22404	794629		24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	210	SR Technics Switzerland
22404	794629		24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package B	1	REPLACE PROTECTIVE FINISH		2405	SR Technics Switzerland
22404	794629		24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package C	2	REPAIR SURFACE DAMAGE		2100	SR Technics Switzerland
22404	794629		24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package SB00	PW4ENG 72-619	INLET COMP. FRONT CONE SEGMENT REPL.		545	SR Technics Switzerland
22404	794629		24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package SB01	PW4G-100-72-70	INLET CONE SEGMENT: P/N 794629 TO 51A760		545	SR Technics Switzerland
22404	794629	EASA;FAA;CAAC;ANAC	24	28	72-31-80	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE FROI	Package A	CLN/INSP	CLEANING AND INSPECTION		400	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package F	5	REPAIR TRAILING EDGE DELAMINATION		4365	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package H	7	AXIAL CRACK REPAIR		5805	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package I	8	HEAT INLET CONE TO REMOVE MOISTURE		1185	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package K	10	DELAMINATION REPAIR		3600	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package L	ASSEMBLY-01	BALANCE CONE SEGMENT ACC. EM 72-31-81 ASSEMBLY 01		1325	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package N	13	PROTECTIVE COATING - TOUCH UP REP		3060	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package SB00	PW4G-100-72-217	MODIFICATION OF TO INCORPORATE A NEW SEAL TO MINIMIZE LEAKAGE FOR INCREASED ENGINE PERFORMANCE		1325	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package SB01	PW4ENG 72-792	MODIFICATION OF TO INCORPORATE A NEW SEAL WITH IMPROVED RETENTION FOR INCREASED DURABILITY		1285	SR Technics Switzerland
22465	51A043-001; 51A045; 51A045-002; 51A112-01; 51A609-01; 51A709-01; 52,		38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package SB02	PW4ENG 72-629	MODIFICATION OF TO PROVIDE A CONE ASSY		200	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package A	CLN/INSP	CLEANING AND INSPECTION		1545	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	100	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package B	1	REPLACE INLET CONE SEAL REPAIR		3350	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package B	01A	REAR SEAL REPLACEMENT REPAIR		3350	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package B	01B	REAR SEAL REPLACEMENT REPAIR		3350	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package B	01C	REAR SEAL REPLACEMENT REPAIR		3350	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package C	2	REPLACE PROTECTIVE FINISH (COMPLETE REPLACEMENT)		4365	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package C	4	REPAIR SURFACE DAMAGE		4365	SR Technics Switzerland
22465	51A043-001; 51A045; 51A0	EASA;FAA;CAAC;ANAC;CAA UK	38	28	72-31-81	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR INLET CONE (REA	Package D	3	REPLACE NUT PLATE		945	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package H	7	KNIFE-EDGE SEAL THIN PLASMA COAT REPAIR		4355	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package I	8	BLEND REPAIR SURFACE DAMAGE		2840	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package J	9	PLASMA SPRAY REPAIR THE REAR SNAP DIAMETER		2840	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package K	10	PLASMA SPRAY REPAIR THE FRONT SNAP DIAMETER		2840	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package O	14	MACHINE REPAIR THE REAR SNAP DIAMETER		2130	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package SB00	PW4ENG 72-515	HPC 5TH STG DISK - REMOVAL OF BALANCE FLANGE		2840	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package SB01	PW4ENG 72-653	HPC 5TH STG DISK - REMOVAL OF FRONT KNIFE-EDGE SEAL		3115	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package SB02	AD 2005-25-09	FPI LIFE-LIMITED PART, HPC 5TH STG DISK	IN CONJUNCTION WITH PACKAGE A	430	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 54H705; 54H705-001; 56H605; 56H705; 57H105		39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package SB03	PW4ENG 72-772	HPC 5TH STG VISUAL INSPECTION ON BLADE ROOT & DISK LUG	PART 001	190	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package A	CLN/INSP	CLEANING AND INSPECTION		1905	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package AH	15	KNIFE EDGE SEAL THICK COATING		5620	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package B	1	STRAIGHTEN STAGE 5 HPC DISK KNIFE-EDGE SEAL		3685	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package D		DISASSEMPLY TO PIECE PART LEVEL		340	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package F	5	RESTORE ANTIGALLING COMPOUND IN DISK BLADE SLOTS		3115	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package G	6	BLEND REPAIR KNIFE-EDGE SEALS		595	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC;CAA UK	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package AJ	17	KNIFE EDGE SEAL THIN PLASMA COATING		4355	SR Technics Switzerland
22667	51H005; 51H905; 54H405; 5	EASA;FAA;CAAC;ANAC;CAA UK	39	28	72-35-06	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 5 HPC DISK	Package E	4	SHOTPEEN BLADE SLOTS		3115	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC										
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package A	CLN/INSP	CLEANING AND INSPECTION	PN54H782-01 54H797-01FOR SHOP VISIT ONI	545	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1380	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package C	2	REPLACE NUT PLATES		1375	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2850	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		375	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package L	11	APPLY PWA 578 PAINT		1135	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package SB00	PW4ENG 72-197	SYNCHRONIZING RING - RELOCATION OF RIGGING PIN HOLE		2100	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package SB01	PW4ENG 72-432	SYNCHRONIZING RING - MODIFICATION OF PIN ATTACHMENT		1380	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package SB02	PW4ENG 72-474	SYNCHRONIZING RING - PAINT REMOVAL FROM ID		390	SR Technics Switzerland
22803	50S729; 51H151; 51H151-0(	EASA;FAA;CAAC;ANAC	35	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package SB03	PW4ENG 72-837	SYNCHRONIZING RING STG 5 AND 6 REPL		1825	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AI	34	CHROMIUM PLATE THE PILOT DIAMETER REAR JOURNAL		4830	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AJ	35	NO. 3 BEARING SEAL SEAT SHOULDER PLASMA COAT REPAIR		2915	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package B	1	STRAIGHTEN KNIFE-EDGE SEAL		5285	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package B	8	RESTORE KNIFE-EDGE SEAL PLASMA COAT		5285	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package D	3	MACHINE MISALIGNED TIEBOLT HOLES OVERSIZE		3635	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package E	4	SHOTPEEN BLADE SLOTS		1470	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package F	5	BLEND REPAIR SURFACE DAMAGE		2335	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package G	6	BLEND REPAIR TANGENTIAL SLOT RIM RAILS		925	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package H	7	BLEND REPAIR KNIFE-EDGE SEALS		5805	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package I		REMARKING ILEGIBLE P/N AND S/N		155	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package K	10	NICKEL PLATE HPC REAR HUB NO.3 BRG HEAT SHIELD REAR JOURNAL		4365	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package L	11	NICKEL PLATE HPC REAR HUB NO.3 BRG HEAT SHIELD FRONT JOURNAL		4365	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package O	14	CHROMIUM PLATE HPC REAR HUB NO.3 BRG JOURNAL		5000	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package P	15	CHROMIUM PLATE HPC REAR HUB NO.3 BRG SEAL SPACER JOURNAL		5000	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package Q	16	CHROMIUM PLATE HPC REAR HUB NO.3 BRG FRONT SEAL JOURNAL		4885	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package R	17	NICKEL PLATE HPC REAR HUB NO.3 BRG SEAL SEAT SHOULDER		4885	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB00	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	370	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB01	72-490	CONVERSION OF A PW446O OR PW4462 TO A PW4460 (-3) OR PW446	REMOVE KNIFE EDGE SEAL	6235	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB01	72-504	CONVERSION OF A PW4052, PW4056, PW4060,T0 A PW4052(-3), PW4	REMOVE KNIFE EDGE SEAL	6235	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB01	72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW415:	REMOVE KNIFE EDGE SEAL	6235	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB02	PW4ENG 72-816	SEAL 13TH, 14TH AND 15TH STAGE - REPLACEMENT OF AND INTRODU	TO IMPROVE REAR DRUM ROTOR DURABILIT	1515	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB03	PW4ENG 72-796	FPI OF THE 13TH, 14TH, AND 15TH STAGE BLADE LOADING AND LOCKING SLOTS FOR CRACKS		1120	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package T	19	PLASMA SPRAY REPAIR REAR DRUM FRONT FLANGE SNAP DIAMETER		3635	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package U	20	REPAIR REAR HUB TORQUE SLOTS		1755	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package V	21	BLEND REPAIR TORQUE SLOTS LUGS		375	SR Technics Switzerland
22815	50H936; 50H936-002; 50S425-01; 53H923-001; 53H923-01		43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package Y	24	STRAIGHTEN KNIFE-EDGE SEAL THAT HAS NO COATING		810	SR Technics Switzerland
22815	50H936; 50H936-002; 50S42	EASA;FAA;ANAC;CAA UK	43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AB	27	BLEND REPAIR SPLINE SURFACE DAMAGE		105	SR Technics Switzerland
22815	50H936; 50H936-002; 50S42	EASA;FAA;CAAC;ANAC	43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package A	CLN/INSP	CLEANING AND INSPECTION		2550	SR Technics Switzerland
22815	50H936; 50H936-002; 50S42	EASA;FAA;CAAC;ANAC	43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AA	26	PLASMA REPAIR BRUSH SEAL LAND		3710	SR Technics Switzerland
22815	50H936; 50H936-002; 50S42	EASA;FAA;CAAC;ANAC	43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AE	30	REPAIR THE HEAT SHIELD ANTI-ROTATION SLOT SURFACE DAMAGE		1825	SR Technics Switzerland
22815	50H936; 50H936-002; 50S42	EASA;FAA;CAAC;ANAC;CAA UK	43	28	72-35-08	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AH	33	CHROMIUM PLATE THE PILOT DIAMETER FRONT JOURNAL		4830	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;CAAC;EASA/ANAC BRAZIL DUAL RELEASE										
23023	221-5098-501; 332T4921-27	EASA;FAA;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package A	CLN/INSP	CLEANING AND INSPECTION		260	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package I	12	DAMAGED AREA HEATSHIELD STRAP GUIDE REPAIR		310	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC										
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package A	INSP-05	PRESSURE TEST		260	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package B	1	APPLY ANTIGALLING COMPOUND		95	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package C	2	THRUST WIRE INSTALLATION		310	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package D	4	BLEND REPAIR SURFACE DAMAGE		260	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package E	5	DENT REPAIR		1675	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package F	7	LINER,NUT,REDUCER,ELBOW,SLEEVE REPLACEMENT		915	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package G	10	HEAT SHIELD REPAIR OF BLEED DUCT		515	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package H	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD TUBE CONNECTOR NUTS, COUPLING, FERRULE		320	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package K	SPM	REPLACE DEFECTIVE STOPNUTS ACC. SPM		325	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package SB00	PW4G-100-A72-15	INSPECTION OF STARTING AIR ACTUATION TUBE (AA96)	SB PW4G-100-A72-158	315	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package SB01	PW4G-100-80-5	STARTER, CONNECT. ASSEMBLY MODI OR REPLACEMENT RR TUBE TO	PART 001	2335	SR Technics Switzerland
23023	221-5098-501; 332T4921-27	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 EXTERNAL TUBES	Package W	22	REPEAR CONICAL SEAT		210	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB08	PW4G-100-72-142	REPLACEMENT OR MODIFYING OF TO INCORP. IMPROVED UNDER PLATFORM COATING & INCR. COOLING FLOW		545	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB09	PW4G-100-72-176	FLUORESCENT PENETRANT INSPECTION FOR CRACKS	IN CONJUNCTION WITH PACKAGE A	720	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB10	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	735	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB11	PW4ENG 72-795	INTRODUCTION OF THE ADVANTAGE PERFORMANCE UPGRADE (APU)	TO IMPROVE HIGH PRESSURE TURBINE (HPT)	190	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB12	PW4ENG 72-806	HUB ASSEMBLY, 2ND STAGE HPT, INTRODUCTION OF, COMMON TO OTHER PW4 ENGINE MODELS		185	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB13	PW4ENG 72-537	HPT, STG 2 REMOVE METERING PLUG/PLATE		215	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602-021; 50L602-022; 50L602-023; 50L602-024; 5(		48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB14	PW4G-100-72-220	CONVERSION TO ADVANTAGE 70 ENGINE MODEL		215	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package A	CLN/INSP	CLEANING AND INSPECTION		1355	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package B	1	PLASMA SPRAY OUTER SNAP DIAMETER - STAGE 2 (ROTATING) AIRSEAL CONTACT WEAR		8010	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package C	2	PLASMA SPRAY INNER SNAP DIAMETER - STAGE 2 (ROTATING) AIRSEAL CONTACT WEAR		8010	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package D	3	MACHINE NUT COUPLING MATING FACE		2130	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package E	4	SHOTPEEN HUB		1540	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package F	5	NICKEL PLATE REPAIR STAGE 2 HPT BLADE RETAINING PLATE AXIAL SNAP TURBINE INTERMEDIATE HUB (STAGE 2)		4585	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package I	8	SURFACE DAMAGE BLEND REPAIR		2360	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package J	9	INNER HPC SHAFT PILOT DIAMETER PLASMA COAT/DUAL WIRE ELECTRIC ARC COAT REPAIR		5300	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package K	10	PLASMA COAT REPAIR FRONT MATING SNAP DIAMETER		6620	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package L	11	REAR OUTER DIAMETER MACHINE REPAIR		1985	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package O	14	REMOVE OR INSTALL THE METERING PLUG REPAIR		530	SR Technics Switzerland
24651	50L602; 50L602-001; 50L60	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package Q	16	UNBALANCE MARKING		715	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB00	PW4ENG 72-736	FLUORESCENT PENETRANT INSPECTION FOR CRACKS	IN CONJUNCTION WITH PACKAGE A	720	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB01	PW4ENG 72-435	REPLACEMENT OF, FOR BETTER ENGINE BALANCE		7415	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB02	PW4ENG 72-627	INTRODUCE IMPROVED COOLING TO THE NO. 3 BEARING COMPARTMENT FOR THE LPT		1055	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB03	PW4ENG 72-490	CONVERSION OF A PW4460 OR PW4460 (-3) OR PW4462 (-3)		720	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB05	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		720	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB06	PW4ENG 72-716	REPLACEMENT OF WITH A BLADE WITH PWA 1480 ALLOY AND DIMENSIONAL CHANGES		860	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB07	PW4G-100-72-165	REPLACEMENT OF WITH A BLADE WITH PWA 1480 ALLOY AND DIMENSIONAL CHANGES		515	SR Technics Switzerland
24651	50L602; 50L602-001; 50L602	EASA;FAA;CAAC;ANAC;CAA UK	48	28	72-52-06	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 2)	Package SB04	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060,TO A PW4052(-3), PW4056(-3), OR PW4060(-3)		720	SR Technics Switzerland
27164	1602080-001; 1604220-001;	EASA;FAA;CAAC;ANAC										
27164	1602080-001; 1604220-001;	EASA;FAA;CAAC;ANAC	22	21	75-24-13	AIR-OIL HEAT EXCH VALVE/TCC VALVE - TURBINE CASE COOLING AIR \	Package A	CLN/INSP	CLEANING AND INSPECTION		370	SR Technics Switzerland
27164	1602080-001; 1604220-001;	EASA;FAA;CAAC;ANAC;CAA UK										
27515	53D514	EASA;FAA;CAAC;ANAC	23	28	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 2.5 BLEED DUCT CAM S	Package B	62	2.5 BLEED DUCT CAM SLOT LINER WEAR PLASMA COAT REPAIR		1110	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package C		PREINSPECTION OF FORWARD ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	980	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: THRUST LINK REPLACEMENT (1EA)	855	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: BEAM ASSY REPLACEMENT	2485	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: MOUNT SET ASSY REPLACEMENT	4525	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package G		OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEM	4630	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB00	PW4G-100-71-7	IDENTIFICATION OF THE MOUNT ASSEMBLIES WITH A PART NUMBER	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	125	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB01	PW4G-100-71-12	REPLACE STUD WITH A HARDER MATERIAL BOLT	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	125	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB02	PW4G-100-71-11	REPLACEMENT OF BOLTS THAT ARE MORE DURABLE	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	125	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB03	PW4G-100-71-22	INTRODUCTION OF NEW BEARING HOUSING TO INCREASE DURABILIT	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	125	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB04	PW4G-100-71-26	APPLICATION OF ANTI GALLANT COMPOUND TO THE MOUNT MAIN B	IN CONJUNCTION WITH PACKAGE HEAVY OR	315	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB05	PW4G-100-A71-18	PERIODIC VISUAL INSPECTION OF THE PRIMARY THRUST LOAD PATH	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	175	SR Technics Switzerland
29279	55T407		22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package SB06	PW4G-100-71-8	INTRODUCTION OF NEW ENGINE MOUNT HARDWARE WITH ADDITIOI	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
29279	55T407	EASA;FAA;CAAC;ANAC	22	28	72-34-79	INTERMEDIATE CASE - FWD ENGINE MOUNT ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		470	SR Technics Switzerland
45191	53D227		23	28	72-33-08	FAN CASE - FAN CASEBLEED VALVE DUCT ASSEMBLY	Package B	18	2.5 BLEED DUCT CAM SLOT LINER WEAR PLASMA COAT REPAIR		1110	SR Technics Switzerland
45191	53D227	EASA;FAA;CAAC;ANAC	23	28	72-33-08	FAN CASE - FAN CASEBLEED VALVE DUCT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		505	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package C		PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE MEDIUM	205	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		3090	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EX	EXAMPLE: GEAR SEGMENT OR RESOLVER REP	6015	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EX	EXAMPLE: HOUSING REPLACEMENT	7535	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package G		OVERHAUL	DISASSEMBLY,CLEANING, INSPECTION, ASSEM	13375	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package H	01.Jan	REPLACE STUDS	ASSEMBLED	2790	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB00	JFC131-4-5	ADDS A WASHERLESS GUIDE SHAR FOR THE PRESSURE REGULATING V	IN CONJUNCTION WITH PACKAGE MEDIUM C	640	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB01	JFC131-4-6	REMOVES THE PRESSURE SWITCH AND CONTACTS	IN CONJUNCTION WITH PACKAGE MEDIUM C	640	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB02	JFC131-4-7	IMPROVED RUBBERBOOT TUBING FOR PROXIMITY WIRE PLANNING IN	IN CONJUNCTION WITH PACKAGE MEDIUM C	640	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB03	JFC131-4-8	REPLACE PREFORMED PACKINGS BLACK TO BROWN	IN CONJUNCTION WITH PACKAGE MEDIUM C	640	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB04	JFC131-4-10	REPLACEMENT OF ALL INCORRECT MATERIAL PACKINGS	IN CONJUNCTION WITH PACKAGE MEDIUM C	640	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB05	JFC131-4-12	REMOVAL OF PRESSURE SWITCH PLUG AND ELIMINATION OF HOUSIN	IN CONJUNCTION WITH PACKAGE MEDIUM C	130	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB06	JFC131-4-13	REMOVAL OF BACKSHELL AND BACKSHELL LINER FROM A/F CONNECT	IN CONJUNCTION WITH PACKAGE MEDIUM C	130	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB07	JFC131-4-11	REPLACEMENT OF INCORRECT PISTON SEAL	IN CONJUNCTION WITH PACKAGE MEDIUM C	340	SR Technics Switzerland
45219	808800-1		26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package SB08	JFC131-4-73-16	TORQUE MOTOR NOZZLE INSPECTIO N	IN CONJUNCTION WITH PACKAGE MEDIUM C	340	SR Technics Switzerland
45219	808800-1	EASA;FAA;CAAC;ANAC;CAA UK	26	21	73-21-76	FUEL METRING UNIT - JFC131-4	Package B		BENCH-TEST	READJUSTMENT AND TESTING	2790	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package J	9	LOCK LUGS BLEND REPAIR		880	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package K	10	CLINCH NUT REPLACEMENT REPAIR		1055	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package L	11	FRONT INNER ROTATING AIRSEAL OUTER SNAP DIAMETER PLASMA SPRAY REPAIR		5890	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package O	14	FRONT BEARING SPACER MATING FACE PLASMA COAT REPAIR		1380	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package P	15	MACHINE FRONT OUTER AIRSEAL DIAMETER TO SIZE		2280	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package Q	16	REAR OUTER SNAP DIAMETER PLASMA COAT REPAIR		3440	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package R	17	SURFACE DAMAGE REPAIR		775	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB00	AD 2005-25-09	FPI LIFE-LIMITED PART, HUB TURBINE FRONT		590	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB01	PW4ENG 72-736	PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		590	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB01	PW4G-100-72-176	FPI OF HPT HUBS & OUTER AIRSEAL,1ST & 2ND STG		590	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB02	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060 TO A PW4052(-3), PW4056(-3) OR PW4060(-3)		5710	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB03	PW4ENG 72-795	INTRODUCTION OF THE ADVANTAGE PERFORMANCE UPGRADE CONF (INSPECTION ONLY)		190	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB04	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		2845	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB05	PW4ENG 72-828	INTRODUCTION OF FOR COMMONALITY AND PROVIDE A PROCEDURE TO IDENTIFY FRONT HUBS THAT HAVE FULL L		515	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB06	PW4ENG 72-490	CONVERSION OF A PW446O OR PW4462 TO A PW4460 (-3) OR PW4462 (-3)		2845	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021;	51L901; 52L301; 52L401; 52L401-001; 55L06	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package SB07	PW4G-100-72-250	PROVIDE A PROCEDURE TO IDENTIFY FRONT HUB ASSEMBLIES THAT HAVE FULL LIFE		515	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021	EASA;FAA;CAAC;ANAC	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package A	CLN/INSP	CLEANING AND INSPECTION		2000	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021	EASA;FAA;CAAC;ANAC	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package B	1	AIRSEAL DIAMETER PLASMA SPRAY REPAIR		2835	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021	EASA;FAA;CAAC;ANAC	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package C	2	INNER FRONT DIAMETER PLASMA COAT REPAIR		4505	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021	EASA;FAA;CAAC;ANAC	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package F	5	PLASMA SPRAY REPAIR TURBINE INTERMEDIATE HUB (STAGE 2) MATING SNAP DIAMETER		5965	SR Technics Switzerland
45343	50L501; 51L201; 51L201-021	EASA;FAA;CAAC;ANAC	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package G	6	FRONT INNER ROTATING AIRSEAL SNAP DIAMETER PLASMA SPRAY REPAIR		4195	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
45343	50L501; 51L201; 51L201-02	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package D	3	INNER DIAMETER PLASMA COAT REPAIR		5695	SR Technics Switzerland
45343	50L501; 51L201; 51L201-02	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package E	4	SURFACE DAMAGE BLEND REPAIR		2225	SR Technics Switzerland
45343	50L501; 51L201; 51L201-02	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package H	7	FRONT BEARING SPACER MATING FACE MACHINE REPAIR		2240	SR Technics Switzerland
45343	50L501; 51L201; 51L201-02	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-52-05	HIGH PRESSURE TURBINE (HPT) - TURBINE FRONT HUB (STAGE 1)	Package I	8	FRONT HUB SHOTPEEN REPAIR		970	SR Technics Switzerland
62426	50S013-01		24	28	72-35-84	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 HPC CASE ASSEMBLY	Package F	5	PLASMA SPARY THE REAR SNAP DIAMERERS		2760	SR Technics Switzerland
62426	50S013-01		24	28	72-35-84	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 HPC CASE ASSEMBLY	Package G	6	PLASMA SPRAY THE REAR FLANGE FACE		2760	SR Technics Switzerland
62426	50S013-01	EASA;FAA;CAAC;ANAC;CAA UK	24	28	72-35-84	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1300	SR Technics Switzerland
62427	58H348-01		21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package F	5	FLANGE BOLTS REPLACEMENT REPAIR		915	SR Technics Switzerland
62427	58H348-01		21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package G	6	SURFACE DAMAGE BLEND REPAIR		490	SR Technics Switzerland
62427	58H348-01		21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package H	7	PIN (FLARED ASSEMBLY) REPLACEMENT REPAIR		605	SR Technics Switzerland
62427	58H348-01		21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package I	8	BORESCOPE BOSS REPLACEMENT REPAIR		735	SR Technics Switzerland
62427	58H348-01		21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package J	9	NUT ASSEMBLY REPLACEMENT REPAIR		700	SR Technics Switzerland
62427	58H348-01	EASA;FAA;CAAC;ANAC	21	28	72-35-85	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		600	SR Technics Switzerland
62428	58H317		22	28	72-35-86	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 HPC CASE ASSEMBLY	Package B	1	FRONT SNAP DIA PLASMA COAT REPAIR		2270	SR Technics Switzerland
62428	58H317		22	28	72-35-86	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 HPC CASE ASSEMBLY	Package C	2	REAR SNAP DIAMETER PLASMA COAT REPAIR		2270	SR Technics Switzerland
62428	58H317		22	28	72-35-86	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 HPC CASE ASSEMBLY	Package F	5	TOUCH-UP COAT REPAIR (PWA 77 COATED PARTS)		650	SR Technics Switzerland
62428	58H317		22	28	72-35-86	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 HPC CASE ASSEMBLY	Package G	6	SURFACE DAMAGE BLEND REPAIR (PWA 77 COATED PARTS)		635	SR Technics Switzerland
62428	58H317	EASA;FAA;CAAC;ANAC	22	28	72-35-86	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		800	SR Technics Switzerland
62429	58H318-01		21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package B	1	FRONT DIAMETER PLASMA COAT REPAIR		2260	SR Technics Switzerland
62429	58H318-01		21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package C	2	REAR MATING DIAMETER PLASMA COAT REPAIR		2260	SR Technics Switzerland
62429	58H318-01		21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package F	5	FRONT AND REAR FLANGE BOLTS REPLACEMENT REPAIR		595	SR Technics Switzerland
62429	58H318-01		21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package G	6	TOUCH UP COAT REPAIR		555	SR Technics Switzerland
62429	58H318-01		21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package H	7	SURFACE DAMAGE BLEND REPAIR		495	SR Technics Switzerland
62429	58H318-01	EASA;FAA;CAAC;ANAC	21	28	72-35-87	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		770	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package B	1	FRONT SNAP DIA PLASMA COAT REPAIR		3015	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package C	2	REAR SNAP DIAMETER PLASMA COAT REPAIR		2340	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package F	5	REAR FLANGE STUDS REPLACEMENT REPAIR		455	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package G	6	TOUCH-UP COAT REPAIR		580	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package H	7	BLEND SURFACE DAMAGE REPAIR		565	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package I	8	NUT ASSEMBLY REPLACEMENT REPAIR		400	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package J	9	FLARED ASSEMBLY PIN REPLACEMENT REPAIR		610	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package K	10	BORESCOPE BOSS REPLACEMENT REPAIR		740	SR Technics Switzerland
62430	58H322-01		20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package N	13	REAR FLANGE HEAT SHIELD RETAINING POCKET COAT REPAIR		3080	SR Technics Switzerland
62430	58H322-01	EASA;FAA;CAAC;ANAC	20	28	72-35-89	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1130	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package B	1	FRONT SNAP DIAMETER PLASMA COAT REPAIR		2240	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package C	2	REAR SNAP DIAMETER PLASMA COAT REPAIR		2240	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package F	5	REAR FLANGE BOLTS REPLACEMENT REPAIR		450	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package G	6	TOUCH-UP COAT REPAIR		575	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package H	7	SURFACE DAMAGE BLEND REPAIR		565	SR Technics Switzerland
62451	58H320-01		21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package I	8	CLINCH NUT REPLACEMENT REPAIR		395	SR Technics Switzerland
62451	58H320-01	EASA;FAA;CAAC;ANAC	21	28	72-35-88	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 HPC CASE ASSEMBLY	Package A	CLN/INSP	CELANING AND INSPECTION		770	SR Technics Switzerland
62452	58H344-01		23	28	72-35-83	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 HPC CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1485	SR Technics Switzerland
62452	58H344-01		23	28	72-35-83	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 HPC CASE ASSEMBLY	Package B	1	BLEND THE SURFACE DAMAGE		845	SR Technics Switzerland
62452	58H344-01		23	28	72-35-83	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 HPC CASE ASSEMBLY	Package C	2	REPLACE THE REAR FLANGE BOLTS		845	SR Technics Switzerland
62452	58H344-01	EASA;FAA;CAAC;ANAC	23	28	72-35-83	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 HPC CASE ASSEMBLY	Package A		REMOVE CORROSION BY DRY ABRASIVE BLAST		1485	SR Technics Switzerland
62466	50S067-01; 58H343; 58H601	EASA;FAA;CAAC;ANAC										
62466	50S067-01; 58H343; 58H601	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 8 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62468	58H345	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 9 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62469	58H347	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 10 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62470	58H323	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 12 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62471	58H349	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 11 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62472	58H324	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 13 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62473	58H325	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 14 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62477	50S066; 58H326	EASA;FAA;CAAC;ANAC										
62477	50S066; 58H326	EASA;FAA;CAAC;ANAC	6	28	72-35-23	PW4 STG. 15 HPC BLADE OUTER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
62485	50S678-01; 50S678-02; 50S	EASA;FAA;CAAC;ANAC										
62485	50S678-01; 50S678-02; 50S	EASA;FAA;CAAC;ANAC	24	28	72-35-24	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 COMPRESSOR STATOI	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62485	50S678-01; 50S678-02; 50S	EASA;FAA;CAAC;ANAC	24	28	72-35-24	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 COMPRESSOR STATOI	Package B	1	BLEND REPAIR SURFACE DAMAGE		175	SR Technics Airfoil Services Ltd.,
62485	50S678-01; 50S678-02; 50S	EASA;FAA;CAAC;ANAC	24	28	72-35-24	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 COMPRESSOR STATOI	Package F	5	STATOR SEGMENT OUTER PLATFORM COATING REPAIR		375	SR Technics Airfoil Services Ltd.,
62486	50S279-01; 50S279-02; 50S	EASA;FAA;CAAC;ANAC										
62486	50S279-01; 50S279-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-25	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 COMPRESSOR STATOI	Package A	CLN/INSP	CELANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62486	50S279-01; 50S279-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-25	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 COMPRESSOR STATOI	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62486	50S279-01; 50S279-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-25	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 COMPRESSOR STATOI	Package D	3	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62486	50S279-01; 50S279-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-25	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 9 COMPRESSOR STATOI	Package I	8	VANE SURFACE DAMAGE WELD REPAIR		1320	SR Technics Airfoil Services Ltd.,

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
62487	50S680-01; 50S680-02; 50S	EASA;FAA;CAAC;ANAC										
62487	50S680-01; 50S680-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-26	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62487	50S680-01; 50S680-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-26	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 COMPRESSOR STATC	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62487	50S680-01; 50S680-02; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-26	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 10 COMPRESSOR STATC	Package H	7	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62488	50S271-01; 50S271-02; 58H	EASA;FAA;CAAC;ANAC										
62488	50S271-01; 50S271-02; 58H	EASA;FAA;CAAC;ANAC	23	28	72-35-27	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62488	50S271-01; 50S271-02; 58H	EASA;FAA;CAAC;ANAC	23	28	72-35-27	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 COMPRESSOR STATC	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62488	50S271-01; 50S271-02; 58H	EASA;FAA;CAAC;ANAC	23	28	72-35-27	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 11 COMPRESSOR STATC	Package G	6	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62489	50S372-01; 50S372-02; 50S	EASA;FAA;CAAC;ANAC										
62489	50S372-01; 50S372-02; 50S	EASA;FAA;CAAC;ANAC	22	28	72-35-28	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62489	50S372-01; 50S372-02; 50S	EASA;FAA;CAAC;ANAC	22	28	72-35-28	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 COMPRESSOR STATC	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62489	50S372-01; 50S372-02; 50S	EASA;FAA;CAAC;ANAC;CAA UK	22	28	72-35-28	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 12 COMPRESSOR STATC	Package B	1	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62490	50S283-01; 50S283-02; 58H	EASA;FAA;CAAC;ANAC										
62490	50S283-01; 50S283-02; 58H	EASA;FAA;CAAC;ANAC	22	28	72-35-29	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62490	50S283-01; 50S283-02; 58H	EASA;FAA;CAAC;ANAC	22	28	72-35-29	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 COMPRESSOR STATC	Package B	1	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62490	50S283-01; 50S283-02; 58H	EASA;FAA;CAAC;ANAC	22	28	72-35-29	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 13 COMPRESSOR STATC	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62491	50S174-01; 50S474-01; 50S	EASA;FAA;CAAC;ANAC										
62491	50S174-01; 50S474-01; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-30	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		190	SR Technics Airfoil Services Ltd.,
62491	50S174-01; 50S474-01; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-30	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 COMPRESSOR STATC	Package B	1	VANE SURFACE DAMAGE BLEND REPAIR		175	SR Technics Airfoil Services Ltd.,
62491	50S174-01; 50S474-01; 50S	EASA;FAA;CAAC;ANAC	23	28	72-35-30	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 14 COMPRESSOR STATC	Package C	2	OUTER PLATFORM PLASMA COAT REPAIR		375	SR Technics Airfoil Services Ltd.,
62544	58H400		22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package AE	57	BLEND REPAIR		990	SR Technics Switzerland
62544	58H400		22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package AF	62	REMOVAL AND APPLICATION OF PWA 110-31 COAT REPAIR		1440	SR Technics Switzerland
62544	58H400		22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package AG	63	PWA 110 COAT TOUCH-UP REPAIR		1310	SR Technics Switzerland
62544	58H400		22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package AH	64	REMOVAL AND APPLICATION OF PWA 53-47 OR PWA 271-47 COAT		2605	SR Technics Switzerland
62544	58H400		22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package AI	69	REPLACE THE HPC SUPPORT	ONLY LABOR HOURS	4035	SR Technics Switzerland
62544	58H400	EASA;FAA;CAAC;ANAC	22	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC (OUTER) REAR CASE ASSEN	Package A	CLN/INSP	CLEANING AND INSPECTION		1410	SR Technics Switzerland
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC	35	28	72-35-80	HIGH PRESSURE COMPRESSOR (HPC) - HEAT SHIELDS	Package D	3	PLASMA COAT REPAIR		4325	SR Technics Switzerland
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC;ANAC										
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC;ANAC	35	28	72-35-80	HIGH PRESSURE COMPRESSOR (HPC) - HEAT SHIELDS	Package A	CLN/INSP	CLEANING AND INSPECTION		580	SR Technics Switzerland
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC;ANAC	35	28	72-35-80	HIGH PRESSURE COMPRESSOR (HPC) - HEAT SHIELDS	Package B	1	ANTIGALLING COMPOUND REPLACEMENT REPAIR		1705	SR Technics Switzerland
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC;ANAC	35	28	72-35-80	HIGH PRESSURE COMPRESSOR (HPC) - HEAT SHIELDS	Package C	2	WASHER OR RIVET REPLACEMENT REPAIR		505	SR Technics Switzerland
62545	50S027; 50S028; 50S311-01	EASA;FAA;CAAC;ANAC	35	28	72-35-80	HIGH PRESSURE COMPRESSOR (HPC) - HEAT SHIELDS	Package SB00	PW4ENG 72-783	MODIFY THE LOWER HALF OF THE HEATSHIELD TO INCORPORATE AN ANTI-ROTATION FEATURE (PART B)		2180	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package C	16	WELD REPAIR FLANGE K BOLT HOLE CRACKS		3365	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package E	41	REPLACE THE IDENTIFICATION BRACKET		2250	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package F	44	OUTER FRONT SNAP DIA. PLASMA SPRAY		5925	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package G	45	INSERTS REPLACEMENT REPAIR		1535	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package H	47	FRONT FLANGE FACE PLASMA COAT REPAIR		2915	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package I	48	REAR SNAP DIAMETER PLASMA COAT REPAIR		4935	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package K	52	REAR W SEAL SHOULDER PLASMA COAT REPAIR		5615	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package M	53	STAGE 9 W SEAL SHOULDER PLASMA COAT REPAIR		4935	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package N	14	WELD REPAIR FLANGE H BOLT HOLE CRACKS		7020	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package O	54	INNER REAR FLANGE NUT PLATE REPLACEMENT REPAIR		1440	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package Q	56	SURFACE DAMAGE BLEND REPAIR		1515	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package Y	51	PISTON RING SEAL DIA. PLASMACOAT		7020	SR Technics Switzerland
72341	58H367		28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package Z	70	CASE WALL CRACK WELD REPAIR		4080	SR Technics Switzerland
72341	58H367	EASA;FAA;CAAC;ANAC	28	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		1515	SR Technics Switzerland
73288	8241-01; 8242; 8243; 8244;	EASA;FAA;ANAC	12	21	26.10.1962	PW4 FIRE AND OVERHEAT DETECTION SYSTEM	Package B		REPAIR UNSCHEDULED		1430	SR Technics Switzerland
73288	8241-01; 8242; 8243; 8244;	EASA;FAA;CAAC;ANAC										
73288	8241-01; 8242; 8243; 8244;	EASA;FAA;CAAC;ANAC	12	21	26.10.1962	PW4 FIRE AND OVERHEAT DETECTION SYSTEM	Package A		CLEANING, INSPECTION AND TEST		1480	SR Technics Switzerland
73288	8241-01; 8242; 8243; 8244;	EASA;FAA;CAAC;ANAC	12	21	26.10.1962	PW4 FIRE AND OVERHEAT DETECTION SYSTEM	Package C		WELD-REPAIR CLAMP REPLACEMENT		1575	SR Technics Switzerland
129947	80168-1414	EASA;FAA;CAAC;ANAC	5	21	71-20-05	PW4 BARREL NUT, AFT MOUNT	Package A	CLN/INSP	CLEANING & INSPECTION		170	SR Technics Switzerland
129964	73182-624; 786376; ST2115	EASA;FAA;CAAC;ANAC										
129964	73182-624; 786376; ST2115	EASA;FAA;CAAC;ANAC	27	28	72-53-44	LOW PRESSURE TURBINE (LPT) - TURBINE TIEROD NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		80	SR Technics Switzerland
129964	73182-624; 786376; ST2115	EASA;FAA;CAAC;ANAC	27	28	72-53-44	LOW PRESSURE TURBINE (LPT) - TURBINE TIEROD NUT	Package B	1	RESTORE SILVER PLATE	PRICE PER UNIT	80	SR Technics Switzerland
130005	51A299; 51A306; 51A307; 5	EASA;FAA;CAAC;ANAC										
130005	51A299; 51A306; 51A307; 5	EASA;FAA;CAAC;ANAC	22	28	72-53-83	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE (LPT) - TIER	Package A	CLN/INSP	CLEANING AND INSPECTION		105	SR Technics Switzerland
130005	51A299; 51A306; 51A307; 5	EASA;FAA;CAAC;ANAC	22	28	72-53-83	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE (LPT) - TIER	Package B	1	RESTORE SILVER PLATE		115	SR Technics Switzerland
130101	212842		8	21	73-11-05	PISTON RELIEF VALVE	Package B		REWORK PISTON SEAT		305	SR Technics Switzerland
130101	212842	EASA;CAAC;TCCA;CAA UK	8	21	73-11-05	PISTON RELIEF VALVE	Package A	CLN/INSP	CLEANING & INSPECTION		220	SR Technics Switzerland
130632	310T4022-1; 310T4022-2; 310	T4022-3; 310T4022-4	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package E	02.Feb	BEARING HOLE REPAIR		860	SR Technics Switzerland
130632	310T4022-1; 310T4022-2; 310	T4022-3; 310T4022-4	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package F	02.Feb	SCRATCH AND GOUGE REPAIR		560	SR Technics Switzerland
130632	310T4022-1; 310T4022-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		270	SR Technics Switzerland
130632	310T4022-1; 310T4022-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package B	02.Jan	BEARING REPLACEMENT		695	SR Technics Switzerland
130632	310T4022-1; 310T4022-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package C	02.Jan	BUSHING REPLACEMENT		695	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
130632	310T4022-1; 310T4022-2; 3:	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - EVENER BAR ASSY - 94"	Package D	02.Feb	BUSHING HOLE REPAIR		1145	SR Technics Switzerland
130633	52R045; 52R052; 52R054; 7(	EASA;FAA;CAAC;ANAC										
130633	52R045; 52R052; 52R054; 7(	EASA;FAA;CAAC;ANAC	3	21	72-61-19	PW4 FACE (OIL) SEAL ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	350	SR Technics Switzerland
130633	52R045; 52R052; 52R054; 7(	EASA;FAA;CAAC;ANAC;CAA UK										
131637	212844	EASA;FAA;CAAC;ANAC	23	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94" - BODY RELIEF \	Package B		MASCHINE THE PISTON SEAT	ACCORDING CMM	855	SR Technics Switzerland
131669	221-0260-501; 221-0260-503;	221-0260-505; 221-0263-501; 221-0263-503;	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package SB02	PW4NAC 71-74	AFT ENGINE MOUNT INSPECTION		510	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING & INSPECTION		655	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK REPLACEMENT (1EA)	980	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINKS REPLACEMENT (2EA)	1440	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: BEAM ASSY REPLACEMENT	2340	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package G	OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEMBLY. EXCLUDED PIECE	PART REPAIRS	2635	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package SB00	PW4NAC 71-163	REPLACE ATTACHMENT HARDWARE WITH SERIALIZED PARTS	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
131669	221-0260-501; 221-0260-50	EASA;FAA;CAAC;ANAC	21	21	71-20-05	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package SB01	PW4NAC A71-149	INSPECTION AND REPLACEMENT OF BEAM ASSEMBLY	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
132300	38771; 791756	EASA;FAA;CAAC;ANAC										
132300	38771; 791756	EASA;FAA;CAAC;ANAC	24	21	79-10-14	CAP ASSY OIL TANK	Package B		REPLACE O-RING		465	SR Technics Switzerland
132301	51R062; 791755	EASA;FAA;CAAC;ANAC	7	28	72-61-00	PW4 VALVE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	400	SR Technics Switzerland
132301	51R062; 791755	EASA;FAA;CAAC;ANAC	7	28	72-61-00	PW4 VALVE ASSY	Package B		CHECK/REPLACE BUTTERFLY VALVE		165	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC										
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package A	CLN/INSP	CLEAN AND INSPECTION		1545	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK ASSY REPLACEMENT (1EA)	1640	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK ASSY REPLACEMENT (2EA)	3295	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: HANGER ASSY REPLACEMENT	3730	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package G	OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEMBLY. EXCLUDED PIECE	PART REPAIRS	4610	SR Technics Switzerland
132768	310T4020-14; 310T4020-16;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	AFT ENGINE MOUNT - ASSEMBLY - 94"	Package H		ASSEMBLY/DISASSEMBLY OF MOUNT LINK		4480	SR Technics Switzerland
132777	221-0245-501; 221-0245-503		26	21	71-20-04	FWD ENGINE MOUNT - LINK ASSY - 94"	Package F	5	SURFACE DAMAGE BLEND REPAIR		1280	SR Technics Switzerland
132777	221-0245-501; 221-0245-503		26	21	71-20-04	FWD ENGINE MOUNT - LINK ASSY - 94"	Package SB00	PW4NAC 71-86	LINK INSPECTION AND REPLACEMENT OF		3615	SR Technics Switzerland
132777	221-0245-501; 221-0245-50	EASA;FAA;CAAC;ANAC	26	21	71-20-04	FWD ENGINE MOUNT - LINK ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1150	SR Technics Switzerland
132777	221-0245-501; 221-0245-50	EASA;FAA;CAAC;ANAC	26	21	71-20-04	FWD ENGINE MOUNT - LINK ASSY - 94"	Package B	1	BEARING REPLACEMENT		2085	SR Technics Switzerland
132791	50P029; 50P109; 5255; 525!	EASA;FAA;CAAC;ANAC										
132791	50P029; 50P109; 5255; 525!	EASA;FAA;CAAC;ANAC	6	21	77-21-05	THERMOCOUPLE EEC	Package C	TEST	PRE TEST		430	SR Technics Switzerland
132791	50P029; 50P109; 5255; 525!	EASA;FAA;CAAC;ANAC	6	21	77-21-05	THERMOCOUPLE EEC	Package C	TEST	TEST		430	SR Technics Switzerland
132791	50P029; 50P109; 5255; 525!	EASA;FAA;CAAC;ANAC;CAA UK	6	21	77-21-05	THERMOCOUPLE EEC	Package D		OVERHAUL	for PN: 5255; 5255J; HAD18540	920	SR Technics Switzerland
132792	50J344; HAD18952	EASA;FAA;CAAC;ANAC	5	28	73-21-57	THERMOCOUPLE EEC	Package B		BENCHTEST		430	SR Technics Switzerland
132792	50J344; HAD18952	EASA;FAA;CAAC;ANAC	5	28	73-21-57	THERMOCOUPLE EEC	Package C		OVERHAUL		860	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC										
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package A	CLN/INSP	CLEANINGA ND INSPECTION		625	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package AA	29	BONDED STIFFENER REPLACEMENT REPAIR		805	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package AB	32	ACOUSTIC LINER SIDE EDGE DISBOUND REPAIR		545	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package AN	SPM	MARK PART BY MARKER		155	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package B	1	GRAPHITE ID REAR PANEL MINOR REPAIR		830	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package C	2	REPLACE WASHERS		895	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package D	3	REPLACE SEAL		815	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package E	4	REPAIR DAMAGED SEAL ENDS		560	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package F	5	REPAIR DELAMINATION AT THE CORNERS		805	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package H	7	SURFACE DAMAGE PATCH REPAIR		855	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package N	13	CERAMIC FABRIC PATCH REPAIR		830	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package SB00	PW4ENG 72-490	CONVERSION OF A PW4460 OR PW4460 (-3) OR PW4462 (-3)		845	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package SB00	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060,TO A PW4052(-3), PW4056(-3), OR PW4060(-3)		845	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package SB00	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		845	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package T	19	CUT SEAL REPAIR		260	SR Technics Switzerland
132802	50A508; 50A508-001; 50A6(	EASA;FAA;CAAC;ANAC	32	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 94"	Package W	22	NON ACOUSTIC LINER SEGMENT SEAL BONDING REPAIR		545	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC										
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		670	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package B	1	REPLACE WASHERS		1125	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package C	2	REPLACE SPLICE PLATE		505	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package D	3	REPLACE NUT PLATES		895	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package E	4	MINOR SURFACE DAMAGE REPAIR (EPOXY RESIN)		1140	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package F	5	PATCH REPAIR		1310	SR Technics Switzerland
132809	50G663; 50G680; 50G951; 5	EASA;FAA;CAAC;ANAC	30	28	72-33-82	FAN CASE - FAN EXIT INNER (BIFURCATION) FAIRING ASSEMBLY	Package J	10	SURFACE DAMAGE REPAIR (POLYURETHANE COAT)		545	SR Technics Switzerland
132810	53H073	EASA;FAA;CAAC;ANAC	5	21	72-35-00	PW4 BRACKET TO TCC VALVE ACTUATOR	Package B		REPLACE OR TIGHTEN RIVETS		80	SR Technics Switzerland
132812	50P046; 50P374-01; 50P422-01		25	28	72-54-24	TURBINE EXHAUST CASE - AVERAGE PRESSURE AND TEMPERATURE P	Package SB00	PW4ENG 77-16	MODIFICATION OF THE PROBES		700	SR Technics Switzerland
132812	50P046; 50P374-01; 50P422	EASA;FAA;CAAC;ANAC	25	28	72-54-24	TURBINE EXHAUST CASE - AVERAGE PRESSURE AND TEMPERATURE P	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
132812	50P046; 50P374-01; 50P422	EASA;FAA;CAAC;ANAC	25	28	72-54-24	TURBINE EXHAUST CASE - AVERAGE PRESSURE AND TEMPERATURE P	Package B	1	REFACE CONICAL CONNECTOR SEAT		740	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
132812	50P046; 50P374-01; 50P422	EASA;FAA;CAAC;ANAC	25	28	72-54-24	TURBINE EXHAUST CASE - AVERAGE PRESSURE AND TEMPERATURE P	Package C	INSP/CHECK-05	FLOW AND PRESSURE CHECK		200	SR Technics Switzerland
132813	50P048	EASA;FAA;CAAC;ANAC	20	28	72-54-25	TURBINE EXHAUST CASE - THERMOCOUPLE HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		395	SR Technics Switzerland
133447	50P392; HAD20899; HAD21	EASA;FAA;ANAC	13	21	77-21-11	PROBE-THERMOCOUPLE T4.95	Package D		REPAIR		865	SR Technics Switzerland
133447	50P392; HAD20899; HAD21	EASA;FAA;CAAC;ANAC	13	21	77-21-11	PROBE-THERMOCOUPLE T4.95	Package C		BENCH TEST	TESTING AND FAULT ISOLATION	750	SR Technics Switzerland
133447	50P392; HAD20899; HAD21	EASA;FAA;CAAC;ANAC	13	21	77-21-11	PROBE-THERMOCOUPLE T4.95	Package E		OVERHAUL		865	SR Technics Switzerland
133455	221-4027-505; 221-4027-51	EASA;FAA;CAAC;ANAC										
133455	221-4027-505; 221-4027-51	EASA;FAA;CAAC;ANAC	13	21	78-10-03	PLUG EXHAUST	Package A	CLN/INSP	CLEANING AND INSPECTION		2320	SR Technics Switzerland
133455	221-4027-505; 221-4027-51	EASA;FAA;CAAC;ANAC	13	21	78-10-03	PLUG EXHAUST	Package B	1	WELD REPAIR OF CRACKS IN THE PERFORATED OUTER SKIN		2645	SR Technics Switzerland
133455	221-4027-505; 221-4027-51	EASA;FAA;CAAC;ANAC	13	21	78-10-03	PLUG EXHAUST	Package C	10	WELD CONE		2645	SR Technics Switzerland
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC										
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING & INSPECTION		380	SR Technics Switzerland
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: BEARING HOUSING REPLACEMENT	745	SR Technics Switzerland
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK ASSY REPLACEMENT (1EA)	1830	SR Technics Switzerland
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: FITTING ASSY REPLACEMENT	3200	SR Technics Switzerland
133456	310T4020-10; 310T4020-17;	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package G	OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS		3300	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC										
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1005	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package B	01.Jan	RUB STRIP AND SEAL MEMBER REPLACEMENT		3260	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package J	02.01.2009	REPAIR OF HOLES OR PUNCTURES UP TO ONE INCH MAXIMUM LENGTH OF SOLID SKIN		1140	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package K	02.01.2010	REPAIR OF CRACKS UP TO SIX INCH LENGTH IN SOLID SKIN, NOT ADJACENT TO PANEL WELDS		1605	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package O	02.01.2014	REPAIR OF LONGITUDINAL CRACKS IN THE OUTER SLEEVE		1435	SR Technics Switzerland
133457	314T3310-1; 314T3310-10;	EASA;FAA;CAAC;ANAC	20	35	78-11-06	PRIMARY EXHAUST SLEEVE ASSEMBLY	Package P		DISASSEMBLY/ASSEMBLY INNER/OUTER SLEEVE		1640	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. E)	EXAMPLE: BEARING THRUST OR HOUSING OF	5180	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package G	OVERHAUL	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		7005	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package SB00	711000-73-14	INTRODUCTION OF NEW MAIN STAGE BEARINGS	IN CONJUNCTION WITH HEAVY OR OV	135	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package SB01	711000-73-15	INTRODUCTION OF NEW FILTER COVER LOCKING NUTS	IN CONJUNCTION WITH LIGHT	135	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package SB02	711000-73-16	REPLACEMENT OF STATIONARY SHAFT SEAL PREFORMED PACKING	IN CONJUNCTION WITH LIGHT	135	SR Technics Switzerland
133477	825501-10; 825501-11; 825501-12; 825501-8; 825501-9		25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package SB03	711000-73-13	INTRODUCTION OF ALTERNATIVE O-RING PACKINGS	IN CONJUNCTION WITH HEAVY OR OV	135	SR Technics Switzerland
133477	825501-10; 825501-11; 825	EASA;FAA;ANAC;CAA UK	25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	3010	SR Technics Switzerland
133477	825501-10; 825501-11; 825	EASA;FAA;ANAC;CAA UK	25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package C		CRACK INSPECTION OF GEAR HOUSING		125	SR Technics Switzerland
133477	825501-10; 825501-11; 825	EASA;FAA;ANAC;CAA UK	25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. E)	EXAMPLE: BODY RELIEF VALVE OR PISTON RE	2605	SR Technics Switzerland
133477	825501-10; 825501-11; 825	EASA;FAA;ANAC;CAA UK	25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. E)	EXAMPLE: SHAFT DRIVE MAIN REPLACEMEN	3575	SR Technics Switzerland
133477	825501-10; 825501-11; 825	EASA;FAA;CAAC;ANAC;CAA UK	25	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - 94"	Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	125	SR Technics Switzerland
133506	50U391; 51T254; 53T903; H	EASA;FAA;CAAC;ANAC										
133506	50U391; 51T254; 53T903; H	EASA;FAA;CAAC;ANAC	11	21	73-21-47	PROBE-EEC FUEL OIL TEMP	Package A		BENCH TEST		675	SR Technics Switzerland
133506	50U391; 51T254; 53T903; H	EASA;FAA;CAAC;ANAC	11	21	73-21-47	PROBE-EEC FUEL OIL TEMP	Package G		OVERHAUL		1850	SR Technics Switzerland
133511	1A6716; HAD18286	EASA;FAA;CAAC;ANAC										
133511	1A6716; HAD18286	EASA;FAA;CAAC;ANAC	6	21	72-21-59	THERMOCOUPLE (DOT 3)	Package B		OVERHAUL		860	SR Technics Switzerland
133512	221-0051-511; 221-0051-517; 221-0051-519; 221-0051-521; 221-0051-523;		23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package V		REPLACE DEFECTIVE PARTS REFER TO IPL		295	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		2320	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package B	1	INCONEL SKIN CRACK		3010	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package C	2	INCONEL SKIN TO CORE DELAMINATION		4850	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package D	3	INCONEL PANEL SKIN REPAIR		3505	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package J	9	NOZZELE OUTER BARREL TITANIUM SKIN		3825	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package L	11	BARREL ALUMINUM SKIN FLUSH PATCH		4090	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package O	14	NOZZEL BULKHEAD RING REPLACEMENT		11455	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package P	15	PATCH SEAL SPRING DAMAGE TO AFT UPPER OUTER BARREL		8380	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package T	INSP	CHECK AND REPLACE STOP-NUTS	ACC. 78-10-04-CHECK	3620	SR Technics Switzerland
133512	221-0051-511; 221-0051-51	EASA;FAA;CAAC;ANAC	23	35	78-10-04	EXHAUST NOZZLE ASSEMBLY - 94"	Package U	INSP	REAPPLY DRY FILM LUBRICANT	ACC. 78-10-04-CHECK	2100	SR Technics Switzerland
133513	50A680; 50A775; 51A022	EASA;FAA;CAAC;ANAC										
133513	50A680; 50A775; 51A022	EASA;FAA;CAAC;ANAC	12	21	73-21-50	TRANSDUCER-ASSY OF MOTION 94''	Package SB00	PW4ENG 73-88	TRANSDUCER, N1 SPEED, IMPROVED INSTALLATION CONFIGURATION		405	SR Technics Switzerland
133513	50A680; 50A775; 51A022	EASA;FAA;CAAC;ANAC	12	21	73-21-50	TRANSDUCER-ASSY OF MOTION 94''	Package SB01	PW4ENG 73-152	TRANSDUCER, N1 SPEED, REPAIR AND UPGRADE FACILITY EEC		130	SR Technics Switzerland
133514	221-4004-505		23	21	71-20-04	FWD ENGINE MOUNT - CROSSBEAM - 94"	Package D	3	BUSHING REPLACEMENT		2190	SR Technics Switzerland
133514	221-4004-505		23	21	71-20-04	FWD ENGINE MOUNT - CROSSBEAM - 94"	Package F	5	BLEND NICKS, GOUGES AND SCRATCHES		530	SR Technics Switzerland
133514	221-4004-505	EASA;FAA;CAAC;ANAC	23	21	71-20-04	FWD ENGINE MOUNT - CROSSBEAM - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
133519	22640-005; 51U552; 53T424	EASA;FAA;CAAC;ANAC										
133519	22640-005; 51U552; 53T424	EASA;FAA;CAAC;ANAC	13	21	77-24-03	THERMOCOUPLE IMMERSION	Package E		MEDIUM		945	SR Technics Switzerland
133519	22640-005; 51U552; 53T424	EASA;FAA;CAAC;ANAC	13	21	77-24-03	THERMOCOUPLE IMMERSION	Package G		OVERHAUL		1885	SR Technics Switzerland
133519	22640-005; 51U552; 53T424	EASA;FAA;CAAC;ANAC;CAA UK	13	21	77-24-03	THERMOCOUPLE IMMERSION	Package B		BENCH TEST		730	SR Technics Switzerland
133525	221-4006-501; 221-4006-503		23	21	71-20-04	FWD ENGINE MOUNT - MAIN BEAM ASSY - 94"	Package F	5	SURFACE DAMAGE BLEND REPAIR		1025	SR Technics Switzerland
133525	221-4006-501; 221-4006-503		23	21	71-20-04	FWD ENGINE MOUNT - MAIN BEAM ASSY - 94"	Package G	6	SHEAR PIN BUSHING REPLACEMENT		2180	SR Technics Switzerland
133525	221-4006-501; 221-4006-50	EASA;FAA;CAAC;ANAC	23	21	71-20-04	FWD ENGINE MOUNT - MAIN BEAM ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1280	SR Technics Switzerland
133525	221-4006-501; 221-4006-50	EASA;FAA;CAAC;ANAC;DUAL RELEASE EASA/T	23	21	71-20-04	FWD ENGINE MOUNT - MAIN BEAM ASSY - 94"	Package C	2	CROSS BEAM BOLT BUSHING REPLACEMENT		900	SR Technics Switzerland
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC	5	21	26.11.1966	PW4 FIRE/OVERHEAT DETECTORS	Package B	TEST	PRE TEST		415	SR Technics Switzerland
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC	5	21	26.11.1966	PW4 FIRE/OVERHEAT DETECTORS	Package C	TEST	TEST		415	SR Technics Switzerland
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC	5	21	26.11.1966	PW4 FIRE/OVERHEAT DETECTORS	Package D		WELD-REPAIR OF CRACKED PART		165	SR Technics Switzerland
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC	5	21	26.11.1966	PW4 FIRE/OVERHEAT DETECTORS	Package E		REPLACEMENT REPAIR OF DAMAGED PART		155	SR Technics Switzerland
134047	472565; 472566; 472567; 47	EASA;FAA;CAAC;ANAC	5	21	26.11.1966	PW4 FIRE/OVERHEAT DETECTORS	Package F		OVERHAUL		685	SR Technics Switzerland
134178	51U714; 52U362; 54T734		21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: REAR MOUNT SET REPLACEMENT	4545	SR Technics Switzerland
134178	51U714; 52U362; 54T734		21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package G	OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS		4635	SR Technics Switzerland
134178	51U714; 52U362; 54T734		21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package SB00	PW4G-100-71-7	IDENTIFICATION OF THE MOUNT ASSEMBLIES WITH A PART NUMBER	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	150	SR Technics Switzerland
134178	51U714; 52U362; 54T734		21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package SB01	PW4G-100-71-8	INTRODUCTION OF NEW ENGINE MOUNT HARDWARE WITH ADDITIOI	IN CONJUNCTION WITH PACKAGE HEAVY OR	150	SR Technics Switzerland
134178	51U714; 52U362; 54T734	EASA;FAA;CAAC;ANAC	21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package C		PREINSPECTION OF FORWARD ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	540	SR Technics Switzerland
134178	51U714; 52U362; 54T734	EASA;FAA;CAAC;ANAC	21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE	PART REPAIRS	1350	SR Technics Switzerland
134178	51U714; 52U362; 54T734	EASA;FAA;CAAC;ANAC	21	21	71-22-00	AFT ENGINE MOUNT - ASSEMBLY - 100"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK ASSY REPLACEMENT (2EA)	2465	SR Technics Switzerland
134180	75A001-11; 75A001-21		25	21	78-11-12	PLUG ASSY OF EXHAUST - 100"	Package N	13	REMOVE BLIND RIVETS AND INSTALL SOLID RIVETS		1285	SR Technics Switzerland
134180	75A001-11; 75A001-21		25	21	78-11-12	PLUG ASSY OF EXHAUST - 100"	Package O	14	REMOVE AND REPL. BOLT CATCHER		1285	SR Technics Switzerland
134180	75A001-11; 75A001-21		25	21	78-11-12	PLUG ASSY OF EXHAUST - 100"	Package SB00	PW4G-100-78-96	REPLACE END CAP ATTACHMENT RIVETS TO IMPROVE DURABILITY	PART 001	1285	SR Technics Switzerland
134180	75A001-11; 75A001-21	EASA;FAA;CAAC;ANAC	25	21	78-11-12	PLUG ASSY OF EXHAUST - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		445	SR Technics Switzerland
134180	75A001-11; 75A001-21	EASA;FAA;CAAC;ANAC	25	21	78-11-12	PLUG ASSY OF EXHAUST - 100"	Package L	11	REMOVE AND REPL. PLUG END CAP		920	SR Technics Switzerland
135888	ST1264-05; ST5124-05	EASA;FAA;CAAC;ANAC	7	28	72-34-00	PW4 BOLT FLANGE E	Package A	CLN/INSP	CLEANING & INSPECTION		90	SR Technics Switzerland
135888	ST1264-05; ST5124-05	EASA;FAA;CAAC;ANAC	7	28	72-34-00	PW4 BOLT FLANGE E	Package A	INSP-02	CHECK-02 AND REWORK OF FLANGE BOLTS		90	SR Technics Switzerland
135898	51T379; 51T383; 51T387; 51	EASA;FAA;CAAC;ANAC										
135898	51T379; 51T383; 51T387; 51	EASA;FAA;CAAC;ANAC	27	21	72-41-89	DIFFUSER AND COMBUSTOR - FUEL SUPPLY TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		335	SR Technics Switzerland
135898	51T379; 51T383; 51T387; 51	EASA;FAA;CAAC;ANAC	27	21	72-41-89	DIFFUSER AND COMBUSTOR - FUEL SUPPLY TUBE ASSEMBLIES	Package A	CLN/INSP	PRESSURE TEST BY EACH OVERHAUL		335	SR Technics Switzerland
135898	51T379; 51T383; 51T387; 51	EASA;FAA;CAAC;ANAC	27	21	72-41-89	DIFFUSER AND COMBUSTOR - FUEL SUPPLY TUBE ASSEMBLIES	Package B	1	REPLACE ADAPTER - FUEL SUPPLY TUBE ASSEMBLIES		670	SR Technics Switzerland
135898	51T379; 51T383; 51T387; 51	EASA;FAA;CAAC;ANAC	27	21	72-41-89	DIFFUSER AND COMBUSTOR - FUEL SUPPLY TUBE ASSEMBLIES	Package C	2	REPLACE FERRULE - FUEL SUPPLY TUBE ASSEMBLIES		670	SR Technics Switzerland
135900	1A4447		27	28	72-35-78	HIGH PRESSURE COMPRESSOR (HPC) - ROD END BEARINGS	Package B	1	BEARING REPLACEMENT		385	SR Technics Switzerland
135900	1A4447	EASA;FAA;CAAC;ANAC	27	28	72-35-78	HIGH PRESSURE COMPRESSOR (HPC) - ROD END BEARINGS	Package A	CLN/INSP	CLEANING AND INSPECTION		210	SR Technics Switzerland
135901	50A176; 50A726-01	EASA;FAA;CAAC;ANAC;CAA UK	26	28	72-51-99	TURBINE NOZZLE - TURBINE NOZZLE MISCELLANEOUS PARTS - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		245	SR Technics Switzerland
135901	50A176; 50A726-01	EASA;FAA;CAAC;ANAC;CAA UK	26	28	72-51-99	TURBINE NOZZLE - TURBINE NOZZLE MISCELLANEOUS PARTS - 94"	Package B	1	BORESCOPE PLUG PIN REPLACEMENT		1010	SR Technics Switzerland
135902	50A193; 50A656		29	28	72-54-85	TURBINE EXHAUST CASE - NO. 4 BEARING (COVER) SHIELD	Package C	1	CRACK WELD REPAIR (FOR CRACKS MORE THAN 0.125 INCH (3.175 MM)		780	SR Technics Switzerland
135902	50A193; 50A656	EASA;FAA;CAAC;ANAC	29	28	72-54-85	TURBINE EXHAUST CASE - NO. 4 BEARING (COVER) SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		415	SR Technics Switzerland
135902	50A193; 50A656	EASA;FAA;CAAC;ANAC;CAA UK	29	28	72-54-85	TURBINE EXHAUST CASE - NO. 4 BEARING (COVER) SHIELD	Package B	1	CRACK BLEND REPAIR (FOR CRACKS 0.125 INCH (3.175 MM) OR LESS		200	SR Technics Switzerland
135905	50G547; 52G153; 52G409		28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package D	3	REPLACE THE BUSHING		370	SR Technics Switzerland
135905	50G547; 52G153; 52G409		28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package SB00	PW4ENG 72-501	REPLACEMENT OF THE BRACKET ASSEMBLY FOR IMPROVED BOLT CLEARANCE		630	SR Technics Switzerland
135905	50G547; 52G153; 52G409		28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package SB01	PW4ENG 72-692	MODIFICATION OF, TO ELIMINATE AN INTERFERENCE FIT BETWEEN THE BRACKET AND THE INTERMEDIATE CASE		790	SR Technics Switzerland
135905	50G547; 52G153; 52G409	EASA;FAA;CAAC;ANAC	28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package A	CLN/INSP	CLEANING AND INSPECTION		380	SR Technics Switzerland
135905	50G547; 52G153; 52G409	EASA;FAA;CAAC;ANAC	28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package B	1	NICKEL PLATE THE PIN DIAMETER		1125	SR Technics Switzerland
135905	50G547; 52G153; 52G409	EASA;FAA;CAAC;ANAC	28	28	72-34-52	INTERMEDIATE CASE - ANGLE GEARBOX (SUPPORT) BRACKET ASSEMI	Package C	2	REPAIR THE HOLE		1465	SR Technics Switzerland
135909	50J206; 50J393; 50J407; 50J	EASA;FAA;CAAC;ANAC										
135909	50J206; 50J393; 50J407; 50J	EASA;FAA;CAAC;ANAC	26	21	72-41-37	DIFFUSER AND COMBUSTOR - DIFFUSER & COMBUSTOR - TUBE SEALI	Package A	CLN/INSP	CLEANING AND INSPECTION		380	SR Technics Switzerland
135909	50J206; 50J393; 50J407; 50J	EASA;FAA;CAAC;ANAC	26	21	72-41-37	DIFFUSER AND COMBUSTOR - DIFFUSER & COMBUSTOR - TUBE SEALI	Package B	1	NICKEL PLATE REPAIR INNER DIAMETER		2275	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package D	3	FRONT FLANGE FACE PLASMA SPRAY REPAIR		5230	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package E	4	SNAP DIAMETER PLASMA SPRAY REPAIR		4055	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package F	5	RESTORE KNIFE-EDGE SEAL PLASMA COATING		4055	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package G	6	REPLACE FLANGE SEALS		960	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package P	15	SHOTPEEN REPAIR		2200	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package Q	16	KNIFE EDGE THICK COATING		2290	SR Technics Switzerland
135911	50N286; 50N486-01; 50N666-01		30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package SB00	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1300	SR Technics Switzerland
135911	50N286; 50N486-01; 50N66	EASA;FAA;CAAC;ANAC	30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		3800	SR Technics Switzerland
135911	50N286; 50N486-01; 50N66	EASA;FAA;CAAC;ANAC	30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package B	1	KNIFE-EDGE SEALS BLEND REPAIR		675	SR Technics Switzerland
135911	50N286; 50N486-01; 50N66	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 94"	Package C	2	SURFACE DAMAGE BLEND REPAIR		1170	SR Technics Switzerland
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC										
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC	28	28	72-41-93	DIFFUSER AND COMBUSTOR - GEARBOX HEAT SHIELD ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC	28	28	72-41-93	DIFFUSER AND COMBUSTOR - GEARBOX HEAT SHIELD ASSEMBLIES	Package B	1	REPAIR THE HEAT SHIELD WITH A PATCH		390	SR Technics Switzerland
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC	28	28	72-41-93	DIFFUSER AND COMBUSTOR - GEARBOX HEAT SHIELD ASSEMBLIES	Package C	2	HEAT SHIELD PATCH REPAIR		390	SR Technics Switzerland
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC	28	28	72-41-93	DIFFUSER AND COMBUSTOR - GEARBOX HEAT SHIELD ASSEMBLIES	Package D	3	NO. 3 BEARING OIL VENT TUBE HOLE CRACK WELD REPAIR		560	SR Technics Switzerland
135914	52T189-01; 52T190-01; 53T	EASA;FAA;CAAC;ANAC	28	28	72-41-93	DIFFUSER AND COMBUSTOR - GEARBOX HEAT SHIELD ASSEMBLIES	Package E	4	BOLT HOLE PATCH REPAIR		560	SR Technics Switzerland
135917	50T067		24	28	72-61-75	MAIN GEARBOX - OIL TANK SUMP ASSEMBLY	Package C	2	WELD REPAIR OF CRACKS		635	SR Technics Switzerland
135917	50T067	EASA;FAA;CAAC;ANAC	24	28	72-61-75	MAIN GEARBOX - OIL TANK SUMP ASSEMBLY	Package B	1	REPAIR OF SURFACE DAMAGE		350	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package I	13	BLEND LOCK SCREW DAMAGE IN BLADE SLOTS		2265	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package J	14	BLEND REPAIR SURFACE DAMAGE		1555	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package K	15	BLEND REPAIR DAMAGED KNIFE-EDGE SEALS		1540	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB00	AD 2005-25-09	FPI LIFE-LIMITED PART, HPC REAR DRUM		385	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB01	PW4ENG 72-565	BLADES, 14TH AND 15TH STAGE - MODIFICATION TO PROVIDE IMPROVED PLATFORM CLEARANCE AND BLADE LOCK		5630	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H	973-01; 54H803-001; 54H803-002; 54H803-01	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB03	PW4G-100-72-186	FPI OF THE 13TH, 14TH, AND 15TH STAGE BLADE LOADING AND LOCKI	AD 2012-18-17	565	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
135931	50S813-01; 53H973-001; 53H973-01; 54H803-001; 54H803-002; 54H803-01		47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB04	PW4ENG 72-796	FPI OF THE 13TH, 14TH, AND 15TH STAGE BLADE LOADING AND LOCKI	AD 2012-18-17	565	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H973-01; 54H803-001; 54H803-002; 54H803-01		47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB05	PW4ENG 72-816	SEAL 13TH, 14TH AND 15TH STAGE - REPLACEMENT OF AND INTRODU	TO IMPROVE REAR DRUM ROTOR DURABILIT	990	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H973-01; 54H803-001; 54H803-002; 54H803-01		47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB05	PW4G-100-72-240	REPLACEMENT, INTRODUCTION OF A NEW SHOT PEEN SPECIFICATION,	TO IMPROVE REAR DRUM ROTOR DURABILI	990	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53H973-01; 54H803-001; 54H803-002; 54H803-01		47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package SB06	PW4G-100-72-8	BLADES, 14TH AND 15TH STAGE - MODIFICATION TO PROVIDE IMPROVED	PLATFORM CLEARANCE AND BLADE LOCK	5630	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AJ	35	SURFACE DAMAGE BLEND REPAIR		1490	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package AK	36	BLEND REPAIR LOADING AND LOCKING SLOTS		905	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package B	6	RESTORE KNIFE-EDGE SEAL PLASMA COAT		8455	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package C	4	SHOTPEEN BLADE SLOTS		1490	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package D	5	BLEND REPAIR TANGENTIAL SLOT RIM RAILS		1705	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package G	9	PLASMA SPRAY REPAIR REAR DRUM REAR FLANGE SNAP DIAMETER		5630	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package H	12	PLASMA SPRAY BRUSH SEAL LAND		5440	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC;CAA UK	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package A	CLN/INSP	CLEANING AND INSPECTION		2605	SR Technics Switzerland
135931	50S813-01; 53H973-001; 53	EASA;FAA;CAAC;ANAC;CAA UK	47	35	72-35-10	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (REAR) DISK ASS	Package F	8	PLASMA SPRAY REPAIR REAR DRUM FRONT FLANGE SNAP DIAMETER		5630	SR Technics Switzerland
135938	51T430; 52U565-01	EASA;FAA;CAAC;ANAC	6	28	72-61-99	MOUNT IGNITION EXCITER	Package A	CLN/INSP	CLEANING AND INSPECTION		520	SR Technics Switzerland
135938	51T430; 52U565-01	EASA;FAA;CAAC;ANAC	6	28	72-61-99	MOUNT IGNITION EXCITER	Package B	SPM	REPLACE MOUNT RESILIENT	SPM 70-43-00 RIVETING	615	SR Technics Switzerland
135955	50A022; 50A092; 50A093; 5	EASA;FAA;CAAC;ANAC										
135955	50A022; 50A092; 50A093; 5	EASA;FAA;CAAC;ANAC	26	28	72-32-02	LPC/LPT COUPLING - NO. 1.5 ROLLER BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		835	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package B	1	REPLACE LOCATING PIN		675	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package C	2	REPLACE HELICAL COIL INSERTS		715	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package D	3	APPLY ANODIZE TOUCH-UP		490	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package E	4	REPLACE THE BUSHINGS IN THE MOUNT CLEVISES		3155	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package F	5	REPAIR THE FUEL PUMP BEARING HOUSING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package G	6	REPAIR THE REAR HYDR. PUMP BEARING HOUSING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package H	7	REPAIR THE FUEL PUMP GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package I	8	REPAIR THE STARTER DRIVE GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package J	9	REPAIR THE STARTER DRIVE GEARSHAFT BEARING HOUSING WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package K	10	REPAIR THE DRIVESHAFT HOUSING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package L	11	REPAIR THE DRIVESHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package M	12	REPAIR THE IDG GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package N	13	REPAIR THE IDG COVER BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package O	14	REPAIR THE IDG BEARING HOUSING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package P	15	REPAIR THE IDLER SHAFT FRONT BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package Q	16	REPAIR THE IDLER REAR FRONT BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package R	17	REPAIR THE DEOILER BEARING HOUSING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package S	18	REPAIR THE DEOILER GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package SB00	79-56	INCORPORATION OF AN OIL FILLER NECK BRACE		155	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package SB01	PW4ENG 72-802	MODIFICATION AND REPLACEMENT TO IMPROVE DURABILITY		1095	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package SB02	PW4ENG 72-832	GEARSHAFT SCREWS - REPLACEMENT OF, TO IMPROVE SCREW RETENTION		185	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package T	19	REPAIR THE DEOILER CARBON SEAL BORE WITH A BUSHING		2880	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package U	20	REPAIR THE OIL FILTER TRANSFER TUBE HOLES WITH BUSHINGS		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package V	21	REPAIR THE OIL TANK BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package W	22	REPAIR THE SCAVENGE PUMP GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package X	23	REPAIR THE SCAV. PUMP DRIVE GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package Y	24	REPAIR THE EEC OIL NOZZLE FRONT BORE WITH A BUSHING		1835	SR Technics Switzerland
135956	57R000-006; 57R000-008; 57R000-010; 57R000-012; 70R527; 70R900-04; 7		33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package Z	25	REPAIR THE EEC HOUSING BORE WITH A BUSHING		2485	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		2310	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AA	26	REPAIR THE IDG GEARSHAFT FRONT BORE WITH A BUSHING		2805	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AB	27	REPAIR THE SCAV. PUMP DR. GEARS. BEARING HOUS.BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AC	28	REPAIR THE EEC OIL NOZZLE BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AH	33	REPAIR THE GEARBOX CENTER MOUNT BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AI	34	REPAIR THE SCAV. PUMP GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AJ	35	REPAIR THE SCAV. PUMP DRIVE GEARSHAFT BEARING BORE WITH A BUSHING		2580	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AK	36	INSTALL GEARBOX HOUSING ON MACHINE FIXTURE		80	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AN	41	STUD HOLE THREAD DAMAGE HELICAL COIL INSERT REPAIR		1205	SR Technics Switzerland
135956	57R000-006; 57R000-008; 5	EASA;FAA;CAAC;ANAC;CAA UK	33	28	72-61-10	MAIN GEARBOX - GEARBOX HOUSING ASSEMBLY	Package AL	37	STUD AND LOCK RING REPLACEMENT		2745	SR Technics Switzerland
135966	50A593		32	28	72-32-80	LPC/LPT COUPLING - TURBINE SHAFT (COUPLING RETAINING) NUT	Package B	1	ANTIGALLANT REPLACEMENT		1745	SR Technics Switzerland
135966	50A593		32	28	72-32-80	LPC/LPT COUPLING - TURBINE SHAFT (COUPLING RETAINING) NUT	Package C	2	RESTORE CORROSION PREVENTIVE VARNISH		520	SR Technics Switzerland
135966	50A593		32	28	72-32-80	LPC/LPT COUPLING - TURBINE SHAFT (COUPLING RETAINING) NUT	Package D	3	CHROME PLATE REPLACEMENT		1460	SR Technics Switzerland
135966	50A593		32	28	72-32-80	LPC/LPT COUPLING - TURBINE SHAFT (COUPLING RETAINING) NUT	Package E	4	SURFACE DAMAGE BLEND REPAIR		825	SR Technics Switzerland
135966	50A593	EASA;FAA;CAAC;ANAC	32	28	72-32-80	LPC/LPT COUPLING - TURBINE SHAFT (COUPLING RETAINING) NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		605	SR Technics Switzerland
136090	70R106; 70R672; 70R682		27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package E	4	NICKEL PLATE THE OUTSIDE BORE	FOR SHOP VISITS ONLY	640	SR Technics Switzerland
136090	70R106; 70R672; 70R682		27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package F	5	NICKEL PLATE THE OD	FOR SHOP VISITS ONLY	695	SR Technics Switzerland
136090	70R106; 70R672; 70R682		27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package G	6	REPAIR THE FRONT ID WITH A BUSHING	FOR SHOP VISITS ONLY	630	SR Technics Switzerland
136090	70R106; 70R672; 70R682		27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package H	7	REPAIR THE REAR ID WITH A BUSHING	FOR SHOP VISITS ONLY	630	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
136090	70R106; 70R672; 70R682		27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package SB00	40	GEARSHAFT SCREWS - REPLACEMENT OF, TO IMPROVE SCREW RETEN	FOR SHOP VISITS ONLY	185	SR Technics Switzerland
136090	70R106; 70R672; 70R682	EASA;FAA;CAAC;ANAC	27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package B	1	REPLACE HELICAL COIL INSERTS	FOR SHOP VISITS ONLY	490	SR Technics Switzerland
136090	70R106; 70R672; 70R682	EASA;FAA;CAAC;ANAC	27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package C	2	ANODIZE TOUCH-UP	FOR SHOP VISITS ONLY	275	SR Technics Switzerland
136090	70R106; 70R672; 70R682	EASA;FAA;CAAC;ANAC	27	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package D	3	NICKEL PLATE THE BEARING JOURNAL	FOR SHOP VISITS ONLY	640	SR Technics Switzerland
136091	70R105		19	28	72-61-12	MAIN GEARBOX - GEARBOX (DEOILER) BEARING HOUSING ASSEMBLY	Package C	2	REPLACE HELICAL COIL INSERTS		320	SR Technics Switzerland
136091	70R105		19	28	72-61-12	MAIN GEARBOX - GEARBOX (DEOILER) BEARING HOUSING ASSEMBLY	Package D	3	NICKEL PLATE THE OD		1225	SR Technics Switzerland
136091	70R105		19	28	72-61-12	MAIN GEARBOX - GEARBOX (DEOILER) BEARING HOUSING ASSEMBLY	Package E	4	REPAIR THE SMALL ID WITH A BUSHING		880	SR Technics Switzerland
136091	70R105	EASA;FAA;CAAC;ANAC	19	28	72-61-12	MAIN GEARBOX - GEARBOX (DEOILER) BEARING HOUSING ASSEMBLY	Package B	1	ANODIZE TOUCH UP		265	SR Technics Switzerland
136092	70R050	EASA;FAA;CAAC;ANAC	25	21	72-61-57	MAIN GEARBOX - GEARBOX DRIVESHAFT PRESSURE TUBE ASSEMBLY	Package B	1	REPLACE ANTIGALLANT		600	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package C	2	SURFACE DAMAGE BLEND REPAIR		525	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package C	10	SURFACE DAMAGE BLEND REPAIR		525	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package D	3	REPLACE HELICAL COIL INSERTS		550	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package E	4	NICKEL PLATE REPAIR THE REAR FACE		1250	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package F	5	NICKEL PLATE REPAIR THE REAR ID		1250	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package G	6	NICKEL PLATE REPAIR THE FRONT FACE		1250	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package H	7	NICKEL PLATE REPAIR THE FRONT OD		1250	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package I	8	REAR BEARING JOURNAL BUSHING REPAIR		3105	SR Technics Switzerland
136094	50G003		25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package J	9	FRONT BEARING JOURNAL BUSHING REPAIR		2350	SR Technics Switzerland
136094	50G003	EASA;FAA;CAAC;ANAC	25	28	72-62-12	ANGLE GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package B	1	ANODIZE TOUCH-UP		165	SR Technics Switzerland
137318	50A083CL1; 50A083CL10; 5(	EASA;FAA;CAAC;ANAC										
137318	50A083CL1; 50A083CL10; 5(	EASA;FAA;CAAC;ANAC	27	28	72-53-81	LOW PRESSURE TURBINE (LPT) - TURBINE SHAFT SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		200	SR Technics Switzerland
137318	50A083CL1; 50A083CL10; 5(	EASA;FAA;CAAC;ANAC	27	28	72-53-81	LOW PRESSURE TURBINE (LPT) - TURBINE SHAFT SPACER	Package B	1	MACHINE SPACER TO CHANGE CLASS		605	SR Technics Switzerland
137362	1A4953; 1A4954; 1A4955; 1	EASA;FAA;CAAC;ANAC										
137362	1A4953; 1A4954; 1A4955; 1	EASA;FAA;CAAC;ANAC	27	28	72-31-13	LOW PRESSURE COMPRESSOR (LPC) - TIEROD NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		65	SR Technics Switzerland
137362	1A4953; 1A4954; 1A4955; 1	EASA;FAA;CAAC;ANAC	27	28	72-31-13	LOW PRESSURE COMPRESSOR (LPC) - TIEROD NUT	Package B	1	RESTORE ANTIGALLING COMPOUND		135	SR Technics Switzerland
137363	50A026		28	28	72-35-95	HIGH PRESSURE COMPRESSOR (HPC) - NO. 2 BEARING RETAINING NU	Package B	1	RESTORE ANTIGALLANT		470	SR Technics Switzerland
137363	50A026	EASA;FAA;CAAC;ANAC	28	28	72-35-95	HIGH PRESSURE COMPRESSOR (HPC) - NO. 2 BEARING RETAINING NU	Package A	CLN/INSP	CLEANING AND INSPECTION		525	SR Technics Switzerland
137365	50A349; 50A653	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 BRACKET, ASSY OF TRANSDUCER	Package A	CLN/INSP	CLEANING &INSPECTION		220	SR Technics Switzerland
137365	50A349; 50A653	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 BRACKET, ASSY OF TRANSDUCER	Package B		DOWEL PIN REPLACEMENT		685	SR Technics Switzerland
137366	50A433; 51A312	EASA;FAA;CAAC;ANAC										
137366	50A433; 51A312	EASA;FAA;CAAC;ANAC	20	28	72-53-82	LOW PRESSURE TURBINE (LPT) - TURBINE (SHAFT) TIEROD	Package A	CLN/INSP	CLEANING AND INSPECTION		90	SR Technics Switzerland
137367	50B040		31	28	72-31-15	LOW PRESSURE COMPRESSOR (LPC) - BEARING (INNER RACE) RETAINI	Package B	1	REPLACE SILVER PLATE	INCL. CLEANING AND INSPECTION	1545	SR Technics Switzerland
137367	50B040	EASA;FAA;CAAC;ANAC	31	28	72-31-15	LOW PRESSURE COMPRESSOR (LPC) - BEARING (INNER RACE) RETAINI	Package A	CLN/INSP	CLEANING AND INSPECTION		815	SR Technics Switzerland
137368	50A222		28	28	72-32-04	LPC/LPT COUPLING - NO. 1.5 BEARING (INNER RACE) RETAINING NUT	Package B	1	ANTIGALLANT REPLACEMENT		690	SR Technics Switzerland
137368	50A222	EASA;FAA;CAAC;ANAC	28	28	72-32-04	LPC/LPT COUPLING - NO. 1.5 BEARING (INNER RACE) RETAINING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		795	SR Technics Switzerland
137370	50A357	EASA;FAA;CAAC;ANAC	26	21	72-34-42	INTERMEDIATE CASE - MAIN BEARING (OUTER) SCAVENGE TUBE ASSI	Package A	CLN/INSP	CLEANING AND INSPECTION		305	SR Technics Switzerland
137371	50A353	EASA;FAA;CAAC;ANAC	27	21	72-34-25	INTERMEDIATE CASE - MAIN BEARING (OIL) PRESSURE TUBE ASSEMB	Package A	CLN/INSP	CLEANING AND INSPECTION		490	SR Technics Switzerland
137372	50A609; 52A022-01	EASA;FAA;CAAC;ANAC	13	28	72-34-30	PW4 NOZZLE OF NO 2 BEARING (100")	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	725	SR Technics Switzerland
137372	50A609; 52A022-01	EASA;FAA;CAAC;ANAC	13	28	72-34-30	PW4 NOZZLE OF NO 2 BEARING (100")	Package SB00	72-116	BRG 1.5/2, MODIFICATION FOR LESS WEAR		400	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package C	2	OIL PRESSURE MANIFOLD SUPPORT BRACKET REPLACEMENT		970	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package D	3	PLASMA SPRAY THE FRONT SUPPORT MATING DIAMETER		2225	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package E	4	PLASMA SPRAY THE FRONT OUTER DIAMETER		2225	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package F	5	PLASMA SPRAY THE REAR OUTER DIAMETAR		2225	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package G	6	OIL PRESSURE MANIFOLD SUPPORT BRACKET BUSHING REPLACEMENT		1215	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package Q	16	BOLT HOLE BLEND REPAIR		625	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package R	17	REPAIR FRONT FLANGE BOLT HOLES		1260	SR Technics Switzerland
137373	50A566; 50A639; 50A640		33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package S	18	REPAIR REAR FLANGE BOLT HOLES		1260	SR Technics Switzerland
137373	50A566; 50A639; 50A640	EASA;FAA;CAAC;ANAC	33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package A	CLN/INSP	CLEANING AND INSPECTION		510	SR Technics Switzerland
137373	50A566; 50A639; 50A640	EASA;FAA;CAAC;ANAC	33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package B	1	ANODIZE TOUCH-UP		565	SR Technics Switzerland
137373	50A566; 50A639; 50A640	EASA;FAA;CAAC;ANAC	33	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 94	Package B	INSP-03	BLEND REPAIR		565	SR Technics Switzerland
137378	50G327; 51G824	EASA;FAA;CAAC;ANAC	31	28	72-34-08	INTERMEDIATE CASE - SHOULDER STUD (NO. 2 BEARING DAMPER)	Package A	CLN/INSP	CLEANING AND INSPECTION		90	SR Technics Switzerland
137378	50G327; 51G824	EASA;FAA;CAAC;ANAC	31	28	72-34-08	INTERMEDIATE CASE - SHOULDER STUD (NO. 2 BEARING DAMPER)	Package B	1	BLEND REPAIR		145	SR Technics Switzerland
137385	50H048; 50H049; 50H051; 5	EASA;FAA;CAAC;ANAC										
137385	50H048; 50H049; 50H051; 5	EASA;FAA;CAAC;ANAC	21	28	72-35-34	HIGH PRESSURE COMPRESSOR (HPC) - INTERMEDIATE CASE - COMPRI	Package A	CLN/INSP	CLEANING AND INSPECTION		120	SR Technics Switzerland
137386	50H053; 51H517; 53H118; 5	EASA;FAA;CAAC;ANAC										
137386	50H053; 51H517; 53H118; 5	EASA;FAA;CAAC;ANAC	25	28	72-35-35	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR TIEROD NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		90	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC										
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package B	1	BLEND REPAIR		680	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package C	2	CLEVIS BOLT HOLE BUSHING REPAIR		1760	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package E	4	REPAIR CLEVIS ACTUATOR BOLT HOLE WITH BUSHING		1545	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package SB00	PW4ENG 72-534	ACTUATOR SUPPORT BRACKET UPPER MOUNT STUDS AND 5TH STG SYNCHRONIZING RING CLEVIS - REPLACEMENT		610	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package SB01	PW4ENG 72-197	HPC 5/6/7TH ST.VAR.VANE ACT.MODI.(SVS19)		645	SR Technics Switzerland
137389	50H432; 50H966; 50H968; 5	EASA;FAA;CAAC;ANAC;CAA UK	29	28	72-35-55	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING CLEVIS /	Package A	CLN/INSP	CLEANING AND INSPECTION		295	SR Technics Switzerland
137392	50H180; 50H186; 50H433; 5	EASA;FAA;CAAC;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137392	50H180; 50H186; 50H433; 5	EASA;FAA;CAAC;ANAC	30	28	72-35-56	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING PLATES	Package A	CLN/INSP	CLEANING AND INSPECTION		240	SR Technics Switzerland
137392	50H180; 50H186; 50H433; 5	EASA;FAA;CAAC;ANAC	30	28	72-35-56	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING PLATES	Package B	1	BLEND REPAIR		390	SR Technics Switzerland
137392	50H180; 50H186; 50H433; 5	EASA;FAA;CAAC;ANAC	30	28	72-35-56	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING PLATES	Package C	2	BOLT HOLE BUSHING REPAIR		1060	SR Technics Switzerland
137392	50H180; 50H186; 50H433; 5	EASA;FAA;CAAC;ANAC	30	28	72-35-56	HIGH PRESSURE COMPRESSOR (HPC) - SYNCHRONIZING RING PLATES	Package SB00	PW4ENG 72-527	SYNCHRONIZING RING STG 5 AND 6 - INCORPORATION OF LOCATING PIN		470	SR Technics Switzerland
137403	50J093		28	21	72-41-30	DIFFUSER AND COMBUSTOR - NO. 3 BEARING ELBOW ASSEMBLY (NO	Package B	1	CHROMIUM PLATE ID SEAL LAND		2285	SR Technics Switzerland
137403	50J093		28	21	72-41-30	DIFFUSER AND COMBUSTOR - NO. 3 BEARING ELBOW ASSEMBLY (NO	Package C	2	NICKEL PLATE REAR OD PILOT DIAMETER		2185	SR Technics Switzerland
137403	50J093		28	21	72-41-30	DIFFUSER AND COMBUSTOR - NO. 3 BEARING ELBOW ASSEMBLY (NO	Package D	3	SHIELD WELD BEAD REPAIR		785	SR Technics Switzerland
137403	50J093		28	21	72-41-30	DIFFUSER AND COMBUSTOR - NO. 3 BEARING ELBOW ASSEMBLY (NO	Package E	4	SHIELD CRACK WELD REPAIR		880	SR Technics Switzerland
137403	50J093	EASA;FAA;CAAC;ANAC	28	21	72-41-30	DIFFUSER AND COMBUSTOR - NO. 3 BEARING ELBOW ASSEMBLY (NO	Package A	CLN/INSP	CLEANING AND INSPECTION		335	SR Technics Switzerland
137406	50J233; 50J916		18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package D	3	REPAIR SEAL RING GROOVE		295	SR Technics Switzerland
137406	50J233; 50J916		18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package E	4	REPAIR SEAL LANDS		1040	SR Technics Switzerland
137406	50J233; 50J916		18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package F	5	REPAIR SEAL RING GROOVE		200	SR Technics Switzerland
137406	50J233; 50J916		18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package G	6	SEAL LANDS WELD REPAIR		1645	SR Technics Switzerland
137406	50J233; 50J916	EASA;FAA;CAAC;ANAC	18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package A	CLN/INSP	CLEANING AND INSPECTION		430	SR Technics Switzerland
137406	50J233; 50J916	EASA;FAA;CAAC;ANAC;CAA UK	18	21	72-41-28	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package C	2	CHROMIUM PLATE SEAL RING TRANSFER TUBEINSIDE DIAMETER FOR WEAR GREATER THAN 1.2015 INCHES (30.518		2085	SR Technics Switzerland
137409	50J248; 50J927-01		29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package D	3	CHROMIUM PLATE PROBE		1185	SR Technics Switzerland
137409	50J248; 50J927-01		29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package E	4	REPAIR SEAL RING GROOVE		610	SR Technics Switzerland
137409	50J248; 50J927-01		29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package E	5	REPAIR SEAL RING GROOVE		610	SR Technics Switzerland
137409	50J248; 50J927-01		29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package G	6	WELD REPAIR SEAL LANDS AND SEAL RING GROOVE		1200	SR Technics Switzerland
137409	50J248; 50J927-01	EASA;FAA;CAAC;ANAC	29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package A	CLN/INSP	CLEANING AND INSPECTION		490	SR Technics Switzerland
137409	50J248; 50J927-01	EASA;FAA;CAAC;ANAC	29	21	72-41-23	DIFFUSER AND COMBUSTOR -TURBINE COOLING DUCT SENSING TUBI	Package C	2	APPLY ANTIGALLANT		735	SR Technics Switzerland
137410	50J252; 51J034	EASA;FAA;CAAC;ANAC	30	21	72-41-32	DIFFUSER AND COMBUSTOR -TURBINE BLADE COOLING TUBES	Package A	CLN/INSP	CLEANING AND INSPECTION		175	SR Technics Switzerland
137410	50J252; 51J034	EASA;FAA;CAAC;ANAC	30	21	72-41-32	DIFFUSER AND COMBUSTOR -TURBINE BLADE COOLING TUBES	Package B	1	NICKEL PLATE SEAL LANDS		1055	SR Technics Switzerland
137411	50J347; 50J353; 50J481	EASA;FAA;CAAC;ANAC										
137411	50J347; 50J353; 50J481	EASA;FAA;CAAC;ANAC	30	28	72-41-38	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRT COOLING DUCT RO	Package A	CLN/INSP	CLEANING AND INSPECTION		435	SR Technics Switzerland
137411	50J347; 50J353; 50J481	EASA;FAA;CAAC;ANAC	30	28	72-41-38	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRT COOLING DUCT RO	Package B	1	REPLACE SILVER PLATE	INCLUDING FPI	545	SR Technics Switzerland
137413	50J366; 50J922-01		33	21	72-41-24	DIFFUSER AND COMBUSTOR - NO. 3 BEARING OIL VENT (INNER) TUBI	Package E	4	WELD REPAIR SEAL LANDS AND SEAL RING GROOVE		1200	SR Technics Switzerland
137413	50J366; 50J922-01	EASA;FAA;CAAC;ANAC	33	21	72-41-24	DIFFUSER AND COMBUSTOR - NO. 3 BEARING OIL VENT (INNER) TUBI	Package A	CLN/INSP	CLEANING AND INSPECTION		360	SR Technics Switzerland
137413	50J366; 50J922-01	EASA;FAA;CAAC;ANAC	33	21	72-41-24	DIFFUSER AND COMBUSTOR - NO. 3 BEARING OIL VENT (INNER) TUBI	Package C	2	REPAIR SEAL RING GROOVE		420	SR Technics Switzerland
137417	50K109		28	28	72-51-06	TURBINE NOZZLE - STAGE 1 HPT DUCT SEGMENT	Package B	1	SHIPLAP WEAR WELD REPAIR		955	SR Technics Switzerland
137417	50K109		28	28	72-51-06	TURBINE NOZZLE - STAGE 1 HPT DUCT SEGMENT	Package C	2	SURFACE DAMAGE BLEND REPAIR		345	SR Technics Switzerland
137417	50K109	EASA;FAA;CAAC;ANAC	28	28	72-51-06	TURBINE NOZZLE - STAGE 1 HPT DUCT SEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		150	SR Technics Switzerland
137418	53L033		28	28	72-52-15	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (BLADE) AIRSEAL	Package SB00	PW4ENG 72-636	MODIFICATION OF TO IMPROVE LOW CYCLE FATIGUE OF THE SECOND STAGE HPT AIR SEAL		345	SR Technics Switzerland
137418	53L033		28	28	72-52-15	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (BLADE) AIRSEAL	Package SB01	PW4G-100-72-93	MODIFICATION OF TO IMPROVE LOW CYCLE FATIGUE OF THE SECOND STAGE HPT AIR SEAL		345	SR Technics Switzerland
137418	53L033	EASA;FAA;CAAC;ANAC	28	28	72-52-15	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (BLADE) AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		505	SR Technics Switzerland
137419	50L246-01		20	28	72-52-36	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (DUCT) BAND SEGMEN	Package B	1	STAGE 2 HPT (DUCT) BAND SEGMENT ASSEMBLY		770	SR Technics Switzerland
137419	50L246-01	EASA;FAA;CAAC;ANAC	20	28	72-52-36	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (DUCT) BAND SEGMEN	Package A	CLN/INSP	CLEANING AND INSPECTION		125	SR Technics Switzerland
137422	50N241; 50N546	EASA;FAA;CAAC;ANAC	5	28	72-53-50	PW4 TURBINE CASE - STG 3 AIRSEALING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		65	SR Technics Switzerland
137422	50N241; 50N546	EASA;FAA;CAAC;ANAC	5	28	72-53-50	PW4 TURBINE CASE - STG 3 AIRSEALING RING	Package B	1	DAMAGE AREA PATCH REPAIR		130	SR Technics Switzerland
137423	50N121-01; 50N122-01; 50N	EASA;FAA;CAAC;ANAC										
137423	50N121-01; 50N122-01; 50N	EASA;FAA;CAAC;ANAC	26	28	72-53-51	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 4 VANE) HEAT	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
137423	50N121-01; 50N122-01; 50N	EASA;FAA;CAAC;ANAC	26	28	72-53-51	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 4 VANE) HEAT	Package B	1	DAMAGE AREA PATCH REPAIR	PRICE PER UNIT	610	SR Technics Switzerland
137424	50N125-01; 50N126-01; 50N	EASA;FAA;CAAC;ANAC										
137424	50N125-01; 50N126-01; 50N	EASA;FAA;CAAC;ANAC	25	28	72-53-53	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 5 VANE) HEAT	Package A	CLN/INSP	CLEANING AND INSPECTION		280	SR Technics Switzerland
137424	50N125-01; 50N126-01; 50N	EASA;FAA;CAAC;ANAC	25	28	72-53-53	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 5 VANE) HEAT	Package B	1	DAMAGE AREA PATCH REPAIR	PRICE PER UNIT	610	SR Technics Switzerland
137425	50N245; 50N564-01	EASA;FAA;CAAC;ANAC	6	28	72-53-54	PW4 TURBINE CASE - STG 5 AIRSEALING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		280	SR Technics Switzerland
137425	50N245; 50N564-01	EASA;FAA;CAAC;ANAC	6	28	72-53-54	PW4 TURBINE CASE - STG 5 AIRSEALING RING	Package B	1	DAMAGE AREA PATCH REPAIR		610	SR Technics Switzerland
137426	50N130-01		26	28	72-53-55	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 6 VANE) HEAT	Package B	1	DAMAGE AREA PATCH REPAIR	PRICE PER UNIT	610	SR Technics Switzerland
137426	50N130-01	EASA;FAA;CAAC;ANAC	26	28	72-53-55	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 6 VANE) HEAT	Package A	CLN/INSP	CLEANING AND INSPECTION		280	SR Technics Switzerland
137427	50P106; 50P107; 50P136; 5(	EASA;FAA;ANAC										
137427	50P106; 50P107; 50P136; 5(	EASA;FAA;CAAC;ANAC										
137427	50P106; 50P107; 50P136; 5(	EASA;FAA;CAAC;ANAC	29	21	72-54-15	TURBINE EXHAUST CASE - NO. 4 BEARING PRESSURE AND SCAVENGE	Package A	CLN/INSP	CLEANING AND INSPECTION		150	SR Technics Switzerland
137427	50P106; 50P107; 50P136; 5(	EASA;FAA;CAAC;ANAC	29	21	72-54-15	TURBINE EXHAUST CASE - NO. 4 BEARING PRESSURE AND SCAVENGE	Package B	1	HEAT SHIELD PATCH REPAIR		420	SR Technics Switzerland
137427	50P106; 50P107; 50P136; 5(	EASA;FAA;CAAC;ANAC;CAA UK										
137442	217346	EASA;FAA;CAAC;ANAC	14	21	73-11-04	FUEL PUMP - 94" - SHAFT DRIVE MAIN	Package A		CRACK INSPECTION, MPI	ACCORDING CMM	265	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package M	12	BENT FLANGE STRAIGHTENING REPAIR		2885	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package O	14	HOOK CRACKS AND GASPATH FOD DAMAGE WELD REPAIR	PW 94 INCH	6595	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package P	15	O-RING GROOVE FLANGE WELD REPAIR		2395	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package S	18	BLEND REPAIR		680	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package SB00	PW4ENG 72-39	MODIFICATION OF 4TH STAGE LPC DUCT AND INNER FAN EXIT CASE		1025	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package SB01	PW4ENG 72-666	LPC IMPROVED RUBBER AIRSEAL MODIFICATION		3930	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package SB02	PW4G-100-72-119	LPC STATOR RUBBER REPLACEMENT		2605	SR Technics Switzerland
137539	50B023; 50B023-001; 50B227;	50B230; 51B150; 51B154	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package T	19	OUTER DIAMETER LUG DAMAGE WELD REPAIR		2185	SR Technics Switzerland
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		1125	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package B	1	ANODIZE TOUCH-UP LPC STAGE 4 DUCT		420	SR Technics Switzerland
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package C	2	REPLACE SILICONE RUBBER RUBSTRIP		3930	SR Technics Switzerland
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package G	6	SILICONE RUBBER AIRSEAL REPAIR - LPC STAGE 4 DUCT		3165	SR Technics Switzerland
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package J	9	BOLT HOLE FUSION WELD REPAIR		915	SR Technics Switzerland
137539	50B023; 50B023-001; 50B22	EASA;FAA;CAAC;ANAC	37	28	72-31-11	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 DUCT	Package L	11	FUSION WELD REPAIR		4225	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AJ	42	OUTER SHROUD PWA 36003 SILICONE RUBBER REPLACEMENT REPAIR		3840	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AK	36	SURFACEE DAMAGE WELD REPAIR		3140	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package B	1	ANODIZE TOUCH-UP		580	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package C	2	BLEND REPAIR VANES		955	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package D	3	REPLACE OUTER SHROUD LIP		8400	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package E	4	CRACK REPAIR LPC STAGE 1 COMPRESSOR STATOR ASSEMBLY INNER SHROUD		1215	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package F	5	CRACK REPAIR LPC STAGE 1 COMPRESSOR STATOR INNER SHROUD BUTT JOINT		2220	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package G	6	SILICONE RUBBER INNER AIRSEAL REPAIR		7405	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package H	7	BLEND REPAIR OUTER SHROUD		1235	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package J	9	REPLACE STATOR VANE		11275	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package K	10	CRACK (MAJOR) REPAIR LPC STAGE 1 COMPRESSOR STATOR ASSEMBLY INNER SHROUD		3830	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package L	11	ALUMINUM BAND REPLACEMENT		3915	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package M	12	REPLACEMENT INNER SHROUD		21135	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package N	13	BUTT JOINT (MAJOR) CRACK REPAIR		11765	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package O	14	DEBONDED ALUMINUM BAND REPAIR		3385	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package SB00	PW4ENG 72-666	LPC, 1ST STAGE STATOR & 4TH STAGE DUCT - REPL. OF, OR MODIFIC. ` LPC STAGE 1 STATOR IMPROVED RUBBER REF		7405	SR Technics Switzerland
137540	50B271; 50B271-001		36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package Y	24	REPLACE DAMAGED VANE POTTING COMPOUND REPAIR		2975	SR Technics Switzerland
137540	50B271; 50B271-001	EASA;FAA;CAAC;ANAC	36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package A	CLN/INSP	CLEANING AND INSPECTION		1030	SR Technics Switzerland
137540	50B271; 50B271-001	EASA;FAA;CAAC;ANAC	36	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AI	34	BENT FLANGE STRAIGHTENING REPAIR		3295	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package D	3	SURFACE DAMAGE BLEND REPAIR		2365	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package E	4	BLEND REPAIR BALANCE FLANGE		1000	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package H	7	PLASMA SPRAY FRONT SNAP DIAMETER		5410	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package I	8	REPAIR TIEROD HOLES		3840	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package J	9	SHOTPEEN DRUM ROTOR DISK SLOTS		4290	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package L	11	BALANCE COUNTERWEIGHT REMOVAL AND INSTALLATION REPAIR		610	SR Technics Switzerland
137541	50B422; 51B022-01; 53B200-01		31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package SB00	PW4ENG 72-665	REPETITIVE EDDY CURRENT INSPECTION OF THE BLADE LEADING EDGI	ONLY BLADED DISK	1000	SR Technics Switzerland
137541	50B422; 51B022-01; 53B20(	EASA;FAA;CAAC;ANAC	31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package C	2	BLEND REPAIR KNIFE EDGE SEAL		1070	SR Technics Switzerland
137541	50B422; 51B022-01; 53B20(	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package A	CLN/INSP	CLEANING AND INSPECTION		2435	SR Technics Switzerland
137541	50B422; 51B022-01; 53B20(	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package B	1	STRAIGHTEN KNIFE-EDGE SEAL		1440	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package E	4	REAR INNER SEAL FACE PLASMA COAT REPAIR		4070	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package H	7	STAGE 1 HPT SEAL REPLACEMENT REPAIR		410	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package I	8	ANTI-ROTATION LUG CRACK WELD REPAIR		1970	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package K	10	DISASSEMBLE AND ASSEMBLE THE SUPPORT ASSEMBLY REPAIR		815	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	11	FRONT INNER DIAMETER PLASMA SPRAY REPAIR		5395	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	12	VANE RETAINING SLOTS WELD REPAIR		5395	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package L	15	ANTIROTATION LOCK LUG CRACK WELD REPAIR		5395	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package Q	16	REAR OUTER FACE PLASMA SPRAY REPAIR		3580	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package T	19	FRONT INNER FACE PLASMA SPRAY REPAIR		3885	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 50K358-01; 50K613		24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package U	20	REAR OUTER FACE PLASMA SPRAY REPAIR		3500	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 5(	EASA;FAA;CAAC;ANAC	24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		995	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 5(	EASA;FAA;CAAC;ANAC	24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package AC	28	ANTI-ROTATION LOCK BOLT HOLE WELD REPAIR		1645	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 5(	EASA;FAA;CAAC;ANAC	24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package AE	30	SUPPORT FORWARD LIP PLASMA COAT REPAIR		2265	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 5(	EASA;FAA;CAAC;ANAC	24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package B	1	VANE RETAINING SLOTS WELD REPAIR		2420	SR Technics Switzerland
137542	50K107; 50K182; 50K184; 5(	EASA;FAA;CAAC;ANAC	24	28	72-51-01	TURBINE NOZZLE - STAGE 1 (VANE) HPT SUPPORT ASSEMBLY	Package C	2	REAR OUTER FACE PLASMA SPRAY REPAIR		1640	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package F	5	REPAIR DUCT SEGMENT HOLES		3170	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package G	6	REPAIR DUCT SEGMENT CRACKS		3170	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package H	7	REPAIR DUCT SEGMENT SURFACE DAMAGE WITH POTTING COMPOUND		3170	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package I	8	REPLACE SOME OF THE DUCT SEGMENTS		5635	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package J	9	REPLACE ALL DUCT SEGMENTS		15555	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package SB01	PW4ENG 72-671	INSPECTION THE DUCT SEGMENT RECESS OF THE FAN CASE FOR TOOL MARKS		320	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package SB04	000913-ED01	FAN EXIT GUIDE VANES-LEADING EDGE METAL SHIELD REPLACEMENT ED R.ESEE.000913-ED01		1095	SR Technics Switzerland
137544	50D496; 50D728; 50D923-001; 50D959; 51D707		34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package SB05	PW4ENG 72-489	INTRODUCTION OF DUCT SEGMENTS WITH INTERRUPTED CIRCUMFERENTIAL GROOVE		7695	SR Technics Switzerland
137544	50D496; 50D728; 50D923-0(	EASA;FAA;CAAC;ANAC	34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		2625	SR Technics Switzerland
137544	50D496; 50D728; 50D923-0(	EASA;FAA;CAAC;ANAC	34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package B	1	REPLACE FAN CASE ASSEMBLY LOCATING PIN		420	SR Technics Switzerland
137544	50D496; 50D728; 50D923-0(	EASA;FAA;CAAC;ANAC	34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package C	2	BLEND SURFACE DAMAGE REPAIR		2120	SR Technics Switzerland
137544	50D496; 50D728; 50D923-0(	EASA;FAA;CAAC;ANAC	34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package D	3	RUBSTRIP REPAIR		3150	SR Technics Switzerland
137544	50D496; 50D728; 50D923-0(	EASA;FAA;CAAC;ANAC;CAA UK	34	28	72-33-01	FAN CASE ASSEMBLY - 94"	Package E	4	PLASMA SPRAY THE REAR SNAP DIAMETER		1850	SR Technics Switzerland
137545	50G506		23	28	72-34-12	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEAR	Package B	1	BEARING JOURNAL DIAMETER CHROMIUM PLATE REPAIR		5320	SR Technics Switzerland
137545	50G506		23	28	72-34-12	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEAR	Package C	2	INNER DIAMETER CHROMIUM PLATE REPAIR		6615	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137545	50G506		23	28	72-34-12	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEAR	Package D	3	BEARING JOURNAL DIAMETER GROWTH REPAIR		895	SR Technics Switzerland
137545	50G506	EASA;FAA;CAAC;ANAC	23	28	72-34-12	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		590	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package O	9	REPLACE VANES		5150	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package R	10	BLEND STATOR VANES (TITANIUM) REPAIR		1575	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package SB00	PW4ENG 72-819	REPLACEMENT OR MODIFICATION OF, TO INCORPORATE A BOLT LOCKING FEATURE		1395	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package SB01	PW4ENG 72-454	IMPROV.TI-INNER SHROUD		310	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package U	14	VANE RUBBER REPAIR	SEAL INNER SHROUD VANE	4700	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package V	14	VANE RUBBER REPAIR	SEAL OUTER SHROUD VANE	4375	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package W	15	BLEND THE OUTER SHROUD SURFACE DAMAGED		965	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package X	18	REMOVAL OF REMAINING CORROSION REPAIR		785	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package Y	22	INNER SHROUD BOLT HOLE DAMAGE REAM REPAIR		875	SR Technics Switzerland
137547	51G174; 51G174-002; 51G774; 51G774-001; 51G874; 51G874-001; 52G274		35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package Z	23	BLEND REPAIR ON INNER SHROUD BOLT HOLES		820	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		1200	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package AC	20	SEALANT TOUCH-UP REPAIR		2045	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package B	1	TOUCH-UP PROTECTIVE COATING		635	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package C	2	REPLACE PIN		675	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package D	3	BLEND STATOR VANES REPAIR	REP.01 INCLUDED	1515	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package G	6	WELD THE LUGS ON THE OUTER SHROUD	REP.01 INCLUDED	3605	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package H	7	REPLACE VANES		7805	SR Technics Switzerland
137547	51G174; 51G174-002; 51G7	EASA;FAA;CAAC;ANAC	35	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package K	8	SMOOTH DAMAGE ON THE INNER SHROUD LUGS	REP.01 INCLUDED	1740	SR Technics Switzerland
137549	50H021; 56H279		6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package C	4	PLASMA SPRAY REPAIR SNAP DIAMETER		3145	SR Technics Switzerland
137549	50H021; 56H279		6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package D	6	REPAIR OF DAMAGED BALANCE FLANGE		1040	SR Technics Switzerland
137549	50H021; 56H279		6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package E	7	BLEND REPAIR SURFACE DAMAGE		1075	SR Technics Switzerland
137549	50H021; 56H279		6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package SB00	PW4ENG 72-653	FRONT KNIFE EDGE MODIFICATION TO IMPROVE DURABILITY		2430	SR Technics Switzerland
137549	50H021; 56H279	EASA;FAA;CAAC;ANAC	6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package A	CLN/INSP	CLEANING & INSPECTION		935	SR Technics Switzerland
137549	50H021; 56H279	EASA;FAA;CAAC;ANAC	6	28	72-35-31	PW4 HPC INLET AIRSEAL	Package B	2	BLEND REPAIR KNIFE EDGE SEAL		205	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package E	4	RESTORE KNIFE-EDGE SEAL PLASMA COAT		3295	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package F	7	PLASMA REPAIR DIAMETER		3140	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package G	8	RESTORE HARDFACE OF BRUSH SEAL LAND		4700	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package G	12	RESTORE HARDFACE OF BRUSH SEAL LAND		4700	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package H	5	PLASMA COAT OR NICKEL PLATE REPAIR FRONT OUTSIDE DIAMETER		3915	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package J	9	SURFACE DAMAGE BLEND REPAIR		3910	SR Technics Switzerland
137550	50H218; 54H792; 54H846		36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package J	17	SURFACE DAMAGE BLEND REPAIR		3910	SR Technics Switzerland
137550	50H218; 54H792; 54H846	EASA;FAA;CAAC;ANAC	36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1150	SR Technics Switzerland
137550	50H218; 54H792; 54H846	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package B	1	KNIFE-EDGE SEAL REPAIR		1145	SR Technics Switzerland
137550	50H218; 54H792; 54H846	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-35-32	HIGH PRESSURE COMPRESSOR (HPC) - DIFFUSER AIRSEAL	Package D	3	BLEND REPAIR KNIFE-EDGE SEALS		895	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 54H798-01; 54H881; 54H882		32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package SB00	PW4ENG 72-432	SYNCHRONIZING RING - MODIFICATION OF PIN ATTACHMENT		1380	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 54H798-01; 54H881; 54H882		32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package SB01	PW4ENG 72-474	SYNCHRONIZING RING - PAINT REMOVAL FROM ID		390	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package A	CLN/INSP	CLEANING AND INSPECTION	PN50H792 FOR SHOP VISIT ONLY	415	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1380	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package C	2	REPLACE NUT PLATES		680	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2855	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		680	SR Technics Switzerland
137552	50H793; 53H929; 53H930; 5	EASA;FAA;CAAC;ANAC	32	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package L	11	APPLY PWA 578 PAINT		1115	SR Technics Switzerland
137571	50A126; 50A127; 50A128; 5	EASA;FAA;CAAC;ANAC										
137571	50A126; 50A127; 50A128; 5	EASA;FAA;CAAC;ANAC	6	28	72-41-82	PW4 BEARING ROLLER NO. 3 MAIN	Package A	CLN/INSP	Cleaning and inspection		895	SR Technics Switzerland
137571	50A126; 50A127; 50A128; 5	EASA;FAA;CAAC;ANAC	6	28	72-41-82	PW4 BEARING ROLLER NO. 3 MAIN	Package SB00	PW4ENG 72-372	NO.3 BRG. EDDY CURRENT INSP./ SPEC.UNITS		485	SR Technics Switzerland
137574	50J301		6	28	72-41-03	PW4 STAGE 15 HPC AIRSEALING RING	Package B	1	PLASMA SPRAY SNAP DIAMETER		2870	SR Technics Switzerland
137574	50J301	EASA;FAA;CAAC;ANAC	6	28	72-41-03	PW4 STAGE 15 HPC AIRSEALING RING	Package A	CLN/INSP	CLEANING & INSPECTION		780	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package C	2	PLASMA SPRAY SNAP DIAMETER		2880	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package D	3	PLASMA COAT REPAIR OIL PRESSURE TUBE BOSS ID		2880	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package E	4	PLASMA COAT REPAIR OIL SCAVENGE BOSS ID		2370	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package F	5	PLASMA COAT REPAIR BREATHER BOSS ID		2540	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package G	6	SLEEVE REPAIR OIL PRESSURE TUBE BOSS ID		2880	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package H	7	SLEEVE REPAIR OIL SCAVENGE BOSS ID		2605	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package I	8	SLEEVE REPAIR BREATHER BOSS ID		2605	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package J	9	SLEEVE REPAIR 12TH STAGE AIR SUPPLY TUBE BOSS		2880	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package K	10	SLEEVE REPAIR TOBI SENSE TUBE BOSS		2705	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package L	11	SLEEVE REPAIR OIL WEEP TUBE BOSS		2705	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package M	12	SLEEVE REPAIR NO. 3 BEARING COMPARTMENT BUFFER AIR BOSS		2705	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package N	13	BLEND REPAIR		865	SR Technics Switzerland
137575	50J419		28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package O	14	BLEND REPAIR THE WORN ANTI - ROTATION SLOT		895	SR Technics Switzerland
137575	50J419	EASA;FAA;CAAC;ANAC	28	28	72-41-05	DIFFUSER AND COMBUSTOR - DIFFUSER AIRSEALING RING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		870	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	488-01; 50J612-01; 50J748-01; 50J943-001; 50J	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AK	58	REAR STIFFENER CRACK WELD REPAIR		2355	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AL		59 REAR STIFFENER PATCH REPAIR		2955	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AM		64 COMBUSTION CHAMBER DOME DAMAGE WELD REPAIR		590	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package D		3 REPLACE THE HARDFACE ON THE SNAP DIAMETER REPAIR		845	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package E		4 REPLACE HARDFACE ON REAR STIFFENER REPAIR		990	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package F		5 BULKHEAD CRACK WELD REPAIR		5880	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package G		6 BULKHEAD CRACK PATCH REPAIR		3515	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package H		7 MOUNT LUG BUSHING REPLACEMENT		860	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package I		8 RESTORE PWA 265 PLASMA COAT REPAIR	SOURCE DEMO	3375	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package J		9 2ND WELD LINER CRACKS	NOT IN TO DOUBLE PASS AEREA	5805	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package J		9 WELD LINER CRACKS	NOT IN TO DOUBLE PASS AEREA	5805	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package K		10 2ND WELD LINER CRACKS	IN TO DOUBLE PASS AEREA	4805	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package K		10 WELD LINER CRACKS	IN TO DOUBLE PASS AEREA	4805	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package L		11 2ND PATCH WELD LINER CRACKS		4835	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package L		11 PATCH WELD LINER CRACKS		4835	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package M		12 RESIZE EXIT LINER AND REAR STIFFENER		1020	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package N		13 RESTORE LOUVER GAP		1225	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package O		14 REPLACE IGNITER BOSS ASSEMBLY		1435	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package P		15 RESIZE REAR STIFFENER PLASMA REPAIR		1000	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Q		16 REPLACE NO. 7 AND 8 LINERS		6785	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package S		18 REPLACE NO. 4 THROUGH 6 LINERS REPAIR		5430	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB00	PW4ENG 72-152	IGNITOR PLUG INSP. OF FOR WEAR	& COMBUSTION CHAMBER ASSEMBLY, OUTE	3010	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB04	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW415	AIRBUS	13390	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB05	PW4ENG 72-601	CHAMBER ASSY, OUTER COMBUSTION - MODIF. OF TO INCORP. AN IGNITER GUIDE ASSEMBLY THAT WILL NOT ROT		630	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package U		20 REPLACE BULKHEAD ASSEMBLY REPAIR		2415	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package W		22 REPLACE BULKHEAD HARDFACE REPAIR		840	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package X		23 REPLACE ONE NOZZLE STATOR AND POSITIONING RINGS		2415	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Y		24 REPAIR FUEL NOZZLE GUIDE RIVET HOLE		3150	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J488-01; 50J612-01; 50J748-01; 50J943-001; 50J		33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Z		25 WELD THE MOUNT LUGS		2840	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package A	CLN/INSP	CLEANING AND INSPECTION		4395	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AA		26 WELD REPAIR WEAR ON BULKHEAD FRONT FACE		4940	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AC		28 STRESS-RELIEF CYCLE		430	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AD		29 LINER TRAILING EDGE WELD REPAIR		3175	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AE		30 REPLACE NO. 4 THROUGH 8 LINER REPAIR		9590	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AG		41 PLASMA COAT BUILD-UP REPAIR		4940	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AH		43 WELD CRACKS IN FILLET WELDS OF REAR SEAL STIFFENER RING		1045	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AI		44 AFT LOUVER LIP DISTRESS PATCH REPAIR		860	SR Technics Switzerland
137576	50J464-01; 50J488-001; 50J	EASA;FAA;CAAC;ANAC	33	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AJ		47 BULKHEAD PATCH REPAIR	FILET RADIUS	860	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285-001; 51J285-01; 51J385-001; 51J385-01; 51J68		25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package SB00	PW4ENG 72-464	REPLACEMENT OR MODIFICATION OF TO INCORPORATE JACKSCREW HOLES		865	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1300	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package B		1 REPLACE ANTIGALLING COMPOUND		625	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package C		2 BLEND THE COMPRESSOR EXIT STATOR ASSEMBLY VANES		1885	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package D		3 HONEYCOMB REPLACEMENT REPAIR		8730	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package E		4 PLASMA SPRAY REAR SNAP DIAMETER		4475	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package F		5 PLASMA SPRAY FRONT SNAP DIAMETER		4475	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package G		6 WELD REPAIR OUTER SHROUD SLOT CRACKS		8640	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package H		7 WELD REPAIR VANE CRACKS		12895	SR Technics Switzerland
137577	50J685; 50J685-001; 51J285	EASA;FAA;CAAC;ANAC	25	28	72-41-02	DIFFUSER AND COMBUSTOR - COMPRESSOR EXIT STATOR ASSEMBLY	Package I		8 WELD REPAIR INNER FLANGE BOLT HOLES		8210	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365-01		27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package F		5 AXIAL AND RADIAL CRACK WELD REPAIR		3020	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365-01		27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package G		6 COMBUSTION CHAMBER GUIDE TAB WELD REPAIR		3020	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365-01		27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package L		11 BOROSCOPE BOSS WELD REPAIR		3175	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365	EASA;FAA;CAAC;ANAC	27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package A	CLN/INSP	CLEANING AND INSPECTION		455	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365	EASA;FAA;CAAC;ANAC	27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package B		1 HARDFACE COAT REPAIR		1545	SR Technics Switzerland
137580	50K036; 50K193-01; 50K365	EASA;FAA;CAAC;ANAC;CAA UK	27	28	72-51-08	TURBINE NOZZLE - COMBUSTION CHAMBER GUIDE ASSEMBLY (UPPEI	Package E		4 WELD BUILD-UP COMBUSTION CHAMBER GUIDE (END TAB) SEAL MATING SURFACE		3020	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package AC		28 SIZE THE REAR SUPPORT		1180	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package AH		33 SUPPORT MATING FACE PLASMA COAT REPAIR		3655	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package AK		6 WELD REPAIR INNER LINER CRACKS IN THE CONSTANT THICKNESS SEC	2ND WELD REPAIR	1070	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package AL		7 WELD REPAIR INNER LINER CRACKS EXTENDING INTO DOUBLE PASS SI	2ND WELD REPAIR	1070	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package C		1 ONE LUG NUT PLATE REPLACEMENT REPAIR		1500	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package D		2 HARDFACE SUPPORT MATING FACE REPAIR		715	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package E		4 HARDFACE FRONT LINER		950	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package F		5 RESTORE PWA 265 PLASMA COAT REPAIR	SOURCE DEMO	4140	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package G		6 WELD REPAIR INNER LINER CRACKS IN THE CONSTANT THICKNESS SECTION		4140	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package H		7 WELD REPAIR INNER LINER CRACKS EXTENDING INTO DOUBLE PASS SECTION		3915	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package I		8 PATCH WELD REP. INNER LINER CRACKS > 0.030 INCH (0.762 MM) AND EXT. INTO THE DOUBLE PASS SECTION		4445	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package J	9	RESTORE COMBUSTION CHAMBER LOUVER GAP		295	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package K	10	CRACK WELD REPAIR COMBUSTION CHAMBER ASSEMBLY REAR SUPPORT PLATE		3060	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package L	11	REPLACE INNER COMBUSTION CHAMBER (REAR) SUPPORT PLATE		2120	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package N	13	REPLACE NO. 1 AND 2 COMBUSTION CHAMBER LINER SEGMENTS		3685	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package O	14	REPLACE NO. 4 AND 5 COMBUSTION CHAMBER LINER SEGMENTS		7020	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package P	15	REPLACE NO. 7 AND 8 COMBUSTION CHAMBER LINER SEGMENTS		3515	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package Q	16	SIZE THE FRONT LINER		1385	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package R	17	WELD REPAIR LINER LOUVER TRAILING EDGE		2645	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package SB00		MODIFICATION OF COMBUSTION CHAMBER OUTER/INNER LINER	ACCORDING TO SB PW4ENG 72-187.1 AND SE	2635	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package SB01	PW4ENG 72-490	CONVERSION OF A PW4460 OR PW4460 (-3) OR PW4462 (-3)	MCDONELL DOUGLAS	5605	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package SB02	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060,TO A PW4052(-3), PW4	BOEING	5090	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package SB03	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW415:	AIRBUS	5410	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K488-01		35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package T	19	REPLACE NO. 4 THROUGH 8 COMBUSTION CHAMBER LINER SEGMENT		8310	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K	EASA;FAA;CAAC;ANAC	35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		2470	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K	EASA;FAA;CAAC;ANAC	35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		2470	SR Technics Switzerland
137581	50K359-01; 50K464-01; 50K	EASA;FAA;CAAC;ANAC	35	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 94"	Package AA	26	STRESS RELIEVE		1775	SR Technics Switzerland
137582	50L276; 50L278; 50L371; 50	EASA;FAA;CAAC;ANAC										
137582	50L276; 50L278; 50L371; 50	EASA;FAA;CAAC;ANAC	14	28	72-52-31	PW4 STAGE 1 HPT DUCT SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		120	SR Technics Switzerland
137582	50L276; 50L278; 50L371; 50	EASA;FAA;CAAC;ANAC	14	28	72-52-31	PW4 STAGE 1 HPT DUCT SUPPORT ASSEMBLY	Package SB00	PW4NG 72-34	MODIFICATION OF THE CASTCASE ASSY AND 1ST STAGE HPT DUCT SU	REPLACEMENT OF 2ND AND 1ST STAGE HPT I	145	SR Technics Switzerland
137583	50L014; 50L193; 50L659		19	28	72-52-21	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (INNER ROTATING) AIR	Package D	3	NICKEL PLATE REPAIR SNAP DIAMETER		2135	SR Technics Switzerland
137583	50L014; 50L193; 50L659		19	28	72-52-21	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (INNER ROTATING) AIR	Package E	72-069548	REPL OF T1 AIRSEAL OR COATING OF KNIFE E		2140	SR Technics Switzerland
137583	50L014; 50L193; 50L659	EASA;FAA;CAAC;ANAC	19	28	72-52-21	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (INNER ROTATING) AIR	Package A	CLN/INSP	CLEAN AND INSPECTION		1335	SR Technics Switzerland
137583	50L014; 50L193; 50L659	EASA;FAA;CAAC;ANAC	19	28	72-52-21	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (INNER ROTATING) AIR	Package B	1	SURFACE DAMAGE BLEND REPAIR		1005	SR Technics Switzerland
137583	50L014; 50L193; 50L659	EASA;FAA;CAAC;ANAC	19	28	72-52-21	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (INNER ROTATING) AIR	Package C	2	KNIFE-EDGE SEALS BLEND REPAIR		1380	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package E	3	PLASMA SPRAY REAR OUTER SNAP DIAMETER		4050	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package F	4	PLASMA SPRAY FRONT INNER SNAP DIAMETER		4050	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package G	5	PLASMA SPRAY FRONT OUTER SNAP DIAMETER		4050	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package I	7	KNIFE-EDGE SEALS BLEND REPAIR		1000	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package J	8	PLASMA SPRAY REPAIR FRONT INNER MATING FACE		4050	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package K	9	COATING REPAIR FRONT OUTER MATING FACE		4920	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package L	10	MACHINE REPAIR FRONT INNER SNAP DIAMETER		2360	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package M	11	MACHINE REPAIR FRONT OUTER SNAP DIAMETER		2360	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package N	12	MACHINE REPAIR REAR INNER SNAP DIAMETER		2360	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package O	13	MACHINE REPAIR REAR OUTER SNAP DIAMETER		2360	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package SB01	PW4G-100-A72-80	AIR SEAL (ROTATING), HPT 2ND STAGE - INSPECTION OF FOR CRACKS		10650	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package SB02	PW4ENG A72-628	AIR SEAL (ROTATING), HPT 2ND STAGE - INSPECTION OF FOR CRACKS		10245	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package SB03	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	410	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53L030		38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package SB04	FAA-2011-25-09	LIFE LIMIT REDUCTION		545	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53	EASA;FAA;CAAC;ANAC	38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1755	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53	EASA;FAA;CAAC;ANAC	38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package B	INSP/CHK-03	CORROSION REPAIR ACCORDING SPOP 09 AND 10 SPM / CLEANING 01		2190	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53	EASA;FAA;CAAC;ANAC	38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package C	1	PLASMA SPRAY REAR MATING SURFACE		4050	SR Technics Switzerland
137584	50L156; 50L195; 53L027; 53	EASA;FAA;CAAC;ANAC;CAA UK	38	28	72-52-22	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (ROTATING) AIRSEAL	Package D	2	PLASMA SPRAY REAR INNER SNAP DIAMETER		4050	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package E	4	COAT REAR OD MATING SURFACE		5275	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package F	5	SHOTPEEN REPAIR		810	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package SB00	PW4ENG 72-487	INCORPORATION OF HPT 1, TWO KNIFE EDGE SEAL		2835	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package SB01	PW4ENG 72-736	HPT-FPI HUBS & OUT.AIRSEAL,1ST & 2ND STG		450	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package SB02	PW4G-100-72-176	HPT-FPI HUBS & OUT.AIRSEAL,1ST & 2ND STG		450	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package SB03	PW4ENG A72-724	HPT STG 1 ROTATING AIRSEAL - INSPECTION	INSPECTION FOR SHARP RADIUS AND CRACKS	595	SR Technics Switzerland
137585	50L248; 50L485; 50L879		32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package SB04	AD 2011-25-09	LIFE LIMIT CHECK	IN CONJUNCTION WITH PACKAGE A	175	SR Technics Switzerland
137585	50L248; 50L485; 50L879	EASA;FAA;CAAC;ANAC	32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package A	CLN/INSP	CLEANING AND INSPECTION		1755	SR Technics Switzerland
137585	50L248; 50L485; 50L879	EASA;FAA;CAAC;ANAC	32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package C	1	SURFACE DAMAGE BLEND REPAIR		1740	SR Technics Switzerland
137585	50L248; 50L485; 50L879	EASA;FAA;CAAC;ANAC;CAA UK	32	28	72-52-20	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT (OUTER ROTATING) AII	Package D	2	KNIFE-EDGE SEALS BLEND REPAIR		1590	SR Technics Switzerland
137587	50L287; 50L678		7	28	72-52-37	PW4 STAGE 2 HPT DUCT SUPPORT (SEGMENT)	Package SB00	72-462	ADDIT. COOLING HOLES & NEW SEALS		545	SR Technics Switzerland
137587	50L287; 50L678	EASA;FAA;CAAC;ANAC	7	28	72-52-37	PW4 STAGE 2 HPT DUCT SUPPORT (SEGMENT)	Package A	CLN/INSP	CLEANING AND INSPECTION		385	SR Technics Switzerland
137587	50L287; 50L678	EASA;FAA;CAAC;ANAC	7	28	72-52-37	PW4 STAGE 2 HPT DUCT SUPPORT (SEGMENT)	Package B	1	REPLACE ANTI-ROTATION PIN		455	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package C	2	SURFACE DAMAGE BLEND REPAIR		1055	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package E	4	BLADE CONTACT FACE COAT REPAIR		1985	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package F	5	SNAP DIAMETER PLASMA SPRAY REPAIR		4415	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package G	6	REMOVE BENT COUNTERWEIGHT TAB REPAIR		1270	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package H	7	BALANCE REPAIR		1395	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package I	8	SHOTPEEN REPAIR		1055	SR Technics Switzerland
137590	50N008; 50N521		34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package M	CLN-01	REMOVE CORROSION BY WET BLASTING		525	SR Technics Switzerland
137590	50N008; 50N521	EASA;FAA;CAAC;ANAC;CAA UK	34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package A	CLN/INSP	CLEANING AND INSPECTION		1450	SR Technics Switzerland
137590	50N008; 50N521	EASA;FAA;CAAC;ANAC;CAA UK	34	28	72-53-39	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER ROTATING) AIR	Package B	1	KNIFE-EDGE SEAL BLEND REPAIR		1665	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137591	50N434-01; 50N450-01; 51N	EASA;FAA;ANAC										
137591	50N434-01; 50N450-01; 51N	EASA;FAA;ANAC	5	28	72-53-29	PW4 STAGE 3 LPT (OUTER) DUCT SEGMENT	Package SB00	FAA-2020-25-09	REMOVE AND REPLACE 3RD STG LPT OTD		400	SR Technics Switzerland
137591	50N434-01; 50N450-01; 51N	EASA;FAA;CAAC;ANAC	5	28	72-53-29	PW4 STAGE 3 LPT (OUTER) DUCT SEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		400	SR Technics Switzerland
137598	50N291-01; 50N527-01	EASA;FAA;CAAC;ANAC										
137598	50N291-01; 50N527-01	EASA;FAA;CAAC;ANAC	4	28	72-53-34	PW4 STG 5 LPT (OUTER) AIRSEALING RING	Package A	CLN/INSP	CLEANING & INSPECTION		105100	SR Technics Switzerland
137599	50N292-01; 50N528-01; 51N	EASA;FAA;CAAC;ANAC										
137599	50N292-01; 50N528-01; 51N	EASA;FAA;CAAC;ANAC	5	28	72-53-35	PW4 STG 6 LPT (OUTER) AIRSEALING RING	Package A	CLN/INSP	CLEANING & INSPECTION		75	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package H	7	REAR DIAMETER COAT REPAIR		3090	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package I	8	FRONT DIAMETER PLASMA/DUAL WIRE ELECTRIC ARC COAT REPAIR		2180	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package J	9	BALANCE REPAIR		1185	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package N	13	SHOTPEEN REPAIR		1095	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package O	INSP-01	REMOVE CORROSION BY WET BLASTING		525	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package SB00	AD 2015-22-03	LPT 4TH STAGE AIR SEAL REPLACEMENT	ONLY FOR 100" ENGINE	465	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package SB00	AD 2015-22-03	LPT 4TH STAGE AIR SEAL REPLACEMENT	ONLY FOR 94" ENGINE	465	SR Technics Switzerland
137601	50N009; 50N346; 50N478;	50N478-001; 51N038; 51N113; 51N119	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package SB01	AD 2018-13-02	PREVENT FAILURE OF THE 4TH STAGE LPT AIR SEAL		220	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;ANAC;CAA UK	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package G	6	BLADE MATING SURFACE PLASMA COAT REPAIR		3330	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1195	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package B	1	SURFACE DAMAGE BLEND REPAIR		900	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package C	2	KNIFE-EDGE SEALS BLEND REPAIR		1270	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package D	3	ANTI-ROTATION LUG WELD REPAIR	P/N 50N009	3655	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package F	5	FRONT FACE PLASMA SPRAY REPAIR		3495	SR Technics Switzerland
137601	50N009; 50N346; 50N478; 5	EASA;FAA;CAAC;ANAC;CAA UK	41	28	72-53-40	LOW PRESSURE TURBINE (LPT) - STAGE 4 LPT (ROTATING) AIRSEAL	Package D	10	WELD REPAIR ANTI-ROTATION LUG	P/N 50N346, P/N 50N478, P/N 50N478-001, P	3655	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package D	3	ANTI-ROTATION LUG WELD REPAIR		3775	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package G	6	FRONT FACE PLASMA SPRAY REPAIR		3930	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package H	7	BLADE MATING SURFACE COAT REPAIR		3930	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package I	8	REAR MATING DIAMETER PLASMA COAT REPAIR		3250	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package J	9	FRONT MATING DIAMETER PLASMA COAT/DUAL WIREELECTRIC ARC COAT REPAIR		3635	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package K	10	BALANCE REPAIR		1235	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package M	12	ANTI-ROTATION LUG WELD REPAIR	P/N 50N324A, 50N419	2630	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 50N419		30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package N	13	SHOTPEEN REPAIR		1155	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 5	EASA;FAA;CAAC;ANAC	30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1870	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 5	EASA;FAA;CAAC;ANAC	30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package B	1	KNIFE-EDGE SEALS BLEND REPAIR		1245	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 5	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package AE		REMOVE CORROSION		525	SR Technics Switzerland
137602	50N162; 50N324; 50N347; 5	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-53-41	LOW PRESSURE TURBINE (LPT) - STAGE 5 LPT (ROTATING) AIRSEAL	Package C	2	SURFACE DAMAGE BLEND REPAIR		1255	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC										
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package A	CLN/INSP	CLEANING AND INSPECTION		430	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package B	1	WELD REPAIR		1605	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package C	1	COLD STRAIGHTENING REPAIR		625	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package D	2	REPLACE WORN TUBE REPAIR		1365	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package E	3	REPLACE WORN GUIDES REPAIR		1080	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package F	4	REPLACE WORN TCC MANIFOLD (FRONT) BRACKET REPAIR		760	SR Technics Switzerland
137621	50T085; 50T086; 50T087; 5(	EASA;FAA;CAAC;ANAC	32	28	72-09-76	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package G	SPM	REPAIR OF DEFECT NUTS, GUIDES, BRACKETS AND RIVETS ACCORDING SPM		630	SR Technics Switzerland
137625	50T060; 50T061; 50T062; 5(	EASA;FAA;CAAC;ANAC										
137625	50T060; 50T061; 50T062; 5(	EASA;FAA;CAAC;ANAC	29	28	72-09-75	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package A	CLN/INSP	CLEANING AND INSPECTION		430	SR Technics Switzerland
137625	50T060; 50T061; 50T062; 5(	EASA;FAA;CAAC;ANAC	29	28	72-09-75	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package B	1	WELD REPAIR TURBINE CASE COOLING MANIFOLD		2195	SR Technics Switzerland
137625	50T060; 50T061; 50T062; 5(	EASA;FAA;CAAC;ANAC	29	28	72-09-75	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package B	2	REPLACE THE BRACKET AND PIN		2195	SR Technics Switzerland
137625	50T060; 50T061; 50T062; 5(	EASA;FAA;CAAC;ANAC	29	28	72-09-75	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING MANI	Package B	3	NUTPLATE REPLACEMENT REPAIR		2195	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package E	4	REPLACE DAMAGED SUPPORT		1055	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package F	5	REPLACE DAMAGED SEAL		910	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package H	7	STUD REPLACEMENT REPAIR		810	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package SB00	PW4ENG 72-513	3RD STG DUCT AND SEAL SUPPORT MODIFICATION		1475	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package SB01	PW4ENG 72-294	3RD STG REPLACEMENT OF LPT DUCT SEAL		1475	SR Technics Switzerland
137640	50N260; 50N331; 50N536		28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package SB02	PW4G-100-72-41	REPLACE/MODIFY THE 3RD STAGE LPT SEALING RING SUPPORT ASSY AND 3RD STAGE LPT DUCT SEGMENTS.		1475	SR Technics Switzerland
137640	50N260; 50N331; 50N536	EASA;FAA;CAAC;ANAC	28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package A	CLN/INSP	CLEANING AND INSPECTION		1050	SR Technics Switzerland
137640	50N260; 50N331; 50N536	EASA;FAA;CAAC;ANAC	28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package B	1	SURFACE DAMAGE BLEND REPAIR		410	SR Technics Switzerland
137640	50N260; 50N331; 50N536	EASA;FAA;CAAC;ANAC	28	21	72-53-18	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) DUCT ASSEMBL	Package D	3	REPLACE DAMAGED DUCT SEGMENT REPAIR		1605	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package F	5	REPAIR THE DAMPER JOURNAL WITH A BUSHING		7375	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package J	9	SURFACE DAMAGE BLEND REPAIR		455	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package K	10	OVERSIZED PIN REPLACEMENT REPAIR		775	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package P	5	CHROME PLATE BUSHING		4475	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package SB00	PW4ENG 72-179	BEARINGS FRT REPLACEMENT OF OIL TUBES AND SEALS		1055	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 51G250		38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package SB01	PW4ENG 72-204	SEAL ASSEMBLY, NO 2 BEARING - MODIFICATION OF		5985	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 5	EASA;FAA;CAAC;ANAC	38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		895	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 5	EASA;FAA;CAAC;ANAC	38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package B	1	PIN REPLACEMENT REPAIR		775	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137641	50G417; 51D766; 51G082; 5	EASA;FAA;CAAC;ANAC	38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package C	2	REPLACE HELICOIL INSERT		1260	SR Technics Switzerland
137641	50G417; 51D766; 51G082; 5	EASA;FAA;CAAC;ANAC	38	28	72-34-06	INTERMEDIATE CASE - NO. 2 BEARING SUPPORT ASSEMBLY	Package E	4	PLASMA SPRAY THE INTERMEDIATE CASE SNAP DIAMETER		4060	SR Technics Switzerland
137643	50H100; 53H367		28	28	72-35-36	HIGH PRESSURE COMPRESSOR (HPC) - NO. 3 BEARING (INNER REAR H	Package C	2	RESTORE CORROSION PROTECTIVE COATING		1555	SR Technics Switzerland
137643	50H100; 53H367		28	28	72-35-36	HIGH PRESSURE COMPRESSOR (HPC) - NO. 3 BEARING (INNER REAR H	Package D	3	BLEND REPAIR		610	SR Technics Switzerland
137643	50H100; 53H367		28	28	72-35-36	HIGH PRESSURE COMPRESSOR (HPC) - NO. 3 BEARING (INNER REAR H	Package E	4	FRONT FACE BLEND REPAIR		610	SR Technics Switzerland
137643	50H100; 53H367	EASA;FAA;CAAC;ANAC	28	28	72-35-36	HIGH PRESSURE COMPRESSOR (HPC) - NO. 3 BEARING (INNER REAR H	Package A	CLN/INSP	CLEANING AND INSPECTION		610	SR Technics Switzerland
137643	50H100; 53H367	EASA;FAA;CAAC;ANAC	28	28	72-35-36	HIGH PRESSURE COMPRESSOR (HPC) - NO. 3 BEARING (INNER REAR H	Package B	1	RESTORE ANTIGALLANT		700	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 310T4021-5; 310T4021-7		24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package E	01.Feb	SHEAR PIN HOLE REPAIR		2715	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 310T4021-5; 310T4021-7		24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package F	01.Feb	SCRATCH AND GOUGE REPAIR		1265	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 3:	EASA;FAA;CAAC;ANAC	24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1100	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 3:	EASA;FAA;CAAC;ANAC	24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package B	01.Jan	BUSHING REPLACEMENT		2900	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 3:	EASA;FAA;CAAC;ANAC	24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package C	01.Feb	LUG HOLE REPAIR		3405	SR Technics Switzerland
137649	310T3021-1; 310T4021-1; 3:	EASA;FAA;CAAC;ANAC	24	21	71-21-16	FWD ENGINE MOUNT - FITTING ASSY - 94"	Package D	01.Feb	JOURNAL REPAIR		5300	SR Technics Switzerland
137651	310T3032-1; 310T3032-2; 3:	EASA;FAA;CAAC;ANAC										
137651	310T3032-1; 310T3032-2; 3:	EASA;FAA;CAAC;ANAC	23	21	71-21-16	AFT ENGINE MOUNT - TANGENTIAL LINK - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1115	SR Technics Switzerland
137651	310T3032-1; 310T3032-2; 3:	EASA;FAA;CAAC;ANAC	23	21	71-21-16	AFT ENGINE MOUNT - TANGENTIAL LINK - 94"	Package B	06.Jan	BEARING REPLACEMENT		1585	SR Technics Switzerland
137651	310T3032-1; 310T3032-2; 3:	EASA;FAA;CAAC;ANAC	23	21	71-21-16	AFT ENGINE MOUNT - TANGENTIAL LINK - 94"	Package C	06.Feb	BEARING HOLE REPAIR		1915	SR Technics Switzerland
137656	50J603-01; 51J039-01		27	28	72-41-22	NO.3 BEARING AND AIRFRAME (OIL VENT AND TURBINE COOLING AIF	Package C	5	REPAIR SEAL RING GROOVE	PN 51J039-01	1020	SR Technics Switzerland
137656	50J603-01; 51J039-01		27	28	72-41-22	NO.3 BEARING AND AIRFRAME (OIL VENT AND TURBINE COOLING AIF	Package D	3	RESTORE ANTIGALLING COMPOUND		470	SR Technics Switzerland
137656	50J603-01; 51J039-01	EASA;FAA;CAAC;ANAC	27	28	72-41-22	NO.3 BEARING AND AIRFRAME (OIL VENT AND TURBINE COOLING AIF	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
137656	50J603-01; 51J039-01	EASA;FAA;CAAC;ANAC	27	28	72-41-22	NO.3 BEARING AND AIRFRAME (OIL VENT AND TURBINE COOLING AIF	Package C	2	REPAIR SEAL RING GROOVE	PN 50J603-01	1020	SR Technics Switzerland
137710	70R639; 70R666; 70T520	EASA;FAA;CAAC;ANAC										
137710	70R639; 70R666; 70T520	EASA;FAA;CAAC;ANAC	24	28	72-61-69	MAIN GEARBOX - OIL TANK DEAERATOR ASSEMBLY	Package B	1	ANODIZE TOUCH-UP		345	SR Technics Switzerland
137710	70R639; 70R666; 70T520	EASA;FAA;CAAC;ANAC	24	28	72-61-69	MAIN GEARBOX - OIL TANK DEAERATOR ASSEMBLY	Package C	2	REPLACE HELICAL COIL INSERTS		420	SR Technics Switzerland
137715	50L013; 50L242		30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package C	2	FRONT OUTER MATING FACE PLASMA SPRAY REPAIR		3805	SR Technics Switzerland
137715	50L013; 50L242		30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package D	3	PLASMA SPRAY REPAIR WIRE SEAL AXIAL MATING FACE		3305	SR Technics Switzerland
137715	50L013; 50L242		30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package E	4	PLASMA SPRAY REPAIR ID BUMPER AXIAL MATING FACE		3305	SR Technics Switzerland
137715	50L013; 50L242		30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package F	5	PLASMA SPRAY REPAIR FRONT INNER SNAP DIAMETER		3305	SR Technics Switzerland
137715	50L013; 50L242		30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package L	11	UMBALANCE MARKING REPAIR		565	SR Technics Switzerland
137715	50L013; 50L242	EASA;FAA;CAAC;ANAC	30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package A	CLN/INSP	CLEANING AND INSPECTION		445	SR Technics Switzerland
137715	50L013; 50L242	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-52-23	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT BLADE RETAINING PLA	Package B	1	SURFACE DAMAGE BLEND REPAIR		645	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB10	PW4ENG-1-09	IMC-LINER BRACKETS INSPECTION		545	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB11	PW4ENG 72-848	IMC-MODI TO PREVENT LINER LIBERATION		825	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB12	PWENG 72-743	REPLACEMENT WITH ASYMMETRIC VANE PATTERN		26010	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB16	72-264	CONVERSION FROM AI OR MCD TO BOEING APPLICATIONS		150	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package T	110	REPLACE THE CENTER BRACKET ASSEMBLIES		2020	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package T	122	REAR BRACKET REPLACEMENT REPAIR		2020	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package T	35	REPAIR THE THREADED HOLES IN THE GROUND HANDLING PAD		2020	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package T	37	REPLACE THE BAFFLES		2020	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package U	31	CRACKS/DAMAGE WELD REPAIR		4140	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package V	32	MACHINE THE FRONT MOUNT INNER SURFACE		1290	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package W	123	BLEND THRUST CLEVIS BRACKET		955	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package X	34	REPLACE A FAIRING WITH RIVETS ALL AROUND WITH A FAIRING WITHOUT INITIAL RIVET HOLES		5095	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Z	39	REPLACE THE TIMING PIN		655	SR Technics Switzerland
137716	50G849; 50G849-001; 50G918; 50G918-001; 50G918-005; 51G021; 51G021		50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Z	41	APPLY ANODIZE TOUCH-UP SOLUTION		655	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3590	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AA	42	WELD THE NO. 2 BEARING ALIGNMENT PIN HOLE		3805	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AC	44	BLEND SURFACE DAMAGE ON THE FAN EXIT CASE FLANGE ASSEMBLY		955	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AD	49	SURFACE DAMAGE BLEND REPAIR		1815	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AE	100	STOP DRILL THE FAN EXIT FAIRING COVER CRACKS		345	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AF	101	FAN EXIT FAIRING COVER REPLACEMENT		1185	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AG	107	REPLACE HELICAL COIL INSERTS IN BOSSES WITH INSERTS		985	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AH	SPM 70-11-00	ADD ENGINE SERIAL NUMBER ACC. SPM 70-11-00 GENERAL-01		185	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AK	46	REPLACE OR BOND A STRUT SEAL		1585	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AL	140	BLEND REPAIR BRG 2 ALIGNEMENT PIN HOLE		140	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AM	70	REPLACE CENTER BRACKETS		1125	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AN	109	REPLACE FRONT BRACKETS		1125	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package B	74	REPLACE NUT PLATES		1045	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package C	105	BLEND REPAIR FAIRING ASSEMBLY		1235	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package H	15	INSTALL INSERTS IN THE ANGLE GEARBOX MOUNT PAD THREADED HOLES		1025	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package I	45	REPLACE THE PROTECTIVE LAYER		2760	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package J	17	REPLACE REAR INNER FLANGE HELICAL COIL INSERTS WITH INSERTS		2975	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package J	23	REPLACE FOURTH STATOR MOUNTING FLANGE HELICAL COIL INSERTS		2975	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package J	36	SEALANT REPAIR		2975	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package K		18 REPLACE INNER FAN EXIT CASE MOUNTING FLANGE HELICAL COIL INSERTS WITH INSERTS		1040	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package L		19 REPAIR THREADED BOSS HOLES OR REPLACE BOSS HOLE HELICAL COIL INSERTS WITH INSERTS		1025	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package M		20 BLEND THE SURFACE DAMAGE		1290	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package N		21 REPLACE NUT PLATE ON FRONT FAN EXIT CASE BRACKET ASSEMBLY		580	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package O		22 REPLACE A FAIRING WITH NO RIVETS AT THE LEADING EDGE WITH THE SAME		1400	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package P		24 REPLACE HELICAL COIL INSERTS AT 2, 4, AND 8 O'CLOCK POSITIONS		1070	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Q		26 REPLACE THE FRONT FAN EXIT CASE BRACKET ASSEMBLIES		505	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package R		27 REPLACE THE REAR FAN EXIT CASE BRACKET ASSEMBLIES		965	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package S		29 REPLACE THE TRUST MOUNT BUSHINGS		3605	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB01	PW4ENG 72-448	PROVIDE SHORTER INSERT FOR ALTERNATE USE WHERE REQUIRED		575	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB02	PW4ENG 72-490	CONVERSION OF A PW4460 OR PW4462 TO A PW4460 (-3) OR PW4462 (-3)		9695	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB03	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060,TO A PW4052(-3), PW4056(-3), OR PW4060(-3)		9695	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB04	PW4ENG 72-572	CONVERSION OF PW4152/56A/58 TO -3 / M34		9695	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB05	PW4ENG 72-669	REPLACEMENT OF WITH ALUMINUM FAIRINGS		520	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB06	PW4ENG 72-778	IMPROVED ATTACHMENT STRUT FAIRINGS		12485	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB07	PW4ENG 73-0088	PROBE (OR TRANSDUCER), N1, SPEED, IMPROVED INSTALLATION CON 2.C. INSTALL STUD		360	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB08	PW4ENG 72-333	X-RAY INSPECTION OF THRUST BRACKET WELDS		630	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB09	PW4ENG 72-767	INSPECTION OF STRUT FAIRINGS FOR MISSING OR LOOSE RIVETS		485	SR Technics Switzerland
137716	50G849; 50G849-001; 50G9	EASA;FAA;CAAC;ANAC;CAA UK	50	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package I		16 REPLACE NO. 1 BEARING SUPPORT FLANGE HELICAL COIL INSERTS WITH INSERTS		2760	SR Technics Switzerland
137717	50G034		28	28	72-62-10	ANGLE GEARBOX - ANGLE GEARBOX HOUSING ASSEMBLY	Package B		6 REPAIR THE BORE WITH A BUSHING	FOR SHOP VISITS ONLY	1755	SR Technics Switzerland
137717	50G034		28	28	72-62-10	ANGLE GEARBOX - ANGLE GEARBOX HOUSING ASSEMBLY	Package C		2 ANODIZE TOUCH-UP	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
137717	50G034		28	28	72-62-10	ANGLE GEARBOX - ANGLE GEARBOX HOUSING ASSEMBLY	Package D		3 SURFACE DAMAGE BLEND REPAIR	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
137717	50G034		28	28	72-62-10	ANGLE GEARBOX - ANGLE GEARBOX HOUSING ASSEMBLY	Package E		4 PLASMA SPRAY THE OUTER DIAMETER	FOR SHOP VISITS ONLY	1080	SR Technics Switzerland
137717	50G034	EASA;FAA;CAAC;ANAC	28	28	72-62-10	ANGLE GEARBOX - ANGLE GEARBOX HOUSING ASSEMBLY	Package B		1 REPLACE HELICAL COIL INSERTS	FOR SHOP VISITS ONLY	1755	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package B		1 REPLACE HELICAL COIL INSERTS		825	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package C		2 ANODIZE TOUCH-UP		500	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package D		3 SURFACE DAMAGE BLEND REPAIR		605	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package E		4 PLATE THE GEARBOX HOUSING ID WITH NICKEL		2360	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package F		5 BOTTOM COVER ID NICKEL PLATE REPAIR		2075	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package H		7 HOLLOW PIN REPLACEMENT REPAIR		1470	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package I		8 REPLACE THE BUSHING		2045	SR Technics Switzerland
137718	50G001		25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package J		9 UPPER BEARING JOURNAL BUSHING REPAIR		2775	SR Technics Switzerland
137718	50G001	EASA;FAA;CAAC;ANAC	25	28	72-62-01	ANGLE GEARBOX - HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1755	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package H		7 SMOOTH THE DAMAGE		4655	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package I		8 CORROSION REMOVAL (INNER SURFACE) REPAIR		4520	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package J		9 B1 FLANGE SCALLOP CRACK REPAIR		980	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package L		11 COATING REPLACEMENT (INNER SURFACE) REPAIR		1825	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package N		13 FLANGE B BOLTHOLES BLEND/MACHINE REPAIR		775	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package O		14 CORROSION REMOVAL (INNER SURFACE) REPAIR		4045	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package P		15 DOUBLER REPAIR 94"	OEM CIR REPAIR	4835	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package SB00	PW4ENG 72-347	MODIFICATION OF TO INCORPORATE ADDITIONAL CUT IN THE B1 FLANGE		1710	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 50D901-001; 51D720; 53D925		37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package SB01	PW4ENG 72-754	MODIFICATION OF FAN EXIT OUTER CASE		3540	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		3620	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package B		1 APPLY ANODIZE TOUCH-UP SOLUTION		605	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package D		3 STRAIGHTEN THE B1 FLANGE AND CRACK WELD REPAIR		3425	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package G		6 PLASMA COAT THE OUTER REAR FLANGE SNAP DIAMETER		4250	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC;CAA UK	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package C		2 SMOOTH THE DAMAGE		1020	SR Technics Switzerland
137725	50D361; 50D364; 50D901; 5	EASA;FAA;CAAC;ANAC;CAA UK	37	28	72-33-03	FAN CASE - FAN EXIT (OUTER) CASE	Package E		4 REPAIR A VANE BOLTHOLE WITH A BUSHING 94"	OEM CIR REPAIR	4370	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package G		6 WELD REPAIR OF STATOR CYLINDER LOWER SUPPORT LUGS		4700	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package H		7 WELD REPAIR OF CRACKED BOLT HOLES IN FLANGE		4335	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package I		8 WELD REPAIR OF CRACKS IN THE HPC FRONT CASE ASSEMBLY		6240	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package J		9 BLEND METAL SURFACE DAMAGE		1115	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package M		12 WELD REPAIR OF SVA UPPER AND LOWER SUPPORT LUG HOLES		6240	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package N		13 PLASMA SPRAY REPAIR THE REAR FLANGE FACE		3710	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package O		14 PLASMA SPRAY REPAIR THE FRONT FLANGE FACE		4195	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package P		15 PLASMA SPRAY REPAIR THE 8TH STAGE STATOR MATING SNAP DIAMETER		6495	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package Q		16 PLASMA SPRAY REPAIR THE REAR SNAP DIAMETER		3555	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package R		17 PLASMA SPRAY REPAIR THE FRONT SNAP DIAMETER		8910	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package R		31 PLASMA SPRAY REPAIR THE FRONT SNAP DIAMETER		8910	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package S		18 FRONT FLANGE BOLT HOLE REPAIR (FLANGE E)		2635	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB00	PW4ENG 72-220	CASE ASSEMBLY, HPC, FRONT - REPLACEMENT OF		1365	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB02	PW4ENG 72-755	ROTOR STATOR MODULE, HPC - MODIF. OF TO INCORP. A RING CASE	BOEING CONFIG.	3070	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB02	PW4ENG 72-756	ROTOR STATOR MODULE, HPC - MODIF. OF TO INCORP. A RING CASE	AIRBUS CONFIG.	3070	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB02	PW4ENG 72-757	ROTOR STATOR MODULE, HPC - MODIF. OF TO INCORP. A RING CASE	MCDONNELL CONFIG	3070	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB03	PW4ENG 72-326	CASE ASSEMBLY, HPC, FRONT - INCORPORATION OF BORESCOPE PLUGS WITH LOCKING TAB WASHERS		1365	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB04	PW4ENG 72-837	CASE ASSEMBLY, HPC, FRONT		330	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB05	PW4ENG 72-679	HPC,MODI OF FRT CASE+SHROUD WITH COATING		545	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package U		54 STAGE 7 FLOWPATH WEAR WELD BUILD-UP		1720	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package X		23 HPC VSV-BEARING REPLACEMENT		785	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package Y		24 REPLACE HPC FRONT CASE/OUTER AIRSEAL SET HELICOIL INSERTS		1105	SR Technics Switzerland
137726	50S001; 50S001-001; 50S007-01; 51H224; 51H532; 51H532-001; 51H532-0		51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package Z		25 BORESCOPE THREADED .5625-18 HOLE INSERT REPAIR		1105	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package E		4 REPLACE .250-28 THREADED INSERTS FOR HPC FRONT CASE/OUTER AIRSEAL SET 6/7 OUTER SHROUD BOLTS		760	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AB		27 BLEND METAL SURFACE DAMAGE		1040	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AC		48 COMPRESSOR STATOR CYLINDER SUPPORT MOUNTING BRACKET LOCATING PIN REPLACEMENT REPAIR		1225	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AD		49 STAGE 6 SHROUD LIP FACE PLASMA COAT REPAIR		3350	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AE		30 PLASMA SPRAY REPAIR THE REAR SNAP DIAMETER		3695	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AF		41 SHROUD GROOVE WEAR WELD REPAIR		6720	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AG		47 STAGE 5 SHROUD AXIAL CONTACT SURFACES PLASMA COAT REPAIR		3295	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AH		DISMANTLE AND COMLETE BRACKETS		645	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AI		35 REPLACE THE 7TH STAGE HPC RING STOP		690	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AJ		37 PLASMA SPRAY REPAIR THE 6/7TH STAGE STATOR MATING FACE		6165	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AK		42 STAGE 5-7 SHROUD AXIAL CONTACT SURFACES PLASMA COAT REPAIR		7290	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AL		39 SPLIT FLANGE BOLT HOLES EDGE REPAIR		945	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AN		44 REPLACEMENT OF HPC VSV BEARINGS		6725	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AN		53 STAGE 5 THRU STAGE 7 SHROUD GROOVES WEAR WELD REPAIR		6725	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package B		1 REPLACE WORN HPC BEARING		1270	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package D		3 REPLACE THREADED INSERT FOR HPC FRONT CASE/OUTER AIRSEAL SET BORESCOPE BOSS		680	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package F		5 BUSHING REPAIR - HPC FRONT CASE/OUTER AIRSEAL SET STATOR ACTUATOR SUPPORT LUGS		2775	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC;CAA UK	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package A	CLN/INSP	CLEANING AND INSPECTION		3000	SR Technics Switzerland
137726	50S001; 50S001-001; 50S00	EASA;FAA;CAAC;ANAC;CAA UK	51	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package C		2 REPLACE HPC FRONT CASE/OUTER AIRSEAL SET HELICOIL INSERTS		1280	SR Technics Switzerland
137727	51D747; 51D747-001; 53D316		35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package F		5 REPLACE HELICAL COIL INSERTS		645	SR Technics Switzerland
137727	51D747; 51D747-001; 53D316		35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package G		10 UPPER BEARING JOURNAL BUSHING REPAIR		3295	SR Technics Switzerland
137727	51D747; 51D747-001; 53D316		35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package SB00	PW4ENG A72-656	INSPECTION OF THE SUPPORT FOR A THIN WALL CONDITION		1915	SR Technics Switzerland
137727	51D747; 51D747-001; 53D3	EASA;FAA;CAAC;ANAC	35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		435	SR Technics Switzerland
137727	51D747; 51D747-001; 53D3	EASA;FAA;CAAC;ANAC	35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package C		8 PLASMA SPRAY REAR SNAP DIAMETER BY (PWA 53-13 OR PWA 53-38)		2150	SR Technics Switzerland
137727	51D747; 51D747-001; 53D3	EASA;FAA;CAAC;ANAC	35	28	72-34-20	INTERMEDIATE CASE - NO. 1.5 BEARING SUPPORT ASSEMBLY	Package E		4 REPLACE CLINCH NUTS		645	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package D		3 NICKEL PLATE THE FRONT ID		1375	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package E		4 NICKEL PLATE THE REAR OD		1545	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package F		5 NICKEL PLATE THE OIL TUBE HOLE INNER DIAMETER		1625	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package G		6 NICKEL PLATE THE FLANGE FACE		1545	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package H		7 REPLACE THE BUSHINGS IN THE MOUNT CLEVISES		1115	SR Technics Switzerland
137729	70R051; 70R911		24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package I		8 REPAIR THE REAR ID WITH A BUSHING		2325	SR Technics Switzerland
137729	70R051; 70R911	EASA;FAA;CAAC;ANAC	24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package B		1 REPLACE HELICAL COIL INSERTS		560	SR Technics Switzerland
137729	70R051; 70R911	EASA;FAA;CAAC;ANAC	24	28	72-61-23	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY	Package C		2 ANODIZE TOUCH-UP		485	SR Technics Switzerland
137730	70R061		25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package C		2 ANODIZE TOUCH-UP		770	SR Technics Switzerland
137730	70R061		25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package D		3 NICKEL PLATE THE OD		1555	SR Technics Switzerland
137730	70R061		25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package E		4 REPAIR THE FRONT ID WITH A BUSHING		2020	SR Technics Switzerland
137730	70R061		25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package F		5 REPAIR THE MIDDLE ID WITH A BUSHING		2020	SR Technics Switzerland
137730	70R061		25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package G		6 REPAIR THE REAR ID WITH A BUSHING		2020	SR Technics Switzerland
137730	70R061	EASA;FAA;CAAC;ANAC	25	28	72-61-30	MAIN GEARBOX - GEARBOX BEARING HOUSING ASSEMBLY	Package B		1 REPLACE HELICAL COIL INSERTS		590	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package D		3 NICKEL PLATE THE OD		1200	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package E		4 REPAIR THE FRONT ID WITH A BUSHING		1535	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package F		5 REPAIR THE MIDDLE ID WITH A BUSHING		1985	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package G		6 REPAIR THE REAR ID WITH A BUSHING		1535	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package H		7 REPLACE LOCATING PIN		400	SR Technics Switzerland
137731	70R063; 70R910		24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package I		8 REPAIR THE LOCATING PIN HOLE BUSHING	POST REQUISITE REPAIR-07 ALLREADY INCLUI	1750	SR Technics Switzerland
137731	70R063; 70R910	EASA;FAA;CAAC;ANAC	24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package B		1 REPLACE HELICAL COIL INSERTS		485	SR Technics Switzerland
137731	70R063; 70R910	EASA;FAA;CAAC;ANAC	24	28	72-61-28	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) BEARING HOUSING A	Package C		2 ANODIZE TOUCH-UP		175	SR Technics Switzerland
137732	70R065; 71R117; 71R169		24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package E		4 REPAIR THE FRONT ID WITH A BUSHING		855	SR Technics Switzerland
137732	70R065; 71R117; 71R169		24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package F		5 REPAIR THE MIDDLE ID WITH A BUSHING		855	SR Technics Switzerland
137732	70R065; 71R117; 71R169		24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package G		6 REPAIR THE REAR ID WITH A BUSHING		990	SR Technics Switzerland
137732	70R065; 71R117; 71R169	EASA;FAA;ANAC	24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package D		3 NICKEL PLATE THE OUTER DIAMETER		1000	SR Technics Switzerland
137732	70R065; 71R117; 71R169	EASA;FAA;CAAC;ANAC	24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package B		1 REPLACE HELICAL COIL INSERTS		425	SR Technics Switzerland
137732	70R065; 71R117; 71R169	EASA;FAA;CAAC;ANAC	24	28	72-61-26	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package C		2 ANODIZE TOUCH-UP		340	SR Technics Switzerland
137733	70R067		26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package C		2 ANODIZE TOUCH-UP		370	SR Technics Switzerland
137733	70R067		26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package D		3 NICKEL PLATE THE OD		1555	SR Technics Switzerland
137733	70R067		26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package E		4 REPAIR THE FRONT ID WITH A BUSHING		1905	SR Technics Switzerland
137733	70R067		26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package F		5 REPAIR THE MIDDLE ID WITH A BUSHING		1905	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137733	70R067		26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package J	SPM	REMOVE DEFECTIVE BOLTS FROM CLAMP	SPM 70-00-00-350-006/ SPOP 416	180	SR Technics Switzerland
137733	70R067	EASA;FAA;CAAC;ANAC	26	28	72-61-32	MAIN GEARBOX - GEARBOX IDG DRIVE BEARING HOUSING ASSEMBLY	Package B	1	REPLACE HELICAL COIL INSERTS		590	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 70R	647-001; 70R654; 70R914; 70R914-001; 70R9	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package SB01	PW4ENG 72-525	OIL FILTER HOUSING : NEW DUAL ELEMENT FILTER	FOR SHOP VISITS ONLY	1030	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package B	1	REPLACE HELICAL COIL INSERTS	FOR SHOP VISITS ONLY	420	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package C	2	ANODIZE TOUCH-UP	FOR SHOP VISITS ONLY	345	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package D	3	REPAIR THE FRONT ID WITH A BUSHING	FOR SHOP VISITS ONLY	865	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package E	4	REPAIR THE MIDDLE IDS WITH A BUSHING	FOR SHOP VISITS ONLY	865	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package F	5	REPAIR THE REAR BORES WITH BUSHINGS	FOR SHOP VISITS ONLY	865	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package H	6	REPLACE DAMAGED OR LOOSE STUDS	FOR SHOP VISITS ONLY	745	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package H	7	REPLACE DAMAGED OR LOOSE STUDS	FOR SHOP VISITS ONLY	745	SR Technics Switzerland
137734	51R184; 70R093; 70R647; 7(	EASA;FAA;CAAC;ANAC	28	28	72-61-60	MAIN GEARBOX - MAIN OIL FILTER HOUSING ASSEMBLY	Package SB00	PW4ENG 72-701	MGB-OIL FILTER HOUSING-MODIF.WITH STUDS	FOR SHOP VISITS ONLY	1185	SR Technics Switzerland
137735	70R102		24	28	72-61-18	MAIN GEARBOX - GEARBOX DEOILER HOUSING ASSEMBLY	Package C	2	ANODIZE TOUCH-UP		320	SR Technics Switzerland
137735	70R102		24	28	72-61-18	MAIN GEARBOX - GEARBOX DEOILER HOUSING ASSEMBLY	Package D	3	NICKEL PLATE THE OD		810	SR Technics Switzerland
137735	70R102		24	28	72-61-18	MAIN GEARBOX - GEARBOX DEOILER HOUSING ASSEMBLY	Package E	4	NICKEL PLATE THE FLANGE FACE		810	SR Technics Switzerland
137735	70R102	EASA;FAA;CAAC;ANAC	24	28	72-61-18	MAIN GEARBOX - GEARBOX DEOILER HOUSING ASSEMBLY	Package B	1	REPLACE HELICAL COIL INSERTS		345	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package E	4	PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 FRONT SEAL SEAT JOURNAL		3475	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package F	5	NO. 2 FRONT SEAL SEAT SHOULDER COAT REPAIR		4660	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package G	6	PLASMA SPRAY REPAIR - HPC FRONT HUB SNAP DIAMETER		3260	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package H	7	PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING SHOULDER		3260	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package I	8	PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING SEAL SEAT PILOT		3200	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package J	9	PLASMA SPRAY REPAIR - HPC FRONT HUB NO. 2 BEARING JOURNAL		3685	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package K	10	REPAIR ANTI-TORQUE SLOTS		3115	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package L	11	BLEND REPAIR ANTI-TORQUE LUGS		1105	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package N	13	THREAD BLEND REPAIR		745	SR Technics Switzerland
137736	50H470; 51H572		32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package SB00	PW4ENG 72-201	HPC MOD.OF FRT HUB + DRUM ROT. DISK ASSY		545	SR Technics Switzerland
137736	50H470; 51H572	EASA;FAA;CAAC;ANAC	32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package A	CLN/INSP	CLEANING AND INSPECTION		1235	SR Technics Switzerland
137736	50H470; 51H572	EASA;FAA;CAAC;ANAC;CAA UK	32	28	72-35-05	HIGH PRESSURE COMPRESSOR (HPC) - FRONT HUB	Package D	3	SURFACE DAMAGE BLEND REPAIR		1560	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package C	2	NICKEL PLATE THE REAR SNAP DIAMETER		1115	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package D	3	SURFACE DAMAGE BLEND REPAIR		465	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package E	4	PIN AND COLLAR SEALING COMPOUND REPAIR		545	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package F	5	CRACK WELD REPAIR		1105	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package G	6	BENT MOUNT TAB COLD STRAIGHTENING REPAIR		430	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package H	7	FLANGE BOLT HOLE WELD REPAIR		855	SR Technics Switzerland
137737	50A559; 51A006-01		28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package M	INSP/CHECK 3	REPLACE DRIVE SHAFT HOUSING HELICOIL		360	SR Technics Switzerland
137737	50A559; 51A006-01	EASA;FAA;CAAC;ANAC	28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	650	SR Technics Switzerland
137737	50A559; 51A006-01	EASA;FAA;CAAC;ANAC	28	28	72-61-81	MAIN GEARBOX - GEARBOX DRIVESHAFT (FRONT) HOUSING / HOUSIN	Package B	1	NICKEL PLATE THE FRONT SNAP DIAMETER		1045	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package F	5	CHROMIUM PLATE FRONT BEARING JOURNAL		2480	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package F	7	PLATE THE FRONT BEARING SHOULDER WITH CHROMIUM		2480	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package G	6	CHROMIUM PLATE REAR BEARING JOURNAL		2480	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package G	8	PLATE THE REAR BEARING SHOULDER WITH CHROMIUM		2480	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package SB00	PW4ENG 72-581	MODIFICATION OT TO REMOVE THE CUP PLUG		175	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 71R	071; 71R165	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package SB01	PW4ENG 72-802	MODIFICATION AND REPLACEMENT TO IMPROVE DURABILITY		2480	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 7:	EASA;FAA;CAAC;ANAC	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1190	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 7:	EASA;FAA;CAAC;ANAC	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package B	1	LAP CARBON SEAL MATING FACE		420	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 7:	EASA;FAA;CAAC;ANAC	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package C	2	REPLACE OIL SCOOP		715	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 7:	EASA;FAA;CAAC;ANAC	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package D	3	CHROMIUM PLATE FRONT SEALING FACE		1645	SR Technics Switzerland
137738	70R508; 70R509; 70R693; 7:	EASA;FAA;CAAC;ANAC	30	28	72-61-31	MAIN GEARBOX - GEARBOX IDG DRIVE SPUR GEARSHAFT ASSEMBLY	Package E	4	CHROMIUM PLATE SEALING FACE		1775	SR Technics Switzerland
137739	70R149; 71R154		28	28	72-61-11	MAIN GEARBOX - GEARBOX (DEOILER) SPUR GEARSHAFT ASSEMBLY	Package F	5	LAP THE SEALING FACE		420	SR Technics Switzerland
137739	70R149; 71R154		28	28	72-61-11	MAIN GEARBOX - GEARBOX (DEOILER) SPUR GEARSHAFT ASSEMBLY	Package SB00	PW4ENG 72-802	MODIFICATION AND REPLACEMENT TO IMPROVE DURABILITY		645	SR Technics Switzerland
137739	70R149; 71R154	EASA;FAA;CAAC;ANAC	28	28	72-61-11	MAIN GEARBOX - GEARBOX (DEOILER) SPUR GEARSHAFT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	650	SR Technics Switzerland
137739	70R149; 71R154	EASA;FAA;CAAC;ANAC	28	28	72-61-11	MAIN GEARBOX - GEARBOX (DEOILER) SPUR GEARSHAFT ASSEMBLY	Package B	1	NICKEL/CHROMIUM PLATE SEALING FACE		2355	SR Technics Switzerland
137740	50H953		32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package B	1	PLASMA COAT INNER FLANGE SNAP DIAMETER		3080	SR Technics Switzerland
137740	50H953		32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package D	3	PLASMA COAT OUTER FLANGE FRONT FACE		2805	SR Technics Switzerland
137740	50H953		32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package E	4	PLASMA COAT OUTER FLANGE SNAP DIAMETER (POST SB PW4ENG 72-298 AND SB PW4G-100-72-52)		2805	SR Technics Switzerland
137740	50H953		32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package G	EA-12KC324	PLASMA COAT OUTER FLANGE FRONT FACE	EXTENDED LIMITS FOR MPN 55H302 ONLY	9995	SR Technics Switzerland
137740	50H953		32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package J	9	INNER FACE FRONT FLANGE PLASMA COAT REPAIR		2835	SR Technics Switzerland
137740	50H953	EASA;FAA;CAAC;ANAC	32	28	72-35-67	HIGH PRESSURE COMPRESSOR (HPC) - HPC REAR SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		455	SR Technics Switzerland
137741	50A289		32	28	72-34-11	INTERMEDIATE CASE - NO. 2 BEARING RETAINING NUT	Package B	1	REPAIR THE ANTIGALLANT COMPOUND		465	SR Technics Switzerland
137741	50A289		32	28	72-34-11	INTERMEDIATE CASE - NO. 2 BEARING RETAINING NUT	Package C	2	BEARING FACE MACHINE REPAIR		680	SR Technics Switzerland
137741	50A289		32	28	72-34-11	INTERMEDIATE CASE - NO. 2 BEARING RETAINING NUT	Package SB00	PW4G-100-72-185	INCREASED TORQUE		155	SR Technics Switzerland
137741	50A289		32	28	72-34-11	INTERMEDIATE CASE - NO. 2 BEARING RETAINING NUT	Package SB01	PW4ENG 72-748	INCREASED FINAL ANGLE OF TURN		155	SR Technics Switzerland
137741	50A289	EASA;FAA;CAAC;ANAC	32	28	72-34-11	INTERMEDIATE CASE - NO. 2 BEARING RETAINING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		320	SR Technics Switzerland
137742	50A313; 50A691		30	21	72-34-27	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING TUBE CONNECTOR AS	Package C	2	ANODIZE TOUCH-UP		315	SR Technics Switzerland
137742	50A313; 50A691		30	21	72-34-27	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING TUBE CONNECTOR AS	Package D	3	REPLACE HELICOIL INSERT		340	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137742	50A313; 50A691		30	21	72-34-27	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING TUBE CONNECTOR AS	Package E	4	BUSHING REPLACEMENT REPAIR		1480	SR Technics Switzerland
137742	50A313; 50A691	EASA;FAA;CAAC;ANAC	30	21	72-34-27	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING TUBE CONNECTOR AS	Package A	CLN/INSP	CLEANING AND INSPECTION		250	SR Technics Switzerland
137742	50A313; 50A691	EASA;FAA;CAAC;ANAC	30	21	72-34-27	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING TUBE CONNECTOR AS	Package B	1	PIN REPLACEMENT		345	SR Technics Switzerland
137743	50G005; 50G949		8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package C	2	LOWER BEARING JOURNAL CHROMIUM PLATE		1675	SR Technics Switzerland
137743	50G005; 50G949		8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package D	3	UPPER BEARING SHOULDER CHROMIUM PLATE		1675	SR Technics Switzerland
137743	50G005; 50G949		8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package E	4	LOWER BEARING SHOULDER CHROMIUM PLATE		1675	SR Technics Switzerland
137743	50G005; 50G949		8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package F	5	SURFACE DAMAGE BLEND REPAIR		210	SR Technics Switzerland
137743	50G005; 50G949	EASA;FAA;CAAC;ANAC	8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	385	SR Technics Switzerland
137743	50G005; 50G949	EASA;FAA;CAAC;ANAC	8	28	72-62-02	PW4 ANGLE GEARBOX BEVEL GEAR ASSY	Package B	1	UPPER BEARING JOURNAL CHROMIUM PLATE		1675	SR Technics Switzerland
137744	50L629; 53L135		9	28	72-52-35	PW4 STAGE 2 DUCT SEGMENT	Package SB00	72-795	INTRODUCTION OF THE ADVANTAGE PERFORMANCE UPGRADE CONFIGURATION TO IMPROVE HPT PERFORMANCE		545	SR Technics Switzerland
137744	50L629; 53L135		9	28	72-52-35	PW4 STAGE 2 DUCT SEGMENT	Package SB01	PW4G-100-72-219	INCORPORATION OF THE ADVANTAGE 70 PERFORMANCE AND DURABILITY UPGRADE KIT		545	SR Technics Switzerland
137744	50L629; 53L135		9	28	72-52-35	PW4 STAGE 2 DUCT SEGMENT	Package SB02	PW4G-100-72-220	CONVERSION OF A PW4168A ENGINE TO A PW4164-1D, PW4168-1D, PW4168A-1D, OR PW4170 ENGINE		545	SR Technics Switzerland
137744	50L629; 53L135	EASA;FAA;CAAC;ANAC	9	28	72-52-35	PW4 STAGE 2 DUCT SEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		115	SR Technics Switzerland
137744	50L629; 53L135	EASA;FAA;CAAC;ANAC	9	28	72-52-35	PW4 STAGE 2 DUCT SEGMENT	Package C	2	GRIND REPLACEMENT DUCT SEGMENTS		565	SR Technics Switzerland
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC										
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC	6	28	72-35-63	PW4 HPC 5 SHROUD SET (6 SEGMENTS)	Package A	CLN/INSP	CLEANING AND INSPECTION		645	SR Technics Switzerland
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC	6	28	72-35-63	PW4 HPC 5 SHROUD SET (6 SEGMENTS)	Package SB00	72-679	MODIFICATION OF TO INCORPORATE CERAMIC THERMAL BARRIER COATING AT THE 5TH STAGE		835	SR Technics Switzerland
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC	6	28	72-35-63	PW4 HPC 5 SHROUD SET (6 SEGMENTS)	Package SB01	72-755	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	BOEING	610	SR Technics Switzerland
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC	6	28	72-35-63	PW4 HPC 5 SHROUD SET (6 SEGMENTS)	Package SB02	72-756	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	AIRBUS	610	SR Technics Switzerland
137745	50S055-001; 50S055-002; 5(	EASA;FAA;CAAC;ANAC	6	28	72-35-63	PW4 HPC 5 SHROUD SET (6 SEGMENTS)	Package SB03	72-757	MODIFICATION OF TO INCORPORATE A RING CASE CONFIGURATION F	MD11	610	SR Technics Switzerland
137746	70R005; 71R073		29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package C	1	CHROMIUM PLATE FRONT BEARING JOURNAL		1850	SR Technics Switzerland
137746	70R005; 71R073		29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package E	4	CHROMIUM PLATE REAR BEARING SHOULDER		1850	SR Technics Switzerland
137746	70R005; 71R073		29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package F	5	100" CHROMIUM PLATING FRONT BEARING JOURNAL		1895	SR Technics Switzerland
137746	70R005; 71R073		29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package G	6	100" CHROMIUM PLATING REAR BEARING JOURNAL		1850	SR Technics Switzerland
137746	70R005; 71R073		29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package J	9	GEAR TEETH INVOLUTE SURFACE REPAIR		310	SR Technics Switzerland
137746	70R005; 71R073	EASA;FAA;CAAC;ANAC	29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1250	SR Technics Switzerland
137746	70R005; 71R073	EASA;FAA;CAAC;ANAC	29	28	72-61-22	MAIN GEARBOX - GEARBOX (DRIVE) SPUR GEARSHAFT	Package B	2	CHROMIUM PLATE THE REAR BEARING JOURNAL		1970	SR Technics Switzerland
137747	70R003; 71R120		29	28	72-61-21	MAIN GEARBOX - GEARBOX (IDLER) SPUR GEAR	Package SB00	PW4ENG 72-664	DEOILER IDLER BRG WITH ANTI-ROT FEATURES	PW4000 - 94"	1970	SR Technics Switzerland
137747	70R003; 71R120		29	28	72-61-21	MAIN GEARBOX - GEARBOX (IDLER) SPUR GEAR	Package SB01	PW4G-100-72-115	DEOILER IDLER BRG WITH ANTI-ROT FEATURES	PW4000 - 100"	1720	SR Technics Switzerland
137747	70R003; 71R120	EASA;FAA;CAAC;ANAC	29	28	72-61-21	MAIN GEARBOX - GEARBOX (IDLER) SPUR GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		250	SR Technics Switzerland
137747	70R003; 71R120	EASA;FAA;CAAC;ANAC	29	28	72-61-21	MAIN GEARBOX - GEARBOX (IDLER) SPUR GEAR	Package D	3	PLASMA COAT THE SHOULDER		1175	SR Technics Switzerland
137748	70R722		4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package B	1	CHROMIUM PLATE THE BEARING SHOULDER		1750	SR Technics Switzerland
137748	70R722		4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package C	2	NICKEL PLATE THE REAR PILOT DIAMETER		920	SR Technics Switzerland
137748	70R722		4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package D	3	NICKEL PLATE FRONT PILOT DIAMETER		920	SR Technics Switzerland
137748	70R722		4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package E	4	CHROMIUM PLATE THE BEARING JOURNAL		1900	SR Technics Switzerland
137748	70R722		4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package F	5	APPLY CADMIUM PLATE		285	SR Technics Switzerland
137748	70R722	EASA;FAA;CAAC;ANAC	4	28	72-61-20	PW4 GEARBOX IDLER SHAFT	Package A	CLN/INSP	CLEANING & INSPECTION		590	SR Technics Switzerland
137749	70R554; 70R790-01		7	28	72-61-41	PW4 GEARBOX SPUR GEARSHAFT (SCAVENGE PUMP DRIVE)	Package C	2	CHROMIUM PLATE REAR BRG JOURNAL		1420	SR Technics Switzerland
137749	70R554; 70R790-01		7	28	72-61-41	PW4 GEARBOX SPUR GEARSHAFT (SCAVENGE PUMP DRIVE)	Package D	3	CHROMIUM PLATE FRONT BRG SHOULDER		1420	SR Technics Switzerland
137749	70R554; 70R790-01		7	28	72-61-41	PW4 GEARBOX SPUR GEARSHAFT (SCAVENGE PUMP DRIVE)	Package E	4	CHROMIUM PLATE REAR BRG SHOULDER		1420	SR Technics Switzerland
137749	70R554; 70R790-01	EASA;FAA;CAAC;ANAC	7	28	72-61-41	PW4 GEARBOX SPUR GEARSHAFT (SCAVENGE PUMP DRIVE)	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	525	SR Technics Switzerland
137749	70R554; 70R790-01	EASA;FAA;CAAC;ANAC	7	28	72-61-41	PW4 GEARBOX SPUR GEARSHAFT (SCAVENGE PUMP DRIVE)	Package B	1	CHROMIUM PLATE FRONT BRG JOURNAL		1420	SR Technics Switzerland
137750	50N535		7	28	72-53-18	PW4 STAGE 3 LPT(INNER) DUCT ASSEMBLY	Package C	2	RESTORE PWA 73 COATING		560	SR Technics Switzerland
137750	50N535		7	28	72-53-18	PW4 STAGE 3 LPT(INNER) DUCT ASSEMBLY	Package H	7	STUD REPLACEMENT		610	SR Technics Switzerland
137750	50N535		7	28	72-53-18	PW4 STAGE 3 LPT(INNER) DUCT ASSEMBLY	Package SB01	72-513	3RD STG DUCT SEAL SUPPORT MODIF.		410	SR Technics Switzerland
137750	50N535		7	28	72-53-18	PW4 STAGE 3 LPT(INNER) DUCT ASSEMBLY	Package SB02	PW4G-100-72-41	LPT STG3 INNER DUCT- & SEAL RING PLASMA		410	SR Technics Switzerland
137750	50N535	EASA;FAA;CAAC;ANAC	7	28	72-53-18	PW4 STAGE 3 LPT(INNER) DUCT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		425	SR Technics Switzerland
137751	50L494; 50L497; 50L627; 50	EASA;FAA;CAAC;ANAC										
137751	50L494; 50L497; 50L627; 50	EASA;FAA;CAAC;ANAC	9	28	72-52-32	PW4000 STAGE 1 HPT DUCT SEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		115	SR Technics Switzerland
137751	50L494; 50L497; 50L627; 50	EASA;FAA;CAAC;ANAC	9	28	72-52-32	PW4000 STAGE 1 HPT DUCT SEGMENT	Package C	2	GRIND REPLACEMENT DUCT SEGMENTS		565	SR Technics Switzerland
137752	50R402; 70H249	EASA;FAA;CAAC;ANAC										
137752	50R402; 70H249	EASA;FAA;CAAC;ANAC	21	28	72-35-71	HIGH PRESSURE COMPRESSOR (HPC) - GEARBOX DRIVESHAFT HOUSIN	Package A	CLN/INSP	CLEANING AND INSPECTION		150	SR Technics Switzerland
137753	50G103; 53D281		26	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 94"	Package C	2	REPLACE THE BEARING		680	SR Technics Switzerland
137753	50G103; 53D281		26	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 94"	Package D	3	REPLACE THE ANTIGALLING COMPOUND		490	SR Technics Switzerland
137753	50G103; 53D281	EASA;FAA;CAAC;ANAC	26	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		260	SR Technics Switzerland
137753	50G103; 53D281	EASA;FAA;CAAC;ANAC	26	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 94"	Package B	1	HOLE REPAIR		890	SR Technics Switzerland
137756	50A045; 50A048; 50G635; 5	EASA;FAA;CAAC;ANAC										
137756	50A045; 50A048; 50G635; 5	EASA;FAA;CAAC;ANAC	25	28	72-34-23	INTERMEDIATE CASE - GEARSHAFT BALL BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	545	SR Technics Switzerland
137757	50D380; 50D390; 50D580; 5	EASA;FAA;CAAC;ANAC										
137757	50D380; 50D390; 50D580; 5	EASA;FAA;CAAC;ANAC	8	28	72-33-05	PW4 (94") FAN EXIT VANE AND CASE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		180	SR Technics Switzerland
137757	50D380; 50D390; 50D580; 5	EASA;FAA;CAAC;ANAC	8	28	72-33-05	PW4 (94") FAN EXIT VANE AND CASE ASSY	Package C	2	AIRFOIL PATCH	ON MODULE LEVEL ONLY	430	SR Technics Switzerland
137757	50D380; 50D390; 50D580; 5	EASA;FAA;CAAC;ANAC	8	28	72-33-05	PW4 (94") FAN EXIT VANE AND CASE ASSY	Package T	19	LEADING EDGE FLUOROELASTOMER REPAIR	PP-LEVEL	330	SR Technics Switzerland
137757	50D380; 50D390; 50D580; 5	EASA;FAA;CAAC;ANAC	8	28	72-33-05	PW4 (94") FAN EXIT VANE AND CASE ASSY	Package V	21	LEVEL SURFACE EROSION REPAIR	PP-LEVEL	710	SR Technics Switzerland
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package B	1	NICKEL PLATE INNER SNAP DIAMETER		2510	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package D	3	RESTORE ANTIGALLANT NO.3		1200	SR Technics Switzerland
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package E	4	WELD REPAIR CRACKS		5420	SR Technics Switzerland
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package I	8	PLASMA SPRAY REP LARGE BOSS BORES		3410	SR Technics Switzerland
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package J	9	OUTER SNAP DIAMETER PLASMA COAT REPAIR		2360	SR Technics Switzerland
137761	50J602-01		37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package K	10	OUTER DIAMETER ROUND REPAIR		1385	SR Technics Switzerland
137761	50J602-01	EASA;FAA;CAAC;ANAC	37	28	72-41-06	DIFFUSER AND COMBUSTOR - NO. 3 BEARING FRONT COOLING DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		1000	SR Technics Switzerland
137762	50D151; 50D151-001; 52D300; 53D296		35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package F	5	REPLACE BUSHINGS		1155	SR Technics Switzerland
137762	50D151; 50D151-001; 52D300; 53D296		35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package G	6	HOLE REPAIR		2130	SR Technics Switzerland
137762	50D151; 50D151-001; 52D300; 53D296		35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package H	7	BLEND REPAIR		1575	SR Technics Switzerland
137762	50D151; 50D151-001; 52D300; 53D296		35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package SB00	PW4ENG 72-660	MODIFICATION OF THE 2.5 BLEED CAM FOLLOWER SLOTS		995	SR Technics Switzerland
137762	50D151; 50D151-001; 52D3(	EASA;FAA;CAAC;ANAC	35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1130	SR Technics Switzerland
137762	50D151; 50D151-001; 52D3(	EASA;FAA;CAAC;ANAC	35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package B	1	ANODIZE TOUCH-UP		830	SR Technics Switzerland
137762	50D151; 50D151-001; 52D3(	EASA;FAA;CAAC;ANAC	35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package C	2	REPLACE RUBBER SEAL		1670	SR Technics Switzerland
137762	50D151; 50D151-001; 52D3(	EASA;FAA;CAAC;ANAC	35	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 94"	Package E	4	RESTORE TEFLON COATING		2290	SR Technics Switzerland
137764	50N266; 50N382-01; 50N529-01; 50N529-101		32	28	72-53-19	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING A	Package SB00	PW4G-100-A72	REPLACEMENT AND/OR MODIFICATION OF DISK & SEALS		1185	SR Technics Switzerland
137764	50N266; 50N382-01; 50N52	EASA;FAA;CAAC;ANAC	32	28	72-53-19	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING A	Package A	CLN/INSP	CLEANING AND INSPECTION		600	SR Technics Switzerland
137764	50N266; 50N382-01; 50N52	EASA;FAA;CAAC;ANAC	32	28	72-53-19	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING A	Package B	1	REPLACE HARDFACE		1105	SR Technics Switzerland
137764	50N266; 50N382-01; 50N52	EASA;FAA;CAAC;ANAC	32	28	72-53-19	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING A	Package D	3	CRACK WELD REPAIR		6165	SR Technics Switzerland
137764	50N266; 50N382-01; 50N52	EASA;FAA;CAAC;ANAC	32	28	72-53-19	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING A	Package K	SPM	REMOVE AND INSTALL DAMPER RING	ACC. SPM 70-43-00	600	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package A	CLN/INSP	CLEANING AND INSPECTION	PN50J362-001P15 50J362-001P20 FOR SHOP '	745	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package B	1	CLINCH NUT REPLACEMENT		630	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package C	2	NICKEL PLATE REPAIR FRONT ID SNAP		1825	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package D	3	REAR SNAP INNER DIAMETER NICKEL PLATE REPAIR		1575	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package E	4	SEAL RING GROOVE REPAIR		1490	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package F	5	REPLACE RETAINING PIN(S)		1635	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package G	6	SMOOTH OUT DAMAGE TO THREADS		400	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package I	8	REPAIR THREADED HOLES - HELICAL COIL REPLACEMENT		560	SR Technics Switzerland
137765	50J362; 50J362-001; 50J362	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package J	9	BLEND SURFACE DAMAGE		560	SR Technics Switzerland
137766	50N232; 50N309; 50N444	EASA;FAA;CAAC;ANAC										
137766	50N232; 50N309; 50N444	EASA;FAA;CAAC;ANAC	7	28	72-53-30	PW4 STAGE 3 LPT OUTER DUCT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
137766	50N232; 50N309; 50N444	EASA;FAA;CAAC;ANAC	7	28	72-53-30	PW4 STAGE 3 LPT OUTER DUCT ASSEMBLY	Package E	4	DUCT SEGMENT REPLACEMENT		565	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package M	12	PLASMA SPRAY STG.1 OUTER AIR SEAL		4940	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package N	13	FRONT INNER RAIL CRACK WELD REPAIR		15165	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB00	PW4ENG 72-490	CONVERSION OF A PW4460 OR PW4460 (-3) OR PW4462 (-3)		590	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB01	PW4ENG 72-504	CONVERSION OF A PW4052, PW4056, PW4060,TO A PW4052(-3), PW4056(-3), OR PW4060(-3)		565	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB02	PW4ENG 72-572	CONVERSION OF A PW4152, PW4156A, PW4158 ENGINE TO A PW4152(-3), PW4156A(-3), OR PW4158(-3) ENGINE		590	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB03	PW4ENG 72-157	CASE & VANE ASSY, TURBINE - MODIFICATION OF TO INCORPORATE A SECOND STAGE TURBINE BORESCOPE PORT		1475	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB04	PW4ENG 72-392	CASE ASSY, HPT - MAKE A MODIFICATION TO MACHINE SCALLOPS IN M AND N FLANGES		7190	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB05	PW4ENG 72-34	CASE & VANE ASSY, TURBINE - MODIF. OF THE CAST CASE ASSY & THE & REPL. OF THE 2ND & 1ST STG HPT DUCT SU		3430	SR Technics Switzerland
137767	50L324; 50L440-003; 50L533; 50L533-001; 50L533-002; 50L542; 50L669; 5(		40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package SB06	PW4ENG 72-462	ROTOR AND STATOR, HPT MODULE - INCORPORATE OF ADDITIONAL COOLING HOLES AND NEW SEALS		3140	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		2035	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package AA	26	BOSS CORNER CRACK BLEND REPAIR		4925	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package AD	29	BRACKET REPLACEMENT		430	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package B	1	REPLACE NUT PLATES		965	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package C	2	PLASMA SPRAY REAR SNAP DIAMETER		4425	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package D	3	PLASMA SPRAY REAR FLANGE FACE		1960	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package E	4	PLASMA SPRAY REPAIR FRONT OD SNAP DIAMETER		5260	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package F	5	FRONT FLANGE FACE PLASMA COAT REPAIR		5455	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package H	7	RESTORE PWA 53-5 PLASMA SPRAY ON FRONT FACE		6260	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package J	9	SURFACE DAMAGE BLEND REPAIR		3870	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package K	10	PLASMA SPRAY REPAIR THE STAGE 2 HPT VANE MOUNT FLANGE		2560	SR Technics Switzerland
137767	50L324; 50L440-003; 50L53:	EASA;FAA;CAAC;ANAC;TCCA	40	28	72-52-30	HIGH PRESSURE TURBINE (HPT) - TURBINE CASE ASSEMBLY	Package L	11	REPAIR THREADED HOLES WITH HELICAL-COIL INSERTS		1115	SR Technics Switzerland
137768	50B110; 50B233; 50B234; 5(	EASA;FAA;CAAC;ANAC										
137768	50B110; 50B233; 50B234; 5(	EASA;FAA;CAAC;ANAC	20	28	72-31-14	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BALL BEARING - 94" & 10(	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1565	SR Technics Switzerland
137768	50B110; 50B233; 50B234; 5(	EASA;FAA;CAAC;ANAC	20	28	72-31-14	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BALL BEARING - 94" & 10(	Package SB00	PW4ENG 72-768	BRG NO.1 BALL-RECONDITIONING OF BEARING		510	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package E	4	PLASMA COAT REPAIR THE COOLING DUCT FRONT SNAP DIAMETE		3755	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package F	5	NICKEL PLATE REPAIR THE COOLING DUCT REAR SNAP DIAMETER		4055	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package F	5	PLASMA COAT REPAIR THE COOLING DUCT REAR SNAP DIAMETER		4055	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package G	6	NICKEL PLATE REPAIR FRONT CARBON SEAL SUPPORT SNAP DIAMETER		4275	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package H	7	NICKEL PLATE REPAIR REAR CARBON SEAL SUPPORT SNAP DIAMETER		3945	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package I	8	NICKEL PLATE REPAIR THE INNER MOUNT FLANGE SNAP DIAMETER		4055	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package I	8	PLASMA COAT REPAIR THE INNER MOUNT FLANGE SNAP DIAMETER		4055	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package J	9	NICKEL PLATE REPAIR OUTER MOUNT FLANGE SNAP DIAMETER		3945	SR Technics Switzerland
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package J	9	PLASMA COAT REPAIR OUTER MOUNT FLANGE MATING DIAMETER		3945	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137771	50J337; 50J504; 50J782		31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package K	10	REPAIR THREADED (JACKSCREW) HOLES		770	SR Technics Switzerland
137771	50J337; 50J504; 50J782	EASA;FAA;CAAC;ANAC	31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		900	SR Technics Switzerland
137771	50J337; 50J504; 50J782	EASA;FAA;CAAC;ANAC	31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package B	1	SMOOTH OUT DAMAGE TO THREADS		770	SR Technics Switzerland
137771	50J337; 50J504; 50J782	EASA;FAA;CAAC;ANAC	31	28	72-41-10	DIFFUSER AND COMBUSTOR - NO. 3 BEARING HOUSING	Package E	4	NICKEL PLATE REPAIR THE COOLING DUCT FRONT SNAP DIAMETER		3755	SR Technics Switzerland
137772	51H270; 51H470-001; 54H8	EASA;FAA;CAAC;ANAC										
137772	51H270; 51H470-001; 54H8	EASA;FAA;CAAC;ANAC	5	28	72-35-41	PW4000 SHROUD 4 HPC INLET	Package A	CLN/INSP	CLEANING AND INSPECTION		200	SR Technics Switzerland
137772	51H270; 51H470-001; 54H8	EASA;FAA;CAAC;ANAC	5	28	72-35-41	PW4000 SHROUD 4 HPC INLET	Package SB00	72-650	WELD THE ALIGNMENT PINS TO INNER SHROUDS		100	SR Technics Switzerland
137773	50A712-01		14	28	72-41-86	NO. 3 BEARING SEAL RING HOLDER	Package A	INSP-05	LEAK CHECK		650	SR Technics Switzerland
137773	50A712-01		14	28	72-41-86	NO. 3 BEARING SEAL RING HOLDER	Package D	3	REPLACE RETAINING PIN		3240	SR Technics Switzerland
137773	50A712-01		14	28	72-41-86	NO. 3 BEARING SEAL RING HOLDER	Package F	5	INSERT REPLACEMENT REPAIR		345	SR Technics Switzerland
137773	50A712-01		14	28	72-41-86	NO. 3 BEARING SEAL RING HOLDER	Package M	12	BLEND SURFACE DAMAGE (MPN 50A712-01)		345	SR Technics Switzerland
137773	50A712-01	EASA;FAA;CAAC;ANAC	14	28	72-41-86	NO. 3 BEARING SEAL RING HOLDER	Package A	CLN/INSP	CLEANING AND INSPECTION		650	SR Technics Switzerland
137785	50A095; 50A096; 50A097; 5	EASA;FAA;CAAC;ANAC										
137785	50A095; 50A096; 50A097; 5	EASA;FAA;CAAC;ANAC	26	28	72-34-14	INTERMEDIATE CASE - NO. 2 BALL BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	835	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package C	2	CHROMIUM PLATE CARBON SEAL MATING FACE		1950	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package D	3	CHROMIUM PLATE FRONT BEARING JOURNAL		2785	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package D	5	PLATE THE FRONT BEARING SHOULDER WITH CHROMIUM		2785	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package E	4	CHROMIUM PLATE REAR BEARING JOURNAL		2785	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package E	6	PLATE THE REAR BEARING SHOULDER WITH CHROMIUM		2785	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package H	7	REPLACE THE BOLT		830	SR Technics Switzerland
137786	70R077; 71R147-01		28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package SB00	PW4ENG 72-802	MODIFICATION AND REPLACEMENT TO IMPROVE DURABILITY		560	SR Technics Switzerland
137786	70R077; 71R147-01	EASA;FAA;CAAC;ANAC	28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1140	SR Technics Switzerland
137786	70R077; 71R147-01	EASA;FAA;CAAC;ANAC	28	28	72-61-24	MAIN GEARBOX - GEARBOX (STARTER DRIVE) GEARSHAFT ASSEMBLY	Package B	1	LAP CARBON SEAL MATING FACE		320	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-01		31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package F	5	REPAIR SEAL RING GROOVE		490	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-01		31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package G	6	WELD REPAIR SEAL RING GROOVE		1155	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-01		31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package H	7	SEAL LANDS PLASMA COAT REPAIR		810	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-	EASA;FAA;CAAC;ANAC	31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package A	CLN/INSP	CLEANING AND INSPECTION	PN50J110P5 FOR SHOP VISIT ONLY	335	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-	EASA;FAA;CAAC;ANAC	31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package C	2	REPAIR SEAL RING GROOVE		490	SR Technics Switzerland
137789	50J110; 50J110P10; 50J912-	EASA;FAA;CAAC;ANAC	31	21	72-41-34	DIFFUSER AND COMBUSTOR - DIFFUSER SEAL AIR VENT TUBE ASSEMI	Package E	4	REPAIR BRACE TACK WELDS		465	SR Technics Switzerland
137790	50A160		27	28	72-41-83	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OUTER RACE) RETAINI	Package B	1	REPLACE SILVER PLATE	INCLUDING CLEANING, FPI AND INSPECTION	865	SR Technics Switzerland
137790	50A160		27	28	72-41-83	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OUTER RACE) RETAINI	Package B	2	BLEND REPAIR		865	SR Technics Switzerland
137790	50A160	EASA;FAA;CAAC;ANAC	27	28	72-41-83	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OUTER RACE) RETAINI	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package C	2	BLEND REPAIR SURFACE DAMAGE		1020	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package D	3	KNIFE-EDGE SEAL BLEND REPAIR		1255	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package E	4	RESTORE CORROSION PROTECTIVE COATING REPAIR		690	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package F	5	NICKEL PLATE REPAIR REAR SNAP DIAMETER		2750	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package G	6	NICKEL PLATE REPAIR FRONT SNAP DIAMETER		2750	SR Technics Switzerland
137791	50A082		31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package H	7	PLASMA SPRAY REPAIR REAR SHOULDER FACE		2250	SR Technics Switzerland
137791	50A082	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-53-85	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT AIRSEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		400	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC										
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package B	1	HOLE REPAIR		1440	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package C	2	REPLACE THE ANTIGALLANT		565	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package D	3	REPLACE THE BEARING		750	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package E	4	REPLACE SMALL BUSHING REPAIR		680	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package F	5	REPLACE LARGE BUSHING REPAIR		680	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package G	6	CONNECTING PIN HOLE REPAIR		1270	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package G	7	CONNECTING PIN HOLE REPAIR		1270	SR Technics Switzerland
137794	50D153; 50D611; 51D593; 5	EASA;FAA;CAAC;ANAC	27	28	72-33-13	FAN CASE - BLEED VALVE LINKAGE BELL CRANK ASSEMBLY	Package SB00	PW4ENG 72-672	MODIFICATION OF THE BELLCRANK ASSEMBLY, 2.5 BLEED		1335	SR Technics Switzerland
137795	50P020; 50P191	EASA;FAA;CAAC;ANAC										
137795	50P020; 50P191	EASA;FAA;CAAC;ANAC	25	21	72-54-82	TURBINE EXHAUST CASE - NO. 4 BEARING SEAL (REAR) SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		175	SR Technics Switzerland
137796	50P021	EASA;FAA;CAAC;ANAC	25	21	72-54-80	TURBINE EXHAUST CASE - NO. 4 BEARING SEAL (FRONT) SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		175	SR Technics Switzerland
137798	50J604-01; 51J041-01		31	21	72-41-20	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OIL) PRESSURE TUBE A	Package SB01	AOWC9264-G57233	NUMBER 3 BEARING COMPARTMENT OIL PRESSURE TUBE WELD CRACK		185	SR Technics Switzerland
137798	50J604-01; 51J041-01		31	21	72-41-20	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OIL) PRESSURE TUBE A	Package SB02	AD 2010-24-09	INSPECTION ACC. AD	IN CONJUNCTION WITH PACKAGE A	95	SR Technics Switzerland
137798	50J604-01; 51J041-01	EASA;FAA;CAAC;ANAC	31	21	72-41-20	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OIL) PRESSURE TUBE A	Package A	CLN/INSP	CLEANING AND INSPECTION	PN50J108 FOR SHOP VISIT ONLY	240	SR Technics Switzerland
137798	50J604-01; 51J041-01	EASA;FAA;CAAC;ANAC	31	21	72-41-20	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OIL) PRESSURE TUBE A	Package SB00	PW4G-100-72-193	INSPECTION OF TO REMOVE TUBES WHICH MAY HAVE WELD CONTAMINATION		310	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package B	1	NICKEL PLATE REPAIR OF NO. 3 BEARING REAR COOLING DUCT ASSEMBLY OUTER SNAP DIAMETER		1865	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package C	2	NICKEL PLATE REPAIR OF NO. 3 BEARING REAR COOLING DUCT ASSEMBLY INNER SNAP DIAMETER		1750	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package D	3	RESTORE ANTIGALLING COMPOUND		750	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package E	4	WELD REPAIR CRACKS IN ASSEMBLY		2805	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package F	5	PLASMA COAT OUTER SNAP DIAMETER REPAIR		2500	SR Technics Switzerland
137806	50A435		31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package G	6	INNER DUCT WALL WELD REPAIR - NO. 3 BEARING REAR COOLING DUCT ASSEMBLY		3045	SR Technics Switzerland
137806	50A435	EASA;FAA;CAAC;ANAC	31	28	72-41-88	DIFFUSER AND COMBUSTOR - NO. 3 BEARING REAR COOLING DUCT A	Package A	CLN/INSP	CLEANING AND INSPECTION		640	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package A	CLN/ISNP	CLEANING AND INSPECTION		625	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package B	1	MINOR SURFACE DAMAGE REPAIR		1905	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package C	2	PATCH REPAIR		1925	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package D	3	REPLACE WASHERS		1555	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC	29	28	72-33-83	FAN CASE - FAN EXIT OUTER (BIFURCATION) FAIRING ASSEMBLY	Package E	4	REPAIR DISBONDED TITANIUM SHIELD		735	SR Technics Switzerland
137807	50G693; 50G695; 51G531-0	EASA;FAA;CAAC;ANAC;CAA UK										
137811	50N102		25	28	72-53-21	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING [	Package B	1	REPLACE HARDFACE		915	SR Technics Switzerland
137811	50N102	EASA;FAA;CAAC;ANAC	25	28	72-53-21	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER) SEALING RING [	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
137813	70R555; 70R618		13	28	72-61-44	PW4 SCAVENGE PUMP SPUR GEARSHAFT	Package C	2	BEARING SHOULDER CHROMIUM PLATE REPAIR		1145	SR Technics Switzerland
137813	70R555; 70R618	EASA;FAA;CAAC;ANAC	13	28	72-61-44	PW4 SCAVENGE PUMP SPUR GEARSHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	340	SR Technics Switzerland
137813	70R555; 70R618	EASA;FAA;CAAC;ANAC	13	28	72-61-44	PW4 SCAVENGE PUMP SPUR GEARSHAFT	Package B	1	BEARING JOURNAL CHROMIUM PLATE REPAIR		1060	SR Technics Switzerland
137814	50B199; 50B247; 50B275; 5(	EASA;FAA;CAAC;ANAC										
137814	50B199; 50B247; 50B275; 5(	EASA;FAA;CAAC;ANAC	26	28	72-31-17	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING (CARBON) SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		125	SR Technics Switzerland
137814	50B199; 50B247; 50B275; 5(	EASA;FAA;CAAC;ANAC	26	28	72-31-17	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING (CARBON) SEAL	Package C	2	REPLACE THE CLINCH NUTS		1030	SR Technics Switzerland
137814	50B199; 50B247; 50B275; 5(	EASA;FAA;CAAC;ANAC	26	28	72-31-17	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING (CARBON) SEAL	Package D	3	PLASMA SPRAY OD SNAP (TITANIUM PART)		1885	SR Technics Switzerland
137814	50B199; 50B247; 50B275; 5(	EASA;FAA;CAAC;ANAC	26	28	72-31-17	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING (CARBON) SEAL	Package SB00	PW4ENG-72-237	REPLACEMENT OR MODIFICATION, TO IMPROVE RESTITANCE TO OIL LEAKS		175	SR Technics Switzerland
137816	50G436; 50G988; 51D764		15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package D	3	PLASMA SPRAY THE BEARING SHOULDER		1965	SR Technics Switzerland
137816	50G436; 50G988; 51D764		15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package F	5	REPLACE THE SLAP PINS		315	SR Technics Switzerland
137816	50G436; 50G988; 51D764		15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package SB00	PW4G-100-72-185	INCREASED FINAL ANGLE OF TURN INCORPORATION OF	ONLY DIMENSIONAL INSPECTION	135	SR Technics Switzerland
137816	50G436; 50G988; 51D764		15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package SB01	PW4ENG 72-748	INCREASED FINAL ANGLE OF TURN INCORPORATION OF	ONLY DIMENSIONAL INSPECTION	135	SR Technics Switzerland
137816	50G436; 50G988; 51D764	EASA;FAA;CAAC;ANAC	15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1355	SR Technics Switzerland
137816	50G436; 50G988; 51D764	EASA;FAA;CAAC;ANAC	15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package B	1	SMOOTH OUT DAMAGE TO THREAD		220	SR Technics Switzerland
137816	50G436; 50G988; 51D764	EASA;FAA;CAAC;ANAC	15	28	72-34-09	INTERMEDIATE CASE - NO. 2 BEARING HOUSING ASSEMBLY	Package C	2	BEARING JOURNAL COAT REPAIR		2135	SR Technics Switzerland
137817	51H486; 51H586-001; 51H5(	EASA;FAA;CAAC;ANAC										
137817	51H486; 51H586-001; 51H5(	EASA;FAA;CAAC;ANAC	4	18	72-35-43	PW4000 STG. 6 HPC SHROUD SEGMENT ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		200	SR Technics Switzerland
137818	50R410; 70T533; 70T626	EASA;FAA;CAAC;ANAC	26	28	72-41-91	DIFFUSER AND COMBUSTOR - GEARBOX LUG GUIDE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1045	SR Technics Switzerland
137818	50R410; 70T533; 70T626	EASA;FAA;CAAC;ANAC	26	28	72-41-91	DIFFUSER AND COMBUSTOR - GEARBOX LUG GUIDE ASSEMBLY	Package B	1	NICKEL PLATE REAR END FACE		1250	SR Technics Switzerland
137818	50R410; 70T533; 70T626	EASA;FAA;CAAC;ANAC	26	28	72-41-91	DIFFUSER AND COMBUSTOR - GEARBOX LUG GUIDE ASSEMBLY	Package C	2	NICKEL PLATE BEARING HOUSING		1475	SR Technics Switzerland
137820	70R113		10	28	72-61-61	PW4 RELIEF VALVE HOUSING (PRESSURE REGULATOR)	Package B	1	NICKEL PLATE THE FRONT OD SEAL LANDS		565	SR Technics Switzerland
137820	70R113		10	28	72-61-61	PW4 RELIEF VALVE HOUSING (PRESSURE REGULATOR)	Package C	2	NICKEL PLATE THE REAR OD SEAL LANDS		565	SR Technics Switzerland
137820	70R113	EASA;FAA;CAAC;ANAC	10	28	72-61-61	PW4 RELIEF VALVE HOUSING (PRESSURE REGULATOR)	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	150	SR Technics Switzerland
137821	50A432; 51A512; 52A118	EASA;FAA;CAAC;ANAC										
137821	50A432; 51A512; 52A118	EASA;FAA;CAAC;ANAC	31	28	72-32-84	LPC/LPT COUPLING - TURBINE SHAFT NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		665	SR Technics Switzerland
137821	50A432; 51A512; 52A118	EASA;FAA;CAAC;ANAC	31	28	72-32-84	LPC/LPT COUPLING - TURBINE SHAFT NUT	Package B	1	REPLACE ANTIGALLANT		680	SR Technics Switzerland
137822	50G405; 50G406; 50G407; 5	EASA;FAA;CAAC;ANAC										
137822	50G405; 50G406; 50G407; 5	EASA;FAA;CAAC;ANAC	20	28	72-34-22	INTERMEDIATE CASE - GEARSHAFT ROLLER BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		595	SR Technics Switzerland
137823	50P000; 50P001; 50P005; 5(	EASA;FAA;CAAC;ANAC										
137823	50P000; 50P001; 50P005; 5(	EASA;FAA;CAAC;ANAC	25	28	72-54-14	TURBINE EXHAUST CASE - NO. 4 ROLLER BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	830	SR Technics Switzerland
137824	50A617; 50A662-01; 50A66:	EASA;FAA;CAAC;ANAC										
137824	50A617; 50A662-01; 50A66:	EASA;FAA;CAAC;ANAC	22	28	72-34-80	INTERMEDIATE CASE - NO. 1 BEARING (OIL) PRESSURE MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		580	SR Technics Switzerland
137824	50A617; 50A662-01; 50A66:	EASA;FAA;CAAC;ANAC	22	28	72-34-80	INTERMEDIATE CASE - NO. 1 BEARING (OIL) PRESSURE MANIFOLD	Package B	1	FERRULE OUTER DIAMETER CHROMIUM PLATE REPAIR		1325	SR Technics Switzerland
137824	50A617; 50A662-01; 50A66:	EASA;FAA;CAAC;ANAC	22	28	72-34-80	INTERMEDIATE CASE - NO. 1 BEARING (OIL) PRESSURE MANIFOLD	Package C	2	REPLACE THE FRONT SUPPORT PIN		860	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J037-01		29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package F	5	REPAIR TUBE INSULATION		545	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J037-01		29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package H	7	REMOVE WEAR ON CONNECTORS		540	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J037-01		29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package I	8	REPAIR SEAL RING CONNECTOR GROOVE		900	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J037-01		29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package J	9	REPAIR SEAL RING HOLDER GROOVE		900	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J0:	EASA;FAA;CAAC;ANAC	29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package A	CLN/INSP	CLEANING AND INSPECTION		375	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J0:	EASA;FAA;CAAC;ANAC	29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package D	3	SLEEVE REPLACEMENT REPAIR		965	SR Technics Switzerland
137825	50J400-01; 50J661-01; 51J0:	EASA;FAA;CAAC;ANAC	29	21	72-41-25	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (SCAVENGE) TUBE ASSI	Package E	4	REPAIR SEAL RING HOLDER GROOVE		965	SR Technics Switzerland
137827	50G038		7	28	72-62-13	PW4 GEARBOX DRIVE COUPLING	Package B	1	SPLINE TEETH SURFACE DAMAGE BLEND REPAIR		200	SR Technics Switzerland
137827	50G038		7	28	72-62-13	PW4 GEARBOX DRIVE COUPLING	Package C	2	FRONT FACE CHROMIUM PLATE REPAIR		1105	SR Technics Switzerland
137827	50G038		7	28	72-62-13	PW4 GEARBOX DRIVE COUPLING	Package D	3	FRONT INNER DIAMETER CHROMIUM PLATE REPAIR		1175	SR Technics Switzerland
137827	50G038	EASA;FAA;CAAC;ANAC	7	28	72-62-13	PW4 GEARBOX DRIVE COUPLING	Package A	CLN/INSP	CLEANING AND INSPECTION		440	SR Technics Switzerland
137828	50J109; 50J915-01		29	21	72-41-27	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (COMPARTMENT) COO	Package E	4	REPAIR SEAL RING FERRULE GROOVE		810	SR Technics Switzerland
137828	50J109; 50J915-01		29	21	72-41-27	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (COMPARTMENT) COO	Package F	5	REPAIR TUBE INSULATION		675	SR Technics Switzerland
137828	50J109; 50J915-01		29	21	72-41-27	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (COMPARTMENT) COO	Package H	7	REPAIR SEAL RING HOLDER GROOVES		1045	SR Technics Switzerland
137828	50J109; 50J915-01	EASA;FAA;CAAC;ANAC	29	21	72-41-27	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (COMPARTMENT) COO	Package A	CLN/INSP	CLEANING AND INSPECTION		385	SR Technics Switzerland
137828	50J109; 50J915-01	EASA;FAA;CAAC;ANAC	29	21	72-41-27	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (COMPARTMENT) COO	Package D	3	REPAIR SEAL RING HOLDER GROOVE		830	SR Technics Switzerland
137831	70R011; 70R691		26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package C	2	NICKEL/CHROMIUM PLATE SEALING FACE		2225	SR Technics Switzerland
137831	70R011; 70R691		26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package D	3	CHROMIUM PLATE FRONT BEARING JOURNAL		2225	SR Technics Switzerland
137831	70R011; 70R691		26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package E	4	CHROMIUM PLATE REAR BEARING JOURNAL		2225	SR Technics Switzerland
137831	70R011; 70R691		26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package F	5	PLATE THE BEARING SHOULDER WITH CHROMIUM		2225	SR Technics Switzerland
137831	70R011; 70R691	EASA;FAA;CAAC;ANAC	26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package A	CLN/INSP	CLEANING AND INSPECTION		1185	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137831	70R011; 70R691	EASA;FAA;CAAC;ANAC	26	28	72-61-34	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) SPUR (	Package B	1	LAP CARBON SEAL MATING FACE		320	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package B	1	CHROMIUM PLATE SEALING FACE		2750	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package C	2	CHROMIUM PLATE FRONT BEARING JOURNAL		2750	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package C	4	PLATE THE FRONT BEARING SHOULDER WITH CHROMIUM		2750	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package D	3	CHROMIUM PLATE REAR BEARING JOURNAL		2750	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package D	6	PLATE THE REAR BEARING SHOULDER WITH CHROMIUM		2750	SR Technics Switzerland
137832	70R010		30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package E	5	LAP THE SEALING FACE		580	SR Technics Switzerland
137832	70R010	EASA;FAA;CAAC;ANAC	30	28	72-61-29	MAIN GEARBOX - GEARBOX (REAR HYDRAULIC PUMP DRIVE) SPUR GE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1185	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package B	1	LAP CARBON SEAL MATING FACE		340	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package C	2	NICKEL AND CHROMIUM PLATE SEALING FACE		2285	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package D	3	CHROMIUM PLATE FRONT BEARING JOURNAL		2285	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package D	6	CHROMIUM PLATE FRONT BEARING SHOULDER		2285	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package E	4	CHROMIUM PLATE REAR BEARING JOURNAL		2335	SR Technics Switzerland
137833	70R009		30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package E	5	CHROMIUM PLATE RAER BEARING SHOULDER		2335	SR Technics Switzerland
137833	70R009	EASA;FAA;CAAC;ANAC	30	28	72-61-27	MAIN GEARBOX - GEARBOX (FUEL PUMP DRIVE) SPUR GEARSHAFT AS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1185	SR Technics Switzerland
137834	50A076; 51J322		30	28	72-41-81	DIFFUSER AND COMBUSTOR - NO. 3 BEARING SEAL SPACER	Package C	2	NICKEL PLATE REP. END FACES		1650	SR Technics Switzerland
137834	50A076; 51J322		30	28	72-41-81	DIFFUSER AND COMBUSTOR - NO. 3 BEARING SEAL SPACER	Package D	3	BALANCE REPAIR		690	SR Technics Switzerland
137834	50A076; 51J322		30	28	72-41-81	DIFFUSER AND COMBUSTOR - NO. 3 BEARING SEAL SPACER	Package E	INSP/CHECK-03	BLEND DAMAGE INSPECTION		160	SR Technics Switzerland
137834	50A076; 51J322	EASA;FAA;CAAC;ANAC	30	28	72-41-81	DIFFUSER AND COMBUSTOR - NO. 3 BEARING SEAL SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
137834	50A076; 51J322	EASA;FAA;CAAC;ANAC	30	28	72-41-81	DIFFUSER AND COMBUSTOR - NO. 3 BEARING SEAL SPACER	Package B	1	NICKEL PLATE REP. ID PILOT DIAMETER		1555	SR Technics Switzerland
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC										
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC	6	28	72-34-01	PW4 FAIRING TO STRUT ON INTERMEDIATE CASE	Package A	CLN/INSP	CLEANING & INSPECTION		385	SR Technics Switzerland
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC	6	28	72-34-01	PW4 FAIRING TO STRUT ON INTERMEDIATE CASE	Package B	1	PATCH REPAIR	FLOUROELASTOMER	955	SR Technics Switzerland
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC	6	28	72-34-01	PW4 FAIRING TO STRUT ON INTERMEDIATE CASE	Package B	1	PATCH REPAIR	ORGANIC FIBRE	955	SR Technics Switzerland
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC	6	28	72-34-01	PW4 FAIRING TO STRUT ON INTERMEDIATE CASE	Package E	4	PATCH REPAIR	EPOXY	955	SR Technics Switzerland
137835	50G533; 50G534; 51G546-0	EASA;FAA;CAAC;ANAC	6	28	72-34-01	PW4 FAIRING TO STRUT ON INTERMEDIATE CASE	Package E	4	PATCH REPAIR	FLOUROELASTOMER	955	SR Technics Switzerland
137836	50J112; 50J619-01; 51J033-01		33	21	72-41-31	DIFFUSER AND COMBUSTOR - TURBINE BLADE COOLING TUBES	Package G	8	REPAIR SEAL RING HOLDER GROOVE		830	SR Technics Switzerland
137836	50J112; 50J619-01; 51J033-(	EASA;FAA;CAAC;ANAC	33	21	72-41-31	DIFFUSER AND COMBUSTOR - TURBINE BLADE COOLING TUBES	Package A	CLN/INSP	CLEANING AND INSPECTION		386	SR Technics Switzerland
137836	50J112; 50J619-01; 51J033-(	EASA;FAA;CAAC;ANAC	33	21	72-41-31	DIFFUSER AND COMBUSTOR - TURBINE BLADE COOLING TUBES	Package B	2	CHROMIUM PLATE TURBINE BLADE COOLING TUBES INSIDE DIAMETER		2195	SR Technics Switzerland
137836	50J112; 50J619-01; 51J033-(	EASA;FAA;CAAC;ANAC	33	21	72-41-31	DIFFUSER AND COMBUSTOR - TURBINE BLADE COOLING TUBES	Package C	3	REPAIR SEAL RING HOLDER GROOVE		1020	SR Technics Switzerland
137837	51R073; 51R074		22	28	72-41-92	DIFFUSER AND COMBUSTOR - GEARBOX SUPPORT CLEVIS, LEFT AND I	Package D	3	LUG INNER SURFACE BLENDING		390	SR Technics Switzerland
137837	51R073; 51R074		22	28	72-41-92	DIFFUSER AND COMBUSTOR - GEARBOX SUPPORT CLEVIS, LEFT AND I	Package E		REMOVE DEFECTIVE BOLTS FROM CLAMP		200	SR Technics Switzerland
137837	51R073; 51R074	EASA;FAA;CAAC;ANAC	22	28	72-41-92	DIFFUSER AND COMBUSTOR - GEARBOX SUPPORT CLEVIS, LEFT AND I	Package A	CLN/INSP	CLEANING AND INSPECTION		730	SR Technics Switzerland
137837	51R073; 51R074	EASA;FAA;CAAC;ANAC	22	28	72-41-92	DIFFUSER AND COMBUSTOR - GEARBOX SUPPORT CLEVIS, LEFT AND I	Package C	2	BUSHING REPAIR SUPPORT CLEVIS REPAIR		895	SR Technics Switzerland
137839	70R616; 70R777; 70R964		19	28	72-61-45	MAIN GEARBOX - GEARBOX (EEC/PMA ALTERNATOR DRIVE) SPUR GE/	Package D	3	INNER BEARING SHOULDER CHROMIUM PLATE REPAIR		1360	SR Technics Switzerland
137839	70R616; 70R777; 70R964	EASA;FAA;CAAC;ANAC	19	28	72-61-45	MAIN GEARBOX - GEARBOX (EEC/PMA ALTERNATOR DRIVE) SPUR GE/	Package A	CLN/INSP	CLEANING AND INSPECTION		1205	SR Technics Switzerland
137839	70R616; 70R777; 70R964	EASA;FAA;CAAC;ANAC	19	28	72-61-45	MAIN GEARBOX - GEARBOX (EEC/PMA ALTERNATOR DRIVE) SPUR GE/	Package B	1	FRONT BEARING JOURNAL CHROMIUM PLATE REPAIR		1185	SR Technics Switzerland
137839	70R616; 70R777; 70R964	EASA;FAA;CAAC;ANAC	19	28	72-61-45	MAIN GEARBOX - GEARBOX (EEC/PMA ALTERNATOR DRIVE) SPUR GE/	Package C	2	CHROMIUM PLATE REAR BEARING JOURNAL		1185	SR Technics Switzerland
137845	50A017		27	28	72-34-21	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEARSHAFT	Package B	1	CHROMIUM PLATE OR COAT REPAIR UPPER BEARING JOURNAL		1280	SR Technics Switzerland
137845	50A017		27	28	72-34-21	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEARSHAFT	Package C	2	CHROMIUM PLATE OR COAT LOWER BEARING JOURNAL		2025	SR Technics Switzerland
137845	50A017		27	28	72-34-21	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEARSHAFT	Package D	3	SMOOTH OUT DAMAGE TO THE SURFACE		680	SR Technics Switzerland
137845	50A017	EASA;FAA;CAAC;ANAC	27	28	72-34-21	INTERMEDIATE CASE - GEARBOX DRIVE BEVEL GEARSHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		600	SR Technics Switzerland
137846	50A452; 50A641; 51A398		31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package D	3	PLASMA SPRAY THE INNER FRONT DIAMETER		1640	SR Technics Switzerland
137846	50A452; 50A641; 51A398		31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package E	4	PLASMA SPRAY THE REAR ID		1640	SR Technics Switzerland
137846	50A452; 50A641; 51A398		31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package L	INSP/CHECK-03	BLEND AEREA B AND OR D		235	SR Technics Switzerland
137846	50A452; 50A641; 51A398	EASA;FAA;CAAC;ANAC	31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1025	SR Technics Switzerland
137846	50A452; 50A641; 51A398	EASA;FAA;CAAC;ANAC	31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package B	1	RESTORE PROTECTIVE COATING ON NO. 1 BEARING FRONT SUPPORT		680	SR Technics Switzerland
137846	50A452; 50A641; 51A398	EASA;FAA;CAAC;ANAC	31	28	72-34-82	INTERMEDIATE CASE - NO. 1 BEARING FRONT SUPPORT	Package C	2	PLASMA SPRAY THE BEARING JOURNAL		1905	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC										
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		625	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package B	1	LINER SEGMENT PATCH REPAIR		955	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package C	2	LINER SEGMENT ASSEMBLY EPOXY REPAIR		1235	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package D	3	LINER SEGMENT ASSEMBLY EPOXY REPAIR		490	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package H	7	NON-ACOUSTIC OUTER DIAMETER LINER FLOW SURFACE FLUOROELASTOMER TOUCH-UP REPAIR		1575	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package K	10	WASHER REPLACEMENT REPAIR		645	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package L	11	FAN EXIT OUTER DIAMETER SEAL BONDING REPAIR		815	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package M	12	FAN EXIT (OUTER) LINER SEGMENT ASSEMBLIES SURFACE DAMAGE PATCH REPAIR		1175	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package O	14	FAN EXIT (OUTER) LINER SEGMENT ACOUSTIC LINER REPAIR		1475	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package P	15	LINER SEGEMENT ASSEMBLY LOOSE OR DAMAGE SPACER REPLACEMENT REPAIR		860	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package Q	16	STRUT 1 OUTER LINER SEGMENT NUT PLATE REPLACEMENT REPAIR		575	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package R	17	LINER SEGMENT DEPRESSED IMPERFECTIONS		605	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC	37	28	72-34-70	INTERMEDIATE CASE - FAN EXIT OUTER LINER	Package SB00	PW4G-100-72-174	CASE ASSEMBLY, COMPRESSOR INTERMEDIATE - REPLACEMENT OF F/	BRACKET ASSEMBLIES WITH REDESIGNED AT	700	SR Technics Switzerland
137847	50G517; 50G518; 50G519; 5	EASA;FAA;CAAC;ANAC;CAA UK										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137848	50J111	EASA;FAA;CAAC;ANAC	6	21	72-41-33	PW4 DIFFUSER SEAL AIR VENT TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		265	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC										
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package A	CLN/INSP	CLEANING AND INSPECTION		415	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package F	5	REPAIR TUBE INSULATION		450	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package H	7	REPAIR SEAL RING CONNECTOR GROOVE		1100	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package I	8	REPAIR SEAL RING HOLDER GROOVE		865	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package L	11	REMOVE WEAR ON CONNECTORS		450	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package N	13	REPAIR SEAL RING CONNECTOR GROOVE		1095	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package SB00	PW4ENG 72-696	INSPECTION OF WELD BEAD GROOVE		295	SR Technics Switzerland
137849	50J489-01; 50J605-01; 50J6:	EASA;FAA;CAAC;ANAC	33	21	72-41-19	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (BREATHER) TUBE ASSE	Package SB03	PW4G-100-72-144	NO3 BRG BREATHER TUBE,INSP.WELD GROOVE		310	SR Technics Switzerland
137852	50G342; 52G112-01		33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package C	2	NUT PLATE REPLACEMENT		1060	SR Technics Switzerland
137852	50G342; 52G112-01		33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package D	3	SMOOTH SURFACE DAMAGE		1115	SR Technics Switzerland
137852	50G342; 52G112-01		33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package E	4	REPLACE ANTI-GALLANT COMPOUND		760	SR Technics Switzerland
137852	50G342; 52G112-01		33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package H	7	FAN EXIT GUIDE VANE FLANGE PLASMA COAT REPAIR		2360	SR Technics Switzerland
137852	50G342; 52G112-01	EASA;FAA;CAAC;ANAC	33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		410	SR Technics Switzerland
137852	50G342; 52G112-01	EASA;FAA;CAAC;ANAC	33	28	72-34-02	INTERMEDIATE CASE - FAN EXIT CASE FLANGE ASSEMBLY	Package B	1	TOUCH UP PROTECTION LAYER		745	SR Technics Switzerland
137853	310T3152-16; 310T3152-17;	EASA;FAA;CAAC;ANAC										
137853	310T3152-16; 310T3152-17;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	FWD ENGINE MOUNT - BOLT- 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		290	SR Technics Switzerland
137853	310T3152-16; 310T3152-17;	EASA;FAA;CAAC;ANAC	22	21	71-21-16	FWD ENGINE MOUNT - BOLT- 94"	Package B	10.Jan	CHROMIUM PLATE SHAFT OUTER DIAMETER		360	SR Technics Switzerland
137854	310T4038-1		5	21	71-21-16	PW4 ENGINE FORWARD MOUNT SHEAR PIN	Package N	13	CHROME PLATE REPAIR		500	SR Technics Switzerland
137854	310T4038-1	EASA;FAA;CAAC;ANAC	5	21	71-21-16	PW4 ENGINE FORWARD MOUNT SHEAR PIN	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
137855	310T3150-1; 310T3150-2; 3:	EASA;FAA;CAAC;ANAC										
137855	310T3150-1; 310T3150-2; 3:	EASA;FAA;CAAC;ANAC	5	21	71-21-16	PW4 ENGINE AFT MOUNT PIN-LINK PIVOT	Package A	CLN/INSP	CLEANING & INSPECTION		220	SR Technics Switzerland
137855	310T3150-1; 310T3150-2; 3:	EASA;FAA;CAAC;ANAC	5	21	71-21-16	PW4 ENGINE AFT MOUNT PIN-LINK PIVOT	Package J	09.Jan	PLATING PIN		745	SR Technics Switzerland
137855	310T3150-1; 310T3150-2; 3:	EASA;FAA;CAAC;ANAC	5	21	71-21-16	PW4 ENGINE AFT MOUNT PIN-LINK PIVOT	Package SB00	767-SL-54-016	AFT MOUNT, INSPECTION OF PIVOT-LINK PIN		140	SR Technics Switzerland
137856	310T3037-4		6	21	71-21-16	PW4 BOEING AFT ENGINE MOUNT SHEAR PIN	Package B	12.Jan	CHROME PLATE REPAIR		915	SR Technics Switzerland
137856	310T3037-4	EASA;FAA;CAAC;ANAC	6	21	71-21-16	PW4 BOEING AFT ENGINE MOUNT SHEAR PIN	Package A	CLN/INSP	CLEANING & INSPECTION		410	SR Technics Switzerland
137895	50G492; 51G088	EASA;FAA;CAAC;ANAC	6	28	72-62-17	PW4 ANGLE GEARBOX (REAR OIL) NOZZLE ASSY	Package B	1	REPLACE PROTECTIVE COATING	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
137895	50G492; 51G088	EASA;FAA;CAAC;ANAC	6	28	72-62-17	PW4 ANGLE GEARBOX (REAR OIL) NOZZLE ASSY	Package SB00	PW4ENG 72-131	MODIFICATION OF AGB OIL NOZZLE ASSIES	FOR SHOP VISITS ONLY	810	SR Technics Switzerland
137896	50G911; 51G090; 71R050	EASA;FAA;CAAC;ANAC										
137896	50G911; 51G090; 71R050	EASA;FAA;CAAC;ANAC	6	28	72-62-15	PW4000 NOZZLE ASSY ANGLE GEARBOX	Package B	1	REPLACE PROTECTIVE COATING	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
137896	50G911; 51G090; 71R050	EASA;FAA;CAAC;ANAC	6	28	72-62-15	PW4000 NOZZLE ASSY ANGLE GEARBOX	Package SB00	PW4ENG 72-131	MODIFICATION OF AGB OIL NOZZLE ASSIES	FOR SHOP VISITS ONLY	810	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;ANAC										
137902	50U402-01; 50U403-001; 50	EASA;FAA;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPETION		785	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC										
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package B	1	REPLACE WORN GUIDE PINS		740	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package C	2	REPLACE WORN GUIDE PINS		470	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package D	3	REPLACE WORN GUIDE PINS (INCONEL 718)		770	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package E	4	BLEND REPAIR OIL COOLER BRACKET ASSEMBLY		340	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package F	5	REPALCE THE OIL COOLER BRACKET ASSEMBLY BEARING		955	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package J	9	LOOP CLAMP BRACKET ASSEMBLY WELD BEAD CRACK REPAIR		750	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package L	11	OIL COOLER BRACKET ASSEMBLY BEARING REPLACEMENT REPAIR		1290	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package M	12	BIFURCATION ELECTRICAL CONDUIT LINK ASSEMBLY BEARING REPLACEMENT		630	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package O	14	ANTI SLIP STRIP ADHESIVE REPLACEMENT		775	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package Q	16	LAMINATE REPAIR		770	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package R	17	RUBBER CUSHION REPLACEMENT REPAIR		530	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package S	18	LOOP CLAMP BRACKET ASSEMBLY ELONGATED HOLE WELD REPAIR		670	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package SB00	PW4ENG 75-131	AIR - BRACKET ASSEMBLIES, TURBINE CASE COOLING /TCC) AIR TUBE SUPPORT - MODIFICATION OF TO INCORPORA		530	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package SB01	PW4ENG 79-76	OIL - TUBES, NO. 4 BEARING PRESSURE AND SCAVENGE - REROUTING FROM THE BEARING HOUSING TO THE INTERF		525	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package SB02	PW4ENG 72-595	NUT PLATE, SELF-LOCKING-REPLACEMENT TO ELIMINATE GALLING AND SEIZING OF BOLTS		500	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package T	19	LOOP LAMP BRACKET ELONGATED HOLE WELD REPAIR		630	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package U	20	WELD BEAD CRACK WELD REPAIR		605	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package X	23	NUTPLATE AND LUG REPLACEMENT REPAIR		500	SR Technics Switzerland
137902	50U402-01; 50U403-001; 50	EASA;FAA;CAAC;ANAC;CAA UK	26	21	72-09-73	ENGINE GENERAL - COMMON PARTS - BRACKETS - TCC MANIFOLD	Package G	6	LOOP CLAMP BRACKET ASSEMBLY WELD REPAIR		515	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package F	5	REPAIR DENTS		1340	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package G	6	SURFACE DAMAGE BLEND REPAIR		645	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package I	20	WELD OIL TANK CRACK AND SKIN PENETRATION		2630	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package J	21	NICKEL PLATE REPAIR		1665	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package K	22	TUBE BOSS INNER DIAMETER NICKEL PLATE REPAIR		1665	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package SB00	PW4ENG 79-56	INCORPORATION OF AN OIL FILLER NECK BRACE		2480	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package SB01	PW4ENG 79-47	REMOVAL OF OIL TANK REMOTE FILL OPTION		310	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package SB02	PW4ENG 79-65	RELOCATION OF FILLER NECK		95	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R053-01; 51R118-01; 51R126-01		32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package X	23	WELD REPAIR ON SUMP PUMP LOCK WIRE TAB		1635	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R	EASA;FAA;CAAC;ANAC	32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	645	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137907	50R367-01; 50R380-01; 51R	EASA;FAA;CAAC;ANAC	32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package B	1	REPLACE NUT PLATE	PN50R315-01 FOR SHOP VISIT ONLY	1095	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R	EASA;FAA;CAAC;ANAC	32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package C	2	WELD LOOSE INTERNAL PARTS		720	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R	EASA;FAA;CAAC;ANAC	32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package D	3	NICKEL PLATE MOUNT FLANGE SEAL LANDS		1635	SR Technics Switzerland
137907	50R367-01; 50R380-01; 51R	EASA;FAA;CAAC;ANAC	32	28	72-61-73	MAIN GEARBOX - LUBE OIL TANK ASSEMBLY	Package E	4	WELD OIL TANK CRACK AND SKIN PENETRATION		1080	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package C	2	NICKEL&CHROMIUM PLATE NO. 3 BEARING TRANSFER TUBE INSIDE D	FOR WEAR GREATER THAN 2.3265 INCHES	2645	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package D	3	REPAIR SEAL RING GROOVE		310	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package E	4	WELD REPAIR SEAL LANDS		1740	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package F	5	REPAIR SEAL RING GROOVE		275	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package G	6	SEAL LANDS WELD REPAIR		1740	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package H	7	LUGS WELD REPAIR		1325	SR Technics Switzerland
137912	50J352; 50J926		26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package I	8	PLASMA COAT REPAIR		1250	SR Technics Switzerland
137912	50J352; 50J926	EASA;FAA;CAAC;ANAC	26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package A	CLN/INSP	CLEANING AND INSPECTION	PN50J352P10 50J352P15 FOR SHOP VISIT ON	235	SR Technics Switzerland
137912	50J352; 50J926	EASA;FAA;CAAC;ANAC;TCCA	26	21	72-41-21	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package B	INSP-03	BLEND REPAIR		125	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package D	3	REPAIR SEAL RING GROOVE		560	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package E	4	REPAIR SEAL LANDS		1515	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package F	5	WELD REPAIR SEAL LANDS		1430	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package G	6	REPAIR SEAL RING GROOVE		560	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package H	7	BLEND REPAIR		490	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package I	8	LUGS WELD REPAIR		900	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package SB00	PW4ENG 72-652	TUBES - SPHERICAL SEAL LAND CONFIGURATIO		1375	SR Technics Switzerland
137913	50J348; 50J911		20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package SB01	PW4G-100-72-102	TUBES - SPHERICAL SEAL LAND CONFIGURATIO		1345	SR Technics Switzerland
137913	50J348; 50J911	EASA;FAA;CAAC;ANAC	20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package A	CLN/INSP	CLEANING AND INSPECTION		495	SR Technics Switzerland
137913	50J348; 50J911	EASA;FAA;CAAC;ANAC	20	21	72-41-26	DIFFUSER AND COMBUSTOR - NO. 3 BEARING PACKING TRANSFER TU	Package C	2	INNER DIAMETER NICKEL-CHROMIUM PLATE		2750	SR Technics Switzerland
137914	50J234; 50J925		22	21	72-41-29	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package D	3	REPAIR SEAL RING GROOVE		465	SR Technics Switzerland
137914	50J234; 50J925		22	21	72-41-29	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package E	4	REPAIR SEAL LANDS		955	SR Technics Switzerland
137914	50J234; 50J925		22	21	72-41-29	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package F	5	REPAIR SEAL RING GROOVE		190	SR Technics Switzerland
137914	50J234; 50J925	EASA;FAA;CAAC;ANAC	22	21	72-41-29	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package A	CLN/INSP	CLEANING AND INSPECTION		560	SR Technics Switzerland
137914	50J234; 50J925	EASA;FAA;CAAC;ANAC	22	21	72-41-29	DIFFUSER AND COMBUSTOR - SEAL RING TRANSFER (NO. 3 BEARING (	Package C	2	CHROMIUM PLATE SEAL RING TRANSFER TUBEINSIDE DIAMETER FOR	WEAR GREATER THAN 1.2015 INCHES (30.518	1995	SR Technics Switzerland
137916	50D447; 55D089		31	28	72-33-10	FAN CASE - ROD END CLEVIS (BLEED VALVE ACTUATOR)	Package C	2	REPLACE THE ANTIGALLANT		495	SR Technics Switzerland
137916	50D447; 55D089		31	28	72-33-10	FAN CASE - ROD END CLEVIS (BLEED VALVE ACTUATOR)	Package C	3	REPLACE THE ANTIGALLANT	PN 55D089	495	SR Technics Switzerland
137916	50D447; 55D089	EASA;FAA;CAAC;ANAC	31	28	72-33-10	FAN CASE - ROD END CLEVIS (BLEED VALVE ACTUATOR)	Package A	CLN/INSP	CLEANING AND INSPECTION		250	SR Technics Switzerland
137916	50D447; 55D089	EASA;FAA;CAAC;ANAC	31	28	72-33-10	FAN CASE - ROD END CLEVIS (BLEED VALVE ACTUATOR)	Package B	1	HOLE REPAIR		945	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC										
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		825	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package B	1	MINOR REPAIR - ID FRONT FLOWPATH LINER		680	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package C	2	PATCH REPAIR - ID FRONT FLOWPATH LINER		990	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package D	3	REPLACE NUT PLATES		465	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package E	4	REPLACE SPLICE PLATE		740	SR Technics Switzerland
137917	50G664; 50G666; 50G668; 5	EASA;FAA;CAAC;ANAC	26	28	72-33-18	FAN CASE - FAN EXIT LINER SEGMENT ASSEMBLY	Package F	5	REPLACE WASHERS		465	SR Technics Switzerland
137921	50G667; 51G770-01; 52G195-01		26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package C	2	REPLACE NUT PLATES		1140	SR Technics Switzerland
137921	50G667; 51G770-01; 52G195-01		26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package D	3	REPLACE WASHERS		775	SR Technics Switzerland
137921	50G667; 51G770-01; 52G195-01		26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package F	5	SURFACE DAMAGE REPAIR (MINOR)		775	SR Technics Switzerland
137921	50G667; 51G770-01; 52G195-01		26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package G	6	LINER SURFACE PATCH REPAIR		1135	SR Technics Switzerland
137921	50G667; 51G770-01; 52G195-01		26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package H	7	LEADING EDGE EROSION REPAIR		775	SR Technics Switzerland
137921	50G667; 51G770-01; 52G19!	EASA;FAA;CAAC;ANAC	26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		870	SR Technics Switzerland
137921	50G667; 51G770-01; 52G19!	EASA;FAA;CAAC;ANAC	26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
137921	50G667; 51G770-01; 52G19!	EASA;FAA;CAAC;ANAC	26	28	72-33-81	FAN CASE - FAN EXIT (FRONT) LINER SEGMENT ASSEMBLY	Package B	1	REPLACE SPLICE PLATE		1140	SR Technics Switzerland
137922	802473		26	28	72-54-02	TURBINE EXHAUST CASE - ENGINE SUPPORT CLEVIS BOSS ASSEMBLY	Package B	1	REPAIR THREADED HOLES WITH HELICAL COIL INSERTS		680	SR Technics Switzerland
137922	802473		26	28	72-54-02	TURBINE EXHAUST CASE - ENGINE SUPPORT CLEVIS BOSS ASSEMBLY	Package C	2	REPLACE BUSHING		2240	SR Technics Switzerland
137922	802473		26	28	72-54-02	TURBINE EXHAUST CASE - ENGINE SUPPORT CLEVIS BOSS ASSEMBLY	Package D	3	NICKEL PLATE REPAIR HOLE ID		3055	SR Technics Switzerland
137922	802473		26	28	72-54-02	TURBINE EXHAUST CASE - ENGINE SUPPORT CLEVIS BOSS ASSEMBLY	Package SB00	PW4ENG 72-198	BOSS ASSEMBLY, ENGINE SUPPORT CLEVIS - MODIFICATION		920	SR Technics Switzerland
137922	802473	EASA;FAA;CAAC;ANAC	26	28	72-54-02	TURBINE EXHAUST CASE - ENGINE SUPPORT CLEVIS BOSS ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		590	SR Technics Switzerland
137924	310T4025-2		21	21	71-21-16	FWD ENGINE MOUNT - BEARING HOUSING - 94"	Package B	04.Jan	BEARING REPLACEMENT		645	SR Technics Switzerland
137924	310T4025-2		21	21	71-21-16	FWD ENGINE MOUNT - BEARING HOUSING - 94"	Package C	04.Jan	SCRATCH AND GOUGE REPAIR		925	SR Technics Switzerland
137924	310T4025-2	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - BEARING HOUSING - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1185	SR Technics Switzerland
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC										
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC	13	21	71-21-16	PW4 AFTER ENGINE MOUNT HANGER ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1240	SR Technics Switzerland
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC	13	21	71-21-16	PW4 AFTER ENGINE MOUNT HANGER ASSY	Package B	08.Jan	BUSHING REPLACEMENT		600	SR Technics Switzerland
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC	13	21	71-21-16	PW4 AFTER ENGINE MOUNT HANGER ASSY	Package C	08.Jan	APPLICATION OF PROTECTIVE COATING		2290	SR Technics Switzerland
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC	13	21	71-21-16	PW4 AFTER ENGINE MOUNT HANGER ASSY	Package C	08.Feb	SCRATCH AND GOUGE REPAIR		2290	SR Technics Switzerland
137925	310U4031-1; 310U4031-11;	EASA;FAA;CAAC;ANAC	13	21	71-21-16	PW4 AFTER ENGINE MOUNT HANGER ASSY	Package D	08.Feb	BUSHING HOLE REPAIR		1970	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package D	2	MACHINE REPAIR FRONT FACE		1145	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package E	3	PLASMA SPRAY REPAIR REAR AIRSEAL SNAP DIAMETER (ID)		2430	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package F	4	PLASMA SPRAY REPAIR REAR AIRSEAL SNAP DIAMETER (OD)		2290	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package G	5	PLASMA SPRAY REPAIR FRONT AIRSEAL SNAP DIAMETER		2325	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package H	7	SHOTPEEN REPAIR		975	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package I	8	PLASMA SPRAY AIRSEAL MATING FACE		2430	SR Technics Switzerland
137926	50N003; 50N803		31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package SB00	2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1435	SR Technics Switzerland
137926	50N003; 50N803	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package A	CLN/INSP	CLEANING AND INSPECTION		1740	SR Technics Switzerland
137926	50N003; 50N803	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-53-13	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT DISK	Package C	1	SURFACE DAMAGE BLEND REPAIR		1850	SR Technics Switzerland
137930	50L194; 50L668		31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package B	2	PLASMA SPRAY REPAIR FRONT FACE		5510	SR Technics Switzerland
137930	50L194; 50L668		31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package B	3	INNER DIAMETER PLASMA COAT REPAIR		5510	SR Technics Switzerland
137930	50L194; 50L668		31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package E	4	BLEND REPAIR		390	SR Technics Switzerland
137930	50L194; 50L668		31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package SB00	SB PW4ENG 72-33	FEATURING ADDITIONAL CLEARANCES WITH MATING PARTS		1045	SR Technics Switzerland
137930	50L194; 50L668		31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package SB01	SB PW4ENG 72-46	INCORPORATION OF ADDITIONAL COOLING HOLES AND NEW SEALS		1605	SR Technics Switzerland
137930	50L194; 50L668	EASA;FAA;CAAC;ANAC	31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
137930	50L194; 50L668	EASA;FAA;CAAC;ANAC	31	28	72-52-38	HIGH PRESSURE TURBINE (HPT) - STAGE 2 HPT (REAR CASE) SEAL	Package B	1	RESTORE REAR FACE HARDFACE		5510	SR Technics Switzerland
137931	50P024	EASA;FAA;CAAC;ANAC	25	28	72-54-01	TURBINE EXHAUST CASE - HOUSING NO. 4 BRG SEAL OF TURBINE EXH	Package B	47	NICKEL PLATE REPAIR THE FIT BETWEEN CARBON SEAL HOUSING AND TEC FLANGE INNER DIAMETER		1980	SR Technics Switzerland
137932	50P138; 50P263	EASA;FAA;CAAC;ANAC	26	28	72-54-01	TURBINE EXHAUST CASE ASSEMBLY - NO. 4 BRG HEATSHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		275	SR Technics Switzerland
137932	50P138; 50P263	EASA;FAA;CAAC;ANAC	26	28	72-54-01	TURBINE EXHAUST CASE ASSEMBLY - NO. 4 BRG HEATSHIELD	Package AB	27	WELD REPAIR RIVET HOLE DAMAGE	TURBINE EXHAUST CASE ASSY REQUIRED!	1115	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package C	2	CHROMIUM PLATE OR PWA 36206?1 COAT REAR BEARING JOURNAL		1285	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package D	2	NICKEL AND CHROMIUM PLATE REAR BEARING JOURNAL		1325	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package E	3	CHROMIUM PLATE OR PWA 36206?1 COAT FRONT BEARING SHOULDER		1250	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package F	4	CHROMIUM PLATE OR PWA 36206?1 COAT REAR BEARING SHOULDER		1250	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package G	5	SURFACE DAMAGE BLEND REPAIR		600	SR Technics Switzerland
138114	50G057; 51G373		14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package H	6	REPLACE THE CUP PLUG		760	SR Technics Switzerland
138114	50G057; 51G373	EASA;FAA;CAAC;ANAC	14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	415	SR Technics Switzerland
138114	50G057; 51G373	EASA;FAA;CAAC;ANAC	14	28	72-62-03	ANGLE GEARBOX BEVEL GEARSHAFT ASSY	Package B	1	CHROMIUM PLATE OR PWA 36206?1 COAT FRONT BEARING JOURNAL		1250	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB03	PW4G 100-72-205	MODIFICATION OF THE 12TH STAGE DISK TO REMOVE CRACKS AND REDUCE STRESS		20705	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB04	PW4ENG 72-799	10TH STAGE DISK HPC INSPECTION OF THE AVT SHELF SLOTS FOR CRA	FAA-2010-24-14	630	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB05	PW4G-100-72-226	10TH STAGE DISK HPC INSPECTION OF THE AVT SHELF SLOTS FOR CRA	FAA-2010-24-14	485	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB07	PW4ENG A72-722	BORESKOPE INSPECTION OF THE 6TH TO 7TH STAGE SPACER AREA FO	AD-FAA-2002-12-15	2325	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB08	PW4G-100-72-239	BLEED TUBE ASSY 9TH STAGE HPC, INTRODUCTION OF, TO IMPROVE	FRONT COMPRESSOR DURABILITY	1685	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB09	PW4ENG 72-201	MODIFICATION OF HPC FRONT; AND DISK ASSEMBLY, DRUM ROTOR		205	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB10	PW4ENG A72-833	EDDY CURRENT AND ULTRASONIC INSPECTION OF THE 10TH STAGE D	AD 2016-08-09	5520	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB11	PW4G100-A72-255	EDDY CURRENT AND ULTRASONIC INSPECTION OF THE 10TH STAGE D	AD 2016-08-09	5520	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB12	PW4ENG 72-814	REPL./MODI OF ANTI VORTEX TUBES		1215	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB13	PW4G-100-72-	FPI HPC FRNT DRUM SHELF SLOTS		375	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB15	PW4ENG 72-845	HPC, NEW DRUM ROTOR DISK ASSY		545	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB16	PW4G-100-72-260	HPC, NEW DRUM ROTOR DISK ASSY		545	SR Technics Switzerland
138115	50H859; 50H859-001; 50S106-01; 50S826-01; 51H426-01; 52H559-01; 52H!		51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB17	PW4ENG 72-809	FPI HPC FRONT DRUM SHELF SLOTS (ONE TIME)	PART ONE	545	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package A	CLN/INSP	CLEANING AND INSPECTION		4100	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package AI	34	FRONT DRUM REAR MATING DIAMETER DUAL WIRE ARC COAT REPAIR		3320	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package D	3	SHOTPEEN BLADE SLOTS	(INCL. REP-010)	3725	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package H	7	BLEND REPAIR TANGENTIAL SLOT RIM RAILS		1115	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package I	8	BLEND REPAIR KNIFE-EDGE SEALS		915	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package J	9	RESTORE KNIFE-EDGE SEAL THIN PLASMA COATING		4780	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package K	10	RESTORE ANTIGALLING COATING TO AXIAL BLADE SLOTS (STAGE 6, 7 AND 8)		2785	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package L	11	SURFACE DAMAGE BLEND REPAIR		6370	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package M	12	REPLACE 9TH STAGE HPC DRUM ROTOR (FRONT) DISK TUBE ASSEMBLY		3365	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package N	13	PLASMA SPRAY REPAIR FRONT DRUM FRONT OUTER ID SNAP DIAMETER		5170	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package O	14	PLASMA SPRAY REPAIR FRONT DRUM FRONT INNER OD SNAP DIAMETER		5170	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package P	15	PLASMA SPRAY REPAIR FRONT DRUM REAR SNAP DIAMETER		5170	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package S	18	REPLACE ANTI-VORTEX TUBES		2600	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB00	AD 2005-25-09	FPI LIFE-LIMITED PART, HPC FRONT DRUM	IN CONJUNCTION WITH PACKAGE A	110	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB01	PW4ENG 72-322	RESTORE ANTIGALLING COATING TO BLADE SLOT STG. 6		1990	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC;CAA UK	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package AN	39	RESTORE KNIFE-EDGE SEAL THICK PLASMA COATING		3375	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC;CAA UK	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB02	PW4ENG 72-745	FLUORECENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	105	SR Technics Switzerland
138115	50H859; 50H859-001; 50S1(	EASA;FAA;CAAC;ANAC;CAA UK	51	28	72-35-07	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR (FRONT) DISK AS	Package SB03	PW4ENG 72-782	MODIFICATION OF THE 12TH STAGE DISK TO REMOVE CRACKS AND REDUCE STRESS		20705	SR Technics Switzerland
138121	70R229; 70R738	EASA;FAA;CAAC;ANAC										
138121	70R229; 70R738	EASA;FAA;CAAC;ANAC	26	28	72-61-48	MAIN GEARBOX - GEARBOX BEARING SEAL SEAT	Package B	1	LAP CARBON SEAL MATING FACE	FOR SHOP VISITS ONLY	320	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: MOUNT SUPPORT REPLACEMENT	810	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: LINK ASSY REPLACEMENT (2EA)	1935	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE F	EXAMPLE: CROSSBEAM ASSY REPLACEMENT	3320	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package G	OVERHAUL	DISASSEMBLY, CLEANIG, INSPECTION, ASSEMBLY. EXCLUDED PIECE	PART REPAIRS	3405	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB00	PW4NAC 71-111	MODIFICATION OF MOUNT RETAINER ASSEMBLY	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB01	PW4NAC 71-74	INSPECTION AND ELECTRO ETCHING	IN CONJUNCTION WITH PACKAGE HEAVY OR	330	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB02	PW4NAC 71-58	REPLACEMENT OF STOP BOLTS	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB03	PW4NAC 71-77	REPLACEMENT OF MAIN BEAM AND BEARING	IN CONJUNCTION WITH PACKAGE HEAVY OR	125	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB04	PW4MD11 71-36	MODIFICATION OF RETAINER ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	130	SR Technics Switzerland
138122	221-4049-503; 221-4049-50	EASA;FAA;CAAC;ANAC	22	21	71-20-04	FWD ENGINE MOUNT - ASSEMBLY - 94"	Package SB05	PW4NAC 71-163	REPLACE ATTACHMENT HARDWARE WITH SERIALIZED PARTS		125	SR Technics Switzerland
138141	50R280-01; 51R059-01; 51R	EASA;FAA;CAAC;ANAC										
138141	50R280-01; 51R059-01; 51R	EASA;FAA;CAAC;ANAC	25	28	72-61-74	MAIN GEARBOX - OIL TANK HEAT SHIELD ASSEMBLY	Package B	1	REPAIR DAMAGED AREA	FOR SHOP VISITS ONLY	500	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package F	5	AIRSEAL MATING DIAMETER PLASMA COAT REPAIR		3820	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package G	6	MATING SNAP DIAMETER PLASMA SPRAY REPAIR		3650	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package H	7	MATING SNAP DIAMETER PLASMA SPRAY REPAIR		3830	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package J	9	AIRSEAL SNAP DIAMETER PLASMA SPRAY REPAIR		4275	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package K	10	SHOTPEEN REPAIR		1150	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 51N405; 51N505		26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package SB00	AD 2005-25-09	FPI OF LIFE LIMITED PARTS		985	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 5	EASA;FAA;CAAC;ANAC	26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package A	CLN/INSP	CLEANING AND INSPECTION		1600	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 5	EASA;FAA;CAAC;ANAC	26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package C	2	FRONT FACE MACHINE REPAIR		1340	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 5	EASA;FAA;CAAC;ANAC	26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package D	3	FRONT FLANGE FACE PLASMA SPRAY REPAIR		4165	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 5	EASA;FAA;CAAC;ANAC;CAA UK	26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package B	1	SURFACE DAMAGE BLEND REPAIR		1145	SR Technics Switzerland
138148	50N405; 50N505; 51N305; 5	EASA;FAA;CAAC;ANAC;CAA UK	26	28	72-53-15	LOW PRESSURE TURBINE (LPT) - STAGE 5 REAR TURBINE HUB	Package E	4	INNER SNAP DIAMETER PLASMA SPRAY REPAIR		3820	SR Technics Switzerland
138149	310T4031-1; 310T4031-10;	EASA;FAA;CAAC;ANAC										
138149	310T4031-1; 310T4031-10;	EASA;FAA;CAAC;ANAC	24	21	71-21-16	AFT ENGINE MOUNT - HANGER ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1390	SR Technics Switzerland
138149	310T4031-1; 310T4031-10;	EASA;FAA;CAAC;ANAC	24	21	71-21-16	AFT ENGINE MOUNT - HANGER ASSY - 94"	Package B	05.Jan	BUSHING REPLACEMENT		2265	SR Technics Switzerland
138149	310T4031-1; 310T4031-10;	EASA;FAA;CAAC;ANAC	24	21	71-21-16	AFT ENGINE MOUNT - HANGER ASSY - 94"	Package C	05.Feb	BUSHING HOLE REPAIR		2970	SR Technics Switzerland
138162	221-4047-503; 221-4047-505; 221-4047-507		27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package J	9	BUSHING REPLACEMENT		1765	SR Technics Switzerland
138162	221-4047-503; 221-4047-505; 221-4047-507		27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package J	10	BUSHING REPLACEMENT	FOR PN 221-4047-507	1765	SR Technics Switzerland
138162	221-4047-503; 221-4047-505; 221-4047-507		27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package SB00	PW4NAC 71-74	INSPECTION AND ELECTRO ETCHING		140	SR Technics Switzerland
138162	221-4047-503; 221-4047-505; 221-4047-507		27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package SB01	PW4MD11 71-104	BERYLLIUM COPPER BUSHING INSTALLATION	MD11	1765	SR Technics Switzerland
138162	221-4047-503; 221-4047-505; 221-4047-507		27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package SB01	PW4NAC 71-152	BERYLLIUM COPPER BUSHING INSTALLATION	AIRBUS	1765	SR Technics Switzerland
138162	221-4047-503; 221-4047-50	EASA;FAA;CAAC;ANAC	27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		1215	SR Technics Switzerland
138162	221-4047-503; 221-4047-50	EASA;FAA;CAAC;ANAC	27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package F	5	NICKS, GOUGES AND SCRATCHES REPAIR		390	SR Technics Switzerland
138162	221-4047-503; 221-4047-50	EASA;FAA;CAAC;ANAC	27	21	71-20-04	FWD ENGINE MOUNT - MOUNT SUPPORT - 94"	Package I	8	APPLICATION OF CORROSION RESISTANT FINISHES TO SUPPORT		1040	SR Technics Switzerland
138164	221-4004-503		6	21	71-20-04	PW4 ENG FWD MOUNT CROSSBEAM	Package D	3	BUSHING REPLACEMENT		2190	SR Technics Switzerland
138164	221-4004-503	EASA;FAA;CAAC;ANAC	6	21	71-20-04	PW4 ENG FWD MOUNT CROSSBEAM	Package A	CLN/INSP	CLEANING & INSPECTION		390	SR Technics Switzerland
138166	50H552; 53H090		26	28	72-35-74	HIGH PRESSURE COMPRESSOR (HPC) - LEVER SET	Package SB00	PW4ENG 72-246	INCORPORATION OF MORE DURABLE COMPRESSOR STATOR CYLINDER SUPPORT		680	SR Technics Switzerland
138166	50H552; 53H090	EASA;FAA;CAAC;ANAC	26	28	72-35-74	HIGH PRESSURE COMPRESSOR (HPC) - LEVER SET	Package A	CLN/INSP	CLEANING AND INSPECTION		1200	SR Technics Switzerland
138166	50H552; 53H090	EASA;FAA;CAAC;ANAC	26	28	72-35-74	HIGH PRESSURE COMPRESSOR (HPC) - LEVER SET	Package B	1	PLASMA SPRAY HPC INLET LEVER OD JOURNAL		1920	SR Technics Switzerland
138178	PW4000 MOD-41-1		6	28	72-41-XX	PW4 OUTER COMBUSTION CASE (PARTS) 94"	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	1165	SR Technics Switzerland
138236	50H084CL1; 50H084CL2; 50I	EASA;FAA;CAAC;ANAC										
138236	50H084CL1; 50H084CL2; 50I	EASA;FAA;CAAC;ANAC	4	28	72-35-40	PW4 VSV-BEARING TO HPC FRONT CASE	Package B	1	REWORK OUTER DIAMETER FOR INSTALLATION		80	SR Technics Switzerland
138236	50H084CL1; 50H084CL2; 50I	EASA;FAA;CAAC;ANAC	4	28	72-35-40	PW4 VSV-BEARING TO HPC FRONT CASE	Package C	23	REWORK OUTER DIAMETER FOR INSTALLATION		80	SR Technics Switzerland
138236	50H084CL1; 50H084CL2; 50I	EASA;FAA;CAAC;ANAC	4	28	72-35-40	PW4 VSV-BEARING TO HPC FRONT CASE	Package D	44	REWORK OUTER DIAMETER FOR INSTALLATION		80	SR Technics Switzerland
138241	50B426; 51B026; 53B516; 5	EASA;FAA;CAAC;ANAC										
138241	50B426; 51B026; 53B516; 5	EASA;FAA;CAAC;ANAC	27	28	72-31-03	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.6 LPC BLADE - 94"	Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		70	SR Technics Switzerland
138241	50B426; 51B026; 53B516; 5	EASA;FAA;CAAC;ANAC	27	28	72-31-03	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.6 LPC BLADE - 94"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
138242	50B202; 50B902	EASA;FAA;CAAC;ANAC	26	28	72-31-04	LOW PRESSURE COMPRESSOR (LPC) - STAGE 2 LPC BLADE - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		70	SR Technics Switzerland
138242	50B202; 50B902	EASA;FAA;CAAC;ANAC	26	28	72-31-04	LOW PRESSURE COMPRESSOR (LPC) - STAGE 2 LPC BLADE - 94"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
138243	50B203; 50B903	EASA;FAA;CAAC;ANAC	24	28	72-31-05	LOW PRESSURE COMPRESSOR (LPC) - STAGE 3 LPC BLADE - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		70	SR Technics Switzerland
138243	50B203; 50B903	EASA;FAA;CAAC;ANAC	24	28	72-31-05	LOW PRESSURE COMPRESSOR (LPC) - STAGE 3 LPC BLADE - 94"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
138244	51B104; 51B404	EASA;FAA;CAAC;ANAC	25	28	72-31-06	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 LPC BLADE - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		70	SR Technics Switzerland
138244	51B104; 51B404	EASA;FAA;CAAC;ANAC	25	28	72-31-06	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 LPC BLADE - 94"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package B	1	REPLACE LPC STATOR NUT PLATES		400	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package C	2	REPLACE LPC SPLITTER FAIRING NUT OPTION		375	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package D	3	REPLACE BLEED VALVE DUCT BRACKET		3555	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package D	5	REPLACE DUCT BRACKET		3555	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package D	7	REPLACE DUCT BRACKET		3555	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package E	4	REPLACE BLEED VALVE DUCT BRACKET ASSEMBLY NUT OPTIONS		1225	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package F	6	REPLACE BLEED VALVE DUCT BRACKET ASSEMBLY NUT OPTIONS		965	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package G	8	REPLACE BLEED VALVE DUCT HELICOIL INSERTS		400	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package H	9	REPLACE REAR ANGLE GANGNUT ASSEMBLY		775	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package H	10	REPLACE REAR GANGNUT ASSEMBLY NUT PLATES		775	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package I	11	REPLACE BRACKET ASSEMBLY		1720	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package I	12	REPLACE BRACKET ASSEMBLY NUT PLATES		1720	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package J	13	REPLACE THE GUIDE VANE PIN RIVET AND COLLAR		200	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package K	14	TOUCH UP ANODIZE		375	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package L	16	REPLACE RUBBER SEAL		1135	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package M	17	REPLACE A RIVETED BEARING PAD WITH A RIVETED BEARING PAD		2070	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package N	18	REPLACE BEARINGS IN BELLCRANK BRACKET		505	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package R	22	REPLACE A BONDED BEARING PAD WITH A BONDED BEARING PAD		1825	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package S	24	REPLACE A BONDED BEARING PAD WITH A RIVETED BEARING PAD		2580	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package SB00	PW4ENG 72-39	LPC, 4TH STAGE, AND, CASE ASSEMBLY, FAN EXIT, INNER - MODIFICATION OF OD SNAP DIAMETERS		770	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package SB01	PW4ENG 72-346	REPLACEMENT OF OR MODIFICATION OF	TO INCORPORATE BOLTED - ON BELLCRANK E	895	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package SB02	PW4ENG 72-660	MODIF.OF,TO INCORP. NEW 2.5 BLD ROLLER CAM FOLLOWERS, STEEL CAM FOLLOWER SLOT LINERS, & BEARING PA		12140	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package T	25	REPAIR THE ABLATIVE COATING		1715	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package U	27	WELD THE CAM SLOTS IN THE BLEED VALVE DUCT		3755	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package V	28	REPAIR DAMAGED FIRE ABLATIVE COATING WITH FIRE ABLATIVE BLANKETS		2270	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package W	29	WELD CRACKS AND RECONTOUR THE GUSSETS IN THE BLEED VALVE DUCT		6105	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package X	42	REPAIR DAMAGED FOIL ON THE FIRE ABLATIVE BLANKETS		2470	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package Y	44	FRONT INNER CASE (NEW) REPLACEMENT REPAIR		2030	SR Technics Switzerland
138252	50D373-007; 50D628-003; 50D628-01; 50D630-003; 50D937-003; 50D937-(		37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package Z	45	REPLACE LINER REPAIR		1025	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION	FPI CASE	2585	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AA	46	CAM SLOT TAB OUTSIDE DIAMETER REPAIR		5575	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AC	48	BENT SPLITTER FAIRING FLANGE REPAIR		3290	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AD	49	INNER CASE DOUBLER PLATE REPAIR		3910	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AE	52	WELD A CRACKED OR OVERSIZED CAM SLOT LINER RIVET HOLE		4720	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AF	53	WELD AN OVERSIZED BEARING PAD RIVET HOLE		8535	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AG	55	WELD DAMAGED SPLITTER FAIRING NUTPLATE BOLT OR RIVET HOLE REPAIR		1540	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AI	67	FRONT CASE REAR FLANGE RIVET HOLE CRACK WELD REPAIR		4260	SR Technics Switzerland
138252	50D373-007; 50D628-003; 5	EASA;FAA;CAAC;ANAC;CAA UK	37	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 94"	Package AH	63	BLEED VALVE SCREEN INNER SURFACE BLEND REPAIR		575	SR Technics Switzerland
138258	50J439; 50J618	EASA;FAA;CAAC;ANAC	29	28	72-41-12	DIFFUSER AND COMBUSTOR - DOWELED END (COMBUSTION CHAMB	Package A	CLN/INSP	CLEANING AND INSPECTION		220	SR Technics Switzerland
138258	50J439; 50J618	EASA;FAA;CAAC;ANAC	29	28	72-41-12	DIFFUSER AND COMBUSTOR - DOWELED END (COMBUSTION CHAMB	Package C	2	RESTORE HARDFACE COATING TO DOWELED END	MINIMUM OF 10 EA	655	SR Technics Switzerland
138259	50A620; 50A695; 51A008; 5	EASA;FAA;CAAC;ANAC										
138259	50A620; 50A695; 51A008; 5	EASA;FAA;CAAC;ANAC	16	28	72-33-84	FAN CASE - NO. 3 BEARING AIR COOLER ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1175	SR Technics Switzerland
138267	9-15 HPC BLADES		20	28	72-35-38	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR AND BLADES (FF	Package B	ASSEMBLY 02	GRIND STAGE 9 THROUGH 12 HPC BLADE PLATFORMS - 94"	FOR SHOP VISIT ONLY	1360	SR Technics Switzerland
138267	9-15 HPC BLADES		20	28	72-35-38	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR AND BLADES (FF	Package C	ASSEMBLY 03	GRIND STAGE 13 THROUGH 15 HPC BLADE PLATFORMS - 94"	FOR SHOP VISIT ONLY	1360	SR Technics Switzerland
138267	9-15 HPC BLADES		20	28	72-35-38	HIGH PRESSURE COMPRESSOR (HPC) - DRUM ROTOR AND BLADES (FF	Package D	ASSEMBLY 03	GRIND AND MEASURE THE AXIAL COMPRESSOR ROTOR ASSEMBLY BL	FOR SHOP VISIT ONLY	1360	SR Technics Switzerland
138378	50K306		25	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - PLATI	Package K	10	CRACK WELD REPAIR REAR SUPPORT PLATE		3070	SR Technics Switzerland
138378	50K306	EASA;FAA;CAAC;ANAC	25	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - PLATI	Package B	1	ONE LUG NUT PLATE REPLACEMENT REPAIR		1575	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 70R969; 70R976		24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package G	6	REPLACE DAMAGED OR LOOSE STUDS		1145	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 70R969; 70R976		24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package H	7	BEARING SUPPORT BORE NICKEL PLATE REPAIR		1365	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package B	1	REPLACE HELICAL COIL INSERTS		580	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package C	2	ANODIZE TOUCH-UP		565	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package D	3	NICKEL PLATE THE OIL METERING PLUG HOLE OUTSIDE BORE		1185	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package E	4	NICKEL PLATE THE OIL METERING PLUG HOLE INSIDE BORE		1185	SR Technics Switzerland
138379	70R529; 70R637; 70R698; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-33	MAIN GEARBOX - GEARBOX (FRONT HYDRAULIC PUMP DRIVE) BEARI	Package F	5	NICKEL PLATE THE OD		1260	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package K	10	REPAIR OF CRACKS IN SVA BRACKET FLANGE		4050	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package M	12	RIVET REPLACEMENT REPAIR ON STIFFENING PANELS		3850	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package Q	16	EPOXY COAT REPAIR		1575	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package R	17	NUT PLATE NUT REPLACEMENT REPAIR		2415	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package SB00	PW4ENG 72-685	PROVIDE A NEW COMPRESSOR STATOR CYLINDER SUPPORT ASSEMBLY WITH A BRACE THAT HAS A CLEARANCE CU1		1245	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H214-01; 54H967; 54H974-01; 54H975-01; 58HC		32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package SB00	PW4G-100-72-130	PROVIDE A NEW COMPRESSOR STATOR CYLINDER SUPPORT ASSEMBLY WITH A BRACE THAT HAS A CLEARANCE CU1		1245	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package A	CLN/INSP	CLEANING AND INSPECTION		500	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package AN		STOP NUTS REPLACEMENT	ACCORDING SPM 70-00-00	735	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package B	1	NICKEL PLATE REPAIR FOR COMPRESSOR CYLINDER SUPPORT ASSEMBLY LOWER JOURNALS		5820	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package C	2	NICKEL PLATE REPAIR FOR COMPRESSOR CYLINDER SUPPORT ASSEMBLY UPPER JOURNALS		6695	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package D	3	NICKEL PLATE REPAIR FOR HOLES		4730	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package E	4	REPAIR OF WORN LOWER ATTACHMENT HOLES		3530	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package F	5	RESTORE THICKNESS OF WORN LOWER SUPPORT LEAVES - (SVA BRACKET)		3615	SR Technics Switzerland
138380	51H229-01; 53H036-01; 53H	EASA;FAA;CAAC;ANAC	32	28	72-35-73	HIGH PRESSURE COMPRESSOR (HPC) - COMPRESSOR STATOR CYLINDI	Package I	8	RESTORE THICKNESS OF WORN LOWER SUPPORT LEAVES		3615	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 70R902; 71R003		24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package F	5	REPAIR THE MIDDLE ID WITH A BUSHING		1235	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 70R902; 71R003		24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package G	6	REPLACE HELICAL COIL INSERTS		430	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 70R902; 71R003		24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package H	7	PMA DRIVE HOUSING BLEND REPAIR		625	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 70R902; 71R003		24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package I	8	PMA DRIVE HOUSING BLEND REPAIR		470	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 70R902; 71R003		24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package SB00	78F-98.A	EEC GENERATOR HOUSING - TAPPING OF HOLES		565	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package B	1	REPLACE HELICAL COIL INSERTS		680	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package C	2	APPLY ANODIZE TOUCH-UP SOLUTION		565	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package D	3	NICKEL PLATE THE OD		1325	SR Technics Switzerland
138381	70R234; 70R633; 70R771; 7(	EASA;FAA;CAAC;ANAC	24	28	72-61-47	MAIN GEARBOX - GEARBOX GENERATOR (EEC/PMA ALTERNATOR) HC	Package E	4	REPAIR THE FRONT ID WITH A BUSHING		1235	SR Technics Switzerland
138382	310T3033-1; 310T3033-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	AFT ENGINE MOUNT - CENTER LINK ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		335	SR Technics Switzerland
138382	310T3033-1; 310T3033-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	AFT ENGINE MOUNT - CENTER LINK ASSY - 94"	Package B	07.Jan	BEARING REPLACEMENT		1360	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138382	310T3033-1; 310T3033-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	AFT ENGINE MOUNT - CENTER LINK ASSY - 94"	Package C	07.Jan	BLEND REPAIR		295	SR Technics Switzerland
138382	310T3033-1; 310T3033-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	AFT ENGINE MOUNT - CENTER LINK ASSY - 94"	Package D	07.Feb	REPAIR FOR OVERSIZE BEARING		2045	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package B	1	REPLACE CORROSION PROTECTIV COATING		630	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package C	2	NICKEL PLATE THE PACKING LANDS		1360	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package D	3	NICKEL PLATE THE END FACE		1360	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package E	4	CHROMIUM PLATE THE REAR BEARING SHOULDER		2050	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package F	5	CHROMIUM PLATE THE FRONT BEARING SHOULDER		2050	SR Technics Switzerland
138579	70R043		27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package G	6	NICKEL PLATE THE FRONT INNER DIAMETER		1360	SR Technics Switzerland
138579	70R043	EASA;FAA;CAAC;ANAC	27	28	72-61-35	MAIN GEARBOX - GEARBOX FRONT HYDRAULIC PUMP DRIVE BEARIN	Package A	CLN/INSP	CLEANING AND INSPECTION		570	SR Technics Switzerland
138580	312T4311-1; 312T4336-1; 3	EASA;FAA;ANAC										
138580	312T4311-1; 312T4336-1; 3	EASA;FAA;CAAC;ANAC										
138580	312T4311-1; 312T4336-1; 3	EASA;FAA;CAAC;ANAC	5	21	36-10-06	PNEUMATIC DUCTS B-767	Package A	CLN/INSP	CLEANING AND INSPECTION		670	SR Technics Switzerland
138580	312T4311-1; 312T4336-1; 3	EASA;FAA;CAAC;ANAC	5	21	36-10-06	PNEUMATIC DUCTS B-767	Package D	LIGHT	MINOR REPAIR		1270	SR Technics Switzerland
138580	312T4311-1; 312T4336-1; 3	FAA;CAAC;ANAC										
138628	50P128; 50P274-01; 50P275	EASA;FAA;CAAC;ANAC	32	21	72-54-08	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (OUTER) TU	Package A	CLN/INSP	CLEANING AND INSPECTION		545	SR Technics Switzerland
138628	50P128; 50P274-01; 50P275	EASA;FAA;CAAC;ANAC	32	21	72-54-08	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (OUTER) TU	Package B	1	FERRULE TUBE FITTING PLASMA COAT REPAIR		650	SR Technics Switzerland
138628	50P128; 50P274-01; 50P275	EASA;FAA;CAAC;ANAC	32	21	72-54-08	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (OUTER) TU	Package G	6	REPLACE THE PIN		1050	SR Technics Switzerland
138628	50P128; 50P274-01; 50P275	EASA;FAA;CAAC;ANAC	32	21	72-54-08	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (OUTER) TU	Package K	SPM	REPAIR OF THE TUBE CONICAL SEAT	ACC SPM 70-00-00 REPAIR 22	345	SR Technics Switzerland
138629	50A374; 51A142-01; 51A16	EASA;FAA;CAAC;ANAC										
138629	50A374; 51A142-01; 51A16	EASA;FAA;CAAC;ANAC	31	21	72-54-09	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (INNER) TUI	Package A	CLN/INSP	BORESCOPE INSPECTION		445	SR Technics Switzerland
138629	50A374; 51A142-01; 51A16	EASA;FAA;CAAC;ANAC	31	21	72-54-09	TURBINE EXHAUST CASE - NO. 4 BEARING OIL SCAVENGE (INNER) TUI	Package A	CLN/INSP	CLEANING AND INSPECTION		445	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276-01; 50P312-01		34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package G	6	REPLACE THE PIN		840	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276-01; 50P312-01		34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package J	9	HOUSING WEAR PLASMA COAT REPAIR		945	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276	EASA;FAA;CAAC;ANAC	34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package A	CLN/INSP	BORESCOPE INSPECTION		545	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276	EASA;FAA;CAAC;ANAC	34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package A	CLN/INSP	CLEANING AND INSPECTION		545	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276	EASA;FAA;CAAC;ANAC	34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package B	1	FERRULE TUBE FITTING AND SLEEVE PLASMA COAT REPAIR		830	SR Technics Switzerland
138630	50P070; 50P273-01; 50P276	EASA;FAA;CAAC;ANAC	34	21	72-54-07	TURBINE EXHAUST CASE - NO. 4 BEARING OIL PRESSURE TUBE ASSEN	Package C		REMOVAL OF CARBON IN TUBE (BAKE METHOD)		845	SR Technics Switzerland
138631	50P031	EASA;FAA;CAAC;ANAC	5	28	72-54-10	PW4 NO. 4 BEARING (OIL) NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		410	SR Technics Switzerland
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC										
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC	32	28	72-41-40	DIFFUSER AND COMBUSTOR - FUEL NOZZLE SUPPLY MANIFOLD ASSE	Package A	CLN/INSP	CLEANING AND INSPECTION		405	SR Technics Switzerland
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC	32	28	72-41-40	DIFFUSER AND COMBUSTOR - FUEL NOZZLE SUPPLY MANIFOLD ASSE	Package B	1	INNER DIAMETER TUBE REPAIR		900	SR Technics Switzerland
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC	32	28	72-41-40	DIFFUSER AND COMBUSTOR - FUEL NOZZLE SUPPLY MANIFOLD ASSE	Package SB00	PW4G-100-73-6	INCORPORATION OF NEW MANIFOLDS AND MORE DURABLE PREFORM PACKINGS		530	SR Technics Switzerland
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC	32	28	72-41-40	DIFFUSER AND COMBUSTOR - FUEL NOZZLE SUPPLY MANIFOLD ASSE	Package SB01	PW4G-100-73-48	INSTALLATION OF NEW HARDWARE FOR IMPROVED DURABILITY	AD FAA 2019-06-07	375	SR Technics Switzerland
138647	50J105; 50J105-001; 50J372	EASA;FAA;CAAC;ANAC	32	28	72-41-40	DIFFUSER AND COMBUSTOR - FUEL NOZZLE SUPPLY MANIFOLD ASSE	Package W	22	REPAIR CONICAL SEAT	SPM 70-00-00	310	SR Technics Switzerland
138662	50B245-01		32	28	72-31-28	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING SEAL SUPPORT ,	Package C	3	LOOSE OR DAMAGED CLINCH NUT REPLACEMENT REPAIR		565	SR Technics Switzerland
138662	50B245-01		32	28	72-31-28	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING SEAL SUPPORT ,	Package D	5	OUTER MATING DIAMETER PLASMA COAT REPAIR	(TITANIUM PART)	2120	SR Technics Switzerland
138662	50B245-01	EASA;FAA;CAAC;ANAC	32	28	72-31-28	LOW PRESSURE COMPRESSOR (LPC) - NO. 1 BEARING SEAL SUPPORT ,	Package A	CLN/INSP	CLEANING AND INSPECTION		800	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 51G447; 52G113-01		32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package F	98	FAN EXIT CASE FLANGE ASSEMBLY ANTI-GALLANT REPAIR		775	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 51G447; 52G113-01		32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package G	117	PLASMA SPRAY REPAIR FLANGE D1 SURFACE		2130	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 5	EASA;FAA;CAAC;ANAC	32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		940	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 5	EASA;FAA;CAAC;ANAC	32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package B	44	BLEND SURFACE DAMAGE ON THE FAN EXIT CASE FLANGE ASSEMBLY		955	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 5	EASA;FAA;CAAC;ANAC	32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package C	50	MAKE STRAIGHT AND BLEND THE FAN EXIT CASE FLANGE		835	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 5	EASA;FAA;CAAC;ANAC	32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package D	96	TOUCH UP FAN EXIT CASE FLANGE ASSEMBLY PROTECTION LAYER REPAIR		775	SR Technics Switzerland
138663	50G439; 51G232; 51G233; 5	EASA;FAA;CAAC;ANAC	32	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package E	97	FAN EXIT CASE FLANGE ASSEMBLY NUT PLATE REPLACEMENT		920	SR Technics Switzerland
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC										
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC	7	21	72-33-20	PW4 BELL CRANK BRACKET ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		355	SR Technics Switzerland
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC	7	21	72-33-20	PW4 BELL CRANK BRACKET ASSEMBLY	Package B	1	REPLACE THE BEARINGS 94"		635	SR Technics Switzerland
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC	7	21	72-33-20	PW4 BELL CRANK BRACKET ASSEMBLY	Package C	2	REPLACE THE BEARINGS 100"		370	SR Technics Switzerland
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC	7	21	72-33-20	PW4 BELL CRANK BRACKET ASSEMBLY	Package D	3	REPLACE THE GUIDE PIN		315	SR Technics Switzerland
138667	50D939-01; 51D778-001; 51	EASA;FAA;CAAC;ANAC	7	21	72-33-20	PW4 BELL CRANK BRACKET ASSEMBLY	Package SB00	PW4G-100-72-112	FC, SLOT LINER MODI 2.5 BLEED SYSTEM		400	SR Technics Switzerland
138805	51A578		15	28	72-53-84	LOW PRESSURE TURBINE (LPT) - NO 4 BEARING RETAINING PLATE	Package B	1	NICKEL PLATE REPAIR SNAP DIAMETER		1135	SR Technics Switzerland
138805	51A578		15	28	72-53-84	LOW PRESSURE TURBINE (LPT) - NO 4 BEARING RETAINING PLATE	Package C	2	NICKEL PLATE REPAIR PREFORMED PACKING SEAL LAND		1135	SR Technics Switzerland
138805	51A578		15	28	72-53-84	LOW PRESSURE TURBINE (LPT) - NO 4 BEARING RETAINING PLATE	Package D	INSP/CHECK-03	REMOVE DAMAGE BY BLENDING		150	SR Technics Switzerland
138805	51A578	EASA;FAA;CAAC;ANAC	15	28	72-53-84	LOW PRESSURE TURBINE (LPT) - NO 4 BEARING RETAINING PLATE	Package A	CLN/INSP	CLEANING AND INSPECTION		445	SR Technics Switzerland
138809	217563-1	EASA;FAA;CAAC;ANAC	24	21	73-11-04	FUEL-PUMP/DISTRIBUTION VALVE - FUEL PUMP - INLET HOUSING	Package B		REPLACE SLEEVE BEARING	ACCORDING CMM	1575	SR Technics Switzerland
138811	800999-1	EASA;FAA;ANAC	22	21	73-21-64	FUEL METRING UNIT - JFC131-2 - HOUSING	Package B	01.Jan	REMOVAL AND REPLACEMENT OF RING LOCKED STUDS		785	SR Technics Switzerland
139219	50J309; 50J310; 50J311; 50J	EASA;FAA;CAAC;ANAC										
139219	50J309; 50J310; 50J311; 50J	EASA;FAA;CAAC;ANAC	25	28	72-41-01	DIFFUSER AND COMBUSTOR - CHANNEL ASSY OF DIFFUSER CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		160	SR Technics Switzerland
139219	50J309; 50J310; 50J311; 50J	EASA;FAA;CAAC;ANAC	25	28	72-41-01	DIFFUSER AND COMBUSTOR - CHANNEL ASSY OF DIFFUSER CASE	Package B	SPM-02	REPAIR OF GANG NUT ASSEMBLIES	SPM 70-00-00 P/N 585005 REP.02	745	SR Technics Switzerland
139219	50J309; 50J310; 50J311; 50J	EASA;FAA;CAAC;ANAC	25	28	72-41-01	DIFFUSER AND COMBUSTOR - CHANNEL ASSY OF DIFFUSER CASE	Package B	SPM-11	REPLATING OF CASE FLANGE NUTS	SPM 70-00-00 P/N 585005 REP.11	745	SR Technics Switzerland
139226	50A191; 50A191-001; 50A6	EASA;FAA;CAAC;ANAC										
139226	50A191; 50A191-001; 50A6	EASA;FAA;CAAC;ANAC	21	28	72-54-83	TURBINE EXHAUST CASE - NO. 4 BEARING COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		680	SR Technics Switzerland
139226	50A191; 50A191-001; 50A6	EASA;FAA;CAAC;ANAC	21	28	72-54-83	TURBINE EXHAUST CASE - NO. 4 BEARING COVER	Package SB00	PW4ENG 72-385	MODIFICATION OF, TO INCLUDE JACKSCREW HOLES		900	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package B	1	BRUSH SEAL REPLACEMENT REPAIR		1145	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package C	2	PLASMA SPRAY SNAP DIAMETER		2395	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package D	3	PLASMA COAT REPAIR OIL PRESSURE TUBE BOSS ID		2395	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package E	4	PLASMA COAT REPAIR OIL SCAVENGE BOSS ID		2260	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package F	5	PLAMA SPRAY REPAIR BREATHER BOSS ID		2260	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package G	6	SLEEVE REPAIR OIL PRESSURE TUBE BOSS ID		2760	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package H	7	SLEEVE REPAIR OIL SCAVENGE TUBE BOSS ID		2570	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package I	8	SLEEVE REPAIR BREATHER BOSS ID		2570	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package J	9	SLEEVE REPAIR 12TH STAGE AIR SUPPLY TUBE BOSS		2570	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package K	10	SLEEVE REPAIR TOBI SENSE TUBE BOSS		2480	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package L	11	SLEEVE REPAIR OIL WEEP TUBE BOSS		2480	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package M	12	SLEEVE REPAIR NO.3 BEARING COMPARTMENT BUFFER AIR BOSS		2570	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package N	13	SURFACE DAMAGE BLEND REPAIR		1175	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package O	14	SNAP DIAMETER PLASMA SPRAY REPAIR		2615	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package R	17	WELD REPAIR BUFFER AIR BOSS OUTSIDE DIAMETER		3225	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package SB00	72-219577	N2-VIBRATION PREVENTIVE ACTIONS	ONLY BRUSH SEAL INSPECTION	110	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package T	19	ANIT ROTATION SLOT BLEND REPAIR		325	SR Technics Switzerland
139227	50J550-01		35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package V	21	PARTIAL TUBE BOSS WELD REPAIR		3420	SR Technics Switzerland
139227	50J550-01	EASA;FAA;CAAC;ANAC	35	28	72-41-41	DIFFUSER AND COMBUSTOR - HPC (REAR) EXIT BRUSH SEAL ASSEMBL	Package A	CLN/INSP	CLEANING AND INSPECTION		445	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J987-01		32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package G	6	SUPPORT CRACK WELD REPAIR		2075	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J987-01		32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package SB00	PW4ENG 72-630	HPC EXIT BRUSH SEAL SUPPORT MODIFICATION		1480	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J987-01		32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package SB01	72-219577	N2-VIBRATION PREVENTIVE ACTIONS	ONLY BRUSH SEAL INSPECTION	110	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J9	EASA;FAA;CAAC;ANAC	32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J9	EASA;FAA;CAAC;ANAC	32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package B	1	REPLACE BRUSH SEAL		910	SR Technics Switzerland
139228	50J837-01; 50J841-01; 50J9	EASA;FAA;CAAC;ANAC	32	28	72-41-39	DIFFUSER AND COMBUSTOR - HPC EXIT BRUSH SEAL SUPPORT ASSEM	Package F	5	SURFACE DAMAGE BLEND REPAIR		635	SR Technics Switzerland
139229	50K154-01		34	28	72-51-12	TURBINE NOZZLE - STAGE 1 HPT BRUSH SEAL AND SUPPORT ASSEMBL	Package B	1	HPT BRUSH SEAL REPLACEMENT REPAIR		1235	SR Technics Switzerland
139229	50K154-01		34	28	72-51-12	TURBINE NOZZLE - STAGE 1 HPT BRUSH SEAL AND SUPPORT ASSEMBL	Package E	4	SURFACE DAMAGE BLEND REPAIR		345	SR Technics Switzerland
139229	50K154-01	EASA;FAA;CAAC;ANAC	34	28	72-51-12	TURBINE NOZZLE - STAGE 1 HPT BRUSH SEAL AND SUPPORT ASSEMBL	Package A	CLN/INSP	CLEANING AND INSPECTION		830	SR Technics Switzerland
139276	50L247-01; 55L032-01	EASA;FAA;CAAC;ANAC;CAA UK	21	28	72-52-33	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT BAND SEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		380	SR Technics Switzerland
139276	50L247-01; 55L032-01	EASA;FAA;CAAC;ANAC;CAA UK	21	28	72-52-33	HIGH PRESSURE TURBINE (HPT) - STAGE 1 HPT BAND SEGMENT	Package B	1	CRACK REPAIR		830	SR Technics Switzerland
139300	664508; 740535	EASA;FAA;CAAC;ANAC										
139300	664508; 740535	EASA;FAA;CAAC;ANAC	5	28	72-61-65	PW4 PRESSURE RELIEF VALVE (FILTER ELEMENT)	Package A	TEST	PRESSURE TEST		490	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package AA	26	REAR HUB FRONT JOURNAL CHROMIUM P		3260	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package AB	27	REAR HUB TURBINE PILOT DIAMETER REAR JOURNAL CHROMIUM PLATE		5515	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package AC	28	NO3 BEARING SEAL SEAT SHOULDER PLASMA COAT REPAIR		5520	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package AG	32	SPLINE GALLING REPAIR		925	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package B	1	NICKEL PLATE HPC REAR HUB NO. 3 BEARING HEAT SHIELD REAR JOURNAL		4990	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package C	2	NICKEL PLATE HPC REAR HUB NO. 3 BEARING HEAT SHIELD FRONT JOURNAL		4990	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package F	5	CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING JOURNAL		5295	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package G	6	CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING SEAL SPACER JOURNAL		5295	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package H	7	CHROMIUM PLATE HPC REAR HUB NO. 3 BEARING FRONT SEAL JOURNAL		5295	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package I	8	NICKEL PLATE HPC REAR HUB NO. 3 BEARING SEAL SEAT SHOULDER		5425	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package J	9	BLEND REPAIR REAR HUB TORQUE SLOT LUGS		1515	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package L	11	PLASMA SPRAY HPC FRONT SNAP DIAMETER		5300	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package O	14	BLEND REPAIR SURFACE DAMAGE		1070	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package P	15	BLEND REPAIR KNIFE-EDGE SEALS		915	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package R	17	BLEND REPAIR SPLINE SURFACE DAMAGE		1340	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package U	20	REPAIR THE HEAT SHIELD ANTI-ROTATION SLOT SURFACE DAMAGE		2785	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package X	23	SKIM MACHINE CUT REPAIR FRONT SNAP DIAMETER		1645	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package Y	24	SKIM MACHINE CUT REPAIR REAR SNAP DIAMETER		1645	SR Technics Switzerland
139302	54H767		38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package Z	25	SKIM MACHINE CUT REPAIR NO3 BEARING STACKUP SHOULDER REAR HUB		545	SR Technics Switzerland
139302	54H767	EASA;FAA;CAAC;ANAC;CAA UK	38	35	72-35-09	HIGH PRESSURE COMPRESSOR (HPC) - TURBINE DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		975	SR Technics Switzerland
139323	50A722; 51A358		31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package C	2	NICKEL PLATE REPAIR FRONT ID PILOT DIAMETER		3435	SR Technics Switzerland
139323	50A722; 51A358		31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package D	3	MACHINE REPAIR FRONT FACE		2130	SR Technics Switzerland
139323	50A722; 51A358		31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package E	4	OUTER SURFACE CORROSION REPAIR		425	SR Technics Switzerland
139323	50A722; 51A358		31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package I	8	REAR FLANGE DENTS POLISH		125	SR Technics Switzerland
139323	50A722; 51A358	EASA;FAA;CAAC;ANAC	31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		605	SR Technics Switzerland
139323	50A722; 51A358	EASA;FAA;CAAC;ANAC	31	28	72-52-80	HIGH PRESSURE TURBINE (HPT) - NO. 3 BEARING RETAINING NUT	Package B	1	REPLACE SILVER PLATE		1055	SR Technics Switzerland
139324	94" REAR COMPR ROTOR ASSY		28	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package B	ASSEMBLY 03	HIGH SPEED GRINDING OF BLADE TIP	FOR SHOP VISITS ONLY	10435	SR Technics Switzerland
139324	94" REAR COMPR ROTOR ASSY		28	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package C	1	BLEND INSTALLED HPC BLADES	FOR SHOP VISITS ONLY	3170	SR Technics Switzerland
139324	94" REAR COMPR ROTOR ASSY		28	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package SB00	PW4ENG 72-755	HIGH SPEED GRINDING OF BLADE TIP (RING CASE CONFIGURATION)	BOEING	10435	SR Technics Switzerland
139324	94" REAR COMPR ROTOR ASSY		28	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package SB00	PW4ENG 72-756	HIGH SPEED GRINDING OF BLADE TIP (RING CASE CONFIGURATION)	AIRBUS	10435	SR Technics Switzerland
139324	94" REAR COMPR ROTOR ASSY		28	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package SB00	PW4ENG 72-757	HIGH SPEED GRINDING OF BLADE TIP (RING CASE CONFIGURATION)	MCDONNELL DOUGLAS	10435	SR Technics Switzerland
139326	HPC REAR CASE-14.		19	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package B		MACHINING OF ASSY STATORS (STAGE 8-15)	FOR SHOP VISITS ONLY	5375	SR Technics Switzerland
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1275	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package AI	34	REVISE THE STAGE 5, 6 AND 7 SHROUD SETS RUBSTRIPS		4400	SR Technics Switzerland
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package B		LEVEL INNER SHROUD (HONEYCOMB) FOR KNIFE EDGE CLEARENACE		3300	SR Technics Switzerland
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package SB00	PW4G-100-72-269	REPLACEMENT OF HPC 5TH STG BLADES (PART B-NON RCC ENG)	PART 001	350	SR Technics Switzerland
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package V	21	REWORK SHROUD STG. 5-7 (FELTMETAL)		4040	SR Technics Switzerland
139327	SHRD SET STG 5-7; SHROUD SET 5-7.STG		31	28	72-35-40	HIGH PRESSURE COMPRESSOR (HPC) - FRONT CASE/OUTER AIRSEAL S	Package W	22	REWORK SHROUD STG. 5-7 (PLASMA COAT)		4040	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB02	PW4ENG 72-609	MODIFICATION OF TO INCREASE CLEARENCE WITH THE PT4.95 SENSE TUBE		275	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB03	PW4ENG 74-5	IGNITION EXCITER HEATSH. LOCATION IDENTIFICATION		155	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB04	PW4ENG 73-118	INCORPORATION OF NEW TERMINAL LUG CONNECTORS		205	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA										
139328	14510-113; 1A8431; 221-43	EASA;FAA;ANAC										
139328	14510-113; 1A8431; 221-43	EASA;FAA;ANAC;TCCA										
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC										
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package B		NUTPLATES REPLACEMENT	ACC. SPM	185	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC										
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package A	CLN/INSP	CLEANING AND INSPECTION		160	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package B		INSERTS REPLACEMENT	ACC. SPM	185	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB01	PW4ENG 72-595	REPLACEMENT TO ELIMINATE GALLING AND SEIZING OF BOLTS		140	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB05	PW4ENG 74-4	EXCITER FR.HEATSHIELD ASSY- MODIFICATION		155	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC;TCCA										
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package B		SPRING TENSION CLIP REPLACEMENT	ACC. SPM	185	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package C	1	WELD REPAIR POWER PLANT BRACKETS	71-09-73	255	SR Technics Switzerland
139328	14510-113; 1A8431; 221-43	EASA;FAA;CAAC;ANAC;TCCA	28	21	72-09-00	ENGINE GENERAL - COMMON PARTS - VARIOUS ENGINE BRACKETS AI	Package SB00	PW4G-100-72-60	INCORPORATION OF NEW SPRING TENSION CLIPS		245	SR Technics Switzerland
139332	50A721		29	28	72-52-83	HIGH PRESSURE TURBINE (HPT) - TURBINE SHAFT SPACER	Package B	1	SURFACE DAMAGE MACHINE GRIND REPAIR		955	SR Technics Switzerland
139332	50A721	EASA;FAA;CAAC;ANAC	29	28	72-52-83	HIGH PRESSURE TURBINE (HPT) - TURBINE SHAFT SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
139575	800967-1		24	21	73-21-64	FUEL METRING UNIT - JFC131-2 - GEAR	Package SB00	SB JFC131-2-73-	REPLACEMENT OF THE SPUR GEAR AND THE SEGMENT GEAR		745	SR Technics Switzerland
139575	800967-1	EASA;FAA;ANAC	24	21	73-21-64	FUEL METRING UNIT - JFC131-2 - GEAR	Package F	05.Feb	REPAIR OF THE TRANSMITTER RESOLVER AND CONTACTS WHEN THE SPUR GEAR IS WORN IN TWO OPPOSITE QUAD		330	SR Technics Switzerland
139579	51G470; 51G472; 51G487; 5	EASA;FAA;CAAC;ANAC	12	28	72-34-01	PW4 (94") COVER ASSY OF FAN EXIT CASE ASSEMBLY	Package B	100	STOP DRILL FAIRING COVER CRACKS		345	SR Technics Switzerland
139579	51G470; 51G472; 51G487; 5	EASA;FAA;CAAC;ANAC	12	28	72-34-01	PW4 (94") COVER ASSY OF FAN EXIT CASE ASSEMBLY	Package C	101	REPLACEMENT OF FAN EXIT FAIRING		1185	SR Technics Switzerland
139579	51G470; 51G472; 51G487; 5	EASA;FAA;CAAC;ANAC	12	28	72-34-01	PW4 (94") COVER ASSY OF FAN EXIT CASE ASSEMBLY	Package D	SPM	REPLACE STOPS ACC. SPM		110	SR Technics Switzerland
139579	51G470; 51G472; 51G487; 5	EASA;FAA;CAAC;ANAC;CAA UK	12	28	72-34-01	PW4 (94") COVER ASSY OF FAN EXIT CASE ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		145	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;ANAC										
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC										
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package A		PRESSURE TEST		475	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package A	CLN/INSP	CLEANING & INSPECTION		475	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package D	SPM	REPAIR CONICAL SEAT		485	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package SB00	PW4ENG 79-91	INSPECTION FOR VACUUM TESTING MARKING ON "B" NUT		250	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package SB01	PW4ENG 72-645	MODIFICATION OF METAL HOSE (AS12) TO ENSURE SAFETY WIRE PROVISIONS		315	SR Technics Switzerland
139590	50T955; 50T963; 50U214; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 FLEXIBLE EXTERNAL HOSES	Package SB02	PW4G-100-73-32	OFF-WING INSPECTION OF FM11 TUBE ASSY		250	SR Technics Switzerland
139603	SCREW-NUT-SPACER-SET2; ST1075-11		25	28	72-00-00	ENGINE GENERAL - COMMON PARTS - SCREWS, NUTS AND SPACERS F	Package B	LIGHT	REFURBISHMENT OF REMOVED SET OF PARTS	LESS THAN 4 OF ENG. MODULES PARTIALLY/F	4250	SR Technics Switzerland
139603	SCREW-NUT-SPACER-SET2; ST1075-11		25	28	72-00-00	ENGINE GENERAL - COMMON PARTS - SCREWS, NUTS AND SPACERS F	Package C	MEDIUM	REFURBISHMENT OF REMOVED SET OF PARTS	MODULE 33 AND 34 PARTIALLY/FULLY DISASS	16905	SR Technics Switzerland
139603	SCREW-NUT-SPACER-SET2; ST1075-11		25	28	72-00-00	ENGINE GENERAL - COMMON PARTS - SCREWS, NUTS AND SPACERS F	Package D	HEAVY	REFURBISHMENT OF REMOVED SET OF PARTS	MODULE 35 PARTIALLY/FULLY DISASSEMBLEI	35195	SR Technics Switzerland
139603	SCREW-NUT-SPACER-SET2;	EASA	25	28	72-00-00	ENGINE GENERAL - COMMON PARTS - SCREWS, NUTS AND SPACERS F	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	650	SR Technics Switzerland
139613	51T857; 51U728; 51U729; 5	EASA;FAA;ANAC										
139613	51T857; 51U728; 51U729; 5	EASA;FAA;CAAC;ANAC										
139613	51T857; 51U728; 51U729; 5	EASA;FAA;CAAC;ANAC	5	21	75-24-00	PW4TCC IDLER ARM LINKAGE WITH BEARING	Package B		REPLACE BEARING		130	SR Technics Switzerland
139620	51U671; 54T700; ST1614-11	EASA;FAA;CAAC;ANAC										
139620	51U671; 54T700; ST1614-11	EASA;FAA;CAAC;ANAC	24	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUS1	Package A	CLN/INSP	CLEANING AND INSPECTION		115	SR Technics Switzerland
139620	51U671; 54T700; ST1614-11	EASA;FAA;CAAC;ANAC	24	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUS1	Package C	2	LOCK NUT THREADS SILVER PLATE REPAIR		235	SR Technics Switzerland
139630	420193; 55T119		11	21	24-21-43	CABLE POWER ELECTRICAL ID	Package G		OVERHAUL		2730	SR Technics Switzerland
139630	420193; 55T119	EASA;FAA;CAAC;ANAC	11	21	24-21-43	CABLE POWER ELECTRICAL ID	Package E		REPAIR		1530	SR Technics Switzerland
139630	420193; 55T119	EASA;FAA;CAAC;ANAC;CAA UK	11	21	24-21-43	CABLE POWER ELECTRICAL ID	Package C		TEST		840	SR Technics Switzerland
139672	50A526; 51A480; 52A078; 5	EASA;FAA;CAAC;ANAC	35	28	72-31-83	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR BLADE (STAGE 1)	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
139672	50A526; 51A480; 52A078; 5	EASA;FAA;CAAC;ANAC	35	28	72-31-83	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR BLADE (STAGE 1)	Package B	1	REPLACE ANTIROTATION PIN		390	SR Technics Switzerland
139672	50A526; 51A480; 52A078; 5	EASA;FAA;CAAC;ANAC	35	28	72-31-83	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR BLADE (STAGE 1)	Package D	3	PWA 595 ALUMINUM COATING REPAIR		4945	SR Technics Switzerland
139672	50A526; 51A480; 52A078; 5	EASA;FAA;CAAC;ANAC	35	28	72-31-83	LOW PRESSURE COMPRESSOR (LPC) - COMPRESSOR BLADE (STAGE 1)	Package E	INSP-03	INSP/CHECK-03 BLEND SURFACE DAMAGE		155	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC										
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package A	CLN/ISNP	CLEANING AND INSPECTION		625	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package AE	30	ACOUSTIC LINER SEGMENT SEAL, GASKET AND BLEED VALVE DUCT BONDING REPAIR		545	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package G	6	FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES EPOXY REPAIR		645	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package J	9	REPLACE WASHERS		960	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package L	11	REPAIR DISCONNECTED INSULATION BLANKET		545	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package M	12	REPLACE COOLING AIR DUCT SEAL		1290	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51C	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package M	12	REPLACE INSULATION BLANKET		1290	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package M	12	REPLACE LINER WITH FLAME ARRESTOR		1290	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package M	12	REPLACE NUT PLATES		1290	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package O	14	INSULATION BLANKET OUTER FABRIC PATCH REPAIR		545	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package P	15	INSULATION BLANKET DAMAGED ALUMINUM FOIL REPAIR		695	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package Q	16	REPAIR PUNCTURES OR CRACKS		545	SR Technics Switzerland
139674	51D901-01; 51D902-01; 51D	EASA;FAA;CAAC;ANAC	23	28	72-33-80	FAN CASE - FAN EXIT (INNER) LINER SEGMENT ASSEMBLIES - 100"	Package T	19	CUT SEAL REPAIR		260	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC										
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package A	CLN/INSP	CLEANING AND INSPECTION		670	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	155	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package B	1	REPLACE WASHERS		645	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package C	2	SURFACE DAMAGE REPAIR (POLYURETHANE COAT)		635	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package D	3	REPLACE FAN EXIT FAIRING PANEL SPACERS		565	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package E	4	NUT PLATE REPLACEMENT REPAIR		610	SR Technics Switzerland
139684	51G528-01; 51G529-01; 51G	EASA;FAA;CAAC;ANAC	27	28	72-33-86	FAN CASE - FAN EXIT (BIFURCATION) FAIRING ASSEMBLY LEFT AND RI	Package F	5	SMALL SURFACE DAMAGE REPAIR		960	SR Technics Switzerland
139689	51R071; 51R130		6	28	72-41-91	PW4 GEARBOX LUG GUIDE ASSEMBLY	Package C	INSP/CHECK-06	GEARBOX LUG GUIDE ASSEMBLY		120	SR Technics Switzerland
139689	51R071; 51R130		6	28	72-41-91	PW4 GEARBOX LUG GUIDE ASSEMBLY	Package SB00	PW4G-100-72-10	REPLACEMENT OF MAIN GEARBOX MOUNT CENTER GUIDE		545	SR Technics Switzerland
139689	51R071; 51R130	EASA;FAA;CAAC;ANAC	6	28	72-41-91	PW4 GEARBOX LUG GUIDE ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		385	SR Technics Switzerland
139689	51R071; 51R130	EASA;FAA;CAAC;ANAC	6	28	72-41-91	PW4 GEARBOX LUG GUIDE ASSEMBLY	Package B	5	PLASMA COAT BEARING HOUSING		1615	SR Technics Switzerland
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC										
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC	22	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUST	Package A	CLN/INSP	CLEANING AND INSPECTION		155	SR Technics Switzerland
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC	22	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUST	Package B	1	PWA 474 ANTIGALLING COMPOUND REPLACEMENT REPAIR	FOR P/N 54T696, 54T697, 54T684 AND 54T67	115	SR Technics Switzerland
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC	22	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUST	Package C	1	PWA 474 ANTIGALLING COMPOUND REPLACEMENT REPAIR	FOR P/N 54T676, 54T680, 54T683 AND 58T75	165	SR Technics Switzerland
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC	22	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUST	Package D	1	PWA 474 ANTIGALLING COMPOUND REPLACEMENT REPAIR	FOR P/N 54T662, 54T663, 57T206 AND 59T69	205	SR Technics Switzerland
139690	54T662; 54T663; 54T674; 54	EASA;FAA;CAAC;ANAC	22	21	71-21-10	FWD ENGINE MOUNT - BOLTS, NUTS, PLATES, WASHERS AND THRUST	Package E	1	PWA 474 ANTIGALLING COMPOUND REPLACEMENT REPAIR	ONLY REMOVE ANTIGALLANT COUNPOUND	85	SR Technics Switzerland
139695	54T937; 54T939; 55T619		24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - SECONDARY	Package D	3	SECONDARY LINK OUTER SURFACE PLASMA SPRAY REPAIR		610	SR Technics Switzerland
139695	54T937; 54T939; 55T619		24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - SECONDARY	Package E	4	PRIMARY AND SECONDARY LINK SURFACE DAMAGE BLEND REPAIR		505	SR Technics Switzerland
139695	54T937; 54T939; 55T619	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - SECONDARY	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
139695	54T937; 54T939; 55T619	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - SECONDARY	Package B	1	REAR MOUNT LINK AND LINK ASSEMBLY BEARING DISASSEMBLY, MARKING, REPLACEMENT AND ASSEMBLY		400	SR Technics Switzerland
139695	54T937; 54T939; 55T619	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - SECONDARY	Package C	2	SECONDARY LINK BEARING OVAL TRACK PLASMA SPRAY REPAIR		630	SR Technics Switzerland
139714	50U594-01; 58T656-001; 58	EASA;FAA;CAAC;ANAC	19	21	72-35-00	HIGH PRESSURE COMPRESSOR (HPC) - BRACKET-ASSY OF LC	Package A	CLN/INSP	CLEANING AND INSPECTION		260	SR Technics Switzerland
139714	50U594-01; 58T656-001; 58	EASA;FAA;CAAC;ANAC	19	21	72-35-00	HIGH PRESSURE COMPRESSOR (HPC) - BRACKET-ASSY OF LC	Package AE		REPLACE DEFECTIVE NUTPLATES	ACC. SPM 70-43-00	185	SR Technics Switzerland
139714	50U594-01; 58T656-001; 58	EASA;FAA;CAAC;ANAC	19	21	72-35-00	HIGH PRESSURE COMPRESSOR (HPC) - BRACKET-ASSY OF LC	Package SB00	PW4G-100-72-75	MODIFICATON OF TO REMOVE AND UNSUSED NUTPLAT		360	SR Technics Switzerland
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC										
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC	24	28	72-09-72	ENGINE GENERAL - COMMON PARTS - EXTERNAL DUCTS	Package A	CLN/INSP	CLEANING AND INSPECTION		260	SR Technics Switzerland
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC	24	28	72-09-72	ENGINE GENERAL - COMMON PARTS - EXTERNAL DUCTS	Package B	1	WELD REPAIR OF DAMAGED COOLING DUCT		1435	SR Technics Switzerland
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC	24	28	72-09-72	ENGINE GENERAL - COMMON PARTS - EXTERNAL DUCTS	Package D	3	WELD REPAIR OF AIR STARTER VALVE DUCT ASSEMBLY KEY		1365	SR Technics Switzerland
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC	24	28	72-09-72	ENGINE GENERAL - COMMON PARTS - EXTERNAL DUCTS	Package E	4	REPLACE AIR STARTER VALVE DUCT ASSEMBLY KEY		1470	SR Technics Switzerland
139715	50U039-01; 52U600-01; 58T	EASA;FAA;CAAC;ANAC	24	28	72-09-72	ENGINE GENERAL - COMMON PARTS - EXTERNAL DUCTS	Package F		REPLACE RIVETED PARTS		140	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package H	7	BLEND REPAIR		520	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package I	8	REPLACE SILICONE RUBBER SEAL		1650	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package J	9	HOLE REPAIR		2120	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package L	11	REPLACE TEFLON COATING		2285	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package M	12	BUSHING REPLACEMENT		1155	SR Technics Switzerland
139722	50D461; 53D546		33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package SB00	PW4G-100-72-112	MODIFICATION OF TO INCORPORATE NEW ROLLER CAM FOLLOWERS		1990	SR Technics Switzerland
139722	50D461; 53D546	EASA;FAA;CAAC;ANAC	33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		1130	SR Technics Switzerland
139722	50D461; 53D546	EASA;FAA;CAAC;ANAC	33	28	72-33-09	FAN CASE - BLEED VALVE ASSEMBLY - 100"	Package B	1	ANODIZE TOUCH-UP		830	SR Technics Switzerland
139723	50D653; 53D361		28	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 100"	Package D	3	REPLACE THE ANTIGALLING COMPOUND		515	SR Technics Switzerland
139723	50D653; 53D361		28	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 100"	Package E	4	CONNECTING PIN HOLE REPAIR		865	SR Technics Switzerland
139723	50D653; 53D361	EASA;FAA;CAAC;ANAC	28	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
139723	50D653; 53D361	EASA;FAA;CAAC;ANAC	28	28	72-33-12	FAN CASE - BLEED VALVE CONNECTING LINK - 100"	Package C	2	REPLACE THE BEARING		865	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package H	7	OUTER FLANGE BOLTHOLE CRACKS WELD REPAIR		5425	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package I	8	OUTER FLANGE FRONT FACE WELD REPAIR		4680	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package J	9	FUNCTIONAL AIRFLOW (CHECK) REPAIR		1650	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package N	13	REPLACE THE CLINCH NUTS		770	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package O	14	PLASMA COAT REPAIR THE BRUSH SEAL SUPPORT DIAMETER		3430	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package P	15	INNER FLANGE BOLT HOLE CRACKS WELD REPAIR		4555	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package R	17	OUTER FLANGE FRONT FACE PLASMA SPRAY REPAIR		3455	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package SB00	PW4G-100-72-109	INCORP. OF ADDITIONAL PLATFORM AND AIRFOIL COOLING WHICH REQUIRES A NEW FIRST STAGE HPT COOLING D		3830	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package SB01	PW4G-100-72-172	INSPECTION AND MODIFICATION OF THE VANE CAVITIES		715	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package SB02	PW4G-100-72-219	MODIFICATION OF TO INCORPORATE THE ADVANTAGE 70 PERFORMANCE		1650	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package SB03	PW4G-100-72-220	CONVERSION OF PW4164 PW4168 OR PW4168A TO A PW4164-1D PW	MODIFY OLD ASSY TO THE NEW FLOW CONFI	2730	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package SB04	000696-ED01	MODIFICATION TO INCREASE TOBI FLOW		3655	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package Y	24	OUTER FLANGE REAR FACE PLASMA COAT REPAIR		3325	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50K373-001; 50K373-01; 50K610-01; 50K610-101		29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package Z	25	BLEND REPAIR		600	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package A	CLN/INSP	CLEANING AND INSPECTION		540	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package B	1	FRONT FLANGE FACE PLASMA SPRAY REPAIR		3990	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package D	3	PLASMA SPRAY INNER COMBUSTION CHAMBER DIAMETER		3915	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package E	4	FRONT DIAMETER PLASMA SPRAY REPAIR		3915	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package F	5	LOCATING PIN REPLACEMENT		920	SR Technics Switzerland
139725	50K138-001; 50K138-01; 50I	EASA;FAA;CAAC;ANAC	29	28	72-51-03	TURBINE NOZZLE - STAGE 1 HPT (BLADE) COOLING DUCT ASSEMBLY -	Package G	6	WELD REPAIR THE PS4 TUBE HOLE		4870	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 50N420		31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package E	4	SNAP DIAMETER PLASMA SPRAY REPAIR		3540	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 50N420		31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package F	5	AIRSEAL BALANCE REPAIR		1250	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 50N420		31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package F	7	AIRSEAL BALANCE REPAIR		1250	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 50N420		31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package I	8	COUNTERWEIGHT TAB REPAIR		1740	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 50N420		31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package M	CLN-01	REMOVE CORROSION BY WET BLASTING		525	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 5	EASA;FAA;CAAC;ANAC	31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package A	CLN/INSP	CLEANING AND INSPECTION		1200	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 5	EASA;FAA;CAAC;ANAC	31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package B	1	KNIFE-EDGE SEALS BLEND REPAIR		1575	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 5	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package B	6	KNIFE-EDGE SEALS BLEND REPAIR		1575	SR Technics Switzerland
139726	50N007; 50N381; 50N412; 5	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-53-38	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (INNER ROTATING) AIRS	Package C	2	SURFACE DAMAGE BLEND REPAIR		1320	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package C	2	PLASMA SPRAY TURBINE SHAFT COUPLING NO. 1.5 BEARING SPACER JOURNAL		5205	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package D	3	PLASMA SPRAY TURBINE SHAFT COUPLING NO. 1.5 BEARING JOURNAL		5425	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package E	4	PLASMA SPRAY TURBINE SHAFT COUPLING FAN HUB SHOULDER		5005	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package F	5	PLASMA SPRAY TURBINE SHAFT COUPLING FAN HUB FRONT PILOT DIAMETER		4700	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package G	6	FRONT PILOT DIAMETER PLASMA COAT REPAIR		5710	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package H	7	PLASMA SPRAY TURBINE SHAFT COUPLING NUT PILOT DIAMETER		6475	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package I	8	PLASMA SPRAY TURBINE SHAFT COUPLING FAN HUB REAR PILOT DIAMETER		3885	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package J	9	PLASMA SPRAY TURBINE SHAFT COUPLING REAR PILOT DIAMETER		4515	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package K	10	PLASMA SPRAY TURBINE SHAFT COUPLING MOTION PICKUP DIAMETER		6520	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package L	11	REPLACE TURBINE SHAFT COUPLING ASSEMBLY MOTION PICKUP WHEEL		575	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package M	12	BLEND REPAIR		1475	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package N	13	FAN HUB SHOULDER PLASMA COAT REPAIR	FRONT	2140	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package O	14	PLASMA SPRAY REPAIR		2140	SR Technics Switzerland
139728	50A281; 51A275		39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package P	15	FAN HUB SHOULDER PLASMA COAT REPAIR	REAR	2140	SR Technics Switzerland
139728	50A281; 51A275	EASA;FAA;CAAC;ANAC	39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1005	SR Technics Switzerland
139728	50A281; 51A275	EASA;FAA;CAAC;ANAC;CAA UK	39	28	72-32-01	LPC/LPT COUPLING - TURBINE SHAFT COUPLING ASSEMBLY	Package B	1	REPLACE ANTIGALLANT		920	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package B	1	ANODIZE TOUCH-UP		565	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package B	INSP-03	BLEND REPAIR		565	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package C	7	OIL PRESSURE MANIFOLD SUPPORT BRACKET REPLACEMENT		965	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package G	6	OIL PRESSURE MANIFOLD SUPPORT BRACKET BUSHING REPLACEMENT		1215	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package Q	16	BOLT HOLE BLEND REPAIR		625	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package R	19	REPAIR FRONT FLANGE BOLT HOLES		1260	SR Technics Switzerland
139730	51A397-01		32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package S	20	REPAIR REAR FLANGE BOLT HOLES		1260	SR Technics Switzerland
139730	51A397-01	EASA;FAA;CAAC;ANAC	32	28	72-34-81	INTERMEDIATE CASE - NO. 1 BEARING REAR SUPPORT ASSEMBLY - 10	Package A	CLN/INSP	CLEANING AND INSPECTION		635	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package G	6	REPLACE PROTECTIVE LAYER REPAIR		3410	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package I	8	INSIDE DIAMETER SURFACE ABRASION REPAIR		775	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package K	10	REPLACE DAMAGED LEADING EDGE SHIELD		2425	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package L	11	LEADING EDGE EROSION (HOLE) REPAIR		855	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package L	11	LEADING EDGE FILLER REPAIR		855	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package L	11	METAL SHIELD BUT JOINT GAP REPAIR		855	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package M	12	CRUSHED REAR EDGE REPAIR		2260	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package S	18	LEADING EDGE SHIELD INNER LIP DISBOND REPAIR		1000	SR Technics Switzerland
139732	50A178; 50A786-01; 51A541-01; 51A627-01; 51A630-01; 51A754-01		33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package SB00	PW4ENG 72-296	MODIF OF LEADING EDGE		4920	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		695	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package AN		PART- AND SERIAL NUMBER MARKING		160	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package B	1	REPLACE FAN EXIT FAIRING ANTIGALLING COMPOUND		775	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package C	2	PUNCTURE REPAIR FAN EXIT FAIRING		1585	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package D	3	REPAIR CHIPPED, ABRADED OR DELAMINATED FAN EXIT FAIRING		1865	SR Technics Switzerland
139732	50A178; 50A786-01; 51A54	EASA;FAA;CAAC;ANAC	33	28	72-31-84	LOW PRESSURE COMPRESSOR (LPC) - FAN EXIT FAIRING	Package G	5	TOUCH-UP FAN EXIT FAIRING PROTECTIVE COATING		3410	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AE	30	BOLT HOLE FUSION WELD REPAIR		1985	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AG	32	WELD OVERSIZED VANE ATTACHMENT RIVET HOLES		6400	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AI	34	BENT FLANGE STRAIGHTENING REPAIR		3295	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AJ	42	OUTER SHROUD PWA 36003 SILICONE RUBBER REPLACEMENT REPAIR		3835	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AK	40	OUTER SHROUD SURFACE DAMAGE WELD REPAIR		1960	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AL	41	FAIRING TO INNER SHROUD CRACK REPAIR		1560	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package B	1	ANODIZE TOUCH-UP		580	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package Q	16	BLEND REPAIR VANES AND OUTER SHROUD		965	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package S	18	CRACK REPAIR LPC STAGE 1 COMPRESSOR STATOR ASSEMBLY INNER SHROUD		1740	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package T	19	REPLACE LPC (STAGE 1) COMPRESSOR STATOR ASSEMBLY INNER AIRSEAL		2525	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package V		21 FAIRING SCUFFING, FRAYING, NICKS, CHIPS AND DENTS REPAIR		2745	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package Y		24 REPLACE DAMAGED VANE POTTING COMPOUND REPAIR		3900	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55B051-01		35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package Z		25 FAIRING POTTING FILLER COMPOUND VOID AND CRACK REPAIR		2640	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55	EASA;FAA;CAAC;ANAC	35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package A	CLN/INSP	CLEANING AND INSPECTION		1470	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55	EASA;FAA;CAAC;ANAC	35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AA		26 REPLACE DAMAGED STATOR VANE REPAIR		11265	SR Technics Switzerland
139733	51B571-001; 51B571-01; 55	EASA;FAA;CAAC;ANAC	35	28	72-31-09	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 COMPRESSOR STATOR	Package AC		28 REPLACE INDIVIDUAL INNER SHROUD SEGMENT REPAIR		15370	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package C		2 REPLACE PIN		670	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package G		6 WELD THE LUGS ON THE OUTER SHROUD	REP.01 INCLUDED	2220	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package L		9 REPLACE VANES		3230	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package N		10 BLEND STATOR VANES (TITANIUM) REPAIR		775	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package O		11 PLASMA SPRAY INNER SHROUD		2215	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package Q		13 BLEND REPAIR FOR DAMAGED INNER SHROUD LUGS		775	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package R		14 VANE RUBBER REPAIR	SEAL INNER SHROUD VANE	4700	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package S		14 VANE RUBBER REPAIR	SEAL OUTER SHROUD VANE	5470	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package SB00	PW4G-100-72-243	REPLACEMENT OR MODIFICATION OF, TO INCORPORTE A BOLT LOCKING FEATURE		1400	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package T		15 BLEND THE QUTER SHROUD SURFACE DAMAGED		330	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package U		20 SEALANT TOUCH-UP REPAIR		2555	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package V		22 INNER SHROUD BOLTHOLES REPAIR		850	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package W		18 REMOVAL OF REMAINING CORROSION REPAIR		1720	SR Technics Switzerland
139734	51D874-01; 53G174		37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package X		23 BLEND REPAIR ON IN SHROUD BOLTHOLES		820	SR Technics Switzerland
139734	51D874-01; 53G174	EASA;FAA;CAAC;ANAC	37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		1200	SR Technics Switzerland
139734	51D874-01; 53G174	EASA;FAA;CAAC;ANAC	37	28	72-34-50	INTERMEDIATE CASE - FOURTH STAGE COMPRESSOR STATOR ASSEM	Package B		1 TOUCH-UP PROTECTIVE COATING		635	SR Technics Switzerland
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC										
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC	5	28	72-33-15	PW4 (100") FAN EXIT BASE AND VANE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		180	SR Technics Switzerland
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC	5	28	72-33-15	PW4 (100") FAN EXIT BASE AND VANE ASSY	Package C		2 AIRFOIL PATCH		430	SR Technics Switzerland
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC	5	28	72-33-15	PW4 (100") FAN EXIT BASE AND VANE ASSY	Package T		19 LEADING EDGE FLUOROELASTOMER REPAIR	PP-LEVEL	330	SR Technics Switzerland
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC	5	28	72-33-15	PW4 (100") FAN EXIT BASE AND VANE ASSY	Package V		21 SURFACE EROSION REPAIR	PP-LEVEL	710	SR Technics Switzerland
139735	51D910; 52D680; 52D680-0(	EASA;FAA;CAAC;ANAC;CAA UK										
139736	51J092; 51J102; 51J104; 51J	EASA;FAA;CAAC;ANAC										
139736	51J092; 51J102; 51J104; 51J	EASA;FAA;CAAC;ANAC	26	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package B		60 PLASMA COATING REPLACEMENT		630	SR Technics Switzerland
139737	50K202; 50K204; 50K205; 5(	EASA;FAA;CAAC;ANAC										
139737	50K202; 50K204; 50K205; 5(	EASA;FAA;CAAC;ANAC;CAA UK										
139737	50K202; 50K204; 50K205; 5(	EASA;FAA;CAAC;ANAC;CAA UK	27	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - LINEF	Package B		34 PLASMA COATING REPLACEMENT		630	SR Technics Switzerland
139738	50K037; 51K209-01; 51K211-01		28	28	72-51-80	TURBINE NOZZLE - COMBUSTION CHAMBER CLAMP ASSEMBLY	Package D		3 TAB WELD REPAIR		1575	SR Technics Switzerland
139738	50K037; 51K209-01; 51K211-01		28	28	72-51-80	TURBINE NOZZLE - COMBUSTION CHAMBER CLAMP ASSEMBLY	Package E		4 WELD JOINT CRACK WELD REPAIR		1515	SR Technics Switzerland
139738	50K037; 51K209-01; 51K211	EASA;FAA;CAAC;ANAC	28	28	72-51-80	TURBINE NOZZLE - COMBUSTION CHAMBER CLAMP ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		500	SR Technics Switzerland
139738	50K037; 51K209-01; 51K211	EASA;FAA;CAAC;ANAC	28	28	72-51-80	TURBINE NOZZLE - COMBUSTION CHAMBER CLAMP ASSEMBLY	Package B		1 HARDFACE REPLACEMENT REPAIR		1105	SR Technics Switzerland
139738	50K037; 51K209-01; 51K211	EASA;FAA;CAAC;ANAC	28	28	72-51-80	TURBINE NOZZLE - COMBUSTION CHAMBER CLAMP ASSEMBLY	Package C		2 TAB BLEND REPAIR		575	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package H		35 REPLACE FRONT ANGLE GANG NUT ASSEMBLIES		610	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package I		36 REPLACE THE ANGLE GANG NUT ASSEMBLY NUT PLATES		610	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package K		41 REPLACE REAR ANGLE GANG NUT ASSEMBLIES		525	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package L		42 REPAIR DAMAGED FOIL ON THE FIRE ABLATIVE BLANKETS		2460	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package N		47 REPLACE FIRE SHIELD SEGMENT REPAIR		880	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package O		55 WELD DAMAGED SPLITTER FAIRING NUTPLATE BOLT OR RIVET HOLE REPAIR		1540	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package P		57 CUT SEAL REPAIR		645	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package Q		58 WELD DAMAGE ON THE VANES IN THE BLEED VALVE DUCT		1115	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package R		59 REPAIR HEAT SHIELD BLANKET		815	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package S		61 BLEND REPAIR SURFACE DAMAGE		715	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package SB00	PW4G-100-72-164	MODIFICATION OF INNER CASE		1875	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package SB01	PW4G-100-72-163	FIRE SHIELD AT FAN INNR EXIT CASE, INSPECTION	PROCEDURE A	1650	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package SB02	PW4G-100-72-163	FIRE SHIELD AT FAN INNR EXIT CASE, INSPECTION	PROCEDURE B	4615	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 51D629; 51D703; 51D705; 51D986; 52D321-001		34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package U		64 REPLACE HELICAL INSERTS		345	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		2585	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package AE		48 BENT SPLITTER FAIRING FLANGE REPAIR		1115	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package AJ		68 CASE WALL INNER DIAMETER BLEND REPAIR		630	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package AL		69 BLEND OR REAM REAR FLANGE BOLTHOLE		630	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package AM		70 BLEND OR REAM SPLITTER FAIRING FLANGE BOLTOLES		635	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package B		14 TOUCH UP ANODIZE		375	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package C		30 REPLACE THE FAN EXIT INNER CASE GUIDE VANE PIN RIVET AND COLLAR		1265	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package D		31 SCREEN REPLACEMENT		970	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package E		32 REPLACE RUBBER SEAL		1715	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package E		60 REPLACE RUBBER SEAL		1715	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package F		33 REPLACE LPC STATOR NUT PLATES		400	SR Technics Switzerland
139739	50D757; 51D627; 51D628; 5	EASA;FAA;CAAC;ANAC	34	35	72-33-04	FAN CASE - FAN EXIT INNER CASE ASSEMBLY - 100"	Package G		34 REPLACE LPC SPLITTER FAIRING NUT OPTION		375	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139740	52D315-001; 52D315-002; 52D315-01; 52D333-001; 52D333-002; 52D333-(		33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package SB00	PW4G-100-72-89	RUBSTRIP INSPECTION FOR WEAR AND WEAR INDICATOR HOLES		1070	SR Technics Switzerland
139740	52D315-001; 52D315-002; 52D315-01; 52D333-001; 52D333-002; 52D333-(		33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package SB01	000913-ED01	FAN EXIT GUIDE VANES-LEADING EDGE METAL SHIELD REPLACEMENT ED R.ESEE.000913-ED01		1095	SR Technics Switzerland
139740	52D315-001; 52D315-002; 52D315-01; 52D333-001; 52D333-002; 52D333-(		33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package T		19 BLEND SURFACE DAMAGE REPAIR		720	SR Technics Switzerland
139740	52D315-001; 52D315-002; 52D315-01; 52D333-001; 52D333-002; 52D333-(		33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package V		21 PLASMA SPRAY THE REAR SNAP DIAMETER		3035	SR Technics Switzerland
139740	52D315-001; 52D315-002; 52D315-01; 52D333-001; 52D333-002; 52D333-(		33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package X		23 ACOUSTIC LINER SURFACE DAMAGE BLEND REPAIR		1540	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		3675	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package AB		27 BLEND REPAIR		685	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package AC		28 RESTORE CORROSION PROTECTIVE COATING REPAIR		1030	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package AF		31 360 DEGREE EPOXY FILLER RUBSTRIP PANEL REPAIR		45035	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package AI		34 ICE LINER JOINT DISBOND REPAIR		1650	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package AL		37 KEVLAR BELT EPOXY FILLET SEAL ADHESIVE		1910	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package O		14 BONDED FAN CASE LINERS LOCAL REPAIRS		3260	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package P		15 REPAIR FOR WEAR AND HOLES IN RUBSTRIP AS DEEP AS THE KEVLAR REINFORCED LAYER		3435	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package Q		16 RUB STRIP AND SEPTUM REPAIR		3150	SR Technics Switzerland
139740	52D315-001; 52D315-002; 5	EASA;FAA;CAAC;ANAC	33	35	72-33-01	FAN CASE ASSEMBLY - 100"	Package R		17 AROMATIC POLYAMIDE FIBER FABRIC PROTECTIVE COATING REPAIR		1650	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AE		30 STRESS RELIEVE		680	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AG		32 REPLACE INNER LINER SEGMENTS		3140	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AL		37 BLEND REPAIR OF CHAFING		575	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AM		38 WELD REPAIR OF CHAFING OR CRACKS		945	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AN		39 NUT PLATE CLEARANCE HOLES AND RIVET HOLES WELD REPAIR		3045	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AN		39 TWO LUG NUT PLATE REPLACEMENT REPAIR		3045	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package C		2 HARDFACE SUPPORT MATING FACE REPAIR		1225	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package E		20 FRONT LINER HARDFACE REPAIR		1545	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package K		21 CRACK WELD REPAIR COMBUSTION CHAMBER ASSEMBLY REAR SUPPORT PLATE		3175	SR Technics Switzerland
139747	51K000; 51K100; 52K200		31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package Z		25 REPLACE INNER LINER SEGMENTS		4045	SR Technics Switzerland
139747	51K000; 51K100; 52K200	EASA;FAA;CAAC;ANAC	31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		1340	SR Technics Switzerland
139747	51K000; 51K100; 52K200	EASA;FAA;CAAC;ANAC	31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AB		27 SIZE THE FRONT LINER		2670	SR Technics Switzerland
139747	51K000; 51K100; 52K200	EASA;FAA;CAAC;ANAC	31	28	72-51-05	TURBINE NOZZLE - INNER COMBUSTION CHAMBER ASSEMBLY - 100"	Package AD		29 SIZE THE REAR SUPPORT		745	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package C		2 INSTALL NEW RUBBER SEAL		1865	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package C		2 REPLACE RUBBER SEAL		1865	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package D		3 REPLACE A RIVETED BEARING PAD AFTER INSTALLATION		2180	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package F		5 WELD THE CAM SLOTS		1540	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package G		6 INSTALL HELICAL TWINSERTS		580	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package G		6 REPLACE HELICAL INSERTS		580	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package I		8 INSTALL NEW INSULATION BLANKETS		735	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package I		8 REPLACE DAMAGED INSULATION BLANKETS		735	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package J		9 REPAIR DAMAGED INSULATION BLANKETS		640	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package K		10 REPLACE ANTIGALLANT COMPOUND REPAIR		560	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package L		11 BLEND REPAIR		735	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package M		12 CAM SLOT TAB OUTSIDE DIAMETER REPAIR		4390	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package N		13 REPLACE LINER REPAIR		1385	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package O		14 WELD A CRACKED OR OVERSIZED CAM SLOT LINER RIVET HOLE		2190	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package P		15 WELD AN OVERSIZED BEARING PAD RIVET HOLE		3060	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package Q		16 REPAIR DAMAGED FOIL ON THE FIRE ABLATIVE BLANKETS		1395	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package Q		17 REPAIR DAMAGED FOIL ON THE FIRE ABLATIVE BLANKETS		1395	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package SB00	PW4G-100-72-67	REPLACEMENT OF OR MODIFICATION OF THE BEARING PADS		3700	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53D539-01		29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package SB01	PW4G-100-72-112	SLOT LINER MODIFICATION		2955	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53	EASA;FAA;CAAC;ANAC	29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package A	CLN/ISNP	CLEANING AND INSPECTION		1455	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53	EASA;FAA;CAAC;ANAC	29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package AE		3 REPLACE A RIVETED BEARING PAD BEFORE INSTALLATION		1780	SR Technics Switzerland
139749	51D998-001; 53D062-01; 53	EASA;FAA;CAAC;ANAC	29	28	72-33-08	FAN CASE - BLEED VALVE DUCT ASSEMBLY - 100"	Package B		1 TOUCH UP ANODIZE		545	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AJ		35 RADIAL SHRINKAGE ON DOME SNAP DIAMETER REPAIR		1215	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AM		71 REAR SHELL STIFFENER WELD REPAIR		1420	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AN		73 REAR STIFFENER WELD REPAIR		1775	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package D		3 REPLACE THE HARDFACE ON THE SNAP DIAMETER REPAIR		890	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package E		36 REPLACE HARDFACE ON REAR STIFFENER REPAIR		760	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package F		5 BULKHEAD CRACK WELD REPAIR		4335	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package G		6 BULKHEAD CRACK PATCH REPAIR		6115	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package H		7 MOUNT LUG BUSHING REPLACEMENT		1200	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package O		39 REPLACE IGNITER GUIDE ASSEMBLY		1825	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package P		40 RESIZE REAR STIFFENER PLASMA REPAIR		760	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Q		38 REPLACE LINER SEGMENTS		7860	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB00	PW4G-100-72-74	MODIFICATION OF TO INCORPORATE A SPARK IGNITER GUIDE WITH ANTI-ROTATION FEATURE		695	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB01	PW4G-100-72-253	REPLACEMENT OF, WITH WASPALOY NUTS TO REDUCE NUT LIBERATION		5205	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package W		22 REPLACE BULKHEAD HARDFACE REPAIR		680	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package X		23 REPLACE ONE NOZZLE STATOR AND POSITIONING RINGS		2915	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Y		24 REPAIR FUEL NOZZLE GUIDE RIVET HOLE		3260	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200; 54J300; 54J300-001		37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package Z		25 WELD THE MOUNT LUGS		3415	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200	EASA;FAA;CAAC;ANAC	37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package A	CLN/INSP	CLEANING AND INSPECTION		3525	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200	EASA;FAA;CAAC;ANAC	37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AA		26 WELD REPAIR WEAR ON BULKHEAD FRONT FACE		3745	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200	EASA;FAA;CAAC;ANAC	37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AC		37 STRESS-RELIEF CYCLE FOR OUTER COMBUSTION CHAMBER ASSEMBLY		1850	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200	EASA;FAA;CAAC;ANAC	37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AG		41 PLASMA COAT BUILD-UP REPAIR		2060	SR Technics Switzerland
139750	52J200; 52J200-001; 54J200	EASA;FAA;CAAC;ANAC	37	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AI		64 COMBUSTION CHAMBER DOME DAMAGE WELD REPAIR		1475	SR Technics Switzerland
139751	56T081; 59T795		26	21	71-21-13	FWD ENGINE MOUNT - THRUST LINK BEAM ASSEMBLY - 100"	Package C		2 OVERSIZE BUSHING REPAIR		4175	SR Technics Switzerland
139751	56T081; 59T795	EASA;FAA;CAAC;ANAC	26	21	71-21-13	FWD ENGINE MOUNT - THRUST LINK BEAM ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		370	SR Technics Switzerland
139751	56T081; 59T795	EASA;FAA;CAAC;ANAC	26	21	71-21-13	FWD ENGINE MOUNT - THRUST LINK BEAM ASSEMBLY - 100"	Package B		1 BLEND THE SURFACE DAMAGE		400	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AM		115 REPLACE THE FAN EXIT CASE FRONT BRACKETS		1745	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package B		20 BLEND THE SURFACE DAMAGE		1395	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package C		33 WELD CRACKED STRUTS		8645	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package C		34 REPLACE A FAIRING WITH RIVETS ALL AROUND WITH A FAIRING WITHOUT INITIAL RIVET HOLES		8645	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package D		23 REPLACE FOURTH STATOR MOUNTING FLANGE HELICAL COIL INSERTS		1555	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package E		24 REPLACE HELICAL COIL INSERTS AT 2, 4, AND 8 O'CLOCK POSITIONS		1055	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package F		32 MACHINE THE FRONT MOUNT INNER SURFACES		430	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package G		31 CRACKS/DAMAGE WELD REPAIR		2855	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package I		43 WELD THE WEAR ON THE INLET GUIDE VANE MATING FACE		3950	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package J	SPM 70-43-00	REPLACE RIVETS ACC. SPM 70-43-00		515	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package J	SPM 70-48-00	REPLACE PROTECTIVE SHIELD ACC. SPM 70-48-00		515	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package K		44 BLEND SURFACE DAMAGE ON THE FAN EXIT CASE FLANGE ASSEMBLY		1455	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package N		54 REPAIR THE THREADED HOLES IN GROUND HANDLING PADS		1515	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package O		55 SEALANT REPAIR		4780	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package P		56 REPLACE E FLANGE SCREW THREAD INSERTS (HELICAL COIL)		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Q		57 REPLACE INNER FAN EXIT CASE MOUNTING FLANGE SCREW THREAD INSERTS (HELICAL COIL)		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package R		58 REPAIR THREADED BOSS HOLES OR REPLACE BOSS HOLE SCREW THREAD INSERTS		6910	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package S		59 REPLACE 2.5 BLEED VALVE DUCT FLANGE SCREW THREAD INSERTS		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB00	AD 2000-16-02	FWD ENGINE MOUNT - VISUAL INSPECTION		575	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB01	PW4G-100-72-017	REPLACEMENT WITH ASYMMETRIC VANE PATTERN		2955	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB02	PW4G-100-72-110	INSPECTION OF FRONT ENGINE MOUNT RECESS FIT AND MACHINING TO CORRECT IF REQUIRED		1270	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB04	PW4G-100-72-173	INSPECTION OF FAN EXIT CASE REAR, REAR BRACKET ASSEMBLY ATTACHMENT FOR LOOSE OR MISSING RIVETS		7005	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB05	PW4G-100-72-174	REPL. OF FAN EXIT CASE OUTSIDE DIA BRACKET ASSEM. WITH REDES. ATTACHMENT FOR IMPROVED DURABILITY		4920	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB06	PW4G-100-72-178	REPLACE THE INTERMEDIATE CASE, FECR FRONT, REAR AND MIDDLE E PART A		4840	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB06	PW4G-100-72-178	REPLACE THE INTERMEDIATE, FECR OD LINER SEGMENTS AND INSTAL PART B		4840	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB07	PW4G-100-72-204	FAIRINGS, ALUMINUM STRUT, COMPRESSOR INTERMEDIATE CASE ASSEMBLY - IMPROVED ATTACHMENT		2780	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package SB08	PW4G-100-72-196	INSPECTION OF STRUT FAIRINGS FOR MISSING OR LOOSE RIVETS		1110	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package T		60 REPLACE NO. 1 BEARING SUPPORT FLANGE SCREW THREAD INSERTS		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package U		61 REPLACE SCREW THREAD INSERTS AT STRUT LOCATION NO. 2 AND 3		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package V		62 REPLACE THE PROTECTIVE LAYER		2995	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package W		41 APPLY ANODIZE TOUCH-UP SOLUTION		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package W		63 APPLY ANODIZE TOUCH-UP SOLUTION		810	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package X		64 REPLACE STRUT SEALANT		2995	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Y		65 REPLACE THE TIMING PIN		1300	SR Technics Switzerland
139752	51D653-001; 51D653-003; 51D653-004; 51D653-01; 51D653-201; 52D348-(		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package Z		66 REPAIR THE SEALANT AROUND THE BAFFLES		980	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3000	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AA		112 REPLACE THE FAN EXIT CASE MID FLANGE BRACKETS		1660	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AA		67 BAFFLE REPLACEMENT REPAIR		1660	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AA		68 REPLACE THE FRONT FAN EXIT CASE BRACKET ASSEMBLIES		1660	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AA		70 REPLACE THE CENTER FAN EXIT CASE BRACKET ASSEMBLIES		1660	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AB		69 REPLACE THE BIFURCATION FAIRING TOP CENTER BRACKET ASSEMBLY		345	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AC		71 REPLACE THE REAR FAN EXIT CASE BRACKET ASSEMBLIES		645	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AD		73 REPLACE THE THRUST MOUNT BUSHINGS		3250	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AE		74 REPLACE NUT PLATES, INNER LINER SEGMENT CONNECTION		1555	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AF		75 REPLACE THE BIFURCATION FAIRING MOUNT BRACKETS		750	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AG		83 FAN EXIT CASE SURFACE DAMAGE BLEND REPAIR		645	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AH		90 COMPRESSOR INTERMEDIATE CASE FLANGE ASSEMBLY PROTECTION LAYER TOUCH UP REPAIR		1650	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AH		91 COMPRESSOR INTERMEDIATE CASE FLANGE ASSEMBLY NUT PLATE REPLACEMENT		1650	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AH		92 COMPRESSOR INTERMEDIATE CASE FLANGE ASSEMBLY ANTIGALLANT COMPOUND REPLACEMENT		1650	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AI		107 REPLACE HELICAL COIL INSERTS IN BOSSES WITH INSERTS		545	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AJ		116 REPLACE HELICAL COIL INSERTS		610	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AK		140 BLEND REPAIR BRG 2 ALIGNEMENT PIN HOLE		105	SR Technics Switzerland
139752	51D653-001; 51D653-003; 5 EASA;FAA;CAAC;ANAC		47	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package AL	SPM 70-11-00	ADD ENGINE SERIAL NUMBER ACC. SPM 70-11-00 GENERAL-01		185	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139755	50B322	EASA;FAA;CAAC;ANAC	23	28	72-31-04	LOW PRESSURE COMPRESSOR (LPC) - STAGE 2 LPC BLADE - 100"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
139756	50B323		27	28	72-31-05	LOW PRESSURE COMPRESSOR (LPC) - STAGE 3 LPC BLADE - 100"	Package SB00	EO 520295	INSPECT BLADE ROOT	ONLY AFTER EO-520294 ON BLADED DRUM	85	SR Technics Switzerland
139756	50B323	EASA;FAA;CAAC;ANAC	27	28	72-31-05	LOW PRESSURE COMPRESSOR (LPC) - STAGE 3 LPC BLADE - 100"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
139757	50B424	EASA;FAA;CAAC;ANAC	22	28	72-31-06	LOW PRESSURE COMPRESSOR (LPC) - STAGE 4 LPC BLADE - 100"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
139758	50B862		25	28	72-31-21	LOW PRESSURE COMPRESSOR (LPC) - INSERT - 100"	Package B	1	BLEND REPAIR		95	SR Technics Switzerland
139758	50B862		25	28	72-31-21	LOW PRESSURE COMPRESSOR (LPC) - INSERT - 100"	Package C	2	REPLACE SILICONE RUBBER SEAL		155	SR Technics Switzerland
139758	50B862	EASA;FAA;CAAC;ANAC	25	28	72-31-21	LOW PRESSURE COMPRESSOR (LPC) - INSERT - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		80	SR Technics Switzerland
139759	50B043; 50B880; 53B023	EASA;FAA;CAAC;ANAC	29	28	72-31-12	LOW PRESSURE COMPRESSOR (LPC) - (DRUM TO HUB) TIEROD	Package A	CLN/INSP	CLEANING AND INSPECTION		115	SR Technics Switzerland
139759	50B043; 50B880; 53B023	EASA;FAA;CAAC;ANAC	29	28	72-31-12	LOW PRESSURE COMPRESSOR (LPC) - (DRUM TO HUB) TIEROD	Package B	1	RESTORE ANTIGALLANT		105	SR Technics Switzerland
139759	50B043; 50B880; 53B023	EASA;FAA;CAAC;ANAC	29	28	72-31-12	LOW PRESSURE COMPRESSOR (LPC) - (DRUM TO HUB) TIEROD	Package B	2	RESTORE ANTIGALLANT		105	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package B	1	STRAIGHTEN KNIFE-EDGE SEAL		1440	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package C	2	BLEND REPAIR KNIFE EDGE SEAL		1070	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package D	3	SURFACE DAMAGE BLEND REPAIR		3015	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package E	4	BLEND REPAIR BALANCE FLANGE		1005	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package H	7	PLASMA SPRAY FRONT SNAP DIAMETER		5410	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package I	8	TIEROD HOLES REPAIR		3840	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package J	9	SHOTPEEN DRUM ROTOR DISK SLOTS		4285	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package L	11	BALANCE COUNTERWEIGHT REMOVAL AND INSTALLATION REPAIR		625	SR Technics Switzerland
139760	50B882-01		18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package SB00	72-EO-520295	LPC, 3RD STG BLADES: INSP. BLADE ROOT		375	SR Technics Switzerland
139760	50B882-01	EASA;FAA;CAAC;ANAC;CAA UK	18	28	72-31-08	LOW PRESSURE COMPRESSOR (LPC) - DRUM ROTOR DISK ASSEMBLY -	Package A	CLN/INSP	CLEANING AND INSPECTION		2350	SR Technics Switzerland
139761	50B936	EASA;FAA;CAAC;ANAC	25	28	72-31-03	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.6 LPC BLADE - 100"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC										
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package A	CLN/INSP	CLEANING AND INSPECTION		675	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package F	5	REPLACE RETAINING PIN(S)		1200	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package G	6	SMOOTH OUT DAMAGE TO THREADS		605	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package I	8	REPAIR THREADED HOLES - HELICAL COIL REPLACEMENT		865	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package K	10	CLINCH NUT REPLACEMENT		915	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package S	18	BLEND SURFACE DAMAGE		900	SR Technics Switzerland
139762	50J763-002; 50J764; 50J764	EASA;FAA;CAAC;ANAC	31	28	72-41-08	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (FRONT) SEAL RING HO	Package SB00	72-216526	INSPECTION OF NO. 3 BRG COMPRESSOR FRONT SUMP THIN WALL		680	SR Technics Switzerland
139764	50N322-01; 50N565-01	EASA;FAA;CAAC;ANAC	26	28	72-53-71	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 6 AIRSEALING	Package A	CLN/INSP	CLEANING AND INSPECTION		125	SR Technics Switzerland
139764	50N322-01; 50N565-01	EASA;FAA;CAAC;ANAC	26	28	72-53-71	LOW PRESSURE TURBINE (LPT) - TURBINE CASE (STAGE 6 AIRSEALING	Package B	1	DAMAGE AREA PATCH REPAIR		690	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package C	2	SURFACE DAMAGE BLEND REPAIR		1025	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package J	9	FRONT FLANGE FACE PLASMA SPRAY REPAIR		5540	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package K	10	FRONT DIAMETER PLASMA SPRAY		3510	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package M	12	REAR FLANGE FACE PLASMA SPRAY REPAIR		3950	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package N	13	REAR DIAMETER PLASMA SPRAY REPAIR		3405	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package P	15	SHOTPEEN REPAIR		690	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package R	17	KNIFE EDGE THICK COATING		3685	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package S	18	RESTORE KNIFE EDGE SEAL PLASMA COATING		5370	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package SB00	AD 2005-25-09	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	485	SR Technics Switzerland
139765	50N886; 51N706		29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package SB01	PW4G-100-72-252	LPT, INSPECT FOR AD AFFECTED T6D's	AD FAA 2015-21-04	545	SR Technics Switzerland
139765	50N886; 51N706	EASA;FAA;CAAC;ANAC	29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package B	1	KNIFE-EDGE SEALS BLEND REPAIR		590	SR Technics Switzerland
139765	50N886; 51N706	EASA;FAA;CAAC;ANAC;CAA UK	29	28	72-53-16	LOW PRESSURE TURBINE (LPT) - STAGE 6 LPT DISK ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		2300	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package B	1	REPLACE THE REAR FLANGE LOCATING PIN		1135	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package D	3	PLASMA SPRAY REPAIR FRONT FLANGE SNAP DIAMETER		2705	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package E	4	PLASMA SPRAY REPAIR REAR SNAP DIAMETER		2705	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package G	6	WELD REPAIR VANE ANTI-ROTATION SLOT		3915	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package H	7	PLASMA SPRAY REPAIR VANE REAR OD PLATFORM MATING SURFACE		2935	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package I	8	PLASMA SPRAY REPAIR THE VANE REAR PLATFORM MATING FACE		2935	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package J	9	SURFACE DAMAGE BLEND REPAIR		1020	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package J	10	ANTIROTATION SLOT FILLET RADII CRACK BLEND REPAIR		1020	SR Technics Switzerland
139778	51N249-01		32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package L	11	ANTIROTATION SLOT FILLET RADII CRACK WELD REPAIR		3720	SR Technics Switzerland
139778	51N249-01	EASA;FAA;CAAC;ANAC	32	28	72-53-67	LOW PRESSURE TURBINE (LPT) - STAGE 7 LPT CASE ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		535	SR Technics Switzerland
139780	51N418-01	EASA;FAA;CAAC;ANAC	4	28	72-53-70	PW4 STG 7 LPT (OUTER) AIRSEALING RING S	Package A	CLN/INSP	CLEANING & INSPECTION		120	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AC	39	MACHINE REPAIR VANE ANTI- ROTATION SLOTS TO REMOVE CRACKS (STAGE 3 AND STAGE 4)		6150	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AD	29	STAGE 3 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		6180	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AE	30	STAGE 4 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		6180	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AF	31	STAGE 5 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		6180	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AG	32	STAGE 6 VANE REAR SUPPORT LIP MATING SURFACE PLASMA COAT REPAIR		6180	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AH	33	STAGE 3 VANE HOOK INNER DIAMETER PLASMA COAT REPAIR		13380	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AK	36	PLASMA SPRAY REPAIR FRONT FLANGE FACE (WITHOUT BRACKET)		3190	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AL	75	CRACK BLEND REPAIR STG. 3-6		605	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AM	38	REAR FLANGE BRACKET REPLACEMENT REPAIR		485	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package B	1	REPLACE FRONT FLANGE LOCATING PIN		910	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package C	2	REPLACE REAR FLANGE LOCATING PIN		1175	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package F	5	SURFACE DAMAGE BLEND REPAIR		1800	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package G	6	STAGE 2 HPT SEAL MATING SURFACE PLASMA COAT REPAIR		3650	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package H	37	PLASMA SPRAY REPAIR REAR FLANGE FACE (WITH BRACKET)		3555	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package I	8	PLASMA SPRAY REPAIR FRONT FLANGE SNAP DIAMETER		3605	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package J	9	PLASMA SPRAY REPAIR REAR FLANGE SNAP DIAMETER		3345	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB03		SPECIAL INSTRUCTION (SI) NO. 224-F18 FPI ON LPT FRONT FLANGE		495	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB03	AD 2012-14-09	AD FAA-2012-14-09.00 / DIM. INSPECTION		495	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB03	PW4G-100-A72-26	ASB PW4G-100-A72-262 / DIMENSIONAL INSPECTION		495	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package SB05	AD 2021-05-16	REMOVE LPT 4TH STAGE AIR SEAL RING SEGMENT ASSEMBLYliesDIMENSIONAL INSPECTION		495	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package T	19	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 3)		5155	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package U	20	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 4)		4050	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package V	21	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 5)		4050	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package W	22	VANE REAR OUTER DIAMETER PLATFORM MATING SURFACE PLASMA COAT REPAIR (STAGE 6)		4050	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package X	44	REPAIR THE FORWARD INNER RAIL CRACKS BY STOP DRILLING		7605	SR Technics Switzerland
139782	51N348-01; 51N548-01		34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package Z	25	REPLACE LPT BORESCOPE BOSS		830	SR Technics Switzerland
139782	51N348-01; 51N548-01	EASA;FAA;CAAC;ANAC	34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package AA	26	REPLACE RIVETED- ON ANGLED BRACKET (POST SB PW4ENG 72-336)		630	SR Technics Switzerland
139782	51N348-01; 51N548-01	EASA;FAA;CAAC;ANAC;CAA UK	34	35	72-53-17	LOW PRESSURE TURBINE (LPT) - LOW PRESSURE TURBINE - REAR TUR	Package A	CLN/INSP	CLEANING AND INSPECTION		2500	SR Technics Switzerland
139784	52B313	EASA;FAA;CAAC;ANAC	28	28	72-31-02	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 LPC BLADE - 100"	Package E		WEIGH AND MATCH BLADES		70	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package J	9	INNER OR OUTER SIDE SEALANT OUTER SHROUD		8175	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package L	11	REPLACE DAMAGED VANE POTTING COMPOUND REPAIR		2510	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package M	12	BOLT HOLE FUSION WELD REPAIR		1575	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package N	13	RIVET HOLES WELD		6240	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package P	15	BENT FLANGE STRAIGHTENING		4525	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package R	17	INNER SHROUD REPLACEMENT REPAIR		4990	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package S	18	SILICONE RUBBER INNER AIRSEAL REPAIR		4015	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package SB00	PW4G-100-72-119	REPLACEMENT OR MODIFICATION OF LPC STATOR ASSY 1.6 - 3 STG 1.3 & 4.TH STG DUCT RUBBER		11325	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package SB01	PW4G-100-72-189	REPLACEMENT OR MODIFICATION TO INCORPORATE IMPROVED INNER SHROUD RUBSTRIPS		9435	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54B613-001; 54B613-01; 56B713-01		33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package T	9	VANE REPLACEMENT		3400	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54	EASA;FAA;CAAC;ANAC	33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package A	CLN/INSP	CLEANING AND INSPECTION		830	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54	EASA;FAA;CAAC;ANAC	33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package B	1	ANODIZE TOUCH-UP		865	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54	EASA;FAA;CAAC;ANAC	33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package C	2	BLEND REPAIR VANES AND OUTER SHROUD		1710	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54	EASA;FAA;CAAC;ANAC	33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package D	3	CRACK REPAIR LPC STAGE 1.3 COMPRESSOR STATOR ASSEMBLY INNER SHROUD		525	SR Technics Switzerland
139785	53B013-001; 53B013-01; 54	EASA;FAA;CAAC;ANAC	33	28	72-31-20	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1.3 COMPRESSOR STATC	Package F	5	SILICONE RUBBER OUTER AIRSEAL REPAIR		5585	SR Technics Switzerland
139786	53H257-01; 56H457; 56H75	EASA;FAA;CAAC;ANAC										
139786	53H257-01; 56H457; 56H75	EASA;FAA;CAAC;ANAC	6	28	72-35-65	PW4 (100") STG 7 HPC SHROUD SET	Package A	CLN/INSP	CLEANING AND INSPECTION		160	SR Technics Switzerland
139786	53H257-01; 56H457; 56H75	EASA;FAA;CAAC;ANAC	6	28	72-35-65	PW4 (100") STG 7 HPC SHROUD SET	Package SB00	PW4G-100-72-118	HPC BLADES/STATORS 6-9 STG - ZiOx BLADE		110	SR Technics Switzerland
139787	51H285; 51H385-001; 53H4	EASA;FAA;CAAC;ANAC										
139787	51H285; 51H385-001; 53H4	EASA;FAA;CAAC;ANAC	6	28	72-35-42	PW4000 STG. 5 HPC SHROUD SEGMENT ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		200	SR Technics Switzerland
139787	51H285; 51H385-001; 53H4	EASA;FAA;CAAC;ANAC	6	28	72-35-42	PW4000 STG. 5 HPC SHROUD SEGMENT ASSY	Package SB00	PW4ENG 72-650	HPC, INNER SHROUDS, TACK WELD OF PINS		110	SR Technics Switzerland
139815	50H940; 53H624-01; 54H92	EASA;FAA;CAAC;ANAC	25	28	72-35-99	HIGH PRESSURE COMPRESSOR (HPC) - MISCELLANEOUS PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		210	SR Technics Switzerland
139815	50H940; 53H624-01; 54H92	EASA;FAA;CAAC;ANAC	25	28	72-35-99	HIGH PRESSURE COMPRESSOR (HPC) - MISCELLANEOUS PARTS	Package B	1	REPLACE RUNNER ASSEMBLY	PW100INCH	360	SR Technics Switzerland
139815	50H940; 53H624-01; 54H92	EASA;FAA;CAAC;ANAC	25	28	72-35-99	HIGH PRESSURE COMPRESSOR (HPC) - MISCELLANEOUS PARTS	Package C	2	REPLACE PIN DETAIL	PW100INCH	340	SR Technics Switzerland
139815	50H940; 53H624-01; 54H92	EASA;FAA;CAAC;ANAC	25	28	72-35-99	HIGH PRESSURE COMPRESSOR (HPC) - MISCELLANEOUS PARTS	Package D	3	REPLACE RUNNER DETAIL	PW94INCH / PW100INCH	360	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AI	56	SURFACE DAMAGE BLEND REPAIR		1640	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AL	71	INSERT REPLACEMENT REPAIR		2280	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AM	54	INNER REAR FLANGE NUT PLATE AND GANG NUT CHANNEL REPLACEMENT REPAIR		1555	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AN	72	REAR SUPPORT REPLACEMENT REPAIR		2730	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package C	17	WELD REPAIR INNER FLANGE BOLT HOLE CRACKS		3510	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package D	22	REPLACE HELICAL COIL INSERTS		890	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package F	24	PLASMA SPRAY REP REAR FLANGE FACE		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package G	25	PLASMA SPRAY REP FRONT FLANGE FACE		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package H	26	PLASMA SPRAY REP REAR SNAP DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package I	27	PLASMA SPRAY REP FRONT "W" SEAL SHOULDER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package J	28	PLASMA SPRAY 9/10TH FRONT SUPPORT OUTER SNAP DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package K	29	PLASMA SPRAY 9/10TH FRONT SUPPORT INNER SNAP DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package L	30	PLASMA SPRAY REP OUTER FRONT SNAP DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package M	31	PLASMA SPRAY 9/10TH INTERMEDIATE SUPPORT OUTER SNAP DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package N	32	WELD REPAIR FLANGE H BOLT HOLE CRACKS		3510	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package O	33	WELD REPAIR FLANGE J BOLT HOLE CRACKS		3510	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package P	34	WELD REPAIR FLANGE K BOLT HOLE CRACKS		3510	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package Q	35	PLASMA SPRAY 9/10TH FRONT SUPPORT INNER DIAMETER		5395	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package R	36	HELICAL COIL INSERT REP OF .5625-18 THREADED BORESCOPE HOLE		995	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package S	37	PLASMA SPRAY REP REAR SNAP AXIAL SURFACE		5395	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package T		REMOVAL AND VISUALLY INSPECTION OF ALL BRACKETS		840	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package U	39	WALL BLEND REPAIR		695	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package V	41	REPLACE THE IDENTIFICATION BRACKET		2250	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package W	67	REAR CASE ASSEMBLY WELD REPAIR		3105	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203-01; 56H397-01		43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package Z	47	FRONT FLANGE FACE PLASMA COAT REPAIR		2915	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203	EASA;FAA;CAAC;ANAC	43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		2000	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203	EASA;FAA;CAAC;ANAC	43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AA	48	REAR SNAP DIAMETER PLASMA COAT REPAIR		4935	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203	EASA;FAA;CAAC;ANAC	43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AE	52	REAR W SEAL SHOULDER PLASMA COAT OR DUAL WIRE ELECTRIC ARC COAT REPAIR		5940	SR Technics Switzerland
139822	50S060-01; 50S061; 55H203	EASA;FAA;CAAC;ANAC;CAA UK	43	28	72-35-69	HIGH PRESSURE COMPRESSOR (HPC) - HPC OUTER REAR CASE ASSEM	Package AF	53	STAGE 9 W SEAL SHOULDER PLASMA COAT REPAIR		5615	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H818-01; 55H820-01; 56H075-01; 56H076-01		37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package SB00	PW4G-100-72-114	SYNCHRONIZING RING - MODIFICATION FOR IMPROVED ARM DURABI	Package B and C	1245	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H818-01; 55H820-01; 56H075-01; 56H076-01		37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package SB01	72-EO-520754	INSPECT THE UNISON RING PINS ON THE IGV STAGE FOR WEAR/LOSSENESS		675	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H818-01; 55H820-01; 56H075-01; 56H076-01		37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package SB02	PW4G-100-72-171	REPETITIVE INSPECTION FOR TACK WELD CRACKS AND WAER		675	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package A	CLN/INSP	CLEANING AND INSPECTION	PN54H779-01 54H794-01 FOR SHOP VISIT ON	415	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1355	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package C	2	REPLACE NUT PLATES		670	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2805	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		670	SR Technics Switzerland
139830	54H779-01; 54H794-01; 55H	EASA;FAA;CAAC;ANAC	37	28	72-35-51	HIGH PRESSURE COMPRESSOR (HPC) - INLET SYNCHRONIZING RING A	Package L	11	APPLY PWA 578 PAINT		1100	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package A	CLN/INSP	CLEANING AND INSPECTION	PN54H781-01 54H903-01 55H827-01 FOR SHC	420	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package B	1	REPLACE RING ASSEMBLY PIN AND LEVER ARM		1435	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package C	2	REPLACE NUT PLATES		815	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2935	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		385	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package L	11	APPLY PWA 578 PAINT		1170	SR Technics Switzerland
139834	54H781-01; 54H796-01; 54H	EASA;FAA;CAAC;ANAC	35	28	72-35-53	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 6 HPC SYNCHRONIZING	Package SB00	PW4G-100-72-114	SYNCHRONIZING RING - MODIFICATION FOR IMPROVED ARM DURABILITY		1290	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H087-01; 56H090-01		36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package H	7	BLEND RING SEGMENT SURFACE DAMAGE		370	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H087-01; 56H090-01		36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package L	11	APPLY PWA 578 PAINT		1115	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H087-01; 56H090-01		36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package SB00	PW4G-100-72-114	SYNCHRONIZING RING - MODIFICATION FOR IMPROVED ARM DURABILITY		1255	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H	EASA;FAA;CAAC;ANAC	36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package A	CLN/INSP	CLEANING AND INSPECTION	PN55H831-01 FOR SHOP VISIT ONLY	495	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H	EASA;FAA;CAAC;ANAC	36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package B	1	REPLACE RING ASSEMBLYPIN AND LEVER ARM		1310	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H	EASA;FAA;CAAC;ANAC	36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package C	2	REPLACE NUT PLATES		780	SR Technics Switzerland
139836	55H831-01; 55H833-01; 56H	EASA;FAA;CAAC;ANAC	36	28	72-35-54	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 7 HPC SYNCHRONIZING	Package F	5	WELD REPAIR OF VANE ARM PIN HOLES		2835	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package C	2	APPLY ANODIZE TOUCH-UP SOLUTION		140	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package D	3	PIN REPLACEMENT		155	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package E	4	FRONT OUTER MATING DIAMETER NICKEL PLATE REPAIR		1320	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package F	5	REAR OUTER MATING DIAMETER NICKEL PLATE REPAIR		1320	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package G	6	FRONT FACE NICKEL PLATE REPAIR		1385	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package H	7	REAR FACE NICKEL PLATE REPAIR-		1320	SR Technics Switzerland
139842	70R673		17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package I	8	INSERT REPLACEMENT REPAIR		140	SR Technics Switzerland
139842	70R673	EASA;FAA;CAAC;ANAC	17	28	72-61-50	MAIN GEARBOX - GEARBOX DRIVESHAFT HOUSING ASSEMBLY (REAR)	Package B	1	REPLACE HELICAL COIL INSERTS		165	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package B	1	REPLACE HELICAL COIL INSERTS		320	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package C	2	APPLY ANODIZE TOUCH-UP SOLUTION		315	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package D	3	NICKEL PLATE FRONT ID		1285	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package F	5	NICKEL PLATE TRANSFER TUBE HOLE ID		1865	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package G	6	NICKEL PLATE REAR FLANGE FACE		2045	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package H	7	BUSHING REPLACEMENT IN MOUNT CLEVISES		1560	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package I	8	NICKEL PLATE REAR ID		1145	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package J	9	NICKEL PLATE FRONT FLANGE FACE		2020	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package K	10	NICKEL PLATE ALTERNATOR PORT ID		2020	SR Technics Switzerland
139843	70R675		27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package L	11	NICKEL PLATE BUSHING HOLE		2645	SR Technics Switzerland
139843	70R675	EASA;FAA;CAAC;ANAC	27	28	72-61-52	MAIN GEARBOX - GEARBOX DRIVE SHAFT HOUSING ASSEMBLY (FRON	Package A	CLN/INSP	CLEANING AND INSPECTION		410	SR Technics Switzerland
139844	70R680		15	28	72-61-93	MAIN GEARBOX - GEARBOX SPUR GEAR	Package B	1	SILVER FLASH REPAIR		1450	SR Technics Switzerland
139844	70R680	EASA;FAA;CAAC;ANAC	15	28	72-61-93	MAIN GEARBOX - GEARBOX SPUR GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		390	SR Technics Switzerland
139845	70R792		25	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package C	2	ANODIZE TOUCH-UP		295	SR Technics Switzerland
139845	70R792		25	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package I	8	REPAIR THE REAR ID WITH A BUSHING		1335	SR Technics Switzerland
139845	70R792		25	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package J	9	REPLACE HELICAL COIL INSERTS		715	SR Technics Switzerland
139845	70R792		25	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package M	12	NICKEL PLATE THE OD		1490	SR Technics Switzerland
139845	70R792	EASA;FAA;CAAC;ANAC	25	28	72-61-42	MAIN GEARBOX - GEARBOX (SCAVENGE PUMP DRIVE) BEARING HOUS	Package B	1	REPLACE HELICAL COIL INSERTS		500	SR Technics Switzerland
139847	70R934; 70R935		10	28	72-61-44	PW4 GEARBOX (SCAVENGE PUMP DRIVE) SPUR	Package E	4	CHROMIUM PLATE BEARING SHOULDER		1185	SR Technics Switzerland
139847	70R934; 70R935	EASA;FAA;CAAC;ANAC	10	28	72-61-44	PW4 GEARBOX (SCAVENGE PUMP DRIVE) SPUR	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
139847	70R934; 70R935	EASA;FAA;CAAC;ANAC	10	28	72-61-44	PW4 GEARBOX (SCAVENGE PUMP DRIVE) SPUR	Package D	3	CHROMIUM PLATE BEARING JOURNAL		1185	SR Technics Switzerland
139853	55A221; 55A221-002; 57A721; 57A821		25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package SB00	PW4G-100-72-150	ULTRASONIC INSPECTION OF THE BLADE ROOT ATTACHMENT AREA FOR CRACKS		210	SR Technics Switzerland
139853	55A221; 55A221-002; 57A721; 57A821		25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package SB01	PW4G-100-72-175	MODIFICATION OF TO INCORPORATE A MORE DURABLE BLADE ROOT COATING		110	SR Technics Switzerland
139853	55A221; 55A221-002; 57A721; 57A821		25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package SB02	PW4G-100-72-101	REPL. OF OR MODIFICATION OF TO REDEFINE THE GROOVE IN PLATFORM UPPER SURFACE		110	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139853	55A221; 55A221-002; 57A7	EASA;FAA;CAAC;ANAC	25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	PN55A221-001 FOR SHOP VISIT ONLY	250	SR Technics Switzerland
139853	55A221; 55A221-002; 57A7	EASA;FAA;CAAC;ANAC	25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package C	10	MOMENT WEIGHT ADJUSTMENT		115	SR Technics Switzerland
139853	55A221; 55A221-002; 57A7	EASA;FAA;CAAC;ANAC	25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package C	INSP/CHK-05	MOMENT WEIGH BLADE ASSEMBLY		115	SR Technics Switzerland
139853	55A221; 55A221-002; 57A7	EASA;FAA;CAAC;ANAC	25	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE ASSEMBLY	Package SB00	PW4G-100-1-99	LUBRICATION OF THE 1ST STAGE LPC BLADE ASSEMBLY (FAN BLADE) ROOT		210	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1905	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package B	ASSEMBLY 16	HIGH SPEED GRINDING OF BLADE TIP		10445	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package B	PW4G-100-72-118	MODI. OR REPL. BLADES TO ZIRCONIUM OXIDE COATED TIPS AND SHI	COMPRESSOR ROTOR BLADE TIP GRINDING C	10445	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package B	PW4G-100-72-219	MODIFCATION OF TO INCORPORATE THE ADVANTAGE 70TM PERFORI	COMPRESSOR ROTOR BLADE TIP GRINDING C	10445	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package B	PW4G-100-72-220	CONVERSION OF PW4164 PW4168 OR PW4168A TO A PW4164-1D PW	COMPRESSOR ROTOR BLADE TIP GRINDING C	10445	SR Technics Switzerland
139855	100" REAR COMPR ROTOR ASSY		36	28	72-35-01	HIGH PRESSURE COMPRESSOR (HPC) - REAR COMPRESSOR ROTOR AS	Package C	1	BLEND INSTALLED HPC BLADES		3175	SR Technics Switzerland
139860	54T656-01; 59T792-01		27	21	71-21-15	FWD ENGINE MOUNT - MOUNT SET ASSY - 100"	Package C	2	MOUNT SET HALVES SURFACE DAMAGE BLEND REPAIR		595	SR Technics Switzerland
139860	54T656-01; 59T792-01		27	21	71-21-15	FWD ENGINE MOUNT - MOUNT SET ASSY - 100"	Package E	4	REPLACE THE ANTIGALLING COMPOUND REPAIR		610	SR Technics Switzerland
139860	54T656-01; 59T792-01		27	21	71-21-15	FWD ENGINE MOUNT - MOUNT SET ASSY - 100"	Package SB04	PW4G-100-71-26	APPLICATION OF ANTI-GALLANT COMPOUND TO THE MOUNT MAIN BEAM (SNOUT)		315	SR Technics Switzerland
139860	54T656-01; 59T792-01	EASA;FAA;CAAC;ANAC	27	21	71-21-15	FWD ENGINE MOUNT - MOUNT SET ASSY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
139860	54T656-01; 59T792-01	EASA;FAA;CAAC;ANAC	27	21	71-21-15	FWD ENGINE MOUNT - MOUNT SET ASSY - 100"	Package B	1	MOUNT SET SURFACE DAMAGE BLEND REPAIR		1545	SR Technics Switzerland
139862	52U420; 54T658; 54T659; 5	EASA;FAA;CAAC;ANAC										
139862	52U420; 54T658; 54T659; 5	EASA;FAA;CAAC;ANAC	26	21	71-21-12	FWD ENGINE MOUNT - BEARING RETAINER, BUSHING AND HOUSING	Package B	1	BEARING HOUSING BUSHING REPLACEMENT REPAIR		1495	SR Technics Switzerland
139862	52U420; 54T658; 54T659; 5	EASA;FAA;CAAC;ANAC	26	21	71-21-12	FWD ENGINE MOUNT - BEARING RETAINER, BUSHING AND HOUSING	Package C	2	SURFACE DAMAGE BLEND REPAIR		785	SR Technics Switzerland
139862	52U420; 54T658; 54T659; 5	EASA;FAA;CAAC;ANAC;CAA UK	26	21	71-21-12	FWD ENGINE MOUNT - BEARING RETAINER, BUSHING AND HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		380	SR Technics Switzerland
140113	51U670; 52U364; 55T497; 5	EASA;FAA;CAAC;ANAC										
140113	51U670; 52U364; 55T497; 5	EASA;FAA;CAAC;ANAC	25	21	71-22-10	AFT ENGINE MOUNT - BOLTS, NUTS, PINS, PLATES, SPACERS AND WA	Package A	CLN/INSP	CLEANING AND INSPECTION		170	SR Technics Switzerland
140113	51U670; 52U364; 55T497; 5	EASA;FAA;CAAC;ANAC	25	21	71-22-10	AFT ENGINE MOUNT - BOLTS, NUTS, PINS, PLATES, SPACERS AND WA	Package B	1	ANTIGALLANT REPLACEMENT REPAIR		110	SR Technics Switzerland
140113	51U670; 52U364; 55T497; 5	EASA;FAA;CAAC;ANAC	25	21	71-22-10	AFT ENGINE MOUNT - BOLTS, NUTS, PINS, PLATES, SPACERS AND WA	Package C	2	LOCK NUT THREADS SILVER PLATE REPAIR		255	SR Technics Switzerland
140266	51D742-01		26	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package B	89	BLEND COMPRESSOR INTERMEDIATE CASE FLANGE ASSEMBLY		950	SR Technics Switzerland
140266	51D742-01		26	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package C	90	PROTECTION LAYER TOUCH UP REPAIR		775	SR Technics Switzerland
140266	51D742-01		26	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package D	91	NUT PLATE REPLACEMENT		915	SR Technics Switzerland
140266	51D742-01		26	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package E	92	ANTIGALLANT COMPOUND REPLACEMENT		775	SR Technics Switzerland
140266	51D742-01	EASA;FAA;CAAC;ANAC	26	28	72-34-01	INTERMEDIATE CASE - COMPRESSOR INTERMEDIATE CASE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1020	SR Technics Switzerland
140742	51U691-01; 56T060; 59T793-01		21	21	71-22-15	AFT ENGINE MOUNT - MOUNT SET ASSY - 100"	Package D	3	OVERSIZE BUSHING REPAIR		3370	SR Technics Switzerland
140742	51U691-01; 56T060; 59T793	EASA;FAA;CAAC;ANAC	21	21	71-22-15	AFT ENGINE MOUNT - MOUNT SET ASSY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		1150	SR Technics Switzerland
140742	51U691-01; 56T060; 59T793	EASA;FAA;CAAC;ANAC	21	21	71-22-15	AFT ENGINE MOUNT - MOUNT SET ASSY - 100"	Package B	1	MOUNT BUSHINGS BLEND REPAIR		390	SR Technics Switzerland
140742	51U691-01; 56T060; 59T793	EASA;FAA;CAAC;ANAC	21	21	71-22-15	AFT ENGINE MOUNT - MOUNT SET ASSY - 100"	Package C	2	SURFACE DAMAGE BLEND REPAIR		390	SR Technics Switzerland
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;ANAC										
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 HOSE NON-METALIC HYDRAULIC	Package A		PRESSURE TEST		475	SR Technics Switzerland
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 HOSE NON-METALIC HYDRAULIC	Package A	CLN/INSP	CLEANING & INSPECTION		475	SR Technics Switzerland
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 HOSE NON-METALIC HYDRAULIC	Package N	13	MINOR GAUGE, TEAR OR CUT OF FLEXIBLE TUBE FIRE SLEEVE REPAIR		320	SR Technics Switzerland
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 HOSE NON-METALIC HYDRAULIC	Package W	22	REPAIR OUTER/INNER CONICAL SEAT	SPM 70-00-00	400	SR Technics Switzerland
140744	50U204; 51U178; 51U179; 5	EASA;FAA;CAAC;EASA/ANAC BRAZIL DUAL RELEASE										
144406	50T218; 52T926; 55T351-01		26	28	72-09-77	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING DUCT	Package D	3	TURBINE CASE COOLING DUCT BOTTOM SEGMENT REPAIR		2245	SR Technics Switzerland
144406	50T218; 52T926; 55T351-01	EASA;FAA;CAAC;ANAC	26	28	72-09-77	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		430	SR Technics Switzerland
144406	50T218; 52T926; 55T351-01	EASA;FAA;CAAC;ANAC	26	28	72-09-77	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING DUCT	Package B	1	REPLACE LOOSE OR MISSING RIVETS REPAIR - TCC DUCT ASSEMBLY		610	SR Technics Switzerland
144406	50T218; 52T926; 55T351-01	EASA;FAA;CAAC;ANAC	26	28	72-09-77	ENGINE GENERAL - COMMON PARTS - TURBINE CASE COOLING DUCT	Package C	2	WELD DAMAGED ON ELONGATED RIVET HOLES REPAIR - TCC DUCT ASSEMBLY		840	SR Technics Switzerland
144410	50J479; 50J781		7	28	72-41-11	PW4 (94") STATOR, FUEL NOZZLE	Package D	42	FUEL NOZZLE GUIDE FRONT LIP WELD REPAIR		555	SR Technics Switzerland
144410	50J479; 50J781	EASA;FAA;CAAC;ANAC	7	28	72-41-11	PW4 (94") STATOR, FUEL NOZZLE	Package B	1	REPLACE FUEL NOZZLE GUIDE HARDFACE		370	SR Technics Switzerland
144410	50J479; 50J781	EASA;FAA;CAAC;ANAC	7	28	72-41-11	PW4 (94") STATOR, FUEL NOZZLE	Package C	2	REPLACE FUEL NOZZLE GUIDE CERAMIC COAT		125	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC										
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package A	CLN/INSP	CLEANING AND INSPECTION		270	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package B	03.Jan	BEARING REPLACEMENT		645	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package C	03.Jan	BUSHING REPLACEMENT		1280	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package D	03.Feb	BUSHING HOLE REPAIR		2270	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package E	03.Feb	BEARING HOLE REPAIR		860	SR Technics Switzerland
144420	310T4023-1; 310T4023-2; 3	EASA;FAA;CAAC;ANAC	21	21	71-21-16	FWD ENGINE MOUNT - THRUST LINK ASSY - 94"	Package F	03.Feb	SCRATCH AND GOUGE REPAIR		590	SR Technics Switzerland
144422	7101-129-1250/750-8; 7101	EASA;FAA;ANAC										
144422	7101-129-1250/750-8; 7101	EASA;FAA;CAAC;ANAC										
144422	7101-129-1250/750-8; 7101	EASA;FAA;CAAC;ANAC	13	21	26.10.1965	FIRE/OVERHEAT DETECTOR MODEL 801RDS	Package B	TEST	TEST		1575	SR Technics Switzerland
144422	7101-129-1250/750-8; 7101	EASA;FAA;CAAC;ANAC	13	21	26.10.1965	FIRE/OVERHEAT DETECTOR MODEL 801RDS	Package C	TEST	PRE TEST	CLEANING AND VISUAL INSPECTION	410	SR Technics Switzerland
144727	56T082; 59T796		26	21	71-21-14	FWD ENGINE MOUNT - THRUST LINK ASSEMBLY - 100"	Package C	2	SURFACE DAMAGE BLEND REPAIR		395	SR Technics Switzerland
144727	56T082; 59T796	EASA;FAA;CAAC;ANAC	26	21	71-21-14	FWD ENGINE MOUNT - THRUST LINK ASSEMBLY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		380	SR Technics Switzerland
144727	56T082; 59T796	EASA;FAA;CAAC;ANAC	26	21	71-21-14	FWD ENGINE MOUNT - THRUST LINK ASSEMBLY - 100"	Package B	1	BEARING REPLACEMENT REPAIR		2495	SR Technics Switzerland
144729	50U455; 50U479; 51U690; 5	EASA;FAA;CAAC;ANAC										
144729	50U455; 50U479; 51U690; 5	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - PRIMARY - 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
144729	50U455; 50U479; 51U690; 5	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - PRIMARY - 100"	Package A	INSP/CHECK-06	INSPECTION POSTREQUISITES - APPLY PWA 474 ANTIGALLING		255	SR Technics Switzerland
144729	50U455; 50U479; 51U690; 5	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - PRIMARY - 100"	Package B	1	REAR MOUNT LINK AND LINK ASSEMBLY BEARING DISASSEMBLY, MARKING, REPLACEMENT AND ASSEMBLY		370	SR Technics Switzerland
144729	50U455; 50U479; 51U690; 5	EASA;FAA;CAAC;ANAC	24	21	71-22-11	AFT ENGINE MOUNT - LINK AND LINK ASSEMBLY - PRIMARY - 100"	Package E	4	PRIMARY AND SECONDARY LINK SURFACE DAMAGE BLEND REPAIR		505	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144808	50G199; 50G244; 51G282-0	EASA;FAA;CAAC;ANAC										
144808	50G199; 50G244; 51G282-0	EASA;FAA;CAAC;ANAC	17	28	72-33-91	FAN CASE - FAN EXIT FAIRING COVER PLATE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
144808	50G199; 50G244; 51G282-0	EASA;FAA;CAAC;ANAC	17	28	72-33-91	FAN CASE - FAN EXIT FAIRING COVER PLATE ASSEMBLIES	Package B	1	BLEND REPAIR COATED COVER PLATES		310	SR Technics Switzerland
144808	50G199; 50G244; 51G282-0	EASA;FAA;CAAC;ANAC	17	28	72-33-91	FAN CASE - FAN EXIT FAIRING COVER PLATE ASSEMBLIES	Package B	1	BLEND REPAIR NOT COATED COVER PLATES		310	SR Technics Switzerland
144808	50G199; 50G244; 51G282-0	EASA;FAA;CAAC;ANAC	17	28	72-33-91	FAN CASE - FAN EXIT FAIRING COVER PLATE ASSEMBLIES	Package C	2	REPLACE NUT PLATE REPAIR		200	SR Technics Switzerland
601742	70R114	EASA;FAA;CAAC;ANAC	6	28	72-61-62	PW4 PRESSURE (REGULATOR) RELEF VALVE	Package B	1	CHROMIUM PLATE PILOT DIAMETER	FOR SHOP VISITS ONLY	460	SR Technics Switzerland
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC										
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 EXTERNAL FLEXIBLE HOSES ONLY	Package A	CLN/INSP	CLEANING & INSPECTION		260	SR Technics Switzerland
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 EXTERNAL FLEXIBLE HOSES ONLY	Package A	INSP-CHECK-05	PRESSURE TEST		260	SR Technics Switzerland
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC	5	21	72-09-71	PW4 EXTERNAL FLEXIBLE HOSES ONLY	Package B		REPAIR INNER/OUTER CONICAL SEAT		275	SR Technics Switzerland
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC;CAA UK										
602323	51U718; 51U739; 51U740; 5	EASA;FAA;CAAC;ANAC;CAA UK	5	21	72-09-71	PW4 EXTERNAL FLEXIBLE HOSES ONLY	Package SB00	PW4G-100-29-7	INSPECTION AND REPLACEMENT OF SUSPECT HYDRAULIC PRESSURE HOSES		190	SR Technics Switzerland
603649	50N288		15	28	72-53-31	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER VANE) DUCT AS	Package B	1	DUCT CRACKS AND WORN AREAS WELD REPAIR		1985	SR Technics Switzerland
603649	50N288	EASA;FAA;CAAC;ANAC;CAA UK	15	28	72-53-31	LOW PRESSURE TURBINE (LPT) - STAGE 3 LPT (OUTER VANE) DUCT AS	Package A	CLN/INSP	CLEANING AND INSPECTION		850	SR Technics Switzerland
609966	51G530-01; 51G595; 52G194-01; 52G412-01		21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package E	4	SPLICE PLATE REPLACEMENT REPAIR		900	SR Technics Switzerland
609966	51G530-01; 51G595; 52G194-01; 52G412-01		21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package F	5	NUT PLATES REPLACEMENT REPAIR		645	SR Technics Switzerland
609966	51G530-01; 51G595; 52G194-01; 52G412-01		21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package G	6	MINOR SURFACE DAMAGE REPAIR		1020	SR Technics Switzerland
609966	51G530-01; 51G595; 52G194-01; 52G412-01		21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package I	8	SURFACE DAMAGE REPAIR (POLYURETHANE COATING)		995	SR Technics Switzerland
609966	51G530-01; 51G595; 52G19	EASA;CAAC;EASA/ANAC BRAZIL DUAL RELEAS	21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package C	2	PROTECTIVE (FLUOROELASTOMER) FINISH REPAIR		995	SR Technics Switzerland
609966	51G530-01; 51G595; 52G19	EASA;FAA;CAAC;ANAC	21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package A	CLN/INSP	CLEANING AND INSPECTION		670	SR Technics Switzerland
609966	51G530-01; 51G595; 52G19	EASA;FAA;CAAC;ANAC	21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package AN		MARKING OF PART IF P/N AND/OR S/N IS ILLEGIBLE	SPM TASK 70-11-00-800-001-001	165	SR Technics Switzerland
609966	51G530-01; 51G595; 52G19	EASA;FAA;CAAC;ANAC	21	28	72-33-85	FAN CASE - FAN EXIT LEADING EDGE	Package D	3	WASHERS REPLACEMENT REPAIR		860	SR Technics Switzerland
610164	70R104		23	28	72-61-15	MAIN GEARBOX - GEARBOX DEOILER IMPELLER ASSEMBLY	Package D	3	NICKEL PLATE THE PILOT DIAMETER		1115	SR Technics Switzerland
610164	70R104		23	28	72-61-15	MAIN GEARBOX - GEARBOX DEOILER IMPELLER ASSEMBLY	Package E	4	NICKEL PLATE THE OD SNAP DIAMETER		1200	SR Technics Switzerland
610164	70R104	EASA;FAA;CAAC;ANAC	23	28	72-61-15	MAIN GEARBOX - GEARBOX DEOILER IMPELLER ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		945	SR Technics Switzerland
610214	21W4068-509; 21W4068-51	EASA;FAA;CAAC;ANAC										
610214	21W4068-509; 21W4068-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - INLET COWL WIRE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	515	SR Technics Switzerland
610214	21W4068-509; 21W4068-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - INLET COWL WIRE HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3525	SR Technics Switzerland
610214	21W4068-509; 21W4068-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - INLET COWL WIRE HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4935	SR Technics Switzerland
610214	21W4068-509; 21W4068-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - INLET COWL WIRE HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	6340	SR Technics Switzerland
610412	221-4950-691; 221D4020-5(	EASA;FAA;CAAC;ANAC										
610412	221-4950-691; 221D4020-5(	EASA;FAA;CAAC;ANAC	5	21	71-00-15	PW4 DIVERSE HOSES (CMM 71-00-15)	Package A	CLN/INSP	CLEANING & INSPECTION		350	SR Technics Switzerland
610741	21W4150-505; 21W4150-507		22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4935	SR Technics Switzerland
610741	21W4150-505; 21W4150-507		22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5915	SR Technics Switzerland
610741	21W4150-505; 21W4150-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	500	SR Technics Switzerland
610741	21W4150-505; 21W4150-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3250	SR Technics Switzerland
610742	21W4140-503; 21W4140-50	EASA;FAA;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER PDU AND SLV-VALVE WIRE	Package SB00	PW4NAC 71-136	THRUST REVERSER COMMAND CIRCUIT REWIRE	IN CONJUNCTION WITH PACKAGE MEDIUM C	1210	SR Technics Switzerland
610742	21W4140-503; 21W4140-50	EASA;FAA;CAAC;ANAC										
610742	21W4140-503; 21W4140-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER PDU AND SLV-VALVE WIRE	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	595	SR Technics Switzerland
610742	21W4140-503; 21W4140-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER PDU AND SLV-VALVE WIRE	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2835	SR Technics Switzerland
610742	21W4140-503; 21W4140-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER PDU AND SLV-VALVE WIRE	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4935	SR Technics Switzerland
610742	21W4140-503; 21W4140-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER PDU AND SLV-VALVE WIRE	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	6065	SR Technics Switzerland
610743	21W4132-505; 21W4132-507		22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3525	SR Technics Switzerland
610743	21W4132-505; 21W4132-507		22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	4025	SR Technics Switzerland
610743	21W4132-505; 21W4132-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	505	SR Technics Switzerland
610743	21W4132-505; 21W4132-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - FIRE DETECTOR, ENGINE TO PYLON WIRE HAR	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3115	SR Technics Switzerland
610744	21W4120-507; 21W4120-511; 21W4120-515; 21W4120-521		22	21	71-51-01	EEC, A CHANNEL WIRE HARNESS	Package SB00	PW4NAC 71-155	REWORK OF EEC WIRE HARNESS (W1W2 AND SUPLEMENTAL CONTRO	IN CONJUNCTION WITH PACKAGE MEDIUM C	1110	SR Technics Switzerland
610744	21W4120-507; 21W4120-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	EEC, A CHANNEL WIRE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	575	SR Technics Switzerland
610744	21W4120-507; 21W4120-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	EEC, A CHANNEL WIRE HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3795	SR Technics Switzerland
610744	21W4120-507; 21W4120-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	EEC, A CHANNEL WIRE HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6355	SR Technics Switzerland
610744	21W4120-507; 21W4120-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	EEC, A CHANNEL WIRE HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	9075	SR Technics Switzerland
610745	21W4118-507; 21W4118-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - EEC, B CHANNEL WIRE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	465	SR Technics Switzerland
610745	21W4118-507; 21W4118-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - EEC, B CHANNEL WIRE HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3525	SR Technics Switzerland
610745	21W4118-507; 21W4118-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - EEC, B CHANNEL WIRE HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4515	SR Technics Switzerland
610745	21W4118-507; 21W4118-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - EEC, B CHANNEL WIRE HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5495	SR Technics Switzerland
610746	21W4116-503; 21W4116-505; 21W4116-507		22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER INLET ANTI-ICE WIRE HARN	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5640	SR Technics Switzerland
610746	21W4116-503; 21W4116-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER INLET ANTI-ICE WIRE HARN	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	605	SR Technics Switzerland
610746	21W4116-503; 21W4116-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER INLET ANTI-ICE WIRE HARN	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2410	SR Technics Switzerland
610746	21W4116-503; 21W4116-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - THRUST REVERSER INLET ANTI-ICE WIRE HARN	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4865	SR Technics Switzerland
610747	21W4114-507; 21W4114-509		22	21	71-51-01	ELECTRICAL HARNESS - IDG CONTROL WIRE HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6355	SR Technics Switzerland
610747	21W4114-507; 21W4114-509		22	21	71-51-01	ELECTRICAL HARNESS - IDG CONTROL WIRE HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	9075	SR Technics Switzerland
610747	21W4114-507; 21W4114-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - IDG CONTROL WIRE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610747	21W4114-507; 21W4114-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - IDG CONTROL WIRE HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3795	SR Technics Switzerland
610748	21W4083-501; 21W4083-503		22	21	71-51-01	ELECTRICAL HARNESS - BAROSWITCH HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2690	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610748	21W4083-501; 21W4083-503		22	21	71-51-01	ELECTRICAL HARNESS - BAROSWITCH HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	3525	SR Technics Switzerland
610748	21W4083-501; 21W4083-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - BAROSWITCH HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	465	SR Technics Switzerland
610748	21W4083-501; 21W4083-50	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - BAROSWITCH HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1915	SR Technics Switzerland
610749	21W4076-511		22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 5 CONNECTION	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2620	SR Technics Switzerland
610749	21W4076-511		22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 5 CONNECTION	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4650	SR Technics Switzerland
610749	21W4076-511		22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 5 CONNECTION	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5640	SR Technics Switzerland
610749	21W4076-511	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 5 CONNECTION	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610750	21W4076-509; 21W4076-515; 21W4076-519		22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 7 CONNECTION	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	6765	SR Technics Switzerland
610750	21W4076-509; 21W4076-515; 21W4076-519		22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 7 CONNECTION	Package SB00	PW4NAC 71-136	THRUST REVERSER COMMAND CIRCUIT REWIRE	IN CONJUNCTION WITH PACKAGE MEDIUM C	1100	SR Technics Switzerland
610750	21W4076-509; 21W4076-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 7 CONNECTION	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
610750	21W4076-509; 21W4076-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 7 CONNECTION	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2410	SR Technics Switzerland
610750	21W4076-509; 21W4076-51	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - TR CONTROL WIRE HARNESS - 7 CONNECTION	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5220	SR Technics Switzerland
610751	21W4072-531; 21W4072-535; 21W4072-537; 21W4072-539; 21W4072-541		22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB02	PW4NAC 71-89	WIRE HARNESS REWORK TO ACCOMMADATE NEW FUEL METERING U	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610751	21W4072-531; 21W4072-535; 21W4072-537; 21W4072-539; 21W4072-541		22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB03	PW4NAC 71-88	MODIFICATION OF WIRE HARNESS TO ADD JUMPER WIRE	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610751	21W4072-531; 21W4072-535; 21W4072-537; 21W4072-539; 21W4072-541		22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB04	PW4NAC 71-133	WIRE HARNESS CONNECTOR FOR THE FMU SOLENOID - REPLACEMEN	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610751	21W4072-531; 21W4072-535; 21W4072-537; 21W4072-539; 21W4072-541		22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB05	PW4NAC 71-147	HARNESS TO STARTER - MODIFICATION AND REROUTING	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	3390	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	6810	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	9515	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	13440	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB00	PW4NAC 71-70	REPLACEMENT OF HIGH STALE TEMPERATURE SENSOR CABLE	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610751	21W4072-531; 21W4072-53	EASA;FAA;CAAC;ANAC	22	21	71-51-01	ELECTRICAL HARNESS - CORE WIRE HARNESS	Package SB01	PW4NAC 71-73	ENGINE WIRE HARNESS CONNECTORS - MODIFICATION OF	IN CONJUNCTION WITH PACKAGE MEDIUM C	1105	SR Technics Switzerland
610765	21W4058-505; 21W4062-50	EASA;FAA;ANAC	12	21	71-51-01	PW4 AI DIVERS EBU WIRE HARNESSES	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	415	SR Technics Switzerland
610765	21W4058-505; 21W4062-50	EASA;FAA;CAAC;ANAC										
610765	21W4058-505; 21W4062-50	EASA;FAA;CAAC;ANAC	12	21	71-51-01	PW4 AI DIVERS EBU WIRE HARNESSES	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	5510	SR Technics Switzerland
610765	21W4058-505; 21W4062-50	EASA;FAA;CAAC;ANAC	12	21	71-51-01	PW4 AI DIVERS EBU WIRE HARNESSES	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	8645	SR Technics Switzerland
610765	21W4058-505; 21W4062-50	EASA;FAA;CAAC;ANAC	12	21	71-51-01	PW4 AI DIVERS EBU WIRE HARNESSES	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	11785	SR Technics Switzerland
610832	221W5068-503; 221W5068-505; 221W5068-507		21	21	71-51-02	ELECTRICAL HARNESS - FAN CATEGORY I/IV HARNESS ASSEMBLY - MC	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5470	SR Technics Switzerland
610832	221W5068-503; 221W5068-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - FAN CATEGORY I/IV HARNESS ASSEMBLY - MC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	720	SR Technics Switzerland
610832	221W5068-503; 221W5068-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - FAN CATEGORY I/IV HARNESS ASSEMBLY - MC	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1845	SR Technics Switzerland
610832	221W5068-503; 221W5068-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - FAN CATEGORY I/IV HARNESS ASSEMBLY - MC	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4425	SR Technics Switzerland
610845	221W5144-513		21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER RH LVDT HARNESS ASSEME	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1845	SR Technics Switzerland
610845	221W5144-513		21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER RH LVDT HARNESS ASSEME	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4410	SR Technics Switzerland
610845	221W5144-513		21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER RH LVDT HARNESS ASSEME	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5470	SR Technics Switzerland
610845	221W5144-513	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER RH LVDT HARNESS ASSEME	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	705	SR Technics Switzerland
610856	221W5198-503; 221W5198-	EASA;FAA;CAAC;ANAC										
610856	221W5198-503; 221W5198-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - BELLMOUTH CATEGORY II HARNESS ASSEMBL	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	525	SR Technics Switzerland
610856	221W5198-503; 221W5198-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - BELLMOUTH CATEGORY II HARNESS ASSEMBL	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1490	SR Technics Switzerland
610856	221W5198-503; 221W5198-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - BELLMOUTH CATEGORY II HARNESS ASSEMBL	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3250	SR Technics Switzerland
610856	221W5198-503; 221W5198-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - BELLMOUTH CATEGORY II HARNESS ASSEMBL	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	3960	SR Technics Switzerland
610866	221W5194-501; 221W5194-	EASA;FAA;CAAC;ANAC										
610866	221W5194-501; 221W5194-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER LH HARNESS ASSEMBLY - M	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610866	221W5194-501; 221W5194-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER LH HARNESS ASSEMBLY - M	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1545	SR Technics Switzerland
610866	221W5194-501; 221W5194-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER LH HARNESS ASSEMBLY - M	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3730	SR Technics Switzerland
610866	221W5194-501; 221W5194-	EASA;FAA;CAAC;ANAC	21	21	71-51-02	ELECTRICAL HARNESS - THRUST REVERSER LH HARNESS ASSEMBLY - M	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	4620	SR Technics Switzerland
610901	420684; 55T139		21	21	73-21-18	EEC WIRING HARNESS WF04 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5685	SR Technics Switzerland
610901	420684; 55T139		21	21	73-21-18	EEC WIRING HARNESS WF04 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7285	SR Technics Switzerland
610901	420684; 55T139	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF04 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	840	SR Technics Switzerland
610901	420684; 55T139	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF04 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2180	SR Technics Switzerland
610903	420012		21	21	73-21-18	EEC WIRING HARNESS WF05 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2180	SR Technics Switzerland
610903	420012		21	21	73-21-18	EEC WIRING HARNESS WF05 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5685	SR Technics Switzerland
610903	420012		21	21	73-21-18	EEC WIRING HARNESS WF05 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7285	SR Technics Switzerland
610903	420012	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF05 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	840	SR Technics Switzerland
610904	420686; 55T137		21	21	73-21-18	EEC WIRING HARNESS WF06 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5685	SR Technics Switzerland
610904	420686; 55T137		21	21	73-21-18	EEC WIRING HARNESS WF06 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7285	SR Technics Switzerland
610904	420686; 55T137	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF06 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	840	SR Technics Switzerland
610904	420686; 55T137	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF06 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2180	SR Technics Switzerland
610905	420687; 55T140		21	21	73-21-18	EEC WIRING HARNESS WF07 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	7300	SR Technics Switzerland
610905	420687; 55T140		21	21	73-21-18	EEC WIRING HARNESS WF07 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	9430	SR Technics Switzerland
610905	420687; 55T140	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF07 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1070	SR Technics Switzerland
610905	420687; 55T140	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF07 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2690	SR Technics Switzerland
610906	420015; 55T128		21	21	73-21-18	EEC WIRING HARNESS WF08 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3960	SR Technics Switzerland
610906	420015; 55T128		21	21	73-21-18	EEC WIRING HARNESS WF08 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	4935	SR Technics Switzerland
610906	420015; 55T128	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF08 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	525	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610906	420015; 55T128	EASA;FAA;CAAC;ANAC	21	21	73-21-18	EEC WIRING HARNESS WF08 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1925	SR Technics Switzerland
610907	420016; 421137; 55T129		22	21	73-21-18	EEC WIRING HARNESS WF09 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	2995	SR Technics Switzerland
610907	420016; 421137; 55T129		22	21	73-21-18	EEC WIRING HARNESS WF09 - 100"	Package SB00	73-39	REPLACEMENT OF ALUMEL AND CHROMEL CONTACTS	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610907	420016; 421137; 55T129	EASA;FAA;CAAC;ANAC	22	21	73-21-18	EEC WIRING HARNESS WF09 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
610907	420016; 421137; 55T129	EASA;FAA;CAAC;ANAC	22	21	73-21-18	EEC WIRING HARNESS WF09 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1260	SR Technics Switzerland
610907	420016; 421137; 55T129	EASA;FAA;CAAC;ANAC	22	21	73-21-18	EEC WIRING HARNESS WF09 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2505	SR Technics Switzerland
610914	420017; 55T130		21	21	73-21-18	WIRING HARNESS WF10 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2510	SR Technics Switzerland
610914	420017; 55T130		21	21	73-21-18	WIRING HARNESS WF10 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	3045	SR Technics Switzerland
610914	420017; 55T130	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF10 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	495	SR Technics Switzerland
610914	420017; 55T130	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF10 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140	SR Technics Switzerland
610915	420018; 55T131		21	21	73-21-18	WIRING HARNESS WF11 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2420	SR Technics Switzerland
610915	420018; 55T131		21	21	73-21-18	WIRING HARNESS WF11 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	2955	SR Technics Switzerland
610915	420018; 55T131	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF11 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	495	SR Technics Switzerland
610915	420018; 55T131	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF11 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140	SR Technics Switzerland
610916	420692; 421138; 55T138		22	21	73-21-18	WIRING HARNESS WF12 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5645	SR Technics Switzerland
610916	420692; 421138; 55T138		22	21	73-21-18	WIRING HARNESS WF12 - 100"	Package SB00	73-39	REPLACEMENT OF ALUMEL AND CHROMEL CONTACTS	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610916	420692; 421138; 55T138	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS WF12 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610916	420692; 421138; 55T138	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS WF12 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4585	SR Technics Switzerland
610916	420692; 421138; 55T138	EASA;FAA;CAAC;ANAC;CAA UK	22	21	73-21-18	WIRING HARNESS WF12 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2185	SR Technics Switzerland
610918	420020; 55T133		21	21	73-21-18	WIRING HARNESS WF13 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4585	SR Technics Switzerland
610918	420020; 55T133		21	21	73-21-18	WIRING HARNESS WF13 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5645	SR Technics Switzerland
610918	420020; 55T133	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF13 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610918	420020; 55T133	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF13 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2185	SR Technics Switzerland
610919	420021; 55T134		21	21	73-21-18	WIRING HARNESS WF14 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5420	SR Technics Switzerland
610919	420021; 55T134		21	21	73-21-18	WIRING HARNESS WF14 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	6755	SR Technics Switzerland
610919	420021; 55T134	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF14 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	840	SR Technics Switzerland
610919	420021; 55T134	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF14 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2185	SR Technics Switzerland
610920	420695; 55T141		21	21	73-21-18	WIRING HARNESS WF15 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4335	SR Technics Switzerland
610920	420695; 55T141		21	21	73-21-18	WIRING HARNESS WF15 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5210	SR Technics Switzerland
610920	420695; 55T141	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF15 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610920	420695; 55T141	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS WF15 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2140	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC										
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1400	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3200	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	9430	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	12350	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package SB00	73-59	VIBRATION WIRE CHAFING ELIMINATION	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package SB01	PW4G-100-73-28	INSPECTION HARNESS FOR WIRE CHAFE AND LOOSE HARNESS CLAMP	IN CONJUNCTION WITH PACKAGE LIGHT, MEI	320	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package SB02	73-39	REPLACEMENT OF ALUMEL AND CHROMEL CONTACTS	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610921	420651; 420651-1; 420651-;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 1 - 100"	Package SB03	PW4G-100-73-39	INSTALLATION OF SPIRAL WRAP	UNISON SB 73-73	320	SR Technics Switzerland
610922	420844; 421259; 59T783		21	21	73-21-18	WIRING HARNESS-ASSY WC 2 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	13890	SR Technics Switzerland
610922	420844; 421259; 59T783		21	21	73-21-18	WIRING HARNESS-ASSY WC 2 - 100"	Package SB00	72-39	REPLACEMENT OF ALUMELAND AND CHROMEL CONTACTS WITH STAI	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610922	420844; 421259; 59T783	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 2 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1635	SR Technics Switzerland
610922	420844; 421259; 59T783	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 2 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3635	SR Technics Switzerland
610922	420844; 421259; 59T783	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 2 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	10095	SR Technics Switzerland
610923	420653; 420653-2; 421260;	55T113	21	21	73-21-18	WIRING HARNESS-ASSY WC 3 - 100"	Package SB00	73-59	VIBRATION WIRE CHAFING ELIMINATION	IN CONJUNCTION WITH PACKAGE MEDIUM C	320	SR Technics Switzerland
610923	420653; 420653-2; 421260;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 3 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	955	SR Technics Switzerland
610923	420653; 420653-2; 421260;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 3 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2285	SR Technics Switzerland
610923	420653; 420653-2; 421260;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 3 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6025	SR Technics Switzerland
610923	420653; 420653-2; 421260;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 3 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7585	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC										
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package C	TEST	PRE TEST	PN52U879 FOR SHOP VISIT ONLY	1950	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	4175	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	12520	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	16060	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package SB00	73-66	FIELD REPLACEMENT OF FUEL FILTER DELTA P CONNECTOR	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610924	420654; 420814; 420814-1;	EASA;FAA;CAAC;ANAC;CAA UK	23	21	73-21-18	WIRING HARNESS-ASSY WC 4 - 100"	Package SB01	73-39	REPLACEMENT OF ALUMEL AND CHROMEL CONTACTS	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610925	420655; 420815; 420815-2;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 5 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	625	SR Technics Switzerland
610925	420655; 420815; 420815-2;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 5 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2105	SR Technics Switzerland
610925	420655; 420815; 420815-2;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 5 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4335	SR Technics Switzerland
610925	420655; 420815; 420815-2;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 5 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5210	SR Technics Switzerland
610925	420655; 420815; 420815-2;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 5 - 100"	Package SB00	73-59	VIBRATION WIRE CHAFING ELIMINATION	IN CONJUNCTION WITH PACKAGE MEDIUM C	320	SR Technics Switzerland
610926	420656; 420816; 420816-3;	421342; 55T148	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package SB01	73-39	REPLACEMENT OF ALUMEL AND CHROMEL CONTACTS	IN CONJUNCTION WITH PACKAGE HEAVY	320	SR Technics Switzerland
610926	420656; 420816; 420816-3;	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	955	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610926	420656; 420816; 420816-3;	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2285	SR Technics Switzerland
610926	420656; 420816; 420816-3;	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6025	SR Technics Switzerland
610926	420656; 420816; 420816-3;	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7585	SR Technics Switzerland
610926	420656; 420816; 420816-3;	EASA;FAA;CAAC;ANAC	22	21	73-21-18	WIRING HARNESS-ASSY WC 6 - 100"	Package SB00	73-59	VIBRATION WIRE CHAFING ELIMINATION	IN CONJUNCTION WITH PACKAGE MEDIUM C	320	SR Technics Switzerland
610927	420777; 420777-3; 421343; 55T144		21	21	73-21-18	WIRING HARNESS-ASSY WC 7 - 100"	Package SB00	73-59	VIBRATION WIRE CHAFING ELIMINATION	IN CONJUNCTION WITH PACKAGE MEDIUM C	320	SR Technics Switzerland
610927	420777; 420777-3; 421343;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 7 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	505	SR Technics Switzerland
610927	420777; 420777-3; 421343;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 7 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1670	SR Technics Switzerland
610927	420777; 420777-3; 421343;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 7 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3395	SR Technics Switzerland
610927	420777; 420777-3; 421343;	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 7 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	4050	SR Technics Switzerland
610928	420658; 55T117		21	21	73-21-18	WIRING HARNESS-ASSY WC 8 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6855	SR Technics Switzerland
610928	420658; 55T117		21	21	73-21-18	WIRING HARNESS-ASSY WC 8 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8615	SR Technics Switzerland
610928	420658; 55T117	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 8 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1070	SR Technics Switzerland
610928	420658; 55T117	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 8 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2585	SR Technics Switzerland
610929	420659; 55T118		21	21	73-21-18	WIRING HARNESS-ASSY WC 9 - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4335	SR Technics Switzerland
610929	420659; 55T118		21	21	73-21-18	WIRING HARNESS-ASSY WC 9 - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5195	SR Technics Switzerland
610929	420659; 55T118	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 9 - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	630	SR Technics Switzerland
610929	420659; 55T118	EASA;FAA;CAAC;ANAC	21	21	73-21-18	WIRING HARNESS-ASSY WC 9 - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2105	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;ANAC										
610968	420054; 420054-1; 420054-;	EASA;FAA;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	12870	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC										
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1400	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3200	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	9730	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB00	73-54	DEACTIVATION OF TRC AND TCA CIRCUITS (BOEING)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB00	73-61	DEACTIVATION OF TRC AND TCA CIRCUITS (AIRBUS)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB01	73-55	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB01	73-62	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB02	72-0755	RCC MODIFICATION (BOEING)	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610968	420054; 420054-1; 420054-;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W1 (11 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB02	72-0756	RCC MODIFICATION (AIRBUS)	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC										
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package C	TEST	PRE TEST	PN45508 FOR SHOP VISIT ONLY	1180	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3065	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	8430	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	10995	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package SB00	73-28	REMOVAL OF TRC/ BVCA SWITCH BRANCHES	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610974	420103; 420446; 420751; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W5 - AIRBUS	Package SB01	73-32	CHAFE PROTECTION IN THE FMU BACKSHELL	IN CONJUNCTION WITH PACKAGE HEAVY	575	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC										
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1180	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3065	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	8430	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	10995	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB00	73-31	REMOVAL OF TRC/TBVCA SWITCH BRANCHES (BOEING)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610978	420080; 420094; 420094-1;	EASA;FAA;CAAC;ANAC	22	21	73-21-60	EEC WIRE HARNESS W5 (10 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB01	73-32	CHAFE PROTECTION IN THE FMU BACKSHELL	IN CONJUNCTION WITH PACKAGE HEAVY	575	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC										
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1180	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3065	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	8430	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	11030	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package SB00	73-62	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	845	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package SB01	73-61	DEACTIVATION OF TRC AND TCA CIRCUITS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610979	45778; 45794; 45854; 4598	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W2 (9 CONNECTIONS) - AIRBUS	Package SB02	72-0756	RCC MODIFICATION (AIRBUS)	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610980	420084		6	21	73-21-XX	W12/PW4 94' (4 PLUG) EEC WIRE HARNESS	Package B	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2410	SR Technics Switzerland
610980	420084		6	21	73-21-XX	W12/PW4 94' (4 PLUG) EEC WIRE HARNESS	Package C	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6635	SR Technics Switzerland
610980	420084		6	21	73-21-XX	W12/PW4 94' (4 PLUG) EEC WIRE HARNESS	Package D	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8605	SR Technics Switzerland
610980	420084	EASA;FAA;CAAC;ANAC	6	21	73-21-XX	W12/PW4 94' (4 PLUG) EEC WIRE HARNESS	Package A	TEST	PRE TEST	TESTING AND FAULT ISOLATION	450	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC										
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1495	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3485	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	10570	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	14060	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package SB00	73-54	DEACTIVATION OF TRC AND TCA CIRCUITS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package SB01	73-55	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610981	420086; 420086-2; 420437;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W1 (12 CONNECTIONS) - BOEING	Package SB02	72-0755	RCC MODIFICATION	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC										
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package C	TEST	PRE TEST	PN46902 FOR SHOP VISIT ONLY	1070	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2745	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	7530	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	9850	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB00	73-54	DEACTIVATION OF TRC AND TCA CIRCUITS (BOEING)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB00	73-61	DEACTIVATION OF TRC AND TCA CIRCUITS (AIRBUS)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB01	73-55	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB01	73-62	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB02	72-0755	RCC MODIFICATION (BOEING)	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610982	420060; 420076; 420076-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (8 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB02	72-0756	RCC MODIFICATION (AIRBUS)	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610983	420087; 46228; 46462; 46462-5		21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package SB00	73-54	DEACTIVATION OF TRC AND TCA CIRCUITS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610983	420087; 46228; 46462; 46462-5		21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package SB01	73-55	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610983	420087; 46228; 46462; 46462-5		21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package SB02	72-0755	RCC MODIFICATION	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610983	420087; 46228; 46462; 464(	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	960	SR Technics Switzerland
610983	420087; 46228; 46462; 464(	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2585	SR Technics Switzerland
610983	420087; 46228; 46462; 464(	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6730	SR Technics Switzerland
610983	420087; 46228; 46462; 464(	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (7 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8615	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC										
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1400	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3200	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	9730	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	12895	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package SB00	40	DEACTIVATION OF TRC AND TCA CIRCUITS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package SB01	41	INSTALLATION OF JUMPER WIRES FOR ELECTRONIC ENGINE CONTROL	IN CONJUNCTION WITH PACKAGE MEDIUM C	840	SR Technics Switzerland
610984	420088; 420088-2; 420088-:	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (11 CONNECTIONS) - BOEING	Package SB02	42	RCC MODIFICATION	IN CONJUNCTION WITH PACKAGE HEAVY	840	SR Technics Switzerland
610985	420438; 420438-3; 421661; 57T797		21	21	73-21-60	EEC WIRE HARNESS W2 (12 CONNECTIONS) - BOEING	Package SB00	73-54	DEACTIVATION OF TRC AND TCA CIRCUITS	IN CONJUNCTION WITH PACKAGE MEDIUM C	1380	SR Technics Switzerland
610985	420438; 420438-3; 421661;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (12 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1280	SR Technics Switzerland
610985	420438; 420438-3; 421661;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (12 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3275	SR Technics Switzerland
610985	420438; 420438-3; 421661;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (12 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	10245	SR Technics Switzerland
610985	420438; 420438-3; 421661;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W2 (12 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	13980	SR Technics Switzerland
610986	420077; 46476; 53T877		21	21	73-21-60	EEC WIRE HARNESS W3 (8 CONNECTIONS) - MC DONNELL DOUGLAS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7715	SR Technics Switzerland
610986	420077; 46476; 53T877	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (8 CONNECTIONS) - MC DONNELL DOUGLAS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	840	SR Technics Switzerland
610986	420077; 46476; 53T877	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (8 CONNECTIONS) - MC DONNELL DOUGLAS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2290	SR Technics Switzerland
610986	420077; 46476; 53T877	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (8 CONNECTIONS) - MC DONNELL DOUGLAS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5900	SR Technics Switzerland
610987	420090; 420100; 420630; 45	EASA;FAA;CAAC;ANAC										
610987	420090; 420100; 420630; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (7 CONNECTIONS) - BOEING OR AIRBUS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	960	SR Technics Switzerland
610987	420090; 420100; 420630; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (7 CONNECTIONS) - BOEING OR AIRBUS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2585	SR Technics Switzerland
610987	420090; 420100; 420630; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (7 CONNECTIONS) - BOEING OR AIRBUS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6730	SR Technics Switzerland
610987	420090; 420100; 420630; 45	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (7 CONNECTIONS) - BOEING OR AIRBUS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8615	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC										
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package C	TEST	PRE TEST	PN420079 420442 FOR SHOP VISIT ONLY	840	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2290	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5900	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7715	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB00	73-28	REMOVAL OF TRC/BVCA SWITCH BRANCHES (MD11)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB00	73-31	REMOVAL OF TRC/BVCA SWITCH BRANCHES (BOEING)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610988	420079; 420091; 420442; 42	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (6 CONNECTIONS) - BOEING, AIRBUS OR MC	Package SB01	73-32	CHAFE PROTECTION IN THE FMU BACKSHELL	IN CONJUNCTION WITH PACKAGE HEAVY	575	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;ANAC										
610989	420078; 420092; 420092-1;	EASA;FAA;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6730	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB01	73-32	CHAFE PROTECTION IN THE FMU BACKSHELL	IN CONJUNCTION WITH PACKAGE HEAVY	575	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC										
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package C	TEST	PRE TEST	PN420441 FOR SHOP VISIT ONLY	960	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2585	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8615	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB00	73-28	REMOVAL OF TRC/BVCA SWITCH BRANCHES (MD11)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610989	420078; 420092; 420092-1;	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W4 (7 CONNECTIONS) - BOEING, AIRBUS OR MC [	Package SB00	73-31	REMOVAL OF TRC/BVCA SWITCH BRANCHES (BOEING)	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
610991	420095; 56T002		21	21	73-21-60	EEC WIRE HARNESS W8 - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2485	SR Technics Switzerland
610991	420095; 56T002		21	21	73-21-60	EEC WIRE HARNESS W8 - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	3060	SR Technics Switzerland
610991	420095; 56T002	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W8 - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1165	SR Technics Switzerland
610991	420095; 56T002	EASA;FAA;CAAC;ANAC;CAA UK	21	21	73-21-60	EEC WIRE HARNESS W8 - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	490	SR Technics Switzerland
610992	420081; 421101; 421273; 46	EASA;FAA;CAAC;ANAC										
610992	420081; 421101; 421273; 46	EASA;FAA;CAAC;ANAC	23	21	73-21-60	EEC WIRE HARNESS W6 - BOEING, AIRBUS OR MC DONNELL DOUGLAS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
610992	420081; 421101; 421273; 46	EASA;FAA;CAAC;ANAC	23	21	73-21-60	EEC WIRE HARNESS W6 - BOEING, AIRBUS OR MC DONNELL DOUGLAS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1665	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610992	420081; 421101; 421273; 4	EASA;FAA;CAAC;ANAC	23	21	73-21-60	EEC WIRE HARNESS W6 - BOEING, AIRBUS OR MC DONNELL DOUGLAS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	3455	SR Technics Switzerland
610992	420081; 421101; 421273; 4	EASA;FAA;CAAC;ANAC	23	21	73-21-60	EEC WIRE HARNESS W6 - BOEING, AIRBUS OR MC DONNELL DOUGLAS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	4235	SR Technics Switzerland
610992	420081; 421101; 421273; 4	EASA;FAA;CAAC;ANAC	23	21	73-21-60	EEC WIRE HARNESS W6 - BOEING, AIRBUS OR MC DONNELL DOUGLAS	Package SB00	73-15	W6 WIRING HARNESS REPLACEMENT		320	SR Technics Switzerland
611008	46094; 46152; 46231; 4638	EASA;FAA;CAAC;ANAC										
611008	46094; 46152; 46231; 4638	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (6 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
611008	46094; 46152; 46231; 4638	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (6 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2095	SR Technics Switzerland
611008	46094; 46152; 46231; 4638	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (6 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	5730	SR Technics Switzerland
611008	46094; 46152; 46231; 4638	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W3 (6 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	7435	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;ANAC										
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC										
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	1180	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	3065	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	8430	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	11030	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package SB00	73-31	REMOVAL OF TRC/BVCA SWITCH BRANCHES	IN CONJUNCTION WITH PACKAGE MEDIUM C	1910	SR Technics Switzerland
611009	420440; 420750; 45866; 461	EASA;FAA;CAAC;ANAC	21	21	73-21-60	EEC WIRE HARNESS W5 (9 CONNECTIONS) - BOEING	Package SB01	73-32	CHAFE PROTECTION IN THE FMU BACKSHELL	IN CONJUNCTION WITH PACKAGE HEAVY	575	SR Technics Switzerland
611010	420083; 420135; 420578; 4	EASA;FAA;CAAC;ANAC										
611010	420083; 420135; 420578; 4	EASA;FAA;CAAC;ANAC	21	21	73-21-61	EEC WIRE HARNESS W11 - MC DONNELL DOUGLAS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
611010	420083; 420135; 420578; 4	EASA;FAA;CAAC;ANAC	21	21	73-21-61	EEC WIRE HARNESS W11 - MC DONNELL DOUGLAS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2410	SR Technics Switzerland
611010	420083; 420135; 420578; 4	EASA;FAA;CAAC;ANAC	21	21	73-21-61	EEC WIRE HARNESS W11 - MC DONNELL DOUGLAS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6635	SR Technics Switzerland
611010	420083; 420135; 420578; 4	EASA;FAA;CAAC;ANAC	21	21	73-21-61	EEC WIRE HARNESS W11 - MC DONNELL DOUGLAS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8605	SR Technics Switzerland
611011	420104; 46963		21	21	73-21-53	EEC WIRE HARNESS W11 - AIRBUS	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	6635	SR Technics Switzerland
611011	420104; 46963		21	21	73-21-53	EEC WIRE HARNESS W11 - AIRBUS	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	8605	SR Technics Switzerland
611011	420104; 46963	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W11 - AIRBUS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
611011	420104; 46963	EASA;FAA;CAAC;ANAC	21	21	73-21-53	EEC WIRE HARNESS W11 - AIRBUS	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	2410	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC										
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1020	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	2290	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	3115	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package I		ASSEMBLY AND DISASSEMBLY		375	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package SB00	SB1-77-21-04	EGT HARNESS AND JUNCTION BOX - REPLACEMENT NUTS, RETAINING	IN CONJUNCTION WITH PACKAGE MEDIUM C	1140	SR Technics Switzerland
611190	26257-000; 50P090; 50P228	EASA;FAA;CAAC;ANAC;CAA UK	22	21	77-21-04	EGT (T4.95) THERMOCOUPLE BOX AND CABLE	Package C		PRE-TEST	TESTING AND FAULT ISOLATION	500	SR Technics Switzerland
611194	23830-000; HAD21988		21	21	77-21-06	EGT (T3)THERMOCOUPLE BOX AND CABLE - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	4565	SR Technics Switzerland
611194	23830-000; HAD21988		21	21	77-21-06	EGT (T3)THERMOCOUPLE BOX AND CABLE - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	5895	SR Technics Switzerland
611194	23830-000; HAD21988	EASA;FAA;CAAC;ANAC	21	21	77-21-06	EGT (T3)THERMOCOUPLE BOX AND CABLE - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1760	SR Technics Switzerland
611194	23830-000; HAD21988	EASA;FAA;CAAC;ANAC;CAA UK	21	21	77-21-06	EGT (T3)THERMOCOUPLE BOX AND CABLE - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485	SR Technics Switzerland
611204	922-224-000-031		21	21	77-32-14	VIBRO-METER ENGINE VIBRATION ACCELEROMETER HARNESS - 100"	Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	760	SR Technics Switzerland
611204	922-224-000-031		21	21	77-32-14	VIBRO-METER ENGINE VIBRATION ACCELEROMETER HARNESS - 100"	Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONNE	1660	SR Technics Switzerland
611204	922-224-000-031		21	21	77-32-14	VIBRO-METER ENGINE VIBRATION ACCELEROMETER HARNESS - 100"	Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AFFI	2070	SR Technics Switzerland
611204	922-224-000-031	EASA;FAA;CAAC;ANAC	21	21	77-32-14	VIBRO-METER ENGINE VIBRATION ACCELEROMETER HARNESS - 100"	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;ANAC										
612638	108280-171; 14527-503; 14	EASA;FAA;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package D		2 BALL MANDREL REPAIR OF SMOOTH DENTS		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC										
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package A	CLN/INSP	CLEANING AND INSPECTION		350	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package D		1 BLEND REPAIR		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package D		3 DOUBLER REPAIR AND SECTION REPLACEMENT		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package I		5 INSULATION BLANKET PATCH REPAIR		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package I		6 WELD REPAIR OF TURBINE CASE COOLING DUCT LUG		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package I		7 WELD REPAIR OF TURBINE CASE COOLING DUCT FLANGE		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package I		8 DUCT AND MANIFOLD ASSEMBLY SUPPORT BRACKET BUSHING REPAIR		1965	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB00	PW4NAC 71-131	REPLACEMENT OF WIRE HARNESS SUPPORT BRACKETS ON THE OIL TANK		645	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB01	PW4NAC 71-168	MODIFICATION OF THE PYLON DRAIN TUBE		915	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB02	PW4NAC 36-14	MODIFICATION OF THE TURBINE CASE COOLING DUCT		1440	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB03	PW4NAC 71-139	REPLACEMENT OF THE ENGINE CORE BRACKET AND DUCT ASSEMBLY		360	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB04	IA 80-069705	MD-11 MODIFICATION OF STARTER DUCT BRACKET		410	SR Technics Switzerland
612638	108280-171; 14527-503; 14	EASA;FAA;CAAC;ANAC	21	21	71-00-15	PNEUMATIC DUCTS, TUBES AND HOSES	Package SB05	PW4NAC 36-5	REPLACEMENT OF 8TH STAGE RIGHT HAND DUCT ELBOW		360	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01;	53T234-01; 54T418-01; 55T611-01; 57T397-0	8	21	72-09-71	PW4 TUBES EXTERNAL	Package SB00	PW4ENG 79-64	NO. 3 BRG TUBE (LP19) COUPLING NUT REPLACEMENT		260	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package A	CLN/INSP	CLEANING AND INSPECTION		260	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package A	INSP-05	PRESSURE TEST		260	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package B		1 ANTISIZE COMPOUND APPLICATION		175	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package C		2 THRUST WIRE INSTALLATION		310	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package D		4 BLEND REPAIR SURFACE DAMAGE		260	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package E		5 DENT REPAIR		1675	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package F		7 LINER,NUT,REDUCER,ELBOW,SLEEVE REPLACEMENT		915	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package G	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD		320	SR Technics Switzerland
614222	51T370; 51T461; 52T836-01	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES EXTERNAL	Package H	22	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00	210	SR Technics Switzerland
619760	51R122	EASA;FAA;CAAC;ANAC	5	21	XX-XX-XX	PW4 MISCELLANEOUS PARTS	Package B		INSERT REPLACEMENT ACCORDING SPM		230	SR Technics Switzerland
619764	50L923-01		16	28	72-52-16	HIGH PRESSURE TURBINE (HPT) - HPT FLANGE SPACER	Package B	1	LOOSE DAMAGED OR MISSING RIVETS REPLACEMENT REPAIR	PN 50L923-01 ONLY	390	SR Technics Switzerland
619764	50L923-01	EASA;FAA;CAAC;ANAC	16	28	72-52-16	HIGH PRESSURE TURBINE (HPT) - HPT FLANGE SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		185	SR Technics Switzerland
620009	50A234	EASA;FAA;CAAC;ANAC	24	21	72-54-12	TURBINE EXHAUST CASE - NO. 4 BEARING (PRESSURE AND SCAVENGE	Package A	CLN/INSP	CLEANING AND INSPECTION		330	SR Technics Switzerland
624103	730842B	EASA;FAA;CAAC;ANAC	4	21	24-19-03	PW4 (94") QUICK ATTACH-DETACH ADAPTER	Package A	CLN/INSP	CLEANING & INSPECTION		785	SR Technics Switzerland
624121	730464A; 749865; 753693	EASA;FAA;CAAC;ANAC										
624121	730464A; 749865; 753693	EASA;FAA;CAAC;ANAC	6	21	24-19-06	PW4 100" QUICK ATTACH-DETACH ADAPTER	Package A	CLN/INSP	CLEANING & INSPECTION		765	SR Technics Switzerland
624132	14611-14; S332N303-14	EASA;FAA;CAAC;ANAC										
624132	14611-14; S332N303-14	EASA;FAA;CAAC;ANAC	5	21	36-11-30	STARTER DUCT ASSEMBLY FOR BOEING	Package A	CLN/INSP	CLEANING & INSPECTION		545	SR Technics Switzerland
624175	332T4521-2; 332T4521-48; 3	EASA;FAA;CAAC;ANAC										
624175	332T4521-2; 332T4521-48; 3	EASA;FAA;CAAC;ANAC	5	21	71-04-28	HEAT SHIELD ASSEMBLY FOR BOEING	Package A	CLN/INSP	CLEANING & INSPECTION		120	SR Technics Switzerland
624175	332T4521-2; 332T4521-48; 3	EASA;FAA;CAAC;ANAC	5	21	71-04-28	HEAT SHIELD ASSEMBLY FOR BOEING	Package B	01.Jan	THERMAL SHIELD ASSEMBLY		1455	SR Technics Switzerland
626263	51U093; 59T303-01; 70R745	EASA;FAA;CAAC;ANAC										
626263	51U093; 59T303-01; 70R745	EASA;FAA;CAAC;ANAC	22	28	72-61-99	MAIN GEARBOX - MAIN GEARBOX MISCELLANEOUS PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1070	SR Technics Switzerland
626263	51U093; 59T303-01; 70R745	EASA;FAA;CAAC;ANAC	22	28	72-61-99	MAIN GEARBOX - MAIN GEARBOX MISCELLANEOUS PARTS	Package B	1	PROTECTIVE COAT REPLACEMENT REPAIR		2265	SR Technics Switzerland
629647	71A304-001; 76A013-1; 76A	EASA;FAA;CAAC;ANAC										
629647	71A304-001; 76A013-1; 76A	EASA;FAA;CAAC;ANAC	6	21	78-11-11	PW4 (100") SADDLE OF NOZZLE ASSY	Package B	R.ESEE.000899	CHANEL WEAR WELD REPAIR		3540	SR Technics Switzerland
630155	58H435-01		17	28	72-35-93	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 AIR SEAL SUPPORT SE	Package B	1	BOLT, RIVET AND BOLT RETAINER REPLACEMENT REPAIR		1080	SR Technics Switzerland
630155	58H435-01	EASA;FAA;CAAC;ANAC	17	28	72-35-93	HIGH PRESSURE COMPRESSOR (HPC) - STAGE 8 AIR SEAL SUPPORT SE	Package A	CLN/INSP	CLEANING AND INSPECTION		755	SR Technics Switzerland
631312	420504; 52U192; 58T213; 9	EASA;FAA;CAAC;ANAC	8	21	24-21-42	IDG POWER CABLES DICONNECT BLOCK	Package B		TEST		430	SR Technics Switzerland
631312	420504; 52U192; 58T213; 9	EASA;FAA;CAAC;ANAC	8	21	24-21-42	IDG POWER CABLES DICONNECT BLOCK	Package D		LIGHT REPAIR		590	SR Technics Switzerland
631312	420504; 52U192; 58T213; 9	EASA;FAA;CAAC;ANAC	8	21	24-21-42	IDG POWER CABLES DICONNECT BLOCK	Package E		MEDIUM REPAIR		860	SR Technics Switzerland
631312	420504; 52U192; 58T213; 9	EASA;FAA;CAAC;ANAC	8	21	24-21-42	IDG POWER CABLES DICONNECT BLOCK	Package F		HEAVY REPAIR		1280	SR Technics Switzerland
636094	50A220; 51G096; 51G176; 5	EASA;FAA;CAAC;ANAC										
636094	50A220; 51G096; 51G176; 5	EASA;FAA;CAAC;ANAC	22	28	72-34-36	INTERMEDIATE CASE - NO. 1.5 AND 2 BEARING SEAL SUPPORT ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		270	SR Technics Switzerland
636895	50P140-01; 50P141; 50P264	EASA;FAA;CAAC;ANAC										
636895	50P140-01; 50P141; 50P264	EASA;FAA;CAAC;ANAC	18	28	72-54-35	TURBINE EXHAUST CASE - NO. 4 BEARING SHIELD - HEATSHIELD (INSL	Package A	CLN/INSP	CLEANING AND INSPECTION		250	SR Technics Switzerland
636895	50P140-01; 50P141; 50P264	EASA;FAA;CAAC;ANAC	18	28	72-54-35	TURBINE EXHAUST CASE - NO. 4 BEARING SHIELD - HEATSHIELD (INSL	Package C	2	DAMAGED FOIL MATERIAL SPOT WELD REPAIR		600	SR Technics Switzerland
648903	332T4340-21; 332T4710-90;	EASA;FAA;ANAC										
648903	332T4340-21; 332T4710-90;	EASA;FAA;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package V	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	175	SR Technics Switzerland
648903	332T4340-21; 332T4710-90;	EASA;FAA;CAAC;ANAC										
648903	332T4340-21; 332T4710-90;	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		185	SR Technics Switzerland
648903	332T4340-21; 332T4710-90;	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	INSP-05	PRESSURE TEST		185	SR Technics Switzerland
648903	332T4340-21; 332T4710-90;	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package B	1	APPLY THE ANTIGALLING COMPOUND		85	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;ANAC										
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC										
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC										
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		240	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	INSP-05	PRESSURE TEST		240	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package B	1	APPLY THE ANTIGALLING COMPOUND		95	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		330	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package SB02	PW4ENG 72-773	HOSE CP11 AND CR13 HOSE AND TUBE ASSEMBLIES LP01 AND LP03	INSPECTION FOR DAMAGE	165	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package V	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	400	SR Technics Switzerland
648904	50T279; 50T429; 50T467; 51	EASA;FAA;CAAC;ANAC	17	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package X	SPM	RIVET REMOVAL PROCEDURE	SPM 70-43-00	330	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA										
648905	50T854; 50T860; 50T860-00	EASA;FAA;ANAC										
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC										
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC										
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	INSP-05	PRESSURE TEST		475	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package AN	48	OIL TUBE COATING REPAIR		775	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package B	1	APPLY THE ANTIGALLING COMPOUND		95	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package E	4	BLEND REPAIR OF SURFACE DAMAGE		145	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package F	5	DENT REPAIR		1915	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package L	11	BLEND REPAIR SURFACE DAMAGE TUBE CONNECTOR NUTS COUPLINGS AND FERRULE DETAILS		175	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package SB00	PW4ENG 79-87	REPLACEMENT OR MODIFICATION OF TO IMPROVE CLEARANCE		1245	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package SB01	PW4G-100-79-42	INSPECTION FOR SUSPECT ELBOWS		825	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package V	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	155	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package X	SPM	RIVET REMOVAL PROCEDURE	SPM 70-43-00	325	SR Technics Switzerland
648905	50T854; 50T860; 50T860-00	EASA;FAA;CAAC;ANAC	19	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package Y	EO 524706	BSI BRG 4 LUBRICATION AND SCAVANGE	SRT COMPANY EDITION	95	SR Technics Switzerland
648906	221-5097-501; 50U010-01; 5	EASA;FAA;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648906	221-5097-501; 50U010-01; !	EASA;FAA;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		590	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		330	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC										
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	INSP-05	PRESSURE TEST		590	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package B	1	APPLY THE ANTIGALLING COMPOUND		95	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package E	4	BLEND REPAIR OF SURFACE DAMAGE		165	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package F	5	DENT REPAIR		1225	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package H	7	REPLACE THE COUPLING FERRULE LINER NUT REDUCER ELBOW OR SLEEVE		1020	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package L	11	BLEND REPAIR SURFACE DAMAGE TUBE CONNECTOR NUTS COUPLINGS AND FERRULE DETAILS		320	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package N	13	MINOR GOUGE, TEAR, CUT OF FLEXIBLE TUBE FIRE SLEEVE REPAIR		320	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package S	18	FLANGE COAT REPLACEMENT		925	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package SB03	PW4ENG 73-205	OFF-WING INSPECTION OF FUEL PUMP INLET (FM11)		250	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package U	20	MAIN BEARING STRAINER ELEMENT HOUSING ASSEMBLY FLANGE COATING REPLACEMENT REPAIR		320	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package V	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	400	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package X	SPM	RIVET REMOVAL PROCEDURE	SPM 70-43-00	330	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package Y	EO 524706	BSI BRG 4 LUBRICATION AND SCAVANGE	SRT COMPANY EDITION	95	SR Technics Switzerland
648906	221-5097-501; 50U010-01; !	EASA;FAA;CAAC;ANAC	18	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package Z	SPM	INSERTS REMOVAL PROCEDURE		110	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;ANAC										
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC										
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		450	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package A	INSP-05	PRESSURE TEST		450	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package AN	48	OIL TUBE COATING REPAIR		775	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package B	1	APPLY THE ANTIGALLING COMPOUND		95	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package SB02	PW4ENG 72-773	HOSE CP11 AND CR13 HOSE AND TUBE ASSEMBLIES LP01 AND LP03 INSPECTION FOR DAMAGE		165	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package V	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	155	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package X	SPM	RIVET REMOVAL PROCEDURE	SPM 70-43-00	325	SR Technics Switzerland
648907	50U147-01; 50U201; 50U22	EASA;FAA;CAAC;ANAC	23	21	72-09-71	GENERAL PROCEDURES - HOSES AND TUBE ASSEMBLIES	Package Y	EO 524706	BSI BRG 4 LUBRICATION AND SCAVANGE	SRT COMPANY EDITION	95	SR Technics Switzerland
648908	51U148; 51U149; 51U150; 5	EASA;FAA;CAAC;ANAC										
648908	51U148; 51U149; 51U150; 5	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 HEAT SHIELD FOR TUBES AND DUCTS	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
648908	51U148; 51U149; 51U150; 5	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 HEAT SHIELD FOR TUBES AND DUCTS	Package B	10	HEAT SHIELD REPAIR		515	SR Technics Switzerland
648908	51U148; 51U149; 51U150; 5	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 HEAT SHIELD FOR TUBES AND DUCTS	Package C	12	HEAT SHIELD STRAP GUIDE REPAIR		310	SR Technics Switzerland
649902	51A042; 51A547	EASA;FAA;CAAC;ANAC										
649902	51A042; 51A547	EASA;FAA;CAAC;ANAC	16	28	72-32-81	LPC/LPT COUPLING - PLUG TURBINE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		370	SR Technics Switzerland
650120	55T439; 55T440; 58T383; 7	EASA;FAA;ANAC										
650120	55T439; 55T440; 58T383; 7	EASA;FAA;CAAC;ANAC										
650120	55T439; 55T440; 58T383; 7	EASA;FAA;CAAC;ANAC	17	21	75-26-13	NACELLE CORE COMPARTMENT COOLING SYSTEM - COOLING DUCT S	Package A	CLN/INSP	CLEANING AND INSPECTION		490	SR Technics Switzerland
650120	55T439; 55T440; 58T383; 7	EASA;FAA;CAAC;ANAC;CAA UK										
650957	51G253		15	28	72-34-16	HPC SHROUD 5. STG RETAINING RING	Package B	1	SHROUD RETAINING RING OUTER LUG FRONT FACE PLASMA COAT REPAIR		1640	SR Technics Switzerland
650957	51G253		15	28	72-34-16	HPC SHROUD 5. STG RETAINING RING	Package D	INSP/CHK-03	VISUAL INSPECTION		600	SR Technics Switzerland
650957	51G253	EASA;FAA;CAAC;ANAC	15	28	72-34-16	HPC SHROUD 5. STG RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		535	SR Technics Switzerland
651079	50A367-01	EASA;FAA;CAAC;ANAC	4	21	72-54-00	PW4 NO.4 BRG HEATSHIELD BEARING ASSY	Package A	CLN	CLEANING & INSPECTION		80	SR Technics Switzerland
651115	50P361-01; 50P366-01	EASA;FAA;CAAC;ANAC										
651115	50P361-01; 50P366-01	EASA;FAA;CAAC;ANAC	5	28	72-54-21	PW4 NOZZLE, NO.4 BRG FRONT ASSY OF MODULE 54	Package A	CLN/INSP	CLEANING & INSPECTION	BORESCOPE INSPECTION INCLUDED	450	SR Technics Switzerland
651409	771724	EASA;FAA;CAAC;ANAC	6	21	72-54-03	PW4 PIN, ENGINE SUPPORT BOSS	Package A	CLN/INSP	CLEANING & INSPECTION		310	SR Technics Switzerland
652052	50P359	EASA;FAA;CAAC;ANAC	5	21	72-54-19	PW4 TUBE, TRANSFER (DAMPER TUBE)	Package A	CLN/INSP	CLEANING & INSPECTION	BORESCOPE INSPECTION INCLUDED	135	SR Technics Switzerland
652054	50P022	EASA;FAA;CAAC;ANAC	4	28	72-54-16	NO.4 BEARING HOUSING SEAL RING	Package A	CLN/INSP	CLEANING & INSPECTION		220	SR Technics Switzerland
652057	50P023	EASA;FAA;CAAC;ANAC	5	28	72-54-13	PW4 PLATE, NO.4 BRG (OUTER RACE) RETAINING	Package A	CLN/INSP	CLEANING & INSPECTION		155	SR Technics Switzerland
652076	50G682	EASA;FAA;CAAC;ANAC	6	28	72-35-96	PW4 NUT LOCK, NO. 2 BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		365	SR Technics Switzerland
652104	50G039		7	28	72-34-53	PW4 DRIVESHAFT ASSEMBLY, GEARBOX	Package B	1	EXPANSION PLUG REPLACEMENT		145	SR Technics Switzerland
652104	50G039	EASA;FAA;CAAC;ANAC;CAA UK	7	28	72-34-53	PW4 DRIVESHAFT ASSEMBLY, GEARBOX	Package A	CLN/INSP	CLEANING AND INSPECTION		495	SR Technics Switzerland
652105	616464	EASA;FAA;CAAC;ANAC	6	28	72-34-24	PW4 COUPLING, GEARBOX DRIVESHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		330	SR Technics Switzerland
652109	50R044; 50R450	EASA;FAA;CAAC;ANAC										
652109	50R044; 50R450	EASA;FAA;CAAC;ANAC	4	18	72-61-80	PW4 DRIVESHAFT, GEARBOX	Package A	CLN/INSP	CLEANING & INSPECTION		1465	SR Technics Switzerland
652128	50L159; KT50L159	EASA;FAA;ANAC										
652128	50L159; KT50L159	EASA;FAA;CAAC;ANAC	9	28	72-52-13	PW4 STAGE 1 HPT BLADE (HUB RIM)	Package A	CLN/INSP	CLEANING & INSPECTION		60	SR Technics Switzerland
652129	50A130	EASA;FAA;CAAC;ANAC	6	28	72-52-81	PW4 LOCK, NO.3 BEARING NUT	Package A	CLN/INSP	CLEANING & INSPECTION		410	SR Technics Switzerland
652132	50L128; 50L654	EASA;FAA;CAAC;ANAC										
652132	50L128; 50L654	EASA;FAA;CAAC;ANAC	4	28	72-52-09	PW4 DAMPER, STAGE 1 HPT BLADE	Package A	CLN/INSP	CLEANING & INSPECTION		45	SR Technics Switzerland
652148	50L273	EASA;FAA;CAAC;ANAC	5	28	72-52-24	STAGE 2 HPT (BLADE RETAINING PLATE) KEY	Package A	CLN/INSP	CLEANING & INSPECTION		170	SR Technics Switzerland
652149	50L133CL1; 50L133CL2; 50L	EASA;CAAC										
652149	50L133CL1; 50L133CL2; 50L	EASA;FAA;CAAC;ANAC	8	21	72-52-14	PW4 COVER, STAGE 1 HPT BLADE (HUB RIM)	Package A	CLN/INSP	CLEANING & INSPECTION		55	SR Technics Switzerland
652150	50L016	EASA;FAA;CAAC;ANAC	5	28	72-52-25	PW4 LOCK, TURBINE HUB	Package A	CLN/INSP	CLEANING & INSPECTION		175	SR Technics Switzerland
652165	50N279	EASA;FAA;CAAC	6	28	72-53-37	PW4 STAGE 6 LPT (OUTER) AIRSEALING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		305	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
652173	50N297; 50N580	EASA;FAA;CAAC;ANAC										
652173	50N297; 50N580	EASA;FAA;CAAC;ANAC	4	28	72-53-XX	PW4 PLUG, INSTRUMENTATION (BORESCOPE) B	Package A	CLN/INSP	CLEANING & INSPECTION		55	SR Technics Switzerland
652178	5005438-01	EASA;FAA;CAAC;ANAC	4	28	72-53-XX	PW4 STOP, INSTRUMENTATION PLUG	Package A	CLN/INSP	CLEANING & INSPECTION		55	SR Technics Switzerland
652196	50A335; 50A728	EASA;FAA;CAAC;ANAC										
652196	50A335; 50A728	EASA;FAA;CAAC;ANAC	4	28	72-54-81	PW4 SEAL, NO.4 BEARING (CARBON)	Package A	CLN/INSP	CLEANING & INSPECTION		85	SR Technics Switzerland
652197	50P032; 50P358-01; 50P365	EASA;FAA;CAAC;ANAC										
652197	50P032; 50P358-01; 50P365	EASA;FAA;CAAC;ANAC	5	21	72-54-20	NO. 4 BEARING DAMPER SUPPLY TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		235	SR Technics Switzerland
652198	50A197; 50A710	EASA;FAA;CAAC;ANAC										
652198	50A197; 50A710	EASA;FAA;CAAC;ANAC	5	28	72-51-04	PW4 DEFLECTOR, HPT COOLING DUCT	Package A	CLN/INSP	CLEANING & INSPECTION		295	SR Technics Switzerland
652199	50K069; 50K258-01; 51K210	EASA;FAA;ANAC										
652199	50K069; 50K258-01; 51K210	EASA;FAA;CAAC;ANAC										
652199	50K069; 50K258-01; 51K210	EASA;FAA;CAAC;ANAC	6	28	72-51-10	COMBUSTION CHAMBER GUIDE PLATE	Package A	CLN/INSP	CLEANING & INSPECTION		45	SR Technics Switzerland
652204	70R124	EASA;FAA;CAAC;ANAC	4	21	72-61-36	PW4 GEARBOX SPACER, SLEEVE	Package A	CLN/INSP	CLEANING & INSPECTION		160	SR Technics Switzerland
652205	50K110	EASA;CAAC	6	28	72-51-07	PW4 STOP, STAGE 1 HPT DUCT	Package A	CLN/INSP	CLEANING & INSPECTION		55	SR Technics Switzerland
652406	50J647-01	EASA;FAA;CAAC;ANAC	5	28	72-41-99	PW4 COVER ASSY, BOSS	Package A	CLN/INSP	CLEANING &INSPECTION		210	SR Technics Switzerland
652512	50J329; 50J541; 50J588; 51J	EASA;FAA;CAAC;ANAC										
652512	50J329; 50J541; 50J588; 51J	EASA;FAA;CAAC;ANAC	13	28	72-41-35	DIFFUSER AND COMBUSTOR - NO. 3 BEARING (OIL) NOZZLE ASSEMBL	Package A	CLN/INSP	CLEANING AND INSPECTION		395	SR Technics Switzerland
652515	50J855-01	EASA;FAA;CAAC;ANAC	4	21	72-41-99	PW4 IGNITER, BOSS	Package A	CLN/INSP	CLEANING & INSPECTION		300	SR Technics Switzerland
654914	70T332	EASA;FAA;CAAC;ANAC	5	28	72-61-90	GEARBOX UPPER SUPPORT LINK PIN SPACER	Package A	CLN/INS	CLEANING & INSPECTION		135	SR Technics Switzerland
654928	1A7891; 50H602; 54H933	EASA;FAA;CAAC;ANAC										
654928	1A7891; 50H602; 54H933	EASA;FAA;CAAC;ANAC	6	28	72-35-76	PW4 HPC CLEVISES	Package A	CLN/INSP	CLEANING AND INSPECTION		185	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AC		28 FLANGE SNAP DIAMETER PLASMA SPRAY REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AF		31 INNER DIAMETER SPACER BORE PLASMA SPRAY REPAIR		3770	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AI		34 PLASME COATE 6TH STAGE LPT AIRSEAL FRONT SNAP MATING DIAMETER		2690	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AL		41 MARK HIGHPOINT AXIAL RUNOUT		670	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AM		40 PROTECTIVE COAT REMOVAL AND COAT REPAIR		4400	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AN		39 COAT TOUCH-UP BY PWA 36252		2480	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package E		4 REPAIR NO. 4 BEARING RETAINING PLATE HOLES		1515	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package R		17 SHAFT BALANCE (BY WAX APPLICATION) REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package S		18 SURFACE DAMAGE BLEND REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package S		32 SHOTPEEN AFTER BLEND REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package SB01	PW4G-100-72-263	REPLACEMENT COATING		4055	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package U		20 REAR COUPLING PILOT DIAMETER PLASMA SPRAY REPAIR		4475	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package V		21 FRONT COUPLING PILOT DIAMETER PLA		990	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package W		22 NICKEL PLATE REPAIR NO. 4 BEARING RETAINING PLATE MATING DIAMETER		3010	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package X		23 MACHINE REPAIR FRONT SPACER SURFACE		4475	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52A577-01		22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package Z		25 TIEBOLD HOLES BUSHING REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52	EASA;FAA;CAAC;ANAC	22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AA		26 NICKEL PLATE REPAIR FOR 7TH STAGE LPT AIRSEAL SHOULDER		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52	EASA;FAA;CAAC;ANAC	22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package AB		27 FLANGE FACE PLASMA SPRAY REPAIR		4730	SR Technics Switzerland
655052	52A402-01; 52A402-101; 52	EASA;FAA;CAAC;ANAC;CAA UK	22	35	72-53-80	LOW PRESSURE TURBINE (LPT) - FRONT COMPRESSOR DRIVE TURBINI	Package A	CLN/INSP	CLEANING AND INSPECTION		2820	SR Technics Switzerland
655302	50D118	EASA;FAA;CAAC;ANAC	7	28	72-33-11	SHOULDER BOLT OF BLEED VALVE ACTUATUATOR CLEVIS	Package A	CLN/INSP	CLEANING AND INSPECTION		325	SR Technics Switzerland
655303	50A688; 51G971	EASA;FAA;CAAC;ANAC										
655303	50A688; 51G971	EASA;FAA;CAAC;ANAC	7	28	72-34-38	PW4 CONNECTOR TO MAIN BEARING	Package A	CLN/INSP	CLEANING & INSPECTION		1140	SR Technics Switzerland
655313	50G873	EASA;FAA;CAAC;ANAC	12	28	72-34-10	PW4 RING, NO 2 BRG HOUSING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		800	SR Technics Switzerland
655315	50A028; 50A028CL1; 50A02	EASA;FAA;CAAC;ANAC										
655315	50A028; 50A028CL1; 50A02	EASA;FAA;CAAC;ANAC	6	28	72-34-13	PW4 RING, SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		310	SR Technics Switzerland
655315	50A028; 50A028CL1; 50A02	EASA;FAA;CAAC;ANAC	6	28	72-34-13	PW4 RING, SPACER	Package B	SPM	BLEND NICKS AND SCRATCHES ACC. SPM		165	SR Technics Switzerland
655319	50A290; 51A363-01	EASA;FAA;CAAC;ANAC										
655319	50A290; 51A363-01	EASA;FAA;CAAC;ANAC	8	21	72-34-43	SCAVENGE TUBE ASSY OF MAIN BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1310	SR Technics Switzerland
655320	51G085; 51G449	EASA;FAA;CAAC;ANAC										
655320	51G085; 51G449	EASA;FAA;CAAC;ANAC	11	21	72-34-31	OIL PRESSURE TUBE OF GEARBOX	Package A	CLN/INSP	CLEANING AND INSPECTION		670	SR Technics Switzerland
655333	50S025-01; 50S026-01; 58H	EASA;FAA;CAAC;ANAC										
655333	50S025-01; 50S026-01; 58H	EASA;FAA;CAAC;ANAC	6	28	72-35-81	PW4 RETAINER AND COVER, HEAT SHIELD HPC	Package A	CLN/INSP	CLEANING AND INSPECTION		405	SR Technics Switzerland
655333	50S025-01; 50S026-01; 58H	EASA;FAA;CAAC;ANAC;CAA UK										
655336	58H438-01	EASA;FAA;CAAC;ANAC	5	28	72-35-82	PW4 SPACER SET, HPC	Package A	CLN/INSP	CLEANING &INSPECTION		240	SR Technics Switzerland
655630	50D320; 51D805; 52D344; 5	EASA;FAA;CAAC;ANAC										
655630	50D320; 51D805; 52D344; 5	EASA;FAA;CAAC;ANAC	8	28	72-33-14	PW4 STG 2.5 VLV CAM FOLLOWER	Package A	CLN/INSP	CLEANING AND INSPECTION		150	SR Technics Switzerland
656280	70T328	EASA;FAA;CAAC;ANAC;CAA UK	5	28	72-61-84	PW4 LINK GEARBOX SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		280	SR Technics Switzerland
656432	50B046	EASA;FAA;CAAC;ANAC	10	28	72-31-17	PIN NO. 1 BRG SEAL ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		90	SR Technics Switzerland
656433	50B048	EASA;FAA;CAAC;ANAC	4	28	72-31-17	SPACER NO.1 BRG SEAL ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		155	SR Technics Switzerland
656434	50A037	EASA;FAA;CAAC;ANAC	6	21	72-31-17	COLLAR NO.1 BRG SEAL ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		55	SR Technics Switzerland
656574	50S059; 50S753		6	28	72-35-XX	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB01	PW4G-100-72-269	REPLACE THE HPC 5TH STAGE BLADES WITH NEW BLADES	PART 000	570	SR Technics Switzerland
656574	50S059; 50S753	EASA;FAA;CAAC;ANAC	6	28	72-35-XX	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package B		MACHINE STAGE 5 - 15 OUTER AIR SEAL SET		13475	SR Technics Switzerland
656574	50S059; 50S753	EASA;FAA;CAAC;ANAC	6	28	72-35-XX	PW4 (100") 5TH - 15TH STAGE HPC SEAL SET	Package SB00	PW4G-100-72-260	INTRODUCTION OF A NEW HPC DRUM ROTOR DISK	PART 000	570	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657988	50U394-01		6	21	72-54-41	PW4 #4 BRG OIL SCAVANGE TUBE	Package B		22 CONICAL SEAT REPAIR	SPM/SOP	485	SR Technics Switzerland
657988	50U394-01		6	21	72-54-41	PW4 #4 BRG OIL SCAVANGE TUBE	Package SB00	72-EO-524706	BSI BRG. #4 LUBRICATION & SCAVENGE TUBES	BORESCOPE INSPECTION	125	SR Technics Switzerland
657988	50U394-01	EASA;FAA;CAAC;ANAC	6	21	72-54-41	PW4 #4 BRG OIL SCAVANGE TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		405	SR Technics Switzerland
661210	PW4000 MOD-41/2		6	28	72-41-XX	PW4 OUTER COMBUSTION CASE (PARTS) 100" - MOD-41/2	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	1165	SR Technics Switzerland
661211	PW4000 MOD-51/1		5	21	72-51-XX	PW4 INNER COMBUSTION CASE (PARTS) 94"	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	1150	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AG		77 OUTER LINER (SHELL) SLOT WEAR WELD REPAIR		2250	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AH		55 WEAR ON BULKHEAD FRONT FACE WELD REPAIR		1815	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AI		64 COMBUSTION CHAMBER DOME DAMAGE WELD REPAIR		1625	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AJ		80 INNER WALL CHAFING WELD REPAIR		2700	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AK		50 DOME SNAP DIAMETER RADIAL SHRINKAGE REPAIR		2250	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AL		52 REPLACE BULKHEAD HARDFACE REPAIR		1375	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AM		56 LINER SEGMENT REPLACEMENT REPAIR		3275	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AN		56 FUEL NOZZLE GUIDE SWIRLER AND HEAT SHIELD REPLACEMENT REPAIR		2940	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package E		36 REPLACE HARDFACE ON REAR STIFFENER REPAIR		845	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package H		7 MOUNT LUG BUSHING REPLACEMENT		1320	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package N		73 REAR STIFFENER WELD REPAIR		2145	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package O		39 REPLACE IGNITER GUIDE ASSEMBLY		2005	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package P		40 RESIZE REAR STIFFENER PLASMA REPAIR		845	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package R		75 BULKHEAD FUEL NOZZLE PORTS CRACK WELD REPAIR		3745	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package S		76 LINER COOLING HOLE AXIAL CRACK WELD REPAIR		3385	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB00	PW4G100-72-253	REPLACEMENT OF WITH WASPALOY NUTS TO REDUCE NUT LIBERATION		4475	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB01	FAA-2020-25-09	REPLACEMENT OF 3RD STAGE LPT OTD		600	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J497; 51J500		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package SB02	PW4G-100-72-265	OUTER CC MODIFICATION TO INCREASE DURABILITY		1275	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J EASA;FAA;CAAC		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AE		49 DOME DIAMETER HARDFACE REPLACEMENT REPAIR		1815	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J EASA;FAA;CAAC;ANAC		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package A	CLN/INSP	CLEANING AND INSPECTION		3945	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J EASA;FAA;CAAC;ANAC		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AD		48 WELD THE MOUNT LUGS		2400	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J EASA;FAA;CAAC;ANAC		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AF		51 PLASMA COAT BUILD-UP REPAIR		1615	SR Technics Switzerland
662554	51J100; 51J381; 51J382; 51J EASA;FAA;CAAC;ANAC;CAA UK		19	28	72-41-11	DIFFUSER AND COMBUSTOR - OUTER COMBUSTION CHAMBER ASSEN	Package AC		37 STRESS-RELIEF CYCLE FOR OUTER COMBUSTION CHAMBER ASSEMBLY		2040	SR Technics Switzerland
663222	55A221-003; 55A221-004; 5 EASA;FAA;CAAC;ANAC											
663222	55A221-003; 55A221-004; 5 EASA;FAA;CAAC;ANAC		13	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE SINGLE	Package A	CLN/INSP	CLEANING AND INSPECTION	PN57A721-001 FOR SHOP VISIT ONLY	185	SR Technics Switzerland
663222	55A221-003; 55A221-004; 5 EASA;FAA;CAAC;ANAC		13	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE SINGLE	Package B	INSP/CHECK-05	MOMENT WEIGH BLADE ASSEMBLY		130	SR Technics Switzerland
663222	55A221-003; 55A221-004; 5 EASA;FAA;CAAC;ANAC		13	28	72-31-82	LOW PRESSURE COMPRESSOR (LPC) - STAGE 1 LPC BLADE SINGLE	Package SB00	PW4G-100-1-99	LUBRICATION OF THE 1ST STAGE LPC BLADE ASSEMBLY (FAN BLADE) ROOT		130	SR Technics Switzerland
663441	30377-300; 30377-500; 303 EASA;FAA;ANAC											
663441	30377-300; 30377-500; 303 EASA;FAA;ANAC		15	28	72-00-00	ENGINE GENERAL - COMMON PARTS - MISCELLANEOUS CLAMPS GEN	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
663441	30377-300; 30377-500; 303 EASA;FAA;ANAC		15	28	72-00-00	ENGINE GENERAL - COMMON PARTS - MISCELLANEOUS CLAMPS GEN	Package B		REPLACE DEFECT INSERTS		175	SR Technics Switzerland
663441	30377-300; 30377-500; 303 EASA;FAA;ANAC		15	28	72-00-00	ENGINE GENERAL - COMMON PARTS - MISCELLANEOUS CLAMPS GEN	Package C		REPLACE DEFECT NUTPLATES		175	SR Technics Switzerland
663441	30377-300; 30377-500; 303 EASA;FAA;CAAC;ANAC											
663961	50H236; 50J284; 50U654; 5 EASA;FAA;ANAC											
663961	50H236; 50J284; 50U654; 5 EASA;FAA;CAAC;ANAC											
663961	50H236; 50J284; 50U654; 5 EASA;FAA;CAAC;ANAC		6	28	7X-XX-XX	PW4000 INSPECTION OF VARIOUS PARTS ACC.	Package A	CLN/INSP	CLEANING & INSPECTION		135	SR Technics Switzerland
663961	50H236; 50J284; 50U654; 5 EASA;FAA;CAAC;ANAC		6	28	7X-XX-XX	PW4000 INSPECTION OF VARIOUS PARTS ACC.	Package B		REPLACE DEFECTIVE RIVETS / PARTS		65	SR Technics Switzerland
664060	50R175; 50R176; 70R116; 7(EASA;FAA;CAAC;ANAC											
664060	50R175; 50R176; 70R116; 7(EASA;FAA;CAAC;ANAC		5	28	72-61-66	PW4 PACKING TRANSFER TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		235	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package F		5 FRONT INNER FLANGE MATING DIAMETER PLASMA COAT REPAIR		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package G		6 PLASMA SPRAY FRONT FLANGE OUTER SNAP DIAMETER		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package H		7 REAR OUTER MATING DIAMETER PLASMA COAT/DUAL WIRE ELECTRIC ARC COAT REPAIR		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package I		8 PLASMA SPRAY STAGE 1 TURBINE VANE SUPPORT SNAP DIAMETER		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package J		9 PLASMA SPRAY NO. 3 BEARING MOUNTING FLANGE SNAP DIAMETER		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package K		10 PLASMA SPRAY FRONT OUTER FLANGE FACE		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package L		11 PLASMA SPRAY FRONT INNER FLANGE FACE		2460	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package M		12 PLASMA SPRAY REAR OUTER FLANGE FACE		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package N		13 PLASMA SPRAY REAR INNER FLANGE FACE		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package O		14 BLEND SURFACE DAMAGE		920	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package P		15 REPLACE GANG NUT CHANNEL ASSEMBLIES		880	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package Q		16 REPLACE FUEL NOZZLE PAD INSERT		1340	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package R		26 BUSHING REPAIR INTERNAL TUBE BOSS ID (TACK WELD METHOD)		7045	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package S		27 BUSHING REPAIR NO. 3 BEARING (OIL) PRESSURE TUBE BOSS ID (TACK WELD METHOD)		1960	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB00	PW4ENG A72-753	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	735	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB01	PW4ENG A72-681	RE-IDENTIFICATION AND INSPECTION OF AREA BETWEEN THE TT3 (OVAL) BOSS AND THE BRACKET (ROUND) BOSS		715	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB01	PW4G100 A72-123	RE-IDENTIFICATION AND INSPECTIUN-OF AREA BETWEEN THE TT3 (OVAL) BOSS AND THE BRACKET (ROUND) BOSS		715	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB02	PW4ENG 72-699	MODIFICATION OF TO REDUCE STRESS IN THE TT3 BOSS AREA		160	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB03	PW4ENG 72-710	MODIFICATION OF TO REMOVE CRACKS AND POROSITY IN THE BRACKET BOSS AREAS		160	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package SB03	PW4G-100-72-157	MODIFICATION OF TO REMOVE CRACKS AND POROSITY IN THE BRACKET BOSS AREAS		160	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package T		28 BUSHING REPAIR INTERNAL TUBE BOSS ID (TACK WELD METHOD)		2910	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package U	30	WELD REPAIR CRACKS (VENDOR APPLICATION)		12110	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package V	31	STRUT SURFACE CRACK REPAIR (VENDOR APPLICATION)		12110	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package W	32	HELICAL COIL INSERT REPAIR EEC BURNER PRESSURE BOSS AND PS3 MUSCLE AIR BOSS		835	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package X	33	HELICAL COIL INSERT REPAIR SERVICE BOSS THREADS		1125	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package Y	34	HELICAL COIL INSERT REPAIR BRACKET MOUNTING (DOGBONE) BOSSES		835	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package Z	40	OVERSIZE THREADED INSERT REPAIR FOR FUEL NOZZLE PAD		2745	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713-002; 50J713-003; 50J713-01; 50J779-001; 50J7		18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package Z	42	OVERSIZE THREADED INSERT REPAIR FOR BRACKET MOUNTING BOSSES		2745	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package A	CLN/INSP	CLEANING AND INSPECTION		3200	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AA	45	REPAIR THE REAR FACE OF THE REAR INNER HOOK		5070	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AB	46	BUSHING REMOVAL REPAIR, TUBE BOSS INSIDE DIAMETER		865	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AC	51	STRUT EXTENDED CRACK MACHINE REPAIR		2195	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AD	53	REAR INNER HOOK, NOZZLE SEATING SURFACE PLASMA COAT REPAIR		5070	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AE	52	EXIT STATOR SNAP DIAMETER PLASMA COAT REPAIR		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AF	55	IGNITER BOSS THREAD SLEEVE REPAIR		2880	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AG	59	PLASMA SPRAY EXIT STATOR SNAP DIAMETER		5055	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package AH	60	DIFFUSER CASE ASSEMBLY		3200	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package B	1	EXIT STATOR SNAP DIAMETER PLASMA COAT REPAIR		4680	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package C	2	REPLACE DIFFUSER CASE ASSEMBLY REAR FLANGE LOCATING PIN		1365	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package D	3	REPAIR DIFFUSER CASE ASSEMBLY BORESCOPE BOSS THREADS USING HELICAL COIL INSERT		1755	SR Technics Switzerland
664199	50J036; 50J713-001; 50J713	EASA;FAA;CAAC;ANAC	18	45	72-41-01	PW4 CASE ASSY OF DIFFUSER	Package E	4	PLASMA SPRAY AIRSEAL MOUNTING FLANGE SNAP DIAMETER		4730	SR Technics Switzerland
664337	50A294; 50A314; 50A737; 5	EASA;FAA;ANAC										
664337	50A294; 50A314; 50A737; 5	EASA;FAA;ANAC	6	28	7X-XX-XX	PW4000 INSPECTION OF VARIOUS PARTS ACC.	Package B		REPLACE NUTPLATES (SPM)		260	SR Technics Switzerland
664337	50A294; 50A314; 50A737; 5	EASA;FAA;CAAC;ANAC										
664337	50A294; 50A314; 50A737; 5	EASA;FAA;CAAC;ANAC	6	28	7X-XX-XX	PW4000 INSPECTION OF VARIOUS PARTS ACC.	Package A	CLN/INSP	CLEANING & INSPECTION		310	SR Technics Switzerland
664337	50A294; 50A314; 50A737; 5	EASA;FAA;CAAC;ANAC;CAA UK										
664374	221-4134-7; 221-4134-8; 22	EASA;FAA;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package D	SPM	REPLACE SPRING TENSION CLIP (SPM)		155	SR Technics Switzerland
664374	221-4134-7; 221-4134-8; 22	EASA;FAA;CAAC;ANAC										
664374	221-4134-7; 221-4134-8; 22	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package A	CLN/INSP	Cleaning and inspection		325	SR Technics Switzerland
664374	221-4134-7; 221-4134-8; 22	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package B	SPM	REPLACE INSERTS (SPM)		165	SR Technics Switzerland
664374	221-4134-7; 221-4134-8; 22	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package C	SPM	REPLACE NUTPLATES (SPM)		175	SR Technics Switzerland
664520	50G958; 50R384-01; 50U22	EASA										
664520	50G958; 50R384-01; 50U22	EASA;CAAC;EASA/ANAC BRAZIL DUAL RELEASE										
664520	50G958; 50R384-01; 50U22	EASA;FAA;CAAC;ANAC										
664520	50G958; 50R384-01; 50U22	EASA;FAA;CAAC;ANAC	5	28	7X-XX-XX	PW4 VARIOUS GEARBOX BRACKETS GENERAL SP	Package A	CLN/INSP	CLEANING & INSPECTION		405	SR Technics Switzerland
664520	50G958; 50R384-01; 50U22	EASA;FAA;CAAC;ANAC	5	28	7X-XX-XX	PW4 VARIOUS GEARBOX BRACKETS GENERAL SP	Package B		REPLACE INSERTS (SPM)		155	SR Technics Switzerland
664520	50G958; 50R384-01; 50U22	EASA;FAA;CAAC;ANAC	5	28	7X-XX-XX	PW4 VARIOUS GEARBOX BRACKETS GENERAL SP	Package C		REPLACE NUTPLATES (SPM)		175	SR Technics Switzerland
664520	50G958; 50R384-01; 50U22	EASA;FAA;CAAC;ANAC	5	28	7X-XX-XX	PW4 VARIOUS GEARBOX BRACKETS GENERAL SP	Package D		REPLACE SPRING TENSION CLIP		165	SR Technics Switzerland
664520	50G958; 50R384-01; 50U22	FAA;ANAC										
664521	59T209-01; 59T860-01; 59T	EASA;FAA;CAAC;ANAC										
664521	59T209-01; 59T860-01; 59T	EASA;FAA;CAAC;ANAC	6	28	72-09-73	PW4 VARIOUS GEARBOX BRACKETS GENERAL AT	Package A	CLN/INSP	Cleaning and inspection		405	SR Technics Switzerland
664521	59T209-01; 59T860-01; 59T	EASA;FAA;CAAC;ANAC	6	28	72-09-73	PW4 VARIOUS GEARBOX BRACKETS GENERAL AT	Package B	SPM	REPLACE INSERTS (SPM)		155	SR Technics Switzerland
664521	59T209-01; 59T860-01; 59T	EASA;FAA;CAAC;ANAC	6	28	72-09-73	PW4 VARIOUS GEARBOX BRACKETS GENERAL AT	Package C	SPM	REPLACE NUTPLATES (SPM)		175	SR Technics Switzerland
664521	59T209-01; 59T860-01; 59T	EASA;FAA;CAAC;ANAC	6	28	72-09-73	PW4 VARIOUS GEARBOX BRACKETS GENERAL AT	Package D	SPM	REPLACE SPRING TENSION CLIP (SPM)		165	SR Technics Switzerland
665040	51G175	EASA;FAA;CAAC;ANAC	6	28	72-34-35	CARBON SEAL ASSEMBLY BRG.1.5/2	Package A	ASSEMBLY	ASSEMBLE SEAL ASSEMBLY		355	SR Technics Switzerland
665041	51D765	EASA;FAA;CAAC;ANAC	6	28	72-34-04	SEAL ASSY BRG.2	Package A	ASSEMBLY	ASSEMBLE SEAL ASSEMBLY		405	SR Technics Switzerland
665124	75A007-5		11	21	78-11-12	EXHAUST PLUG END CAP	Package E	4	CRACKS WELD REPAIR		2360	SR Technics Switzerland
665124	75A007-5		11	21	78-11-12	EXHAUST PLUG END CAP	Package I	8	WELD REPAIR		2835	SR Technics Switzerland
665124	75A007-5	EASA;FAA;CAAC;ANAC	11	21	78-11-12	EXHAUST PLUG END CAP	Package A	CLN/INSP	CLEANING AND INSPECTION		410	SR Technics Switzerland
665210	58R000-001; 58R000-002; 5	EASA;FAA;CAAC;ANAC										
665210	58R000-001; 58R000-002; 5	EASA;FAA;CAAC;ANAC	6	28	72-61-00	GEARBOX ASSY MAIN MODULE	Package A	ASSEMBLY	ASSEMBLY AIRBUS		3570	SR Technics Switzerland
665210	58R000-001; 58R000-002; 5	EASA;FAA;CAAC;ANAC	6	28	72-61-00	GEARBOX ASSY MAIN MODULE	Package A	ASSEMBLY	ASSEMBLY BOEING		3570	SR Technics Switzerland
665210	58R000-001; 58R000-002; 5	EASA;FAA;CAAC;ANAC	6	28	72-61-00	GEARBOX ASSY MAIN MODULE	Package A	ASSEMBLY	ASSEMBLY MD11		3570	SR Technics Switzerland
665212	50G000-002; 51G000; 51G0	EASA;FAA;CAAC;ANAC	6	28	72-62-00	GEARBOX ASSEMBLY-ANGLE	Package A	ASSEMBLY	ASSEMBLY AIRBUS		2590	SR Technics Switzerland
665212	50G000-002; 51G000; 51G0	EASA;FAA;CAAC;ANAC	6	28	72-62-00	GEARBOX ASSEMBLY-ANGLE	Package A	ASSEMBLY	ASSEMBLY BOEING		2590	SR Technics Switzerland
665212	50G000-002; 51G000; 51G0	EASA;FAA;CAAC;ANAC	6	28	72-62-00	GEARBOX ASSEMBLY-ANGLE	Package A	ASSEMBLY	ASSEMBLY MD11		2590	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package A	INSP-05	PRESSURE TEST		475	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package E	4	BLEND REPAIR SURFACE DAMAGE		145	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package F	5	DENT REPAIR WITHOUT REMOVABLE PARTS		1915	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package L	11	BLEND REPAIR OF SURFACE DAMAGED AREA ON HEAT SHIELD, TUBE CONNECTOR NUTS, COUPLING, FERRULE		175	SR Technics Switzerland
665443	71R152-01		4	21	72-09-71	PW4 TUBES	Package W	22	REPAIR OUTER/INNER CONICAL SEAT	SPM 70-00-00	275	SR Technics Switzerland
665443	71R152-01	EASA;FAA;CAAC;ANAC	4	21	72-09-71	PW4 TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		475	SR Technics Switzerland
665464	4042813; 4042814; 404281	EASA;FAA;CAAC;ANAC										

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
665464	4042813; 4042814; 4042815	EASA;FAA;CAAC;ANAC	6	21	71-22-10	PW4 ENGINE REAR MOUNT PARTS 100"	Package A	CLN/INSP	CLEANING AND INSPECTION		280	SR Technics Switzerland
665464	4042813; 4042814; 4042815	EASA;FAA;CAAC;ANAC	6	21	71-22-10	PW4 ENGINE REAR MOUNT PARTS 100"	Package B	1	ANTIGALLANT RELACEMENT REPAIR		110	SR Technics Switzerland
665464	4042813; 4042814; 4042815	EASA;FAA;CAAC;ANAC	6	21	71-22-10	PW4 ENGINE REAR MOUNT PARTS 100"	Package C	2	APPLICATION OF SILVER PLATE ONLY		485	SR Technics Switzerland
665464	4042813; 4042814; 4042815	EASA;FAA;CAAC;ANAC	6	21	71-22-10	PW4 ENGINE REAR MOUNT PARTS 100"	Package C	2	SILVER PLATE REPAIR; SILVER PLATE		485	SR Technics Switzerland
665511	52G414-01; 52G455-01	EASA;FAA;CAAC;ANAC	6	28	72-33-00	PW4000 FAIRING ASSY	Package A	CLN	CLEANING & INSPECTION		165	SR Technics Switzerland
665511	52G414-01; 52G455-01	EASA;FAA;CAAC;ANAC	6	28	72-33-00	PW4000 FAIRING ASSY	Package B		REPLACE NUTPLATES		100	SR Technics Switzerland
667758	51D378-01; 51D379-01; 51C	EASA;FAA;ANAC										
667758	51D378-01; 51D379-01; 51C	EASA;FAA;CAAC;ANAC										
667758	51D378-01; 51D379-01; 51C	EASA;FAA;CAAC;ANAC	6	28	72-34-01	FAN EXIT CASE BRACKET ASSEMBLY	Package A	CLN/INSP	Cleaning and inspection		355	SR Technics Switzerland
667758	51D378-01; 51D379-01; 51C	EASA;FAA;CAAC;ANAC	6	28	72-34-01	FAN EXIT CASE BRACKET ASSEMBLY	Package B	SPM	REPLACE NUT PLATES ACCORDING SPM		485	SR Technics Switzerland
668091	51A562-002	EASA;FAA;CAAC;ANAC	7	28	72-41-85	CARBON SEAL ASSEMBLY BRG.3 REAR	Package A	CLN/INSP	DISASSEMBLY, CLEANING, ASSEMBLY, TEST		1215	SR Technics Switzerland
668484	51T197; 53T754	EASA;FAA;CAAC;ANAC										
668484	51T197; 53T754	EASA;FAA;CAAC;ANAC	5	28	7X-XX-XX	PW4000 INSPECTION OF PARTS IN MODUL INSP	Package A	CLN/INSP	CLEANING & INSPRECTION		105	SR Technics Switzerland
670946	51A681; 51A760		8	28	72-31-80	PW4 COVER FOR CONESEGMENT	Package D	3	LOCAL REPAIR OF PROTECTIVE SURFAC		1920	SR Technics Switzerland
670946	51A681; 51A760		8	28	72-31-80	PW4 COVER FOR CONESEGMENT	Package SB00	PW4ENG 72-619	INLET COMP. FRONT CONE SEGMENT REPL.		430	SR Technics Switzerland
670946	51A681; 51A760		8	28	72-31-80	PW4 COVER FOR CONESEGMENT	Package SB01	PW4G-100-72-70	INLET CONE SEGMENT: P/N 794629 TO 51A681		410	SR Technics Switzerland
670946	51A681; 51A760	EASA;FAA;CAAC;ANAC	8	28	72-31-80	PW4 COVER FOR CONESEGMENT	Package A	CLN/INSP	CLEANING AND INSPECTION		335	SR Technics Switzerland
670946	51A681; 51A760	EASA;FAA;CAAC;ANAC;CAA UK	8	28	72-31-80	PW4 COVER FOR CONESEGMENT	Package C	2	LOCAL REPAIR OF SURFACE DAMAGE		860	SR Technics Switzerland
671061	50S069	EASA;FAA;CAAC;ANAC	6	28	72-35-69	PW4 RCC REAR SUPPORT HPC REAR CASE	Package A	CLN/INSP	CLEANING & INSPECTION		1100	SR Technics Switzerland
671157	50A614	EASA;FAA;CAAC;ANAC	7	28	72-34-32	PW4 GEARBOX DRIVE (OIL) NOZZLE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	NOT ON PPR LEVEL	385	SR Technics Switzerland
671176	50A317	EASA;FAA;CAAC;ANAC	9	28	72-34-29	PW4 OIL NOZZLE ASSEMBLY BRG NO. 1.5	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	280	SR Technics Switzerland
672293	420587; 58T543		5	21	73-21-19	PW4 BIFURCATION CONDUIT (100")	Package H	7	REPLACE NUT PLATES		160	SR Technics Switzerland
672293	420587; 58T543		5	21	73-21-19	PW4 BIFURCATION CONDUIT (100")	Package J	9	REPLACE RUBBER BUMPER PLUG IN THE SHOEBOX BUMPER BRACKET		185	SR Technics Switzerland
672293	420587; 58T543	EASA;FAA;CAAC;ANAC	5	21	73-21-19	PW4 BIFURCATION CONDUIT (100")	Package A	CLN/INSP	CLEANING & INSPECTION		400	SR Technics Switzerland
672293	420587; 58T543	EASA;FAA;CAAC;ANAC	5	21	73-21-19	PW4 BIFURCATION CONDUIT (100")	Package B	TEST	PRE TEST		1355	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AA	57	REPLACE INNER FAN EXIT CASE MONTING FLANGE SCREW THREAD IN	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AB	58	REPAIR OR REPLACE BOSS H	72-34-01	6910	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AC	59	REPLACE 2.5 BLEED VALVE DUCT FLANGE SCREW THREAD INSERTS	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AC	60	REPLACE NO. 1 BEARING SUPPORT FLANGE SCREW THREAD INSERTS	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AC	61	REPLACE SCREW THREAD INSERTS AT STRUT LOCATION NO. 2 AND 3	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AD	61	BLEND REPAIR SURFACE DAMAGE	72-33-04	715	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AE	R.ESEE.000913-E	REPAIR FEGV LEADING EDGE	72-00-33	575	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AF	62	REPAIR PROTECTIVE LAYER	72-34-01	2995	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AG		REPLACE PROTECTIVE SHIELD ACC. SPM		515	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AG		REPLACE RIVETS ACC. SPM		515	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AH	64	REPLACE STRUT SEALANT	72-34-01	2995	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AI	65	REPLACE TIMING PIN	72-34-01	1300	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AJ	66	REPAIR SEALANT AROUND BAFFLES	72-34-01	980	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AK	112	REPLACE FAN EXIT CASE MID-FLANGE BRAKETS	72-34-01	1760	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AK	67	BAFFEL REPLACEMENT	72-34-01	1760	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AK	68	REPLACE FRONT FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	1760	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AK	70	REPLACE CENTER FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	1760	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AK	71	REPLACE REAR FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	1760	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AL	74	REPLACE NUT PLATES INNER LINER SEGMENT CONNECTION	72-34-01	1555	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AM	83	FAN EXIT CASE SURFACE DAMAGE BLEND REPAIR	72-34-01	645	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AN	107	REPLACE HELICAL COIL INSERTS IN BOSSES	72-34-01	1045	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AN	116	HELICAL INSERT REPLACEMENT	72-34-01	1045	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AO	33	REPLACE LPC STATOR NUT PLATES	72-33-04	400	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AP	31	SCREEN REPLACEMENT	72-33-04	970	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AQ		ADD ENGINE SERIAL NUMBER ACC. SPM	FOR SHOP VISITS ONLY	185	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AR	7	SMOOTH THE DAMAGE	72-33-03	6985	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AS	73	REPLACEMENT OF THRUST MOUTH BUSHING	72-34-01	4880	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AT	28	RESTORE CORROSION PROTECTIVE COATING	72-33-01	1545	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AU	20	SEALANT TOUCH-UP REPAIR	72-34-50	3835	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AV	11	COATING REPLACEMENT (INNER SURFACE) REPAIR	72-33-03	2735	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AW	27	BLEND REPAIR	72-33-01	1030	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AX	19	LEADING EDGE FLUOROELASTOMER REPAIR	72-33-05	7860	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package AY	21	SURFACE EROSION REPAIR	72-33-05	3825	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package C	2	AIRFOIL PATCH	72-33-05	430	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package D	3	BEARING PADS SINGLE REPLACEMENT BEFORE INSTALLATION	72-33-08	1780	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package E	6	INSTALL HELICAL TWINSERTS	72-33-08	580	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package E	6	REPLACE HELICAL INSERTS	72-33-08	580	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package F	9	REPAIR DAMAGED INSULATION BLANKETS	72-33-08	640	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package G	13	REPLACE LINER REPAIR	72-33-08	1385	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package H	14	TOUCH UP ANODIZE REPAIR	72-33-04	375	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package I	14	(ALUMINIUM LINER) FAN CASE LINER	72-33-01	2080	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package J	14	(WIRE MESH LINER) FAN CASE LINER	72-33-01	1855	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package K	15	REPAIR FOR WEAR AND HOLES IN RUBSTRIP	72-33-01	3435	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package L	1	TOUCH UP ANODIZE	72-33-08	720	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package L	19	BLEND SURFACE DAMAGE	72-33-01	720	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package M	20	BLEND SURFACE DAMAGE	72-34-01	1395	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package N	23	ACUSTIC LINER BLEND REPAIR	72-33-01	2975	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package N	23	LINER PROTECTIVE COATING REPLACEMENT	72-33-01	2975	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package N	23	REPLACE FOURTH STATOR MOUNTING FLANGE HELICAL COIL INSERTS	72-34-01	2975	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package O	24	REPLACE HELICAL COIL INSERTS AT 2, 4 AND 8 O'CLOCK POSITION	72-34-01	1070	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package P	30	REPLACE PIN RIVET AND COLLAR	72-33-04	1265	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package Q	34	FAIRING REPLACEMENT	72-34-01	9165	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package R	34	REPLACE LPC SPLITTER FAIRING NUT	72-33-04	375	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package S	34-1	LINER JOINT DISBOND REPAIR	72-33-01	1650	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package S	34-2	LINER-INSERT DISBOND REPAIR	72-33-01	1650	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package S	34-3	LINER-JOINT FILLER REPAIR	72-33-01	1650	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package T	35	REPLACE FRONT ANGLE GANG	72-33-04	610	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package U	41	APPLY ANODIZE TOUCH-UP SOLUTION	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package U	63	APPLY ANODIZE TOUCH-UP SOLUTION	72-34-01	810	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package V	42	REPAIR OF DAMAGED FOIL ON THE FIRE ABLATIVE BLANKETS	72-33-04	2470	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package W	44	BLEND SURFACE DAMAGE ON THE FAN EXIT CASE FLANGE ASSEMBLY	72-34-01	1545	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package X	47	REPLACE FIRE SHIELD SEGMENT	72-33-04	880	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package Y	55	SEALANT REPAIR	72-34-01	4780	SR Technics Switzerland
672294	33_34_MOD_INSP_100		13	28	72-XX-XX	FAN AND INTERMEDIATE CASE ASSY 100"	Package Z	56	HELICAL E-FLANGE SCREW THREAD INSERTS	72-34-01	810	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AA	15	INSTALL INSERTS IN ANGLE GEARBOX MOUNT PAD	72-34-01	1540	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AB	16	REPLACE NO.1 BRG. SUPPORT FLANGE HELICAL COIL INSERTS	72-34-01	4135	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AC	17	REPLACE REAR INNER FLANGE ANGE HELICAL COIL INSERTS	72-34-01	4465	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AD	18	REPLACE INNER FAN EXIT CASE MOUNTING FLANGE HELICAL COIL INS	72-34-01	1555	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AE	19	REPAIR THREADED BOSS HOLES	72-34-01	1540	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AF	20	BLEND THE SURFACE DAMAGE	72-34-01	2095	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AG	21	REPLACE NUT PLATE ON FRONT FAN EXIT CASE BRACKET ASSEMBLY B	72-34-01	865	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AH	22	REPLACE A FAIRING WITH NO RIVETS	72-34-01	2100	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AI	23	REPLACE 4TH STATOR MOUNTING FLANGE HELICAL COIL INSERTS	72-34-01	4465	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AJ	24	REPLACE HELICAL COIL NSERTS AT 2,4, AND 8 O'CLOCK POSITIONS	72-34-01	1600	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AK	26	REPLACE THE FRONT FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	755	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AL	42	REPAIR DAMAGED FOIL ON FIRE ABLATIVE BLANKETS	72-33-04	3705	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AM	45	REPLACE LINER	72-33-04	1540	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AN	63	BLEED VALVE SCREEN INNER SURFACE BLEND REPAIR	72-33-04	855	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AO	27	REPLACE THE REAR FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	1445	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AR	34	REPLACE A FAIRING WITH RIVETS	72-34-01	8100	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AS	35	REPAIR THE THREADED HOLES IN THE GROUND HANDLING PAD	72-34-01	3030	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AT	36	SEALANT REPAIR	72-34-01	4465	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AU	37	REPLACE THE BAFFLES	72-34-01	3030	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AV	39	REPLACE THE TIMING PIN	72-34-01	985	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AW	41	APPLY ANODIZE TOUCH-UP SOLUTION	72-34-01	1210	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AX	44	BLEND SURFACE DAMAGE ON THE FAN EXIT CASE FLANGE ASSEMBLY	72-34-01	2315	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AY	45	REPLACE THE PROTECTIVE LAYER	72-34-01	4135	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package AZ	3	BOND OR REPLACE STRUT SEAL	72-00-34	2760	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package B	1	REPLACE LPC STATOR NUT PLATES	72-33-04	595	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BA	49	SURFACE DAMAGE BLEND REPAIR	72-34-01	2715	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BB	70	REPLACE THE CENTER FAN EXIT CASE BRACKET ASSEMBLIES	72-34-01	2640	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BC	74	REPLACE NUT PLATES	72-34-01	2330	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BD	100	STOP DRILL FAN EXIT FAIRING	72-34-01	515	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BE	101	FAN EXIT FAIRING COVER REPLACEMENT	72-34-01	1775	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BF	105	BLEND REPAIR FAIRING ASSEMBLY	72-34-01	1850	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BG	107	REPLACE HELICAL COIL NSERTS IN BOSSES	72-34-01	1565	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BH	109	REPLACE FRONT FAN EXIT BRACKETS	72-34-01	1690	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BI	110	REPLACE THE CENTER BRACKET ASSEMBLIES	72-34-01	3030	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BJ	122	REAR BRACKET REPLACEMENT REPAIR	72-34-01	3030	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BK	123	BLEND THRUST CLEVIS BRACKET	72-34-01	1430	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BL	R.ESEE.000913-E	REPAIR FEGV LEADING EDGE	72-00-33	855	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BM		REPLACE MOD-34 INSERT 12 O'CLOCK ACC. SPM		275	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BN		REPLACE NUT PLATES ACCORDING SPM		275	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package		Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BO			ADD ENGINE SERIAL NUMBER ACC. SPM	FOR SHOP VISITS ONLY	275	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BQ		2	SMOOTH THE DAMAGE	72-33-03	1530	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BR		20	SEALANT TOUCH-UP REPAIR	72-34-50	3830	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BS		29	REPLACE THE TRUST MOUNT BUSHINGS	72-34-01	5410	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BT		2	SMOOTH THE DAMAGE	72-33-03	7590	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BT		14	CORROSION REMOVAL (INNER SURFACE) REPAIR	72-33-03	7590	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BU		11	COATING REPLACEMENT (INNER SURFACE) REPAIR REPAIR	72-33-03	2735	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BV		15	DOUBLER REPAIR	72-33-03	7250	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BW		19	LEADING EDGE FLUOROELASTOMER REPAIR	72-33-05	7860	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package BX		21	SURFACE EROSION REPAIR	72-33-05	3825	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package C		2	REPLACE LPC FAIRING NUT	72-33-04	560	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package D		3	REPLACE BLEED VALVE DUCT BRACKET	72-33-04	5330	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package E		4	REPLACE DUCT BRACKET NUT	72-33-04	1835	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package F		5	REPLACE DUCT BRACKET	72-33-04	5330	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package G		6	REPLACE BLEED VALVE DUCT BRACKET	72-33-04	1445	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package H		7	REPLACE DUCT BRACKET	72-33-04	5330	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package I		8	REPLACE VALVE DUCT HELICOIL INSERTS	72-33-04	595	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package J		9	REPLACE EXIT CASE GANG NUT	72-33-04	1160	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package K		10	REPLACE EXIT CASE NUT PLATES	72-33-04	1160	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package L		11	REPLACE EXIT INNER CASE BRACKET ASSEMBLY	72-33-04	2575	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package M		12	REPLACE BRACKET NUT PLATE	72-33-04	2575	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package N		13	REPLACE INNER CASE RIVET	72-33-04	295	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package O		14	TOUCH UP ANODIZE FAN EXIT	72-33-04	560	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package P		2	AIRFOIL PATCH	72-33-05	645	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package Q		16	REPLACE RUBBER SEAL	72-33-04	1700	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package R		1	REPLACE FAN CASE ASSEMBLY LOCATING PIN	72-33-01	630	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package S		2	BLEND SURFACE DAMAGE REPAIR	72-33-01	3180	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package T		5	REPAIR DUCT SEGMENT HOLES	72-33-01	4755	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package U		6	REPAIR DUCT SEGMENT CRACKS	72-33-01	4755	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package V		7	REPAIR DUCT SEGMENT SURFACE DAMAGE	72-33-01	4755	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package W		22	REPLACE BONDED PADS	72-33-04	2735	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package X		1	PATCH REPAIR (FLOUROELASTOMER)	72-34-01	1430	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package X		1	PATCH REPAIR(ORGANIC FIBRE)	72-34-01	1430	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package Y		4	PATCH REPAIR (EPOXY)	72-34-01	1430	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package Y		4	PATCH REPAIR (FLOUROELASTOMER)	72-34-01	1430	SR Technics Switzerland
672311	33_34_MOD_INSP_94		16	21	7X-XX-XX	FAN AND IINTERMEDIATE CASE ASSY 94"	Package Z		25	REPAIR THE ABLATIVE COATING	72-33-04	2570	SR Technics Switzerland
672446	52R100-10; 52R100-11; 52R	EASA;FAA;CAAC;ANAC											
672446	52R100-10; 52R100-11; 52R	EASA;FAA;CAAC;ANAC	6	28	72-61-00	PW4 100" GEARBOX ASSEMBLY	Package A	CLN/INSP		CLEANING & INSPECTION		385	SR Technics Switzerland
672466	53_MOD_INSP_100; 53_MOD_INSP_94		6	28	72-XX-XX	LOW PRESSURE TURBINE (LPT)	Package AN		39	TOUCH-UP P/N 52A402-101 AND 52A577-01	72-53-80	2690	SR Technics Switzerland
672466	53_MOD_INSP_100; 53_MOD_INSP_94		6	28	72-XX-XX	LOW PRESSURE TURBINE (LPT)	Package B		1	FEATHERSEAL REPLACEMENT, 72-00-53	FOR SHOP VISITS ONLY	2465	SR Technics Switzerland
672466	53_MOD_INSP_100; 53_MOD_INSP_94		6	28	72-XX-XX	LOW PRESSURE TURBINE (LPT)	Package C		2	FEATHERSEAL REPLACEMENT, 72-00-53	FOR SHOP VISITS ONLY	2465	SR Technics Switzerland
672466	53_MOD_INSP_100; 53_MOD_INSP_94		6	28	72-XX-XX	LOW PRESSURE TURBINE (LPT)	Package D		3	3STG LEADING EDGE BLEND REPAIR	72-00-53	1950	SR Technics Switzerland
672466	53_MOD_INSP_100; 53_MOD_INSP_94		6	28	72-XX-XX	LOW PRESSURE TURBINE (LPT)	Package P		15	LOCAL TOUCH-UP COATING	72-53-80	2620	SR Technics Switzerland
672592	50H033; 50H653; 50H654; 5	EASA;FAA;CAAC;ANAC											
672592	50H033; 50H653; 50H654; 5	EASA;FAA;CAAC;ANAC	4	21	72-35-00	PW4000 INSPECTION OF VARIOUS MODULE 35 PARTS	Package A	CLN/INSP		CLEANING & INSPECTION		115	SR Technics Switzerland
672592	50H033; 50H653; 50H654; 5	EASA;FAA;CAAC;ANAC	4	21	72-35-00	PW4000 INSPECTION OF VARIOUS MODULE 35 PARTS	Package SB00	PW4ENG 72-565		HPC 14/15 STAGE BLADES MODIFICA|TION		140	SR Technics Switzerland
672592	50H033; 50H653; 50H654; 5	EASA;FAA;CAAC;ANAC	4	21	72-35-00	PW4000 INSPECTION OF VARIOUS MODULE 35 PARTS	Package SB01	PW4G-100-72-8		HPC 14/15 STAGE BLADES MODIFICA|TION		140	SR Technics Switzerland
672785	52G530-01		6	28	72-34-01	FAN EXIT CASE BRACKET ASSEMBLY	Package B	SPM		REPLACE NUTPLATES		310	SR Technics Switzerland
672785	52G530-01	EASA;FAA;CAAC;ANAC	6	28	72-34-01	FAN EXIT CASE BRACKET ASSEMBLY	Package A	CLN/INSP		CLEANING AND INSPECTION		405	SR Technics Switzerland
672786	51T766-01; 52T309-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package A	CLN/INSP		CLEANING AND INSPECTION		405	SR Technics Switzerland
672786	51T766-01; 52T309-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package B	SPM		REPLACE INSERTS		155	SR Technics Switzerland
672786	51T766-01; 52T309-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package C	SPM		REPLACE NUTPLATES		175	SR Technics Switzerland
672786	51T766-01; 52T309-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-73	PW4 VARIOUS BRACKETS GENERAL	Package D	SPM		REPLACE SPRING TENSION CLIP		165	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package A	INSP-CHECK-05		PRESSURE TEST		260	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package B		1	APPLY ANTIGALLING COMPOUND		95	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package C		2	THRUST WIRE INSTALLATION		310	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package D		4	BLEND REPAIR SURFACE DAMAGE		260	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package E		5	DENT REPAIR		1675	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package F		7	LINER,NUT,REDUCER,ELBOW,SLEEVE REPLACEMENT		915	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package G		10	HEAT SHIELD REPAIR OF BLEED DUCT		515	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package H		11	REPAIR OF DAMAGED AREA ON HEAT SHIELD TUBE CONNECTOR NUTS, COUPLING, FERRULE		320	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package I		12	DAMAGED AREA HEATSHIELD STRAP GUIDE REPAIR		310	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package SB00	PW4G-100-A72-15		INSPECTION OF STARTING AIR ACTUATION TUBE (AA96)	SB PW4G-100-A72-158	315	SR Technics Switzerland
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package SB01	PW4G-100-80-5		STARTER, CONNECT. ASSEMBLY MODI OR REPLACEMENT RR TUBE TO	PART 001	2335	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672791	56T214-01		4	21	72-09-71	PW4 EXTERNAL TUBES	Package W	22	REPEAR CONICAL SEAT	70-00-00	210	SR Technics Switzerland
672791	56T214-01	EASA;FAA;CAAC;ANAC	4	21	72-09-71	PW4 EXTERNAL TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		260	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package A	CLN/INSP	Cleaning and inspection		475	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package A	INSP-05	PRESSURE TEST		475	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package B	1	ANTISIZE COMPOUND APPLICATION		95	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package C	2	THRUST WIRE INSTALLATION		450	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package D	48	OIL TUBE, COATING REPAIR		825	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package E	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	485	SR Technics Switzerland
672809	50U794-01; 52T574-01; 52T	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4000 TUBES	Package F	SPM	RIVET REMOVAL PROCEDURE	SPM 70-43-00	405	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC										
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		240	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package A	INSP-05	PRESSURE TEST		240	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package D		REPAIR INNER CONICAL SEAT	SPM 70-00-00 / REP-22	400	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package D		REPAIR OUTER CONICAL SEAT	SPM 70-00-00 / REP-22	400	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package F		REPLACE RIVETED STOP NUT	SPM 70-43-00	265	SR Technics Switzerland
672810	50A457; 50A778-01; 50A77	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4000 TUBES	Package H	48	OIL TUBE, COATING REPAIR		775	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P196-01; 51A296-01; 59T129-01		6	21	72-09-71	PW4 TUBES EXTERNAL	Package E	5	DENT REPAIR		1620	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P196-01; 51A296-01; 59T129-01		6	21	72-09-71	PW4 TUBES EXTERNAL	Package F	7	LINER, NUT, REDUCER, ELBOW, SLEEVE REPLACEMENT		1020	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P196-01; 51A296-01; 59T129-01		6	21	72-09-71	PW4 TUBES EXTERNAL	Package G	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD TUBE		320	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P196-01; 51A296-01; 59T129-01		6	21	72-09-71	PW4 TUBES EXTERNAL	Package H	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	315	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES EXTERNAL	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES EXTERNAL	Package A	INSP-05	INSPECTION CHECK 05	PRESSURE TEST	475	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES EXTERNAL	Package B	1	ANTISIZE COMPOUND APPLICATION		95	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES EXTERNAL	Package C	2	THRUST WIRE INSTALLATION		325	SR Technics Switzerland
672811	50P187-01; 50P189-01; 50P	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES EXTERNAL	Package D	4	REBLEND REPAIR SURFACE DAMAGE		210	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		450	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package D	4	BLEND REPAIR SURFACE DAMAGE		260	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package E	5	DENT REPAIR		1620	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package F	7	LINER,NUT,REDUCER,ELBOW,SLEEVE REPLACEMENT		1020	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package G	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD		320	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package H	13	MINOR GOUGE, TEAR, CUT OF FLEXIBLE TUBE FIRE SLEEVE REPAIR		320	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package I	18	FLANGE COAT REPLACEMENT		880	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package J	20	STRAINER ELEMENT HOUSING ASSY FLA		425	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package K	SPM	REPLACE DEFECT INSERTS		250	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package L	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	485	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T362-01		6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package M	SPM	REPLACE RIVETED STOP NUT	SPM 70-43-00	405	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package A	CLN/INSP	Cleaning and inspection		475	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package A	INSP-05	INSPECTION CHECK 05	PRESSURE TEST	475	SR Technics Switzerland
672812	52T576-01; 53T209-01; 58T	EASA;FAA;CAAC;ANAC;TCCA	6	21	72-09-71	PW4 TUBES (REPAIR HEAVY) CCP > 4000 USD	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package A	INSP-05	INSPECTION CHECK 05	PRESSURE TEST	475	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package D	4	BLEND REPAIR SURFACE DAMAGE		145	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package E	5	DENT REPAIR WITHOUT REMOVABLE PARTS		1675	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package F	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD		320	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package G	48	OIL TUBE, COATING REPAIR		775	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package H	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	485	SR Technics Switzerland
672813	53T165-01		6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package I	SPM	REPLACE RIVETED STOP NUT ACC.	SPM 70-43-00	405	SR Technics Switzerland
672813	53T165-01	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES (REPAIR MEDIUM) CCP 2000-4000	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
672814	50G809; 50G811; 51G864-01; 51U930-01; 57T896-01; 58T064-01		8	21	72-09-71	PW4 TUBES	Package F	11	REPAIR OF DAMAGED AREA ON HEAT SHIELD TUBE		275	SR Technics Switzerland
672814	50G809; 50G811; 51G864-01; 51U930-01; 57T896-01; 58T064-01		8	21	72-09-71	PW4 TUBES	Package G	48	OIL TUBE COATING REPAIR		775	SR Technics Switzerland
672814	50G809; 50G811; 51G864-01; 51U930-01; 57T896-01; 58T064-01		8	21	72-09-71	PW4 TUBES	Package H	SPM	REPAIR OF THE TUBE CONICAL SEAT	SPM 70-00-00 REP-22	400	SR Technics Switzerland
672814	50G809; 50G811; 51G864-01; 51U930-01; 57T896-01; 58T064-01		8	21	72-09-71	PW4 TUBES	Package I	SPM	REPLACE RIVETED STOP NUT	SPM 70-43-00	330	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;ANAC	8	21	72-09-71	PW4 TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		295	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;ANAC	8	21	72-09-71	PW4 TUBES	Package A	INSP-05	PRESSURE TEST		295	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		330	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES	Package D	4	BLEND REPAIR OF SURFACE DAMAGE		165	SR Technics Switzerland
672814	50G809; 50G811; 51G864-0	EASA;FAA;CAAC;ANAC	8	21	72-09-71	PW4 TUBES	Package E	5	DENT REPAIR		1675	SR Technics Switzerland
672815	56T656-01		6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package A	INSP-05	PRESSURE TEST		475	SR Technics Switzerland
672815	56T656-01		6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672815	56T656-01		6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		325	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672815	56T656-01		6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package D	SPM	REPAIR CONICAL SEAT		485	SR Technics Switzerland
672815	56T656-01		6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package E	SPM	REPLACE RIVETED STOP NUT ACC.	SPM 70-43-00	325	SR Technics Switzerland
672815	56T656-01	EASA;FAA;CAAC;ANAC	6	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 20	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51G822-01; 51G862-01; 53T684-01		7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package E	SPM	REPLACE RIVETED STOP NUT ACC.	SPM 70-43-00	405	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51C	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51C	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package A	INSP-05	PRESSURE TEST		475	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51C	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51C	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package C	2	TUBE NUT THRUST WIRE INSTALLATION		450	SR Technics Switzerland
672816	51G818-01; 51G819-01; 51C	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (REPAIR LIGHT) CCP 800 - 2000	Package D	SPM	REPAIR CONICAL SEAT		485	SR Technics Switzerland
672817	51G861; 52G126-01		7	21	72-09-71	PW4 TUBES (INSPECTION ONLY) CCP <800	Package B	1	APPLY ANTI-SIZE COMPOUND		95	SR Technics Switzerland
672817	51G861; 52G126-01		7	21	72-09-71	PW4 TUBES (INSPECTION ONLY) CCP <800	Package C	SPM	REPAIR CONICAL SEAT		345	SR Technics Switzerland
672817	51G861; 52G126-01	EASA;FAA;ANAC	7	21	72-09-71	PW4 TUBES (INSPECTION ONLY) CCP <800	Package A	CLN/INSP	CLEANING AND INSPECTION		355	SR Technics Switzerland
672817	51G861; 52G126-01	EASA;FAA;CAAC;ANAC	7	21	72-09-71	PW4 TUBES (INSPECTION ONLY) CCP <800	Package A	INSP-05	PRESSURE TEST		355	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;ANAC										
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC										
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package A	CLN/INS	CLEANING & INSPECTION		125	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE INSERTS	ACC. SPM	185	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE NUTPLATES	ACC. SPM	185	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE SPRING TENSION CLIP	ACC. SPM	185	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package SB00	PW4G-100-72-60	MODIFICATION OF BRACKET ASSEMBY BY REPLACING OF SPRING TENSION CLIPS		245	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package SB01	PW4ENG 72-595	SELF-LOCKING NUT PLATES REPLACEMENT	72-00-00	140	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package SB02	PW4ENG 75-112	INTRODUCTION OF NEW OR REDESIGNED BRACKET ASSEMBLY	75-00-00	205	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC	7	21	7X-XX-XX	PW4000 VARIOUS BRACKETS GENERAL	Package SB03	PW4ENG 72-306	MODIFICATION OF EEC/SCU ATTACHMENT OF PROGRAMMING PLUG	72-33-00	140	SR Technics Switzerland
672821	50D311; 50D775; 50D776; 5	EASA;FAA;CAAC;ANAC;CAA UK										
672825	332T4921-213; 50P102; 50P	EASA										
672825	332T4921-213; 50P102; 50P	EASA;CAAC;EASA/ANAC BRAZIL DUAL RELEAS	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE SPRING TENSION CLIP	ACC. SPM	185	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;ANAC										
672825	332T4921-213; 50P102; 50P	EASA;FAA;ANAC;TCCA										
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC										
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package A	CLN/INSP	CLEANING & INSPECTION		125	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE INSERTS	ACC. SPM	185	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package B		REPLACE NUTPLATES	ACC. SPM	185	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package SB00	PW4G-100-72-60	MODIFICATION OF BRACKET ASSEMBY BY REPLACING OF SPRING TENSION CLIPS		245	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package SB01	PW4ENG 72-595	SELF-LOCKING NUT PLATES REPLACEMENT	72-00-00	140	SR Technics Switzerland
672825	332T4921-213; 50P102; 50P	EASA;FAA;CAAC;ANAC	5	21		PW4000 VARIOUS BRACKETS GENERAL	Package SB02	PW4ENG 72-609	MODIFICATION OF TO INCREASE CLEARENCE WITH THE PT4.95 SENSE TUBE		275	SR Technics Switzerland
672831	51D768-01; 51D772-01; 52C	EASA;FAA;CAAC;ANAC										
672831	51D768-01; 51D772-01; 52C	EASA;FAA;CAAC;ANAC	9	21	72-09-73	PW4 ENGINE BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION		355	SR Technics Switzerland
672831	51D768-01; 51D772-01; 52C	EASA;FAA;CAAC;ANAC	9	21	72-09-73	PW4 ENGINE BRACKET	Package O	14	ANTI SLIP STRIP ADHESIVE REPLACEMENT		775	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AJ	47	INNER AIRSEAL REPLACEMENT REPAIR		9600	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AK	48	INNER SHROUD REPLACEMENT REPAIR		16385	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package B	1	ANODIZE TOUCH-UP		605	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package C	2	BLEND REPAIR VANES		1550	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package C	5	BLEND REPAIR OUTER SHROUD		1550	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package D	3	CRACK REPAIR (MINOR) LPC (STAGE 1.6, 2, AND 3) COMPRESSOR STATOR ASSEMBLY INNER SHROUD		560	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package G	6	REPLACE VANE REPAIR		18700	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package M	12	PUT THE JACKSCREW HOLES IN NEW POSITIONS		1765	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package N	13	REPLACE SILICONE RUBBER RUBSTRIP LPC (STAGE 1.6, 2 AND 3) COMPRESSOR STATOR ASSEMBLY		12690	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package Q	16	REPAIR THE AREA AROUND A JACKSCREW HOLE WITH A DOUBLER		1155	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package SB00	PW4ENG 72-666	LPC, 1ST STAGE STATOR & 4TH STAGE DUCT -REPL. OF, OR MODIFIC. T	LPC STAGE 1.6, 2 AND 3 IMPROVED RUBBER F	19410	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package SB01	PW4ENG 72-781	NEW 1.6, 2ND, AND 3RD STAGE LPC SHROUD SEGMENTS AND SEAL SEGMENTS		24575	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AI	46	MISSING SILICONE RUBBER SEALANT REPLACEMENT REPAIR		9350	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AJ	47	INNER AIRSEAL REPLACEMENT REPAIR		9600	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AK	48	INNER SHROUD REPLACEMENT REPAIR		16385	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package B	1	ANODIZE TOUCH-UP		605	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package C	2	BLEND REPAIR VANES		1550	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package C	5	BLEND REPAIR OUTER SHROUD		1550	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package D	3	CRACK REPAIR (MINOR) LPC (STAGE 1.6, 2, AND 3) COMPRESSOR STATOR ASSEMBLY INNER SHROUD		560	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package G	6	REPLACE VANE REPAIR		18700	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package M	12	PUT THE JACKSCREW HOLES IN NEW POSITIONS		1765	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package N	13	REPLACE SILICONE RUBBER RUBSTRIP LPC (STAGE 1.6, 2 AND 3) COMPRESSOR STATOR ASSEMBLY		12690	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package Q	16	REPAIR THE AREA AROUND A JACKSCREW HOLE WITH A DOUBLER		1155	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package SB00	PW4ENG 72-666	LPC, 1ST STAGE STATOR & 4TH STAGE DUCT -REPL. OF, OR MODIFIC. T	LPC STAGE 1.6, 2 AND 3 IMPROVED RUBBER F	19410	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021-01; 56B016-001; 56B016-01; 56B116; 56B116		11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package SB01	PW4ENG 72-781	NEW 1.6, 2ND, AND 3RD STAGE LPC SHROUD SEGMENTS AND SEAL SEGMENTS		24575	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1240	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AE	30	DAMAGED VANE POTTING (DRY ROTTED) COMPOUND REPLACEMENT REPAIR		10255	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AF	39	BENT FLANGE STRAIGHTENING REPAIR		3435	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	10	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AI	46	MISSING SILICONE RUBBER SEALANT REPLACEMENT REPAIR		9350	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1240	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AE	30	DAMAGED VANE POTTING (DRY ROTTED) COMPOUND REPLACEMENT REPAIR		10255	SR Technics Switzerland
672854	51B426-01; 54B916; 55B021	EASA;FAA;CAAC;ANAC	11	28	72-31-10	PW4000 94" LPC COMPRESSOR STG. 1,6,2 & 3	Package AF	39	BENT FLANGE STRAIGHTENING REPAIR		3435	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package B	1	ANODIZE TOUCH-UP		605	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package R	17	BLEND REPAIR OUTER SHROUD AND VANE		1550	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package S	18	SILICONE RUBBER OUTER AIRSEAL REPAIR		10350	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package SB00	PW4G-100-72-119	REPLACEMENT OR MODIFICATION OF LPC STATOR ASSY 1.6 - 3 STG 1.3 & 4.TH STG DUCT RUBBER		16165	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package SB01	PW4G-100-72-189	REPLACEMENT OR MODIFICATION TO INCORPORATE IMPROVED INNER SHROUD RUBSTRIPS		13555	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package SB02	PW4G-100-72-259	REPLACEMENT OR MODIFICATION TO INCREASE THE 3RD STAGE BLADE TIP TO OUTER AIR SEAL (OAS) CLEARANCE		680	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package SB03	PW4G-100-72-259	C3STATOR INCREASED BLADE TIP CLEARANCE		8490	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package T	19	CRACK REPAIR LPC STAGE 1.6, 2 AND 3 COMPRESSOR STATOR ASSEMBLY INNER SHROUD		560	SR Technics Switzerland
672857	51B626-001; 51B626-002; 51B626-01; 53B186; 53B226-01; 59B816-001; 59		8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package V	21	REPLACE VANE REPAIR		17640	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1240	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AE	30	DAMAGED VANE POTTING (DRY ROTTED) COMPOUND REPLACEMENT REPAIR		10255	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AF	44	INNER AIRSEAL REPLACEMENT REPAIR		9600	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AG	46	MISSING SILICONE RUBBER SEALANT REPLACEMENT REPAIR		9350	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AK	36	INNER SHROUD ALUMINUM BAND REPLACEMENT REPAIR		10060	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AM	43	INNER SHROUD REPLACEMENT REPAIR		15455	SR Technics Switzerland
672857	51B626-001; 51B626-002; 5	EASA;FAA;CAAC;ANAC	8	28	72-31-10	PW4000 100" LPC COMPRESSOR STG 1.6 - 3	Package AN	39	BENT FLANGE STRAIGHTENING REPAIR		3435	SR Technics Switzerland
673029	56H191-01		8	28	72-35-61	PW4 STG 11 & 12 COMPRESSOR STATOR SET	Package O	14	REPLACE PWA 53-78 PLASMA COAT		1320	SR Technics Switzerland
673029	56H191-01		8	28	72-35-61	PW4 STG 11 & 12 COMPRESSOR STATOR SET	Package P	15	BLEND STAGE 11 AND 12 HPC		730	SR Technics Switzerland
673029	56H191-01		8	28	72-35-61	PW4 STG 11 & 12 COMPRESSOR STATOR SET	Package R	17	WELD CRACKS IN ANTI ROTATION SLOT		1780	SR Technics Switzerland
673029	56H191-01		8	28	72-35-61	PW4 STG 11 & 12 COMPRESSOR STATOR SET	Package S	18	WELD CRACKS IN THE OUTER SHROUD LUG		1460	SR Technics Switzerland
673029	56H191-01	EASA;FAA;CAAC;ANAC;CAA UK	8	28	72-35-61	PW4 STG 11 & 12 COMPRESSOR STATOR SET	Package A	CLN/INSP	CLEANING AND INSPECTION		2500	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package AA	26	WELD CRACKS IN THE ANTI-ROTATION SLOTS		2110	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package AB	27	WELD CRACKS IN THE OUTER SHROUD LUG		1275	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package AF	31	BOROSCOPE BOSS REPLACEMENT REPAIR		1835	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package AG	32	FEATHERSEAL SLOT AND FELTMETAL RUBSTRIP POCKET WELD		9485	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package B	1	BLEND REPAIR		630	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package R	17	DUAL ARC WIRE COATING OF THE FRONT FACE FOR WEAR UP		2395	SR Technics Switzerland
673032	57H283-01		7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package S	18	REMOVE AND REPLACE PWA 53-78		1060	SR Technics Switzerland
673032	57H283-01	EASA;FAA;CAAC;ANAC	7	28	72-35-62	PW4 STG 13 AND 14 COMPRESSOR STATOR SET	Package A	CLN/INSP	CLEANING AND INSPECTION		3000	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package AE	28	WELD REPAIR DAMAGED SHROUD AREAS		2715	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package AI	32	AXIAL FLANGE CREACKS WELD REPAIR		4390	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package AJ	32	PLASMA AND WELD REPAIR AXIAL FLAN		6250	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package AK	36	INTERMIXING STATOR SET STG. 9 AND STG. 10		655	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package B	1	BLEND VANES		1365	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package C	2	REMOVE AND REPLACE NUT ASSEMBLIES		515	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package I	8	INTERMEDIATE "W" SEAL FACE		3010	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package J	9	PLASMA SPRAY FRONT SEAL FACE		3275	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package K	10	PLASMA SPRAY REPAIR OF THE REAR SNAP DIAMETER (SURFACE XC)		3370	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package L	11	PLASMA SPRAY REPAIR OF THE INTERMEDIATE "W" SEAL INNER SNAP DIAMETER (SURFACE D)		3615	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package M	12	PLASMA SPRAY REPAIR THE INTERMEDIATE "W" SEAL OUTER SNAP DIAMETER (SURFACE E)		3615	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package N	13	PLASMA SPRAY REPAIR OF THE FRONT SEAL INNER SNAP DIAMETER (SURFACE F)		3615	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package O	14	PLASMA SPRAY REPAIR OF THE FRONT SEAL OUTER SNAP DIAMETER (SURFACE G)		3615	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package R	17	REPAIR CRACKED SEGMENT END FLANGE HOLES		2225	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package S	18	WELD REPAIR CRACKS IN THE OUTER SHROUD LUG		1720	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package V	21	REPLACE THE INNER AIR SEAL ANTI-ROTATION PINS		1475	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package X	23	WELD THE 9TH STAGE VANE DAMAGE		3580	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package Y	24	AXIAL FLANGE SQUARENESS REPAIR		1380	SR Technics Switzerland
673035	56H519-01		8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package Z	25	BORESCOPE BOSS REPLACEMENT REPAIR		1915	SR Technics Switzerland
673035	56H519-01	EASA;FAA;CAAC;ANAC	8	35	72-35-60	PW4 STAGE 9 AND 10 COMPRESSOR STATOR SET	Package A	CLN/INSP	CLEANING AND INSPECTION		2500	SR Technics Switzerland
673637	51H530; 55H302		6	28	72-35-67	PW4 HPC REAR SUPPORT	Package D	3	PLASMA COAT OUTER FLANGE FRONT FACE		2725	SR Technics Switzerland
673637	51H530; 55H302		6	28	72-35-67	PW4 HPC REAR SUPPORT	Package E	4	PLASMA COAT OUTER FLANGE SNAP DIAMETER		2725	SR Technics Switzerland
673637	51H530; 55H302		6	28	72-35-67	PW4 HPC REAR SUPPORT	Package F	5	RESTORE CORROSION PROTECTIVE COATING		1460	SR Technics Switzerland
673637	51H530; 55H302		6	28	72-35-67	PW4 HPC REAR SUPPORT	Package J	9	INNER FACE FRONT FLANGE PLASMA COAT REPAIR		2500	SR Technics Switzerland
673637	51H530; 55H302	EASA;FAA;CAAC;ANAC	6	28	72-35-67	PW4 HPC REAR SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		500	SR Technics Switzerland
673637	51H530; 55H302	EASA;FAA;CAAC;ANAC	6	28	72-35-67	PW4 HPC REAR SUPPORT	Package B	1	PLASMA COAT INNER FLANGE SNAP DIAMETER		2725	SR Technics Switzerland
673642	50R408; 50R409; 70T530; 7(	EASA;FAA;CAAC;ANAC	7	28	72-41-92	PW4 GEARBOX SUPPORT CLEVIS, LEFT AND RI	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
673642	50R408; 50R409; 70T530; 7(	EASA;FAA;CAAC;ANAC	7	28	72-41-92	PW4 GEARBOX SUPPORT CLEVIS, LEFT AND RI	Package B	1	CHROME PLATE INDEX 1 HOLE SUPPORT CLEVIS		1675	SR Technics Switzerland
673642	50R408; 50R409; 70T530; 7(	EASA;FAA;CAAC;ANAC	7	28	72-41-92	PW4 GEARBOX SUPPORT CLEVIS, LEFT AND RI	Package C	2	BUSHING REPAIR SUPPORT CLEVIS HOLES		960	SR Technics Switzerland

© 2020 SR Technics. All rights reserved

Capabilities and Fixed Prices Catalogue 2026 for

PW4000

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
673642	50R408; 50R409; 70T530; 7(	EASA;FAA;CAAC;ANAC	7	28	72-41-92	PW4 GEARBOX SUPPORT CLEVIS, LEFT AND RI	Package D		REMOVE DEFECTIVE BOLTS FROM CLAMP		200	SR Technics Switzerland
673649	70T334	EASA;FAA;CAAC;ANAC	7	28	72-61-87	PW4 GEARBOX SUPPORT LINK LOWER HOLLOW PIN	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	200	SR Technics Switzerland
673657	796146		9	28	72-53-84	PW4 NO.4 BEARING RETAINING PLATE STEEL	Package B		1 NICKEL PLATE SNAP DIAMETER		925	SR Technics Switzerland
673657	796146		9	28	72-53-84	PW4 NO.4 BEARING RETAINING PLATE STEEL	Package C		2 NICKEL PLATE PACKING SEAL LAND		925	SR Technics Switzerland
673657	796146		9	28	72-53-84	PW4 NO.4 BEARING RETAINING PLATE STEEL	Package D	INSP/CHECK-03	REMOVE DAMAGE BY BLENDING		160	SR Technics Switzerland
673657	796146	EASA;FAA;CAAC;ANAC;CAA UK	9	28	72-53-84	PW4 NO.4 BEARING RETAINING PLATE STEEL	Package A	CLN/INSP	CLEANING AND INSPECTION		560	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package C		2 PLASMA SPRAY REAR SNAP DIAMETER		2110	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package D		3 PLASMA SPRAY No.1.5 BEARING JOURN		2215	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package E		4 REPLACE CLINCH NUTS		340	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package F		5 REPLACE HELICAL COIL INSERTS		175	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package SB00	PW4G-100-A72-10	INSPECTION OF THE SUPPORT FOR A THIN WALL CONDITION		2245	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package SB01	PW4ENG 72-789	INSPECTION FOR DUPLICATE SERIAL NUMBERS ON BEARING SUPPORTS		80	SR Technics Switzerland
673659	50A182		7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package SB02	PW4ENG 72-678	INSPECTION OF TO IDENTIFY CERTAIN THAT MUST BE REMOVED FROM SERVICESUPPORTS		80	SR Technics Switzerland
673659	50A182	EASA;FAA;CAAC;ANAC	7	28	72-34-20	PW4 BRG 1.5 BEARING SUPPORT ASSEMBLY ST	Package A	CLN/INSP	CLEANING AND INSPECTION		550	SR Technics Switzerland
673662	50B198; 50B770		8	28	72-31-28	PW4 #1 BEARING SEAL SUPPORT ASSY	Package E		4 OUTER MATING DIAMETER PLASMA COAT	ALUMINIUM PART	2805	SR Technics Switzerland
673662	50B198; 50B770		8	28	72-31-28	PW4 #1 BEARING SEAL SUPPORT ASSY	Package F		5 OUTER MATING DIAMETER PLASMA COAT	TITANIUM PART	3060	SR Technics Switzerland
673662	50B198; 50B770	EASA;FAA;CAAC;ANAC	8	28	72-31-28	PW4 #1 BEARING SEAL SUPPORT ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		855	SR Technics Switzerland
673662	50B198; 50B770	EASA;FAA;CAAC;ANAC	8	28	72-31-28	PW4 #1 BEARING SEAL SUPPORT ASSY	Package D		3 CLINCH NUT REPLACEMENT		4465	SR Technics Switzerland
673666	51A478-01		7	28	72-54-83	PW4 NO.4 BEARING COVER ASSEMBLY TITANIU	Package SB00	PW4ENG 72-385	ADD JACKSCREW HOLES TO NO.4 BEARING COVER		530	SR Technics Switzerland
673666	51A478-01	EASA;FAA;CAAC;ANAC	7	28	72-54-83	PW4 NO.4 BEARING COVER ASSEMBLY TITANIU	Package A	CLN/INSP	CLEANING AND INSPECTION		330	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package A	INSP-05	INSP/CHK-05 LEAK CHECK		475	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package B		1 NICKEL PLATE INSIDE SNAP DIA		3140	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package C		2 SEAL RING GROOVE REPAIR		1440	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package D		3 REPLACE RETAINING PIN		3435	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package E		4 NICKEL PLATE FRONT SNAP INNER DIA		3140	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package F		5 INSERT REPLACEMENT REPAIR		345	SR Technics Switzerland
673681	50A478		7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package L		11 BLEND SURFACE DAMAGE	MPN 50A478	345	SR Technics Switzerland
673681	50A478	EASA;FAA;CAAC;ANAC	7	28	72-41-86	PW4 NO.3 BARING SEAL RING HOLDER NICKEL	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
673746	782475-1	EASA;FAA;CAAC;ANAC	5	21	80-12-06	PW4000 Adapter and Clamp	Package A	CLN/INSP	CLEANING & INSPECTION		310	SR Technics Switzerland
673760	PW4000 BASIS ENGINE		5	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package C		REPLACE INSERTS MODULE		320	SR Technics Switzerland
673760	PW4000 BASIS ENGINE		5	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package D		REPLACE INSERTS TEST CELL		350	SR Technics Switzerland
673760	PW4000 BASIS ENGINE		5	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package E		REPLACE INSERTS QTL		320	SR Technics Switzerland
673760	PW4000 BASIS ENGINE	EASA;FAA;ANAC	5	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package B		REPLACE INSERTS ENGINE		320	SR Technics Switzerland
673782	50R403	EASA;FAA;TCCA	5	28	72-35-72	PW4 GEARBOX DRIVESHAFT HOUSING SUPPORT	Package A	CLN/INSP	CLEANING & INSPECTION		255	SR Technics Switzerland
673857	70R112; 70R115	EASA;FAA;CAAC;ANAC										
673857	70R112; 70R115	EASA;FAA;CAAC;ANAC	4	28	72-61-63	PW4000 RELIEF VALVE PLUG AND SPRING	Package A	CLN/INSP	CLEANING & INSPECTION		175	SR Technics Switzerland

© 2020 SR Technics. All rights reserved