

NEW REPAIR CAPABILITY ANNOUNCEMENT



CFM56-7B FAN FRAME SHROUD

“ADDING VALUE TO YOUR ASSETS”




Relevant for CFM56-7B Operators / Airlines / MRO Engine Shops / Parts traders & brokers

Spotlight Repairs

- Repair-018: IDG Air/Oil Cooler Attachment Bolt Holes Bushing Repair
- Repair 042: Repair of the attachment holes on B7 and/or B8 flanges.
- Repair 053: V-groove wear strip replacement
- Repair 007 Fan Frame Shroud Handling Boss Blend Repair
- Repair 045 AGB Clevis Mount Lug

Benefits:

- Increased in house capabilities on piece part repair level, 85% of ESM repairs implemented.
- Improved TAT for Engine Shop Visits due to in-house repairs.
- Costs savings due to no external vendor & logistics costs.



Rep 018: Installed Bushing



Repair 053: V-groove wear strip replacement

CONTACT US: sales@srtechnics.com | enginepartsrepair@srtechnics.com
www.srtechnics.com | cpc.srtechnics.com

We safely power your flight