



CAPABILITIES AND
FIXED PRICES CATALOGUE



ENGINE PARTS
REPAIR SERVICES

Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
251	336-095-401-0	EASA;FAA;CAAC;ANAC	37	28	72-55-04	LOW PRESSURE TURBINE SHAFT - REAR ROTATING AIR/OIL SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		805	SR Technics Switzerland
251	336-095-402-0	EASA;FAA;CAAC;ANAC			72-55-04		Package B	001	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR/OIL SEAL WH DIA A		3,115	SR Technics Switzerland
251					72-55-04		Package E	004	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR/OIL SEAL WH DIA X		1,895	SR Technics Switzerland
1459	301-298-909-0	EASA;FAA;CAAC;ANAC;CAA UK	34	28	72-55-17	LOW PRESSURE TURBINE SHAFT - SLOTTED NUT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	250	SR Technics Switzerland
1459	337-112-901-0	EASA;FAA;CAAC;ANAC			72-55-17		Package B	001	REPAIR OF THE MATING FACE		2,135	SR Technics Switzerland
1459					72-55-17		Package C	002	REPAIR OF THE SILVER PLATING		745	SR Technics Switzerland
1459					72-55-17		Package D	003	BLENDING OF THE SLOT		345	SR Technics Switzerland
2055	336-009-801-0	EASA;FAA;CAAC;ANAC;CAA UK	31	28	72-55-14	LOW PRESSURE TURBINE SHAFT - NO.4 BEARING FORWARD ROTATING	Package A	CLN/INSP	CLEANING AND INSPECTION		665	SR Technics Switzerland
2055					72-55-14		Package B	001	RECONDITIONING OF THE 5 PERCENT NI-AL UNDERCOAT AND THE AL-SI-POLYES		2,930	SR Technics Switzerland
2055					72-55-14		Package C	002	REPAIR OF RABBET DIAMETER A		2,480	SR Technics Switzerland
2055					72-55-14		Package E	004	REPAIR MATING SURFACE		2,250	SR Technics Switzerland
2200	1523M40G02	EASA;FAA;CAAC;ANAC	38	28	72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		1,235	SR Technics Switzerland
2200	1808M56G01	EASA;FAA;CAAC;ANAC			72-41-03		Package SB01	72-0373	INTRODUCTION OF NEW HPT INNER STATOR STATIONARY SEAL HEAT SHIELD TO		5,740	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	545	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	545	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	545	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	545	SR Technics Switzerland
2200					72-41-03		Package SB04	72-1125-000	INSPECTION OF OF HPT INNER STATIONARY SEAL FOR HONEYCOMB SEPARATIO PART 000		545	SR Technics Switzerland
2591	1559M40G03	EASA;FAA;CAAC;ANAC	51	28	72-33-01	COMPRESSOR REAR STATOR - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1,820	SR Technics Switzerland
2591					72-33-01		Package B	INSP-001	REMOVAL OF HIGH METAL		1,435	SR Technics Switzerland
2591					72-33-01		Package B	INSP-001	BLEND PATH PICK-UP		1,435	SR Technics Switzerland
2591					72-33-01		Package C	002	LEADING/TRAILING EDGES	72-33-02	945	SR Technics Switzerland
2591					72-33-01		Package F	005	REPAIR OF DAMAGED FLOW PATH SURFACES		7,625	SR Technics Switzerland
2591					72-33-01		Package G	006	REPAIR OF FORWARD LIP OUTER DIAMETER (DIAMETER D)		6,625	SR Technics Switzerland
2591					72-33-01		Package SB00	SB 72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CFM56-5B2 AND CFM56-5B6/2 TO CFM56-5B6/2P , CF		390	SR Technics Switzerland
2741	338-001-503-0	EASA;FAA;CAAC;ANAC	41	28	72-21-03	FAN AND BOOSTER - FAN DISK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	ROBOTIC ECI (SPEC PROC-002)	6,930	SR Technics Switzerland
2741	338-001-504-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-03		Package B	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS		790	SR Technics Switzerland
2741					72-21-03		Package C	SPEC PROC-001	ULTRASONIC INSPECTION		2,005	SR Technics Switzerland
2741					72-21-03		Package G	006	SHOT-PEENING OF THE FAN DISK DOVETAILS		1,575	SR Technics Switzerland
2741					72-21-03		Package M	012	BLEND REPAIR OF THE FAN DISK		2,590	SR Technics Switzerland
2741					72-21-03		Package N	013	REPAIR OF THE FACE THAT MATES WITH THE SEALING FLANGE OF THE BOOSTER		3,710	SR Technics Switzerland
2741					72-21-03		Package Q	016	REPLACEMENT OF THE CRIMPED SPACERS		1,245	SR Technics Switzerland
2741					72-21-03		Package SB00	AD 2002-13-03	DISK FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE AND DOVETA		3,960	SR Technics Switzerland
2882	1795M36P01	EASA;FAA;CAAC;ANAC	45	28	72-52-03	HIGH PRESSURE TURBINE ROTOR - FRONT AIR ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	4,400	SR Technics Switzerland
2882	1795M36P02	EASA;FAA;CAAC;ANAC			72-52-03		Package B	INSP-001 002	REMOVAL OF HIGH METAL		600	SR Technics Switzerland
2882	2116M20P02	EASA;FAA;CAAC;ANAC			72-52-03		Package C	002	REPAIR OF DIAMETER R		2,800	SR Technics Switzerland
2882	2410M50P02	EASA;FAA;CAAC;ANAC;CAA UK			72-52-03		Package E	005	REPLACEMENT OF SEAL TEETH COATING		4,705	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA B	4,980	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA C	4,980	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBET THERMAL SPRAY REPAIR	DIA B	4,980	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBET THERMAL SPRAY REPAIR	DIA C	4,980	SR Technics Switzerland
2882					72-52-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND EDDY CURRENT INSPECTION (IN CONJUNCTION WITH PACKAGE A		645	SR Technics Switzerland
2882					72-52-03		Package SB02	72-1074	REPL. OF ROTATING AIR HPT FRONT SEAL PN 1795M36P02	AD EASA-2019-0146	430	SR Technics Switzerland
2882					72-52-03		Package SB05	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	545	SR Technics Switzerland
2882					72-52-03		Package SB05	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	545	SR Technics Switzerland
2882					72-52-03		Package SB05	72-1125-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2026-0033	545	SR Technics Switzerland
2882					72-52-03		Package SB06	72-EO-52905	REPLACEMENT OF AFFECTED ROTATING AIR HPT	FAA-2021-16-08	545	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3043	218920-1	EASA;FAA;ANAC	25	21	73-11-14	FUEL PUMP - MAIN GEAR HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		255	SR Technics Switzerland
3043	219821-1	EASA;FAA;ANAC			73-11-14		Package M	012	NEW VALVE SEAT INSERT INSTALLATION		1,325	SR Technics Switzerland
3043					73-11-14		Package N	013	REWORK MAIN GEAR HOUSING		1,185	SR Technics Switzerland
3043					73-11-14		Package SB00	714900-73-108	INTRODUCTION OF NEW FUEL PUMP WITH NEW FILTER COVER ATTACHMENT		745	SR Technics Switzerland
3043					73-11-14		Package SB01	73-0111	REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT OF THE FUEL FOF THE MAIN FUEL PUMP EQUIPPED WITH		235	SR Technics Switzerland
3044	217780-1	EASA;FAA;ANAC	11	21	73-11-13	MAIN GEAR HOUSING ASSEMBLY	Package B		TEST AND INSPECTION		285	SR Technics Switzerland
3044	219822-1	EASA;FAA;ANAC			73-11-13		Package E		REPLACEMENT OF DAMAGED STUDS		980	SR Technics Switzerland
3044					73-11-13		Package E		REWORK MAIN GEAR HOUSING		980	SR Technics Switzerland
3044					73-11-13		Package SB01	73-0111	REPL. OF CURRENT DEFECTIVE 6TH ATTACHMENT OF THE FUEL FILTER COVER		135	SR Technics Switzerland
3207	338-010-103-0	EASA;FAA;CAAC;ANAC	28	28	72-53-06	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 1	Package B		BASIC REPAIR	TYPE 1/2/3	300	SRTAS
3207	338-010-104-0	EASA;FAA;CAAC;ANAC			72-53-06		Package B	INSP-001	VISUAL / DIMENSIONAL		300	SRTAS
3207	338-010-106-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C		MINOR REPAIR	TYPE 1/2/3	675	SRTAS
3207	338-010-107-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	1	AIRFOIL BLEND REPAIR		675	SRTAS
3207	338-010-108-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	5	REPAIR OF APVS COATING		675	SRTAS
3207	338-010-203-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	55	OVERCOATING OF APVS PROTECTION		675	SRTAS
3207	338-010-204-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	INSP-001	VISUAL / DIMENSIONAL		675	SRTAS
3207	338-010-206-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D		MEDIUM REPAIR	TYPE 1	6,370	SRTAS
3207	338-010-207-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	1	AIRFOIL BLEND REPAIR		6,370	SRTAS
3207	338-010-208-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	17	FULL BRAZING REPAIR	INCLUDING CRACK REPAIR WITH NO BAFFI	6,370	SRTAS
3207	338-108-606-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	5	REPAIR OF APVS COATING		6,370	SRTAS
3207	338-108-607-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	INSP-001	VISUAL / DIMENSIONAL		6,370	SRTAS
3207	338-108-608-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E		FULL REPAIR	TYPE 1	6,515	SRTAS
3207	338-108-609-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	1	AIRFOIL BLEND REPAIR		6,515	SRTAS
3207	338-108-614-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	17	FULL BRAZING REPAIR	INCLUDING ANY COMBINATION OF ASPEC	6,515	SRTAS
3207	338-108-706-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		6,515	SRTAS
3207	338-108-707-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	5	REPAIR OF APVS COATING		6,515	SRTAS
3207	338-108-708-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	INSP-001	VISUAL / DIMENSIONAL		6,515	SRTAS
3207	338-108-709-0	EASA;FAA;CAAC;ANAC			72-53-06		Package F		ADDITIONAL WORKSCOPE	TYPE 1	860	SRTAS
3207	338-108-714-0	EASA;FAA;CAAC;ANAC			72-53-06		Package F	72-0229	NEW PART RELEASE OR REWORK OLD PART. EDM HOLES IN AFT FLANGE & SEAL PERFORMED DURING ANY OF THE PACKAC		860	SRTAS
3207	340-256-251-0	EASA;FAA;CAAC;ANAC			72-53-06		Package G		ADDITIONAL WORKSCOPE	TYPE 1/2/3	1,175	SRTAS
3207	340-256-252-0	EASA;FAA;CAAC;ANAC			72-53-06		Package G	22	WELD REPAIR OF SEAL SLOT BREAKOUT		1,175	SRTAS
3207	340-256-254-0	EASA;FAA;CAAC;ANAC			72-53-06		Package H		ADDITIONAL WORKSCOPE	TYPE 1/2/3	4,165	SRTAS
3207	340-256-351-0	EASA;FAA;CAAC;ANAC			72-53-06		Package H	12	AIRFLOW RESTORATION BY DIFFUSION BRAZING		4,165	SRTAS
3207	340-256-352-0	EASA;FAA;CAAC;ANAC			72-53-06		Package K		MEDIUM REPAIR	TYPE 2/3	6,370	SRTAS
3207	340-256-354-0	EASA;FAA;CAAC;ANAC			72-53-06		Package K	1	AIRFOIL BLEND REPAIR		6,370	SRTAS
3207					72-53-06		Package K	27	FULL BRAZING REPAIR	CRACK REPAIR WITH NO BAFFLE, REMOVA	6,370	SRTAS
3207					72-53-06		Package K	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		6,370	SRTAS
3207					72-53-06		Package K	5	REPAIR OF APVS COATING		6,370	SRTAS
3207					72-53-06		Package K	INSP-001	VISUAL / DIMENSIONAL		6,370	SRTAS
3207					72-53-06		Package L		FULL REPAIR	TYPE 2/3	6,515	SRTAS
3207					72-53-06		Package L	1	AIRFOIL BLEND REPAIR		6,515	SRTAS
3207					72-53-06		Package L	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		6,515	SRTAS
3207					72-53-06		Package L	27	FULL BRAZING REPAIR	INCLUDING ANY COMBINATION OF ASPEC	6,515	SRTAS
3207					72-53-06		Package L	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		6,515	SRTAS
3207					72-53-06		Package L	5	REPAIR OF APVS COATING		6,515	SRTAS
3207					72-53-06		Package L	INSP-001	VISUAL / DIMENSIONAL		6,515	SRTAS
3207					72-53-06		Package N		GLOBAL AIRFLOW REPAIR BY DICA		11,310	SRTAS

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3207					72-53-06		Package N		ADDITIONAL WORKSCOPE	TYPE 2/3	11,310	SRTAS
3473	336-024-704-0	EASA;FAA;CAAC;ANAC	50	28	72-56-06	LOW PRESSURE TURBINE REAR FRAME - OIL INLET COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		1,770	SR Technics Switzerland
3473	336-024-705-0	EASA;FAA;CAAC;ANAC			72-56-06		Package B	001	REPLACEMENT OF THE COATED RING OR REPLACEMENT OF THE ORIGINAL COAT		5,255	SR Technics Switzerland
3473	336-024-706-0	EASA;FAA;CAAC;ANAC			72-56-06		Package C	002	REPAIR OF THE CRIMPED SELF-LOCKING NUTS		910	SR Technics Switzerland
3473	336-024-707-0	EASA;FAA;CAAC;ANAC			72-56-06		Package E	004	REPAIR OF SEAL TEETH BY WELD UP		3,110	SR Technics Switzerland
3473	336-024-708-0	EASA;FAA;CAAC;ANAC			72-56-06		Package G	006	PLASMA REPAIR OF REAR CONTACT FACE		3,375	SR Technics Switzerland
3473					72-56-06		Package SB00	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1,280	SR Technics Switzerland
3473					72-56-06		Package SB01	72-0320	INTRODUCTION OF NEW OIL INLET COVER ASSY		1,280	SR Technics Switzerland
3975	1358M80P04	EASA;FAA;CAAC;ANAC	30	28	72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SEAL RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		535	SR Technics Switzerland
3975					72-51-10		Package B	001	REPAIR WEAR ON THE HPT NOZZLE EXTERNAL PRESSURE SEAL RETAINER		3,825	SR Technics Switzerland
7808	301-546-107-0	EASA;FAA;CAAC;ANAC	28	28	72-55-16	LOW PRESSURE TURBINE SHAFT - PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		385	SR Technics Switzerland
7808	337-124-601-0	EASA;FAA;CAAC;ANAC			72-55-16		Package B	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAFT BY PLASMA DIA A		1,700	SR Technics Switzerland
7808	337-124-620-0	EASA;FAA;CAAC;ANAC			72-55-16		Package C	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAFT BY PLASMA DIA B		1,700	SR Technics Switzerland
7808	338-072-102-0	EASA;FAA;CAAC;ANAC			72-55-16		Package D	002	RECONDITIONING OF THE INNER LOCATING DIAMETER (DIA C) WITH THE CENTE		1,705	SR Technics Switzerland
7808	338-072-103-0	EASA;FAA;CAAC;ANAC;DGCA CIVI			72-55-16		Package E	003	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		1,225	SR Technics Switzerland
7808	340-310-501-0	EASA;FAA;CAAC;ANAC			72-55-16		Package F	004	CLEANING AND PACKAGING		235	SR Technics Switzerland
8457	238-0860-501	EASA;FAA;CAAC;ANAC;CAA UK	12	21	71-00-17	CFM56-5B FIRE DETECTOR SUPPORT TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		865	SR Technics Switzerland
8457	238-0861-501	EASA;FAA;CAAC;ANAC			71-00-17		Package F	005	CRACK REPAIR FIRE DETECTOR		320	SR Technics Switzerland
8457	642-5861-501	EASA;FAA;CAAC;ANAC			71-00-17		Package G	006	RUPTURE REPAIR FIRE		375	SR Technics Switzerland
8457					71-00-17		Package H	007	GOUGE REPAIR FIRE DETECTOR		325	SR Technics Switzerland
8457					71-00-17		Package I	008	CLAMPS WELD REPLACEMENT		350	SR Technics Switzerland
8457					71-00-17		Package J	017	SUPPORT TUBE WELD REPAIR		540	SR Technics Switzerland
8521	1358M35G02	EASA;FAA;CAAC;ANAC;CAA UK	35	28	72-51-08	HIGH PRESSURE TURBINE NOZZLE - AFT INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,110	SR Technics Switzerland
8521	1522M46G02	EASA;FAA;CAAC;ANAC			72-51-08		Package B	003	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY	WASPALLOY CONFIGURATION	7,250	SR Technics Switzerland
8521					72-51-08		Package B	004	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY	RENE 41 CONFIGURATION	7,250	SR Technics Switzerland
8521					72-51-08		Package C	001	REPAIR FOR THE HPT AFT INNER NOZZLE SUPPORT PIN REPLACEMENT		2,060	SR Technics Switzerland
8521					72-51-08		Package SB00	72-0171	CONVERSION	CRACK INSPECTION PT "LINIE B"	320	SR Technics Switzerland
8527	301-297-812-0	EASA;FAA;CAAC;ANAC	11	28	72-22-12	CFM56 NO.1 BEARING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		820	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLECTOR AND OIAREA G		1,245	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLECTOR AND OIAREA L		1,245	SR Technics Switzerland
13471	337-100-804-0	EASA;FAA;CAAC;ANAC	21	28	72-23-15	FAN FRAME ASSEMBLY - ACCESSORY DRIVE REAR CLEVIS MOUNT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	580	SR Technics Switzerland
13471	338-075-402-0	EASA;FAA;CAAC;ANAC			72-23-15		Package C	002	REPLACEMENT OF BUSHING		1,250	SR Technics Switzerland
13471	340-077-601-0	EASA;FAA;CAAC;ANAC			72-23-15		Package D	003	SPOT TOUCH UP CLEVIS		465	SR Technics Switzerland
15175	2616M78G01	EASA;FAA;CAAC;ANAC	48	28	72-31-11	COMPRESSOR ROTOR - AIR DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		910	SR Technics Switzerland
15175	9514M54G05	EASA;FAA;CAAC;ANAC;CAA UK			72-31-11		Package C	002	REPAIR ILLEGIBLE PART IDENTIFICATION NUMBERS		205	SR Technics Switzerland
15175					72-31-11		Package G	006	REPLACEMENT OF COMPRESSOR ROTOR AIR DUCT SLEEVE		3,455	SR Technics Switzerland
16715	1559M30G05	EASA;FAA;CAAC;ANAC	86	28	72-32-01	COMPRESSOR FRONT STATOR - CASE	Package A	ASSEMBLY-001	RE-MEASURE FLOW PATH		3,645	SR Technics Switzerland
16715	1559M30G06	EASA;FAA;CAAC;ANAC			72-32-01		Package A	CLN/INSP	CLEANING AND INSPECTION		3,645	SR Technics Switzerland
16715	1559M30G09	EASA;FAA;CAAC;ANAC			72-32-01		Package AB	027	REPAIR OF THE AFT FLANGE PITTING AND CORROSION		6,615	SR Technics Switzerland
16715	1559M30G10	EASA;FAA;CAAC;ANAC			72-32-01		Package AG	032	BLEND CORROSION/PITTING NON-FLOWPATH AREA		1,365	SR Technics Switzerland
16715	1559M30G11	EASA;FAA;CAAC;ANAC			72-32-01		Package AK		MEASURE NEW - / OVHLD PARTS		205	SR Technics Switzerland
16715	1559M30G12	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	BLEND CASE SURFACE		2,360	SR Technics Switzerland
16715	1559M30G13	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	BLEND HOT SPOTS		2,360	SR Technics Switzerland
16715	1559M30G14	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	BLEND CASE CORROSION/DISCOLORATION		2,360	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH	ATA 72-00-32	2,360	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH PICKUP		2,360	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	WET ABRASIVE BLAST CORROSION/DISCOLORATION		2,360	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
16715					72-32-01		Package B	INSP-001	BLENDING FLOW, NICKS, ETC.		2,360	SR Technics Switzerland
16715					72-32-01		Package B	SPM	REMOVE BROKEN BOLTS		2,360	SR Technics Switzerland
16715					72-32-01		Package C	001	REPAIR OF THREADED BOSSES AND PADS		2,415	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS		3,495	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS	RETAP THREADS	3,495	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABBET DIAMETERS OF THE COMPRESSOR FRC DIA B		4,070	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABBET DIAMETERS OF THE COMPRESSOR FRC DIA C		4,070	SR Technics Switzerland
16715					72-32-01		Package G	002	LEADING/TRAILING EDGES	72-32-03	945	SR Technics Switzerland
16715					72-32-01		Package P	015	FLOW PATH REPAIR		12,600	SR Technics Switzerland
16715					72-32-01		Package Q	016	WELD REPAIR OF LINEAR INDICATIONS AT THE HORIZONTAL SPLIT LINE		9,445	SR Technics Switzerland
16715					72-32-01		Package R	017	INTRGRAL PILOT BRACKET (IPB) DIAMETER D REPAIR	DIA D	9,025	SR Technics Switzerland
16715					72-32-01		Package SB01	72-0171	FAN & BOOSTER, MOD FROM -5B/2 TO -5B/2P		320	SR Technics Switzerland
16715					72-32-01		Package V	021	REAMING OF THE AFT FLANGE BOLT HOLES		12,685	SR Technics Switzerland
16715					72-32-01		Package X	023	WELD REPAIR OF LINEAR INDICATIONS AT SPLITLINE BOLT HOLES AND BUSHING		12,445	SR Technics Switzerland
16715					72-32-01		Package Y	024	WELD REPAIR OF DAMAGED MID FLANGE BOLT HOLES AND AFT FACE WEAR		2,980	SR Technics Switzerland
18900	305-025-408-0	EASA;FAA;CAAC;ANAC	56	28	72-55-15	LOW PRESSURE TURBINE SHAFT - AIR/OIL SEPARATOR AND COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		525	SR Technics Switzerland
18900	305-044-506-0	EASA;FAA;CAAC;ANAC			72-55-15		Package B	001	TOUCH-UP OF THE SURFACE PROTECTION ON THE AIR/OIL SEPARATOR		630	SR Technics Switzerland
18900	337-108-502-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-15		Package C	002	TOUCHUP OF SURFACE PROTECTION ON AIR/OIL SEPARATOR COVER		1,000	SR Technics Switzerland
18900	337-108-510-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-15		Package D	003	AIR/OIL SEPARATOR AND COVER REPAIR		2,280	SR Technics Switzerland
18900	337-108-520-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-15		Package E	004	REPAIR OF THE LOCATING DIAMETER WITH LPT SHAFT		4,050	SR Technics Switzerland
18900	337-108-551-0	EASA;FAA;CAAC;ANAC			72-55-15		Package F	005	REPAIR OF THE DIAMETER WHICH LOCATES THE CENTER VENT TUBE REAR EXTEI		1,715	SR Technics Switzerland
18900					72-55-15		Package G	006	REPAIR OF THREE WELD BEADS ON AIR/OIL SEPARATOR		1,290	SR Technics Switzerland
18900					72-55-15		Package H	007	REPLACEMENT OF THE COVER OF THE AIR/OIL SEPARATOR		1,460	SR Technics Switzerland
18900					72-55-15		Package I	008	CLEANING AND PACKAGING		635	SR Technics Switzerland
18900					72-55-15		Package SB03	72-0854	INTRODUCTION OF A NEW AIR/OIL SEPARATOR AND REWORK OF THE OLD ONE		1,355	SR Technics Switzerland
21504	338-002-114-0	EASA;FAA;CAAC;ANAC	48	28	72-21-01	FAN AND BOOSTER - FAN ROTOR BLADE	Package B	ASSEMBLY-001	MEASURE WEIGHT/DISTRIBUTION		130	SR Technics Switzerland
21511	1558M31G03	EASA;FAA;CAAC;ANAC	55	28	72-31-04	COMPRESSOR ROTOR - SPOOL	Package A	CLN/INSP	CLEANING, FLUORESCENT PENETRANT INSPECTION (FPI) AND INSPECTION		2,550	SR Technics Switzerland
21511	1558M31G04	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	BLENDING STAGE 1 AREA M		2,560	SR Technics Switzerland
21511	1558M31G05	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	REMOVAL OF HIGHMETAL		2,560	SR Technics Switzerland
21511	1558M31G07	EASA;FAA;CAAC;ANAC;CAA UK			72-31-04		Package B	INSP-001	BLENDING RETAINER HOOKS		2,560	SR Technics Switzerland
21511	1834M55G01	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	BLENDING INTERSTAGE SEAL		2,560	SR Technics Switzerland
21511					72-31-04		Package B	INSP-001	BLENDING FWD SEAL DIA DZ		2,560	SR Technics Switzerland
21511					72-31-04		Package C	002	REPAIR OF ILLEGIBLE PART MARKINGS		130	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA E	7,075	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA F	7,075	SR Technics Switzerland
21511					72-31-04		Package G	006	APPLICATION OF MOLYDAG 254 COATING ON STAGES 1 AND 2 DOVETAILS		3,430	SR Technics Switzerland
21511					72-31-04		Package H	007	REPAIR OF FRETTED SURFACE G		5,910	SR Technics Switzerland
21511					72-31-04		Package SB00	72-0448	FPI OF HPC STAGE 1-2 SPOOL, STAGE 1 DOVETEIL SLOT BOTTOM		1,155	SR Technics Switzerland
21511					72-31-04		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)		1,645	SR Technics Switzerland
21512	1590M59P01	EASA;FAA;CAAC;ANAC	44	28	72-31-05	COMPRESSOR ROTOR - DISK STAGE 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1,660	SR Technics Switzerland
21512	2116M23P01	EASA;FAA;CAAC;ANAC;CAA UK			72-31-05		Package B	INSP-001	DISK BLENDING PAD AREA E		895	SR Technics Switzerland
21512	9940M55P18	EASA;FAA;CAAC;ANAC			72-31-05		Package C	002	REPAIR OF THE RABBET DIAMETERS		4,255	SR Technics Switzerland
21512					72-31-05		Package L	INSP-001	REMOVE HIGHMETAL		895	SR Technics Switzerland
21512					72-31-05		Package M	INSP-001	DISK BLEND RETAINER HOOK		895	SR Technics Switzerland
21512					72-31-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	960	SR Technics Switzerland
21512					72-31-05		Package SB00	SB 72-0122	ULTRASONIC / EDDY CURRENT INSPECTION		960	SR Technics Switzerland
21514	338-010-601-0	EASA;FAA;CAAC;ANAC;CAA UK	33	28	72-22-01	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,900	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
21514					72-22-01		Package A	CLN/INSP	CLEANING AND INSPECTION	REMOVE HIGH METAL/DAMAGE INCLUDE	1,900	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	RECRIMP SELF LOCKING NUT		700	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	REPAIR THREADS NO.2 BRG		700	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	TOUCH-UP PAINT		700	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	TOUCH-UP PAINT		700	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	RECRIMP SELF LOCKING NUT		700	SR Technics Switzerland
21514					72-22-01		Package C		REMOVE PAINT		3,800	SR Technics Switzerland
21514					72-22-01		Package C		REMOVE PAINT		3,800	SR Technics Switzerland
21514					72-22-01		Package C	001	REPLACEMENT OF THE ALUMINIUM PAINT		3,800	SR Technics Switzerland
21514					72-22-01		Package C	001	REPLACEMENT OF THE ALUMINIUM PAINT		3,800	SR Technics Switzerland
21514					72-22-01		Package D	002	REPLACEMENT OF CRIMPED SELF-LOCKING NUTS		1,200	SR Technics Switzerland
21514					72-22-01		Package D	002	REPLACEMENT OF CRIMPED SELF-LOCKING NUTS		1,200	SR Technics Switzerland
21514					72-22-01		Package SB00	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI).	IN CONJUNCTION WITH PACKAGE A	815	SR Technics Switzerland
21514					72-22-01		Package SB00	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI).	IN CONJUNCTION WITH PACKAGE A	815	SR Technics Switzerland
22647	1348M79P08	EASA;FAA;CAAC;ANAC;CAA MALF	29	21	73-21-18	FUEL - HYDROMECHANICAL CONTROL	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	4,525	SR Technics Switzerland
22647	8061-526	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-18		Package B	TEST	PRE TEST		4,525	SR Technics Switzerland
22647					73-21-18		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST EXCLUDED P		5,280	SR Technics Switzerland
22647					73-21-18		Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED P EXAMPLE: SERVO SLEEVE,TORQUE MOTOI		10,235	SR Technics Switzerland
22647					73-21-18		Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED P EXAMPLE: PILOT VALVE BODY,PRESSURIZI		14,450	SR Technics Switzerland
22647					73-21-18		Package G		OVERHAUL		18,790	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-006	WIRE INSULATION SAFEGUARD IMPROVEMENTS	IN CONJUNCTION WITH PACKAGE LIGHT, N	545	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-008	IMPROVED OVERSPEED GOVERNOR SPEEDER SPRING ASSEMBLY, 8061-526 (134 IN CONJUNCTION WITH PACKAGE LIGHT, N		545	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-009	INSPECTION OF PRESSURIZING VALVE PORT,8061-511(1348M79P06),8061-512(1 IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB01	73-104	REPLACEMENT OF EXISTING PART, REPLACING VIN 1680-684 RESOLVERS IN HMU IN CONJUNCTION WITH PACKAGE MEDIUM		545	SR Technics Switzerland
22647					73-21-18		Package SB01	73-EO-527943	HMU - PREVENTIVE BEARING REPLACEMENT	IN CONJUNCTION WITH PACKAGE MEDIUM	545	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-003	IMPROVEMENTS TO THE TORQUE MOTOR AND RESOLVER, 8061-512 (1348M79) IN CONJUNCTION WITH PACKAGE MEDIUM		545	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-005	INCORPORATION OF ANTI-ROTATION PUMP UNLOADING DESIGN, 8061-512 (134 IN CONJUNCTION WITH PACKAGE MEDIUM		545	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-012	IMPROVED TORQUE MOTOR (CARBIDE TIP ASSEMBLY)	IN CONJUNCTION WITH PACKAGE MEDIUM	545	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-014	IMPROVED PRESSURITING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH PACKAGE MEDIUM	545	SR Technics Switzerland
22647					73-21-18		Package SB02	73-069	DELTA P DRIVE PIN REPLACEMENT	IN CONJUNCTION WITH PACKAGE HEAVY C	545	SR Technics Switzerland
22647					73-21-18		Package SB02	73-102	REPLACEMENT OF MIS-MACHINED PRESSURIZING VALVE SLEEVES	IN CONJUNCTION WITH PACKAGE HEAVY C	545	SR Technics Switzerland
22647					73-21-18		Package SB02	73-112	REPLACEMENT OF OSG DRIVE PIN RETAINERS,REPLACING 3535-196 DRIVE PIN R IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB02	73-127	INSPECTION FOR MISMACHINED VBV PORT, 8061-511(1348M79P06),8061-512(1 IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-001	REWORK OF VALVE ASSEMBLIES TO ELIMINATE POTENTIAL TRAPPED FUEL CONI IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-004	USE OF FLUOROCARBON VITON PREFORMED PACKINGS IN HMU, MIL-R-83248/1 IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-010	INTRODUCTION OF IMPROVED HMU PRESSURIZING VALVE, 8061-512 (1348M79) IN CONJUNCTION WITH PACKAGE HEAVY C		545	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-011	USE OF FLUOROCARBON VITON PREFORMED PACKINGS IN HMU, GLT-6005	IN CONJUNCTION WITH PACKAGE HEAVY C	545	SR Technics Switzerland
22647					73-21-18		Package SB03	EASA-2017-0065	HYDRO-MECHANICAL UNITS - OPERATIONAL LIMITATIONS		545	SR Technics Switzerland
22647					73-21-18		Package SB04	FAA 2013-14-06	CORROSION OF THE DELTA-P VALVE		1,615	SR Technics Switzerland
22647					73-21-18		Package SB05	73-0182	USE OF CIS FUEL IN CFM56-5A ENGINES		545	SR Technics Switzerland
22647					73-21-18		Package SB06	72-0122	USE OF CIS FUEL IN CFM56-5B ENGINES		545	SR Technics Switzerland
24630	336-026-101-0	EASA;FAA;CAAC;ANAC	24	28	72-53-09	STAGE 1 LPT NOZZLE - BORESCOPE PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	220	SR Technics Switzerland
24630					72-53-09		Package B	INSP-001	BLENDING THREAD HIGH METAL		470	SR Technics Switzerland
44969	9531M11G02	EASA;FAA;CAAC;ANAC	24	28	72-42-01	COMBUSTION CHAMBER (SAC) - INNER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		1,010	SR Technics Switzerland
44969					72-42-01		Package C	002	WELD REPAIR AND RESIZING OF THE INNER COWL		1,645	SR Technics Switzerland
61388	1348M79P09	EASA;FAA;ANAC;CAA MALAYSIA;I	45	21	73-21-78	HYDROMECHANICAL FUEL CONTROL	Package B	TEST	PRE TEST		3,855	SR Technics Switzerland
61388	1348M79P10	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	3,855	SR Technics Switzerland

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

**Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply**



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
61388	1348M79P11	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED P		5,805	SR Technics Switzerland
61388	1348M79P12	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED P		8,490	SR Technics Switzerland
61388	1348M79P13	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package G		OVERHAUL		11,595	SR Technics Switzerland
61388	1348M79P14	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB01	73-0122	HMU - CIS FUEL MAINTENANCE REQUIREMENT	IN CONJUNCTION WITH MEDIUM	745	SR Technics Switzerland
61388	8061-531	EASA;FAA;ANAC;CAA MALAYSIA;I			73-21-78		Package SB02	83628-73-003	IMPROVEMENTS TO THE RESOLVER	IN CONJUNCTION WITH MEDIUM	745	SR Technics Switzerland
61388	8061-532	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB03	83628-73-009	WIRE INSULATION SAFEGUARD IMPROVEMENTS	IN CONJUNCTION WITH MEDIUM	745	SR Technics Switzerland
61388	8061-533	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB05	73-EO-527943	HMU - PREVENTIVE BEARING REPLACEMENT	IN CONJUNCTION WITH MEDIUM	2,195	SR Technics Switzerland
61388	8061-534	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB07	83628-73-016_01	IMPROVED PRESSURIZING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH MEDIUM	2,195	SR Technics Switzerland
61388	8061-535	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB08	83628-73-021	IMPROVED SHUTOFF SWITCH MOUNTING	IN CONJUNCTION WITH MEDIUM	2,195	SR Technics Switzerland
61388	8061-536	EASA;FAA;CAAC;ANAC;CAA MALF			73-21-78		Package SB12	73-0122	USE OF CIS FUELS		6,685	SR Technics Switzerland
61388					73-21-78		Package SB14	EASA-2017-0065	OPERATIONAL LIMITATIONS		6,685	SR Technics Switzerland
61388					73-21-78		Package SB15	FAA-2013-14-06	CORROSION OF THE DELTA-P VALVE		6,685	SR Technics Switzerland
61388					73-21-78		Package SB18	8061-5 / 73-001	INTRODUCTION OF HYDROMECHANICAL UNIT VIN 8061-532 (P/N 1348M79P10)	IN CONJUNCTION WITH HEAVY/ OV	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-001	REWORK OF VALVE ASSEMBLIES TO ELIMINATE POTENTIAL TRAPPED FUEL CONI	IN CONJUNCTION WITH HEAVY/ OV	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-002	REPLACEMENT OF VESPEL BALL PIN 1419-240	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-003	IMPROVEMENTS TO THE RESOLVER	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-004	REPLACEMENT OF FMV, VSV, VBV, AND TCC VALVE CAPS TO ELIMINATE TRAPPE	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-005	USE OF FLUOROCARBON (VITON) PREFORMED PACKINGS IN HYDROMECHANICA	IN CONJUNCTION WITH HEAVY/ OV	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-006	INCORPORATION OF ANTI-ROTATION PUMP UNLOADING DESIGN	IN CONJUNCTION WITH LIGHT	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-010	IMPROVED PRESSURIZING AND DELTA P VALVES	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-011	IMPROVED OVERSPEED GOVERNOR SPEEDER SPRING ASSEMBLY	IN CONJUNCTION WITH LIGHT	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-012	REWORK OF HMU VIN 8061-534 (P/N 1348M79P12) TO HMU VIN 8061-535 (P/N	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-013	REWORK OF HMU VIN 8061-533 (P/N 1348M79P11) TO HMU VIN 8061-535 (P/N	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-014	IMPROVED FOUR-PORT PRESSURIZING AND DELTA P VALVES	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-015	USE OF FLUOROCARBON (VITON GLT-600S) PREFORMED PACKINGS IN HYDROM	IN CONJUNCTION WITH HEAVY/ OV	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-016	IMPROVED PRESSURIZING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-017	IMPROVED TORQUE MOTOR (CARBIDE TIP ASSEMBLY)	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-019	REPLACEMENT OF VSV/VBV PILOT VALVES ON SUSPECT LIST FOR PREMATURE W	IN CONJUNCTION WITH MEDIUM	545	SR Technics Switzerland
61388					73-21-78		Package SB19	73-0182	HMU - CIS FUEL MAINTENANCE REQUIREMENT	IN CONJUNCTION WITH MEDIUM	6,685	SR Technics Switzerland
62366	301-785-501-0	EASA;FAA;ANAC;CAA UK	12	21	73-11-13	FUEL PUMP	Package A	INSP	FLUORECENT PENETRANT INSPECTION		440	SR Technics Switzerland
62366	301-785-502-0	EASA;FAA;ANAC;CAA UK			73-11-13		Package B	TEST	BENCH TEST		2,355	SR Technics Switzerland
62366	301-785-503-0	EASA;FAA;ANAC;CAA UK			73-11-13		Package B	TEST	PRE TEST		2,355	SR Technics Switzerland
62366	301-785-504-0	EASA;FAA;CAA UK			73-11-13		Package E		REPAIR		5,455	SR Technics Switzerland
62366	301-785-505-0	EASA;FAA;CAA UK			73-11-13		Package G		OVERHAUL		10,100	SR Technics Switzerland
62366	714900-1	EASA;FAA;ANAC;CAA UK			73-11-13		Package SB00	IA 219071.01	IMPROVED FILTER COVER, D-BOLT & LOCK.NUT		500	SR Technics Switzerland
62366	714900-2	EASA;FAA;ANAC			73-11-13		Package SB01	714900-73-108	INTRODUCTION OF NEW FUEL PUMP WITH NEW FILTER COVER ATTACHMENT		500	SR Technics Switzerland
62366	714900-3	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-114	INTRODUCTION OF NEW PUMP GEARS		4,945	SR Technics Switzerland
62366	714900-4	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-115	INTRODUCTION OF NEW PUMP GEARS		4,945	SR Technics Switzerland
62366	714900-5	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-116	INTRODUCTION OF NEW PUMP GEARS		4,945	SR Technics Switzerland
62366					73-11-13		Package SB04	73-0111	WIRE INSULAT. SAFEGUARD IMPROVEMENTS		500	SR Technics Switzerland
62366					73-11-13		Package SB06	714900-73-112	INTRODUCTION OF NEW FUEL FILTER		4,945	SR Technics Switzerland
62366					73-11-13		Package SB07	828300-73-110	MFP - NEW RETAINING RING		4,945	SR Technics Switzerland
62366					73-11-13		Package SB09	714900-73-101	CONVERSION FROM BRONZE BEARINGS TO ALUMINUM/BRONZE BEARINGS		4,400	SR Technics Switzerland
62366					73-11-13		Package SB10	714900-73-104	INTRODUCTION OF NEW BEARING SEAL		4,400	SR Technics Switzerland
62366					73-11-13		Package SB11	714900-73-113	INTRODUCTION OF NEW FUEL FILTER		4,400	SR Technics Switzerland
62366					73-11-13		Package SB12	714900-73-111	FUEL AND CONTROL INTR.OF IMPR.SHAFT SEAL		500	SR Technics Switzerland
62366					73-11-13		Package SB13	AD 2006-26-01	REPLACING THE FUEL FILTERS ON ENGINE		500	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
72531	9523M11G03	EASA;FAA;CAAC;ANAC	13	28	72-31-09	CFM56 COMPRESSOR ROTOR BLADE RETAINERS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	405	SR Technics Switzerland
72531	9523M12G01	EASA;FAA;CAAC;ANAC			72-31-09		Package B	INSP-001	BLENDING		330	SR Technics Switzerland
73189	338-051-401-0	EASA;FAA;CAAC;ANAC	39	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION BOX PLATE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		550	SR Technics Switzerland
73189	338-051-410-0	EASA;FAA;CAAC;ANAC			72-23-21		Package B	001	REPLACE THE DEFECTIVE SELF-LOCKING INSERT ON THE JUNCTION PLATE ASSEM		950	SR Technics Switzerland
73189	338-051-411-0	EASA;FAA;CAAC;ANAC			72-23-21		Package E	004	REPLACEMENT OF THE RIVETED NUTS ON THE JUNCTION PLATE ASSEMBLY		545	SR Technics Switzerland
73189					72-23-21		Package U	020	REPLACEMENT OF THE DRY FILM LUBRICANT COATING ON THE JUCTION PLATE		3,070	SR Technics Switzerland
73189					72-23-21		Package X	023	REPLACEMENT OF BONDED SILICONE GASKET ON THE JUNCTION PLATE		2,805	SR Technics Switzerland
73190	338-020-703-0	EASA;FAA;CAAC;ANAC	51	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION BOX ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		550	SR Technics Switzerland
73190	338-020-704-0	EASA;FAA;CAAC;ANAC			72-23-21		Package C	002	REPLACEMENT OF CRIMPED SELF-LOCKING INSERT ON THE JUNCTION BOX		785	SR Technics Switzerland
73190	338-020-705-0	EASA;FAA;CAAC;ANAC			72-23-21		Package G	006	REPLACEMENT OF THE BONDED SILICONE ELASTOMER GASKETS ON THE TUBE B		625	SR Technics Switzerland
73190	338-020-706-0	EASA;FAA;CAAC;ANAC			72-23-21		Package N	013	REPLACEMENT OF LATERAL BRACKET PLATE ON THE JUNCTION BOX		1,585	SR Technics Switzerland
73190	338-020-707-0	EASA;FAA;CAAC;ANAC			72-23-21		Package O	014	REPAIR OF CRACKS ON BOX		1,590	SR Technics Switzerland
73190	338-020-708-0	EASA;FAA;CAAC;ANAC			72-23-21		Package P	15-81030	REPLACEMENT ELASTOMER G		730	SR Technics Switzerland
73190					72-23-21		Package SB00	72-0845	REPLACEMENT OF STIFFENER		390	SR Technics Switzerland
73190					72-23-21		Package Z	025	REPLACEMENT OF THE DEFECTIVE RIVETED NUTS		730	SR Technics Switzerland
73191	338-020-603-0	EASA;FAA;CAAC;ANAC;CAA UK	31	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION COVER ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		550	SR Technics Switzerland
73191	338-020-604-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-21		Package AN	015	REPAIR OF CRACKS ON COVER		735	SR Technics Switzerland
125452	215788	EASA;FAA;ANAC	21	21	73-11-14	FUEL PUMP - RING SEAL ROTATING	Package B	002	LAP ROTATING SEAL RING		735	SR Technics Switzerland
135024	238-0230-15	EASA;FAA;CAAC;ANAC	26	21	71-22-07	AFT ENGINE MOUNT - ASSY	Package C	CLN/INSP	PREINSPECTION OF AFT ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, N	2,650	SR Technics Switzerland
135024	238M0230-15	EASA;FAA;CAAC;ANAC			71-22-07		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAEXAMPLE: SHEAR PIN REPLACEMENT		1,095	SR Technics Switzerland
135024	642-2300-11	EASA;FAA;CAAC;ANAC;CAA UK			71-22-07		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAEXAMPLE: ONE LINK REPLACEMENT		1,560	SR Technics Switzerland
135024	642-2300-3	EASA;FAA;CAAC;ANAC			71-22-07		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAEXAMPLE: BEAM REPLACEMENT		2,825	SR Technics Switzerland
135024					71-22-07		Package G		OVERHAUL	DISASSEMBLY, CLEANING, INSPECTION, AS	3,130	SR Technics Switzerland
135024					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS	IN CONJUNCTION WITH PACKAGE HEAVY C	1,040	SR Technics Switzerland
135024					71-22-07		Package SB01	A320-RSA-CFM56-	AFT ENGINE MOUNT LINK NUT TORQUE CHECK	IN CONJUNCTION WITH PACKAGE LIGHT, N	1,245	SR Technics Switzerland
135024					71-22-07		Package SB02	216639	AFT MOUNT LINK, INSTALL NEW RET PLATE BOLTS	IN CONJUNCTION WITH PACKAGE LIGHT, N	730	SR Technics Switzerland
135024					71-22-07		Package SB03	RA32071-115	AFT ENGINE MOUNT NUTS LOOSENING	IN CONJUNCTION WITH PACKAGE LIGHT, N	1,245	SR Technics Switzerland
135024					71-22-07		Package SB05	RA32071-146	INSPECTION OF AFT ENGINE MOUNT RETAINER	N CONJUNCTION WITH PACKAGE LIGHT, M	1,095	SR Technics Switzerland
135024					71-22-07		Package SB06	RA32071-160	REPETITIVE INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LIGHT, M	1,145	SR Technics Switzerland
135024					71-22-07		Package SB07	RA32071-164	INTRODUCTION OF AN IMPROVED AFT ENGINE MOUNT RETAINER ASSEMBLY	N CONJUNCTION WITH PACKAGE LIGHT, M	810	SR Technics Switzerland
135024					71-22-07		Package SB08	RA32071-165	INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LIGHT, M	1,095	SR Technics Switzerland
135024					71-22-07		Package SB09	RA32071-160	REPETITIVE INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LIGHT, M	545	SR Technics Switzerland
135024					71-22-07		Package SB10	RA32071-164	INTRODUCTION OF AN IMPROVED AFT ENGINE MOUNT RETAINER ASSEMBLY	N CONJUNCTION WITH PACKAGE LIGHT, M	610	SR Technics Switzerland
135025	238-0401-501	EASA;FAA;CAAC;ANAC	30	35	78-11-05	EXHAUST - NOZZLE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	4,355	SR Technics Switzerland
135025	642-4001-501	EASA;FAA;CAAC;ANAC;EASA/ANAC			78-11-05		Package B	001	DISASSEMBLY/ASSEMBLY OF THE NOZZLE		9,610	SR Technics Switzerland
135025	642-4612-501	EASA;FAA;CAAC;ANAC			78-11-05		Package C	002	REPLACEMENT OF DAMAGED PYLON SEAL ASSEMBLY	ASSEMBLED CONDITION	2,890	SR Technics Switzerland
135025					78-11-05		Package D	003	NOZZLE SKIN REPAIR		9,480	SR Technics Switzerland
135025					78-11-05		Package K	010	PATCH REPAIR		9,990	SR Technics Switzerland
135025					78-11-05		Package L	011	EXHAUST NOZZLE WEAR PROTECTION	ASSEMBLED CONDITION	1,590	SR Technics Switzerland
135025					78-11-05		Package M	012	6 O'CLOCK EXTERNAL PATCH	ASSEMBLED CONDITION	3,925	SR Technics Switzerland
135131	1324M94P03	EASA;FAA;CAAC;ANAC	18	21	73-21-77	FUEL - HPTCC THERMOCOUPLE	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	965	SR Technics Switzerland
135131	8TC19AAH1	EASA;FAA;CAAC;ANAC			73-21-77		Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE REPAIR	165	SR Technics Switzerland
135147	642-2000-13	EASA;FAA;CAAC;ANAC;CAA UK	27	21	71-21-08	FWD ENGINE MOUNT - ASSY	Package A	CLN/INSP	PREINSPECTION OF FWD ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, N	2,865	SR Technics Switzerland
135147	642-2000-25	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package D		LIGHT	EXAMPLE: SHEAR PIN REPLACEMENT	980	SR Technics Switzerland
135147	642-2000-9	EASA;FAA;CAAC;ANAC			71-21-08		Package E		MEDIUM	EXAMPLE: CROSSBEAM ASSY REPLACEMENT	2,075	SR Technics Switzerland
135147	642M2000-501	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package F		HEAVY	EXAMPLE: BEAM ASSY REPLACEMENT	3,170	SR Technics Switzerland
135147	642M2000-503	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package G		OVERHAUL	DISASSEMBLY, CLEANING, INSPECTION, AS	4,400	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
135147					71-21-08		Package SB00		RA32071-159/EASA AD 2017-0132		360	SR Technics Switzerland
135174			4	21	71-2X-XX	CFM56-5B QEC BOX MISCELLANEOUS PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		835	SR Technics Switzerland
135174					71-2X-XX		Package B		OVERHAUL		1,075	SR Technics Switzerland
138950	1559M27G01	EASA;FAA;CAAC;ANAC	12	28	72-32-05	CFM-56 SEAL-STATIONARY ASSY STG 4-5	Package A		BASIC REPAIR	STG 4/5	120	SRTAS
138950	1559M27G02	EASA;FAA;CAAC;ANAC			72-32-05		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		120	SRTAS
138950	1559M27G06	EASA;FAA;CAAC;ANAC			72-32-05		Package B		FULL REPAIR	STG 4/5	465	SRTAS
138950					72-32-05		Package B	2	HONEYCOMB REPLACEMENT		465	SRTAS
138952	1559M27G03	EASA;FAA;CAAC;ANAC	12	28	72-33-03	CFM56 COMPR.REAR STAT.SEAL STG.6-8	Package A		BASIC REPAIR	STG 6	160	SRTAS
138952	1559M27G04	EASA;FAA;CAAC;ANAC			72-33-03		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		160	SRTAS
138952					72-33-03		Package B		FULL REPAIR	STG 6	410	SRTAS
138952					72-33-03		Package B	1	HONEYCOMB REPLACEMENT		410	SRTAS
138952					72-33-03		Package D		FULL REPAIR	STG 7	410	SRTAS
138952					72-33-03		Package D	1	HONEYCOMB REPLACEMENT		410	SRTAS
138952					72-33-03		Package F		FULL REPAIR	STG 8	410	SRTAS
138952					72-33-03		Package F	1	HONEYCOMB REPLACEMENT		410	SRTAS
138955	1275M27P04	EASA;FAA;CAAC;ANAC	18	28	72-42-02	COMBUSTION CHAMBER - PRIMARY SWIRL NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		65	SR Technics Switzerland
138955					72-42-02		Package C	02	PRIMARY SWIRL NOZZLE REPAIR		200	SR Technics Switzerland
138955					72-42-02		Package D	03	WELD ANTI-ROTATION TANG		140	SR Technics Switzerland
138977	9972M46G05	EASA;FAA;CAAC;ANAC	25	28	72-61-05	INLET GEARBOX & NO.3 BEARING - BEARING NO.3 LOCKING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,105	SR Technics Switzerland
138977					72-61-05		Package C	002	REPAIR OF DAMAGED WRENCH SLOTS		1,170	SR Technics Switzerland
138977					72-61-05		Package D	003	REPLACEMENT OF FIBER WASHER		1,190	SR Technics Switzerland
138977					72-61-05		Package E	004	REPAIR 004 - REPAIR OF 4.6875-12 OR 5.300-16 THREADS		950	SR Technics Switzerland
138977					72-61-05		Package F	005	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		845	SR Technics Switzerland
138977					72-61-05		Package G	006	REPAIR OF GALLING ON DIA B		1,960	SR Technics Switzerland
138977					72-61-05		Package H	007	MACHINING REPAIR OF DIAMETER C		1,510	SR Technics Switzerland
138999	5421-14	EASA;FAA;CAAC;ANAC	1	28	26-10-63	FIRE / OVERHEAT DETECTOR	Package B	TEST	PRE-TEST		230	SR Technics Switzerland
138999	5421-14-932/430-8	EASA;FAA;CAAC;ANAC			26-10-63		Package C	TEST	TESTING AND FAULT ISOLATION		815	SR Technics Switzerland
139018	305-145-401-0	EASA;FAA;CAAC;ANAC	19	28	72-63-11	ACCESSORY GEARBOX - HANDCRANKING DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		390	SR Technics Switzerland
139054	9992M86G07	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-32-20	COMPRESSOR FRONT STATOR - PLUG ASSY-BORESCOPE	Package A	CLN/INSP	CLEANING AND INSPECTION		400	SR Technics Switzerland
139054	9992M86G08	EASA;FAA;CAAC;ANAC;CAA UK			72-32-20		Package B	001	REPLACEMENT OF DAMAGED PARTS ON THE STAGE 6-8 BORESCOPE PLUG ASSE		605	SR Technics Switzerland
139334	1319M17P01	EASA;FAA;CAAC;ANAC	40	28	72-52-10	HIGH PRESSURE TURBINE ROTOR - REAR ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		665	SR Technics Switzerland
139334	1319M17P02	EASA;FAA;CAAC;ANAC			72-52-10		Package A	INSP-001	ROTATION SEAL SERRATIONS DEFFECT REMOVAL		665	SR Technics Switzerland
139334					72-52-10		Package C	001	REPLACEMENT OF SEAL TEETH COATING		4,635	SR Technics Switzerland
139334					72-52-10		Package D	003	THERMAL SPRAY REPAIR OF DIAMETER E		3,290	SR Technics Switzerland
139334					72-52-10		Package F	004	REPAIR OF ILLEGIBLE PART MARKINGS		375	SR Technics Switzerland
139334					72-52-10		Package SB00	72-0171	CONVERT FROM CFM56-5B/2 TO CFM56-5B/2P	ONLY FPI LINE B DIAMETER E	490	SR Technics Switzerland
139335	1360M70G01	EASA;FAA;CAAC;ANAC	25	28	72-61-01	INLET GEARBOX & NO.3 BEARING - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		590	SR Technics Switzerland
139335	1360M70G02	EASA;FAA;CAAC;ANAC			72-61-01		Package B	001	REPLACEMENT OF THE OIL NOZZLES AND PLUGS		1,360	SR Technics Switzerland
139335					72-61-01		Package C	002	REPLACEMENT OF DAMAGED STUDS		1,040	SR Technics Switzerland
139335					72-61-01		Package E	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR WEAR AND I SURFACE A		1,760	SR Technics Switzerland
139335					72-61-01		Package F	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR WEAR AND I DIAMETER C		3,705	SR Technics Switzerland
139335					72-61-01		Package H	007	REPAIR OF THE LOCATING HOLE AL		3,455	SR Technics Switzerland
139335					72-61-01		Package SB01	SB 72-1097	IGB BOLTED JOINT IMPROVEMENT AND REWORK		1,045	SR Technics Switzerland
139336	1361M13P01	EASA;FAA;CAAC;ANAC	28	28	72-61-04	INLET GEARBOX & NO.3 BEARING - ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		935	SR Technics Switzerland
139336					72-61-04		Package A	INSP-001	HAND LAP SEAL SURFACE D		935	SR Technics Switzerland
139336					72-61-04		Package B	001	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		1,355	SR Technics Switzerland
139339	1475M30G03	EASA;FAA;CAAC;ANAC	43	28	72-32-06	COMPRESSOR FRONT STATOR - SHROUD, INLET GUIDE VANES	Package A	CLN/INSP	CLEANING AND INSPECTION		840	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139339					72-32-06		Package B	001	REPLACEMENT OF THE ABRADABLE SEAL ON THE HPC FRONT STATOR IGV SHRO		3,635	SR Technics Switzerland
139339					72-32-06		Package C	002	TRUNNION HOLE WEAR REPAIR	SINGLE	3,255	SR Technics Switzerland
139339					72-32-06		Package D	INSP-001	REMOVE HIGH METAL		190	SR Technics Switzerland
139339					72-32-06		Package E	002	2ND TRUNNION HOLE WEAR REPAIR		2,965	SR Technics Switzerland
139339					72-32-06		Package G	002	TRUNNION HOLE WEAR REPAIR	ALL	6,180	SR Technics Switzerland
139339					72-32-06		Package SB00	72-0107	COMPRESSOR STATOR IGV SHROUD - REIDENTIFICATION		465	SR Technics Switzerland
139341	1498M40P03	EASA;FAA;CAAC;ANAC	41	28	72-52-04	HIGH PRESSURE TURBINE ROTOR - FRONT SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,560	SR Technics Switzerland
139341	1498M40P05	EASA;FAA;CAAC;ANAC			72-52-04		Package A	INSP	MEASUREMENT SHAFT CONCENTRICITY DIA B AND C	TECHNICAL INSTRUCTION	1,560	SR Technics Switzerland
139341	1498M40P06	EASA;FAA;CAAC;ANAC			72-52-04		Package B	INSP-001	REMOVE HIGH METAL		485	SR Technics Switzerland
139341	1873M73P01	EASA;FAA;CAAC;ANAC			72-52-04		Package D	002	THERMAL SPRAY RABBET REPAIR		4,575	SR Technics Switzerland
139341	2048M21P03	EASA;FAA;CAAC;ANAC;CAA UK			72-52-04		Package E	003	THERMAL SPRAY RABBET REPAIR		3,405	SR Technics Switzerland
139341					72-52-04		Package F	005	MACHINING REPAIR OF RIB CORNER FRETTING		1,225	SR Technics Switzerland
139341					72-52-04		Package SB00	72-0891	REPLACE FWD DAMPER SLEEVE		1,275	SR Technics Switzerland
139341					72-52-04		Package SB02	72-1125	REPAIR OF HPT INNER STATIONARY SEAL HONEYCOMB	PART 001	115	SR Technics Switzerland
139342	1498M43P04	EASA;FAA;CAAC;ANAC	62	28	72-52-02	HIGH PRESSURE TURBINE ROTOR - DISK	Package A	CLN/INSP	CLEANING AND INSPECTION	INCLUDED SPEC. PROC-001 - IMMERSION I	7,350	SR Technics Switzerland
139342	1498M43P05	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF BORE EDGE RADIUS		3,540	SR Technics Switzerland
139342	1498M43P06	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF WEB AND HUB FACES		3,540	SR Technics Switzerland
139342	1498M43P07	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF OD FWD AND AFT FACES		3,540	SR Technics Switzerland
139342	2410M49P01	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	REMOVAL OF HIGH METAL		3,540	SR Technics Switzerland
139342	2410M49P02	EASA;FAA;CAAC;ANAC;CAA UK			72-52-02		Package D	1	REPLACEMENT OF THE DISK CLINCH NUTS		3,575	SR Technics Switzerland
139342					72-52-02		Package F	5	THERMAL SPRAY REPAIR OF THE FORWARD FLANGE RABBET		3,560	SR Technics Switzerland
139342					72-52-02		Package G	INSP-002	BLENDING WEAR BLADE RETAINER		1,110	SR Technics Switzerland
139342					72-52-02		Package G	INSP-002	REMOVAL OF HIGH METAL		1,110	SR Technics Switzerland
139342					72-52-02		Package I	8	SHOTPEENING REPAIR OF SURFACE		950	SR Technics Switzerland
139342					72-52-02		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE EDDY CURRENT IN		4,255	SR Technics Switzerland
139342					72-52-02		Package SB01	72-0223	HPT ROTOR DISK REWORK FROM 1498M43P04 TO 1498M43P05		1,045	SR Technics Switzerland
139342					72-52-02		Package SB02	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CFM56-5B2 AND CFM56-5B6/2 TO CFM56-5B6/2P , CF		980	SR Technics Switzerland
139342					72-52-02		Package SB03	72-1072	REPLACEMENT OF SUSPECT HPT ROTOR DISK	PN 1498M43P05	525	SR Technics Switzerland
139342					72-52-02		Package SB04	72-1125	REPAIR OF HPT INNER STATIONARY SEAL HONEYCOMB	PART 001	115	SR Technics Switzerland
139349	1523M35P01	EASA;FAA;CAAC;ANAC;CAA UK	36	28	72-31-08	COMPRESSOR ROTOR - REAR ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1,540	SR Technics Switzerland
139349	2116M25P01	EASA;FAA;CAAC;ANAC;CAA UK			72-31-08		Package B	INSP-001	REMOVAL OF HIGH METAL BY BLENDING		1,255	SR Technics Switzerland
139349					72-31-08		Package C	001	REPAIR OF THE SEAL TEETH COATING		4,415	SR Technics Switzerland
139349					72-31-08		Package D	003	REPAIR THE FORWARD AND AFT RABBET	DIAMETER B+C	4,180	SR Technics Switzerland
139349					72-31-08		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	715	SR Technics Switzerland
139350	1523M37P01	EASA;FAA;CAAC;ANAC	40	28	72-41-05	COMBUSTION CASE - HPT NOZZLE SUPPORT BOLT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		865	SR Technics Switzerland
139350	1523M37P02	EASA;FAA;CAAC;ANAC			72-41-05		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		2,185	SR Technics Switzerland
139350					72-41-05		Package SB01	72-0575	REWORK OF THE BOLT SHIELD OUTSIDE DIAMETER		955	SR Technics Switzerland
139353	1523M43P01	EASA;FAA;CAAC;ANAC	33	28	72-51-11	HIGH PRESSURE TURBINE NOZZLE - SUPPORT NUT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	580	SR Technics Switzerland
139353	2071M15P01	EASA;FAA;CAAC;ANAC			72-51-11		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		4,440	SR Technics Switzerland
139353					72-51-11		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CFM56-5B2 AND CFM56-5B6/2 TO CFM56-5B6/2P , CF		260	SR Technics Switzerland
139354	1523M59G01	EASA;FAA;CAAC;ANAC	31	28	72-53-04	HPT SHROUD - SUPPORT HANGER	Package A		BASIC REPAIR		260	SRTAS
139354	1523M59G05	EASA;FAA;CAAC;ANAC			72-53-04		Package A	INSP-001	INSPECTION/CHECK		260	SRTAS
139354	1808M61G01	EASA;FAA;CAAC;ANAC			72-53-04		Package B		FULL REPAIR (Pre SB 72-0909/0962)		2,080	SRTAS
139354	1808M61G02	EASA;FAA;CAAC;ANAC			72-53-04		Package B	008	STRAIGHT PIN REPLACEMENT		2,080	SRTAS
139354	1808M61G04	EASA;FAA;CAAC;ANAC			72-53-04		Package B	009	PIN HOLE AND AXIAL CRACKS ON FORWARD INNER RAIL WELD REPAIR		2,080	SRTAS
139354	1808M61G05	EASA;FAA;CAAC;ANAC			72-53-04		Package B	013	SEAL SLOT BREAKOUT WELD REPAIR		2,080	SRTAS
139354	1808M61G06	EASA;FAA;CAAC;ANAC			72-53-04		Package B	014	REPAIR USING RBD	ALTERNATIVE TO REPAIRS 002, 003, 005, 0	2,080	SRTAS

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139354	1808M61G07	EASA;FAA;CAAC;ANAC			72-53-04		Package B	015	AFT RAIL WELD REPAIR		2,080	SRTAS
139354	1808M61G08	EASA;FAA;CAAC;ANAC			72-53-04		Package B	016	FORM REPAIR (CHECK SHAPE & TRUE UP)		2,080	SRTAS
139354	1808M61G09	EASA;FAA;CAAC;ANAC			72-53-04		Package B	018	AFT RAIL WELD REPAIR		2,080	SRTAS
139354	1808M61G10	EASA;FAA;CAAC;ANAC			72-53-04		Package B	INSP-001	INSPECTION/CHECK		2,080	SRTAS
139354	1808M61G11	EASA;FAA;CAAC;ANAC			72-53-04		Package C		FULL REPAIR (Post SB 72-0909/0962)		4,375	SRTAS
139354	1808M61G12	EASA;FAA;CAAC;ANAC			72-53-04		Package C	022	FULL REPAIR OF THE RENE 77 MATERIAL SHROUD HANGER	FOR 1808M61G12, 1808M61G13, 1893M4	4,375	SRTAS
139354	1893M42G01	EASA;FAA;CAAC;ANAC			72-53-04		Package D		ADDITIONAL WORKSCOPE		565	SRTAS
139354	1893M42G02	EASA;FAA;CAAC;ANAC			72-53-04		Package D	017	BRAZE REPAIR FOR WEAR ON HANGER RAILS		565	SRTAS
139354	1893M42G03	EASA;FAA;CAAC;ANAC			72-53-04		Package E		ADDITIONAL WORKSCOPE	(WITH FULL REPAIR WORKSCOPE)	815	SRTAS
139354	1893M42G04	EASA;FAA;CAAC;ANAC			72-53-04		Package E	72-0194	ENLARGE COOLING HOLES, INCREASE FORWARD LIP HEIGHT AND ALTER PIN POS 5B		815	SRTAS
139354	1957M74G01	EASA;FAA;CAAC;ANAC			72-53-04		Package E	72-0217	ENLARGE COOLING HOLES, INCREASE FORWARD LIP HEIGHT AND ALTER PIN POS 5B		815	SRTAS
139354	1957M74G02	EASA;FAA;CAAC;ANAC			72-53-04		Package F		ADDITIONAL WORKSCOPE	(WITH ANY OF THE PACKAGED WORKSCOPE)	935	SRTAS
139354	1957M86G01	EASA;FAA;CAAC;ANAC			72-53-04		Package F	72-0909	REWORK TO ADD AIR FILTER	5B	935	SRTAS
139354					72-53-04		Package I		ADDITIONAL WORKSCOPE		1,090	SRTAS
139354					72-53-04		Package I	021	WELD OF THE PIN HOLE AND AXIAL AND RADIAL CRACK		1,090	SRTAS
139354					72-53-04		Package J		ADDITIONAL WORKSCOPE		800	SRTAS
139354					72-53-04		Package J	022	RESTORATION OF FORWARD INNER RAIL THICKNESS BY WELDING	PARTIAL REPAIR 022	800	SRTAS
139381	301-475-207-6	EASA;FAA;CAAC;ANAC	36	28	72-22-14	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING OIL BAFFLE	Package A	CLN/INSP	CLEANING AND INSPECTION		625	SR Technics Switzerland
139381					72-22-14		Package B	002	RESTORATION OF THE SHIMMING FUNCTION		4,695	SR Technics Switzerland
139381					72-22-14		Package C	ASSEMBLY-001	BAFFLE THICKNESS GRINDING		900	SR Technics Switzerland
139382	301-539-211-0	EASA;FAA;CAAC;ANAC	36	28	72-22-03	NO.1 AND NO.2 BEARING SUPPORT - NO. 2 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	915	SR Technics Switzerland
139382					72-22-03		Package B	001	REPLACE OF THE SWAGED SELF-LOCKING INSERTS		635	SR Technics Switzerland
139388	305-135-904-0	EASA;FAA;CAAC;ANAC;CAA UK	44	28	72-63-01	ACCESSORY GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1,425	SR Technics Switzerland
139388	305-135-905-0	EASA;FAA;CAAC;ANAC			72-63-01		Package C	002	REPLACEMENT OF THE KEY-LOCKED STUDS		1,155	SR Technics Switzerland
139388	340-046-602-0	EASA;FAA;CAAC;ANAC			72-63-01		Package D	003	REPLACEMENT OF THE KEY-LOCKED SELF-LOCKING INSERTS		1,005	SR Technics Switzerland
139388	340-046-603-0	EASA;FAA;CAAC;ANAC			72-63-01		Package F	006	REPLACEMENT OF THE RING-LOCKED INSERTS		990	SR Technics Switzerland
139388	340-046-604-0	EASA;FAA;CAAC;ANAC			72-63-01		Package G	005	BUSHING HANDCRANKING LINE DI		3,325	SR Technics Switzerland
139388	340-046-605-0	EASA;FAA;CAAC;ANAC			72-63-01		Package H	007	REPLACEMENT OF THE AXIAL OIL NOZZLES		1,690	SR Technics Switzerland
139388					72-63-01		Package I	008	SPOT TOUCH-UP OF THE NON-MACHINED SURFACES BY OXIDE FILM COATING		530	SR Technics Switzerland
139388					72-63-01		Package N	013	MACHINING OF BEARING SEATING SURFACES		10,510	SR Technics Switzerland
139388					72-63-01		Package O	014	BLEND REPAIR OF MOUNT CLEVIS		595	SR Technics Switzerland
139388					72-63-01		Package P	015	BLENDING HAND CRANKING LOCATION		390	SR Technics Switzerland
139389	305-136-503-0	EASA;FAA;CAAC;ANAC	34	28	72-62-01	TRANSFER GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1,175	SR Technics Switzerland
139389	335-300-403-0	EASA;FAA;CAAC;ANAC;CAA UK			72-62-01		Package AB	007	REPAIR OF DIAMETERS D ON THE TGB HOUSING BY PLASMA SPRAYING		2,270	SR Technics Switzerland
139389	338-089-601-0	EASA;FAA;CAAC;ANAC;CAA UK			72-62-01		Package B	001	REPLACEMENT OF THE SELF-LOCKING INSERTS		860	SR Technics Switzerland
139389	340-050-704-0	EASA;FAA;CAAC;ANAC			72-62-01		Package C	002	REPLACEMENT OF THE KEY-LOCKED STUDS		965	SR Technics Switzerland
139389	340-050-705-0	EASA;FAA;CAAC;ANAC			72-62-01		Package D	003	REPLACEMENT OF THE HEADLESS SHOULDER PINS		965	SR Technics Switzerland
139389					72-62-01		Package E	004	REPLACEMENT OF THE RING-LOCKED INSERTS		965	SR Technics Switzerland
139389					72-62-01		Package F	005	SPOT TOUCHUP OF THE NON-MACHINED SURFACES BY OXIDE FILM COATING		965	SR Technics Switzerland
139389					72-62-01		Package I	008	REPAIR OF SURFACES R ON THE TGB HOUSING BY PLASMA SPRAYING		2,510	SR Technics Switzerland
139389					72-62-01		Package K	010	ID PLATE NAILS		895	SR Technics Switzerland
139389					72-62-01		Package L	011	REPAIR OF MACHINED SURFACES BY PLASMA SPRAYING		1,270	SR Technics Switzerland
139389					72-62-01		Package N	013	BUSHING DIAMETER M OF TGB HOUSING		1,850	SR Technics Switzerland
139389					72-62-01		Package R	007	REPAIR OF DIAMETERS C ON THE TGB HOUSING BY PLASMA SPRAYING		2,270	SR Technics Switzerland
139389					72-62-01		Package S	008	REPAIR OF SURFACES S ON THE TGB HOUSING BY PLASMA SPRAYING		2,510	SR Technics Switzerland
139389					72-62-01		Package SB00	72-0924	MARKING OF TGB ASSEMBLIES ON A SPECIFIC POPULATION OF ENGINES		310	SR Technics Switzerland
139400	305-138-602-0	EASA;FAA;CAAC;ANAC	20	28	72-63-17	ACCESSORY GEARBOX - HORIZONTAL DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,300	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139422	305-148-801-0	EASA;FAA;CAAC;ANAC	25	28	72-62-04	TRANSFER GEARBOX - HOUSING ASSY-HORIZONTAL BEVEL	Package A	CLN/INSP	CLEANING AND INSPECTION		370	SR Technics Switzerland
139422	335-305-000-0	EASA;FAA;CAAC;ANAC			72-62-04		Package B	001	REPLACEMENT OF KEY-LOCKED INSERTS		1,570	SR Technics Switzerland
139422	335-305-600-0	EASA;CAAC;EASA/ANAC BRAZIL D			72-62-04		Package C	002	REPLACEMENT OF JACKSCREW INSERTS		675	SR Technics Switzerland
139422					72-62-04		Package D	003	SPOT TOUCHUP OF NON-MACHINED SURFACES BY OXIDE FILM COATING		715	SR Technics Switzerland
139422					72-62-04		Package E	004	REPLACEMENT OF FLANGED BUSHINGS		770	SR Technics Switzerland
139422					72-62-04		Package F	005	REPLACEMENT OF FLANGED CENTERING BUSHINGS		680	SR Technics Switzerland
139422					72-62-04		Package G	006	MACHINING OF BEARING SEATING SURFACES		1,135	SR Technics Switzerland
139422					72-62-04		Package H	007	MACHINING FLANGE		860	SR Technics Switzerland
139429	305-396-303-0	EASA;FAA;CAAC;ANAC	37	28	72-22-05	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT ROTOR AIR/OIL SEPARA	Package A	CLN/INSP	CLEANING AND INSPECTION		400	SR Technics Switzerland
139429					72-22-05		Package B	001	RECONDITIONING THE RABBET DIAMETER WITH THE FAN SHAFT BY THERMAL SI		2,890	SR Technics Switzerland
139430	305-408-301-0	EASA;FAA;CAAC;ANAC	47	21	72-55-10	LOW PRESSURE TURBINE SHAFT - CENTER VENT TUBE REAR EXTENSION	Package A	CLN/INSP	CLEANING AND INSPECTION		780	SR Technics Switzerland
139430	338-180-101-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-10		Package A	INSP-001	REMOVAL OF HIGH METAL/DAMAGED THREADST		780	SR Technics Switzerland
139430	338-180-401-0	EASA;FAA;CAAC;ANAC			72-55-10		Package B	001	REPLACEMENT OF ONE OR SEVERAL LOCATING PIN		1,040	SR Technics Switzerland
139430	340-170-401-0	EASA;FAA;CAAC;ANAC			72-55-10		Package C	002	REPAIR OF THE SLOTS BY WELD BUILDUP		3,305	SR Technics Switzerland
139430	340-170-402-0	EASA;FAA;CAAC;ANAC			72-55-10		Package D	004	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4,980	SR Technics Switzerland
139430					72-55-10		Package I	008	RESHAPING SEAL TEETH		1,145	SR Technics Switzerland
139432	336-001-804-0	EASA;FAA;CAAC;ANAC;CAA UK	53	28	72-54-03	LOW PRESSURE TURBINE - DISKS, STG 1-4	Package A	CLN/INSP	CLEANING AND INSPECTION		1,240	SR Technics Switzerland
139432	336-001-909-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package B	INSP 001	BLENDING SURFACE		3,385	SR Technics Switzerland
139432	336-002-006-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package C	INSP	INSPECTION OF THE DISKS (AFTER OVERTEMPERATURE AND/OR OVERSPEED) FC HARDNESS AND GROWTH CHECK		700	SR Technics Switzerland
139432	336-002-105-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package D	INSP 001	REMOVE HIGHMETAL ON WEB		1,800	SR Technics Switzerland
139432	337-001-404-0	EASA;FAA;CAAC;ANAC			72-54-03		Package F	001	REPAIR OF STAGE 1 LPT DISKS FORWARD FLANGE BY MACHINIG		4,350	SR Technics Switzerland
139432	337-001-605-0	EASA;FAA;CAAC;ANAC			72-54-03		Package G	001	REPAIR OF STAGE 2 LPT DISKS FORWARD FLANGE BY MACHINIG		5,670	SR Technics Switzerland
139432	337-001-705-0	EASA;FAA;CAAC;ANAC			72-54-03		Package J	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 1	2,075	SR Technics Switzerland
139432	337-001-802-0	EASA;FAA;CAAC;ANAC			72-54-03		Package K	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 2	2,075	SR Technics Switzerland
139432	340-301-001-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package L	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 3	2,075	SR Technics Switzerland
139432	340-301-101-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package M	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 4	2,075	SR Technics Switzerland
139432	340-301-201-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package O	005	MACHINING OF MARKS ON FLANGES STG.1		8,930	SR Technics Switzerland
139432	340-301-301-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package P	005	MACHINING OF MARKS ON FLANGES STG.2		8,930	SR Technics Switzerland
139432					72-54-03		Package Q	005	MACHINING OF MARKS ON FLANGES STG.3		8,930	SR Technics Switzerland
139432					72-54-03		Package R	005	MACHINING OF MARKS ON FLANGES STG.4		8,930	SR Technics Switzerland
139432					72-54-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG1	IN CONJUNCTION WITH PACKAGE A	505	SR Technics Switzerland
139432					72-54-03		Package SB01	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG2	IN CONJUNCTION WITH PACKAGE A	505	SR Technics Switzerland
139432					72-54-03		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG3	IN CONJUNCTION WITH PACKAGE A	505	SR Technics Switzerland
139432					72-54-03		Package SB03	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG4	IN CONJUNCTION WITH PACKAGE A	505	SR Technics Switzerland
139432					72-54-03		Package SB04	72-EO-521902	WORKSCOPE LPT OVERTEMP ANALYSE		145	SR Technics Switzerland
139432					72-54-03		Package SB05	72-0171	CONVERSION CFM56 ENG MODEL 5B1/2 TO 5B1/2P, 5B2/2 TO 5B2/2P, 5B4/2 TC		375	SR Technics Switzerland
139432					72-54-03		Package T	006	RECONDITIONING BY PLASMA SPRAYING OF THE LPT ROTATING AIR SEAL LOCAT STAGE 3		8,930	SR Technics Switzerland
139443	336-013-101-0	EASA;FAA;CAAC;ANAC	27	28	72-54-17	LOW PRESSURE TURBINE - SEAL-ROTATING OIL FORWARD	Package A	CLN/INSP	CLEANING AND INSPECTION		925	SR Technics Switzerland
139443					72-54-17		Package B	001	REPAIR OF THE ALUMINUM-SILICIUM-POLYESTER ABRADABLE COATING		2,825	SR Technics Switzerland
139443					72-54-17		Package C	002	LOCATING DIAMETER		2,840	SR Technics Switzerland
139488	2423M30G01	EASA;FAA;CAAC;ANAC;CAA UK	35	28	72-23-30	FAN FRAME ASSEMBLY - DOWNSTREAM FAN CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		5,455	SR Technics Switzerland
139488	2752M00G01	EASA;FAA;CAAC;ANAC			72-23-30		Package B	001	REPLACE THE HI-LITE BOLTS AND NUTS ON THE DOWNSTREAM FAN CASE ASSEN		775	SR Technics Switzerland
139488	2752M00G02	EASA;FAA;CAAC;ANAC			72-23-30		Package C	002	REPLACEMENT OF THE SWAGED SELF-LOCKING INSERTS		925	SR Technics Switzerland
139488	2752M00G03	EASA;FAA;CAAC;ANAC			72-23-30		Package E	004	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		730	SR Technics Switzerland
139488	2752M00G04	EASA;FAA;CAAC;ANAC			72-23-30		Package I	008	REPLACEMENT OF THE RIVETED SELF-LOCKING NUTS		1,135	SR Technics Switzerland
139488	2752M00G05	EASA;FAA;CAAC;ANAC			72-23-30		Package K	010	BLEND REPAIR FOR CORROSION, NICKS, AND SCRATCHES		790	SR Technics Switzerland
139488	2752M00G06	EASA;FAA;CAAC;ANAC			72-23-30		Package L	011	CORROSION REPAIR OF THE AFT FLANGE BOLT HOLES		5,425	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139488	2752M00G07	EASA;FAA;CAAC;ANAC			72-23-30		Package M	012	CORROSION REPAIR OF THE FORWARD FLANGE BOLT HOLES		3,435	SR Technics Switzerland
139488	2752M00G08	EASA;FAA;CAAC;ANAC			72-23-30		Package N	013	CORROSION REPAIR ON OUTER SURFACE OF FLANGES	B4,B6	9,695	SR Technics Switzerland
139488	2752M00G09	EASA;FAA;CAAC;ANAC			72-23-30		Package O	014	BOLTHOLES REAM/BUSHING REPAIR		4,995	SR Technics Switzerland
139488	338-075-617-0	EASA;FAA;CAAC;ANAC			72-23-30		Package P	015	BLEND REPAIR OF THE OUTER DIA./FACES OF MID FLANGE	B5	1,405	SR Technics Switzerland
139488	338-075-620-0	EASA;FAA;CAAC;ANAC			72-23-30		Package Q	047	MODULE LEVEL BLENDING		3,630	SR Technics Switzerland
139488	338-075-621-0	EASA;FAA;CAAC;ANAC			72-23-30		Package R	016	BLEND REPAIR OF THE OUTER DIA./FACES OF MID FLANGE	B4	1,560	SR Technics Switzerland
139488	338-075-622-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-30		Package S	048	MODULE LEVEL BOLTHOLE REPAIR		2,840	SR Technics Switzerland
139488	338-075-625-0	EASA;FAA;CAAC;ANAC			72-23-30		Package SB00	72-0629	REWORK OF THE DOWNSTREAM FAN CASE HOLES 95 AND 96 OF THE FLANGE B4		520	SR Technics Switzerland
139488	338-075-626-0	EASA;FAA;CAAC;ANAC			72-23-30		Package SB01	72-1063	INSTALL REINFORCEMENT RING ON FLANGE B5		3,765	SR Technics Switzerland
139488	338-075-627-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-30		Package T	051	B4/B6 FLANGE INNER SURFACE BLEND	72-00-23	1,245	SR Technics Switzerland
139488	338-075-628-0	EASA;FAA;CAAC;ANAC			72-23-30		Package U	020	BUSHING REPAIR OF THE ELONGATED BOLTHOLES ON THE B5 FLANGE		2,810	SR Technics Switzerland
139488					72-23-30		Package V	019	BOSS END FITTING REPLACEMENT	PPR LEVEL	850	SR Technics Switzerland
139488					72-23-30		Package W	019	BOSS END FITTING REPLACEMENT	MODUL LEVEL	1,700	SR Technics Switzerland
139505	338-086-601-0	EASA;FAA;CAAC;ANAC	20	28	72-56-10	LOW PRESSURE TURBINE REAR FRAME - AIR HEATER COVER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	935	SR Technics Switzerland
139505					72-56-10		Package B	001	REPLACE THE DEFECTIVE CRIMPED SELF-LOCKING NUTS ON THE AIR HEATER COVER		1,185	SR Technics Switzerland
139515	9542M67P01	EASA;FAA;CAAC;ANAC;CAA UK	20	28	72-61-02	INLET GEARBOX & NO.3 BEARING - GEAR-BEVEL HORIZONTAL 47 TOOTH	Package A	CLN/INSP	CLEANING AND INSPECTION		1,190	SR Technics Switzerland
139515					72-61-02		Package B	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA E	3,225	SR Technics Switzerland
139515					72-61-02		Package C	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA F	3,225	SR Technics Switzerland
139515					72-61-02		Package D	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA G	3,225	SR Technics Switzerland
139515					72-61-02		Package E	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA J	3,225	SR Technics Switzerland
139515					72-61-02		Package F	002	REPAIR OF THE LOCKING PIN HOLES	DIA H	1,155	SR Technics Switzerland
139517	9972M31G03	EASA;FAA;CAAC;ANAC	27	28	72-61-03	INLET GEARBOX & NO.3 BEARING - RADIAL BEVEL GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		875	SR Technics Switzerland
139517					72-61-03		Package B	001	REPLACEMENT OF OIL SEAL		1,385	SR Technics Switzerland
139520	9972M49G02	EASA;FAA;CAAC;ANAC;CAA UK	27	28	72-61-07	INLET GEARBOX & NO.3 BEARING - PULLER RING	Package A	CLN/INSP	CLEANING AND INSPECTION		1,115	SR Technics Switzerland
139520					72-61-07		Package B	001	REPLACEMENT OF FIBER WASHER		1,190	SR Technics Switzerland
139530	238-0210-505	EASA;FAA;CAAC;ANAC	29	21	71-21-08	FWD ENGINE MOUNT - LINK ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1,520	SR Technics Switzerland
139530	238-0210-507	EASA;FAA;CAAC;ANAC			71-21-08		Package D	003	REPLACE BEARING IN FORWARD ENGINE MOUNT LINK ASSEMBLY		1,560	SR Technics Switzerland
139530	238-0210-509	EASA;FAA;CAAC;ANAC			71-21-08		Package E	004	BLEND REPAIR FOR MINOR DAMAGE - FORWARD MOUNT THRUST LINKS		855	SR Technics Switzerland
139530					71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR		170	SR Technics Switzerland
139531	642-2002-503	EASA;FAA;CAAC;ANAC;CAA UK	31	21	71-21-08	FWD ENGINE MOUNT - CROSSBEAM ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1,275	SR Technics Switzerland
139531					71-21-08		Package O	014	BLEND REPAIR FOR MINOR DAMAGE-FORWARD ENGINE MOUNT CROSSBEAM		855	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	CENTER BUSHING	2,120	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	LEFT LUG BUSHING	2,120	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	RIGHT LUG BUSHING	2,120	SR Technics Switzerland
139531					71-21-08		Package R	017	FORWARD ENGINE MOUNT CROSSBEAM INNER CENTER SURFACE WEAR DAMAGE		2,405	SR Technics Switzerland
139532	642-2006-501	EASA;FAA;CAAC;ANAC	36	21	71-21-08	FWD ENGINE MOUNT - BEAM ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1,315	SR Technics Switzerland
139532	642-2006-503	EASA;FAA;CAAC;ANAC			71-21-08		Package B	ASSEMBLY-1	REPLACEMENT OF FASTENER SETS ON FWD BEAM		565	SR Technics Switzerland
139532	642M2000-1	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR		390	SR Technics Switzerland
139532					71-21-08		Package K	010	BLEND OF SNOOT DIAMETER - FORWARD ENGINE MOUNT BEAM		1,210	SR Technics Switzerland
139532					71-21-08		Package L	011	REPLACE AFT BUSHING IN FORWARD MAIN BEAM		1,950	SR Technics Switzerland
139532					71-21-08		Package N	013	BLEND OF SURFACE DAMAGE ON FORWARD ENGINE MOUNT BEAM		840	SR Technics Switzerland
139532					71-21-08		Package SB00	RA 32071-159	BEAM SNOOT INSP. AND REWORK		1,430	SR Technics Switzerland
139535	238-0234-505	EASA;FAA;CAAC;ANAC	31	21	71-22-07	AFT ENGINE MOUNT - LINK ASSEMBLY	Package A	ASSEMBLY-1	REPLACEMENT OF LINK ASSEMBLY FASTENERS		1,395	SR Technics Switzerland
139535	238-0234-507	EASA;FAA;CAAC;ANAC			71-22-07		Package A	CLN/INSP	CLEANING AND INSPECTION		1,395	SR Technics Switzerland
139535	642-2302-501	EASA;FAA;CAAC;ANAC			71-22-07		Package C	002	REPLACE BEARING IN AFT ENGINE MOUNT LINK ASSEMBLY		1,270	SR Technics Switzerland
139535	642-2302-503	EASA;FAA;CAAC;ANAC;CAA UK			71-22-07		Package D	003	REPLACE BUSHINGS IN LINK ASSEMBLY		730	SR Technics Switzerland
139535					71-22-07		Package F	005	BLEND REPAIR FOR MINOR DAMAGE - AFT MOUNT LINKS		415	SR Technics Switzerland

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

**Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply**



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139535					71-22-07		Package G	006	PART NUMBER AND SERIAL NUMBER REPAIR		390	SR Technics Switzerland
139535					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS	LINK ASSEMBLY	1,365	SR Technics Switzerland
139536	238-0231-505	EASA;FAA;CAAC;ANAC	30	21	71-22-07	AFT ENGINE MOUNT - BEAM	Package A	ASSMENBLY-1	REPLACEMENT OF BEAM ASSEMBLY FASTENERS		1,275	SR Technics Switzerland
139536	642-2301-501	EASA;FAA;CAAC;ANAC			71-22-07		Package A	CLN/INSP	CLEANING AND INSPECTION		1,275	SR Technics Switzerland
139536					71-22-07		Package B	001	REPLACE 1 EA BEARINGS IN AFT ENGINE MOUNT BEAM		1,990	SR Technics Switzerland
139536					71-22-07		Package C	001	REPLACE 2 EA BEARINGS IN AFT ENGINE MOUNT BEAM		4,100	SR Technics Switzerland
139536					71-22-07		Package D	001	REPLACE 3 EA BEARINGS IN AFT ENGINE MOUNT BEAM		5,510	SR Technics Switzerland
139536					71-22-07		Package E	004	BLEND REPAIR FOR MINOR DAMAGE - AFT BEAM		730	SR Technics Switzerland
139536					71-22-07		Package G	006	PART NUMBER AND SERIAL NUMBER REPAIR		375	SR Technics Switzerland
139536					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS		1,365	SR Technics Switzerland
139541	1588M89G02	EASA;FAA;CAAC;ANAC	54	28	72-31-06	COMPRESSOR ROTOR - SPOOL STG 4-9	Package A	CLN/INSP	CLEANING AND INSPECTION		2,795	SR Technics Switzerland
139541	1588M89G03	EASA;FAA;CAAC;ANAC			72-31-06		Package B	INSP-001	BLEND BORES STG. 4-9		1,685	SR Technics Switzerland
139541	2048M20G03	EASA;FAA;CAAC;ANAC			72-31-06		Package B	INSP-001	REMOVE HIGH METAL		1,685	SR Technics Switzerland
139541	2048M20G04	EASA;FAA;CAAC;ANAC;CAA UK			72-31-06		Package C	INSP-001	BLEND PLATFORM RAIL OUTER DIA.		1,740	SR Technics Switzerland
139541	2048M20G05	EASA;FAA;CAAC;ANAC;CAA UK			72-31-06		Package D	INSP-001	BLEND FWD SIDE PLATFORM STG 4		1,355	SR Technics Switzerland
139541					72-31-06		Package E	001	REPAIR OF THE SEAL TEETH COATINGS		7,975	SR Technics Switzerland
139541					72-31-06		Package F	002	REPAIR OF ILLEGIBLE PART MARKINGS		200	SR Technics Switzerland
139541					72-31-06		Package G	003	REPAIR OF THE FORWARD AND AFT RABBET DIAMETERS		4,365	SR Technics Switzerland
139541					72-31-06		Package H	004	BLEND REPAIR OF BLADE PLATFORM RAILS		2,045	SR Technics Switzerland
139541					72-31-06		Package I	006	REPAIR OF THE FORWARD AND AFT RABBET DIAMETERS		5,805	SR Technics Switzerland
139541					72-31-06		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1,965	SR Technics Switzerland
139576	2423M70G01	EASA;FAA;CAAC;ANAC;CAA UK	37	28	72-23-04	FAN FRAME ASSEMBLY - OUTLET GUIDE VANE INNER SHROUD ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		935	SR Technics Switzerland
139576	338-007-203-0	EASA;FAA;CAAC;ANAC			72-23-04		Package B	001	TOUCH UP OR TOTAL REPAIR OF SULFURIC ANODIZING		925	SR Technics Switzerland
139576	338-007-205-0	EASA;FAA;CAAC;ANAC			72-23-04		Package C	002	REPLACEMENT OF THE RIVETED SELF-LOCKING NUTS		915	SR Technics Switzerland
139576	340-002-408-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-04		Package E	004	CENTRAL RIVET HOLES ON FWD DIAMETER		720	SR Technics Switzerland
139576					72-23-04		Package P	015-94525	HOLES STRUT NR.5 AND NR.6 CASE A		1,470	SR Technics Switzerland
139966	338-077-904-0	EASA;FAA;CAAC;ANAC	33	28	72-23-01	FAN FRAME ASSEMBLY - FAN FRAME	Package A	CLN/INSP	CLEANING AND INSPECTION		3,885	SR Technics Switzerland
139966	338-077-905-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AG	032	REPLACEMENT OF CRIMPED SELF-LOCKING NUTS		895	SR Technics Switzerland
139966	338-077-907-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AH	043	REPLACE OF RIVETS/FAIRING ON THE STRUTS		2,140	SR Technics Switzerland
139966	338-077-910-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AL	70-43-31	REMOVAL OF ATTACHED PARTS		400	SR Technics Switzerland
139966	338-077-911-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AM	70-41-14	REMOVAL OF BROKEN BOLTS		590	SR Technics Switzerland
139966	338-077-912-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AN	046	BLEND GROUND HANDLING PORTS		400	SR Technics Switzerland
139966	338-077-913-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-01		Package C	002	REPLACE THE RING-LOCKED STUDS		1,280	SR Technics Switzerland
139966	338-077-914-0	EASA;FAA;CAAC;ANAC			72-23-01		Package D	003	REPLACEMENT OF SWAGED SELF-LOCKING INSERTS		745	SR Technics Switzerland
139966					72-23-01		Package SB00	72-0285	REWORK OF FAN FRAME WELDMENT TO INSTALL THE COMPOSITE BO.3 BEARING ON ENGINE WITH NO RACC SYSTEM		1,040	SR Technics Switzerland
139966					72-23-01		Package SB01	72-0708	REWORK OF THE FAN FRAME FROM DAC TO SAC AND REIDENTIFICATION		730	SR Technics Switzerland
139966					72-23-01		Package SB02	72-0633	NEW PLATE WITH TECH INSERTION KITS INST.		1,145	SR Technics Switzerland
139996	2406M74G01	EASA;FAA;CAAC;ANAC	64	28	72-21-05	FAN AND BOOSTER - SPINNER FRONT CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		665	SR Technics Switzerland
139996	2406M74G02	EASA;FAA;CAAC;ANAC;CAA UK			72-21-05		Package AA	026	REPLACEMENT OF DEFECTIVE SWAGED SELF-LOCKING INSERTS ON THE SPINNER		950	SR Technics Switzerland
139996	337-005-118-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-05		Package AC	028	REPAIR BOLT HOLES BY BUSHING		2,195	SR Technics Switzerland
139996	338-001-204-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AF	031	REPAIR ATTACHMENT AREA		1,435	SR Technics Switzerland
139996	338-085-202-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AI	034	BLEND ON ATTACHMENT SURFACE		675	SR Technics Switzerland
139996	338-085-203-0	EASA;FAA;CAAC;ANAC			72-21-05		Package D	003	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE SPINNER REAR CC TECHNICAL INSTRUCTION		1,340	SR Technics Switzerland
139996	338-085-204-0	EASA;FAA;CAAC;ANAC			72-21-05		Package E	004	REPLACEMENT OF THE BONDED INSERTS AND/OR BONDED WASHERS ON THE SPINNER		1,755	SR Technics Switzerland
139996					72-21-05		Package I	008	REPAIR OF THE MOLYBDENUM DISULFIDE COATING ON THE SPINNER FRONT CONE		1,335	SR Technics Switzerland
139996					72-21-05		Package O	014	REMOVE SURFACE DEFECTS AND REPAIR SULPHURIC ANODIZING, ANTI-EROSION		2,530	SR Technics Switzerland
139996					72-21-05		Package Q	016	REPAIR OF THE LOCATING DIAMETER ON THE SPINNER FRONT CONE BY PLASMA		2,045	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139996					72-21-05		Package W	022	REPAIR BOLT HOLES		1,290	SR Technics Switzerland
140019	1795M66P01	EASA;FAA;CAAC;ANAC	38	28	72-52-06	HIGH PRESSURE TURBINE ROTOR - BLADE RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		1,130	SR Technics Switzerland
140019	2002M15P01	EASA;FAA;CAAC;ANAC			72-52-06		Package B	INSP-001	BLENDING OF SEAL		1,175	SR Technics Switzerland
140019	2410M51P01	EASA;FAA;CAAC;ANAC			72-52-06		Package B	INSP-001	REMOVE HIGHMETAL		1,175	SR Technics Switzerland
140019					72-52-06		Package B	INSP-001	STRAIGHT SEAL		1,175	SR Technics Switzerland
140019					72-52-06		Package C	001	REPAIR OF PART/SERIAL NUMBERS THAT CANNOT BE READ ON BLADE RETAINER		390	SR Technics Switzerland
140019					72-52-06		Package D	003	THERMAL SPRAY REPAIR OF DIAMETER E		8,095	SR Technics Switzerland
140077	215371	EASA;FAA;ANAC	22	21	73-11-14	FUEL PUMP - HOUSING, RELIEF VALVE	Package B	011	REWORK PISTON SEAT INNER DIAMETER		1,190	SR Technics Switzerland
140078	215372	EASA;FAA;ANAC	22	21	73-11-14	FUEL PUMP - RELIEF VALVE PISTON	Package B	010	REWORK PISTON SEAT		305	SR Technics Switzerland
140104			20	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - TGB B	Package A	CLN/INSP	CLEANING AND INSPECTION		585	SR Technics Switzerland
140131	1851M59P01	EASA;FAA;CAAC;ANAC	33	28	72-52-08	HIGH PRESSURE TURBINE ROTOR - NO. 4 BEARING RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	675	SR Technics Switzerland
140131	9339M45P03	EASA;FAA;CAAC;ANAC			72-52-08		Package B	INSP-001	RECONDITION OF SILVER PLATE		4,550	SR Technics Switzerland
140131					72-52-08		Package C	INSP-001	BLENDING NUT WRENCH SLOTS		920	SR Technics Switzerland
140149	338-067-007-0	EASA;FAA;CAAC;ANAC	32	28	72-23-03	FAN FRAME ASSEMBLY - OUTLET GUIDE VANE	Package A		BASIC REPAIR		585	SRTAS
140149	338-067-009-0	EASA;FAA;CAAC;ANAC			72-23-03		Package A	CLN/INSP	CLEANING AND INSPECTION		585	SRTAS
140149	338-067-014-0	EASA;FAA;CAAC;ANAC			72-23-03		Package H		ADDITIONAL WORK SCOPE		1,325	SRTAS
140149	338-067-015-0	EASA;FAA;CAAC;ANAC			72-23-03		Package H	007	REPLACEMENT OF METALLIC LEADING EDGE		1,325	SRTAS
140149					72-23-03		Package I		ADDITIONAL WORK SCOPE		1,175	SRTAS
140149					72-23-03		Package I	014	RECONDITIONING OF MATTING OF THE SCREW HEAD IN ATTACHING HOLES		1,175	SRTAS
140150	338-007-103-0	EASA;FAA;CAAC;ANAC;CAA UK	30	28	72-23-23	FAN FRAME ASSEMBLY - FAN SPLITTER FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		1,130	SR Technics Switzerland
140150	340-002-602-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-23		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		1,425	SR Technics Switzerland
140150					72-23-23		Package E	004	REPAIR OF ATTACHMENT HOLE BY WELDING		6,040	SR Technics Switzerland
140150					72-23-23		Package F	005	REPAIR OF THE CONNECTING GROOVE		5,735	SR Technics Switzerland
140150					72-23-23		Package G	006	REPAIR OF ATTACHMENT HOLE BY BUSHING		3,175	SR Technics Switzerland
140290	338-061-004-0	EASA;FAA;CAAC;ANAC	25	28	72-54-12	LOW PRESSURE TURBINE - OUTER STATIONARY AIR SEAL STG 1 - 4	Package A		STG 1 - BASIC REPAIR		265	SRTAS
140290	338-061-005-0	EASA;FAA;CAAC;ANAC			72-54-12		Package A	CLN-001	CLEANING		265	SRTAS
140290	338-061-104-0	EASA;FAA;CAAC;ANAC			72-54-12		Package A	INSP-001	VISUAL / DIMENSIONAL		265	SRTAS
140290	338-082-401-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B		STG 1 - FULL REPAIR		1,245	SRTAS
140290	338-112-603-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,245	SRTAS
140290	338-112-604-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	003	WELD REPAIR OF CRACKS		1,245	SRTAS
140290	338-112-605-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	006	APPLICATION OF APVS COATING		1,245	SRTAS
140290	338-112-606-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	007	REPAIR OF WEAR ON LOCATING DOWEL		1,245	SRTAS
140290	338-112-607-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	CLN-001	CLEANING		1,245	SRTAS
140290	338-112-650-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	INSP-001	VISUAL / DIMENSIONAL		1,245	SRTAS
140290	338-112-651-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C		STG 1 - FULL REPAIR		1,830	SRTAS
140290	338-112-704-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,830	SRTAS
140290	338-112-705-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	003	WELD REPAIR OF CRACKS		1,830	SRTAS
140290	338-112-706-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	005	REMOVAL AND REPLACEMENT OF THRUST (MATERIAL NOT INCLUDED)	REPAIR 005 OR SB 72-0630	1,830	SRTAS
140290	338-112-707-0	EASA;FAA;CAAC			72-54-12		Package C	006	APPLICATION OF APVS COATING		1,830	SRTAS
140290	338-112-708-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	72-0630	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	REPAIR 005 OR SB 72-0630	1,830	SRTAS
140290	338-112-709-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	CLN-001	CLEANING		1,830	SRTAS
140290	338-112-803-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	INSP-001	VISUAL / DIMENSIONAL		1,830	SRTAS
140290	338-112-804-0	EASA;FAA;CAAC;ANAC			72-54-12		Package D		STG 1 - ADDITIONAL WORKSCOPE		190	SRTAS
140290	338-112-805-0	EASA;FAA;CAAC			72-54-12		Package D	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		190	SRTAS
140290	338-121-602-0	EASA;FAA;CAAC			72-54-12		Package E		STG 1 - ADDITIONAL WORKSCOPE		2,620	SRTAS
140290	340-307-201-0	EASA;CAAC			72-54-12		Package E	72-0630	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	STAND ALONE	2,620	SRTAS
140290	340-307-301-0	EASA			72-54-12		Package F		STG 1 - ADDITIONAL WORKSCOPE		140	SRTAS

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140290					72-54-12		Package F	011	REPLACEMENT OF COVER STRIP		140 SRTAS	
140290					72-54-12		Package G		STG-2 - BASIC REPAIR		265 SRTAS	
140290					72-54-12		Package G	CLN-001	CLEANING		265 SRTAS	
140290					72-54-12		Package G	INSP-001	VISUAL / DIMENSIONAL		265 SRTAS	
140290					72-54-12		Package H		STG 2 - FULL REPAIR		1,230 SRTAS	
140290					72-54-12		Package H	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,230 SRTAS	
140290					72-54-12		Package H	003	WELD REPAIR OF CRACKS		1,230 SRTAS	
140290					72-54-12		Package H	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1,230 SRTAS	
140290					72-54-12		Package H	009	WELD BUILD UP OF ANTI ROTATION SLOT		1,230 SRTAS	
140290					72-54-12		Package H	INSP-001	VISUAL / DIMENSIONAL		1,230 SRTAS	
140290					72-54-12		Package I		STG 2 - ADDITIONAL WORKSCOPE		190 SRTAS	
140290					72-54-12		Package I	72-0302	CHAMFER LOCK TO PREVENT INTERFERENCE WITH NGV		190 SRTAS	
140290					72-54-12		Package J		STG 2 - ADDITIONAL WORKSCOPE		335 SRTAS	
140290					72-54-12		Package J	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		335 SRTAS	
140290					72-54-12		Package K		STG-3 - BASIC REPAIR		265 SRTAS	
140290					72-54-12		Package K	CLN-001	CLEANING		265 SRTAS	
140290					72-54-12		Package K	INSP-001	VISUAL / DIMENSIONAL		265 SRTAS	
140290					72-54-12		Package L		STG 3 - FULL REPAIR		1,315 SRTAS	
140290					72-54-12		Package L	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,315 SRTAS	
140290					72-54-12		Package L	003	WELD REPAIR OF CRACKS		1,315 SRTAS	
140290					72-54-12		Package L	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1,315 SRTAS	
140290					72-54-12		Package L	009	WELD BUILD-UP OF THE ANTI ROTATION LOCK		1,315 SRTAS	
140290					72-54-12		Package L	INSP-001	VISUAL / DIMENSIONAL		1,315 SRTAS	
140290					72-54-12		Package M		STG 3 - ADDITIONAL WORKSCOPE		335 SRTAS	
140290					72-54-12		Package M	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		335 SRTAS	
140290					72-54-12		Package N		STG 4 - FULL REPAIR		950 SRTAS	
140290					72-54-12		Package N	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		950 SRTAS	
140290					72-54-12		Package N	003	WELD REPAIR OF CRACKS		950 SRTAS	
140290					72-54-12		Package N	004	REPLACE ANTI-ROTATION LOCK		950 SRTAS	
140290					72-54-12		Package N	INSP-001	VISUAL / DIMENSIONAL		950 SRTAS	
140290					72-54-12		Package O		STG 4 - ADDITIONAL WORKSCOPE		215 SRTAS	
140290					72-54-12		Package O	002	REPLACEMENT OF RETAINING HOOK		215 SRTAS	
140290					72-54-12		Package S		THRUST-MATERAIL IN ADDITON TO REPAIR CHARGE (REPAIR 005/SB 72-0630/05)		455 SRTAS	
140290					72-54-12		Package T		STG 4 - BASIC REPAIR		265 SRTAS	
140290					72-54-12		Package T	CLN-001	CLEANING		265 SRTAS	
140290					72-54-12		Package T	INSP-001	VISUAL / DIMENSIONAL		265 SRTAS	
141267	305-138-501-0	EASA;FAA;CAAC;ANAC	6	28	72-62-07	ADAPTER ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		325 SRTAS	SR Technics Switzerland
141267					72-62-07		Package B	001	REPLACE KEY LOCKED STUDS		420 SRTAS	SR Technics Switzerland
144730	338-077-501-0	EASA;FAA;CAAC;ANAC	38	28	72-54-05	LOW PRESSURE TURBINE - ROTOR SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,155 SRTAS	SR Technics Switzerland
144730	338-077-502-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-05		Package B	INSP-001	REMOVAL OF HIGH MEATAL		745 SRTAS	SR Technics Switzerland
144730	340-301-702-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-05		Package H	007	REPAIR OF THE REAR DIAMETER MATING THE LPT FORWARD ROTATING AIR SEA		3,210 SRTAS	SR Technics Switzerland
144730					72-54-05		Package I	008	REPAIR OF THE DIAMETER LOCATING THE LPT FORWARD ROTATING OIL SEAL	DIA G	3,165 SRTAS	SR Technics Switzerland
144730					72-54-05		Package L	011	REPAIR OF BOLT D-HEAD MARKS ON SURFACE C BY BLENDING		850 SRTAS	SR Technics Switzerland
144730					72-54-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	955 SRTAS	SR Technics Switzerland
144739	2406M75G01	EASA;FAA;CAAC;ANAC;CAA UK	47	28	72-21-05	FAN AND BOOSTER - SPINNER REAR CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		790 SRTAS	SR Technics Switzerland
144739	338-001-304-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-05		Package AB	027	REPAIR OF SPINNER REAR CONE AFT FLANGE BOLT HOLES		1,385 SRTAS	SR Technics Switzerland
144739	338-001-305-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AE	030	REPAIR OF THE FRONT FLANGE OF THE REAR CONE BY BLENDING		1,665 SRTAS	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144739	340-000-205-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-05		Package AG	032	REPAIR OF SPINNER REAR CONE AFT FLANGE BOLT HOLES		2,760	SR Technics Switzerland
144739					72-21-05		Package B	001	REMOVAL OF SURFACE DEFECTS AND SPOT TOUCH-UP OF OXIDE FILM COATING		1,385	SR Technics Switzerland
144739					72-21-05		Package C	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE REAR CONE		1,380	SR Technics Switzerland
144739					72-21-05		Package D	INSP-001	BLEND CORROSION ON SURFACE D		590	SR Technics Switzerland
144739					72-21-05		Package R	017	REPAIR OF THE SPINNER REAR CONE DIAMETERS THAT LOCATES THE SPINNER F		3,855	SR Technics Switzerland
144739					72-21-05		Package T	019	REPLACEMENT OF THE BONDED SEAL ON THE SPINNER REAR CONE ASSEMBLY		1,765	SR Technics Switzerland
144739					72-21-05		Package Z	025	REPAIR OF THE SPINNER REAR CONE SURFACES THAT MATES WITH THE FAN BL		4,715	SR Technics Switzerland
144759	338-010-502-0	EASA;FAA;CAAC;ANAC	35	28	72-22-02	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		915	SR Technics Switzerland
144759	340-033-005-0	EASA;FAA;CAAC;ANAC			72-22-02		Package B	001	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE NO. 1 BEARING SL		675	SR Technics Switzerland
144759					72-22-02		Package L	011	FINAL CLEANING AND CONDITIONING		190	SR Technics Switzerland
144776	1968M59G01	EASA;FAA;CAAC;ANAC	35	28	72-42-01	COMBUSTION CHAMBER (SAC) - OUTER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		865	SR Technics Switzerland
144776	9531M61G06	EASA;FAA;CAAC;ANAC			72-42-01		Package B	001	WELD REPAIR AND RESIZE OF THE H5188 OUTER COWL		1,800	SR Technics Switzerland
144778	336-026-302-0	EASA;FAA;CAAC;ANAC;CAA UK	42	28	72-54-16	LOW PRESSURE TURBINE - FWD ROTATING AIR SEAL ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1,050	SR Technics Switzerland
144778					72-54-16		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINERS		5,090	SR Technics Switzerland
144778					72-54-16		Package C	002	REPAIR OF THE ABRADABLE COATING	DIA H	2,205	SR Technics Switzerland
144778					72-54-16		Package D	003	REPAIR OF THE OUTER DIAMETER MATING THE LPT ROTOR SUPPORT BY PLASM		2,205	SR Technics Switzerland
144778					72-54-16		Package E	004	REPAIR OF THE INNER DIAMETER MATING THE LPT ROTOR SUPPORT, BY PLASM DIA B		2,280	SR Technics Switzerland
144793	336-065-403-0	EASA;FAA;CAAC;ANAC	55	21	72-54-18	LOW PRESSURE TURBINE - AIR SUPPLY TUBE AND MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	535	SR Technics Switzerland
144793	336-504-604-0	EASA;FAA;CAAC;ANAC			72-54-18		Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	535	SR Technics Switzerland
144793	337-110-303-0	EASA;FAA;CAAC;ANAC			72-54-18		Package C	002	REPLACEMENT OF THE CLIP BY BRAZING		760	SR Technics Switzerland
144793	338-118-602-0	EASA;FAA;CAAC;ANAC			72-54-18		Package C	002	REPLACEMENT OF THE CLIP BY BRAZING		760	SR Technics Switzerland
144793	340-027-602-0	EASA;FAA;CAAC;ANAC			72-54-18		Package D	003	REPLACEMENT OF THE INLET FITTING AND/OR THE END FITTING BY WELDING		3,200	SR Technics Switzerland
144793	340-027-603-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-18		Package D	003	REPLACEMENT OF THE INLET FITTING AND/OR THE END FITTING BY WELDING		3,200	SR Technics Switzerland
144793	340-027-604-0	EASA;FAA;CAAC;ANAC			72-54-18		Package E	004	REPLACEMENT OF THE END FITTING AND/OR THE FLANGE ON THE AIR SUPPLY T		3,035	SR Technics Switzerland
144793	340-091-603-0	EASA;FAA;CAAC;ANAC			72-54-18		Package F	002	REPLACEMENT OF THE OUTLET AND/OR INLET END FITTING AND/OR OF THE CLI TECHNICAL INSTRUCTION		3,220	SR Technics Switzerland
144793	340-091-604-0	EASA;FAA;CAAC;ANAC			72-54-18		Package F	002	REPLACEMENT OF THE OUTLET AND/OR INLET END FITTING AND/OR OF THE CLI TECHNICAL INSTRUCTION		3,220	SR Technics Switzerland
144793	340-091-605-0	EASA;FAA;CAAC;ANAC			72-54-18		Package O	014	HOSE AND TUBE ASSEMBLIES REPAIR 014 - EXTERNAL TUBE ASSEMBLIES BRACK GENERAL EXTERNAL TUBING REPAIR REF.		1,070	SR Technics Switzerland
144793					72-54-18		Package O	014	HOSE AND TUBE ASSEMBLIES REPAIR 014 - EXTERNAL TUBE ASSEMBLIES BRACK GENERAL EXTERNAL TUBING REPAIR REF.		1,070	SR Technics Switzerland
144795	338-010-302-0	EASA;FAA;CAAC;ANAC	58	28	72-53-07	STAGE 1 LPT NOZZLE - INNER AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		680	SR Technics Switzerland
144795	338-111-002-0	EASA;FAA;CAAC;ANAC			72-53-07		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINER		6,325	SR Technics Switzerland
144795	338-111-003-0	EASA;FAA;CAAC;ANAC			72-53-07		Package C	002	REPAIR OF THE PLASMA THERMAL COATING ON THE FACE THAT MATES WITH TIEFF. M		2,620	SR Technics Switzerland
144795	338-111-050-0	EASA;FAA;CAAC;ANAC			72-53-07		Package C	002	REPLACEMENT OF THE PLASMA THERMAL COATING ON THE FACE MATING WITIEFF. N		2,620	SR Technics Switzerland
144795	338-111-051-0	EASA;FAA;CAAC;ANAC			72-53-07		Package E	004	REPAIR OF THE COOLING AIR DUCT BORES		4,015	SR Technics Switzerland
144795	340-311-001-0	EASA;FAA;CAAC;ANAC			72-53-07		Package G	006	REPAIR OF THE DIAMETER LOCATING THE STAGE 1 LPT NOZZLE STATIONARY AIR		3,260	SR Technics Switzerland
144795					72-53-07		Package H	007	REPLACEMENT OR RESTORE OF THE KEYING PIN		1,060	SR Technics Switzerland
144795					72-53-07		Package L	011	BLENDING OR BRAZING OF CRACKS BTW FRONT FLANGE AND REAR FLANGE		2,280	SR Technics Switzerland
144795					72-53-07		Package SB00	72-0785	INTRODUCTION OF A NEW FRONT FLANGE WITH 6 VENTILATION HOLES AND RE		855	SR Technics Switzerland
144800	338-085-402-0	EASA;FAA;CAAC;ANAC	28	28	72-54-13	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 3 - 4	Package A		STG 3/4 - BASIC REPAIR		290	SRTAS
144800	338-085-403-0	EASA;FAA;CAAC;ANAC			72-54-13		Package A	INSP-001	VISUAL / DIMENSIONAL		290	SRTAS
144800	338-085-404-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AA		STG 3 - ADDITIONAL		1,535	SRTAS
144800	338-085-405-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AA	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS PART OF FULL REAS PART OF FULL REPAIR		1,535	SRTAS
144800	338-085-452-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AB		STG 3 - ADDITIONAL		3,300	SRTAS
144800	338-085-502-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AB	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	WHEN PERFORMED INDEPENDENTLY	3,300	SRTAS
144800	338-085-503-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AD		STG 3 - ADDITIONAL		1,160	SRTAS
144800	338-085-504-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AD	021	REPLACEMENT OF THE HONEYCOMB LINER	(HONEYCOMB,HONEYCOMB SUPPORT SHI	1,160	SRTAS
144800	338-109-702-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C		STG 3 - MINOR REPAIR		1,695	SRTAS
144800	338-109-704-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	001	AIRFOIL BLEND REPAIR		1,695	SRTAS

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144800	338-109-705-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,695 SRTAS	
144800	338-109-802-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	INSP-001	VISUAL / DIMENSIONAL		1,695 SRTAS	
144800	338-109-804-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E		STG 3 - FULL REPAIR		3,495 SRTAS	
144800	338-109-805-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	001	AIRFOIL BLEND REPAIR		3,495 SRTAS	
144800	338-110-102-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	003	REPAIR CRACKS BY DIFFUSION BRAZING		3,495 SRTAS	
144800	338-110-103-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	005	RECONDITIONING OF THE VAPOUR PHASE ALUMINISATION		3,495 SRTAS	
144800	338-110-202-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3,495 SRTAS	
144800	338-110-203-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE		3,495 SRTAS	
144800	338-161-604-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	INSP-001	VISUAL / DIMENSIONAL		3,495 SRTAS	
144800	338-161-605-0	EASA;FAA;CAAC;ANAC			72-54-13		Package F		STG 3 - ADDITIONAL WORKSCOPE		815 SRTAS	
144800	338-161-607-0	EASA;FAA;CAAC;ANAC			72-54-13		Package F	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES		815 SRTAS	
144800	338-161-608-0	EASA;FAA;CAAC;ANAC			72-54-13		Package G		STG 3 - ADDITIONAL WORKSCOPE		860 SRTAS	
144800	338-161-704-0	EASA;FAA;CAAC;ANAC			72-54-13		Package G	72-0328	REWORK FOR OVERSPEED IMPROVEMENT	(WHEN PERFORMED INDEPENDENTLY)	860 SRTAS	
144800	338-161-705-0	EASA;FAA;CAAC;ANAC			72-54-13		Package H		STG 3 - ADDITIONAL WORKSCOPE		740 SRTAS	
144800	338-161-707-0	EASA;FAA;CAAC;ANAC			72-54-13		Package H	72-0328	REWORK FOR OVERSPEED IMPROVEMENT	(PART OF MINOR OR FULL REPAIR)	740 SRTAS	
144800	338-161-708-0	EASA;FAA;CAAC;ANAC			72-54-13		Package I		STG 4 - ADDITIONAL WORKSCOPE		1,820 SRTAS	
144800	340-303-301-0	EASA;FAA;CAAC;ANAC			72-54-13		Package I	021	REPLACE HONEYCOMB LINER		1,820 SRTAS	
144800	340-303-401-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J		STG 4 - MINOR REPAIR		360 SRTAS	
144800	340-303-501-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J	001	AIRFOIL BLEND REPAIR		360 SRTAS	
144800	340-303-601-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J	INSP-001	VISUAL / DIMENSIONAL		360 SRTAS	
144800					72-54-13		Package K		STG 4 - MEDIUM REPAIR		1,695 SRTAS	
144800					72-54-13		Package K	001	AIRFOIL BLEND REPAIR.		1,695 SRTAS	
144800					72-54-13		Package K	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		1,695 SRTAS	
144800					72-54-13		Package K	INSP-001	VISUAL / DIMENSIONAL		1,695 SRTAS	
144800					72-54-13		Package L		STG 4 - FULL REPAIR		3,495 SRTAS	
144800					72-54-13		Package L	001	AIRFOIL BLEND REPAIR		3,495 SRTAS	
144800					72-54-13		Package L	003	REPAIR CRACKS BY DIFFUSION BRAZING		3,495 SRTAS	
144800					72-54-13		Package L	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		3,495 SRTAS	
144800					72-54-13		Package L	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE		3,495 SRTAS	
144800					72-54-13		Package L	INSP-001	VISUAL / DIMENSIONAL		3,495 SRTAS	
144800					72-54-13		Package M		STG 4 - ADDITIONAL WORKSCOPE		720 SRTAS	
144800					72-54-13		Package M	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES		720 SRTAS	
144800					72-54-13		Package X		STG 4 - ADDITIONAL		1,535 SRTAS	
144800					72-54-13		Package X	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	AS PART OF FULL REPAIR	1,535 SRTAS	
144800					72-54-13		Package Y		STG 4 - ADDITIONAL		3,300 SRTAS	
144800					72-54-13		Package Y	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	WHEN PERFORMED INDEPENDENTLY	3,300 SRTAS	
600262	218921-1	EASA;FAA;ANAC	22	21	73-11-14	FUEL PUMP - PLATE BEARING ASSY	Package B	007	REWORK BEARING PLATE		1,175 SR Technics Switzerland	
603639	2423M40G01	EASA;FAA;CAAC;ANAC	43	35	72-23-02	FAN FRAME ASSEMBLY - FAN INLET / UPSTREAM FAN CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		2,675 SR Technics Switzerland	
603639	338-075-329-6	EASA;FAA;CAAC;ANAC			72-23-02		Package AN	050	WELD BUILD UP BOLTHOLES	72-00-23	18,750 SR Technics Switzerland	
603639	338-075-332-6	EASA;FAA;CAAC;ANAC			72-23-02		Package B	001	REPLACEMENT OF SWAGED SELF-LOCKING INSERTS		1,115 SR Technics Switzerland	
603639	338-075-335-6	EASA;FAA;CAAC;ANAC			72-23-02		Package D	003	REPLACEMENT OF HI-LOK BOLT RIVETS		1,470 SR Technics Switzerland	
603639	338-075-336-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-02		Package H	007	REPLACEMENT OF THE RIVETED AND BONDED BOSSES		1,625 SR Technics Switzerland	
603639					72-23-02		Package I	008	REPLACEMENT OF THE RIVETED SELF LOCKING NUTS		1,710 SR Technics Switzerland	
603639					72-23-02		Package K	010	REPLACE THE DAMPERS ASSEMBLY ON THE UPSTREAM FAN CASE ASSEMBLY AC		1,560 SR Technics Switzerland	
603639					72-23-02		Package L	011	FULL REPLACEMENT OF THE ABRADABLE LINER ON PIECE PART LEVEL		24,515 SR Technics Switzerland	
603639					72-23-02		Package M	012	LOCAL RECONDITIONING OF THE ABRADABLE SILICONE LINER (BLACK COLOR), F		7,760 SR Technics Switzerland	
603639					72-23-02		Package N	011	FULL REPLACEMENT OF THE ABRADABLE LINER ON MODULE LEVEL		31,800 SR Technics Switzerland	

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
603639					72-23-02		Package R	017	REPAIR OF ELONGATED BOLT HOLES AND/OR WEAR ON B1, B3 AND/OR B4 FLAN		3,960	SR Technics Switzerland
603639					72-23-02		Package S	018	BLEND REPAIR FOR CORROSION NICKS AND SCRATCHES		1,710	SR Technics Switzerland
603639					72-23-02		Package SB00	72-0213	INSPECTION OF THE FORWARD ACOUSTICAL PANELS ATTACHMENT		490	SR Technics Switzerland
603639					72-23-02		Package T	019	WELD BUILD UP BOLT HOLES		4,400	SR Technics Switzerland
603639					72-23-02		Package U	038	PARTIAL REPLACEMENT OF ABRADABLE LINER		4,145	SR Technics Switzerland
603670	301-475-904-6	EASA;FAA;CAAC;ANAC	20	28	72-22-00	NO.1 AND NO.2 BEARING SUPPORT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		85	SR Technics Switzerland
603670	337-011-702-6	EASA;FAA;CAAC;ANAC			72-22-00		Package B	ASSEMBLY-001	SHIM WIDTH GRINDING		240	SR Technics Switzerland
604567	642W9810-505	EASA;FAA;CAAC;ANAC	23	21	71-50-03	ENGINE CONTROL UNIT (ECU) CHANNEL A HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	450	SR Technics Switzerland
604567					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,385	SR Technics Switzerland
604567					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,260	SR Technics Switzerland
604567					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,210	SR Technics Switzerland
604600	642W9811-505	EASA;FAA;CAAC;ANAC	23	21	71-50-03	ENGINE CONTROL UNIT (ECU) CHANNEL B AND MISCELLANEOUS EQUIPM	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604600	642W9811-507	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604600					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,400	SR Technics Switzerland
604600					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,865	SR Technics Switzerland
604601	642W9812-505	EASA;FAA;CAAC;ANAC	22	21	71-50-03	ENGINE CONTROL UNIT (ECU) TO THRUST REVERSER JUNCTION BOX CH/	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604601					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604601					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,490	SR Technics Switzerland
604601					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	4,235	SR Technics Switzerland
604602	642W9813-505	EASA;FAA;CAAC;ANAC	22	21	71-50-03	ENGINE CONTROL UNIT (ECU) TO THRUST REVERSER JUNCTION BOX CH/	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604602					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604602					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,490	SR Technics Switzerland
604602					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	4,235	SR Technics Switzerland
604603	642W9814-503	EASA;FAA;CAAC;ANAC	22	21	71-50-03	INTEGRATED DRIVE GENERATOR (IDG) CONTROL AND ANTI-ICE HARNES	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604603	642W9874-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604603					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	5,335	SR Technics Switzerland
604603					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,000	SR Technics Switzerland
604604	642W9815-503	EASA;FAA;CAAC;ANAC	23	21	71-50-03	FAN CASE LEFT SIDE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	450	SR Technics Switzerland
604604	642W9880-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,685	SR Technics Switzerland
604604	642W9880-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	6,055	SR Technics Switzerland
604604	642W9880-505	EASA;FAA;CAAC;ANAC			71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	7,995	SR Technics Switzerland
604605	642W9817-501	EASA;FAA;CAAC;ANAC	23	21	71-50-03	GENERATOR FEEDER HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604605					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	950	SR Technics Switzerland
604605					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	2,005	SR Technics Switzerland
604605					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	3,740	SR Technics Switzerland
604606	642W9818-503	EASA;FAA;CAAC;ANAC	22	21	71-50-03	VIBRATION SENSOR HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604606	642W9818-505	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604606					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	2,690	SR Technics Switzerland
604606					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	2,995	SR Technics Switzerland
604607	642W9819-503	EASA;FAA;CAAC;ANAC	22	21	71-50-03	FIRE DETECTOR - CHANNEL A (FAN) HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604607					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,320	SR Technics Switzerland
604607					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,815	SR Technics Switzerland
604607					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	3,740	SR Technics Switzerland
604608	642W9820-503	EASA;FAA;CAAC;ANAC	22	21	71-50-03	FIRE DETECTOR - CHANNEL B (FAN) HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604608	642W9883-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,320	SR Technics Switzerland
604608					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,815	SR Technics Switzerland
604608					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	3,740	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
604610	642W9945-505	EASA;FAA;CAAC;ANAC	15	21	71-50-03	WIRE HARNESSSES	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	370 SR Technics Switzerland
604610	642W9955-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,210 SR Technics Switzerland
604610	642W9955-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,705 SR Technics Switzerland
604610					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	2,530 SR Technics Switzerland
604611	642W9946-505	EASA;FAA;CAAC;ANAC	15	21	71-50-03	WIRING HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	420 SR Technics Switzerland
604611	642W9956-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED F NO CONNECTIONS ARE AFFECTED		1,385 SR Technics Switzerland
604611	642W9956-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED F LESS THAN OR EQUAL TO 50% OF THE CON		2,070 SR Technics Switzerland
604611					71-50-03		Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED F MORE THAN 50% OF CONNECTIONS ARE A		2,615 SR Technics Switzerland
604612	642W9947-505	EASA;FAA;CAAC;ANAC	14	21	71-50-03	HARNESS VIBRATION SENSOR (TRF)	Package B	TEST	PRE TEST	TESTING AND FAULT ISALATION	345 SR Technics Switzerland
604612	642W9957-501	EASA;FAA;CAAC;ANAC			71-50-03		Package C	LIGTH	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,210 SR Technics Switzerland
604612	642W9957-503	EASA;FAA;CAAC;ANAC			71-50-03		Package D	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,705 SR Technics Switzerland
604612					71-50-03		Package E	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	2,205 SR Technics Switzerland
604613	642W9948-505	EASA;FAA;CAAC;ANAC	10	21	71-50-03	ECS VALVE WIRING HARNESS (4207KS)	Package C	TEST	PRE TEST		360 SR Technics Switzerland
604613	642W9958-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D		LIGHT REPAIR		1,180 SR Technics Switzerland
604613	642W9958-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E		MEDIUM REPAIR		3,950 SR Technics Switzerland
604613					71-50-03		Package F		HEAVY REPAIR		6,095 SR Technics Switzerland
604614	642W9985-501	EASA;FAA;CAAC;ANAC	22	21	71-50-03	INTERPHONE JACK WIRE HARNESS (INLET)	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410 SR Technics Switzerland
604614	642W9995-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	820 SR Technics Switzerland
604614	642W9995-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,550 SR Technics Switzerland
604614					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	1,875 SR Technics Switzerland
609271	320-402-301-0	EASA;FAA;CAAC;ANAC	23	21	73-22-97	ELECTRICAL HARNESS CJ11L DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609271	325-014-802-0	EASA;FAA;CAAC;ANAC			73-22-97		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609271					73-22-97		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,975 SR Technics Switzerland
609271					73-22-97		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,685 SR Technics Switzerland
609271					73-22-97		Package SB02	73-0305	REPLACE OR REPAIR A SPECIFIC POPULATION OF HARNESSSES CJ11/CJ12	REPLACE ALL SHIELDED CABLES	265 SR Technics Switzerland
609410	320-282-901-0	EASA;FAA;CAAC;ANAC	22	21	73-22-83	ELECTRICAL HARNESS CJ11L SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609410					73-22-83		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609410					73-22-83		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,975 SR Technics Switzerland
609410					73-22-83		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,685 SR Technics Switzerland
609411	320-402-401-0	EASA;FAA;CAAC;ANAC	23	21	73-22-98	ELECTRICAL HARNESS CJ12L DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609411	325-014-901-0	EASA;FAA;CAAC;ANAC			73-22-98		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609411					73-22-98		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,260 SR Technics Switzerland
609411					73-22-98		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,760 SR Technics Switzerland
609411					73-22-98		Package SB02	73-0305	REPLACE OR REPAIR A SPECIFIC POPULATION OF HARNESSSES CJ11/CJ12	REPLACE ALL SHIELDED CABLES	265 SR Technics Switzerland
609412	320-290-201-0	EASA;FAA;CAAC;ANAC	22	21	73-22-85	ELECTRICAL HARNESS CJ12L SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609412					73-22-85		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609412					73-22-85		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,260 SR Technics Switzerland
609412					73-22-85		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,760 SR Technics Switzerland
609413	320-364-201-0	EASA;FAA;CAAC;ANAC	24	21	73-22-74	ELECTRICAL HARNESS J9	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609413	320-364-202-0	EASA;FAA;CAAC;ANAC			73-22-74		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609413	320-364-203-0	EASA;FAA;CAAC;ANAC			73-22-74		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,260 SR Technics Switzerland
609413					73-22-74		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,760 SR Technics Switzerland
609413					73-22-74		Package SB00	72-0205	NEW POSITION OF THE C94 CONNECTOR MASTER KEY	IN CONJUNCTION WITH PACKAGE LIGHT, N	400 SR Technics Switzerland
609413					73-22-74		Package SB01	73-0250	INTRODUCTION OF NEW J9 AND J10 HARNESS AND REWORK OF OLD HARNESS	IN CONJUNCTION WITH PACKAGE MEDIUM	400 SR Technics Switzerland
609414	320-366-601-0	EASA;FAA;CAAC;ANAC	22	21	73-22-96	ELECTRICAL HARNESS CJ12R DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400 SR Technics Switzerland
609414					73-22-96		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360 SR Technics Switzerland
609414					73-22-96		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,915 SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
609414					73-22-96		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,485	SR Technics Switzerland
609415	320-290-301-0	EASA;FAA;CAAC;ANAC	25	21	73-22-86	ELECTRICAL HARNESS CJ12R SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609415	320-290-302-0	EASA;FAA;CAAC;ANAC			73-22-86		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609415					73-22-86		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,915	SR Technics Switzerland
609415					73-22-86		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,485	SR Technics Switzerland
609415					73-22-86		Package SB00	73-0228	INTRODUCTION OF NEW CJ12R ELECTRICAL HARNESS OR REWORK OF THE OLD I	IN CONJUNCTION WITH PACKAGE MEDIUM	295	SR Technics Switzerland
609415					73-22-86		Package SB02	73-0305	REPLACE OR REPAIR A SPECIFIC POPULATION OF HARNESSES CJ11/CJ12	REPLACE ALL SHIELDED CABLES	265	SR Technics Switzerland
609416	320-366-501-0	EASA;FAA;CAAC;ANAC	22	21	73-22-95	ELECTRICAL HARNESS CJ11R DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609416					73-22-95		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609416					73-22-95		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,115	SR Technics Switzerland
609416					73-22-95		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,330	SR Technics Switzerland
609417	320-290-101-0	EASA;FAA;CAAC;ANAC	25	21	73-22-84	ELECTRICAL HARNESS CJ11R SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609417	320-290-102-0	EASA;FAA;CAAC;ANAC			73-22-84		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609417					73-22-84		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,115	SR Technics Switzerland
609417					73-22-84		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,330	SR Technics Switzerland
609417					73-22-84		Package SB00	73-0228	INTRODUCTION OF NEW CJ11R AND CJ12R ELECTRICAL HARNESS OR REWORK O	IN CONJUNCTION WITH PACKAGE WITH P/	295	SR Technics Switzerland
609417					73-22-84		Package SB02	73-0305	REPLACE OR REPAIR A SPECIFIC POPULATION OF HARNESSES CJ11/CJ12	REPLACE ALL SHIELDED CABLES	265	SR Technics Switzerland
609418	320-366-301-0	EASA;FAA;CAAC;ANAC	22	21	73-22-94	ELECTRICAL HARNESS J12	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609418					73-22-94		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609418					73-22-94		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,995	SR Technics Switzerland
609418					73-22-94		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	3,975	SR Technics Switzerland
609419	320-296-801-0	EASA;FAA;CAAC;ANAC	22	21	73-22-78	ELECTRICAL HARNESS J12 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609419					73-22-78		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609419					73-22-78		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	1,995	SR Technics Switzerland
609419					73-22-78		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	3,975	SR Technics Switzerland
609420	320-392-801-0	EASA;FAA;CAAC;ANAC	23	21	73-22-91	ELECTRICAL HARNESS J7 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609420	320-401-501-0	EASA;FAA;CAAC;ANAC			73-22-91		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609420					73-22-91		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,975	SR Technics Switzerland
609420					73-22-91		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,485	SR Technics Switzerland
609420					73-22-91		Package SB00	72-0203	INTRODUCTION OF SHORTER 57 WIRING HARNESS TO PREVENT INTERFERENCE	IN CONJUNCTION WITH PACKAGE LIGHT, N	295	SR Technics Switzerland
609421	320-364-001-0	EASA;FAA;CAAC;ANAC	23	21	73-22-72	ELECTRICAL HARNESS J7 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609421	320-392-601-0	EASA;FAA;CAAC;ANAC			73-22-72		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609421	320-392-602-0	EASA;FAA;CAAC;ANAC			73-22-72		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,975	SR Technics Switzerland
609421	320-401-401-0	EASA;FAA;CAAC;J/CAB;ANAC			73-22-72		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,485	SR Technics Switzerland
609421					73-22-72		Package SB00	72-0203	INTRODUCTION OF SHORTER 57 WIRING HARNESS TO PREVENT INTERFERENCE	IN CONJUNCTION WITH PACKAGE LIGHT, N	295	SR Technics Switzerland
609422	320-392-901-0	EASA;FAA;CAAC;ANAC	23	21	73-22-92	ELECTRICAL HARNESS J8 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609422	320-392-902-0	EASA;FAA;CAAC;ANAC			73-22-92		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609422					73-22-92		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,135	SR Technics Switzerland
609422					73-22-92		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,965	SR Technics Switzerland
609422					73-22-92		Package SB00	72-0191	MODIFICATION OF J8 WIRING HARNESSES	IN CONJUNCTION WITH PACKAGE LIGHT, N	295	SR Technics Switzerland
609423	320-392-701-0	EASA;FAA;CAAC;ANAC	24	21	73-22-73	ELECTRICAL HARNESS J8 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	545	SR Technics Switzerland
609423	320-392-702-0	EASA;FAA;CAAC;ANAC			73-22-73		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609423					73-22-73		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,385	SR Technics Switzerland
609423					73-22-73		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,905	SR Technics Switzerland
609423					73-22-73		Package SB00	72-0191	MODIFICATION OF J8 WIRING HARNESSES	IN CONJUNCTION WITH PACKAGE LIGHT, N	295	SR Technics Switzerland
609424	320-364-501-0	EASA;FAA;CAAC;ANAC	26	21	73-22-79	ELECTRICAL HARNESS J13	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609424	320-366-401-0	EASA;FAA;CAAC;ANAC			73-22-79		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
609424	320-366-402-0	EASA;FAA;CAAC;ANAC			73-22-79		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	5,760	SR Technics Switzerland
609424	320-401-101-0	EASA;FAA;CAAC;JICAB;ANAC			73-22-79		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,560	SR Technics Switzerland
609424					73-22-79		Package SB00	72-0191	MODIFICATION OF J8 AND J13 WIRING HARNESSSES	IN CONJUNCTION WITH PACKAGE LIGHT, N	295	SR Technics Switzerland
609438	320-372-601-0	EASA;FAA;CAAC;ANAC	24	21	73-22-75	ELECTRICAL HARNESS J10 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609438	320-372-602-0	EASA;FAA;CAAC;ANAC			73-22-75		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609438					73-22-75		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,260	SR Technics Switzerland
609438					73-22-75		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,890	SR Technics Switzerland
609438					73-22-75		Package SB00	73-0250	INTRODUCTION OF NEW J9 AND J10 HARNESS AND REWORK OF OLD HARNESS	IN CONJUNCTION WITH PACKAGE MEDIUM	400	SR Technics Switzerland
609439	320-298-101-0	EASA;FAA;CAAC;ANAC	22	21	73-22-82	ELECTRICAL HARNESS DPM	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400	SR Technics Switzerland
609439					73-22-82		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609439					73-22-82		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,050	SR Technics Switzerland
609439					73-22-82		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	4,935	SR Technics Switzerland
609445	320-364-401-0	EASA;FAA;CAAC;ANAC	22	21	73-22-76	ELECTRICAL HARNESS J11 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	425	SR Technics Switzerland
609445					73-22-76		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,210	SR Technics Switzerland
609445					73-22-76		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,015	SR Technics Switzerland
609445					73-22-76		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,685	SR Technics Switzerland
609446	320-366-701-0	EASA;FAA;CAAC;ANAC	16	21	73-22-87	HARNESS WIRING CJ13	Package C	TEST	PRE TEST		400	SR Technics Switzerland
609446	320-401-201-0	EASA;FAA;CAAC;ANAC			73-22-87		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,360	SR Technics Switzerland
609446					73-22-87		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	5,760	SR Technics Switzerland
609446					73-22-87		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	8,560	SR Technics Switzerland
609447	320-366-201-0	EASA;FAA;CAAC;ANAC	22	21	73-22-93	ELECTRICAL HARNESS J11 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	415	SR Technics Switzerland
609447					73-22-93		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,210	SR Technics Switzerland
609447					73-22-93		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	4,015	SR Technics Switzerland
609447					73-22-93		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	5,685	SR Technics Switzerland
610350	301-797-401-0	EASA;FAA;CAAC;ANAC;CAA MALF	26	21	73-11-14	FUEL PUMP	Package B	TEST	BENCH-TEST	READJUSTMENT AND TESTING	2,280	SR Technics Switzerland
610350	301-797-402-0	EASA;FAA;CAAC;ANAC;CAA MALF			73-11-14		Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE LIGHT, N	170	SR Technics Switzerland
610350	724400-1	EASA;FAA;CAAC;ANAC;CAA MALF			73-11-14		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED IEXAMPLE: RING SEAL ROTATING OR HOUS		4,695	SR Technics Switzerland
610350	724400-2	EASA;FAA;CAAC;ANAC;CAA MALF			73-11-14		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED IEXAMPLE: PLATE BEARING ASSY REPLACEI		5,455	SR Technics Switzerland
610350					73-11-14		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED IEXAMPLE: MAIN GEAR HOUSING REPLACE		7,450	SR Technics Switzerland
610350					73-11-14		Package G		OVERHAUL		9,340	SR Technics Switzerland
610350					73-11-14		Package SB02	714900-73-112	INTRODUCTION OF A NEW FUEL FILTER	SB 73-0107 - IN CONJUNCTION WITH PACK	260	SR Technics Switzerland
610350					73-11-14		Package SB03	73-0111	REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT OF THE FUEL F EQUIPPED WITH D-HEAD BOLT / IN CONJU		260	SR Technics Switzerland
610350					73-11-14		Package SB04	AD 2006-26-01	CHECK FUEL FILTER PART NUMBER	IN CONJUNCTION WITH PACK LIGHT, MEDI	260	SR Technics Switzerland
610350					73-11-14		Package SB05	EO-526918	REMOVE SRU	IN CONJUNCTION WITH PACK LIGHT, MEDI	260	SR Technics Switzerland
610350					73-11-14		Package SB06	828300-73-110	NEW FILTER BYPASS VALVE RETAINING RING	SB 73-0287	260	SR Technics Switzerland
610350					73-11-14		Package SB07	724400-73-200	INTRODUCTION OF ALTERNATIVE RELIEF VALVE FOR MFP 724400	SB 73-0300	260	SR Technics Switzerland
610972	056-000-217-0	EASA;FAA;CAAC;ANAC	6	21	72-56-01	CFM56 OIL SCAVENGE ELBOW	Package S	018	ADJUSTMENT NEW ELBOW	FOR SHOP VISITS ONLY	170	SR Technics Switzerland
610972					72-56-01		Package S	018	ADJUSTMENT OLD ELBOW		170	SR Technics Switzerland
610972					72-56-01		Package S	018	REPLACE ELBOW NUT		170	SR Technics Switzerland
613126	1523M69P01	EASA;FAA;CAAC;ANAC	26	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		475	SR Technics Switzerland
613126	1523M71G06	EASA;FAA;CAAC;ANAC;CAA UK			72-53-02		Package B	INSP-001	BLENDING THE MID HEAT SHIELD WORN AREA		400	SR Technics Switzerland
613126	1523M71G07	EASA;FAA;CAAC;ANAC;CAA UK			72-53-02		Package Z	25	BRAZE REPAIR OF THE FORWARD HEAT SHIELD		735	SR Technics Switzerland
613853	301-547-206-0	EASA;FAA;CAAC;ANAC	11	28	72-23-06	CFM56 SELF-ALIGNING PLAIN BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	575	SR Technics Switzerland
613853					72-23-06		Package B	001	REPLACE COURBHANE SEAL		730	SR Technics Switzerland
614086	340-165-503-0	EASA;FAA;CAAC;ANAC	24	28	72-56-04	LOW PRESSURE TURBINE REAR FRAME - STREAM FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	800	SR Technics Switzerland
614086					72-56-04		Package B	001	REPLACEMENT OF ANCHOR NUTS		525	SR Technics Switzerland
618231			6	28	72-61-15	CFM56 INLET GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		385	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
618233	9972M48P01	EASA;FAA;CAAC;ANAC	5	28	72-61-06	CFM56-ALL NO.3 BEARING PULLER NUT	Package A	CLN/INSP	CLEANING & INSPECTION		195	SR Technics Switzerland
618234	9542M68P02	EASA;FAA;CAAC;ANAC	21	28	72-61-12	INLET GEARBOX & NO.3 BEARING - OUTER SPANNER NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,090	SR Technics Switzerland
618701	336-026-806-0	EASA;FAA;CAAC;ANAC	45	35	72-56-02	LOW PRESSURE TURBINE REAR FRAME - NO.5 BEARING SUPPORT ASSEM	Package A	CLN/INSP	CLEANING AND INSPECTION		955	SR Technics Switzerland
618701	336-026-807-0	EASA;FAA;CAAC;ANAC			72-56-02		Package C	002	REPAIR OF THE ABRADABLE COATING		3,435	SR Technics Switzerland
618701	340-165-901-0	EASA;FAA;CAAC;ANAC			72-56-02		Package G	006	RECONDITIONING OF RABBET DIAMETER G		3,040	SR Technics Switzerland
618701	340-165-903-0	EASA;FAA;CAAC;ANAC			72-56-02		Package H	007	REPLACEMENT OR CRACKS REPAIR OF OIL SCAVENGE TUBE NIPPLE BY WELD BUI		5,225	SR Technics Switzerland
618701	340-165-904-0	EASA;FAA;CAAC;ANAC			72-56-02		Package I	008	RECONDITIONING OF THE LOCATING DIAMETER OF THE RING BY PLASMA SPRAY		3,435	SR Technics Switzerland
618701					72-56-02		Package J	009	CRACKS REPAIR OF NO. 5 BEARING SUPPORT BY WELD BUILD-UP		5,365	SR Technics Switzerland
618701					72-56-02		Package M	012	COOLING HOLE WELDING		3,990	SR Technics Switzerland
618701					72-56-02		Package N	013	REPAIR OF SAFETY WIRE HOLES ON THE OIL SCAVENGE TUBE NIPPLE		2,075	SR Technics Switzerland
618701					72-56-02		Package R	017	REPAIR OF THE LOCATING DIAMETER WITH THE TURBINE REAR FRAME BY PLASI		3,435	SR Technics Switzerland
618701					72-56-02		Package SB00	72-0292	INTRODUCTION OF NEW NO.5 BEARING SUPPORT		1,255	SR Technics Switzerland
618701					72-56-02		Package SB02	72-0546	INTRODUCTION OF NEW N°5 BEARING SUPPORT NIPPLE DESIGN OR REWORK OI		5,295	SR Technics Switzerland
618701					72-56-02		Package SB03	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		1,435	SR Technics Switzerland
618701					72-56-02		Package U	014	REPAIR OF TAPPED HOLE WITH LOCALLY MANUFACTURED THREADED INSERT		2,695	SR Technics Switzerland
623552	337-111-302-0	EASA;FAA;CAAC;ANAC	22	28	72-55-13	LOW PRESSURE TURBINE SHAFT - BEARING NO.4 RING-RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	395	SR Technics Switzerland
624055	305-037-204-0	EASA;FAA;CAAC;ANAC	8	21	72-23-24	CFM56 TUBE, GUIDE TO VIBRATION SENSOR	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	385	SR Technics Switzerland
625809	217621-1	EASA;FAA;ANAC	19	21	73-11-14	FUEL PUMP - FRONT COVER	Package A	INSP	INSPECTION	FOR SV ONLY	455	SR Technics Switzerland
625809					73-11-14		Package E	004	PUMP COVER ASSEMBLY REPAIR	W/O THRUST BEARING REPLACEMENT	410	SR Technics Switzerland
628689	772896	EASA;FAA;CAAC;ANAC	11	21	24-19-17	QUICK ATTACH-DETACH ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	765	SR Technics Switzerland
630864	1561M26G01	EASA;FAA;CAAC;ANAC	41	28	72-42-02	COMBUSTION CHAMBER (SAC) - DOME	Package A	CLN/INSP	CLEANING AND INSPECTION,		980	SR Technics Switzerland
630864	1561M26G03	EASA;FAA;CAAC;ANAC			72-42-02		Package B	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE COMBUSTION CHAM		2,430	SR Technics Switzerland
630864	1561M26G05	EASA;FAA;CAAC;ANAC			72-42-02		Package F	006	APPLICATION OF THERMAL BARRIER COATING ON COMBUSTION CHAMBER DON		11,795	SR Technics Switzerland
630864	1561M26G06	EASA;FAA;CAAC;ANAC			72-42-02		Package F	008	REPLACEMENT OF THE PRIMARY SWIRL NOZZLE RETAINER		11,795	SR Technics Switzerland
630864	2255M24G06	EASA;FAA;CAAC;ANAC			72-42-02		Package F	009	PLUG WELDING AND DRILLING OF THE BOLTHOLES IN THE COMBUSTION CHAME		11,795	SR Technics Switzerland
630864	2255M24G07	EASA;FAA;CAAC;ANAC			72-42-02		Package F	013	SPECIAL SIZING TECHNIQUE, VENTURI DIAMETER SIZING AND WELD REPAIR		11,795	SR Technics Switzerland
630864	2255M77G01	EASA;FAA;CAAC;ANAC			72-42-02		Package G	004	COMBUSTOR DOME DEFLECTOR PLATE REPLACEMENT		6,070	SR Technics Switzerland
630864	2255M77G02	EASA;FAA;CAAC;ANAC			72-42-02		Package K	010	REPLACEMENT OF THE SLEEVE AND DEFLECTOR		5,990	SR Technics Switzerland
630864	2255M77G03	EASA;FAA;CAAC;ANAC			72-42-02		Package M	012	SECONDARY SWIRL NOZZLE REPLACEMENT		6,705	SR Technics Switzerland
630864	2813M78G01	EASA;FAA;CAAC;ANAC			72-42-02		Package O	014	THICK BELLMOUNT REPLACEMENT REPAIR		8,205	SR Technics Switzerland
630864					72-42-02		Package Q	016	CC DOME-REPLACEMENT OF SECONDARY SWIRLER NOZZLE		4,655	SR Technics Switzerland
630864					72-42-02		Package R	017	CC DOME-REPLACEMENT OF SLEEVE AN DEFLECTOR		2,575	SR Technics Switzerland
630864					72-42-02		Package S	018	RETAINERLESS PRIMARY SWIRLER REPLACEMENT		3,580	SR Technics Switzerland
630864					72-42-02		Package SB00	72-0507	SWIRLERS - THICK FLANGE		8,205	SR Technics Switzerland
630864					72-42-02		Package SB00	72-0888	REWORK THE OLD COMBUSTION CHAMBER DOME TO THE NEW COMBUSTION C		8,205	SR Technics Switzerland
630864					72-42-02		Package SB03	72-1083	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL	REPLACEMENT OF BELMOUTH FLANGES	8,785	SR Technics Switzerland
630864					72-42-02		Package SB04	72-1083	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL	REPLACEMENT OF SECONDARY NOZZLE	8,785	SR Technics Switzerland
631146	1317M57G02	EASA;FAA;CAAC;ANAC	47	28	72-42-03	COMBUSTION CHAMBER (SAC) - INNER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		1,575	SR Technics Switzerland
631146	1317M57G03	EASA;FAA;CAAC;ANAC			72-42-03		Package AN	OS 255084	AIRFLOW TEST OF LARGE DIA. MULTI HOLES ON INNER LINER		3,435	SR Technics Switzerland
631146	1317M57G05	EASA;FAA;CAAC;ANAC			72-42-03		Package C	002	PULSE WELD REPAIR OF THE INNER LINER SEAL		4,365	SR Technics Switzerland
631146	1968M64G01	EASA;FAA;CAAC;ANAC			72-42-03		Package I	008	WELDED PATCH REPAIR		3,435	SR Technics Switzerland
631146	1968M64G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	001	WELD REPAIR AND RESIZING AND STRESS RELIEF OF THE INNER LINER		14,750	SR Technics Switzerland
631146	1968M64G04	EASA;FAA;CAAC;ANAC			72-42-03		Package K	003	REMOVAL OF THE NUT PLATES IN THE LINER		14,750	SR Technics Switzerland
631146	2256M23G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	004	INSTALLATION OF THE NUT PLATES IN THE INNER LINER		14,750	SR Technics Switzerland
631146	2256M23G03	EASA;FAA;CAAC;ANAC			72-42-03		Package K	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE INNER LINER		14,750	SR Technics Switzerland
631146	2256M23G04	EASA;FAA;CAAC;ANAC			72-42-03		Package K	006	APPLY THE THERMAL BARRIER COATING ON THE INNER LINER		14,750	SR Technics Switzerland
631146	2257M42G01	EASA;FAA;CAAC;ANAC			72-42-03		Package K	007	COMBUSTION CHAMBER INNER LINER BOLT HOLE DRILLING REPAIR		14,750	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
631146	2257M42G02	EASA;FAA;CAAC;ANAC		72-42-03		Package K	009	BRAZED DOUBLER WELD REPAIR OF THE INNER LINER AFT SUPPORT RING		14,750	SR Technics Switzerland
631146	2480M43G02	EASA;FAA;CAAC;ANAC		72-42-03		Package K	010	MINOR (LESS THAN SIX) BOLTHOLE REPAIR		14,750	SR Technics Switzerland
631146				72-42-03		Package K	016	REPAIR OF THE INNER LINER IMPROVED GEOMETRY AND MATERIAL AFT SUPPO BY REPLACING MISSING LEGS		14,750	SR Technics Switzerland
631146				72-42-03		Package K	017	WELDING AND RESIZING REPAIR FOR THE INNER LINER WITH IMPROVED GEOMI		14,750	SR Technics Switzerland
631146				72-42-03		Package M	012	(THICK) THERMAL BARRIER COATING REPLACEMENT		1,435	SR Technics Switzerland
631146				72-42-03		Package N	013	INNER LINER AFT FLANGE REPLACEMENT		9,355	SR Technics Switzerland
631146				72-42-03		Package P	015	APPLICATION OF TBC ON INNER LINER WITH LARGE DIA MULTI HOLE	additional TAT +9, in cork	4,650	SR Technics Switzerland
631146				72-42-03		Package SB00	72-0336	INNER AND OUTER LINER THICKER TBC FIELD REWORK		2,660	SR Technics Switzerland
631146				72-42-03		Package SB03	72-0584	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE K	580	SR Technics Switzerland
631146				72-42-03		Package SB05	72-0692	REWORK OF THE INNER COMBUSTION CHAMBER LINER		10,730	SR Technics Switzerland
631146				72-42-03		Package SB06	72-0812	REWORK OF PRE_Tech INSERTION COMBUSTION CHAMBER INNER LINER WITH		2,195	SR Technics Switzerland
631146				72-42-03		Package SB07	72-0844	REWORK OF TECH INSERTION INNER LINER INTO MULTI-HOLE COOLING PATCH \		4,650	SR Technics Switzerland
631146				72-42-03		Package T	019	REPAIR OF THE BRAZE JOINT OF THE COMBUSTION CHAMBER INNER LINER AFT		2,195	SR Technics Switzerland
631146				72-42-03		Package U	020	PLUG-WELD INNER LINER HOLE		7,930	SR Technics Switzerland
631146				72-42-03		Package U	020	WELD AND RESIZE REPAIR OF THE INNER NON-MULTIHOLES AREAS		7,930	SR Technics Switzerland
631146				72-42-03		Package V	021	APPLICATION OF THIN THERMAL BARRIER COATING ON INNER LINERS WITH LAR		4,650	SR Technics Switzerland
631146				72-42-03		Package W	022	CRACK WELDRESIZE	additional TAT +9, in cork	9,645	SR Technics Switzerland
631393	1498M58P01	EASA;FAA;CAAC;ANAC	21	28 72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package A	CLN/INSP	CLEANING & INSPECTION		65	SR Technics Switzerland
631393	1498M58P04	EASA;FAA;CAAC;ANAC		72-41-03		Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		140	SR Technics Switzerland
634072	338-065-603-0	EASA;FAA;CAAC;ANAC	54	35 72-54-07	LOW PRESSURE TURBINE - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1,770	SR Technics Switzerland
634072	338-117-404-0	EASA;FAA;CAAC;ANAC		72-54-07		Package B	001	REPLACEMENT OF RIVETED PARTS AND RIVETS		2,355	SR Technics Switzerland
634072	338-117-406-0	EASA;FAA;CAAC;ANAC		72-54-07		Package C	002	REPAIR OF THE OUTER DIAMETER LOCATING THE HPT SHROUD SUPPORT	DIAMETER "A"	4,805	SR Technics Switzerland
634072	338-117-407-0	EASA;FAA;CAAC;ANAC		72-54-07		Package C	002	REPAIR OF THE OUTER DIAMETER LOCATING THE HPT SHROUD SUPPORT	DIAMETER "G"	4,805	SR Technics Switzerland
634072	338-117-450-0	EASA;FAA;CAAC;ANAC		72-54-07		Package D	003	REPLACEMENT OF THE BORESCOPE BOSSES		1,760	SR Technics Switzerland
634072	338-117-451-0	EASA;FAA;CAAC;ANAC		72-54-07		Package H	007	REPAIR OF THE OUTER DIAMETER LOCATING THE LPT FRAME		6,535	SR Technics Switzerland
634072	338-117-452-0	EASA;FAA;CAAC;ANAC		72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (BARE)		6,535	SR Technics Switzerland
634072	338-117-453-0	EASA;FAA;CAAC;ANAC		72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (PLASMA)		6,535	SR Technics Switzerland
634072	338-117-454-0	EASA;FAA;CAAC;ANAC		72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLASMA SPRAYIN RAIL 1 TO 6		7,005	SR Technics Switzerland
634072	338-117-455-0	EASA;FAA;CAAC;ANAC		72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLASMA SPRAYIN RAIL 1 TO 6		7,005	SR Technics Switzerland
634072	340-305-003-0	EASA;FAA;CAAC;ANAC		72-54-07		Package P	15-94761	BLENDED OF CRACKS ON RAIL 6 ANTI-ROTATION SLOTS		480	SR Technics Switzerland
634072				72-54-07		Package Q	016	WELD BUILD UP OF CRAKS ON RAILS 1,3,5 AND 7 NOZZLE SUPPORT RING	RAIL 1/3/5	17,570	SR Technics Switzerland
634072				72-54-07		Package R	017	REPLACEMENT OF ANTI ROTATION PINS	RD 15-93532	1,900	SR Technics Switzerland
634072				72-54-07		Package S	018	REPAIR OF PAR RAILS NOZZLES SUPPORT RING BY WELD BUILD UP	RAILS 2/4/6/8	23,265	SR Technics Switzerland
634072				72-54-07		Package SB00	72-0589	REIDENTIFICATION OF LPT CASE IN FIELD		260	SR Technics Switzerland
634072				72-54-07		Package SB01	72-0706	REWORK OF THE LPT CASE RAIL "0" SUPPORT RING AND REIDENTIFICATION OF 1		5,620	SR Technics Switzerland
634072				72-54-07		Package SB02	EASA-2014-0130	CHECK LIFE LIMITS		525	SR Technics Switzerland
634072				72-54-07		Package SB03	72-0933	INTRODUCTION OF NEW PLATE		525	SR Technics Switzerland
634072				72-54-07		Package T	019	REPAIR OF ODD RAILS NOZZLES SUPPORT RING BY WELD BUILD UP	RAIL 1/3/5/7	15,525	SR Technics Switzerland
634072				72-54-07		Package V	021	REPAIR OF WEAR MARKS ON RAIL 0 SUPPORT RING BY PLASMA SPRAYING		7,005	SR Technics Switzerland
634151	1523M29G04	EASA;FAA;CAAC;ANAC	52	28 72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,290	SR Technics Switzerland
634151	1784M36G01	EASA;FAA;CAAC;ANAC;CAA UK		72-53-02		Package AC	015	AFT FLANGE HEADLESS STRAIGHT PIN REPLACEMENT		960	SR Technics Switzerland
634151	1784M36G02	EASA;FAA;CAAC;ANAC		72-53-02		Package AM	017	HANGER ANTI-ROTATION PIN REPLACEMENT		645	SR Technics Switzerland
634151	2002M69G02	EASA;FAA;CAAC;ANAC		72-53-02		Package AN	022	THERMAL SPRAY REPAIR OF THE SHROUD HANGER RAIL INNER DIAMETER FACE DIM. L / DIM. K		8,565	SR Technics Switzerland
634151	2002M69G03	EASA;FAA;CAAC;ANAC		72-53-02		Package B	INSP-001	BLEND TO REMOVE HIGH METAL		2,270	SR Technics Switzerland
634151	2002M69G05	EASA;FAA;CAAC;ANAC		72-53-02		Package B	INSP-001	BLENDED WEAR INSIDE DIA.		2,270	SR Technics Switzerland
634151	2002M90G01	EASA;FAA;CAAC;ANAC		72-53-02		Package B	INSP-001	TACK-WELD BOSS		2,270	SR Technics Switzerland
634151	2063M40G01	EASA;FAA;CAAC;ANAC		72-53-02		Package B	INSP-001	TACK-WELD BUSHING		2,270	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634151					72-53-02		Package C	004	FORWARD FLANGE WEAR REPAIR		4,805	SR Technics Switzerland
634151					72-53-02		Package E	018	REPAIR FOR LOCAL WEAR ON THE VANE MOUNT AFT FACE		3,615	SR Technics Switzerland
634151					72-53-02		Package G	012	(EFFECT N) REPLACEMENT OF SUPPORT BUSHINGS		2,975	SR Technics Switzerland
634151					72-53-02		Package H	013	(EFFECT N) REPLACEMENT OF THE BORESCOPE BOSS		505	SR Technics Switzerland
634151					72-53-02		Package M	023	FORWARD RAIL EROSION REPAIR		465	SR Technics Switzerland
634151					72-53-02		Package O	014	SELF RETAINING SLABBED HEAD BOLT REPLACEMENT		655	SR Technics Switzerland
634151					72-53-02		Package SB01	72-0270	HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01		4,980	SR Technics Switzerland
634151					72-53-02		Package SB02	72-0143	MODIFY HPT/LPTN SUPPORT		4,980	SR Technics Switzerland
634151					72-53-02		Package SB03	72-0878	REWORK FWD FLANGE SHROUD NOZZLE SUPPORT		4,980	SR Technics Switzerland
634151					72-53-02		Package T	019	FORWARD FLANGE DIMENSIONAL REPAIR		6,635	SR Technics Switzerland
634151					72-53-02		Package V	021	PLASMA SPRAY REPAIR OF SURFACE AM		2,795	SR Technics Switzerland
634151					72-53-02		Package W	021	PLASMA SPRAY REPAIR OF DIAMETER FM		2,795	SR Technics Switzerland
634151					72-53-02		Package X	022	REPAIR SHROUD ID DIM.M		8,520	SR Technics Switzerland
635241	301-547-905-0	EASA;FAA;CAAC;ANAC;CAA UK	26	28	72-55-07	LOW PRESSURE TURBINE SHAFT - RETAINER NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	410	SR Technics Switzerland
635241	64ECR101	EASA;FAA;CAAC;ANAC			72-55-07		Package N	001	REPAIR OF THE MATING FACES	ITEM 1	575	SR Technics Switzerland
635241	650-784-016-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package O	001	REPAIR OF THE MATING FACES	ITEM 2	575	SR Technics Switzerland
635241	650-784-037-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package P	001	REPAIR OF THE MATING FACES	ITEM 3	575	SR Technics Switzerland
635241	650-784-038-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package Q	001	REPAIR OF THE MATING FACES	ITEM 4	575	SR Technics Switzerland
635241	650-784-075-0	EASA;FAA;CAAC;ANAC			72-55-07		Package U	002	REPAIR OF THE SILVER PLATING	ITEM 1-3	1,525	SR Technics Switzerland
635241					72-55-07		Package X	002	REPAIR OF THE SILVER PLATING	ITEM 4	1,525	SR Technics Switzerland
635521	9324M22G01	EASA;FAA;CAAC;ANAC	17	28	72-00-53	ENGINE MODULES/ASSEMBLIES - HPT SHROUD & STAGE 1 LPT NOZZLE	Package A	CLN/INSP	CLEANING AND INSPECTION		510	SR Technics Switzerland
635521	9324M62G01	EASA;FAA;CAAC;ANAC			72-00-53		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		920	SR Technics Switzerland
637097	1887M18G01	EASA;FAA;CAAC;ANAC	28	28	72-00-31	ENGINE MODULES/ASSEMBLIES - COMPRESSOR ROTOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3,525	SR Technics Switzerland
637097	1887M18G03	EASA;FAA;CAAC;ANAC			72-00-31		Package B	001	BLENDING BLADES STG 1		925	SR Technics Switzerland
637097	1887M18G04	EASA;FAA;CAAC;ANAC			72-00-31		Package C	002	BLENDING BLADES STG 2-3		925	SR Technics Switzerland
637097	9324M78G01	EASA;FAA;CAAC;ANAC			72-00-31		Package D	003	BLENDING BLADES STG 4-9		925	SR Technics Switzerland
637097					72-00-31		Package G	006	LUBRICANT DOVETAIL	72-31-04	925	SR Technics Switzerland
637097					72-00-31		Package H		BLADE LOCK REPLACEMENT	72-31-00	1,030	SR Technics Switzerland
637097					72-00-31		Package N	INSP-001	BLEND STG.2 RETAINER HOOK		565	SR Technics Switzerland
637097					72-00-31		Package O	INSP-001	BLEND STG.4 DOVETAIL FWD		565	SR Technics Switzerland
637097					72-00-31		Package P	INSP-001	BLEND STG.1-2 SEAL TEETH		565	SR Technics Switzerland
637097					72-00-31		Package Q	INSP-001	BLEND STG.4-9 SEAL TEETH		565	SR Technics Switzerland
637097					72-00-31		Package R	INSP-001	LUBRICANT THREAD	72-31-07	565	SR Technics Switzerland
637097					72-00-31		Package S	INSP-001	BLEND LOCKING LUG SLOT	72-00-31	565	SR Technics Switzerland
642808	9968M26P02	EASA;FAA;CAAC;ANAC	18	28	72-42-04	COMBUSTION CHAMBER - IGNITER FERRULE	Package A	CLN/INSP	CLEANING AND INSPECTION		115	SR Technics Switzerland
642808					72-42-04		Package W	022	IGNITER FERRULE BORE WELD REPAIR		450	SR Technics Switzerland
647987	1522M10G01	EASA;FAA;CAAC;ANAC	24	28	72-53-05	HPT SHROUD - AIR IMPINGEMENT MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	980	SR Technics Switzerland
647987	1668M93G01	EASA;FAA;CAAC;ANAC			72-53-05		Package B	001	WELD REPAIR OF AXIAL CRACKS NEXT TO THE AIR IMPINGEMENT MANIFOLD NU		810	SR Technics Switzerland
647987	1668M93G02	EASA;FAA;CAAC;ANAC;CAA UK			72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL B	3,065	SR Technics Switzerland
647987	1668M93G03	EASA;FAA;CAAC;ANAC			72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL C	3,065	SR Technics Switzerland
647987	2071M29G01	EASA;FAA;CAAC;ANAC			72-53-05		Package F	005	SPLASH PLATE AND SPLASH PLATE SUPPORT WELD REPAIR		810	SR Technics Switzerland
647987	2071M29G02	EASA;FAA;CAAC;ANAC			72-53-05		Package G	006	SPLASH PLATE AND SPLASH PLATE SUPPORT WELD REPAIR		810	SR Technics Switzerland
647987	2071M29G03	EASA;FAA;CAAC;ANAC			72-53-05		Package I	008	BRAZE JOINT REPAIR		3,090	SR Technics Switzerland
647987					72-53-05		Package J	009	BRAZE JOINT REPAIR		920	SR Technics Switzerland
647987					72-53-05		Package M	012	FORWARD TABS PLASMA SPRAY REPAIR		1,625	SR Technics Switzerland
647987					72-53-05		Package N	013	BOLT LUG BRAZE JOINT REPAIR		2,180	SR Technics Switzerland
647987					72-53-05		Package N	014	BOLT LUG BRAZE JOINT REPAIR		2,180	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
647987					72-53-05		Package P	015	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		1,355	SR Technics Switzerland
647987					72-53-05		Package Q	016	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		2,205	SR Technics Switzerland
647987					72-53-05		Package SB01	72-0421	HIGH PRESSURE TURBINE NOZZLE (72-51-00) - INTRODUCTION OF FIELD REWOR		3,935	SR Technics Switzerland
648442	338-062-201-0	EASA;FAA;CAAC;ANAC	6	21	72-22-08	CFM56 TUBE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	325	SR Technics Switzerland
648442					72-22-08		Package A	CLN/INSP	PRESSURE TEST		325	SR Technics Switzerland
648442					72-22-08		Package B	01	BLENDING		265	SR Technics Switzerland
648443	338-062-001-0	EASA;FAA;CAAC;ANAC	8	21	72-22-08	CFM56 TUBE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	325	SR Technics Switzerland
648443	338-062-003-0	EASA;FAA;CAAC;ANAC			72-22-08		Package A	CLN/INSP	PRESSURE TEST		325	SR Technics Switzerland
648443	338-062-701-0	EASA;FAA;CAAC;ANAC			72-22-08		Package B	001	BLENDING		330	SR Technics Switzerland
648501	335-070-401-0	EASA;FAA;CAAC;ANAC	16	28	72-56-12	LOW PRESSURE TURBINE REAR FRAME - REAR INSULATION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	260	SR Technics Switzerland
648693	336-031-802-0	EASA;FAA;CAAC;ANAC	15	28	72-56-09	LOW PRESSURE TURBINE REAR FRAME - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		335	SR Technics Switzerland
648717	1864M97P01	EASA;FAA;CAAC;ANAC	15	28	72-52-11	COMPRESSOR FRONT STATOR - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		235	SR Technics Switzerland
648726	1663M70P02	EASA;FAA;CAAC;ANAC	16	28	72-31-14	COMPRESSOR ROTOR - COMPRESSOR SHAFT RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	220	SR Technics Switzerland
648728	1499M47P02_	EASA;FAA;CAAC;ANAC	8	28	72-31-15	COMPRESSOR ROTOR DAMPER RING, STAGE 1-2 SPOOL	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	120	SR Technics Switzerland
654796	9321M97P02	EASA;FAA;CAAC;ANAC	6	28	72-33-20	CFM56 STOP, STATOR SECTOR	Package A	CLN/INSP	CLEANING & INSPECTION		105	SR Technics Switzerland
654828	9971M82P02	EASA;FAA;CAAC;ANAC	8	28	72-52-09	CFM56 RING-RETAINING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	405	SR Technics Switzerland
654909	337-112-801-0	EASA;FAA;CAAC;ANAC	15	21	72-54-14	LOW PRESSURE TURBINE - SUPPORT BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	335	SR Technics Switzerland
654909					72-54-14		Package AE	ASSEMBLY	MOUNT BRACKET REPLACE BUSHING		945	SR Technics Switzerland
654954	305-140-104-0	EASA;FAA;CAAC;ANAC	7	28	72-63-20	CFM56 AGB HORIZONTAL DRIVE SHAFT HOUSING CFM56	Package A	CLN/INSP	CLEANING AND INSPECTION		485	SR Technics Switzerland
655153	1358M93P01	EASA;FAA;CAAC;ANAC	7	28	72-52-09	CFM56 HPT SEAL-BLADE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	45	SR Technics Switzerland
655176	301-298-208-0	EASA;FAA;CAAC;ANAC	17	28	72-22-06	NO.1 AND NO.2 BEARING SUPPORT - REAR ROTATING AIR/OIL SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	865	SR Technics Switzerland
655176	301-298-211-0	EASA;FAA;CAAC;ANAC;CAA UK			72-22-06		Package B	001	RECONDITIONING OF SILVER PLATING ON THE FORWARD MATING FACE AND/OI		495	SR Technics Switzerland
655179	301-298-006-0	EASA;FAA;CAAC;ANAC	17	28	72-22-13	NO.1 & NO.2 BEARING SUPPORT - RETAINING NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		790	SR Technics Switzerland
655179					72-22-13		Package B	001	REPLACEMENT OF SILVER PLATING ON NO. 1 BEARING INNER RACE RETAINING I		1,280	SR Technics Switzerland
655179					72-22-13		Package C	002	REPAIR OF THE SILVER PLATE MATING FACES OF THE RETAINING NUTS		810	SR Technics Switzerland
656214	301-436-804-0	EASA;FAA;CAAC;ANAC	17	28	72-22-13	NO.1 & NO.2 BEARING SUPPORT - RETAINING NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	810	SR Technics Switzerland
656214	337-011-902-0	EASA;FAA;CAAC;ANAC			72-22-13		Package D	003	EQUALIZE THE RETAINING NUT SURFACE B		590	SR Technics Switzerland
656381	305-145-502-0	EASA;FAA;CAAC;ANAC	4	21	72-63-12	ACCESSORY GEARBOX HANDCRANKING NUT	Package A	CLN/INSP	CLEANING & INSPECTION		65	SR Technics Switzerland
656382	305-151-403-0	EASA;FAA;CAAC;ANAC	5	28	72-63-13	ACCESSORY GEARBOX V-CLAMP	Package A	CLN/INSP	CLEANING & INSPECTION		135	SR Technics Switzerland
663314	PBF1340-3-3	EASA;FAA;CAAC;ANAC	8	21	71-21-08	CFM56-5B FWD ENGINE MOUNT BOLT	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	385	SR Technics Switzerland
664390	338-003-504-0	EASA;FAA;CAAC;ANAC	15	28	72-21-09	CFM56-5B STG.5 STEEL BOOSTER VANE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		830	SR Technics Switzerland
664390	338-003-505-0	EASA;FAA;CAAC;ANAC			72-21-09		Package B	1	BLEND REPAIR OF THE VANE AIRFOIL		590	SR Technics Switzerland
664390	338-003-509-0	EASA;FAA;CAAC;ANAC			72-21-09		Package C	2	REPL. OF THE SILICONE ABRADABLE COATING CHARGED WITH HOLLOW GLASS B		3,685	SR Technics Switzerland
664390					72-21-09		Package D	3	REPL. OUTER SHROUD STG 5		5,370	SR Technics Switzerland
664390					72-21-09		Package E	4	REPLACEMENT OF THE SELF-LOCKING CRIMPED NUTS AND/OR THE RIVETED SEL		950	SR Technics Switzerland
664390					72-21-09		Package K	INSP-001	REMOVE HIGHMETAL ON AIRFOIL		980	SR Technics Switzerland
664390					72-21-09		Package L	40	APPLY PAINTING STAGE 5		5,490	SR Technics Switzerland
664390					72-21-09		Package SB01	72-0418	REPLACEMENT OR REWORK OF THE STAGE 5 BOOSTER VANE ASSEMBLY		4,805	SR Technics Switzerland
664390					72-21-09		Package SB02	72-0506	IMPROVEMENT OF THE FAN AND BOOSTER STG 5 VANE ASSY TO PREVENT CORF		8,455	SR Technics Switzerland
672589	338-003-104-0	EASA;FAA;CAAC;ANAC	15	28	72-21-09	CFM56-5B BOOSTER VANE ASSY TITANIUM STG. 1-5	Package A	CLN/INSP	CLEANING AND INSPECTION		895	SR Technics Switzerland
672589	338-003-106-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AL	037	SPOT TOUCH UP BOOSTER VANE		1,710	SR Technics Switzerland
672589	338-003-203-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AL	060	BLEND REPAIR OF CORROSION		1,710	SR Technics Switzerland
672589	338-003-204-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AN	039	REPLACE VANES / NUTS / SHROUDS		6,625	SR Technics Switzerland
672589	338-003-205-0	EASA;FAA;CAAC;ANAC			72-21-09		Package B	INSP-001	REMOVE HIGHMETAL ON AIRFOL		1,385	SR Technics Switzerland
672589	338-003-305-0	EASA;FAA;CAAC;ANAC			72-21-09		Package C	002	REPLACEMENT INNER SHROUD		3,960	SR Technics Switzerland
672589	338-003-306-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-09		Package D	001	BLEND VANE AIRFOIL		6,345	SR Technics Switzerland
672589	338-003-315-0	EASA;FAA;CAAC;ANAC			72-21-09		Package D	003	REPLACE OUTER SHROUD ABRADABLE COATING		6,345	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672589	338-003-316-0	EASA;FAA;CAAC;ANAC			72-21-09		Package E	004	REPLACE LOCKING NUTS STG.5		1,005	SR Technics Switzerland
672589	338-003-403-0	EASA;FAA;CAAC;ANAC			72-21-09		Package G	006	FRONT INNER DIAMETER F / STG.1		3,180	SR Technics Switzerland
672589	338-003-404-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-09		Package H	007	FRONT OUTER DIMENSION O / STG.1		3,180	SR Technics Switzerland
672589	338-003-414-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB00	72-0218	REWORK OF FAN AND BOOSTER STG1 VANE ASSY		5,370	SR Technics Switzerland
672589	338-003-502-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB01	72-0418	REPL. OR REWORK OF THE STG. 5 BOOSTER VANE ASSY		5,370	SR Technics Switzerland
672589	338-003-503-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB02	72-1031	REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2-4		6,345	SR Technics Switzerland
672589	338-003-506-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB03	72-0917	INNER SHROUD REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2		5,370	SR Technics Switzerland
672589					72-21-09		Package SB04	72-1065	REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2-4		2,770	SR Technics Switzerland
672596	1386M56P02	EASA;FAA;CAAC;ANAC	12	28	72-31-07	CFM56 COMPRESSOR ROTOR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,015	SR Technics Switzerland
672596	1386M56P03	EASA;FAA;CAAC;ANAC;CAA UK			72-31-07		Package B	INSP-001	APPLY DRY FILM LUBRICANT		1,710	SR Technics Switzerland
672596	1590M28G01	EASA;FAA;CAAC;ANAC			72-31-07		Package B	INSP-001	BLENDING REPAIR		1,710	SR Technics Switzerland
672596	1590M28G02	EASA;FAA;CAAC;ANAC			72-31-07		Package E	004	REPAIR ROTOR LOCK.SLOT		3,540	SR Technics Switzerland
672596	1590M28G04	EASA;FAA;CAAC;ANAC			72-31-07		Package F	005	REPAIR ROTOR SHAFT		6,500	SR Technics Switzerland
672596	1590M28G05	EASA;FAA;CAAC;ANAC			72-31-07		Package G	006	ROTOR SHAFT DAMAGED THREADS		1,850	SR Technics Switzerland
672596					72-31-07		Package SB00	AD 2002-13-03	ENHANCED LLP INSP	AD 2002-13-03_007	860	SR Technics Switzerland
672792	338-040-751-0	EASA;FAA;CAAC;ANAC	8	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	415	SR Technics Switzerland
672792					72-09-03		Package B	REPAIR	REPAIR AND PRESSURE TEST		1,145	SR Technics Switzerland
672828	336-031-631-0	EASA;FAA;CAAC;ANAC	15	35	72-56-01	CFM56-5B TURBINE REAR FRAME MODUL 56	Package A	CLN/INSP	CLEANING AND INSPECTION		2,910	SR Technics Switzerland
672828	336-031-632-0	EASA;CAAC;EASA/ANAC BRAZIL D			72-56-01		Package AA	18	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY		2,760	SR Technics Switzerland
672828	338-031-642-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AB	26	CLEVIS MOUNT BORES - BUSHING		4,130	SR Technics Switzerland
672828	338-031-643-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AC	15-9464	RECONDITIONING OF THE CLEVIS MOUNT FIXATION AREA		1,815	SR Technics Switzerland
672828	338-061-623-0	EASA;FAA;ANAC			72-56-01		Package AD	29	REPLACEMENT OF INSULATION ASSEMBLY OF THE INNER HUB		1,395	SR Technics Switzerland
672828	338-061-625-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AE	25	REPLACEMENT OF NEW BUSHINGS		3,545	SR Technics Switzerland
672828	338-061-626-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AI	34	REPLACEMENT OF SUMP FLOODING TUBE		1,385	SR Technics Switzerland
672828	338-061-627-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AJ	51	RADIUS DIA K POLISHING		680	SR Technics Switzerland
672828	338-102-904-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AM	38	REPAIR OF THE BRACKET CENTERING DIAMETER OF THE OIL SCAVENGE TUBE AS		4,810	SR Technics Switzerland
672828	338-102-907-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AN	47	WELD BUILD-UP CLEVIS MOUNT AREA		2,290	SR Technics Switzerland
672828	338-102-908-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	1	REPLACEMENT OF THE DEFECTIVE STUDS ON THE AFT FACE OF THE INNER HUB		3,040	SR Technics Switzerland
672828	338-102-909-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	INSP-001	REWELD STOP WELD ON STUDS		3,040	SR Technics Switzerland
672828	338-102-910-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	INSP-001	REMOVE HIGH METAL		3,040	SR Technics Switzerland
672828	338-102-912-0	EASA;FAA;CAAC;ANAC			72-56-01		Package C	2	REPLACEMENT OF THE DEFECTIVE CRIMPED SELF-LOCKING NUTS		1,300	SR Technics Switzerland
672828	338-171-703-0	EASA;FAA;CAAC;ANAC			72-56-01		Package D	3	REPLACEMENT OF THE DEFECTIVE SELF-LOCKING INSERTS		1,530	SR Technics Switzerland
672828	338-171-704-0	EASA;FAA;CAAC;ANAC			72-56-01		Package E	4	REPLACEMENT OF DEFECTIVE FASTENERS AND/ OR DEFECTIVE ASSOCIATED PAR		1,530	SR Technics Switzerland
672828	338-171-705-0	EASA;FAA;CAAC;ANAC			72-56-01		Package F	5	REPLACE THE DEFECTIVE BUSHINGS IN THE HANDLING BRACKETS ON THE TURBI		1,245	SR Technics Switzerland
672828	338-171-706-0	EASA;FAA;CAAC;ANAC			72-56-01		Package H	7	REPAIR OF THE DIAMETER MATING WITH THE LPT CASE		4,805	SR Technics Switzerland
672828	338-171-707-0	EASA;FAA;CAAC;ANAC			72-56-01		Package J	9	REPLACEMENT OF THE END FITTINGS ON THE OIL SUPPLY AND SCAVENGE TUBE		695	SR Technics Switzerland
672828	338-171-751-0	EASA;FAA;CAAC;ANAC			72-56-01		Package L	19	REPLACEMENT OF THE TUBE BOSS CONNECTION NIPPLE		1,720	SR Technics Switzerland
672828	338-171-752-0	EASA;FAA;CAAC;ANAC			72-56-01		Package M	46	REPAIR OF CRACKS IN WELD BEAD OF THE INSULATION BLANKET		1,835	SR Technics Switzerland
672828	338-173-801-0	EASA;FAA;CAAC;ANAC			72-56-01		Package N	22	REPLACEMENT OF THE DEFECTIVE STUDS ON THE FORWARD FACE OF THE INNEI		3,110	SR Technics Switzerland
672828					72-56-01		Package P	15	REPAIR OF THE DIAMETER MATING WITH THE EXHAUST NOZZLE		4,040	SR Technics Switzerland
672828					72-56-01		Package Q	20	WELD REPAIR OF CRACKS FOR WELDED ASSEMBLY FRAME		5,910	SR Technics Switzerland
672828					72-56-01		Package R	14	REPLACEMENT OF THE FIXATION ASSEMBLY OF THE OIL SUPPLY TUBE ASSEMBL		2,075	SR Technics Switzerland
672828					72-56-01		Package S	21	WELD REPAIR OF CRACKS <70MM		7,555	SR Technics Switzerland
672828					72-56-01		Package SB01	72-0499	REWORK AND REIDENTIFICATION OF THE OLD LPT FRAME TO PERMIT THE REPL THE OIL SUPPLY TUBE ON WING OR IN SHC		1,850	SR Technics Switzerland
672828					72-56-01		Package SB02	EASA-2021-0062	LPT REAR FRAMES - INSPECTION/REPLACEMENT		990	SR Technics Switzerland
672828					72-56-01		Package SB03	72-0716	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR ON SAC ENGINE		945	SR Technics Switzerland
672828					72-56-01		Package SB04	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1,080	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672828					72-56-01		Package SB05	72-0331	INTRODUCTION OF NEW COMPOSITE OGV		1,560	SR Technics Switzerland
672828					72-56-01		Package SB06	72-0403	LPT FRAME - REPL . OF OIL SUPPLY TUBE		1,345	SR Technics Switzerland
672828					72-56-01		Package SB07	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL S		1,560	SR Technics Switzerland
672828					72-56-01		Package SB10	EASA 2007-0221	TIME LIMIT AND LIFE REDUCTION		1,560	SR Technics Switzerland
672828					72-56-01		Package SB10	EASA-2014-0130	TIME LIMIT AND MANDATORY INSPECTION		1,560	SR Technics Switzerland
672828					72-56-01		Package SB10	FAA 2009-0110	TIME LIMIT AND MANDATORY INSPECTION		1,560	SR Technics Switzerland
672828					72-56-01		Package SB13	72-0118	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR FRAME ON DAC ENGINES		1,560	SR Technics Switzerland
672828					72-56-01		Package SB14	72-0850	INSPECTION OF TURBINE REAR FRAME		900	SR Technics Switzerland
672828					72-56-01		Package SB17	72-0734	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR FRAME ON DAC ENGINES		900	SR Technics Switzerland
672828					72-56-01		Package SB18	AD 2016-02-04	PREVENT FAILURE OF THE TRF ON THE LPT FRAME		1,535	SR Technics Switzerland
672828					72-56-01		Package SB19	72-0620	INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES		780	SR Technics Switzerland
672828					72-56-01		Package SB20	FAA 2009-18-01	THRESHOLDS INSPECTION FOR LPT REAR FRAMES		760	SR Technics Switzerland
672828					72-56-01		Package SB21		INSPECTION OF TRF (RADIUS DIAMETER K)		1,590	SR Technics Switzerland
672828					72-56-01		Package U	31	RECONDITIONING OF THE DIAMETER OIL SCAVENGE TUBE		6,325	SR Technics Switzerland
672828					72-56-01		Package V	16	REPAIR OF THE DIAMETER MATING WITH THE OIL SUMP ASSEMBLY		4,520	SR Technics Switzerland
672828					72-56-01		Package W	43	REPAIR OF CLEVIS MOUNT AREA		1,850	SR Technics Switzerland
672828					72-56-01		Package X	23	INSTALLATION OF BUSHING IN STUD HOLES		1,385	SR Technics Switzerland
672828					72-56-01		Package Y	15-93481	REPLACEMENT OF INSULATION		1,360	SR Technics Switzerland
672828					72-56-01		Package Z	17	FULL OR PART REPLACEMENT OF THE OIL SUPPLY TUBE ASSEMBLY		2,075	SR Technics Switzerland
673774	338-069-701-0	EASA;FAA;CAAC;ANAC	9	28	72-55-06	CFM56-5B LP TURBINE CENTER VENT TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		540	SR Technics Switzerland
673774	338-180-301-0	EASA;FAA;CAAC;ANAC			72-55-06		Package AN		REMOVE HIGH METAL	SPM 70-41-11	135	SR Technics Switzerland
673774	338-180-302-0	EASA;FAA;CAAC;ANAC			72-55-06		Package B	01	REPAIR OF THE FRONT AND/OR MID JOURNALS		2,185	SR Technics Switzerland
673774	338-180-303-0	EASA;FAA;CAAC;ANAC			72-55-06		Package C	02	REPAIR OF THE AFT JOURNAL		2,750	SR Technics Switzerland
673774	338-180-304-0	EASA;FAA;CAAC;ANAC			72-55-06		Package D	03	CENTRAL SECTION REPLACEMENT		3,820	SR Technics Switzerland
673774					72-55-06		Package E	04	REPLACEMENT OF ONE OR TWO MID JOURNAL SECTIONS		4,110	SR Technics Switzerland
673774					72-55-06		Package F	05	REPLACEMENT OF THE FORWARD SECTION		2,885	SR Technics Switzerland
673774					72-55-06		Package H	07	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4,355	SR Technics Switzerland
673774					72-55-06		Package I	08	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		2,285	SR Technics Switzerland
673774					72-55-06		Package J	09	LAST CLEANING AND CONDITIONING OF THE CENTER VENT TUBE		465	SR Technics Switzerland
673774					72-55-06		Package K	10	WELD BUILD UP OF THE REAR SLOTS FACES		2,000	SR Technics Switzerland
673774					72-55-06		Package L	11	REPAIR OF CRACK IN THE CENTRAL SECTION BY WELD BUILD-UP		2,485	SR Technics Switzerland
673774					72-55-06		Package O	14	REPAIR OF ILLEGIBLE PART MARKINGS		130	SR Technics Switzerland
673774					72-55-06		Package SB00	72-0753	INTRODUCTION OF A NEW CENTER VENT TUBE WITH NEW DAMPER SEAL AND R		1,865	SR Technics Switzerland
453	338-111-303-0	EASA;FAA;CAAC;ANAC	39	28	72-53-08	STAGE 1 LPT NOZZLE - REAR FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		1,155	SR Technics Switzerland
453	338-111-304-0	EASA;FAA;CAAC;ANAC			72-53-08		Package B	002	REPAIR OF THE PLASMA THERMAL COATING ON THE FACE MATING WITH THE S		2,840	SR Technics Switzerland
453	338-111-305-0	EASA;FAA;CAAC;ANAC			72-53-08		Package D	004	REPAIR OF THE MATING FACE BY PLASMA SPRAYING		2,980	SR Technics Switzerland
1518	1559M16G01	EASA;FAA;CAAC;ANAC	44	28	72-33-02	COMPRESSOR REAR STATOR - VANE SECTORS	Package A		BASIC REPAIR STAGE 6/7/8		250	SRTAS
1518	1559M16G02	EASA;FAA;CAAC;ANAC			72-33-02		Package A	CLN 001	CLEANING		250	SRTAS
1518	1559M16G03	EASA;FAA;CAAC;ANAC			72-33-02		Package A	INSP 001	VISUAL/DIMENSIONAL INSPECTION		250	SRTAS
1518	1559M16G04	EASA;FAA;CAAC;ANAC			72-33-02		Package B		FULL REPAIR STAGE 6/7/8		565	SRTAS
1518	1559M17G01	EASA;FAA;CAAC;ANAC			72-33-02		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		565	SRTAS
1518	1559M17G02	EASA;FAA;CAAC;ANAC			72-33-02		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		565	SRTAS
1518	1559M17G03	EASA;FAA;CAAC;ANAC			72-33-02		Package G		ADDITIONAL WORK SCOPE STAGE 6		135	SRTAS
1518	1559M17G04	EASA;FAA;CAAC;ANAC			72-33-02		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	135	SRTAS
1518	1559M18G01	EASA;FAA;CAAC;ANAC			72-33-02		Package H		ADDITIONAL WORK SCOPE STAGE 6		1,025	SRTAS
1518	1559M18G02	EASA;FAA;CAAC;ANAC			72-33-02		Package H	008	INNER PLATFORM J-HOOK REPAIR		1,025	SRTAS
1518	1559M18G03	EASA;FAA;CAAC;ANAC			72-33-02		Package N		ADDITIONAL WORK SCOPE STAGE 7		135	SRTAS

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1518	1559M18G04	EASA;FAA;CAAC;ANAC		72-33-02		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	135	SRTAS
1518	P206G05	EASA;FAA;CAAC;ANAC		72-33-02		Package O		ADDITIONAL WORK SCOPE STAGE 7		1,025	SRTAS
1518	P206G06	EASA;FAA;CAAC;ANAC		72-33-02		Package O	008	INNER PLATFORM J-HOOK REPAIR		1,025	SRTAS
1518	P206G07	EASA;FAA;CAAC;ANAC		72-33-02		Package U		ADDITIONAL WORK SCOPE STAGE 8		135	SRTAS
1518	P206G08	EASA;FAA;CAAC;ANAC		72-33-02		Package U	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	135	SRTAS
1518	P207G01	EASA;FAA;CAAC;ANAC		72-33-02		Package V		ADDITIONAL WORK SCOPE STAGE 8		1,025	SRTAS
1518	P207G02	EASA;FAA;CAAC;ANAC		72-33-02		Package V	008	INNER PLATFORM J-HOOK REPAIR		1,025	SRTAS
1518	P207G03	EASA;FAA;CAAC;ANAC									
1518	P207G04	EASA;FAA;CAAC;ANAC									
1518	P207G05	EASA;FAA;CAAC;ANAC									
1518	P207G06	EASA;FAA;CAAC;ANAC									
1518	P207G07	EASA;FAA;CAAC;ANAC									
1518	P207G08	EASA;FAA;CAAC;ANAC									
1518	P208G01	EASA;FAA;CAAC;ANAC									
1518	P208G02	EASA;FAA;CAAC;ANAC									
1518	P208G03	EASA;FAA;CAAC;ANAC									
1518	P208G04	EASA;FAA;CAAC;ANAC									
1518	P208G05	EASA;FAA;CAAC;ANAC									
1518	P208G06	EASA;FAA;CAAC;ANAC									
1518	P246G01	EASA;FAA;CAAC;ANAC									
1518	P246G02	EASA;FAA;CAAC;ANAC									
1518	P246G03	EASA;FAA;CAAC;ANAC									
1518	P246G04	EASA;FAA;CAAC;ANAC									
1518	P246G09	EASA;FAA;CAAC;ANAC									
1518	P247G01	EASA;FAA;CAAC;ANAC									
1518	P247G02	EASA;FAA;CAAC;ANAC									
1518	P247G03	EASA;FAA;CAAC;ANAC									
1518	P247G04	EASA;FAA;CAAC;ANAC									
1518	P247G09	EASA;FAA;CAAC;ANAC									
1518	P248G01	EASA;FAA;CAAC;ANAC									
1518	P248G02	EASA;FAA;CAAC;ANAC									
1518	P248G03	EASA;FAA;CAAC;ANAC									
1518	P248G04	EASA;FAA;CAAC;ANAC									
1518	P256G01	EASA;FAA;CAAC;ANAC									
1518	P256G02	EASA;FAA;CAAC;ANAC									
1518	P256G03	EASA;FAA;CAAC;ANAC									
1518	P256G04	EASA;FAA;CAAC;ANAC									
1518	P256G05	EASA;FAA;CAAC;ANAC									
1518	P256G06	EASA;FAA;CAAC;ANAC									
1518	P256G07	EASA;FAA;CAAC;ANAC									
1518	P256G08	EASA;FAA;CAAC;ANAC									
1518	P257G01	EASA;FAA;CAAC;ANAC									
1518	P257G02	EASA;FAA;CAAC;ANAC									
1518	P257G03	EASA;FAA;CAAC;ANAC									
1518	P257G04	EASA;FAA;CAAC;ANAC									
1518	P258G01	EASA;FAA;CAAC;ANAC									
1518	P258G02	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1518	P258G03	EASA;FAA;CAAC;ANAC									
1548	1476M51P01	EASA;FAA;CAAC;ANAC;CAA UK	34	28 72-32-13	COMPRESSOR FRONT STATOR - VSV ACTUATION HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION	PRICE PER STAGE	280	SR Technics Switzerland
1548	1476M80P01	EASA;FAA;CAAC;ANAC		72-32-13		Package B	002	REPAIR FOR THE STAGE 1, STAGE 2 AND STAGE 3 BELLCRANK BORES	PRICE PER STAGE	1,145	SR Technics Switzerland
1548	1558M35G01	EASA;FAA;CAAC;ANAC									
1548	1559M91P01	EASA;FAA;CAAC;ANAC									
1548	9511M24P04	EASA;FAA;CAAC;ANAC									
1548	9511M24P07	EASA;FAA;CAAC;ANAC;CAA UK									
1548	9511M26P02	EASA;FAA;CAAC;ANAC									
1820	1523M42G02	EASA;FAA;CAAC;ANAC	35	28 72-51-05	HIGH PRESSURE TURBINE NOZZLE - OUTER STATIONARY SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		915	SR Technics Switzerland
1820	1523M42G04	EASA;FAA;CAAC;ANAC		72-51-05		Package A	INSP-001	TI 315027 CRACKS IN SCALLOPS		915	SR Technics Switzerland
1820	1784M84G01	EASA;FAA;CAAC;ANAC		72-51-05		Package C	002	T400 WEARCOAT REPLACEMENT		2,360	SR Technics Switzerland
1820	1784M84G02	EASA;FAA;CAAC;ANAC		72-51-05		Package D	003	HONEYCOMB REPLACEMENT		8,560	SR Technics Switzerland
1820	1784M84G05	EASA;FAA;CAAC;ANAC		72-51-05		Package E	005	DIAMETER B DIMENSIONAL RESTORATION		2,805	SR Technics Switzerland
1820	1808M58G01	EASA;FAA;CAAC;ANAC		72-51-05		Package G	006	DIAMETER F MACHINING REPAIR		965	SR Technics Switzerland
1820	1808M58G03	EASA;FAA;CAAC;ANAC		72-51-05		Package SB00	72-0231	INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL		1,260	SR Technics Switzerland
1820	1808M58G05	EASA;FAA;CAAC;ANAC									
1820	1808M58G07	EASA;FAA;CAAC;ANAC									
1820	1808M58G08	EASA;FAA;CAAC;ANAC									
1820	2091M57G01	EASA;FAA;CAAC;ANAC									
1820	2091M57G02	EASA;FAA;CAAC;ANAC									
1820	2091M57G03	EASA;FAA;CAAC;ANAC									
2009	1498M45P03	EASA;FAA;CAAC;ANAC	52	28 72-52-05	HIGH PRESSURE TURBINE ROTOR - REAR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1,560	SR Technics Switzerland
2009	1498M45P04	EASA;FAA;CAAC;ANAC;TCCA		72-52-05		Package B	INSP-001	BLENDING AIRSEAL		320	SR Technics Switzerland
2009	1498M45P05	EASA;FAA;CAAC;ANAC		72-52-05		Package B	INSP-001	REMOVE HIGH METAL		320	SR Technics Switzerland
2009	1498M45P06	EASA;FAA;CAAC;ANAC		72-52-05		Package C	001	REPLACEMENT OF SEAL TEETH WEAR COATING		6,400	SR Technics Switzerland
2009	1498M45P07	EASA;FAA;CAAC;ANAC		72-52-05		Package F	005	THERMAL SPRAY REPAIR OF THE BEARING JOURNAL		7,975	SR Technics Switzerland
2009	1498M45P08	EASA;FAA;CAAC;ANAC		72-52-05		Package G	006	HPT AFT SHAFT THERMAL SPRAY REPAIR OF AREA M		7,810	SR Technics Switzerland
2009	1864M90P04	EASA;FAA;CAAC;ANAC;CAA UK		72-52-05		Package H	007	BUSHING REPLACEMENT		1,670	SR Technics Switzerland
2009	1864M90P05	EASA;FAA;CAAC;ANAC		72-52-05		Package M	012	BLEND ANTI-ROTATION SLOTS		705	SR Technics Switzerland
2009	1864M90P06	EASA;FAA;CAAC;ANAC		72-52-05		Package SB00	72-0224	HPT REAR SHAFT AND BUSHING REWORK		2,545	SR Technics Switzerland
2009	1864M90P07	EASA;FAA;CAAC;ANAC									
2009	1873M62G02	EASA;FAA;CAAC;ANAC									
2009	1873M62G03	EASA;FAA;CAAC;ANAC									
2009	1873M62G04	EASA;FAA;CAAC;ANAC									
2009	1873M62G05	EASA;FAA;CAAC;ANAC									
2082	1493M73G04	EASA;FAA;CAAC;ANAC	29	28 72-42-00	COMBUSTION CHAMBER (SAC)	Package A	CLN/INSP	CLEANING AND INSPECTION		4,610	SR Technics Switzerland
2082	1493M73G06	EASA;FAA;CAAC;ANAC		72-42-00		Package F		DISASSEMBLY AND ASSEMBLY	EXCLUDED PIECE PART REPAIRS	3,855	SR Technics Switzerland
2082	1493M73G08	EASA;FAA;CAAC;ANAC		72-42-00		Package SB00	72-0327	INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY	IN CONJUNCTION WITH PACKAGE F	285	SR Technics Switzerland
2082	1968M41G01	EASA;FAA;CAAC;ANAC		72-42-00		Package SB01	72-0765	NEW OUTER LINER FOR HARSH ENVIRONMENT OPERATORS	IN CONJUNCTION WITH PACKAGE F	285	SR Technics Switzerland
2082	1968M41G02	EASA;FAA;CAAC;ANAC		72-42-00		Package SB02	72-0273	COMBUSTION DOME SWIRLER SUPPORT ELIMINATION	IN CONJUNCTION WITH PACKAGE F	285	SR Technics Switzerland
2082	1968M41G03	EASA;FAA;CAAC;ANAC		72-42-00		Package SB05	72-0586	ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS IN CONJUNCTION WITH PACKAGE F		285	SR Technics Switzerland
2082	1968M41G04	EASA;FAA;CAAC;ANAC		72-42-00		Package SB08	72-0237	COMBUSTION CHAMBER INNER COWL BOLT INSPECTION	IN CONJUNCTION WITH PACKAGE F	970	SR Technics Switzerland
2082	1968M46G08	EASA;FAA;CAAC;ANAC		72-42-00		Package SB09	72-0782	NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATO	IN CONJUNCTION WITH PACKAGE F	285	SR Technics Switzerland
2082	1968M46G10	EASA;FAA;CAAC;ANAC		72-42-00		Package SB10	72-0852	INTRODUCTION OF NEW COMBUSTION CHAMBER ASSEMBLY	IN CONJUNCTION WITH PACKAGE F	285	SR Technics Switzerland
2082	1968M65G01	EASA;FAA;CAAC;ANAC									
2082	1968M65G03	EASA;FAA;CAAC;ANAC									
2082	1968M68G04	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2082	1968M68G06	EASA;FAA;CAAC;ANAC										
2082	1968M68G07	EASA;FAA;CAAC;ANAC										
2082	1968M68G08	EASA;FAA;CAAC;ANAC										
2082	1968M68G16	EASA;FAA;CAAC;ANAC										
2082	1968M68G17	EASA;FAA;CAAC;ANAC										
2082	1968M68G19	EASA;FAA;CAAC;ANAC										
2082	1968M68G20	EASA;FAA;CAAC;ANAC										
2082	1968M68G22	EASA;FAA;CAAC;ANAC										
2082	1968M68G41	EASA;FAA;CAAC;ANAC										
2082	2256M26G03	EASA;FAA;CAAC;ANAC										
2082	2256M26G04	EASA;FAA;CAAC;ANAC										
2082	2480M46G01	EASA;FAA;CAAC;CAAC;ANAC										
2187	305-136-803-0	EASA;FAA;CAAC;ANAC;CAA UK	22	28	72-62-06	TRANSFER GEARBOX - HORIZONTAL DRIVE SHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1,215	SR Technics Switzerland
2187	305-136-804-0	EASA;ANAC;CAA UK			72-62-06		Package SB00	72-1078	RE-IDENT OF RADIAL DRIVE SHAFT IN FIELD		305	SR Technics Switzerland
2187	305-136-805-0	EASA;FAA;CAAC;ANAC;CAA UK			72-62-06		Package SB01	72-1109	REMOVAL FROM SERVICE OF SUSPECTED RADIAL DRIVE SHAFT		190	SR Technics Switzerland
2187	340-050-101-0	EASA;FAA;CAAC;ANAC										
2187	340-050-102-0	EASA;FAA;CAAC;ANAC										
2187	340-050-103-0	EASA;FAA;CAAC;ANAC										
2187	340-051-101-0	EASA;FAA;CAAC;ANAC										
2716	238-0851-509	EASA;FAA;CAAC;ANAC	9	21	26-10-00	CFM56-5B FIRE DETECTOR INSTALLATION	Package B		TEST		1,320	SR Technics Switzerland
2716	642-5855-501	EASA;FAA;CAAC;ANAC										
2716	642-5855-503	EASA;FAA;CAAC;ANAC										
3016	9324M67G01	EASA;FAA;ANAC	23	28	72-33-00	COMPRESSOR REAR STATOR - ASSEMBLY	Package B	ASSEMBLY	HONEY COMB GRINDING	PN9324M67G01 9324M77G01 FOR SHOP V	2,005	SR Technics Switzerland
3249	108280-199	EASA;FAA;CAAC;ANAC	38	21	71-00-17	TUBES, DUCTS AND HOSES	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	490	SR Technics Switzerland
3249	108280-211	EASA;FAA;CAAC;ANAC			71-00-17		Package A	TEST	PRESSURE TEST	FOR SHOP VISITS ONLY	490	SR Technics Switzerland
3249	108280-53	EASA;FAA;CAAC;ANAC			71-00-17		Package B	1	BLEND REPAIR OF EXTERNAL TUBING, FIRE DETECTOR SUPPORT RAILS		395	SR Technics Switzerland
3249	110551-503	EASA;FAA;CAAC;ANAC			71-00-17		Package C	2	EXPASION REPAIR OF SMOOTH DENTS		390	SR Technics Switzerland
3249	110560-17	EASA;FAA;ANAC			71-00-17		Package D	3	WELD REPAIR CRACKS		395	SR Technics Switzerland
3249	112441-507	EASA;FAA;CAAC;ANAC			71-00-17		Package E	4	DOUBLE REPAIR AND SECTION REPLACEMENT		430	SR Technics Switzerland
3249	116854-507	EASA;FAA;CAAC;ANAC			71-00-17		Package J	9	WELD REPAIR FOR ANTI-ICE DUCT SHROUD ADAPTER CRACKS		505	SR Technics Switzerland
3249	14495-505	EASA;FAA;CAAC;ANAC			71-00-17		Package K	10	ANTI-ICE DUCT AIRGAB INSULATION REPAIR		540	SR Technics Switzerland
3249	14495-507	EASA;FAA;CAAC;ANAC			71-00-17		Package L	11	REPLACEMENT OF AERODYNAMIC SEALANT		295	SR Technics Switzerland
3249	17451-519	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FITTING SILVER DRAIN MANIFOLD - REPLACE ELBOW FITTI		770	SR Technics Switzerland
3249	17451-525	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FITTING SILVER DRAIN RESERVOIR - REPLACE ELBOW FITTI		770	SR Technics Switzerland
3249	17452-503	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FITTING SILVER DRAIN MANIFOLD - REPLACE UNION FITTII		770	SR Technics Switzerland
3249	238-0502-503	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FITTING SILVER DRAIN RESERVOIR - REPLACE UNION FITTII		770	SR Technics Switzerland
3249	238-0602-503	EASA;FAA;CAAC;ANAC;CAA UK			71-00-17		Package Q	16	HIGH EMISSIVITY COATING REPAIR		675	SR Technics Switzerland
3249	238-0612-503	EASA;FAA;CAAC;ANAC			71-00-17		Package S	18	WELD BUILD-UP BRACKET		1,055	SR Technics Switzerland
3249	238-0701-523	EASA;FAA;CAAC;ANAC			71-00-17		Package S	18	REMOVE DAMAGED BRACKET		1,055	SR Technics Switzerland
3249	238-0701-525	EASA;FAA;CAAC;ANAC			71-00-17		Package SB00	RA32036-10	PNEUMATIC - UPPER 9TH STAGE HIGH PRESSURE DUCT SUPPORT LINK REMOV		450	SR Technics Switzerland
3249	238-0701-527	EASA;FAA;CAAC;ANAC			71-00-17		Package SB01	RA32036-13	INSPECTION OF THE UPPER 9TH STAGE HP DUCT AND SUPPORT LINKS		525	SR Technics Switzerland
3249	238-0701-529	EASA;FAA;CAAC;ANAC			71-00-17		Package SB02	RA32036-11	INSPECTION AND MODIFICATION OF PLYON INTERFACE DUCT		610	SR Technics Switzerland
3249	238-0801-512	EASA;FAA;CAAC;ANAC			71-00-17		Package SB03	RA32030-4	ANTI-ICE DUCT INSULATION PAN-DOWN MODIFICATION		360	SR Technics Switzerland
3249	238-0801-513	EASA;FAA;CAAC;ANAC			71-00-17		Package SB04	RA32036-13	INSPECTION OF THE LOWER 9TH STAGE HP DUCT AND SUPPORT LINKS		260	SR Technics Switzerland
3249	238-0801-535	EASA;FAA;CAAC;ANAC										
3249	238-0801-539	EASA;FAA;CAAC;ANAC										
3249	238-0801-541	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3249	238-0801-543	EASA;FAA;CAAC;ANAC										
3249	238-0801-545	EASA;FAA;CAAC;ANAC										
3249	238-0801-547	EASA;FAA;CAAC;ANAC										
3249	238-0801-549	EASA;FAA;CAAC;ANAC										
3249	238-0801-551	EASA;FAA;CAAC;ANAC										
3249	238-0801-557	EASA;FAA;CAAC;ANAC										
3249	238-0801-561	EASA;FAA;CAAC;ANAC										
3249	238D0551-509	EASA;FAA;CAAC;ANAC										
3249	238D0551-517	EASA;FAA;CAAC;ANAC										
3249	238D0551-519	EASA;FAA;CAAC;ANAC										
3249	238D0561-503	EASA;FAA;CAAC;ANAC										
3249	238D0611-505	EASA;FAA;CAAC;ANAC										
3249	238D0611-507	EASA;FAA;CAAC;ANAC										
3249	238D0611-509	EASA;FAA;ANAC										
3249	642-5503-501	EASA;FAA;CAAC;ANAC										
3249	642-5508-503	EASA;FAA;CAAC;ANAC										
3249	642-5508-505	EASA;FAA;CAAC;ANAC										
3249	642-5510-501	EASA;FAA;CAAC;ANAC										
3249	642-5511-503	EASA;FAA;CAAC;ANAC										
3249	642-5515-507	EASA;FAA;CAAC;ANAC										
3249	642-5520-507	EASA;FAA;CAAC;ANAC										
3249	642-5612-501	EASA;FAA;CAAC;ANAC										
3249	642-5612-503	EASA;FAA;CAAC;ANAC										
3249	642-5658-501	EASA;FAA;CAAC;ANAC										
3249	642-5658-503	EASA;FAA;CAAC;ANAC										
3249	642-5658-505	EASA;FAA;CAAC										
3249	642-5754-501	EASA;FAA;CAAC;ANAC										
3249	642-5754-503	EASA;FAA;CAAC;ANAC										
3249	642-5754-505	EASA;FAA;CAAC;ANAC										
3249	642-5754-507	EASA;FAA;CAAC;ANAC										
3249	642-5801-507	EASA;FAA;CAAC;ANAC										
3249	642-5801-509	EASA;FAA;CAAC;ANAC										
3249	642-5801-511	EASA;FAA;CAAC;ANAC										
3249	642-5801-515	EASA;FAA;CAAC;ANAC										
3249	642-5801-517	EASA;FAA;CAAC;ANAC										
3249	642-5801-519	EASA;FAA;CAAC;ANAC										
3249	642-5801-521	EASA;FAA;CAAC;ANAC										
3249	642-5926-501	EASA;FAA;CAAC;ANAC										
3249	642-5926-503	EASA;FAA;CAAC;ANAC										
3249	642-5926-504	EASA;FAA;CAAC;ANAC										
3249	642D5752-501	EASA;FAA;CAAC;ANAC										
3249	9909873-103	EASA;FAA;CAAC;ANAC										
3249	9909874-107	EASA;FAA;CAAC;ANAC										
3249	9909874-207	EASA;FAA;CAAC;ANAC										
3249	9909875-103	EASA;FAA;CAAC;ANAC										
3249	AE705925-31	EASA;FAA;ANAC;CAA UK										
3249	AE705926-19	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3249	AE705926-23	EASA;FAA;CAAC;ANAC										
3249	AE705926-25	EASA;FAA;CAAC;ANAC										
3249	AE706058-65	EASA;FAA;CAAC;ANAC										
3249	AE706058-8	EASA;FAA;CAAC;ANAC										
3249	AE707418-1	EASA;FAA;ANAC										
3249	AE707419-1	EASA;FAA;CAAC;ANAC										
3249	AE707419-3	EASA;FAA;CAAC;ANAC										
3249	AE707422-1	EASA;FAA;CAAC;ANAC										
3249	AE707422-2	EASA;FAA;CAAC;ANAC										
3249	AE707422-3	EASA;FAA;CAAC;ANAC										
3249	AE708821-1	EASA;FAA;CAAC;ANAC										
3249	AE708821-2	EASA;FAA;CAAC;ANAC										
3249	AE709459-3	EASA;FAA;CAAC;ANAC										
3249	AE709461-1	EASA;FAA;CAAC;ANAC										
3249	AE710155-1	EASA;FAA;CAAC;ANAC										
3249	S700H0391-199	EASA;FAA;CAAC;ANAC										
3249	S700H0391-211	EASA;FAA;CAAC;ANAC										
3249	S700H0391-53	EASA;FAA;CAAC;ANAC										
3249	S700H0981-17	EASA;FAA;CAAC;ANAC										
3461	301-480-220-0	EASA;FAA;CAAC;ANAC	22	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BII RE Package A	CLN/INSP		CLEANING AND INSPECTION		1,470	SR Technics Switzerland
3461	301-480-221-0	EASA;FAA;CAAC;ANAC										
3461	301-480-225-0	EASA;FAA;CAAC;ANAC										
3461	301-480-320-0	EASA;FAA;CAAC;ANAC										
3461	301-480-326-0	EASA;FAA;CAAC;ANAC										
3461	301-480-720-0	EASA;FAA;CAAC;ANAC										
3461	301-480-724-0	EASA;FAA;CAAC;ANAC										
3461	301-480-726-0	EASA;FAA;CAAC;ANAC										
3461	301-480-920-0	EASA;FAA;CAAC;ANAC										
3461	301-480-923-0	EASA;FAA;CAAC;ANAC										
3461	301-480-926-0	EASA;FAA;CAAC;ANAC										
3461	301-481-220-0	EASA;FAA;CAAC;ANAC										
3461	301-481-223-0	EASA;FAA;CAAC;ANAC										
3461	301-481-225-0	EASA;FAA;CAAC;ANAC										
3461	305-100-410-0	EASA;FAA;CAAC;ANAC										
3461	305-100-415-0	EASA;FAA;CAAC;ANAC										
3461	305-115-100-0	EASA;FAA;CAAC;ANAC										
3461	305-115-104-0	EASA;FAA;CAAC;ANAC;CAA UK										
3461	305-115-200-0	EASA;FAA;CAAC;ANAC										
3461	305-115-201-0	EASA;FAA;CAAC;ANAC										
3461	305-115-205-0	ANAC										
3461	305-115-300-0	EASA;FAA;CAAC;ANAC										
3461	305-115-306-0	EASA;FAA;CAAC;ANAC										
3461	305-132-701-0	EASA;FAA;CAAC;ANAC										
3461	305-132-702-0	EASA;FAA;CAAC;ANAC										
3461	305-148-201-0	EASA;FAA;CAAC;ANAC										
3461	305-148-202-0	EASA;FAA;CAAC;ANAC										
3461	335-304-101-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	335-304-102-0	EASA;FAA;CAAC;ANAC									
3461	335-304-103-0	EASA;FAA;CAAC;ANAC									
3461	335-304-104-0	EASA;CAAC;EASA/ANAC BRAZIL D									
3461	335-304-201-0	EASA;FAA;CAAC;ANAC									
3461	335-304-202-0	EASA;FAA;CAAC;ANAC									
3461	335-304-203-0	EASA;FAA;CAAC;ANAC									
3461	335-304-401-0	EASA;FAA;CAAC;ANAC									
3461	335-304-402-0	EASA;FAA;CAAC;ANAC									
3461	335-304-403-0	EASA;FAA;CAAC									
3461	335-304-501-0	EASA;FAA;CAAC;ANAC									
3461	335-304-503-0	EASA;FAA;CAAC;ANAC									
3461	335-304-601-0	EASA;FAA;CAAC;ANAC									
3461	335-304-602-0	EASA;FAA;CAAC;ANAC									
3461	335-304-603-0	EASA;FAA;CAAC;ANAC									
3461	335-304-901-0	EASA;FAA;CAAC;ANAC									
3461	335-304-902-0	EASA;FAA;CAAC;ANAC									
3461	335-304-903-0	EASA;FAA;CAAC;ANAC									
3461	340-050-401-0	EASA;FAA;CAAC;ANAC									
3461	340-050-402-0	EASA;FAA;CAAC;ANAC									
3461	340-050-404-0	EASA;FAA;CAAC;ANAC									
3461	340-050-901-0	EASA;FAA;CAAC;ANAC									
3461	340-050-902-0	EASA;FAA;CAAC;ANAC									
3461	340-051-001-0	EASA;FAA;CAAC;ANAC									
3461	340-051-002-0	EASA;FAA;CAAC;ANAC									
3461	340-052-502-0	EASA;FAA;CAAC;ANAC									
3461	340-052-503-0	EASA;FAA;CAAC;ANAC									
3461	340-052-602-0	EASA;FAA;CAAC;ANAC									
3461	340-052-603-0	EASA;FAA;CAAC;ANAC									
3461	340-054-502-0	EASA;FAA;CAAC;ANAC									
3461	340-054-503-0	EASA;FAA;CAAC;ANAC									
3461	340-055-801-0	EASA;FAA;CAAC;ANAC									
3461	340-055-901-0	EASA;FAA;CAAC;ANAC									
3461	340-056-001-0	EASA;FAA;CAAC;ANAC									
3461	340-056-101-0	EASA;FAA;CAAC;ANAC									
3461	340-056-102-0	EASA;FAA;ANAC;CAA UK									
3461	340-056-202-0	EASA;FAA;CAAC;ANAC									
3461	340-056-302-0	EASA;FAA;CAAC;ANAC									
3461	340-056-401-0	EASA;FAA;CAAC;ANAC									
3461	340-154-101-0	EASA;FAA;CAAC;ANAC									
3461	340-154-201-0	EASA;FAA;CAAC;ANAC									
3461	340-155-101-0	EASA;FAA;CAAC;ANAC									
3461	9541M89P01	EASA;FAA;CAAC;ANAC									
3461	9725M84P08	EASA;FAA;CAAC;ANAC									
3461	9725M84P09	EASA;FAA;CAAC;ANAC									
3461	9972M33P06	EASA;FAA;CAAC;ANAC									
3461	9972M33P07	EASA;FAA;CAAC;ANAC;CAA UK									
3461	9972M33P08	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	9972M34P08	EASA;FAA;CAAC;ANAC										
3461	9972M34P09	EASA;FAA;CAAC;ANAC										
3461	9972M34P10	EASA;FAA;CAAC;ANAC										
3941	J816P050A	EASA;FAA;CAAC;ANAC	8	28	72-21-11	CFM56 BOLT-SHEAR DBL HEX HD FAN AND BOOS	Package A	CLN/INSP	CLEANING AND INSPECTION		45	SR Technics Switzerland
3941	J818P060A	EASA;FAA;CAAC;ANAC										
7611	390-610-001-0	EASA;FAA;CAAC;ANAC	8	21	73-21-94	CFM56-5B IDENTIFICATION PLUG (PUSH - PULL)	Package A	TEST	TESTING AND TROUBLESHOOTING		380	SR Technics Switzerland
7611	390-610-501-0	EASA;FAA;CAAC;ANAC			73-21-94		Package B		REPAIR		860	SR Technics Switzerland
7611	390-611-001-0	EASA;FAA;CAAC;ANAC			73-21-94		Package C		OVERHAUL		1,300	SR Technics Switzerland
7611	390-611-101-0	EASA;FAA;CAAC;ANAC			73-21-94		Package SB00	SB 72-0340	INTRODUCTION OF NEW RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATI		345	SR Technics Switzerland
7611	390-611-201-0	EASA;FAA;CAAC;ANAC			73-21-94		Package SB01	SB 73-0218	INTRODUCTION OF NEW CODING FOR TECH INSERTION ENGINE MODELS		345	SR Technics Switzerland
7611	390-611-301-0	EASA;FAA;CAAC;ANAC;CAA UK			73-21-94		Package SB02	SB 73-0219	INTRODUCTION OF NEW COING FOR TECH INSERTION ENGINE MODELS		345	SR Technics Switzerland
7611	390-611-401-0	EASA;FAA;CAAC;ANAC;CAA UK										
7611	390-611-501-0	EASA;FAA;CAAC;ANAC										
7611	390-611-601-0	EASA;FAA;CAAC;ANAC										
7611	390-611-801-0	EASA;FAA;CAAC;ANAC										
8459	238-0802-503	EASA;FAA;CAAC;ANAC;CAA UK	17	21	71-70-00	DRAIN MODULE MANIFOLD	Package B	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED P FOR SHOP VISITS ONLY		670	SR Technics Switzerland
8459	238-0804-503	EASA;FAA;CAAC;ANAC			71-70-00		Package M	012	REPAIR		2,025	SR Technics Switzerland
8459	238-0811-501	EASA;FAA;CAAC;ANAC										
11542	301-792-202-0	EASA;FAA;CAAC;ANAC	45	28	72-23-35	FAN FRAME ASSEMBLY - FAN FRAME HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	150	SR Technics Switzerland
11542	301-792-302-0	EASA;FAA;CAAC;ANAC										
11542	305-355-901-0	EASA;FAA;ANAC										
11542	337-060-801-0	EASA;FAA;ANAC										
11542	338-077-001-0	EASA;FAA;ANAC										
11542	340-005-202-0	EASA;FAA;CAAC;ANAC										
11542	340-005-301-0	EASA;FAA;CAAC;ANAC										
11542	340-005-302-0	EASA;FAA;CAAC;ANAC										
11542	340-005-401-0	EASA;FAA;CAAC;ANAC										
11542	340-005-402-0	EASA;FAA;CAAC;ANAC										
11542	340-005-502-0	EASA;FAA;CAAC;ANAC										
11542	340-005-602-0	EASA;FAA;CAAC;ANAC										
11542	340-005-801-0	EASA;FAA;CAAC;ANAC										
11542	340-005-802-0	EASA;FAA;CAAC;ANAC										
11542	340-006-202-0	EASA;FAA;CAAC;ANAC										
11542	340-006-301-0	EASA;FAA;CAAC;ANAC										
11542	340-006-502-0	EASA;FAA;CAAC;ANAC										
11542	340-006-503-0	EASA;FAA;CAAC;ANAC										
11542	340-006-504-0	EASA;FAA;CAAC;ANAC										
11542	340-006-602-0	EASA;FAA;CAAC;ANAC										
11542	340-006-603-0	EASA;FAA;CAAC;ANAC										
11542	340-006-604-0	EASA;CAAC;EASA/ANAC BRAZIL D										
11542	340-006-702-0	EASA;FAA;CAAC;ANAC										
11542	340-006-703-0	EASA;FAA;CAAC;ANAC										
11542	340-006-802-0	EASA;FAA;CAAC;ANAC										
11542	340-006-803-0	EASA;FAA;CAAC;ANAC										
11542	340-007-304-0	EASA;FAA;CAAC;ANAC										
11542	340-007-404-0	EASA;FAA;CAAC;ANAC										
11542	340-008-703-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-008-801-0	EASA;FAA;CAAC;ANAC										
11542	340-008-902-0	EASA;FAA;CAAC;ANAC										
11542	340-008-903-0	EASA;FAA;CAAC;ANAC										
11542	340-008-904-0	EASA;FAA;CAAC;ANAC										
11542	340-009-003-0	EASA;FAA;CAAC;ANAC										
11542	340-009-004-0	EASA;FAA;CAAC;ANAC										
11542	340-013-703-0	EASA;FAA;CAAC;ANAC										
11542	340-015-003-0	EASA;FAA;CAAC;ANAC										
11542	340-015-004-0	EASA;FAA;CAAC;ANAC										
11542	340-017-002-0	EASA;FAA;CAAC;ANAC										
11542	340-017-305-0	EASA;FAA;CAAC;ANAC										
11542	340-017-306-0	EASA;FAA;CAAC;ANAC										
11542	340-017-502-0	EASA;FAA;CAAC;ANAC										
11542	340-017-601-0	EASA;FAA;CAAC;ANAC										
11542	340-017-602-0	EASA;FAA;CAAC;ANAC										
11542	340-017-804-0	EASA;FAA;CAAC;ANAC										
11542	340-017-805-0	EASA;FAA;CAAC;ANAC										
11542	340-017-806-0	EASA;FAA;CAAC;ANAC										
11542	340-019-903-0	EASA;FAA;CAAC;ANAC										
11542	340-020-001-0	EASA;FAA;CAAC;ANAC										
11542	340-020-105-0	EASA;FAA;CAAC;ANAC										
11542	340-020-203-0	EASA;FAA;CAAC;ANAC										
11542	340-020-303-0	EASA;FAA;CAAC;ANAC										
11542	340-020-403-0	EASA;FAA;CAAC;ANAC										
11542	340-020-404-0	EASA;FAA;CAAC;ANAC										
11542	340-022-501-0	EASA;FAA;CAAC;ANAC										
11542	340-022-502-0	EASA;FAA;CAAC;ANAC										
11542	340-022-901-0	EASA;FAA;CAAC;ANAC										
11542	340-023-301-0	EASA;FAA;CAAC;ANAC										
11542	340-023-302-0	EASA;FAA;CAAC;ANAC										
11542	340-023-404-0	EASA;FAA;CAAC;ANAC										
11542	340-023-405-0	EASA;FAA;CAAC;ANAC										
11542	340-025-402-0	EASA;FAA;CAAC;ANAC										
11542	340-025-503-0	EASA;FAA;CAAC;ANAC										
11542	340-087-804-0	EASA;FAA;CAAC;ANAC										
11542	340-088-503-0	EASA;FAA;CAAC;ANAC										
11542	340-088-602-0	EASA;FAA;CAAC;ANAC										
11542	340-088-901-0	EASA;FAA;CAAC;ANAC										
11542	340-089-001-0	EASA;FAA;CAAC;ANAC										
11542	340-090-301-0	EASA;FAA;CAAC;ANAC										
11542	340-090-402-0	EASA;FAA;CAAC;ANAC										
11542	340-090-501-0	EASA;FAA;CAAC;ANAC										
11542	340-090-601-0	EASA;FAA;CAAC;ANAC										
11542	340-090-602-0	EASA;FAA;CAAC;ANAC										
11542	340-090-603-0	EASA;FAA;CAAC;ANAC										
11542	340-090-701-0	EASA;FAA;CAAC;ANAC										
11542	340-090-804-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-090-902-0	EASA;FAA;CAAC;ANAC										
11542	340-091-001-0	EASA;FAA;CAAC;ANAC										
11542	340-091-403-0	EASA;FAA;CAAC;ANAC										
11542	340-093-701-0	EASA;FAA;CAAC;ANAC										
11542	340-095-501-0	EASA;FAA;CAAC;ANAC										
11542	340-095-602-0	EASA;FAA;CAAC;ANAC										
11542	340-095-603-0	EASA;FAA;CAAC;ANAC										
11542	340-095-703-0	EASA;FAA;CAAC;ANAC										
11542	340-096-003-0	EASA;FAA;CAAC;ANAC										
11542	340-096-004-0	EASA;FAA;CAAC;ANAC										
11542	340-096-005-0	EASA;FAA;ANAC										
11542	340-096-006-0	EASA;FAA;CAAC;ANAC										
11542	340-099-001-0	EASA;FAA;CAAC;ANAC										
11542	340-099-101-0	EASA;FAA;CAAC;ANAC										
11542	340-099-902-0	EASA;FAA;CAAC;ANAC										
11542	340-099-903-0	EASA;FAA;CAAC;ANAC										
11542	340-103-902-0	EASA;FAA;CAAC;ANAC										
11542	340-103-903-0	EASA;FAA;CAAC;ANAC										
11542	340-104-301-0	EASA;FAA;CAAC;ANAC										
11542	340-104-601-0	EASA;FAA;CAAC;ANAC										
11542	340-105-903-0	EASA;FAA;CAAC;ANAC										
11542	340-106-005-0	EASA;FAA;CAAC;ANAC										
11542	340-106-006-0	EASA;FAA;CAAC;ANAC										
11542	340-106-007-0	EASA;FAA;CAAC;ANAC										
11542	340-106-203-0	EASA;FAA;CAAC;ANAC										
11542	340-106-302-0	EASA;FAA;CAAC;ANAC										
11542	340-106-504-0	EASA;FAA;CAAC;ANAC										
11542	340-106-602-0	EASA;FAA;CAAC;ANAC										
11542	340-106-704-0	EASA;FAA;CAAC;ANAC										
11542	340-109-601-0	EASA;FAA;CAAC;ANAC										
11542	340-109-602-0	EASA;FAA;CAAC;ANAC										
11542	340-112-113-0	EASA;FAA;CAAC;ANAC										
11542	340-115-302-0	EASA;FAA;CAAC;ANAC										
11542	340-115-303-0	EASA;FAA;CAAC;ANAC										
11542	340-118-303-0	EASA;FAA;CAAC;ANAC										
11542	340-118-702-0	EASA;FAA;CAAC;ANAC										
11542	340-118-704-0	EASA;FAA;CAAC;ANAC										
11542	340-118-705-0	EASA;FAA;CAAC;ANAC										
11542	340-119-701-0	EASA;FAA;CAAC;ANAC										
11542	340-119-803-0	EASA;FAA;CAAC;ANAC										
11542	340-120-501-0	EASA;FAA;CAAC;ANAC										
11542	340-120-601-0	EASA;FAA;CAAC;ANAC										
11542	340-120-702-0	EASA;FAA;CAAC;ANAC										
11542	340-120-803-0	EASA;FAA;CAAC;ANAC										
11542	340-120-901-0	EASA;FAA;CAAC;ANAC										
11542	340-121-001-0	EASA;FAA;CAAC;ANAC										
11542	340-121-101-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-121-201-0	EASA;FAA;CAAC;ANAC										
11542	340-121-401-0	EASA;FAA;CAAC;ANAC										
11542	340-121-502-0	EASA;FAA;CAAC;ANAC										
11542	340-121-602-0	EASA;FAA;CAAC;ANAC										
11542	340-121-702-0	EASA;FAA;CAAC;ANAC										
11542	340-121-802-0	EASA;FAA;CAAC;ANAC										
11542	340-122-501-0	EASA;FAA;CAAC;ANAC										
11542	340-122-502-0	EASA;FAA;CAAC;ANAC										
11542	340-122-503-0	EASA;FAA;CAAC;ANAC										
11542	340-122-504-0	EASA;FAA;CAAC;ANAC										
11542	340-123-401-0	EASA;FAA;CAAC;ANAC										
11542	340-123-703-0	EASA;FAA;CAAC;ANAC										
11542	340-123-704-0	EASA;FAA;CAAC;ANAC										
11542	340-123-803-0	EASA;FAA;CAAC;ANAC										
11542	340-123-902-0	EASA;FAA;CAAC;ANAC										
11542	340-124-001-0	EASA;FAA;CAAC;ANAC										
11542	340-124-101-0	EASA;FAA;CAAC;ANAC										
11542	340-124-202-0	EASA;FAA;CAAC;ANAC										
11542	340-124-302-0	EASA;FAA;CAAC;ANAC										
11542	340-124-402-0	EASA;FAA;CAAC;ANAC										
11542	340-124-501-0	EASA;FAA;CAAC;ANAC										
11542	340-124-502-0	EASA;FAA;CAAC;ANAC										
11542	340-124-604-0	EASA;FAA;CAAC;ANAC										
11542	340-124-605-0	EASA;FAA;CAAC;ANAC										
11542	340-124-701-0	EASA;FAA;CAAC;ANAC										
11542	340-124-801-0	EASA;FAA;CAAC;ANAC										
11542	340-124-802-0	EASA;FAA;CAAC;ANAC										
11542	340-124-803-0	EASA;FAA;ANAC										
11542	340-125-702-0	EASA;FAA;CAAC;ANAC										
11542	340-125-703-0	EASA;FAA;CAAC;ANAC										
11542	340-126-102-0	EASA;FAA;CAAC;ANAC										
11542	340-126-104-0	EASA;FAA;CAAC;ANAC										
11542	340-126-107-0	EASA;FAA;ANAC										
11542	340-126-701-0	EASA;FAA;CAAC;ANAC										
11542	340-126-702-0	EASA;FAA;CAAC;ANAC										
11542	340-126-802-0	EASA;FAA;CAAC;ANAC										
11542	340-128-302-0	EASA;FAA;CAAC;ANAC										
11542	340-128-303-0	EASA;FAA;CAAC;ANAC										
11542	340-130-001-0	EASA;FAA;CAAC;ANAC										
11542	340-130-701-0	EASA;FAA;CAAC;ANAC										
11542	340-131-208-0	EASA;FAA;CAAC;ANAC										
11542	340-134-302-0	EASA;FAA;CAAC;ANAC										
11542	340-150-702-0	EASA;FAA;CAAC;ANAC										
11542	340-159-301-0	EASA;FAA;CAAC;ANAC										
11542	649-002-265-0	EASA;FAA;CAAC;ANAC										
11542	649-771-090-0	EASA;FAA;CAAC;ANAC										
11542	649-771-092-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	649-771-093-0	EASA;FAA;CAAC;ANAC										
11542	649-786-799-0	EASA;FAA;CAAC;ANAC										
11542	J534P04	EASA;FAA;CAAC;ANAC										
11542	J534P08	EASA;FAA;CAAC;ANAC										
11542	J534P54	EASA;FAA;CAAC;ANAC										
12552	ALL450-001-0	EASA;FAA;CAAC;ANAC	5	21	71-00-01	CFM56-5B ADAPTER RING KIT V-GROOVE	Package B	SPEC-PROC-002	MAJOR DAMAGE-REPLACE		1,140	SR Technics Switzerland
12552	ALL450-003-0	EASA;FAA;CAAC;ANAC			71-00-01		Package B	SPEC-PROC-002	INSPECTION V-GROOVE	FOR SHOP VISITS ONLY	1,140	SR Technics Switzerland
13451	301-566-807-0	EASA;FAA;CAAC;ANAC	24	28	72-23-10	FAN FRAME ASSEMBLY - AGB STRAIGHT MOUNT PIN	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	155	SR Technics Switzerland
13451	336-030-701-0	EASA;FAA;CAAC;ANAC										
13451	J626P09	EASA;FAA;ANAC										
13451	J626P10	EASA;FAA;ANAC										
13451	J626P11	EASA;FAA;ANAC										
13459	301-417-104-0	EASA;FAA;CAAC;ANAC	23	28	72-23-12	FAN FRAME STRUTS INTERNAL TUBING	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	640	SR Technics Switzerland
13459	301-464-713-0	EASA;FAA;CAAC;ANAC										
13459	336-009-504-0	EASA;FAA;CAAC;ANAC										
13459	336-009-505-0	EASA;FAA;CAAC;ANAC										
13459	336-028-701-0	EASA;FAA;CAAC;ANAC										
13459	337-113-201-0	EASA;FAA;CAAC;ANAC										
13459	337-114-602-0	EASA;FAA;CAAC;ANAC										
13459	337-115-002-0	EASA;FAA;CAAC;ANAC										
13459	337-115-052-0	EASA;FAA;CAAC;ANAC										
13459	340-029-901-0	EASA;FAA;CAAC;ANAC										
13459	340-030-202-0	EASA;FAA;CAAC;ANAC										
13459	340-030-702-0	EASA;FAA;CAAC;ANAC										
13459	340-031-101-0	EASA;FAA;CAAC;ANAC										
13459	340-031-401-0	EASA;FAA;CAAC;ANAC										
13459	340-031-901-0	EASA;FAA;CAAC;ANAC										
13473	336-053-701-0	EASA;FAA;CAAC;ANAC	28	28	72-23-16	FAN FRAME ASSEMBLY - VARIABLE BLEED VALVE FEEDBACK ROD AND CI	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	275	SR Technics Switzerland
13473	336-057-802-0	EASA;FAA;CAAC;ANAC										
13473	340-074-402-0	EASA;FAA;CAAC;ANAC										
13473	340-074-505-0	EASA;FAA;CAAC;ANAC										
13473	340-079-204-0	EASA;FAA;CAAC;ANAC										
13473	340-079-303-0	EASA;FAA;CAAC;ANAC										
13473	340-079-403-0	EASA;FAA;CAAC;ANAC										
13473	340-085-202-0	EASA;FAA;CAAC;ANAC										
13473	340-085-302-0	EASA;FAA;CAAC;ANAC										
13473	340-085-401-0	EASA;FAA;CAAC;ANAC										
13473	340-085-402-0	EASA;FAA;CAAC;ANAC										
13473	340-168-301-0	EASA;FAA;CAAC;ANAC										
13473	340-168-601-0	EASA;FAA;CAAC;ANAC										
13473	340-168-701-0	EASA;FAA;CAAC;ANAC										
13903	336-042-501-0	EASA;FAA;CAAC;ANAC	21	28	72-54-10	LOW PRESSURE TURBINE - THERMAL INSULATION BLANKETS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	135	SR Technics Switzerland
13903	336-042-540-0	EASA;FAA;CAAC;ANAC			72-54-10		Package B	001	PATCH REPAIR OF INSULATION BLANKETS		245	SR Technics Switzerland
13903	336-042-560-0	EASA;FAA;CAAC;ANAC										
13903	336-042-640-0	EASA;FAA;CAAC;ANAC										
13903	336-042-680-0	EASA;FAA;CAAC;ANAC										
13903	336-042-701-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
13903	336-042-740-0	EASA;FAA;CAAC;ANAC										
13903	338-072-002-0	EASA;FAA;CAAC;ANAC										
13903	338-072-021-0	EASA;FAA;CAAC;ANAC										
13903	338-072-042-0	EASA;FAA;CAAC;ANAC										
13903	338-072-061-0	EASA;FAA;CAAC;ANAC										
13903	338-072-081-0	EASA;FAA;CAAC;ANAC										
13903	338-086-702-0	EASA;FAA;CAAC;ANAC										
13903	338-086-752-0	EASA;FAA;CAAC;ANAC										
15119	321-451-005-0	EASA;FAA;CAAC;ANAC	28	21	71-00-01	ADAPTER RING FLANGE SEGEMENT V-GROOVE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	370	SR Technics Switzerland
15119	321-451-300-0	EASA;FAA;CAAC;ANAC			71-00-01		Package B		CORROSION DAMAGE CLEAN UP SRM		435	SR Technics Switzerland
15119	321-451-402-0	EASA;FAA;CAAC;ANAC			71-00-01		Package D	SPEC-PROC-002	ADAPTER RING OUTER FLANGE BLEND REPAIR		1,075	SR Technics Switzerland
15119	321-451-500-0	EASA;FAA;CAAC;ANAC			71-00-01		Package D	SPEC-PROC-003	REPLACEMENT OF ADAPTER RING OUTER FLANGE		1,075	SR Technics Switzerland
15119	321-451-550-0	EASA;FAA;CAAC;ANAC			71-00-01		Package SB00	RA32078-128	INSPECTION OF ADAPTER RINGS FOR CORROSION		860	SR Technics Switzerland
15119	321-451-804-0	EASA;FAA;CAAC;ANAC										
15119	321-451-854-0	EASA;FAA;CAAC;ANAC										
15119	321-452-700-0	EASA;FAA;CAAC;ANAC										
15119	321-458-100-0	EASA;FAA;CAAC;ANAC										
15119	321-458-101-0	EASA;FAA;CAAC;ANAC;CAA UK										
15119	321-458-102-0	EASA;FAA;CAAC;ANAC;CAA UK										
15119	321-458-200-0	EASA;FAA;CAAC;ANAC										
15119	321-458-201-0	EASA;FAA;CAAC;ANAC										
15119	321-458-202-0	EASA;FAA;CAAC;ANAC										
15119	321-458-300-0	EASA;FAA;CAAC;ANAC										
15119	321-458-301-0	EASA;FAA;CAAC;ANAC										
15119	321-458-302-0	EASA;CAAC;ANAC										
15119	321-458-400-0	EASA;FAA;CAAC;ANAC										
15119	321-458-401-0	EASA;FAA;CAAC;ANAC										
15119	321-458-500-0	EASA;FAA;CAAC;ANAC										
15119	321-458-501-0	EASA;FAA;CAAC;ANAC;CAA UK										
15119	321-458-502-0	EASA;FAA;CAAC;ANAC										
15119	321-458-600-0	EASA;FAA;CAAC;ANAC										
15119	321-458-601-0	EASA;FAA;CAAC;ANAC										
15119	321-458-602-0	EASA;CAAC;ANAC										
15119	321-458-700-0	EASA;FAA;CAAC;ANAC										
15119	321-458-701-0	EASA;FAA;CAAC;ANAC										
15119	321-458-702-0	EASA;CAAC;ANAC;CAA UK										
15119	321-458-800-0	EASA;FAA;CAAC;ANAC										
15119	321-458-801-0	EASA;FAA;CAAC;ANAC;CAA UK										
15119	321-458-802-0	EASA;CAAC;ANAC										
15119	ALL458-000-0	EASA;FAA;CAAC;ANAC										
15119	ALL458-001-0	EASA;FAA;CAAC;ANAC										
15119	ALL458-002-0	EASA;CAAC;ANAC										
15119	ALL458-900-0	EASA;FAA;CAAC;ANAC										
15119	ALL458-901-0	EASA;FAA;CAAC;ANAC										
15119	ALL458-902-0	EASA;CAAC;ANAC										
15379	336-043-302-0	EASA;FAA;CAAC;ANAC	7	28	72-56-01	CFM56-5B/7B INSULTION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		405	SR Technics Switzerland
15379	338-107-002-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AD	029	REPLACEMENT OF INSULATION ASSEMBLY		255	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility	
15379	338-107-003-0	EASA;FAA;CAAC;ANAC										
15379	338-107-102-0	EASA;FAA;CAAC;ANAC										
15379	338-107-103-0	EASA;FAA;CAAC;ANAC										
15379	338-107-202-0	EASA;FAA;CAAC;ANAC										
15379	338-107-203-0	EASA;FAA;CAAC;ANAC										
15379	340-101-604-0	EASA;FAA;CAAC;ANAC										
15379	340-101-704-0	EASA;FAA;CAAC;ANAC										
15379	340-156-503-0	EASA;FAA;CAAC;ANAC										
15379	340-156-603-0	EASA;FAA;CAAC;ANAC										
15379	340-156-703-0	EASA;FAA;CAAC;ANAC										
19228	056-000-221-0	EASA;FAA;CAAC;ANAC	30	21	72-56-01	LOW PRESSURE TURBINE REAR FRAME - BEARING NO.5 OIL SCAVENGE/ Package A	CLN/INSP	CLEANING AND INSPECTION		685	SR Technics Switzerland	
19228	056-000-302-6	EASA;FAA;CAAC;ANAC			72-56-01	Package AK	036	REPAIR OF CRACKS TACK WELDING OF THE OIL SUPPLY TUBE BY WELD BUILD UP		1,055	SR Technics Switzerland	
19228	334-007-367-0	EASA;FAA;CAAC;ANAC			72-56-01	Package S	018	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY		1,265	SR Technics Switzerland	
19228	336-052-111-0	EASA;FAA;CAAC;ANAC			72-56-01	Package SB00	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL S		370	SR Technics Switzerland	
19228	338-103-405-0	EASA;FAA;CAAC;ANAC										
19228	340-166-101-0	EASA;FAA;CAAC;ANAC										
21823	338-063-602-0	EASA;FAA;CAAC;ANAC	36	28	72-54-04	LOW PRESSURE TURBINE - SHROUD SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		735	SR Technics Switzerland
21823	338-122-202-0	EASA;FAA;CAAC;ANAC;CAA UK							FOR SHOP VISITS ONLY			
23002	301-581-006-0	EASA;FAA;CAAC;ANAC	24	28	72-54-20	LOW PRESSURE TURBINE - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		340	SR Technics Switzerland
23002	301-581-007-0	EASA;FAA;CAAC;ANAC							FOR SHOP VISITS ONLY			
23002	305-074-104-0	EASA;FAA;CAAC;ANAC										
23002	336-026-002-0	EASA;FAA;CAAC;ANAC										
23002	336-026-052-0	EASA;FAA;CAAC;ANAC										
23002	336-031-201-0	EASA;FAA;CAAC;ANAC										
23002	336-031-301-0	EASA;FAA;CAAC;ANAC										
23002	336-031-401-0	EASA;FAA;CAAC;ANAC										
23002	336-031-501-0	EASA;FAA;CAAC;ANAC										
23002	336-044-102-0	EASA;FAA;CAAC;ANAC										
23002	336-044-202-0	EASA;FAA;CAAC;ANAC										
23002	336-049-301-0	EASA;FAA;CAAC;ANAC										
23002	336-049-603-0	EASA;FAA;CAAC;ANAC										
23002	336-053-602-0	EASA;FAA;CAAC;ANAC										
23002	336-055-106-0	EASA;FAA;CAAC;ANAC										
23002	336-063-001-0	EASA;FAA;CAAC;ANAC										
23002	338-063-501-0	EASA;FAA;CAAC;ANAC										
23002	338-065-501-0	EASA;FAA;CAAC;ANAC										
23002	338-069-901-0	EASA;FAA;CAAC;ANAC										
23002	338-069-951-0	EASA;FAA;CAAC;ANAC										
23002	338-086-101-0	EASA;FAA;CAAC;ANAC										
23002	338-111-801-0	EASA;FAA;CAAC;ANAC										
23002	338-116-402-0	EASA;FAA;CAAC;ANAC										
23002	338-116-502-0	EASA;FAA;CAAC;ANAC										
23002	338-116-503-0	EASA;FAA;CAAC;ANAC										
23002	338-116-602-0	EASA;FAA;CAAC;ANAC										
23002	338-116-603-0	EASA;FAA;CAAC;ANAC;CAA UK										
23002	338-116-702-0	EASA;FAA;CAAC;ANAC;CAA UK										
23002	338-121-701-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
23002	338-121-702-0	EASA;FAA;CAAC;ANAC										
23002	338-180-201-0	EASA;FAA;CAAC;ANAC										
23002	340-304-901-0	EASA;FAA;CAAC;ANAC										
23002	340-306-301-0	EASA;FAA;CAAC;ANAC										
23002	649-051-001-0	EASA;FAA;CAAC;ANAC										
23180	1387M47G01	EASA;FAA;CAAC;ANAC	16	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT AFT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	250	SR Technics Switzerland
23180	1523M72G01	EASA;FAA;CAAC;ANAC			72-53-02		Package A	INSP-001	PERFORM HEAT INITIAL CONTOUR		250	SR Technics Switzerland
23180	2002M71G01	EASA;FAA;CAAC;ANAC;CAA UK										
55101	321-451-602-0	EASA;FAA;CAAC;ANAC	7	21	78-36-55	HOLD-OPEN ROD COMPONENT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	385	SR Technics Switzerland
55101	321-451-604-0	EASA;FAA;CAAC;ANAC										
55101	321-451-605-0	EASA;FAA;CAAC;ANAC										
55101	321-451-606-0	EASA;FAA;CAAC;ANAC										
55101	321-451-654-0	EASA;FAA;CAAC;ANAC										
55101	321-451-655-0	EASA;FAA;CAAC;ANAC										
55101	321-455-202-0	EASA;FAA;CAAC;ANAC										
62444	301-298-111-0	EASA;FAA;CAAC;ANAC	21	28	72-22-15	NO.1 AND NO.2 BEARING SUPPORT - PHONIC WHEEL	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	395	SR Technics Switzerland
62444	301-298-113-0	EASA;FAA;CAAC;ANAC										
62444	340-034-701-0	EASA;FAA;CAAC;ANAC										
65986	1318M20G03	EASA;FAA;CAAC;ANAC	28	28	72-32-11	COMPRESSOR FRONT STATOR - VARIABLE VANE ACTUATION RINGS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	525	SR Technics Switzerland
65986	1318M20G04	EASA;FAA;CAAC;ANAC			72-32-11		Package A	INSP-001	INSPECTION FOR SUSPECTED CRACKS		525	SR Technics Switzerland
65986	1318M21G03	EASA;FAA;CAAC;ANAC;CAA UK			72-32-11		Package A	INSP-001	REPLACE FLANGED BUSHINGS		525	SR Technics Switzerland
65986	1318M22G03	EASA;FAA;CAAC;ANAC;CAA UK			72-32-11		Package A	INSP-001	SECURE LOOSE STRAIGHT PIN		525	SR Technics Switzerland
65986	1318M23G03	EASA;FAA;CAAC;ANAC										
65986	1318M50G03	EASA;FAA;CAAC;ANAC										
65986	1318M51G01	EASA;FAA;CAAC;ANAC										
65986	1318M51G03	EASA;FAA;CAAC;ANAC										
65986	1318M52G01	EASA;FAA;CAAC;ANAC										
65986	1318M52G03	EASA;FAA;CAAC;ANAC										
65986	1318M53G03	EASA;FAA;CAAC;ANAC										
65986	9524M85P02	EASA;FAA;CAAC;ANAC										
68796	1887M11G01	EASA;FAA;CAAC;ANAC	32	28	72-00-52	ENGINE MODULES/ASSEMBLIES - HIGH PRESSURE TURBINE ROTOR ASSE	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	3,900	SR Technics Switzerland
68796	9324M21G01	EASA;FAA;CAAC;ANAC			72-00-52		Package B	001	REP-001 REPLACE MARKED CLINCH N	72-52-02	310	SR Technics Switzerland
72544	305-165-501-0	EASA;FAA;CAAC;ANAC	14	28	72-63-05	ACCESSORY GEARBOX - LUBRICATION UNIT DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		200	SR Technics Switzerland
72544	335-312-603-0	EASA;FAA;CAAC;ANAC										
134895	740123	EASA;FAA;CAAC;ANAC	7	21	24-19-10	CFM56-5B QAD ADAPTER KIT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	895	SR Technics Switzerland
134895	740123A	EASA;FAA;CAAC;ANAC										
135026	238-0451-509	EASA;FAA;CAAC;ANAC	20	35	78-11-05	EXHAUST - CENTERBODY ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3,605	SR Technics Switzerland
135026	238-0451-511	EASA;FAA;CAAC;ANAC										
135026	238-0451-513	EASA;FAA;CAAC;ANAC										
135026	238-0451-515	EASA;FAA;CAAC;ANAC										
135026	238-0451-523	EASA;FAA;CAAC;ANAC										
135150	1348M21P01	EASA;FAA;CAAC;ANAC	11	21	77-23-10	T3 SENSOR, COMPRESSOR OUTLET TEMPERATURE	Package C	TEST	INSPECTION AND TEST		1,080	SR Technics Switzerland
135150	1348M21P04	EASA;FAA;CAAC;ANAC										
135150	1348M21P05	EASA;FAA;CAAC;ANAC										
135150	1853M47P02	EASA;FAA;CAAC;ANAC										
135150	8TC19AAJ1	EASA;FAA;CAAC;ANAC										
135150	8TC19AAK1	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
135150	8TC19AAP1	EASA;FAA;CAAC;ANAC										
135150	8TC19AAR1	EASA;FAA;CAAC;ANAC										
135170	301-795-702-0	EASA;FAA;CAAC;ANAC	16	21	77-21-14	THERMOCOUPLE WIRING HARNESS	Package B	TEST	PRE TEST	TESTING AND FAULT ISOLATION, SB 77-001	515	SR Technics Switzerland
135170	CA170-00	EASA;FAA;CAAC;ANAC			77-21-14		Package C	TEST	TEST		1,110	SR Technics Switzerland
135170	CA170-01	EASA;FAA;CAAC;ANAC			77-21-14		Package SB00	CA211-77-002	FRONT TRANSIENT PROTECTION BOARD FUSE	INSPECTION AND REWORK ON F/IN CONJUNCTION WITH PACKAGE OVERHA	540	SR Technics Switzerland
135170	CA170-02	EASA;FAA;CAAC;ANAC			77-21-14		Package SB01	77-0013	REPLACEMENT OF SUSPECT EGT COUPLING		135	SR Technics Switzerland
135170	CA171-00	EASA;FAA;CAAC;ANAC										
135170	CA171-01	EASA;FAA;CAAC;ANAC										
135170	CA171-02	EASA;FAA;CAAC;ANAC										
135170	CA172-02	EASA;FAA;CAAC;ANAC										
135170	CA172-03	EASA;FAA;CAAC;ANAC										
135170	CA172-04	EASA;FAA;CAAC;ANAC										
135170	CA211-00	EASA;FAA;CAAC;ANAC;CAA UK										
135170	CA212-00	EASA;FAA;CAAC;ANAC;DGCA CIVI										
135170	CA213-00	EASA;FAA;CAAC;ANAC										
135170	TC254-01	EASA;FAA;CAAC;ANAC										
135170	TC254-02	EASA;FAA;CAAC;ANAC										
135170	TC255-01	EASA;FAA;CAAC;ANAC										
135170	TC255-02	EASA;FAA;CAAC;ANAC										
135170	TC255-03	EASA;FAA;CAAC;ANAC										
135170	TC255-04	EASA;FAA;CAAC;ANAC										
135170	TC315-00	EASA;FAA;CAAC;ANAC										
135170	TC315-01	EASA;FAA;CAAC;ANAC										
135170	TC315-02	EASA;FAA;CAAC;ANAC										
135170	TC316-00	EASA;FAA;CAAC;ANAC										
135170	TC316-01	EASA;FAA;CAAC;ANAC										
135170	TC316-02	EASA;FAA;CAAC;ANAC										
138941	335-190-201-0	EASA;FAA;CAAC;ANAC	36	28	72-21-07	FAN AND BOOSTER - BOOSTER BLADES LOCK ASSEMBLY, STAGE 2-5	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	290	SR Technics Switzerland
138941	335-190-202-0	EASA;FAA;CAAC;ANAC			72-21-07		Package B	001	REPLACEMENT OF THE SELF-LOCKING THREADED INSERTS		175	SR Technics Switzerland
138941	335-190-301-0	EASA;FAA;CAAC;ANAC										
138941	335-190-302-0	EASA;FAA;CAAC;ANAC										
138941	335-190-401-0	EASA;FAA;CAAC;ANAC										
138941	335-190-402-0	EASA;FAA;CAAC;ANAC										
138941	338-006-201-0	EASA;FAA;CAAC;ANAC										
138941	338-006-202-0	EASA;FAA;CAAC;ANAC										
138941	338-006-301-0	EASA;FAA;CAAC;ANAC										
138941	338-006-302-0	EASA;FAA;CAAC;ANAC										
138941	338-006-401-0	EASA;FAA;CAAC;ANAC										
138941	338-006-402-0	EASA;FAA;CAAC;ANAC										
138941	338-006-501-0	EASA;FAA;CAAC;ANAC										
138941	338-006-502-0	EASA;FAA;CAAC;ANAC										
138945	1523M39P06	EASA;FAA;CAAC;ANAC	24	28	72-31-20	COMPRESSOR ROTOR - SELF-WRENCHING HOOK BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION	TECHNICAL INSTRUCTION (TI)	50	SR Technics Switzerland
138945	1523M39P07	EASA;FAA;CAAC;ANAC										
138945	2116M22P01	EASA;FAA;CAAC;ANAC;CAA UK										
138945	9115M80P06	EASA;FAA;CAAC;ANAC										
138945	9977M25P01	EASA;FAA;CAAC;ANAC										
138947	1385M33G02	EASA;FAA;CAAC;ANAC	7	28	72-32-10	CFM56 ARM ASSY-VANE ACTUATION	Package A	CLN/INSP	CLEANING & INSPECTION		60	SR Technics Switzerland

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138947	1385M33G03	EASA;FAA;CAAC;ANAC			72-32-10		Package SB00	72-0171	FAN & BOOSTER, MOD FROM -5B/2 TO -5B/2P		40	SR Technics Switzerland
138947	1385M34G01	EASA;FAA;CAAC;ANAC										
138947	1385M34G02	EASA;FAA;CAAC;ANAC										
138947	1834M58G01	EASA;FAA;CAAC;ANAC										
138947	1834M58G02	EASA;FAA;CAAC;ANAC										
138947	1834M59G01	EASA;FAA;CAAC;ANAC										
138947	1834M59G02	EASA;FAA;CAAC;ANAC										
138947	9511M79G01	EASA;FAA;CAAC;ANAC										
138947	9511M79G02	EASA;FAA;CAAC;ANAC										
138947	9523M35G01	EASA;FAA;CAAC;ANAC										
138947	9523M35G03	EASA;FAA;CAAC;ANAC										
138947	9938M48G05	EASA;FAA;CAAC;ANAC										
138947	9938M48G06	EASA;FAA;CAAC;ANAC										
138953	1316M84G01	EASA;FAA;CAAC;ANAC	28	28	72-42-06	COMBUSTION CHAMBER - SELFLOCKING GANG CHANNEL NUT ASSEMBL	Package A	CLN/INSP	CLEANING & INSPECTION		120	SR Technics Switzerland
138953	9945M19G03	EASA;FAA;CAAC;ANAC			72-42-06		Package B	001	REPLACEMENT OF SELFLOCKING GANG CHANNEL NUT ASSY NUTS		640	SR Technics Switzerland
138953	9945M19G04	EASA;FAA;CAAC;ANAC										
138962	305-158-701-0	EASA;FAA;CAAC;ANAC	18	28	72-62-05	TRANSFER GEARBOX - VESPEL NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		440	SR Technics Switzerland
138962	305-158-801-0	EASA;FAA;CAAC;ANAC										
138962	335-322-201-0	EASA;FAA;CAAC;ANAC										
138962	335-322-501-0	EASA;FAA;CAAC;ANAC										
138962	SL40703M45-15FG	EASA;FAA;CAAC;ANAC										
138980	301-297-909-0	EASA;FAA;CAAC;ANAC	25	28	72-22-16	NO.1 AND NO.2 BEARING SUPPORT - KEYWASHERS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	475	SR Technics Switzerland
138980	301-298-408-0	EASA;FAA;CAAC;ANAC			72-22-16		Package B	INSP-001	BLEND RING KEYWASHER		175	SR Technics Switzerland
138980	301-537-803-0	EASA;FAA;CAAC;ANAC			72-22-16		Package C	INSP-001	BLEND RETAINER RING		1,110	SR Technics Switzerland
138980	301-544-203-0	EASA;FAA;CAAC;ANAC			72-22-16		Package D	INSP-001	REPLACE ANTI ROTAIN PIN		625	SR Technics Switzerland
138980	305-398-901-0	EASA;FAA;CAAC;ANAC										
139000	AMB34-4001	EASA;FAA;CAAC;ANAC	15	21	71-21-08	FWD ENGINE MOUNT - BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		415	SR Technics Switzerland
139000	AMB34-4002	EASA;FAA;CAAC;ANAC			71-21-08		Package SB00	RA 32071-159	BEAM SNOUT INSPECTION AND REWORK		265	SR Technics Switzerland
139000	P2A0300-1	EASA;FAA;CAAC;ANAC										
139000	P2A0300-2	EASA;FAA;CAAC;ANAC										
139012	301-298-802-6	EASA;FAA;CAAC;ANAC	20	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE - SHIM	Package B		GRINDING SPACER THICKNESS	FOR SHOP VISITS ONLY	200	SR Technics Switzerland
139012	301-298-803-0	EASA;FAA;CAAC;ANAC										
139012	301-298-804-0	EASA;FAA;CAAC;ANAC										
139012	301-298-805-0	EASA;FAA;CAAC;ANAC										
139012	301-298-806-0	EASA;FAA;CAAC;ANAC										
139012	301-298-807-0	EASA;FAA;CAAC;ANAC										
139012	301-298-808-0	EASA;FAA;CAAC;ANAC										
139012	301-298-809-0	EASA;FAA;ANAC										
139012	301-298-810-0	EASA;FAA;CAAC;ANAC										
139012	301-298-811-0	EASA;FAA;CAAC;ANAC										
139012	301-298-812-0	EASA;FAA;CAAC;ANAC										
139012	301-298-813-0	EASA;FAA;CAAC;ANAC										
139012	301-298-814-0	EASA;FAA;CAAC;ANAC										
139012	301-298-815-0	EASA;FAA;CAAC;ANAC										
139012	301-298-816-0	EASA;FAA;CAAC;ANAC										
139012	301-298-817-0	EASA;FAA;CAAC;ANAC										
139012	301-298-818-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139012	301-298-819-0	EASA;FAA;CAAC;ANAC										
139015	305-115-704-0	EASA;FAA;CAAC;ANAC	26	28	72-63-21	ACCESSORY GEARBOX - SEALOL SEALS	Package A	CLN/INSP	CLEANING AND INSPECTION		140	SR Technics Switzerland
139015	305-115-709-0	EASA;FAA;CAAC;ANAC			72-63-21		Package B	001	LAPPING OF SURFACES OF MATING RING AND CARBON RING		465	SR Technics Switzerland
139015	305-140-801-0	EASA;FAA;CAAC;ANAC			72-63-21		Package C	002	REPLACEMENT OF DEFECTIVE COMPONENTS		220	SR Technics Switzerland
139015	335-310-706-0	EASA;FAA;CAAC;ANAC			72-63-21		Package SB00	72-0660	INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-REWORK OF OLD SEALOL SEAL TO THE NEI		400	SR Technics Switzerland
139015	335-310-707-0	EASA;FAA;CAAC;ANAC										
139015	335-310-708-0	EASA;FAA;CAAC;ANAC										
139015	335-320-304-0	EASA;FAA;CAAC;ANAC										
139015	335-320-305-0	EASA;FAA;CAAC;ANAC										
139015	340-155-304-0	EASA;FAA;CAAC;ANAC										
139015	340-155-305-0	EASA;FAA;CAAC;ANAC										
139015	340-190-001-0	EASA;FAA;CAAC;ANAC										
139015	340-194-201-0	EASA;FAA;CAAC;ANAC										
139019	305-145-601-0	EASA;FAA;CAAC;ANAC	26	28	72-63-09	ACCESSORY GEARBOX - HANDCRANKING COVER PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		765	SR Technics Switzerland
139019	305-166-101-0	EASA;FAA;CAAC;ANAC			72-63-09		Package SB01	72-0156	INTRODUCTION OF A NEW AGB HANDCRANKING COVER		495	SR Technics Switzerland
139019	305-166-102-0	EASA;FAA;CAAC;ANAC										
139020	305-415-401-0	EASA;FAA;CAAC;ANAC	20	28	72-63-18	ACCESSORY GEARBOX - PIN-STRAIGHT	Package A	CLN/INSP	CLEANING AND INSPECTION		390	SR Technics Switzerland
139020	340-077-702-0	EASA;FAA;CAAC;ANAC			72-63-18		Package C	002	REPLACEMENT OF THE BUSHING AND RECONDITIONING OF THE CHROMIUM PL		655	SR Technics Switzerland
139020	340-077-903-0	EASA;FAA;CAAC;ANAC										
139020	340-078-002-0	EASA;FAA;CAAC;ANAC;CAA UK										
139020	340-085-902-0	EASA;FAA;CAAC;ANAC										
139021	301-495-102-0	EASA;FAA;CAAC;ANAC;CAA UK	21	28	72-63-14	ACCESSORY GEARBOX - QAD RING ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		525	SR Technics Switzerland
139021	305-126-601-0	EASA;FAA;CAAC;ANAC			72-63-14		Package B	001	RECONDITIONING OF LUBRICANT VARNISH ON SPHERICAL SEATING SURFACES		785	SR Technics Switzerland
139021	335-311-700-0	EASA;FAA;CAAC;ANAC			72-63-14		Package C	002	RECONDITIONING OF THE SOLID-FILM LUBRICANT COATING		990	SR Technics Switzerland
139021	335-311-701-0	EASA;FAA;CAAC;ANAC										
139021	9009M29P01	EASA;FAA;CAAC;ANAC										
139023	301-367-605-0	EASA;FAA;CAAC;ANAC	20	28	72-55-11	LOW PRESSURE TURBINE SHAFT - ASSEMBLY BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION		170	SR Technics Switzerland
139023	J952P22A	EASA;FAA;CAAC;ANAC										
139024	338-072-601-0	EASA;FAA;CAAC;ANAC	40	21	72-54-14	LOW PRESSURE TURBINE - SUPPORT BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	245	SR Technics Switzerland
139024	338-072-801-0	EASA;FAA;CAAC;ANAC			72-54-14		Package AE	ASSEMBLY	MOUNT BRACKET REPLACE BUSHING		130	SR Technics Switzerland
139024	338-119-202-0	EASA;FAA;CAAC;ANAC			72-54-14		Package E	003	REPAIR OF CRACKS		165	SR Technics Switzerland
139024	338-119-204-0	EASA;FAA;CAAC;ANAC										
139024	340-029-703-0	EASA;FAA;CAAC;ANAC										
139024	340-029-706-0	EASA;FAA;CAAC;ANAC										
139024	340-029-707-0	EASA;FAA;CAAC;ANAC										
139024	340-029-708-0	EASA;FAA;CAAC;ANAC										
139024	340-084-102-0	EASA;FAA;CAAC;ANAC										
139024	340-084-104-0	EASA;FAA;CAAC;ANAC										
139024	340-084-152-0	EASA;FAA;CAAC;ANAC										
139030	338-011-201-0	EASA;FAA;CAAC;ANAC	28	28	72-23-17	FAN FRAME ASSEMBLY - OIL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	285	SR Technics Switzerland
139030	338-011-402-0	EASA;FAA;CAAC;ANAC			72-23-17		Package N	052	REPLACEMENT OF WORN SPHERICAL BEARING ON OIL TANK LINK ROD	EASA / FAA APPROVED SRT DESIGN	1,555	SR Technics Switzerland
139030	338-014-801-0	EASA;FAA;CAAC;ANAC										
139030	338-015-101-0	EASA;FAA;CAAC;ANAC;CAA UK										
139030	338-045-001-0	EASA;FAA;CAAC;ANAC										
139030	338-079-901-0	EASA;FAA;CAAC;ANAC										
139030	338-079-951-0	EASA;FAA;CAAC;ANAC										
139030	340-086-003-0	EASA;FAA;CAAC;ANAC										

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B**
valid until December 31, 2026

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139030	340-086-004-0	EASA;FAA;CAAC;ANAC										
139030	340-086-201-0	EASA;FAA;CAAC;ANAC										
139030	340-086-202-0	EASA;FAA;CAAC;ANAC										
139030	340-086-302-0	EASA;FAA;CAAC;ANAC										
139030	340-086-303-0	EASA;FAA;CAAC;ANAC										
139030	340-168-401-0	EASA;FAA;CAAC;ANAC										
139035	338-068-007-0	EASA;FAA;CAAC;ANAC	60	28	72-23-08	FAN FRAME ASSEMBLY - FAN CASE ACOUSTICAL PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION		300	SR Technics Switzerland
139035	338-068-008-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	002	LOCAL REPAIR OF THE TEDLAR FILM BY PAINTING		1,345	SR Technics Switzerland
139035	338-068-010-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	003	REPLACE THE COMPONENTS AT THE ATTACHMENT POINTS OF THE ACOUSTICAL		1,345	SR Technics Switzerland
139035	338-068-108-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	006	EROSION REPAIR BY EPOXY ADHESIVE		1,345	SR Technics Switzerland
139035	338-068-109-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	010	REPAIR OF THE FORWARD MIDDLE AND AFT ACCUSTICAL PANELS BY RESIN INJE		1,345	SR Technics Switzerland
139035	338-068-111-0	EASA;FAA;CAAC;ANAC			72-23-08		Package I	008	REPLACEMENT OF MID ACOUSTICAL PANEL BONDED DAMPER(S)		830	SR Technics Switzerland
139035	338-068-208-0	EASA;FAA;CAAC;ANAC			72-23-08		Package J	009	REPAIR OF FLANK OF FORWARD ACUSTICAL PANELS WITH EPOXY ADHESIVE		350	SR Technics Switzerland
139035	338-068-209-0	EASA;FAA;CAAC;ANAC			72-23-08		Package L	011	RECONDITIONING OF FWD, MID, AFT ACC. PANELS BY WET LAY-UP PROCESS		3,150	SR Technics Switzerland
139035	338-068-211-0	EASA;FAA;CAAC;ANAC			72-23-08		Package N	013	REPLACE BOSSES AND DAMPING	CONFIG. 1	1,105	SR Technics Switzerland
139035	338-068-307-0	EASA;FAA;CAAC;ANAC			72-23-08		Package N	013	REPLACE BOSSES AND DAMPING	CONFIG. 2	1,105	SR Technics Switzerland
139035	338-068-308-0	EASA;FAA;CAAC;ANAC			72-23-08		Package O	014	REPAIR CRACKS AT STIFFENER		1,925	SR Technics Switzerland
139035	338-068-310-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB00	72-0071	FAN FRAME - REPLACEMENT OF BONDED SEALS WITH SEAL ASSEMBLIES ON AFT		175	SR Technics Switzerland
139035	338-068-408-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB02	72-0865	INTRO NEW/RWK FWD ACOUSTICAL PANEL ASSY		2,045	SR Technics Switzerland
139035	338-068-409-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB03	72-1017	INTRODUCTION OF NEW ACOUSTICAL PANEL ASSEMBLIES AND REWORK OF THE		640	SR Technics Switzerland
139035	338-068-411-0	EASA;FAA;CAAC;ANAC										
139035	338-073-008-0	EASA;FAA;CAAC;ANAC										
139035	338-073-009-0	EASA;FAA;CAAC;ANAC										
139035	338-073-010-0	EASA;FAA;CAAC;ANAC										
139035	338-073-011-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-073-012-0	EASA;FAA;CAAC;ANAC										
139035	338-073-013-0	EASA;FAA;CAAC;ANAC										
139035	338-078-804-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-078-806-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-078-807-0	EASA;FAA;CAAC;ANAC										
139035	338-078-808-0	EASA;FAA;CAAC;ANAC										
139035	338-079-504-0	EASA;FAA;CAAC;ANAC										
139035	338-079-506-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-507-0	EASA;FAA;CAAC;ANAC										
139035	338-079-508-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-705-0	EASA;FAA;CAAC;ANAC										
139035	338-079-706-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-707-0	EASA;FAA;CAAC;ANAC										
139035	338-079-708-0	EASA;FAA;CAAC;ANAC										
139035	340-082-501-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	340-082-504-0	EASA;FAA;CAAC;ANAC										
139035	340-082-506-0	EASA;FAA;CAAC;ANAC										
139035	340-084-201-0	EASA;FAA;CAAC;ANAC										
139035	340-084-302-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	340-085-101-0	EASA;FAA;CAAC;ANAC										
139035	340-085-103-0	EASA;FAA;CAAC;ANAC										
139035	340-085-120-0	EASA;FAA;CAAC;ANAC;CAA UK										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139035	340-085-150-0	EASA;FAA;CAAC;ANAC										
139035	340-116-401-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	338-070-102-0	EASA;FAA;CAAC;ANAC	46	28	72-23-07	FAN FRAME ASSEMBLY - FAN DUCT PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	490	SR Technics Switzerland
139040	338-070-202-0	EASA;FAA;CAAC;ANAC			72-23-07		Package B	001	CRACK REPAIR BY WELD BUILDUP		1,375	SR Technics Switzerland
139040	338-070-302-0	EASA;FAA;CAAC;ANAC			72-23-07		Package C	002	REPLACEMENT OF THE ELASTOMER DAMPING PADS ON THE FAN		980	SR Technics Switzerland
139040	338-070-402-0	EASA;FAA;CAAC;ANAC										
139040	338-070-502-0	EASA;FAA;CAAC;ANAC										
139040	340-075-702-0	EASA;FAA;CAAC;ANAC										
139040	340-075-703-0	EASA;FAA;CAAC;ANAC										
139040	340-075-705-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-802-0	EASA;FAA;CAAC;ANAC										
139040	340-075-803-0	EASA;FAA;CAAC;ANAC										
139040	340-075-805-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-902-0	EASA;FAA;CAAC;ANAC										
139040	340-075-903-0	EASA;FAA;CAAC;ANAC										
139040	340-075-905-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-953-0	EASA;FAA;CAAC;ANAC										
139040	340-076-002-0	EASA;FAA;CAAC;ANAC										
139040	340-076-003-0	EASA;FAA;CAAC;ANAC										
139040	340-076-005-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-102-0	EASA;FAA;CAAC;ANAC										
139040	340-076-103-0	EASA;FAA;CAAC;ANAC										
139040	340-076-105-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-153-0	EASA;FAA;CAAC;ANAC										
139040	340-076-202-0	EASA;FAA;CAAC;ANAC										
139040	340-076-203-0	EASA;FAA;CAAC;ANAC										
139040	340-076-205-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-253-0	EASA;FAA;CAAC;ANAC										
139040	340-076-302-0	EASA;FAA;CAAC;ANAC										
139040	340-076-303-0	EASA;FAA;CAAC;ANAC										
139040	340-076-305-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-402-0	EASA;FAA;CAAC;ANAC										
139040	340-076-403-0	EASA;FAA;CAAC;ANAC										
139040	340-076-405-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-502-0	EASA;FAA;CAAC;ANAC										
139040	340-076-503-0	EASA;FAA;CAAC;ANAC										
139040	340-076-505-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-553-0	EASA;FAA;CAAC;ANAC										
139040	340-076-602-0	EASA;FAA;CAAC;ANAC										
139040	340-076-603-0	EASA;FAA;CAAC;ANAC										
139040	340-076-605-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-702-0	EASA;FAA;CAAC;ANAC										
139040	340-076-703-0	EASA;FAA;CAAC;ANAC										
139040	340-076-705-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-084-002-0	EASA;FAA;CAAC;ANAC										
139040	340-084-003-0	EASA;FAA;CAAC;ANAC;CAA UK										
139055	338-006-102-0	EASA;FAA;CAAC;ANAC	30	28	72-21-10	FAN AND BOOSTER - FAN BLADES SPACERS	Package A	CLN/INSP	CLEANING AND INSPECTION			90 SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139055	340-001-215-0	EASA;FAA;CAAC;ANAC			72-21-10		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		170	SR Technics Switzerland
139055	340-001-216-0	EASA;FAA;CAAC;ANAC										
139055	340-001-217-0	EASA;FAA;CAAC;ANAC										
139055	340-001-261-0	EASA;FAA;CAAC;ANAC										
139055	340-001-262-0	EASA;FAA;CAAC;ANAC										
139056	301-295-106-0	EASA;FAA;CAAC;ANAC	26	28	72-23-05	FAN FRAME ASSEMBLY - INNER/OUTER HOUSING/SUPPORT RDS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	855	SR Technics Switzerland
139056	301-295-909-0	EASA;FAA;CAAC;ANAC			72-23-05		Package C	002	REPAIR THE OUTER LOCATING DIAMETER OF THE OUTER RADIAL DRIVE SHAFT H		2,120	SR Technics Switzerland
139056	340-029-803-0	EASA;FAA;CAAC;ANAC			72-23-05		Package E	004	REPAIR OF THE OUTER LOCATING DIAMETER OF THE INNER RADIAL DRIVE SHAF		2,120	SR Technics Switzerland
139056	340-032-604-0	EASA;FAA;CAAC;ANAC			72-23-05		Package SB00	72-0934	REPL. OF SUSPECTED BATCH OF RADIAL DRIVE SHAFT ASSY AND ASSOCIATED RA		170	SR Technics Switzerland
139056	340-032-606-0	EASA;FAA;CAAC;ANAC;CAA UK										
139056	340-050-004-0	EASA;FAA;CAAC;ANAC										
139056	340-050-005-0	EASA;FAA;CAAC;ANAC;CAA UK										
139340	1476M79P01	EASA;FAA;CAAC;ANAC	8	28	72-52-07	CFM56 HPT ROTOR FR. SHAFT DAMPER SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	505	SR Technics Switzerland
139340	1476M79P02	EASA;FAA;CAAC;ANAC										
139340	1476M79P03	EASA;FAA;CAAC;ANAC										
139344	1385M91P01	EASA;FAA;CAAC;ANAC	24	28	72-52-09	HIGH PRESSURE TURBINE ROTOR - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	400	SR Technics Switzerland
139344	1498M46P01	EASA;FAA;CAAC;ANAC;CAA UK			72-52-09		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CFM56-5B2 AND CFM56-5B6/2 TO CFM56-5B6/2P ENC		420	SR Technics Switzerland
139344	1522M86P01	EASA;FAA;CAAC;ANAC										
139344	1847M57P01	EASA;FAA;CAAC;ANAC										
139344	1847M57P02	EASA;FAA;CAAC;ANAC										
139344	2410M52P01	EASA;FAA;CAAC										
139360	1559M14G05	EASA;FAA;CAAC;ANAC	43	28	72-32-03	COMPRESSOR FRONT STATOR - VANE SECTORS	Package A		BASIC REPAIR STAGE 4,5		235	SRTAS
139360	1559M14G06	EASA;FAA;CAAC;ANAC			72-32-03		Package A	CLN 001	CLEANING		235	SRTAS
139360	1559M14G07	EASA;FAA;CAAC;ANAC			72-32-03		Package A	INSP 001	VISUAL/DIMENSIONAL INSPECTION		235	SRTAS
139360	1559M14G08	EASA;FAA;CAAC;ANAC			72-32-03		Package B		FULL REPAIR STAGE 4		575	SRTAS
139360	1559M15G01	EASA;FAA;CAAC;ANAC			72-32-03		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		575	SRTAS
139360	1559M15G02	EASA;FAA;CAAC;ANAC			72-32-03		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		575	SRTAS
139360	1559M15G03	EASA;FAA;CAAC;ANAC			72-32-03		Package G		ADDITIONAL WORKSCOPE STAGE 4		190	SRTAS
139360	1559M15G04	EASA;FAA;CAAC;ANAC			72-32-03		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	190	SRTAS
139360	1834M94G01	EASA;FAA;CAAC;ANAC			72-32-03		Package H		ADDITIONAL WORKSCOPE STAGE 4		985	SRTAS
139360	1834M94G02	EASA;FAA;CAAC;ANAC			72-32-03		Package H	006	INNER PLATFORM J-HOOK REPAIR		985	SRTAS
139360	1834M94G03	EASA;FAA;CAAC;ANAC			72-32-03		Package I		FULL REPAIR STAGE 5		595	SRTAS
139360	1834M94G04	EASA;FAA;CAAC;ANAC			72-32-03		Package I	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		595	SRTAS
139360	2031M14G05	EASA;FAA;CAAC;ANAC			72-32-03		Package I	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		595	SRTAS
139360	2031M14G06	EASA;FAA;CAAC;ANAC			72-32-03		Package N		ADDITIONAL WORKSCOPE STAGE 5		110	SRTAS
139360	2031M14G07	EASA;FAA;CAAC;ANAC			72-32-03		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	110	SRTAS
139360	2031M14G08	EASA;FAA;CAAC;ANAC			72-32-03		Package O		ADDITIONAL WORKSCOPE STAGE 5		1,025	SRTAS
139360	P244G05	EASA;FAA;CAAC;ANAC			72-32-03		Package O	006	INNER PLATFORM J-HOOK REPAIR		1,025	SRTAS
139360	P244G06	EASA;FAA;CAAC;ANAC										
139360	P244G07	EASA;FAA;CAAC;ANAC										
139360	P244G08	EASA;FAA;CAAC;ANAC										
139360	P245G01	EASA;FAA;CAAC;ANAC										
139360	P245G02	EASA;FAA;CAAC;ANAC										
139360	P245G03	EASA;FAA;CAAC;ANAC										
139360	P245G04	EASA;FAA;CAAC;ANAC										
139360	P264G01	EASA;FAA;CAAC;ANAC										
139360	P264G02	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139360	P264G03	EASA;FAA;CAAC;ANAC										
139360	P264G04	EASA;FAA;CAAC;ANAC										
139360	P264G05	EASA;FAA;CAAC;ANAC										
139360	P264G06	EASA;FAA;CAAC;ANAC										
139360	P264G07	EASA;FAA;CAAC;ANAC										
139360	P264G08	EASA;FAA;CAAC;ANAC										
139360	P265G01	EASA;FAA;CAAC;ANAC										
139360	P265G02	EASA;FAA;CAAC;ANAC										
139360	P265G03	EASA;FAA;CAAC;ANAC										
139360	P265G04	EASA;FAA;CAAC;ANAC										
139360	P265G05	EASA;FAA;CAAC;ANAC										
139360	P265G06	EASA;FAA;CAAC;ANAC										
139360	P265G07	EASA;FAA;CAAC;ANAC										
139360	P265G08	EASA;FAA;CAAC;ANAC										
139378	301-333-307-0	EASA;FAA;CAAC;ANAC	35	28	72-55-20	LOW PRESSURE TURBINE SHAFT - LOCATING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY		385 SR Technics Switzerland
139378	301-333-404-0	EASA;FAA;CAAC;ANAC;CAA UK										
139378	305-415-103-0	EASA;FAA;CAAC;ANAC										
139378	337-111-801-0	EASA;FAA;CAAC;ANAC										
139378	337-111-802-0	EASA;FAA;CAAC;ANAC										
139378	337-111-803-0	EASA;FAA;CAAC;ANAC										
139378	337-111-901-0	EASA;FAA;CAAC;ANAC										
139378	337-111-902-0	EASA;FAA;CAAC;ANAC										
139378	337-111-903-0	EASA;FAA;CAAC;ANAC										
139378	340-161-101-0	EASA;FAA;CAAC;ANAC										
139378	340-161-103-0	EASA;FAA;CAAC;ANAC										
139378	340-161-201-0	EASA;FAA;CAAC;ANAC										
139378	340-161-203-0	EASA;FAA;CAAC;ANAC;CAA UK										
139390	305-136-605-0	EASA;FAA;CAAC;ANAC	20	28	72-62-02	TRANSFER GEARBOX - BEVEL GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION			1,255 SR Technics Switzerland
139390	305-136-704-0	EASA;FAA;CAAC;ANAC			72-62-02		Package SB00	72-0364	RETROFIT OF -WITH SUSPECTED TGB			525 SR Technics Switzerland
139390	305-163-301-0	EASA;FAA;CAAC;ANAC										
139390	305-163-401-0	EASA;FAA;CAAC;ANAC										
139390	340-049-501-0	EASA;FAA;CAAC;ANAC										
139390	340-049-601-0	EASA;FAA;CAAC;ANAC										
139401	305-138-805-0	EASA;FAA;CAAC;ANAC	27	28	72-63-02	ACCESSORY GEARBOX - MOUNTING DRIVE PADS	Package A	CLN/INSP	CLEANING AND INSPECTION			535 SR Technics Switzerland
139401	305-138-807-0	EASA;FAA;CAAC;ANAC			72-63-02		Package B	001	REPLACEMENT OF THE KEY-LOCKED STUDS			880 SR Technics Switzerland
139401	305-139-002-0	EASA;FAA;CAAC;ANAC			72-63-02		Package E	004	REPLACE THE SWAGED SELF-LOCKING INSERTS			570 SR Technics Switzerland
139401	305-139-003-0	EASA;FAA;CAAC;ANAC			72-63-02		Package H	007	RECONDITIONING OR SPOT TOUCH-UP OF NON-MACHINED SURFACES BY OXIDE			675 SR Technics Switzerland
139401	305-139-203-0	EASA;FAA;CAAC;ANAC										
139401	305-139-204-0	EASA;FAA;CAAC;ANAC										
139401	305-139-406-0	EASA;FAA;CAAC;ANAC										
139401	305-139-407-0	EASA;FAA;CAAC;ANAC										
139401	305-139-602-0	EASA;FAA;CAAC;ANAC										
139401	305-139-603-0	EASA;FAA;CAAC;ANAC										
139401	305-139-701-0	EASA;FAA;CAAC;ANAC										
139401	305-139-801-0	EASA;FAA;CAAC;ANAC										
139401	305-140-001-0	EASA;FAA;CAAC;ANAC										
139401	305-142-601-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139401	335-301-000-0	EASA;FAA;CAAC;ANAC										
139401	335-301-200-0	EASA;FAA;CAAC;ANAC										
139401	340-047-802-0	EASA;FAA;CAAC;ANAC										
139401	340-047-804-0	EASA;FAA;CAAC;ANAC										
139401	340-047-805-0	EASA;FAA;CAAC;ANAC										
139401	340-047-807-0	EASA;FAA;CAAC;ANAC										
139401	340-048-102-0	EASA;FAA;CAAC;ANAC										
139401	340-048-103-0	EASA;FAA;CAAC;ANAC;CAA UK										
139401	340-048-104-0	EASA;FAA;CAAC;ANAC										
139401	340-048-602-0	EASA;FAA;CAAC;ANAC										
139401	340-048-802-0	EASA;FAA;CAAC;ANAC										
139401	340-048-803-0	EASA;FAA;CAAC;ANAC										
139401	340-055-602-0	EASA;FAA;CAAC;ANAC										
139423	305-137-101-0	EASA;FAA;CAAC;ANAC	36	28	72-63-03	ACCESSORY GEARBOX - GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1,275	SR Technics Switzerland
139423	305-137-203-0	EASA;FAA;CAAC;ANAC			72-63-03		Package C	002	REPLACEMENT OF THE OIL RETAINING RING ON THE 40-TOOTH INPUT DRIVE GE		1,435	SR Technics Switzerland
139423	305-137-501-0	EASA;FAA;CAAC;ANAC			72-63-03		Package E	004	REPLACE THE OIL RETAINING SLEEVES ON THE AGB 70-TOOTH GEARSHAFT		860	SR Technics Switzerland
139423	305-137-602-0	EASA;FAA;CAAC;ANAC										
139423	305-137-701-0	EASA;FAA;CAAC;ANAC										
139423	305-137-802-0	EASA;FAA;CAAC;ANAC										
139423	305-137-902-0	EASA;FAA;CAAC;ANAC										
139423	305-138-202-0	EASA;FAA;CAAC;ANAC										
139423	305-146-302-0	EASA;FAA;CAAC;ANAC										
139423	305-146-402-0	EASA;FAA;CAAC;ANAC										
139423	305-151-501-0	EASA;FAA;CAAC;ANAC										
139423	305-163-501-0	EASA;FAA;CAAC;ANAC										
139423	305-165-201-0	EASA;FAA;CAAC										
139423	305-165-301-0	EASA;FAA;CAAC;ANAC										
139423	305-165-401-0	EASA;FAA;CAAC;ANAC										
139423	305-165-601-0	EASA;FAA;CAAC;ANAC										
139423	305-167-001-0	EASA;FAA;CAAC;ANAC										
139423	335-302-902-0	EASA;FAA;CAAC;ANAC										
139423	335-303-002-0	EASA;FAA;CAAC;ANAC										
139423	335-303-201-0	EASA;FAA;CAAC;ANAC										
139423	335-303-502-0	EASA;FAA;CAAC;ANAC										
139423	335-303-503-0	EASA;FAA;CAAC;ANAC										
139423	335-303-506-0	EASA;FAA;CAAC;ANAC										
139423	335-303-601-0	EASA;FAA;CAAC;ANAC										
139423	335-324-101-0	EASA;FAA;CAAC;ANAC										
139423	340-048-301-0	EASA;FAA;CAAC;ANAC										
139423	340-051-602-0	EASA;FAA;CAAC;ANAC										
139423	340-051-801-0	EASA;FAA;CAAC;ANAC										
139423	340-051-901-0	EASA;FAA;CAAC;ANAC										
139423	340-052-802-0	EASA;FAA;CAAC;ANAC										
139423	340-055-202-0	EASA;FAA;CAAC;ANAC										
139423	340-151-101-0	EASA;FAA;CAAC;ANAC										
139423	340-151-501-0	EASA;FAA;CAAC;ANAC										
139423	340-154-301-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139424	305-140-501-0	EASA;FAA;CAAC;ANAC	6	28	72-63-25	ACCESSORY GEARBOX HARDWARE MODULE 63	Package A	CLN/INSP	CLEANING & INSPECTION		385	SR Technics Switzerland
139424	305-147-001-0	EASA;FAA;CAAC;ANAC			72-63-25		Package B	02	APPLY ALODINE		330	SR Technics Switzerland
139424	305-159-001-0	EASA;FAA;CAAC;ANAC										
139440	336-002-203-0	EASA;FAA;CAAC;ANAC	50	28	72-54-06	LOW PRESSURE TURBINE - ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		625	SR Technics Switzerland
139440	336-002-302-0	EASA;FAA;CAAC;ANAC;TCCA			72-54-06		Package AN	SPM 70-41-11	REMOVE HIGH METAL		280	SR Technics Switzerland
139440	336-003-002-0	EASA;FAA;CAAC;ANAC			72-54-06		Package C	001	REPAIR OF THE TITANIUM/ALUMINUM OXIDE COATING ON THE SEAL TEETH	PRICE PER STAGE	3,485	SR Technics Switzerland
139440	336-003-102-0	EASA;FAA;CAAC;ANAC			72-54-06		Package D	002	REPAIR OF RETAINING RING MATING FACE		3,035	SR Technics Switzerland
139440	338-111-502-0	EASA;FAA;CAAC;ANAC			72-54-06		Package E	003	TOUCH-UP OF SEAL TEETH		1,110	SR Technics Switzerland
139440	338-111-603-0	EASA;FAA;CAAC;ANAC;CAA UK										
139440	338-111-701-0	EASA;FAA;CAAC;ANAC										
139440	338-111-703-0	EASA;FAA;CAAC;ANAC										
139440	340-304-002-0	EASA;FAA;ANAC										
139440	340-304-101-0	EASA;FAA;CAAC;ANAC										
139440	340-304-301-0	EASA;FAA;CAAC;ANAC										
139447	337-123-301-0	EASA;FAA;CAAC;ANAC	17	28	72-23-27	NO.1 AND NO.2 BEARING SUPPORT - RETAINER WASHER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	115	SR Technics Switzerland
139447	340-032-501-0	EASA;FAA;ANAC										
139448	338-000-405-0	EASA;FAA;CAAC;ANAC	31	28	72-54-01	LOW PRESSURE TURBINE - BLADES STG 1	Package B		FULL REPAIR		345	SRTAS
139448	338-000-461-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	11	WELD REPAIR RUB BETWEEN SEAL TEETH		345	SRTAS
139448	338-000-481-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	2	AIRFOIL BLEND REPAIR		345	SRTAS
139448	338-000-482-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	3	RE-SETTING THE PRE-TWIST ANGLE		345	SRTAS
139448	338-108-204-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	4	REPAIR OF SEAL TEETH BY PLASMA SPRAYING		345	SRTAS
139448	338-108-206-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	40	LASER CLADDING OF HARD FACING AND MATING FACES OF THE TIP SHROUD		345	SRTAS
139448	338-108-207-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	5	REPAIR OF THE SEAL TEETH ON THE BLADE TIP SHROUD BY WELD BUILD-UP WIT		345	SRTAS
139448	338-108-208-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	55	OVER-COATING OF APVS COATING		345	SRTAS
139448	338-108-210-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	7	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS, BY WE		345	SRTAS
139448	338-115-703-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	8	REPAIR OF VAPOUR PHASE ALUMINAZATION		345	SRTAS
139448	338-115-705-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	9	CORROSION REMOVAL ON ROOT BY BLENDING		345	SRTAS
139448	338-115-706-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	INSP 001	VISUAL & DIMENSIONAL INSPECTION		345	SRTAS
139448	338-115-707-0	EASA;FAA;CAAC;ANAC			72-54-01		Package C		ADDITIONAL REPAIR		160	SRTAS
139448	338-115-709-0	EASA;FAA;CAAC;ANAC			72-54-01		Package C	5A	DIMENSIONAL RESTORATION OF THE SEAL TEETH		160	SRTAS
139448	340-302-001-0	EASA;FAA;CAAC;ANAC										
139448	340-310-001-0	EASA;FAA;CAAC;ANAC										
139483	338-063-702-0	EASA;FAA;CAAC;ANAC	24	28	72-22-11	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT - STATIONARY AIR/OIL	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	850	SR Technics Switzerland
139483	338-063-703-0	EASA;FAA;CAAC;ANAC										
139483	338-063-704-0	EASA;FAA;CAAC;ANAC										
139483	338-063-705-0	EASA;FAA;CAAC;ANAC										
139483	338-063-751-0	EASA;FAA;CAAC;ANAC										
139483	338-156-002-0	EASA;FAA;CAAC;ANAC										
139483	338-156-003-0	EASA;FAA;CAAC;ANAC										
139485	1585M80G01	EASA;FAA;CAAC;ANAC	6	28	72-09-02	CFM56-ALL MGB/IGB/TGB GEARBOX NOZZLE	Package A	CLN/INSP	CLEANING AND INSPECTION		485	SR Technics Switzerland
139485	305-142-702-0	EASA;FAA;CAAC;ANAC										
139485	305-142-802-0	EASA;FAA;CAAC;ANAC										
139485	305-142-901-0	EASA;FAA;CAAC;ANAC										
139485	305-143-002-0	EASA;FAA;CAAC;ANAC										
139485	305-143-102-0	EASA;FAA;CAAC;ANAC										
139485	305-143-201-0	EASA;FAA;CAAC;ANAC										
139485	305-143-301-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139485	305-143-401-0	EASA;FAA;CAAC;ANAC										
139485	305-143-502-0	EASA;FAA;CAAC;ANAC										
139485	305-146-802-0	EASA;FAA;CAAC;ANAC										
139485	305-147-102-0	EASA;FAA;CAAC;ANAC										
139485	9542M72G03	EASA;FAA;CAAC;ANAC										
139485	9973M28G01	EASA;FAA;CAAC;ANAC										
139485	9973M28G02	EASA;FAA;CAAC;ANAC										
139490	338-075-801-0	EASA;FAA;CAAC;ANAC	31	28	72-54-02	LOW PRESSURE TURBINE - BLADES STG 2 - 4	Package AH		STG 4 - ADDITIONAL WORKSCOPE		160 SRTAS	
139490	338-082-802-0	EASA;FAA;CAAC;ANAC			72-54-02		Package AH	017A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMIT		160 SRTAS	
139490	338-082-803-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B		STG 2 - FULL REPAIR		485 SRTAS	
139490	338-082-804-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	002	PLASMA SPRAY SEAL TEETH ZIRCONIUM OXIDE-YTTRIUM (3 PARTS PER SET)		485 SRTAS	
139490	338-082-852-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	003	RESET PRE TWIST ANGLE		485 SRTAS	
139490	338-082-853-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	004	AIRFOIL BLEND REPAIR		485 SRTAS	
139490	338-082-854-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	006	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS		485 SRTAS	
139490	338-084-003-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	011	BLEND TO REMOVE ROOT SULPHIDATION/ CORROSION		485 SRTAS	
139490	338-084-023-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	018	REPAIR APVS COATING		485 SRTAS	
139490	338-084-052-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	020	WELD REPAIR SEAL TEETH WITH COAST METAL 64		485 SRTAS	
139490	338-084-072-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	041	LASER CLADDING OF HARDFACING AND MATING FACES OF BLADE TIP SHROUDS		485 SRTAS	
139490	338-086-203-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	055	OVER COATING OF VAPOUR PHASE ALUMINAZATION		485 SRTAS	
139490	338-086-228-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	INSP-001	VISUAL / DIMENSIONAL INSPECTION		485 SRTAS	
139490	338-086-253-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C		STG 3 - FULL REPAIR		330 SRTAS	
139490	338-086-278-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	002	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTTRIUM		330 SRTAS	
139490	338-108-304-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	003	RESET PRE TWIST ANGLE		330 SRTAS	
139490	338-108-305-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	005	AIRFOIL BLEND REPAIR		330 SRTAS	
139490	338-108-403-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	007	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH COAST METAL 64		330 SRTAS	
139490	338-108-503-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	017	WELD REPAIR SEAL TEETH WITH COAST METAL 64		330 SRTAS	
139490	338-108-504-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	028	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		330 SRTAS	
139490	338-108-553-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	039	CORROSION REMOVAL FROM BLADE ROOT SURFACES		330 SRTAS	
139490	338-108-554-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	INSP-001	VISUAL / DIMENSIONAL		330 SRTAS	
139490	338-115-902-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D		STG 4 - FULL REPAIR		330 SRTAS	
139490	338-116-102-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	002	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTTRIUM		330 SRTAS	
139490	338-116-103-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	003	RESET PRE TWIST ANGLE		330 SRTAS	
139490	338-116-152-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	005	AIRFOIL BLEND REPAIR		330 SRTAS	
139490	338-116-153-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	008	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH T800		330 SRTAS	
139490	338-116-303-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	009	REPLACE RBD 191 WITH T800 ON TIP SHROUDS		330 SRTAS	
139490	338-116-304-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	017	WELD REPAIR SEAL TEETH WITH COAST METAL 64		330 SRTAS	
139490	340-302-101-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	028	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		330 SRTAS	
139490	340-302-201-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	039	CORROSION REMOVAL FROM BLADE ROOT SURFACES		330 SRTAS	
139490	340-302-202-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	INSP-001	VISUAL / DIMENSIONAL		330 SRTAS	
139490	340-302-301-0	EASA;FAA;CAAC;ANAC			72-54-02		Package N		STG 2 - ADDITIONAL WORKSCOPE		160 SRTAS	
139490	340-310-101-0	EASA;FAA;CAAC;ANAC			72-54-02		Package N	020A	DIMENSIONAL RESTORATION OF THE SEAL TEETH ON BLADES THAT ARE WITHIN		160 SRTAS	
139490	340-310-202-0	EASA;FAA;CAAC;ANAC			72-54-02		Package X		STG 3 - ADDITIONAL WORKSCOPE		160 SRTAS	
139490	340-310-301-0	EASA;FAA;CAAC;ANAC			72-54-02		Package X	017A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMIT		160 SRTAS	
139533	238-0207-503	EASA;FAA;CAAC;ANAC	25	21	71-21-08	FWD ENGINE MOUNT - SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1,275 SR Technics Switzerland	
139533	238-0207-505	EASA;FAA;CAAC;ANAC			71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR .		85 SR Technics Switzerland	
139533	238-0207-506	EASA;FAA;CAAC;ANAC			71-21-08		Package G	006	REPLACE BEARING - SUPPORT ASSEMBLY		1,280 SR Technics Switzerland	
139533	238-0207-507	EASA;FAA;CAAC;ANAC			71-21-08		Package P	015	BLEND REPAIR - SUPPORT ASSEMBLY		525 SR Technics Switzerland	

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139533	238-0207-508	EASA;FAA;CAAC;ANAC										
139533	238-0207-509	EASA;FAA;CAAC;ANAC;CAA UK										
139533	238-0207-510	EASA;FAA;CAAC;ANAC;CAA UK										
139533	238-0207-511	EASA;FAA;CAAC;ANAC										
139533	238-0207-512	EASA;FAA;CAAC;ANAC										
139533	238-0207-513	EASA;FAA;CAAC;ANAC										
139533	238-0207-514	EASA;FAA;CAAC;ANAC										
139533	238-0207-515	EASA;FAA;CAAC;ANAC										
139533	238-0207-521	EASA;FAA;CAAC;ANAC										
139533	238-0207-522	EASA;FAA;CAAC;ANAC										
139537	8862-01-1150-707-9	EASA;FAA;ANAC	8	21	26-10-82	MODEL 801RDS FIRE/OVERHEAT DETECTOR	Package B	TEST	PRE-TEST	CLEANING AND VISUAL INSPECTION	230	SR Technics Switzerland
139537	8862-101	EASA;FAA;CAAC;ANAC;CAA UK			26-10-82		Package C	TEST	TEMPERATURE TEST		815	SR Technics Switzerland
139537	8862-101-1150-707-9	EASA;FAA;ANAC										
139550	335-191-202-0	EASA;FAA;CAAC;ANAC	38	28	72-21-02	FAN AND BOOSTER - BOOSTER BLADES, STAGES 2-4	Package A	CLN/INSP	CLEANING AND INSPECTION		50	SR Technics Switzerland
139550	335-191-203-0	EASA;FAA;CAAC;ANAC			72-21-02		Package E		WEIGH AND MATCH BLADE		50	SR Technics Switzerland
139550	335-191-204-0	EASA;FAA;CAAC;ANAC										
139550	335-191-205-0	EASA;FAA;CAAC;ANAC										
139550	335-191-302-0	EASA;FAA;CAAC;ANAC										
139550	335-191-303-0	EASA;FAA;CAAC;ANAC										
139550	335-191-304-0	EASA;FAA;CAAC;ANAC										
139550	335-191-305-0	EASA;FAA;CAAC;ANAC										
139550	338-002-206-0	EASA;FAA;CAAC;ANAC										
139550	338-002-207-0	EASA;FAA;CAAC;ANAC										
139550	338-002-208-0	EASA;FAA;CAAC;ANAC										
139550	338-002-209-0	EASA;FAA;CAAC;ANAC										
139550	338-002-218-0	EASA;FAA;CAAC;ANAC										
139550	338-002-219-0	EASA;FAA;CAAC;ANAC										
139550	338-002-220-0	EASA;FAA;CAAC;ANAC										
139550	338-002-221-0	EASA;FAA;CAAC;ANAC										
139550	338-002-306-0	EASA;FAA;CAAC;ANAC										
139550	338-002-307-0	EASA;FAA;CAAC;ANAC										
139550	338-002-308-0	EASA;FAA;CAAC;ANAC										
139550	338-002-309-0	EASA;FAA;CAAC;ANAC										
139550	338-002-318-0	EASA;FAA;CAAC;ANAC										
139550	338-002-319-0	EASA;FAA;CAAC;ANAC										
139550	338-002-320-0	EASA;FAA;CAAC;ANAC										
139550	338-002-321-0	EASA;FAA;CAAC;ANAC										
139550	338-002-406-0	EASA;FAA;CAAC;ANAC										
139550	338-002-407-0	EASA;FAA;CAAC;ANAC										
139550	338-002-408-0	EASA;FAA;CAAC;ANAC										
139550	338-002-409-0	EASA;FAA;CAAC;ANAC										
139550	338-002-418-0	EASA;FAA;CAAC;ANAC										
139550	338-002-419-0	EASA;FAA;CAAC;ANAC										
139550	338-002-420-0	EASA;FAA;CAAC;ANAC										
139550	338-002-421-0	EASA;FAA;CAAC;ANAC										
139550	338-002-518-0	EASA;FAA;CAAC;ANAC										
139550	338-002-519-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139550	338-002-520-0	EASA,FAA,CAAC,ANAC										
139550	338-002-521-0	EASA,FAA,CAAC,ANAC										
139550	338-002-534-0	EASA,FAA,CAAC,ANAC										
139550	338-002-535-0	EASA,FAA,CAAC,ANAC										
139550	338-002-536-0	EASA,FAA,CAAC,ANAC										
139550	338-002-537-0	EASA,FAA,CAAC,ANAC										
139550	338-002-542-0	EASA,FAA,CAAC,ANAC										
139550	338-002-543-0	EASA,FAA,CAAC,ANAC										
139550	338-002-544-0	EASA,FAA,CAAC,ANAC										
139550	338-002-545-0	EASA,FAA,CAAC,ANAC										
139550	340-057-201-0	EASA,FAA,CAAC,ANAC										
139550	340-057-202-0	EASA,FAA,CAAC,ANAC										
139550	340-057-203-0	EASA,FAA,CAAC,ANAC										
139550	340-057-204-0	EASA,FAA,CAAC,ANAC										
139550	340-057-301-0	EASA,FAA,CAAC,ANAC										
139550	340-057-302-0	EASA,FAA,CAAC,ANAC										
139550	340-057-303-0	EASA,FAA,CAAC,ANAC										
139550	340-057-304-0	EASA,FAA,CAAC,ANAC										
139550	340-057-401-0	EASA,FAA,CAAC,ANAC										
139550	340-057-402-0	EASA,FAA,CAAC,ANAC										
139550	340-057-403-0	EASA,FAA,CAAC										
139550	340-057-404-0	EASA,FAA,CAAC										
139550	340-057-409-0	EASA,FAA,CAAC,ANAC										
139550	340-057-410-0	EASA,FAA,CAAC,ANAC										
140037	338-083-003-0	EASA,FAA,CAAC,ANAC	24	28	72-54-08	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 2	Package A		BASIC REPAIR	PN338-083-104-0 338-083-154-0 FOR SHO	290 SRTAS	
140037	338-083-004-0	EASA,FAA,CAAC,ANAC			72-54-08		Package A	INSP-001	VISUAL / DIMENSIONAL		290 SRTAS	
140037	338-083-053-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C		MINOR REPAIR		1,695 SRTAS	
140037	338-083-054-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	1	AIRFOIL BLEND REPAIR		1,695 SRTAS	
140037	338-083-104-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1,695 SRTAS	
140037	338-083-105-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	32	RD 15-94412 - OVERCOATING OF APVS PROTECTION		1,695 SRTAS	
140037	338-083-154-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	4	REPAIR OF APVS COATING		1,695 SRTAS	
140037	338-083-155-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	INSP-001	VISUAL / DIMENSIONAL		1,695 SRTAS	
140037	338-083-204-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D		FULL REPAIR		3,540 SRTAS	
140037	338-083-205-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	1	AIRFOIL BLEND REPAIR.		3,540 SRTAS	
140037	338-083-254-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	15	RD 15-94438 - RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURF/		3,540 SRTAS	
140037	338-083-255-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3,540 SRTAS	
140037	338-109-104-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	20	FULL BRAZING REPAIR		3,540 SRTAS	
140037	338-109-105-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	4	REPAIR OF APVS COATING.		3,540 SRTAS	
140037	338-109-106-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	INSP-001	VISUAL / DIMENSIONAL		3,540 SRTAS	
140037	338-109-107-0	EASA,FAA,CAAC,ANAC			72-54-08		Package E		ADDITIONAL WORKSCOPE		900 SRTAS	
140037	338-109-108-0	EASA,FAA,CAAC,ANAC			72-54-08		Package E	19	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.		900 SRTAS	
140037	338-109-109-0	EASA,FAA,CAAC,ANAC			72-54-08		Package F	72-0328	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB REPLACEMENT WHEN PERFORMED INDEPENDENTLY)		895 SRTAS	
140037	338-109-150-0	EASA,FAA,CAAC,ANAC			72-54-08		Package G	72-0328	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB REPLACEMENT WHEN PERFORMED AS PART OF MINOR C		750 SRTAS	
140037	338-109-151-0	EASA,FAA,CAAC,ANAC			72-54-08		Package H	29	REPLACEMENT OF THE HONEYCOMB LINER		1,030 SRTAS	
140037	338-109-204-0	EASA,FAA,CAAC,ANAC										
140037	338-109-205-0	EASA,FAA,CAAC,ANAC										
140037	338-109-206-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140037	338-109-207-0	EASA;FAA;CAAC;ANAC									
140037	338-109-208-0	EASA;FAA;CAAC;ANAC									
140037	338-109-209-0	EASA;FAA;CAAC;ANAC									
140037	338-109-250-0	EASA;FAA;CAAC;ANAC									
140037	338-109-251-0	EASA;FAA;CAAC;ANAC									
140037	338-109-304-0	EASA;FAA;CAAC;ANAC									
140037	338-109-305-0	EASA;FAA;CAAC;ANAC									
140037	338-109-306-0	EASA;FAA;CAAC;ANAC									
140037	338-109-307-0	EASA;FAA;CAAC;ANAC									
140037	338-109-308-0	EASA;FAA;CAAC;ANAC									
140037	338-109-309-0	EASA;FAA;CAAC;ANAC									
140037	338-109-350-0	EASA;FAA;CAAC;ANAC									
140037	338-109-351-0	EASA;FAA;CAAC;ANAC									
140037	340-303-001-0	EASA;FAA;CAAC;ANAC									
140037	340-303-101-0	EASA;FAA;CAAC;ANAC									
140037	340-303-201-0	EASA;FAA;CAAC;ANAC									
140121	1276M85P05	EASA;FAA;CAAC;ANAC	20	28 72-32-15	COMPRESSOR STATOR SUPPORT PLATE AND LINK	Package A	CLN/INSP	CLEANING AND INSPECTION		760	SR Technics Switzerland
140121	1276M86P05	EASA;FAA;CAAC;ANAC		72-32-15		Package SB00	72-0114	BELLCRANK VANE ACTUATION LINK BUSHING REPLACEMENT		2,520	SR Technics Switzerland
140121	1591M23P02	EASA;FAA;CAAC;ANAC									
140121	1591M24G01	EASA;FAA;CAAC;ANAC									
140121	9511M34P01	EASA;FAA;CAAC;ANAC									
140245	338-061-302-0	EASA;FAA;CAAC;ANAC	50	28 72-54-11	LOW PRESSURE TURBINE - COOLING MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	640	SR Technics Switzerland
140245	338-061-352-0	EASA;FAA;CAAC;ANAC		72-54-11		Package B	001	REPLACEMENT OF ONE OR SEVERAL COOLING AIR TUBES		1,200	SR Technics Switzerland
140245	338-119-301-0	EASA;FAA;CAAC;ANAC		72-54-11		Package F	005	REPLACEMENT OF THE FORWARD AND / OR REAR LUGS		900	SR Technics Switzerland
140245	340-027-505-0	EASA;FAA;CAAC;ANAC		72-54-11		Package H	007	SMOOTHING OF BRAZE		625	SR Technics Switzerland
140245	340-027-506-0	EASA;FAA;CAAC;ANAC		72-54-11		Package K	006	REPAIR OF CRACKS ON LUG BY TIG WELDING		490	SR Technics Switzerland
140245	340-027-507-0	EASA;FAA;CAAC;ANAC;CAA UK		72-54-11		Package L	004	REPLACEMENT OF SLEEVE		3,435	SR Technics Switzerland
140245	340-027-508-0	EASA;FAA;CAAC;ANAC									
140245	340-027-555-0	EASA;FAA;CAAC;ANAC									
140245	340-027-556-0	EASA;FAA;CAAC;ANAC									
140245	340-027-557-0	EASA;FAA;CAAC;ANAC									
140245	340-038-251-0	EASA;FAA;CAAC;ANAC;CAA UK									
140245	340-038-307-0	EASA;FAA;CAAC;ANAC									
140245	340-038-351-0	EASA;FAA;CAAC;ANAC;CAA UK									
140245	340-311-401-0	EASA;FAA;CAAC;ANAC									
140245	340-311-402-0	EASA;FAA;CAAC;ANAC									
144718	1498M53G01	EASA;FAA;CAAC;ANAC	29	28 72-41-07	COMBUSTION CASE - COMPRESSOR STATOR SUPPORT CDP BULKHEAD	Package A	CLN/INSP	CLEANING AND INSPECTION		1,115	SR Technics Switzerland
144718	1834M52P01	EASA;FAA;CAAC;ANAC		72-41-07		Package B	001	DIMENSIONAL RESTORATION		4,885	SR Technics Switzerland
144718	1834M52P02	EASA;FAA;CAAC;ANAC		72-41-07		Package C		MEASURE NEW - / OVHLD PARTS		130	SR Technics Switzerland
144718	1993M20G01	EASA;FAA;CAAC;ANAC		72-41-07		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P,CFM56-5B2/2 TO CFM565B2/ CFM56-5B6/2 TO CFM56-5B6/2P, CFM565		775	SR Technics Switzerland
144718	2428M60G01	EASA;FAA;CAAC;ANAC									
144741	305-397-203-0	EASA;FAA;CAAC;ANAC	23	21 72-23-26	FAN FRAME ASSEMBLY - AIR TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	725	SR Technics Switzerland
144741	338-171-501-0	EASA;FAA;CAAC;ANAC		72-23-26		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF SULFURIC ANODIZING		175	SR Technics Switzerland
144741	340-032-401-0	EASA;FAA;CAAC;ANAC									
144755	338-001-905-0	EASA;FAA;CAAC;ANAC	40	28 72-21-04	FAN AND BOOSTER - BOOSTER SPOOL	Package A	CLN/INSP	CLEANING AND INSPECTION		2,125	SR Technics Switzerland
144755	338-001-906-0	EASA;FAA;CAAC;ANAC		72-21-04		Package B	001	REPLACEMENT OF THE HI-LOCK FASTENERS AND/OR THE SEALING FLANGE		2,480	SR Technics Switzerland
144755	340-000-814-0	EASA;FAA;CAAC;ANAC		72-21-04		Package C	002	SPOT TOUCH-UP OR FULL REPAIR OF CHROMIC OR SULFURIC ANODIZING ON SE.		465	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144755	340-000-815-0	EASA;FAA;CAAC;ANAC			72-21-04		Package E		REMOVE BOOSTER SPOOL FWD FLANGE PLUG		465	SR Technics Switzerland
144755	340-000-816-0	EASA;FAA;CAAC;ANAC			72-21-04		Package K	010	TOUCH UP OF SEAL TEETH		2,755	SR Technics Switzerland
144755	340-000-824-0	EASA;FAA;CAAC;ANAC										
144755	340-000-825-0	EASA;FAA;CAAC;ANAC										
144755	340-000-826-0	EASA;FAA;CAAC;ANAC;CAA UK										
144756	338-002-701-0	EASA;FAA;CAAC;ANAC	27	28	72-21-04	FAN AND BOOSTER - SEALING FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		640	SR Technics Switzerland
144756	338-002-702-0	EASA;FAA;CAAC;ANAC			72-21-04		Package C	002	SPOT TOUCH-UP FULL OR RECONDITIONING OF THE CHROMIC OR SULFURIC ANI		895	SR Technics Switzerland
144756	338-002-703-0	EASA;FAA;CAAC;ANAC										
144756	340-003-103-0	EASA;FAA;CAAC;ANAC										
144787	337-002-910-0	EASA;FAA;CAAC;ANAC	63	28	72-55-01	LOW PRESSURE TURBINE SHAFT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1,575	SR Technics Switzerland
144787	338-010-003-0	EASA;FAA;CAAC;ANAC			72-55-01		Package A	INSP	BORESCOPE INSPECTION (BSI)		1,575	SR Technics Switzerland
144787	338-010-004-0	EASA;FAA;CAAC;ANAC			72-55-01		Package AF	031	REPLACEMENT OF THREADED INSERTS		1,200	SR Technics Switzerland
144787	338-010-005-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-01		Package B	INSP-001	OUTER PAINTED SURFACE - CORROSION	BLENDED AND TOUCHUP REPAIR	1,105	SR Technics Switzerland
144787	338-010-006-0	EASA;FAA;CAAC;ANAC			72-55-01		Package C	INSP-001	INNER SURFACE - CORROSION	BLASTING AND TOUCHUP REPAIR	1,385	SR Technics Switzerland
144787	340-074-703-0	EASA;FAA;CAAC;ANAC			72-55-01		Package D	001	FULL REPAIR OF THE ALUMINUM PAINT		4,190	SR Technics Switzerland
144787	340-074-705-0	EASA;FAA;CAAC;ANAC			72-55-01		Package H	014	BLENDED OF THE FORWARD ANTI-ROTATION LUGS		1,045	SR Technics Switzerland
144787	340-074-706-0	EASA;FAA;CAAC;ANAC			72-55-01		Package Q	016	CLEANING AND PACKAGING		465	SR Technics Switzerland
144787	340-074-707-0	EASA;FAA;CAAC;ANAC			72-55-01		Package S	018	REPAIR OF THE LOCATING DIAMETER WITH AIR/OIL SEPARATOR		2,795	SR Technics Switzerland
144787	340-074-720-0	EASA;FAA;CAAC;ANAC			72-55-01		Package SB00	72-0559	INSPECTION OF THE FORWARD LPT SHAFT FOR MISSING PAINT	IN CONJUNCTION WITH PACKAGE A	1,095	SR Technics Switzerland
144787	340-074-721-0	EASA;FAA;CAAC;ANAC			72-55-01		Package SB01	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI)	IN CONJUNCTION WITH PACKAGE A	810	SR Technics Switzerland
144787	340-074-722-0	EASA;FAA;CAAC;ANAC										
144787	340-074-723-0	EASA;FAA;CAAC;ANAC;CAA UK										
144788	336-025-102-0	EASA;FAA;CAAC;ANAC	29	28	72-56-03	LOW PRESSURE TURBINE REAR FRAME - OIL COLLECTOR	Package A	CLN/INSP	CLEANING AND INSPECTION		640	SR Technics Switzerland
144788	338-170-601-0	EASA;FAA;CAAC;ANAC										
144788	340-175-802-0	EASA;FAA;CAAC;ANAC;CAA UK										
144788	340-175-803-0	EASA;FAA;CAAC;ANAC										
144794	336-009-602-0	EASA;FAA;ANAC	41	28	72-53-11	STAGE 1 LPT NOZZLE - INTERMEDIATE FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		770	SR Technics Switzerland
144794	338-111-201-0	EASA;FAA;CAAC;ANAC			72-53-11		Package B	001	REPAIR OF THERMAL COATING ON MATING FACE & RABBET DIA WITH STG 1 LPTAREA A EFF. M		3,685	SR Technics Switzerland
144794	338-111-202-0	EASA;FAA;CAAC;ANAC;CAA UK										
604609	642W9821-501	EASA;FAA;CAAC;ANAC	22	21	71-50-03	JUNCTION BOX TO THRUST REVERSER CHANNEL A AND CHANNEL B HAR	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	410	SR Technics Switzerland
604609	642W9853-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1,345	SR Technics Switzerland
604609	642W9853-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CON	3,790	SR Technics Switzerland
604609	642W9854-501	EASA;FAA;CAAC;ANAC			71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE A	4,995	SR Technics Switzerland
604609	642W9854-505	EASA;FAA;CAAC;ANAC										
604609	642W9872-501	EASA;FAA;CAAC;ANAC										
604609	642W9873-501	EASA;FAA;CAAC;ANAC										
604609	642W9881-501	EASA;FAA;CAAC;ANAC										
604609	642W9882-501	EASA;FAA;CAAC;ANAC										
604609	642W9884-501	EASA;FAA;CAAC;ANAC										
614157	9542M62P02	EASA;FAA;CAAC;ANAC	13	28	72-61-13	INLET GEARBOX & NO.3 BEARING - REAR INSULATION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		1,175	SR Technics Switzerland
614157	9542M62P03	EASA;FAA;CAAC;ANAC										
619936	336-031-901-0	EASA;FAA;CAAC;ANAC	33	28	72-56-07	LOW PRESSURE TURBINE REAR FRAME - FLANGE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	780	SR Technics Switzerland
619936	337-087-302-0	EASA;FAA;CAAC;ANAC			72-56-07		Package B	001	REPLACEMENT OF THE EQUIPMENT		1,045	SR Technics Switzerland
619936	338-171-801-0	EASA;FAA;CAAC;ANAC			72-56-07		Package C	002	REAR COVER, FILLER WELDING OF CRACKS		3,725	SR Technics Switzerland
619936	338-171-802-0	EASA;FAA;CAAC;ANAC			72-56-07		Package D	003	REPLACEMENT OF THE SLEF LOCKING NUTS		775	SR Technics Switzerland
619936	338-171-902-0	EASA;FAA;CAAC;ANAC			72-56-07		Package E	004	CONFIG.2/3 CIRCULAR STAMP ON THE FLANGE		500	SR Technics Switzerland
619936	340-157-501-0	EASA;FAA;CAAC;ANAC			72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.1	545	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
619936	340-157-502-0	EASA;FAA;CAAC;ANAC		72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.2/3	545	SR Technics Switzerland
619936	340-165-601-0	EASA;FAA;CAAC;ANAC									
619936	340-168-802-0	EASA;FAA;CAAC;ANAC									
619936	340-168-803-0	EASA;FAA;CAAC;ANAC									
622278	338-089-701-0	EASA;FAA;CAAC;ANAC	31	28 72-00-63	ENGINE MODULES/ASSEMBLIES - ACCESSORY GEARBOX MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION	INCLUDING CONSERVATION	5,080	SR Technics Switzerland
622278	338-089-702-0	EASA;FAA;CAAC;ANAC									
622278	338-089-703-0	EASA;FAA;CAAC;ANAC									
622278	340-046-503-0	EASA;FAA;CAAC;ANAC									
622278	340-046-504-0	EASA;FAA;CAAC;ANAC									
622278	340-046-505-0	EASA;FAA;CAAC;ANAC									
622278	340-046-508-0	EASA;FAA;CAAC;JICAB;ANAC									
622278	340-046-509-0	EASA;FAA;CAAC;JICAB;ANAC;CAA									
622278	340-046-528-0	EASA;FAA;JICAB;ANAC									
622278	340-188-601-0	EASA;FAA;CAAC;ANAC									
622278	340-188-603-0	EASA;FAA;CAAC;ANAC									
624071	301-360-006-0	EASA;FAA;CAAC;ANAC	25	28 72-23-14	FAN FRAME ASSEMBLY - ACCESSORY DRIVE MOUNT LINK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	585	SR Technics Switzerland
624071	301-360-020-0	EASA;FAA;CAAC;ANAC		72-23-14		Package K	010	REPLACEMENT OF SPHERICAL BEARING ON MOUNT LINKS	72-09-04	1,020	SR Technics Switzerland
624071	305-356-606-0	EASA;FAA;CAAC;ANAC									
624071	305-356-620-0	EASA;FAA;CAAC;ANAC									
624071	338-077-601-0	EASA;FAA;CAAC;ANAC									
624071	338-077-651-0	EASA;FAA;CAAC;ANAC									
624071	340-029-401-0	EASA;FAA;CAAC;ANAC									
624071	340-029-501-0	EASA;FAA;CAAC;ANAC									
624071	340-029-502-0	EASA;FAA;CAAC;ANAC;CAA UK									
624071	340-032-801-0	EASA;FAA;CAAC;ANAC									
624071	340-103-802-0	EASA;FAA;CAAC;ANAC									
624071	340-168-001-0	EASA;FAA;CAAC;ANAC									
624071	340-168-101-0	EASA;FAA;CAAC;ANAC									
624071	340-168-201-0	EASA;FAA;CAAC;ANAC									
624071	340-168-501-0	EASA;FAA;CAAC;ANAC									
629621	1522M71P01	EASA;FAA;CAAC;ANAC	23	28 72-53-05	HPT SHROUD - MISCELLANEOUS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	145	SR Technics Switzerland
629621	1667M72P01	EASA;FAA;CAAC;ANAC									
629938	1318M40G02	EASA;FAA;CAAC;ANAC	26	28 72-32-14	COMPRESSOR FRONT STATOR - VANE ACTUATOR TIE RODS	Package A	CLN/INSP	CLEANING AND INSPECTION		175	SR Technics Switzerland
629938	1318M40G03	EASA;FAA;CAAC;ANAC		72-32-14		Package B	001	INLET GUIDE VANE STAGE 1 AND STAGE 2 LINK SPHERICAL BEARING REPLACEME		360	SR Technics Switzerland
629938	1318M40G06	EASA;FAA;CAAC;ANAC		72-32-14		Package C	002	STAGE 3 LINK SPHERICAL BEARING REPLACEMENT		595	SR Technics Switzerland
629938	1318M41G02	EASA;FAA;CAAC;ANAC									
629938	1590M22P03	EASA;FAA;CAAC;ANAC									
629938	1590M22P04	EASA;FAA;CAAC;ANAC									
629938	1590M22P09	EASA;FAA;CAAC;ANAC									
629938	1590M33P01	EASA;FAA;CAAC;ANAC;CAA UK									
631917	642-2003-501	EASA;FAA;CAAC;ANAC	6	21 71-21-08	CFM56-5B MOUNT FWD ATTACHEMENT PINS	Package A	CLN/INSP	CLEANING & INSPECTION		385	SR Technics Switzerland
634090	1317M56G06	EASA;FAA;CAAC;ANAC	50	28 72-42-04	COMBUSTION CHAMBER (SAC) - OUTER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		1,030	SR Technics Switzerland
634090	1317M56G07	EASA;FAA;CAAC;ANAC		72-42-04		Package AA	026	APPL. OF THIN TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		4,235	SR Technics Switzerland
634090	1317M56G08	EASA;FAA;CAAC;ANAC		72-42-04		Package AB	027	CRACK WELD/RESIZE REPAIR	+9 days TAT	7,260	SR Technics Switzerland
634090	1317M56G09	EASA;FAA;CAAC;ANAC		72-42-04		Package AE	OS 255085	AIRFLOW TEST OF LARGE DIAMETER MULTI-HOLES ON OUTER LINER PANEL		3,170	SR Technics Switzerland
634090	1317M56G10	EASA;FAA;CAAC;ANAC		72-42-04		Package C	002	REPAIR OF THE PLASMA SPRAY WEAR COATING ON THE OUTER LINER SEAL		13,765	SR Technics Switzerland
634090	1317M56G11	EASA;FAA;CAAC;ANAC		72-42-04		Package C	003	REMOVAL OF THE THERMAL BARRIER COATING FROM THE OUTER LINER		13,765	SR Technics Switzerland

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

**Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply**



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634090	1317M56G12	EASA;FAA;CAAC;ANAC			72-42-04		Package C	004	(THIN) APPLY THE THERMAL BARRIER COATING ON THE OUTER LINER		13,765	SR Technics Switzerland
634090	1317M56G13	EASA;FAA;CAAC;ANAC			72-42-04		Package C	005	REMOVAL OF THE COMBUSTION CHAMBER OUTER LINER LUG RING		13,765	SR Technics Switzerland
634090	1317M56G14	EASA;FAA;ANAC			72-42-04		Package C	007	BOLT HOLE DRILLING REPAIR		13,765	SR Technics Switzerland
634090	1968M44G02	EASA;FAA;CAAC;ANAC			72-42-04		Package C	008	WELD REPAIR AND RESIZING OF COMBUSTION CHAMBER OUTER LINERS THAT F		13,765	SR Technics Switzerland
634090	1968M44G03	EASA;FAA;CAAC;ANAC			72-42-04		Package C	009	IGNITER SLEEVE, IGNITER FERRULE RETAINER AND IGNITER FERRULE REPAIR/RE		13,765	SR Technics Switzerland
634090	1968M44G04	EASA;FAA;CAAC;ANAC			72-42-04		Package C	014	COMBUSTION CHAMBER OUTER LINER IGNITOR FERRULE REPLACEMENT REPAIR		13,765	SR Technics Switzerland
634090	1968M44G05	EASA;FAA;CAAC;ANAC			72-42-04		Package C	016	(THICK) THERMAL BARRIER COATING REPLACEMENT		13,765	SR Technics Switzerland
634090	1968M44G06	EASA;FAA;CAAC;ANAC;CAA UK			72-42-04		Package C	017	IGNITER PORT LOCALIZED SIZING REPAIR AND INSPECTION		13,765	SR Technics Switzerland
634090	1968M44G08	EASA;FAA;CAAC;ANAC			72-42-04		Package C	020	WELD REPAIR AND RESIZING OF THE OUTER LINER WITHOUT LUG RING REMOV		13,765	SR Technics Switzerland
634090	1968M44G09	EASA;FAA;ANAC			72-42-04		Package F	012	WELDED PATCH REPAIR		3,175	SR Technics Switzerland
634090	1968M45G03	EASA;FAA;CAAC;ANAC			72-42-04		Package G	013	INCO 718 PLASMA SPRAY REPAIR OF THE LUG RING AFT SURFACE		2,630	SR Technics Switzerland
634090	1968M45G04	EASA;FAA;CAAC;ANAC			72-42-04		Package I	015	AFT SEAL FLANGE WELD REPAIR		4,735	SR Technics Switzerland
634090	1968M63G05	EASA;FAA;CAAC;ANAC			72-42-04		Package S	018	AFT SUPPORT RING REPLACEMENT		4,940	SR Technics Switzerland
634090	1968M63G06	EASA;FAA;CAAC;ANAC			72-42-04		Package SB00	72-0584	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE C	410	SR Technics Switzerland
634090	1968M63G07	EASA;FAA;CAAC;ANAC			72-42-04		Package SB01	72-0656	COMBUSTION CHAMBER OUTER LINER REWORK	RECOATING WITH THICK THERMAL BARRIE	6,040	SR Technics Switzerland
634090	1968M63G08	EASA;FAA;CAAC;ANAC			72-42-04		Package SB02	72-0336	INNER AND OUTER LINER THICKER TBC FIELD REWORK		1,155	SR Technics Switzerland
634090	1968M63G09	EASA;FAA;CAAC;ANAC			72-42-04		Package SB04	72-0825	ALTERATION / THIN THERMAL BARRIER COATING APPLICATION		2,880	SR Technics Switzerland
634090	1968M63G11	EASA;FAA;CAAC;ANAC			72-42-04		Package SB04	72-0831	ALTERATION / THIN THERMAL BARRIER COATING APPLICATION		2,880	SR Technics Switzerland
634090	1968M63G12	EASA;FAA;CAAC;ANAC			72-42-04		Package SB05	72-0799	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING THICK TBC, +9 days TAT		10,610	SR Technics Switzerland
634090	1968M63G15	EASA;FAA;CAAC;ANAC			72-42-04		Package SB06	72-0826	REWORK OF PRE-TECH INSERTION OUTER CC LINER WITH MULTI-HOLE COOLING +9 days TAT		4,235	SR Technics Switzerland
634090	1968M63G16	EASA;FAA;CAAC;ANAC			72-42-04		Package SB08	72-0799	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING THIN TBC, +9 days TAT		10,610	SR Technics Switzerland
634090	1968M63G19	EASA;FAA;CAAC;ANAC			72-42-04		Package SB09	72-1086	OUTER COMBUSTION CHAMBER LINER REMARKING		525	SR Technics Switzerland
634090	2256M22G01	EASA;FAA;CAAC;ANAC			72-42-04		Package SB11	72-1099	OUTER CC LINER WELD BUILDUP INSPECTION AT IGNITER PORT	2256M22G03	1,365	SR Technics Switzerland
634090	2256M22G02	EASA;FAA;CAAC;ANAC			72-42-04		Package V	021	AFT SEAL FLANGE WELD REPAIR		5,090	SR Technics Switzerland
634090	2256M22G03	EASA;FAA;CAAC;ANAC			72-42-04		Package X	023	INSTALLATION OF A LUG RING WITH HIGH TEMPERATURE BRAZE ALLOY		9,345	SR Technics Switzerland
634090	2256M22G04	EASA;FAA;CAAC;ANAC			72-42-04		Package Y	024	WELD PATCH REPAIR FOR THE TECH INSERTION OUTER LINER		3,325	SR Technics Switzerland
634090	2414M75G02	EASA;FAA;CAAC;ANAC			72-42-04		Package Z	025	APPL. OF THICK TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		4,235	SR Technics Switzerland
634090	2414M75G03	EASA;FAA;CAAC;ANAC										
634090	2414M75G04	EASA;FAA;CAAC;ANAC										
634090	2414M75G06	EASA;FAA;CAAC;ANAC										
634090	2414M75G07	EASA;FAA;CAAC;ANAC										
634090	2414M75G08	EASA;FAA;CAAC;ANAC										
634090	2480M42G01	EASA;FAA;ANAC										
634090	2480M42G02	EASA;FAA;ANAC										
635513	336-092-208-0	EASA;FAA;CAAC;ANAC	20	28	72-00-56	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE REAR FRAM	Package A	INSP-001	CLEANING COKING SUPPL/SCAV. TUBES	PN340-035-901-0 FOR SHOP VISIT ONLY	270	SR Technics Switzerland
635513	338-071-401-0	EASA;FAA;CAAC;ANAC			72-00-56		Package C	SPEC-PROC	REPLACE THE TURBINE FRAM MODULE		2,290	SR Technics Switzerland
635513	340-035-901-0	EASA;FAA;ANAC			72-00-56		Package D		CRACK INSPECTION NIPPEL AREA BRG NO 5 HOUSING		190	SR Technics Switzerland
635513	340-035-903-0	EASA;FAA;CAAC;ANAC			72-00-56		Package SB00	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		925	SR Technics Switzerland
635513	340-035-904-0	EASA;FAA;ANAC			72-00-56		Package SB01	EASA-2014-0130	TIME LIMITS - ENGINE STATIONARY PARTS - LIFE LIMITS		295	SR Technics Switzerland
635513	340-035-905-0	EASA;FAA;ANAC										
635513	340-035-906-0	EASA;FAA;ANAC										
635513	340-035-907-0	EASA;FAA;ANAC										
635513	340-035-908-0	EASA;FAA;ANAC										
635520	1887M16G01	EASA;FAA;CAAC;ANAC	19	28	72-00-32	ENGINE MODULES/ASSEMBLIES - COMPRESSOR FRONT STATOR ASSEMI	Package A	CLN/INSP	CLEANING AND INSPECTION	PN9324M76G02 FOR SHOP VISIT ONLY	510	SR Technics Switzerland
635520	1887M16G02	EASA;FAA;CAAC;ANAC			72-00-32		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		920	SR Technics Switzerland
635520	1887M16G05	EASA;FAA;CAAC			72-00-32		Package M	ASSEMBLY	GRINDING STAGE 1-5 HONEYCOMBS		5,140	SR Technics Switzerland
635520	9324M66G01	EASA;FAA;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
635520	9324M66G02	EASA;FAA;ANAC										
635520	9324M76G01	EASA;FAA;CAAC;ANAC										
635520	9324M76G02	EASA;FAA;CAAC;ANAC										
635864	9324M54G04	EASA;FAA;CAAC;ANAC	19	28	72-00-61	ENGINE MODULES/ASSEMBLIES - INLET GEARBOX AND NO3 BEARING M	Package SB00	72-0776	INTRODUCTION OF NO.3 BALL BEARING WITH NITRIDE HARDENING		170	SR Technics Switzerland
635864	9324M54G05	EASA;FAA;CAAC;ANAC										
635864	9324M54G06	EASA;FAA;CAAC;ANAC										
635864	9324M54G07	EASA;FAA;ANAC										
636431	338-071-201-0	EASA;FAA;CAAC;ANAC	23	28	72-00-54	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION		510	SR Technics Switzerland
636431	338-092-301-0	EASA;FAA;CAAC;ANAC			72-00-54		Package B	INSP-001	MINOR MODULE MEASUREMENT RAIL "O"		175	SR Technics Switzerland
636431	338-092-319-0	EASA;FAA;CAAC;ANAC			72-00-54		Package C	002	TEMPRORARY REPLACEMENT OF BROKEN STUD OF T 49.5 EGT SENSOR ASSEMB		1,385	SR Technics Switzerland
636432	338-071-301-0	EASA;FAA;CAAC;ANAC	5	28	72-00-55	CFM56 LPT SHAFT MINOR MODUL	Package A	CLN/INSP	CLEANING & INSPECTION		435	SR Technics Switzerland
636432	338-071-302-0	EASA;FAA;ANAC			72-00-55		Package B	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR		525	SR Technics Switzerland
636432	338-071-305-0	EASA;FAA;ANAC			72-00-55		Package K	010	RECONDITIONING OF SHAFT PAINT	72-00-03	345	SR Technics Switzerland
636432	338-071-306-0	EASA;FAA;ANAC			72-00-55		Package O	014	BLENDING ANTI-ROTATION-LUG	72-55-01	545	SR Technics Switzerland
636432	340-035-801-0	EASA;FAA;ANAC										
636432	340-035-804-0	EASA;FAA;CAAC;ANAC										
636432	340-035-805-0	EASA;FAA;CAAC;ANAC										
636616	338-118-004-0	EASA;FAA;CAAC;ANAC	7	28	72-54-07	CFM56 LPT CASE RING SECTOR SEGMENTS	Package A	CLN/INSP	CLEANING AND INSPECTION		440	SR Technics Switzerland
636616	338-118-104-0	EASA;FAA;CAAC;ANAC			72-54-07		Package B	025	CRACK REPAIR ON SHIELD SHROUD SECTOR		1,145	SR Technics Switzerland
636616	338-118-204-0	EASA;FAA;CAAC;ANAC										
636616	338-118-304-0	EASA;FAA;CAAC;ANAC										
640894	1444M33G02	EASA;FAA;CAAC;ANAC	25	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	355	SR Technics Switzerland
640894	1467M24G01	EASA;FAA;CAAC;ANAC			72-09-03		Package A	TEST	PRESSURE TEST		355	SR Technics Switzerland
640894	1467M30G01	EASA;CAAC;EASA/ANAC BRAZIL D			72-09-03		Package B	001	BLENDING		255	SR Technics Switzerland
640894	1605M78G03	EASA;FAA;CAAC;ANAC			72-09-03		Package G	006	REFACE SPHERICAL SEATINGS		430	SR Technics Switzerland
640894	1813M50G01	EASA;FAA;CAAC;ANAC			72-09-03		Package H	007	REFACE INTERNAL SEATING FACE		430	SR Technics Switzerland
640894	1817M21G02	EASA;FAA;CAAC;ANAC			72-09-03		Package SB00	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES	IN CONJUNCTION WITH PACKAGE A	155	SR Technics Switzerland
640894	1817M38G01	EASA;FAA;CAAC;ANAC			72-09-03		Package SB01	72-0072	MODIFICATION OF PS3 HOSE		220	SR Technics Switzerland
640894	1867M25G01	EASA;FAA;CAAC;ANAC			72-09-03		Package SB03	72-0416	INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WIT		580	SR Technics Switzerland
640894	1867M50G01	EASA;FAA;CAAC;ANAC										
640894	1870M60G01	EASA;FAA;CAAC;ANAC										
640894	1882M92G01	EASA;FAA;CAAC;ANAC										
640894	1892M13G01	EASA;FAA;CAAC;ANAC										
640894	1895M76G01	EASA;FAA;CAAC;ANAC										
640894	1896M60G01	EASA;FAA;CAAC;ANAC										
640894	1958M29G01	EASA;FAA;CAAC;ANAC										
640894	1958M69G01	EASA;FAA;CAAC;ANAC										
640894	1958M71G01	EASA;FAA;CAAC;ANAC										
640894	1971M27G01	EASA;FAA;CAAC;ANAC										
640894	2283M19G01	EASA;FAA;CAAC;ANAC										
640894	2283M20G01	EASA;FAA;CAAC;ANAC										
640894	2283M26G01	EASA;FAA;CAAC;ANAC										
640894	305-872-701-0	EASA;FAA;CAAC;ANAC										
640894	335-104-308-0	EASA;FAA;CAAC;ANAC										
640894	335-104-309-0	EASA;FAA;CAAC;ANAC										
640894	336-098-601-0	EASA;FAA;CAAC;ANAC										
640894	337-153-101-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640894	337-153-901-0	EASA;FAA;CAAC;ANAC										
640894	337-153-903-0	EASA;FAA;CAAC;ANAC										
640894	338-012-403-0	EASA;FAA;CAAC;ANAC										
640894	338-025-104-0	EASA;FAA;CAAC;ANAC										
640894	338-047-802-0	EASA;FAA;CAAC;ANAC										
640894	338-049-602-0	EASA;FAA;CAAC;ANAC										
640894	338-049-802-0	EASA;FAA;CAAC;ANAC										
640894	338-052-602-0	EASA;FAA;CAAC;ANAC										
640894	338-059-901-0	EASA;FAA;CAAC;ANAC										
640894	338-106-602-0	EASA;FAA;CAAC;ANAC										
640894	338-106-603-0	EASA;FAA;CAAC;ANAC										
640894	340-005-103-0	EASA;FAA;CAAC;ANAC										
640894	340-010-201-0	EASA;FAA;CAAC;ANAC										
640894	340-010-801-0	EASA;FAA;CAAC;ANAC										
640894	340-011-402-0	EASA;FAA;CAAC;ANAC										
640894	340-134-002-0	EASA;FAA;CAAC;ANAC										
640894	340-134-052-0	EASA;FAA;CAAC;ANAC										
640894	340-177-801-0	EASA;FAA;CAAC;ANAC										
640894	340-178-001-0	EASA;FAA;CAAC;ANAC;CAA UK										
640894	649-430-000-0	EASA;FAA;CAAC;ANAC										
640894	649-430-030-0	EASA;FAA;CAAC;ANAC										
640894	649-430-070-0	EASA;FAA;CAAC;ANAC										
640894	649-430-073-0	EASA;FAA;CAAC;ANAC										
640894	649-430-212-0	EASA;FAA;CAAC;ANAC										
640894	649-430-242-0	EASA;FAA;CAAC;ANAC										
640894	649-433-150-0	EASA;FAA;CAAC;ANAC										
640894	649-433-253-0	EASA;FAA;CAAC;ANAC										
640894	649-433-404-0	EASA;FAA;CAAC;ANAC										
640894	649-434-030-0	EASA;FAA;CAAC;ANAC										
640894	649-434-093-0	EASA;FAA;CAAC;ANAC										
640894	649-434-095-0	EASA;FAA;CAAC;ANAC										
640894	649-434-220-0	EASA;FAA;ANAC										
640894	649-434-231-0	EASA;FAA;CAAC;ANAC										
640894	649-434-242-0	EASA;FAA;CAAC;ANAC										
640894	649-434-254-0	EASA;FAA;CAAC;ANAC										
640894	649-434-404-0	EASA;FAA;CAAC;ANAC										
640894	649-438-013-0	EASA;FAA;CAAC;ANAC										
640894	649-438-014-0	EASA;FAA;CAAC;ANAC										
640894	649-439-013-0	EASA;FAA;CAAC;ANAC										
640894	9393M48G01	EASA;FAA;CAAC;ANAC										
640894	J534P10	EASA;FAA;CAAC;ANAC										
640894	R287P06	EASA;FAA;ANAC										
640894	R287P08	EASA;FAA;ANAC										
640895	1324M91G01	EASA;FAA;CAAC;ANAC	31	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	355	SR Technics Switzerland
640895	1443M92G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		1,280	SR Technics Switzerland
640895	1527M69G02	EASA;FAA;CAAC;ANAC			72-09-03		Package SB00	72-0416	INTRODUCTION OF NEW AND REWORKED P53 AIR TUBES AND TUBE NIPPLE WIT		580	SR Technics Switzerland
640895	1605M38G02	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	1605M94G01	EASA;FAA;CAAC;ANAC									
640895	1621M50G01	EASA;FAA;CAAC;ANAC									
640895	1645M19G01	EASA;FAA;CAAC;ANAC									
640895	1645M43G02	EASA;FAA;CAAC;ANAC									
640895	1677M61G01	EASA;FAA;CAAC;ANAC									
640895	1787M42G02	EASA;FAA;CAAC;ANAC									
640895	1788M44G01	EASA;FAA;CAAC;ANAC									
640895	1813M94G01	EASA;FAA;CAAC;ANAC									
640895	1817M21G01	EASA;FAA;CAAC;ANAC									
640895	1817M35G01	EASA;FAA;CAAC;ANAC									
640895	1867M38G01	EASA;FAA;CAAC;ANAC									
640895	1867M57G01	EASA;FAA;CAAC;ANAC									
640895	1867M69G01	EASA;FAA;CAAC;ANAC									
640895	1869M33G01	EASA;FAA;CAAC;ANAC									
640895	1870M53G01	EASA;FAA;CAAC;ANAC;CAA UK									
640895	1870M61G01	EASA;FAA;CAAC;ANAC									
640895	1870M97G01	EASA;FAA;CAAC;ANAC									
640895	1871M15G01	EASA;FAA;CAAC;ANAC									
640895	1871M35G01	EASA;FAA;CAAC;ANAC									
640895	1882M86G01	EASA;FAA;CAAC;ANAC									
640895	1892M61G01	EASA;FAA;CAAC;ANAC									
640895	1892M62G01	EASA;FAA;CAAC;ANAC									
640895	1892M80G01	EASA;FAA;CAAC;ANAC									
640895	1896M46G01	EASA;FAA;CAAC;ANAC									
640895	1896M47G01	EASA;FAA;CAAC;ANAC									
640895	1898M42G01	EASA;FAA;CAAC;ANAC									
640895	1898M58G01	EASA;FAA;CAAC;ANAC									
640895	1958M58G01	EASA;FAA;CAAC;ANAC									
640895	1970M21G01	EASA;FAA;CAAC;ANAC									
640895	1970M89G01	EASA;FAA;CAAC;ANAC									
640895	1971M28G01	EASA;FAA;CAAC;ANAC									
640895	1971M49G01	EASA;FAA;CAAC;ANAC									
640895	1971M74G01	EASA;FAA;CAAC;ANAC									
640895	2046M13G01	EASA;FAA;CAAC;ANAC									
640895	2046M41G01	EASA;FAA;CAAC;ANAC									
640895	2283M22G01	EASA;FAA;CAAC;ANAC									
640895	2283M23G01	EASA;FAA;CAAC;ANAC									
640895	2283M38G01	EASA;FAA;CAAC;TCCA									
640895	2283M69G01	EASA;FAA;CAAC;ANAC									
640895	2497M71G01	EASA;FAA;ANAC									
640895	305-397-001-0	EASA;FAA;CAAC;ANAC									
640895	336-451-005-0	EASA;CAAC;EASA/ANAC BRAZIL D									
640895	336-451-205-0	EASA;FAA;CAAC;ANAC									
640895	336-455-405-0	EASA;FAA;CAAC;ANAC									
640895	336-457-407-0	EASA;FAA;CAAC;ANAC									
640895	336-457-606-0	EASA;FAA;CAAC;ANAC									
640895	336-489-402-0	EASA;FAA;CAAC;ANAC									

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	336-489-604-0	EASA;FAA;CAAC;ANAC									
640895	337-026-804-0	EASA;FAA;CAAC;ANAC									
640895	337-027-203-0	EASA;FAA;CAAC;ANAC									
640895	337-029-705-0	EASA;FAA;CAAC;ANAC									
640895	337-029-902-0	EASA;FAA;CAAC;ANAC									
640895	337-152-702-0	EASA;FAA;CAAC;ANAC									
640895	337-153-503-0	EASA;FAA;CAAC;ANAC									
640895	337-154-101-0	EASA;FAA;CAAC;ANAC									
640895	338-011-706-0	EASA;FAA;CAAC;ANAC									
640895	338-011-809-0	EASA;FAA;CAAC;ANAC									
640895	338-011-908-0	EASA;FAA;CAAC;ANAC									
640895	338-012-006-0	EASA;FAA;CAAC;ANAC									
640895	338-023-402-0	EASA;FAA;CAAC;ANAC									
640895	338-023-603-0	EASA;FAA;CAAC;ANAC									
640895	338-023-803-0	EASA;FAA;CAAC;ANAC									
640895	338-023-804-0	EASA;CAAC;EASA/ANAC BRAZIL D									
640895	338-026-403-0	EASA;FAA;CAAC;ANAC									
640895	338-026-607-0	EASA;FAA;CAAC;ANAC									
640895	338-029-204-0	EASA;FAA;CAAC;ANAC									
640895	338-029-407-0	EASA;FAA;CAAC;ANAC									
640895	338-047-204-0	EASA;FAA;CAAC;ANAC									
640895	338-047-402-0	EASA;FAA;CAAC;ANAC									
640895	338-048-002-0	EASA;FAA;CAAC;ANAC									
640895	338-048-204-0	EASA;FAA;CAAC;ANAC									
640895	338-048-403-0	EASA;FAA;CAAC;ANAC									
640895	338-048-604-0	EASA;FAA;CAAC;ANAC									
640895	338-048-802-0	EASA;FAA;CAAC;ANAC									
640895	338-052-202-0	EASA;FAA;CAAC;ANAC									
640895	338-052-203-0	EASA;FAA;CAAC;ANAC									
640895	338-052-802-0	EASA;FAA;CAAC;ANAC									
640895	338-052-803-0	EASA;FAA;CAAC;ANAC									
640895	338-053-002-0	EASA;FAA;CAAC;ANAC									
640895	338-056-502-0	EASA;FAA;CAAC;ANAC									
640895	338-057-601-0	EASA;FAA;ANAC									
640895	338-057-651-0	EASA;FAA;CAAC;ANAC									
640895	338-057-701-0	EASA;FAA;CAAC;ANAC									
640895	338-057-751-0	EASA;FAA;CAAC;ANAC									
640895	338-057-753-0	EASA;FAA;CAAC;ANAC									
640895	338-059-951-0	EASA;FAA;CAAC;ANAC									
640895	338-125-003-0	EASA;FAA;CAAC;ANAC									
640895	338-126-004-0	EASA;FAA;CAAC;ANAC									
640895	338-126-103-0	EASA;FAA;CAAC;ANAC									
640895	338-126-153-0	EASA;FAA;CAAC;ANAC									
640895	338-129-101-0	EASA;FAA;CAAC;ANAC									
640895	338-129-251-0	EASA;FAA;CAAC;ANAC									
640895	338-130-801-0	EASA;FAA;CAAC;ANAC;CAA UK									
640895	340-005-104-0	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	340-005-105-0	EASA;FAA;CAAC;ANAC									
640895	340-006-103-0	EASA;FAA;CAAC;ANAC									
640895	340-007-005-0	EASA;FAA;CAAC;ANAC									
640895	340-007-102-0	EASA;FAA;CAAC;ANAC									
640895	340-007-203-0	EASA;FAA;CAAC;ANAC									
640895	340-008-504-0	EASA;FAA;CAAC;ANAC									
640895	340-009-303-0	EASA;FAA;CAAC;ANAC									
640895	340-010-401-0	EASA;FAA;CAAC;ANAC									
640895	340-010-402-0	EASA;FAA;CAAC;ANAC									
640895	340-010-603-0	EASA;FAA;CAAC;ANAC									
640895	340-011-001-0	EASA;FAA;CAAC;ANAC									
640895	340-011-202-0	EASA;FAA;CAAC;ANAC									
640895	340-011-601-0	EASA;FAA;CAAC;ANAC									
640895	340-011-804-0	EASA;FAA;CAAC;ANAC									
640895	340-012-402-0	EASA;FAA;CAAC;ANAC									
640895	340-014-203-0	EASA;FAA;CAAC;ANAC									
640895	340-014-406-0	EASA;FAA;CAAC;ANAC									
640895	340-014-602-0	EASA;FAA;CAAC;ANAC									
640895	340-015-103-0	EASA;FAA;CAAC;ANAC									
640895	340-016-101-0	EASA;FAA;CAAC;ANAC									
640895	340-016-151-0	EASA;FAA;CAAC;ANAC									
640895	340-016-201-0	EASA;FAA;CAAC;ANAC									
640895	340-016-251-0	EASA;FAA;CAAC;ANAC									
640895	340-016-452-0	EASA;FAA;CAAC;ANAC									
640895	340-016-602-0	EASA;FAA;CAAC;ANAC									
640895	340-016-652-0	EASA;FAA;CAAC;ANAC									
640895	340-016-701-0	EASA;FAA;CAAC;ANAC									
640895	340-016-751-0	EASA;FAA;CAAC;ANAC									
640895	340-018-103-0	EASA;FAA;CAAC;ANAC									
640895	340-021-002-0	EASA;FAA;CAAC;ANAC									
640895	340-021-003-0	EASA;FAA;CAAC;ANAC									
640895	340-021-802-0	EASA;FAA;CAAC;ANAC									
640895	340-021-803-0	EASA;FAA;CAAC;ANAC									
640895	340-021-852-0	EASA;FAA;CAAC;ANAC									
640895	340-021-853-0	EASA;FAA;CAAC;ANAC									
640895	340-022-003-0	EASA;FAA;CAAC;ANAC									
640895	340-022-201-0	EASA;FAA;CAAC;ANAC									
640895	340-023-507-0	EASA;FAA;CAAC;ANAC									
640895	340-088-803-0	EASA;FAA;CAAC;ANAC									
640895	340-138-201-0	EASA									
640895	340-138-401-0	EASA;FAA;CAAC;ANAC									
640895	340-138-901-0	EASA;FAA;CAAC;ANAC									
640895	340-138-951-0	EASA;FAA;CAAC;ANAC									
640895	340-8801-515	EASA;FAA;CAAC;ANAC									
640895	649-430-004-0	EASA;FAA;CAAC;ANAC									
640895	649-430-006-0	EASA;FAA;ANAC									
640895	649-430-036-0	EASA;FAA;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	649-430-069-0	EASA;FAA;CAAC;ANAC										
640895	649-430-201-0	EASA;FAA;CAAC;ANAC										
640895	649-430-203-0	EASA;FAA;CAAC;ANAC										
640895	649-430-219-0	EASA;FAA;CAAC;ANAC										
640895	649-430-233-0	EASA;FAA;CAAC;ANAC										
640895	649-433-030-0	EASA;FAA;CAAC;ANAC										
640895	649-433-034-0	EASA;FAA;CAAC;ANAC										
640895	649-433-036-0	EASA;FAA;CAAC;ANAC										
640895	649-433-047-0	EASA;FAA;CAAC;ANAC;CAA UK										
640895	649-433-051-0	EASA;FAA;CAAC;ANAC										
640895	649-433-086-0	EASA;FAA;CAAC;ANAC										
640895	649-433-087-0	EASA;FAA;CAAC;ANAC										
640895	649-433-093-0	EASA;FAA;CAAC;ANAC										
640895	649-433-094-0	EASA;FAA;CAAC;ANAC										
640895	649-433-095-0	EASA;FAA;CAAC;ANAC										
640895	649-433-147-0	EASA;FAA;CAAC;ANAC										
640895	649-433-219-0	EASA;FAA;CAAC;ANAC;CAA UK										
640895	649-433-220-0	EASA;FAA;ANAC										
640895	649-433-231-0	EASA;FAA;CAAC;ANAC;CAA UK										
640895	649-433-233-0	EASA;FAA;CAAC;ANAC										
640895	649-433-254-0	EASA;FAA;CAAC;ANAC										
640895	649-434-034-0	EASA;FAA;CAAC;ANAC										
640895	649-434-036-0	EASA;FAA;CAAC;ANAC										
640895	649-434-087-0	EASA;FAA;CAAC;ANAC										
640895	649-434-091-0	EASA;FAA;CAAC;ANAC										
640895	649-434-094-0	EASA;FAA;CAAC;ANAC										
640895	649-434-147-0	EASA;FAA;CAAC;ANAC										
640895	649-434-219-0	EASA;FAA;CAAC;ANAC										
640895	649-434-233-0	EASA;FAA;CAAC;ANAC										
640895	649-434-251-0	EASA;FAA;CAAC;ANAC										
640895	649-434-253-0	EASA;FAA;CAAC;ANAC										
640895	649-438-000-0	EASA;FAA;CAAC;ANAC										
640895	649-438-002-0	EASA;FAA;CAAC;ANAC										
640895	649-438-004-0	EASA;FAA;CAAC;ANAC										
640895	649-438-005-0	EASA;FAA;CAAC;ANAC										
640895	649-438-011-0	EASA;FAA;CAAC;ANAC										
640895	649-438-012-0	EASA;FAA;CAAC;ANAC										
640895	649-438-101-0	EASA;FAA;CAAC;ANAC										
640895	649-438-102-0	EASA;FAA;CAAC;ANAC										
640895	649-438-200-0	EASA;FAA;CAAC;ANAC										
640895	649-438-201-0	EASA;FAA;CAAC;ANAC										
640895	649-439-000-0	EASA;FAA;CAAC;ANAC										
640895	649-439-005-0	EASA;FAA;CAAC;ANAC										
640895	649-439-012-0	EASA;FAA;CAAC;ANAC										
640895	649-439-102-0	EASA;FAA;CAAC;ANAC										
640895	649-439-200-0	EASA;FAA;CAAC;ANAC										
640895	9393M42G03	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	9393M46G08	EASA;FAA;CAAC;ANAC										
640896	1605M10G02	EASA;FAA;CAAC;ANAC	36	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	355	SR Technics Switzerland
640896	1605M63G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		2,360	SR Technics Switzerland
640896	1645M11G01	EASA;FAA;CAAC;ANAC										
640896	1645M31G03	EASA;FAA;CAAC;ANAC										
640896	1677M12G02	EASA;FAA;CAAC;ANAC										
640896	1677M20G01	EASA;FAA;CAAC;ANAC										
640896	1677M89G01	EASA;FAA;CAAC;ANAC										
640896	1677M91G01	EASA;FAA;CAAC;ANAC										
640896	1788M40G01	EASA;FAA;CAAC;ANAC										
640896	1813M24G01	EASA;FAA;CAAC;ANAC										
640896	1813M96G01	EASA;FAA;CAAC;ANAC										
640896	1817M52G01	EASA;FAA;CAAC;ANAC										
640896	1817M66G01	EASA;FAA;CAAC;ANAC										
640896	1867M39G01	EASA;FAA;CAAC;ANAC										
640896	1867M67G01	EASA;FAA;CAAC;ANAC										
640896	1870M24G01	EASA;FAA;CAAC;ANAC										
640896	1870M28G01	EASA;FAA;CAAC;ANAC										
640896	1870M45G01	EASA;FAA;CAAC;ANAC										
640896	1870M46G01	EASA;FAA;CAAC;ANAC										
640896	1870M57G01	EASA;FAA;CAAC;ANAC										
640896	1870M70G01	EASA;FAA;CAAC;ANAC										
640896	1870M71G01	EASA;FAA;CAAC;ANAC										
640896	1870M72G01	EASA;FAA;CAAC;ANAC										
640896	1870M73G01	EASA;FAA;CAAC;ANAC										
640896	1870M75G01	EASA;FAA;CAAC;ANAC										
640896	1882M68G01	EASA;FAA;CAAC;ANAC										
640896	1882M70G01	EASA;FAA;CAAC;ANAC										
640896	1882M72G01	EASA;FAA;CAAC;ANAC										
640896	1882M74G01	EASA;FAA;CAAC;ANAC										
640896	1892M16G01	EASA;FAA;CAAC;ANAC										
640896	1892M18G01	EASA;FAA;CAAC;ANAC										
640896	1892M47G01	EASA;FAA;CAAC;ANAC										
640896	1892M89G01	EASA;FAA;CAAC;ANAC										
640896	1895M58G01	EASA;FAA;CAAC;ANAC										
640896	1897M24G01	EASA;FAA;CAAC;ANAC										
640896	1897M68G01	EASA;FAA;CAAC;ANAC										
640896	1897M72G01	EASA;FAA;CAAC;ANAC										
640896	1897M74G01	EASA;FAA;CAAC;ANAC										
640896	1897M76G01	EASA;FAA;CAAC;ANAC										
640896	1898M13G01	EASA;FAA;CAAC;ANAC										
640896	1958M57G01	EASA;FAA;CAAC;ANAC										
640896	1971M75G01	EASA;FAA;CAAC;ANAC										
640896	2046M11G01	EASA;FAA;CAAC										
640896	2046M12G01	EASA;FAA;CAAC;ANAC										
640896	2046M16G01	EASA;FAA;CAAC;ANAC										
640896	2046M30G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640896	2046M59G01	EASA;FAA;CAAC;ANAC									
640896	2046M71G01	EASA;FAA;CAAC;ANAC									
640896	2046M77G01	EASA;FAA;CAAC;ANAC									
640896	2175M40G01	EASA;FAA;CAAC									
640896	2283M24G01	EASA;FAA;CAAC;ANAC									
640896	2283M70G01	EASA;FAA;CAAC;ANAC									
640896	2283M73G01	EASA;FAA;CAAC;ANAC									
640896	2409M00G01	EASA;CAAC									
640896	2557M32G01	EASA;FAA;CAAC;ANAC									
640896	336-401-402-0	EASA;FAA;CAAC;ANAC									
640896	336-401-403-0	EASA;FAA;CAAC;ANAC									
640896	336-493-204-0	EASA;FAA;CAAC;ANAC									
640896	337-153-702-0	EASA;CAAC;EASA/ANAC BRAZIL D									
640896	337-164-001-0	EASA;FAA;CAAC;ANAC									
640896	338-012-104-0	EASA;FAA;CAAC;ANAC									
640896	338-012-206-0	EASA;FAA;CAAC;ANAC									
640896	338-015-604-0	EASA;FAA;CAAC;ANAC									
640896	338-015-803-0	EASA;FAA;CAAC;ANAC									
640896	338-019-505-0	EASA;FAA;CAAC;JCAB;ANAC									
640896	338-019-703-0	EASA;FAA;CAAC;ANAC									
640896	338-024-004-0	EASA;CAAC;EASA/ANAC BRAZIL D									
640896	338-037-202-0	EASA;FAA;CAAC;ANAC									
640896	338-039-603-0	EASA;FAA;CAAC;ANAC									
640896	338-047-002-0	EASA;FAA;CAAC;ANAC									
640896	338-057-754-0	EASA;CAAC									
640896	338-128-501-0	EASA;FAA;CAAC;ANAC									
640896	340-006-004-0	EASA;FAA;CAAC;ANAC									
640896	340-006-005-0	EASA;FAA;CAAC;ANAC									
640896	340-006-104-0	EASA;FAA;CAAC;ANAC									
640896	340-009-202-0	EASA;FAA;CAAC;ANAC									
640896	340-009-401-0	EASA;FAA;CAAC;ANAC									
640896	340-012-802-0	EASA;FAA;CAAC;ANAC									
640896	340-014-007-0	EASA;FAA;CAAC;ANAC;CAA UK									
640896	340-015-801-0	EASA;FAA;CAAC;ANAC									
640896	340-015-852-0	EASA;FAA;CAAC;ANAC									
640896	340-015-906-0	EASA;FAA;CAAC;ANAC									
640896	340-015-956-0	EASA;FAA;CAAC;ANAC									
640896	340-016-002-0	EASA;FAA;CAAC;ANAC									
640896	340-016-003-0	EASA;FAA;CAAC;ANAC									
640896	340-016-052-0	EASA;FAA;CAAC;ANAC									
640896	340-016-053-0	EASA;FAA;CAAC;ANAC									
640896	340-016-802-0	EASA;FAA;CAAC;ANAC									
640896	340-016-852-0	EASA;FAA;CAAC;ANAC									
640896	340-020-501-0	EASA;FAA;CAAC;ANAC									
640896	340-020-502-0	EASA;FAA;CAAC;ANAC									
640896	340-130-401-0	EASA;FAA;CAAC;ANAC									
640896	340-130-501-0	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640896	642-9848-501	EASA;FAA;CAAC;ANAC										
640896	649-430-071-0	EASA;FAA;ANAC										
640896	649-433-091-0	EASA;FAA;CAAC;ANAC;CAA UK										
640896	649-433-146-0	EASA;FAA;CAAC;ANAC										
640896	649-433-242-0	EASA;FAA;CAAC;ANAC										
640896	649-439-011-0	EASA;FAA;CAAC;ANAC										
640897	1645M25G03	EASA;FAA;CAAC;ANAC	34	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	345	SR Technics Switzerland
640897	1677M55G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		5,355	SR Technics Switzerland
640897	1716M87G01	EASA;FAA;CAAC;ANAC			72-09-03		Package U		RE-ETCH PART NUMBER		155	SR Technics Switzerland
640897	1788M85G03	EASA;FAA;CAAC;ANAC										
640897	1813M52G01	EASA;FAA;CAAC;ANAC										
640897	1813M60G01	EASA;FAA;CAAC;ANAC										
640897	1817M67G01	EASA;FAA;CAAC;ANAC										
640897	1867M43G01	EASA;FAA;CAAC;ANAC										
640897	1867M71G01	EASA;FAA;CAAC;ANAC										
640897	1869M45G01	EASA;FAA;CAAC;ANAC										
640897	1870M27G01	EASA;FAA;CAAC;ANAC										
640897	1870M44G01	EASA;FAA;CAAC;ANAC										
640897	1870M86G01	EASA;FAA;CAAC;ANAC										
640897	1870M90G01	EASA;FAA;CAAC;ANAC										
640897	1870M98G01	EASA;FAA;CAAC;ANAC										
640897	1871M46G01	EASA;FAA;CAAC;ANAC										
640897	1882M76G01	EASA;FAA;CAAC;ANAC										
640897	1882M94G01	EASA;FAA;CAAC										
640897	1888M49G01	EASA;FAA;CAAC;ANAC										
640897	1888M52G01	EASA;FAA;CAAC;ANAC										
640897	1895M60G01	EASA;FAA;CAAC;ANAC										
640897	1895M65G01	EASA;FAA;ANAC										
640897	1896M69G01	EASA;FAA;CAAC;ANAC										
640897	1897M39G01	EASA;FAA;CAAC;ANAC										
640897	1897M51G01	EASA;FAA;CAAC;ANAC										
640897	1897M69G01	EASA;FAA;CAAC;ANAC										
640897	1898M20G01	EASA;FAA;CAAC;ANAC										
640897	1898M35G01	EASA;FAA;CAAC;ANAC										
640897	1898M38G01	EASA;FAA;CAAC;ANAC										
640897	1958M70G01	EASA;FAA;CAAC;ANAC										
640897	1970M36G01	EASA;FAA;CAAC;ANAC										
640897	1971M90G01	EASA;FAA;CAAC;ANAC										
640897	2046M55G01	EASA;FAA;CAAC;ANAC										
640897	2046M79G01	EASA;FAA;CAAC;ANAC										
640897	2174M16G01	EASA;FAA;CAAC;ANAC										
640897	2174M17G01	EASA;FAA;CAAC;ANAC										
640897	2174M18G01	EASA;FAA;ANAC										
640897	2174M19G01	EASA;FAA;CAAC;ANAC										
640897	2175M39G01	EASA;FAA;CAAC;ANAC										
640897	2175M41G01	EASA;FAA;CAAC;ANAC										
640897	2175M42G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640897	2175M45G01	EASA;FAA;ANAC										
640897	2175M48G01	EASA;FAA;CAAC;ANAC										
640897	2480M87G01	EASA;FAA;CAAC;ANAC										
640897	2497M63G01	EASA;FAA;CAAC;ANAC										
640897	2497M70G01	EASA;FAA;CAAC;ANAC										
640897	336-462-002-0	EASA;FAA;CAAC;ANAC;CAA UK										
640897	336-462-003-0	EASA;FAA;CAAC;ANAC										
640897	336-462-051-0	EASA;FAA;CAAC;ANAC										
640897	336-462-052-0	EASA;FAA;CAAC;ANAC										
640897	336-462-071-0	EASA;FAA;CAAC;ANAC										
640897	338-025-003-0	EASA;FAA;CAAC;ANAC										
640897	338-166-604-0	EASA;FAA;CAAC;ANAC										
640897	338-166-804-0	EASA;FAA;CAAC;ANAC										
640897	338-166-904-0	EASA;FAA;CAAC;ANAC										
640897	338-169-302-0	EASA;FAA;CAAC;ANAC										
640897	340-015-302-0	EASA;FAA;CAAC;ANAC										
640897	340-105-302-0	EASA;FAA;CAAC;ANAC										
640897	340-105-352-0	EASA;FAA;CAAC;ANAC										
640897	649-431-650-0	EASA;FAA;CAAC;ANAC										
640897	649-433-251-0	EASA;FAA;CAAC;ANAC										
640897	649-433-252-0	EASA;FAA;CAAC;ANAC;CAA UK										
640897	649-433-330-0	EASA;FAA;CAAC;ANAC;CAA UK										
640897	649-434-330-0	EASA;FAA;CAAC;ANAC										
640897	649-438-302-0	EASA;FAA;CAAC;ANAC										
640950	305-364-002-0	EASA;FAA;CAAC;ANAC	18	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARI Package A	CLN/INSP		CLEANING AND INSPECTION		1,110	SR Technics Switzerland
640950	305-364-103-0	EASA;FAA;CAAC;ANAC;CAA UK										
640950	337-108-201-0	EASA;FAA;CAAC;ANAC										
640950	340-257-001-0	EASA;FAA;CAAC;ANAC										
640951	305-365-702-0	EASA;FAA;CAAC;ANAC	17	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARI Package A	CLN/INSP		CLEANING AND INSPECTION		1,110	SR Technics Switzerland
640951	305-365-704-0	EASA;FAA;CAAC;ANAC										
640951	305-366-203-0	EASA;FAA;CAAC;ANAC										
640951	305-366-204-0	EASA;FAA;CAAC;ANAC										
640951	337-010-702-0	EASA;FAA;CAAC;ANAC										
640951	337-010-703-0	EASA;FAA;CAAC;ANAC										
640951	337-010-761-0	EASA;FAA;CAAC;ANAC										
640951	337-108-301-0	EASA;FAA;CAAC;ANAC										
640951	337-108-302-0	EASA;FAA;CAAC;ANAC										
640951	337-108-351-0	EASA;FAA;CAAC;ANAC										
640951	337-205-401-0	EASA;FAA;CAAC;ANAC										
640951	337-205-501-0	EASA;FAA;CAAC;ANAC;CAA UK										
640951	337-205-601-0	EASA;FAA;CAAC;ANAC										
640951	340-257-101-0	EASA;FAA;CAAC;ANAC										
640952	1361M71P02	EASA;FAA;CAAC;ANAC	19	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARI Package A	CLN/INSP		CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	1,115	SR Technics Switzerland
640952	1361M71P05	EASA;FAA;CAAC;ANAC			72-09-01		Package SB00	72-0590	REDUCED INSPECTION INTERVAL FOR THE ELECTRICAL MASTER CHIP DETECTOR		1,555	SR Technics Switzerland
640952	1364M91P01	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	EASA-2020-004	SB 72-0952-001		545	SR Technics Switzerland
640952	1364M91P02	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	FAA 2021-10-0	SB 72-0952-001		545	SR Technics Switzerland
640952	1364M91P05	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640952	1460M51P05	EASA;FAA;CAAC;ANAC										
640952	1460M52P01	EASA;FAA;CAAC;ANAC										
640952	1460M52P03	EASA;FAA;CAAC;ANAC										
640952	1460M52P05	EASA;FAA;CAAC;ANAC										
640952	1665M98P02	EASA;FAA;CAAC;ANAC										
640952	2124M95P01	EASA;FAA;CAAC;ANAC										
640952	2124M95P02	EASA;FAA;CAAC;ANAC										
640952	2411M39P01	EASA;FAA;CAAC;ANAC										
640952	2411M39P02	EASA;FAA;ANAC										
640952	9542M61P03	EASA;FAA;CAAC;ANAC										
640953	305-351-905-0	EASA;FAA;CAAC;ANAC	18	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARI	Package A	CLN/INSP	CLEANING AND INSPECTION		1,360	SR Technics Switzerland
640953	305-352-004-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	72-0937	MARKING MANAGEMENT OF ROLLER BEARING#5		165	SR Technics Switzerland
640953	337-108-401-0	EASA;FAA;CAAC;ANAC										
640953	337-220-301-0	EASA;FAA;CAAC;ANAC										
640953	337-220-351-0	EASA;FAA;CAAC;ANAC										
640953	340-252-801-0	EASA;FAA;CAAC;ANAC										
640953	340-252-802-0	EASA;FAA;CAAC;ANAC										
640953	340-252-901-0	EASA;FAA;CAAC;ANAC										
640953	340-252-902-0	EASA;FAA;CAAC;ANAC										
640953	340-253-001-0	EASA;FAA;CAAC;ANAC										
640953	340-253-002-0	EASA;FAA;CAAC;ANAC										
640953	340-257-201-0	EASA;FAA;CAAC;ANAC										
640954	305-355-717-0	EASA;FAA;CAAC;ANAC	20	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARI	Package A	CLN/INSP	CLEANING AND INSPECTION		1,255	SR Technics Switzerland
640954	305-355-718-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB03	72-A0393	REPLACEMENT OF NO.4 ROLLER BEARING		295	SR Technics Switzerland
640954	305-355-720-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB10	72-0452	NO.4 ROLLER BRG NEW OUTER RACE MATERIAL		295	SR Technics Switzerland
640954	335-352-301-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB12	72-0425	NEW MATERIAL FOR ROLLER BRG NO.4		295	SR Technics Switzerland
640954	335-352-302-0	EASA;FAA;CAAC;ANAC										
640954	335-352-303-0	EASA;FAA;CAAC;ANAC										
640954	335-352-304-0	EASA;FAA;CAAC;ANAC										
640954	335-352-305-0	EASA;FAA;CAAC;ANAC										
640954	340-167-901-0	EASA;FAA;CAAC;ANAC										
640954	340-167-902-0	EASA;FAA;CAAC;ANAC										
640954	340-167-904-0	EASA;FAA;CAAC;ANAC										
640954	340-167-906-0	EASA;FAA;CAAC;ANAC										
641535	1523M41G02	EASA;FAA;CAAC;ANAC	28	28	72-51-07	HIGH PRESSURE TURBINE NOZZLE - FWD INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		2,650	SR Technics Switzerland
641535	1668M61G01	EASA;FAA;CAAC;ANAC			72-51-07		Package C	5	HONEYCOMB REPAIR		10,570	SR Technics Switzerland
641535	1668M61G03	EASA;FAA;CAAC;ANAC			72-51-07		Package E	4	REPAIR THE DIMENSIONS OF THE AFT FLANGE AND INDUCER DIAMETER SEAL SL		3,225	SR Technics Switzerland
641535	1668M61G05	EASA;FAA;CAAC;ANAC			72-51-07		Package H	7	REPAIR OF THE HPT NOZZLE FRONT INNER SUPPORT		2,520	SR Technics Switzerland
641535	1808M15G01	EASA;FAA;CAAC;ANAC			72-51-07		Package M	12	CHROME CARBIDE EROSION COATING REPAIR		2,820	SR Technics Switzerland
641535	1808M15G03	EASA;FAA;CAAC;ANAC			72-51-07		Package R	17	REPAIR OF CRACKS ON THE CAST INDUCER AFT SURFACE		3,225	SR Technics Switzerland
641535	1808M15G04	EASA;FAA;CAAC;ANAC			72-51-07		Package SB01	72-0592	WITH IMPROVED EROSION COATING		2,705	SR Technics Switzerland
641535	1808M15G05	EASA;FAA;CAAC;ANAC			72-51-07		Package SB03	72-0886	FORWARD INNER NOZZLE SUPPORT REWORK	2131M81G05, 2131M81G06	10,645	SR Technics Switzerland
641535	1808M15G06	EASA;FAA;CAAC;ANAC										
641535	1808M15G08	EASA;FAA;CAAC;ANAC										
641535	1808M15G12	EASA;FAA;CAAC;ANAC										
641535	1808M15G13	EASA;FAA;CAAC;ANAC;CAA UK										
641535	1808M15G16	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
641535	1873M94G05	EASA;FAA;CAAC;ANAC										
641535	1893M96G02	EASA;FAA;ANAC										
641535	2071M27G02	EASA;FAA;CAAC;ANAC										
641535	2071M28G01	EASA;FAA;CAAC;ANAC										
641535	2071M28G02	EASA;FAA;CAAC;ANAC										
641535	2071M28G04	EASA;FAA;CAAC;ANAC										
641535	2071M28G05	EASA;FAA;CAAC;ANAC										
641535	2071M28G07	EASA;FAA;CAAC;ANAC										
641535	2071M28G10	EASA;FAA;CAAC;ANAC										
641535	2131M81G05	EASA;FAA;CAAC;ANAC										
641535	2131M81G06	EASA;FAA;CAAC;ANAC;CAA UK										
641535	2131M82G01	EASA;FAA;CAAC;ANAC										
642820	1498M52G03	EASA;FAA;CAAC;ANAC	33	28	72-41-01	COMBUSTION CASE - ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISIT ONLY	4,895	SR Technics Switzerland
642820	1498M52G05	EASA;FAA;CAAC;ANAC			72-41-01		Package AA	026	INNER WALL BLEND REPAIR		4,400	SR Technics Switzerland
642820	1498M52G06	EASA;FAA;CAAC;ANAC			72-41-01		Package AB	027	REPAIR OF DAMAGED JACKSCREW HOLES		1,125	SR Technics Switzerland
642820	1498M52G08	EASA;FAA;CAAC;ANAC			72-41-01		Package B	INSP-001	BLENDING REPAIR		2,940	SR Technics Switzerland
642820	1498M52G10	EASA;FAA;CAAC;ANAC			72-41-01		Package C	002	OUTLET GUIDE VANES BLENDING REPAIR	BLENDING OF L/E OR T/E	4,745	SR Technics Switzerland
642820	1498M52G11	EASA;FAA;CAAC;ANAC			72-41-01		Package D	INSP-001	REMOVAL OF BROKEN BOLT(S)		1,835	SR Technics Switzerland
642820	1498M52G12	EASA;FAA;CAAC;ANAC			72-41-01		Package D	INSP-001	REPLACEMENT OF CRIMPED NUTS		1,835	SR Technics Switzerland
642820	1668M39G02	EASA;FAA;CAAC;ANAC			72-41-01		Package E	006	DIMENSIONAL RESTORATION OF COMBUSTION CASE FLANGES AND DIAMETERS		6,310	SR Technics Switzerland
642820	1668M39G03	EASA;FAA;CAAC;ANAC			72-41-01		Package F	001	COMBUSTION CASE.REPAIR OF THREADED HOLES		3,385	SR Technics Switzerland
642820	1668M39G04	EASA;FAA;CAAC;ANAC			72-41-01		Package I	008	REPAIR OF FRETTING ON THE HIGH PRESSURE TURBINE COOLING DUCT PAD		9,800	SR Technics Switzerland
642820	1668M39G05	EASA;FAA;CAAC;ANAC			72-41-01		Package P	015	REPAIR OF THE AFT CASE INNER DIAMETER		8,405	SR Technics Switzerland
642820	1784M18G01	EASA;FAA;CAAC;ANAC			72-41-01		Package Q	016	DIAMETER M AND DIAMETER S REPAIR WITH T800 COATING		8,405	SR Technics Switzerland
642820	1784M18G02	EASA;FAA;CAAC;ANAC			72-41-01		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CFM56-5B2 AND CFM56-5B6/2 TO CFM56-5B6/2P,CFM		655	SR Technics Switzerland
642820	1784M82G04	EASA;FAA;CAAC;ANAC			72-41-01		Package SB02	72-0145	INTRODUCTION OF NEW COMBUSTION CASE CONFIGURATION		1,865	SR Technics Switzerland
642820	1784M82G07	EASA;FAA;CAAC;ANAC			72-41-01		Package SB04	IA 219077	INSPECTION OF THE COMBUSTION CHAMBER		340	SR Technics Switzerland
642820	1784M82G08	EASA;FAA;CAAC;ANAC			72-41-01		Package X	023	THERMAL SPRAY REPAIR FOR THE INNER BAND WALL OF THE OUTLET GUIDE VA		7,580	SR Technics Switzerland
642820	1784M82G09	EASA;FAA;CAAC;ANAC										
642820	1784M91G01	EASA;FAA;CAAC;ANAC										
642820	1784M91G02	EASA;FAA;CAAC;ANAC										
642820	1784M91G03	EASA;FAA;CAAC;ANAC										
642820	1784M91G04	EASA;FAA;CAAC;ANAC										
642820	1784M91G05	EASA;FAA;CAAC;ANAC										
642820	1784M91G06	EASA;FAA;CAAC;ANAC										
642820	1784M91G07	EASA;FAA;CAAC;ANAC										
642820	1784M91G08	EASA;FAA;CAAC;ANAC										
642820	1784M91G11	EASA;FAA;CAAC;ANAC										
642820	1784M91G12	EASA;FAA;CAAC;ANAC										
642820	1784M91G13	EASA;FAA;CAAC;ANAC										
642820	1784M91G16	EASA;FAA;CAAC;ANAC										
642820	1784M91G17	EASA;FAA;CAAC;ANAC										
642820	2002M81G01	EASA;FAA;CAAC;ANAC										
642820	2002M81G02	EASA;FAA;CAAC;ANAC										
642820	2002M81G03	EASA;FAA;CAAC;ANAC										
642820	2002M81G04	EASA;FAA;CAAC;ANAC										
642820	2002M81G05	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
642820	2002M81G06	EASA;FAA;CAAC;ANAC									
642820	2002M81G07	EASA;FAA;CAAC;ANAC									
642820	2002M81G08	EASA;FAA;CAAC;ANAC									
642820	2002M81G09	EASA;FAA;CAAC;ANAC									
642820	2002M92G01	EASA;FAA;CAAC;ANAC									
642820	2002M92G02	EASA;FAA;CAAC;ANAC									
642820	2002M92G03	EASA;FAA;CAAC;ANAC									
642820	2002M92G05	EASA;FAA;CAAC;ANAC									
642820	2002M92G06	EASA;FAA;CAAC;ANAC									
642820	2002M92G07	EASA;FAA;CAAC;ANAC									
642820	2002M92G08	EASA;FAA;CAAC;ANAC									
648440	301-544-407-0	EASA;FAA;CAAC;ANAC	9	21 72-22-07	NO.1 AND NO.2 BEARING SUPPORT OIL TUBES	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	325	SR Technics Switzerland
648440	337-010-901-0	EASA;FAA;CAAC;ANAC		72-22-07		Package A	CLN/INSP	PRESSURE TEST		325	SR Technics Switzerland
648440	337-010-902-0	EASA;FAA;CAAC;ANAC		72-22-07		Package B	001	BLENDING		330	SR Technics Switzerland
648440	337-011-202-0	EASA;FAA;CAAC;ANAC									
648440	337-011-303-0	EASA;FAA;CAAC;ANAC									
648440	338-062-501-0	EASA;FAA;CAAC;ANAC									
648440	338-067-302-0	EASA;FAA;CAAC;ANAC									
648440	338-067-351-0	EASA;FAA;CAAC;ANAC									
648440	340-026-302-0	EASA;FAA;CAAC;ANAC									
648459	301-348-412-0	EASA;FAA;CAAC;ANAC	16	28 72-22-17	NO.1 AND NO.2 BEARING SUPPORT - PROBE SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	260	SR Technics Switzerland
648459	337-011-802-0	EASA;FAA;CAAC;ANAC									
648459	340-027-051-0	EASA;FAA;CAAC;ANAC									
648461	305-047-401-0	EASA;FAA;CAAC;ANAC	4	28 72-22-20	CFM56 NO.1 & NO.2 BEARING SUPPORT HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		155	SR Technics Switzerland
648461	AS3217-207	EASA;FAA;CAAC;ANAC									
648461	AS3217-253	EASA;FAA;CAAC;ANAC									
648461	AS3218-247	EASA;FAA;CAAC;ANAC									
648461	J204P0475	EASA;FAA;CAAC;ANAC									
648461	J204P0925	EASA;FAA;CAAC;ANAC									
648461	J205P1100	EASA;FAA;CAAC;ANAC									
648494	305-367-103-0	EASA;FAA;CAAC;ANAC	7	28 72-22-10	CFM56 OIL SEPARATOR DUCT	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	105	SR Technics Switzerland
648494	305-367-104-0	EASA;FAA;CAAC;ANAC									
648697	305-371-802-0	EASA;FAA;CAAC;ANAC	11	28 72-56-08	CFM56 FLAME ARRESTOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	415	SR Technics Switzerland
648697	305-371-803-0	EASA;FAA;CAAC;ANAC									
648698	336-049-702-0	EASA;FAA;CAAC;ANAC	7	21 72-56-05	CFM56 BEARING 5 DRAIN TUBE / OVERBOARD S	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	210	SR Technics Switzerland
648698	338-107-801-0	EASA;FAA;CAAC;ANAC									
648704	338-072-151-0_	EASA;FAA;CAAC;ANAC	15	28 72-55-20	LOW PRESSURE TURBINE SHAFT - PIN-SHOULDER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	125	SR Technics Switzerland
648706	336-022-402-0	EASA;FAA;CAAC;ANAC	6	21 72-53-10	CFM56 STAGE 1 LOW PRESSURE TURBINE NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		45	SR Technics Switzerland
648706	336-022-503-0	EASA;FAA;CAAC;ANAC									
648706	340-256-401-0	EASA;FAA;CAAC;ANAC									
648706	340-256-501-0	EASA;FAA;CAAC;ANAC									
648714	1359M84P06	EASA;FAA;CAAC;ANAC	14	28 72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SEAL RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		560	SR Technics Switzerland
648714	1359M84P08	EASA;FAA;CAAC;ANAC									
648724	2531M86P01	EASA;FAA;CAAC	10	28 72-31-10	CFM56 COMPRESSOR ROTOR BLADE LOCKS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	240	SR Technics Switzerland
648724	2531M86P03	EASA;FAA;CAAC									
648724	2531M87P01	EASA;FAA;CAAC									
648724	2949M01P02	EASA;FAA;CAAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648724	2949M03P01	EASA;FAA;CAAC										
648724	9984M27P01	EASA;FAA;CAAC										
648724	9984M27P02	EASA;FAA;CAAC										
648724	9984M27P03	EASA;FAA;CAAC										
648724	9984M27P04	EASA;FAA;CAAC										
648724	9984M27P07	EASA;FAA;CAAC										
648724	9984M27P08	EASA;FAA;CAAC										
648724	9984M28P01	EASA;FAA										
648724	9984M28P02	EASA;FAA;CAAC										
648724	9984M29P01	EASA;FAA;CAAC										
648724	9984M29P02	EASA;FAA;CAAC										
648724	9984M29P03	EASA;FAA;CAAC										
648731	1476M52P01	EASA;FAA;CAAC;ANAC	6	28	72-32-13	CFM56 BUSHING, COMPR. STATOR ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		65	SR Technics Switzerland
648731	1476M52P02	EASA;FAA;CAAC;ANAC										
648731	1476M52P04	EASA;FAA;CAAC;ANAC										
648731	9131M66P03	EASA;FAA;CAAC;ANAC										
648731	9131M68P02	EASA;FAA;CAAC;ANAC										
648731	9513M97P01	EASA;FAA;CAAC;ANAC										
648731	9513M98P01	EASA;FAA;CAAC;ANAC										
648731	9513M99P01	EASA;FAA;CAAC;ANAC										
648731	9944M24P01	EASA;FAA;CAAC;ANAC										
648731	9945M71P02	EASA;FAA;CAAC;ANAC										
648731	9945M74P06	EASA;FAA;CAAC;ANAC										
648731	9955M10P01	EASA;FAA;CAAC;ANAC										
650669	335-108-701-0	EASA;FAA;CAAC;ANAC	9	28	72-23-37	CFM56-5B SLIDES	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	325	SR Technics Switzerland
650669	335-108-801-0	EASA;FAA;CAAC;ANAC										
650669	335-108-901-0	EASA;FAA;CAAC;ANAC										
652060	2050M55P01	EASA;FAA;CAAC;ANAC	6	28	72-32-09	CFM56 COMPRESSOR STATOR VSV TRUNNION BUSHINGS	Package A	CLN/INSP	CLEANING & INSPECTION		40	SR Technics Switzerland
652060	2050M55P02	EASA;FAA;CAAC;ANAC										
652060	2102M23P04	EASA;FAA;CAAC;ANAC										
652060	2102M23P08	EASA;FAA;CAAC;ANAC										
652453	335-107-102-0	EASA;FAA;CAAC;ANAC	6	21	72-23-36	CFM56 SCOOP	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	310	SR Technics Switzerland
652453	335-108-101-0	EASA;FAA;CAAC;ANAC										
652453	335-108-102-0	EASA;FAA;CAAC;ANAC										
652453	336-095-501-0	EASA;FAA;CAAC;ANAC										
653347	336-472-901-0	EASA;FAA;CAAC;ANAC	15	28	72-23-17	FAN FRAME ASSEMBLY - OEL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		125	SR Technics Switzerland
653347	337-040-403-0	EASA;FAA;CAAC;ANAC										
653347	337-043-001-0	EASA;FAA;CAAC;ANAC										
653347	338-011-603-0	EASA;FAA;CAAC;ANAC										
653347	649-148-149-0	EASA;FAA;CAAC;ANAC										
653347	649-781-842-0	EASA;FAA;CAAC;ANAC										
654965	305-156-502-0	EASA;FAA;CAAC;ANAC	5	21	72-62-12	CFM56-5B TRANSFER GBX BRACKET ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		70	SR Technics Switzerland
654965	305-156-603-0	EASA;FAA;CAAC;ANAC										
655267	305-156-301-0	EASA;FAA;CAAC;ANAC	5	28	72-63-16	CFM56 ACCESSORY GEARBOX BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		85	SR Technics Switzerland
655267	305-156-502-0	EASA;FAA;CAAC;ANAC			72-63-16		Package B		REPLACE RIVETED PARTS		60	SR Technics Switzerland
655267	305-156-901-0	EASA;FAA;CAAC;ANAC										
655267	336-479-401-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
655267	336-527-202-0	EASA;FAA;CAAC;ANAC										
655267	336-527-302-0	EASA;FAA;CAAC;ANAC										
655267	337-049-202-0	EASA;FAA;CAAC;ANAC										
655267	337-050-601-0	EASA;FAA;CAAC;ANAC										
655267	338-036-202-0	EASA;FAA;CAAC;ANAC										
655267	338-045-801-0	EASA;FAA;CAAC;ANAC										
655267	338-050-202-0	EASA;FAA;CAAC;ANAC										
655267	338-053-602-0	EASA;FAA;CAAC;ANAC										
655267	338-103-601-0	EASA;FAA;CAAC;ANAC										
655267	338-103-701-0	EASA;FAA;CAAC;ANAC										
655267	338-106-701-0	EASA;FAA;CAAC;ANAC										
655267	340-089-105-0	EASA;FAA;CAAC;ANAC										
655267	340-089-106-0	EASA;FAA;CAAC;ANAC										
655267	340-091-105-0	EASA;FAA;CAAC;ANAC										
655267	340-091-106-0	EASA;FAA;CAAC;ANAC										
655267	340-104-802-0	EASA;FAA;CAAC;ANAC										
655267	340-119-401-0	EASA;FAA;CAAC;ANAC										
655267	340-126-403-0	EASA;FAA;CAAC;ANAC										
656317	9513M60P02	EASA;FAA;CAAC;ANAC	13	28	72-52-09	CFM56 COUNTER WEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		175	SR Technics Switzerland
656317	9513M61P03	EASA;FAA;CAAC;ANAC										
656317	9513M61P04	EASA;FAA;CAAC;ANAC										
656317	9513M62P04	EASA;FAA;CAAC;ANAC										
656317	9513M62P05	EASA;FAA;CAAC;ANAC										
656317	9513M62P06	EASA;FAA;CAAC;ANAC										
656317	9524M49P04	EASA;FAA;CAAC;ANAC										
656317	9524M49P05	EASA;FAA;CAAC;ANAC										
656317	9524M49P06	EASA;FAA;CAAC;ANAC										
656317	9524M50P06	EASA;FAA;CAAC;ANAC										
656317	9524M50P07	EASA;FAA;CAAC;ANAC										
656317	9524M50P08	EASA;FAA;CAAC;ANAC										
656317	9524M50P09	EASA;FAA;CAAC;ANAC										
656383	305-147-501-0	EASA;FAA;CAAC;ANAC	5	21	72-62-1	TRANSFER GEARBOX OIL NOZZLE PLUGS	Package A	CLN/INSP	CLEANING & INSPECTION		70	SR Technics Switzerland
656384	301-301-600-0	EASA;FAA;CAAC;ANAC	6	28	72-62-20	TRANSFER GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		405	SR Technics Switzerland
656384	305-120-700-0	EASA;FAA;CAAC;ANAC										
656384	305-158-401-6	EASA;FAA;CAAC;ANAC										
656384	305-158-412-0	EASA;FAA;CAAC;ANAC										
656384	305-158-506-0	EASA;FAA;CAAC;ANAC										
656384	335-319-501-0	EASA;FAA;CAAC;ANAC										
656384	335-321-801-6	EASA;FAA;CAAC;ANAC										
656384	649-363-131-0	EASA;FAA;CAAC;ANAC										
657873	1605M68P001A	EASA;FAA;CAAC;ANAC	16	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	65	SR Technics Switzerland
657873	1867M59G01	EASA;FAA;CAAC;ANAC										
657873	1867M73G01	EASA;FAA;CAAC;ANAC										
657873	1867M78G01	EASA;FAA;CAAC;ANAC										
657873	1868M20P001A	EASA;FAA;CAAC;ANAC										
657873	1870M31P001A	EASA;FAA;CAAC;ANAC										
657873	1894M47P001A	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657873	1894M63P001A	EASA;FAA;CAAC;ANAC										
657873	1958M27G01	EASA;FAA;CAAC;ANAC										
657873	1958M30G01	EASA;FAA;CAAC;ANAC										
657873	1969M92G01	EASA;FAA;CAAC;ANAC										
657873	1970M94G01	EASA;FAA;CAAC;ANAC										
657873	2174M42P01	EASA;FAA;CAAC;ANAC										
657873	238-0910-19	EASA;FAA;CAAC;ANAC										
657873	238-0910-37	EASA;FAA;CAAC;ANAC										
657873	238-0910-5	EASA;FAA;CAAC;ANAC										
657873	238-0950-15	EASA;FAA;CAAC;ANAC										
657873	238-0950-285	EASA;FAA;CAAC;ANAC										
657873	238-0950-63	EASA;FAA;CAAC;ANAC										
657873	642-5671-501	EASA;FAA;CAAC;ANAC										
657873	642-5672-501	EASA;FAA;CAAC;ANAC										
657873	642-5673-501	EASA;FAA;CAAC;ANAC										
657873	642-5829-501	EASA;FAA;CAAC;ANAC										
657873	642-9831-503	EASA;FAA;ANAC										
657873	642-9878-501	EASA;FAA;CAAC;ANAC										
657873	642-9928-501	EASA;FAA;CAAC;ANAC										
657873	642-9936-501	EASA;FAA;CAAC;ANAC										
657874	1621M35G01	EASA;FAA;ANAC	16	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	90	SR Technics Switzerland
657874	1677M98G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	130	SR Technics Switzerland
657874	1813M14G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		130	SR Technics Switzerland
657874	1813M15G01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		425	SR Technics Switzerland
657874	1867M32G01	EASA;FAA;CAAC;ANAC										
657874	1867M44G01	EASA;FAA;CAAC;ANAC										
657874	1867M58G01	EASA;FAA;CAAC;ANAC										
657874	1867M60G01	EASA;FAA;CAAC;ANAC										
657874	1867M79G01	EASA;FAA;CAAC;ANAC										
657874	1867M81G01	EASA;FAA;CAAC;ANAC										
657874	1867M83G01	EASA;FAA;CAAC;ANAC										
657874	1867M84G01	EASA;FAA;CAAC;ANAC										
657874	1867M87G01	EASA;FAA;CAAC;ANAC										
657874	1869M13G01	EASA;FAA;CAAC;ANAC										
657874	1870M16G01	EASA;FAA;CAAC;ANAC										
657874	1870M33G01	EASA;FAA;CAAC;ANAC										
657874	1870M64G01	EASA;FAA;CAAC;ANAC										
657874	1870M78G01	EASA;FAA;CAAC;ANAC										
657874	1870M82G01	EASA;FAA;CAAC;ANAC										
657874	1892M21G01	EASA;FAA;CAAC;ANAC										
657874	1892M43G01	EASA;FAA;CAAC;ANAC										
657874	1894M44G01	EASA;FAA;CAAC;ANAC										
657874	1894M86G01	EASA;FAA;CAAC;ANAC										
657874	1894M88G01	EASA;FAA;CAAC;ANAC										
657874	1894M91G01	EASA;FAA;CAAC;ANAC										
657874	1894M94G01	EASA;FAA;CAAC;ANAC										
657874	1895M59G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657874	1958M55G01	EASA;FAA;CAAC;ANAC									
657874	1970M99G01	EASA;FAA;CAAC;ANAC									
657874	2174M33P01	EASA;FAA;CAAC;ANAC									
657874	2174M45G01	EASA;FAA;CAAC;ANAC									
657874	2174M46G01	EASA;FAA;CAAC;ANAC									
657874	2174M59G01	EASA;FAA;CAAC;ANAC									
657874	2175M12G01	EASA;FAA;CAAC;ANAC									
657874	2283M76G01	EASA;FAA;CAAC;ANAC									
657874	238-0660-501	EASA;FAA;CAAC;ANAC									
657874	238-0823-503	EASA;FAA;CAAC;ANAC									
657874	238-0856-159	EASA;FAA;CAAC;ANAC									
657874	238-0950-351	EASA;FAA;CAAC;ANAC									
657874	2423M79G01	EASA;FAA;ANAC;CAA UK									
657874	2468M14G01	EASA;FAA;ANAC									
657874	305-070-901-0	EASA;FAA;CAAC;ANAC									
657874	336-480-505-0	EASA;FAA;CAAC;ANAC									
657874	336-544-204-0	EASA;FAA;CAAC;ANAC									
657874	336-545-002-0	EASA;FAA;CAAC;ANAC									
657874	336-547-902-0	EASA;FAA;CAAC;ANAC									
657874	338-025-402-0	EASA;FAA;CAAC;ANAC									
657874	338-038-402-0	EASA;FAA;CAAC;ANAC									
657874	340-009-006-0	EASA;FAA;CAAC;ANAC									
657874	340-022-504-0	EASA;FAA;CAAC;ANAC									
657874	340-023-303-0	EASA;FAA;CAAC;ANAC									
657874	340-023-406-0	EASA;FAA;CAAC;ANAC									
657874	340-097-102-0	EASA;FAA;CAAC;ANAC									
657874	340-097-201-0	EASA;FAA;CAAC;ANAC									
657874	340-097-203-0	EASA;FAA;CAAC;ANAC									
657874	340-097-501-0	EASA;FAA;CAAC;ANAC									
657874	340-123-904-0	EASA;FAA;ANAC									
657874	340-124-003-0	EASA;FAA;CAAC;ANAC									
657874	340-125-704-0	EASA;FAA;CAAC;ANAC									
657874	340-128-304-0	EASA;FAA;ANAC									
657874	340-130-002-0	EASA;FAA;ANAC									
657874	642-5613-501	EASA;FAA;CAAC;ANAC									
657874	642-5676-501	EASA;FAA;CAAC;ANAC									
657874	642-5702-501	EASA;FAA;CAAC;ANAC									
657874	642-5705-501	EASA;FAA;CAAC;ANAC									
657874	642-9830-501	EASA;FAA;CAAC;ANAC									
657874	642-9831-501	EASA;FAA;CAAC;ANAC									
657874	642-9831-505	EASA;FAA;CAAC;ANAC									
657874	642-9834-501	EASA;FAA;CAAC;ANAC									
657874	642-9849-503	EASA;FAA;CAAC;ANAC									
657874	642-9851-503	EASA;FAA;CAAC;ANAC									
657874	642-9857-503	EASA;FAA;CAAC;ANAC									
657874	642-9868-501	EASA;FAA;CAAC;ANAC									
657874	642-9892-501	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657874	642-9896-501	EASA;FAA;CAAC;ANAC										
657874	642-9897-501	EASA;FAA;CAAC;ANAC										
657874	642-9898-503	EASA;FAA;CAAC;ANAC										
657874	642-9920-501	EASA;FAA;CAAC;ANAC										
657874	642-9921-501	EASA;FAA;CAAC;ANAC										
657874	642-9924-501	EASA;FAA;CAAC;ANAC										
657874	642-9925-501	EASA;FAA;CAAC;ANAC										
657874	642-9927-501	EASA;FAA;CAAC;ANAC										
657874	642-9929-501	EASA;FAA;CAAC;ANAC										
657874	642-9945-501	EASA;FAA;CAAC;ANAC										
657875	1444M20G03	EASA;FAA;CAAC;ANAC	17	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	85	SR Technics Switzerland
657875	1677M30G03	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	165	SR Technics Switzerland
657875	1677M48G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		165	SR Technics Switzerland
657875	1788M89G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		165	SR Technics Switzerland
657875	1817M25G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		60	SR Technics Switzerland
657875	1867M19G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB03	RA32029-14	HIGH PRESSURE LINE 9 O'CLOCK CLAMP CHANGE		320	SR Technics Switzerland
657875	1867M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		105	SR Technics Switzerland
657875	1867M82G01	EASA;FAA;CAAC;ANAC										
657875	1869M14G01	EASA;FAA;CAAC;ANAC										
657875	1869M31G01	EASA;FAA;CAAC;ANAC										
657875	1869M32G01	EASA;FAA;CAAC;ANAC										
657875	1870M12G01	EASA;FAA;CAAC;ANAC										
657875	1870M29G01	EASA;FAA;CAAC;ANAC										
657875	1870M30G01	EASA;FAA;CAAC;ANAC										
657875	1870M34G01	EASA;FAA;CAAC;ANAC										
657875	1870M49G01	EASA;FAA;CAAC;ANAC										
657875	1870M58G01	EASA;FAA;CAAC;ANAC										
657875	1870M65G01	EASA;FAA;CAAC;ANAC										
657875	1870M69G01	EASA;FAA;CAAC;ANAC										
657875	1870M76G01	EASA;FAA;CAAC;ANAC										
657875	1870M77G01	EASA;FAA;CAAC;ANAC										
657875	1870M83G01	EASA;FAA;CAAC;ANAC										
657875	1870M91G01	EASA;FAA;CAAC;ANAC										
657875	1871M72G01	EASA;FAA;CAAC;ANAC										
657875	1892M27G01	EASA;FAA;CAAC;ANAC										
657875	1892M42G01	EASA;FAA;CAAC;ANAC										
657875	1892M46G01	EASA;FAA;CAAC;ANAC										
657875	1892M54G01	EASA;FAA;CAAC;ANAC										
657875	1892M68G01	EASA;FAA;CAAC;ANAC										
657875	1892M75G01	EASA;FAA;CAAC;ANAC										
657875	1892M82G01	EASA;FAA;CAAC;ANAC										
657875	1892M97G01	EASA;FAA;CAAC;ANAC										
657875	1894M12G01	EASA;FAA;CAAC;ANAC										
657875	1894M16G01	EASA;FAA;CAAC;ANAC										
657875	1894M21G01	EASA;FAA;CAAC;ANAC										
657875	1894M39G01	EASA;FAA;CAAC;ANAC										
657875	1894M42G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	1894M54G01	EASA;FAA;CAAC;ANAC									
657875	1894M55G01	EASA;FAA;CAAC;ANAC									
657875	1894M60G01	EASA;FAA;CAAC;ANAC									
657875	1894M66G01	EASA;FAA;CAAC;ANAC									
657875	1894M67G01	EASA;FAA;CAAC;ANAC									
657875	1894M84G01	EASA;FAA;CAAC;ANAC									
657875	1894M87G01	EASA;FAA;CAAC;ANAC									
657875	1894M90G01	EASA;FAA;CAAC;ANAC									
657875	1894M92G01	EASA;FAA;CAAC;ANAC									
657875	1895M79G01	EASA;FAA;CAAC;ANAC									
657875	1895M84G01	EASA;FAA;CAAC;ANAC									
657875	1895M85G01	EASA;FAA;CAAC;ANAC									
657875	1895M90G01	EASA;FAA;CAAC;ANAC									
657875	1896M38G01	EASA;FAA;CAAC;ANAC									
657875	1896M90G01	EASA;FAA;CAAC;ANAC									
657875	1897M49G01	EASA;FAA;CAAC;ANAC									
657875	1897M50G01	EASA;FAA;CAAC;ANAC									
657875	1897M57G01	EASA;FAA;CAAC;ANAC									
657875	1897M70G01	EASA;FAA;CAAC;ANAC									
657875	1898M64G01	EASA;FAA;CAAC;ANAC									
657875	1898M80G01	EASA;FAA;CAAC;ANAC									
657875	1898M86G01	EASA;FAA;CAAC;ANAC									
657875	1958M11G01	EASA;FAA;CAAC;ANAC									
657875	1958M13G01	EASA;FAA;CAAC;ANAC									
657875	1958M24G01	EASA;FAA;CAAC;ANAC									
657875	1958M31G01	EASA;FAA;CAAC;ANAC									
657875	1958M34G01	EASA;FAA;CAAC;ANAC									
657875	1958M40G01	EASA;FAA;CAAC;ANAC									
657875	1958M44G01	EASA;FAA;CAAC;ANAC									
657875	1958M45G01	EASA;FAA;CAAC;ANAC									
657875	1958M53G01	EASA;FAA;CAAC;ANAC									
657875	1958M76G01	EASA;FAA;CAAC;ANAC									
657875	1969M26G01	EASA;FAA;CAAC;ANAC									
657875	1969M93G01	EASA;FAA;CAAC;ANAC									
657875	1970M10G01	EASA;FAA;CAAC;ANAC									
657875	1970M28G01	EASA;FAA;CAAC;ANAC									
657875	1970M38G01	EASA;FAA;CAAC;ANAC									
657875	1970M68G01	EASA;FAA;CAAC;ANAC									
657875	1970M98G01	EASA;FAA;CAAC;ANAC									
657875	1971M11G01	EASA;FAA;CAAC;ANAC									
657875	1971M12G01	EASA;FAA;CAAC;ANAC									
657875	1971M14P01	EASA;FAA;CAAC;ANAC									
657875	1971M78G01	EASA;FAA;CAAC;ANAC									
657875	1971M79G01	EASA;FAA;CAAC;ANAC									
657875	1971M86G01	EASA;FAA;CAAC;ANAC									
657875	1971M98G01	EASA;FAA;CAAC;ANAC									
657875	2046M73G01	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	2174M26G01	EASA;FAA;CAAC;ANAC									
657875	2174M31G01	EASA;FAA;CAAC;ANAC									
657875	2174M32G01	EASA;FAA;CAAC;ANAC									
657875	2174M39G01	EASA;FAA;CAAC;ANAC									
657875	2174M41G01	EASA;FAA;CAAC;ANAC									
657875	2174M43G01	EASA;FAA;CAAC;ANAC									
657875	2174M47G01	EASA;FAA;CAAC;ANAC									
657875	2174M51G01	EASA;FAA;CAAC;ANAC									
657875	2174M52G01	EASA;FAA;CAAC;ANAC									
657875	2174M54G01	EASA;FAA;CAAC;ANAC									
657875	2174M58G01	EASA;FAA;CAAC;ANAC									
657875	2175M10G01	EASA;FAA;CAAC;ANAC									
657875	2175M11G01	EASA;FAA;CAAC;ANAC									
657875	2175M15G01	EASA;FAA;CAAC;ANAC									
657875	2175M63G01	EASA;FAA;CAAC;ANAC									
657875	2283M10G01	EASA;FAA;ANAC									
657875	2283M65G01	EASA;FAA;CAAC;ANAC									
657875	238-0557-501	EASA;FAA;CAAC;ANAC									
657875	238-0654-503	EASA;FAA;CAAC;ANAC									
657875	238-0655-503	EASA;FAA;CAAC;ANAC									
657875	238-0704-505	EASA;FAA;CAAC;ANAC									
657875	238-0708-507	EASA;FAA;CAAC;ANAC									
657875	238-0825-503	EASA;FAA;CAAC;ANAC									
657875	238-0856-139	EASA;FAA;CAAC;ANAC									
657875	238-0856-3	EASA;FAA;CAAC;ANAC									
657875	238-0910-35	EASA;FAA;CAAC;ANAC									
657875	238-0950-237	EASA;FAA;CAAC;ANAC									
657875	238-0950-311	EASA;FAA;CAAC;ANAC									
657875	2464M87G01	EASA;ANAC;TCCA;CAA UK									
657875	2678M59G01	EASA;FAA;ANAC									
657875	332A2911-1	EASA;FAA;CAAC;ANAC									
657875	332A2920-142	EASA;FAA;CAAC;ANAC									
657875	332A2920-92	EASA;FAA;CAAC;ANAC									
657875	332A2930-89	EASA;FAA;CAAC;ANAC									
657875	332A2931-3	EASA;FAA;CAAC;ANAC									
657875	336-479-603-0	EASA;FAA;CAAC;ANAC									
657875	336-515-803-0	EASA;FAA;CAAC;ANAC									
657875	336-523-002-0	EASA;FAA;CAAC;ANAC									
657875	336-544-303-0	EASA;FAA;CAAC;ANAC									
657875	336-544-406-0	EASA;FAA;CAAC;ANAC									
657875	336-544-503-0	EASA;FAA;CAAC;ANAC									
657875	336-544-603-0	EASA;FAA;CAAC;ANAC									
657875	336-544-706-0	EASA;FAA;CAAC;ANAC									
657875	336-544-707-0	EASA;FAA;CAAC;ANAC									
657875	336-544-902-0	EASA;FAA;CAAC;ANAC									
657875	338-014-504-0	EASA;FAA;CAAC;ANAC									
657875	338-014-601-0	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	338-017-301-0	EASA;FAA;CAAC;ANAC									
657875	338-017-502-0	EASA;FAA;CAAC;ANAC									
657875	338-022-101-0	EASA;FAA;CAAC;ANAC									
657875	338-023-203-0	EASA;FAA;CAAC;ANAC									
657875	338-024-404-0	EASA;FAA;CAAC;ANAC									
657875	338-024-405-0	EASA;FAA;ANAC									
657875	338-024-601-0	EASA;FAA;CAAC;ANAC									
657875	338-027-801-0	EASA;FAA;CAAC;ANAC									
657875	338-038-601-0	EASA;FAA;CAAC;ANAC									
657875	338-039-402-0	EASA;FAA;CAAC;ANAC									
657875	338-055-202-0	EASA;FAA;CAAC;ANAC									
657875	338-056-201-0	EASA;FAA;CAAC;ANAC									
657875	338-125-803-0	EASA;FAA;ANAC									
657875	338-126-605-0	EASA;FAA;CAAC;ANAC									
657875	338-168-604-0	EASA;FAA;CAAC;ANAC									
657875	340-019-106-0	EASA;FAA;CAAC;ANAC									
657875	340-020-309-0	EASA;FAA;CAAC;ANAC									
657875	340-097-002-0	EASA;FAA;CAAC;ANAC									
657875	340-097-405-0	EASA;FAA;CAAC;ANAC									
657875	340-097-502-0	EASA;FAA;CAAC;ANAC									
657875	340-097-601-0	EASA;FAA;CAAC;ANAC									
657875	340-097-701-0	EASA;FAA;CAAC;ANAC									
657875	340-119-303-0	EASA;FAA;CAAC;ANAC									
657875	340-119-501-0	EASA;FAA;CAAC;ANAC									
657875	340-119-602-0	EASA;FAA;CAAC;ANAC									
657875	340-139-102-0	EASA;FAA;CAAC;ANAC									
657875	340-8134-523	EASA;FAA;CAAC;ANAC									
657875	642-5652-501	EASA;FAA;CAAC;ANAC									
657875	642-5653-501	EASA;FAA;CAAC;ANAC									
657875	642-5657-503	EASA;FAA;CAAC;ANAC									
657875	642-5657-505	EASA;FAA;CAAC;ANAC									
657875	642-5663-501	EASA;FAA;CAAC;ANAC									
657875	642-5664-503	EASA;FAA;CAAC;ANAC									
657875	642-5665-501	EASA;FAA;CAAC;ANAC									
657875	642-5703-501	EASA;FAA;CAAC;ANAC									
657875	642-5826-501	EASA;FAA;CAAC;ANAC									
657875	642-5827-501	EASA;FAA;CAAC;ANAC									
657875	642-5856-501	EASA;FAA;CAAC;ANAC									
657875	642-5862-501	EASA;FAA;CAAC;ANAC									
657875	642-9825-501	EASA;FAA;CAAC;ANAC									
657875	642-9835-501	EASA;FAA;CAAC;ANAC									
657875	642-9836-501	EASA;FAA;CAAC;ANAC									
657875	642-9838-505	EASA;FAA;CAAC;ANAC									
657875	642-9840-501	EASA;FAA;CAAC;ANAC									
657875	642-9841-501	EASA;FAA;CAAC;ANAC									
657875	642-9844-501	EASA;FAA;CAAC;ANAC									
657875	642-9846-501	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	642-9847-501	EASA;FAA;CAAC;ANAC										
657875	642-9855-501	EASA;FAA;CAAC;ANAC										
657875	642-9855-502	EASA;FAA;CAAC;ANAC										
657875	642-9855-503	EASA;FAA;CAAC;ANAC										
657875	642-9856-501	EASA;FAA;CAAC;ANAC										
657875	642-9857-505	EASA;FAA;CAAC;ANAC										
657875	642-9858-502	EASA;FAA;CAAC;ANAC										
657875	642-9869-501	EASA;FAA;CAAC;ANAC										
657875	642-9871-503	EASA;FAA;CAAC;ANAC										
657875	642-9877-503	EASA;FAA;CAAC;ANAC										
657875	642-9879-501	EASA;FAA;CAAC;ANAC										
657875	642-9887-501	EASA;FAA;CAAC;ANAC										
657875	642-9890-501	EASA;FAA;CAAC;ANAC										
657875	642-9894-501	EASA;FAA;CAAC;ANAC										
657875	642-9895-501	EASA;FAA;CAAC;ANAC										
657875	642-9899-503	EASA;FAA;CAAC;ANAC										
657875	642-9912-501	EASA;FAA;CAAC;ANAC										
657875	642-9915-501	EASA;FAA;CAAC;ANAC										
657875	642-9917-501	EASA;FAA;CAAC;ANAC										
657875	642-9919-501	EASA;FAA;CAAC;ANAC										
657875	642-9923-501	EASA;FAA;CAAC;ANAC										
657875	642-9926-501	EASA;FAA;CAAC;ANAC										
657875	642-9930-501	EASA;FAA;CAAC;ANAC										
657875	642-9934-501	EASA;FAA;CAAC;ANAC										
657875	642-9943-501	EASA;FAA;CAAC;ANAC										
657875	642-9944-501	EASA;FAA;CAAC;ANAC										
657875	642-9950-503	EASA;FAA;CAAC;ANAC										
657875	642-9971-501	EASA;FAA;CAAC;ANAC										
657875	9134M25P121	EASA;FAA;CAAC;ANAC										
657875	9134M25P125	EASA;FAA;CAAC;ANAC										
657876	1677M58G01	EASA;FAA;CAAC;ANAC	22	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKE	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	280	SR Technics Switzerland
657876	1677M63G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	455	SR Technics Switzerland
657876	1716M29G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT ANTI SIPHON	SPM 70-42-XY	455	SR Technics Switzerland
657876	1817M10G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		455	SR Technics Switzerland
657876	1817M53G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		455	SR Technics Switzerland
657876	1867M49G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		175	SR Technics Switzerland
657876	1871M24G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	72-0344	INTRODUCTION OF A NEW PROTECTION STRIP ON THE BRACKET.		295	SR Technics Switzerland
657876	1871M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB02	73-0138	ENGINE FUEL AND CONTROL - REWORK OF PARKING BSV BRACKET		295	SR Technics Switzerland
657876	1871M48G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB04	RA32036-10	NACELLE - PNEUMATIC - UPPER 9TH STAGE HIGH PRESSURE (HP) DUCT SUPPOR		295	SR Technics Switzerland
657876	1871M48G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB05	72-0341	MODIFICATION OF THE BRACKET INSTALLED ON HPTCC AIR TUBE FLANGE		295	SR Technics Switzerland
657876	1871M75G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB06	RA32071-152	FAN CASE B1 FLANGE REPL/RE-TORQUE BOLTS		295	SR Technics Switzerland
657876	1892M37G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB07	RA32036-13	INSP OF THE UPPER HIGH PRES. DUCT		295	SR Technics Switzerland
657876	1894M15G01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		140	SR Technics Switzerland
657876	1894M95G01	EASA;FAA;CAAC;ANAC										
657876	1894M96G01	EASA;FAA;CAAC;ANAC										
657876	1895M16G01	EASA;FAA;CAAC;ANAC										
657876	1895M91G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	1898M98G01	EASA;FAA;CAAC;ANAC									
657876	1958M60G01	EASA;FAA;CAAC;ANAC									
657876	1970M76G01	EASA;FAA;CAAC;ANAC									
657876	1970M90G01	EASA;FAA;CAAC;ANAC									
657876	1971M25G01	EASA;FAA;CAAC;ANAC									
657876	2174M34G01	EASA;FAA;CAAC;ANAC									
657876	2174M40G01	EASA;FAA;CAAC;ANAC									
657876	2175M34G01	EASA;FAA;CAAC;ANAC									
657876	2283M34G01	EASA;FAA;CAAC;ANAC									
657876	238-0513-505	EASA;FAA;CAAC;ANAC									
657876	238-0553-501	EASA;FAA;CAAC;ANAC									
657876	238-0554-501	EASA;FAA;CAAC;ANAC									
657876	238-0556-501	EASA;FAA;CAAC;ANAC									
657876	238-0856-121	EASA;FAA;CAAC;ANAC									
657876	238-0856-127	EASA;FAA;CAAC;ANAC									
657876	238-0856-131	EASA;FAA;CAAC;ANAC									
657876	238-0856-135	EASA;FAA;CAAC;ANAC									
657876	238-0856-143	EASA;FAA;CAAC;ANAC									
657876	238-0856-147	EASA;FAA;CAAC;ANAC									
657876	238-0856-151	EASA;FAA;CAAC;ANAC									
657876	238-0856-173	EASA;FAA;CAAC;ANAC									
657876	238-0856-179	EASA;FAA;CAAC;ANAC									
657876	321-455-302-0	EASA;FAA;CAAC;ANAC									
657876	321-455-654-0	EASA;FAA;CAAC;ANAC									
657876	336-084-701-0	EASA;FAA;CAAC;ANAC									
657876	336-084-751-0	EASA;FAA;CAAC;ANAC									
657876	336-091-201-0	EASA;FAA;CAAC;ANAC									
657876	336-469-605-0	EASA;FAA;CAAC;ANAC									
657876	336-477-901-0	EASA;FAA;CAAC;ANAC									
657876	336-495-706-0	EASA;FAA;CAAC;ANAC									
657876	338-011-002-0	EASA;FAA;CAAC;ANAC									
657876	338-011-101-0	EASA;FAA;CAAC;ANAC									
657876	338-012-601-0	EASA;FAA;CAAC;ANAC									
657876	338-012-602-0	EASA;FAA;CAAC;ANAC									
657876	338-012-701-0	EASA;FAA;CAAC;ANAC									
657876	338-012-702-0	EASA;FAA;CAAC;ANAC									
657876	338-012-902-0	EASA;FAA;CAAC;ANAC									
657876	338-013-302-0	EASA;FAA;CAAC;ANAC									
657876	338-013-402-0	EASA;FAA;CAAC;ANAC									
657876	338-013-901-0	EASA;FAA;CAAC;ANAC									
657876	338-014-104-0	EASA;FAA;CAAC;ANAC									
657876	338-014-106-0	EASA;FAA;CAAC;ANAC									
657876	338-014-203-0	EASA;FAA;CAAC;ANAC									
657876	338-015-202-0	EASA;FAA;CAAC;ANAC									
657876	338-016-403-0	EASA;FAA;CAAC;ANAC									
657876	338-016-902-0	EASA;FAA;CAAC;ANAC									
657876	338-021-604-0	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	338-021-605-0	EASA;FAA;CAAC;ANAC									
657876	338-027-402-0	EASA;FAA;CAAC;ANAC									
657876	338-032-002-0	EASA;FAA;ANAC									
657876	338-032-702-0	EASA;FAA;CAAC;ANAC									
657876	338-033-104-0	EASA;FAA;CAAC;ANAC									
657876	338-033-602-0	EASA;FAA;CAAC;ANAC									
657876	338-037-003-0	EASA;FAA;CAAC;ANAC									
657876	338-039-802-0	EASA;FAA;CAAC;ANAC									
657876	338-040-003-0	EASA;FAA;CAAC;ANAC									
657876	338-041-402-0	EASA;FAA;ANAC									
657876	338-042-202-0	EASA;FAA;CAAC;ANAC									
657876	338-042-802-0	EASA;FAA;CAAC;ANAC									
657876	338-053-204-0	EASA;FAA;CAAC;ANAC									
657876	338-054-001-0	EASA;FAA;CAAC;ANAC									
657876	338-054-303-0	EASA;FAA;CAAC;ANAC									
657876	338-056-701-0	EASA;FAA;CAAC;ANAC									
657876	338-058-401-0	EASA;FAA;CAAC;ANAC									
657876	338-058-601-0	EASA;FAA;CAAC;ANAC									
657876	338-059-402-0	EASA;FAA;CAAC;ANAC									
657876	338-059-403-0	EASA;FAA;CAAC;ANAC									
657876	338-122-903-0	EASA;FAA;CAAC;ANAC									
657876	338-125-503-0	EASA;FAA;CAAC;ANAC									
657876	338-125-603-0	EASA;FAA;CAAC;ANAC									
657876	340-006-704-0	EASA;FAA;CAAC;ANAC									
657876	340-006-804-0	EASA;FAA;CAAC;ANAC									
657876	340-007-303-0	EASA;FAA;CAAC;ANAC									
657876	340-013-004-0	EASA;FAA;CAAC;ANAC									
657876	340-017-201-0	EASA;FAA;CAAC;ANAC									
657876	340-019-802-0	EASA;FAA;CAAC;ANAC									
657876	340-020-205-0	EASA;FAA;CAAC;ANAC									
657876	340-025-405-0	EASA;FAA;CAAC;ANAC									
657876	340-075-203-0	EASA;FAA;CAAC;ANAC									
657876	340-075-303-0	EASA;FAA;CAAC;ANAC									
657876	340-086-102-0	EASA;FAA;ANAC									
657876	340-086-103-0	EASA;FAA;CAAC;ANAC									
657876	340-087-904-0	EASA;FAA;CAAC;ANAC									
657876	340-087-905-0	EASA;FAA;CAAC;ANAC									
657876	340-088-903-0	EASA;FAA;CAAC;ANAC									
657876	340-090-304-0	EASA;FAA;CAAC;ANAC									
657876	340-095-705-0	EASA;FAA;CAAC;ANAC									
657876	340-105-609-0	EASA;FAA;CAAC;ANAC									
657876	340-106-402-0	EASA;FAA;CAAC;ANAC									
657876	340-118-101-0	EASA;FAA;CAAC;ANAC									
657876	340-120-602-0	EASA;FAA;CAAC;ANAC									
657876	340-120-902-0	EASA;FAA;CAAC;ANAC									
657876	340-121-202-0	EASA;FAA;CAAC;ANAC									
657876	340-140-102-0	EASA;FAA;CAAC;ANAC									

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	340-140-902-0	EASA;FAA;CAAC;ANAC										
657876	340-159-501-0	EASA;FAA;CAAC;ANAC										
657876	642-3031-503	EASA;FAA;CAAC;ANAC										
657876	642-9827-501	EASA;FAA;CAAC;ANAC										
657876	642-9829-502	EASA;FAA;CAAC;ANAC										
657876	642-9829-503	EASA;FAA;CAAC;ANAC										
657876	642-9866-503	EASA;FAA;CAAC;ANAC										
657876	642-9867-505	EASA;FAA;CAAC;ANAC										
657876	642-9876-503	EASA;FAA;CAAC;ANAC										
657876	649-400-055-0	EASA;FAA;CAAC;ANAC										
657876	649-400-056-0	EASA;FAA;CAAC;ANAC										
657876	AMBK4-4014	EASA;FAA;CAAC;ANAC										
657876	P40560	EASA;FAA;CAAC;ANAC										
657876	P40570	EASA;FAA;CAAC;ANAC										
663441	30377-300	EASA;FAA;ANAC	15	28	72-00-00	ENGINE GENERAL - COMMON PARTS - MISCELLANEOUS CLAMPS GENER	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY		235 SR Technics Switzerland
663441	30377-500	EASA;FAA;ANAC										
663441	30377-600	EASA;FAA;ANAC										
663441	30398-200	EASA;FAA;ANAC										
663441	30398-400	EASA;FAA;ANAC										
663441	30550-400	EASA;FAA;ANAC										
663441	30659-200	EASA;FAA;ANAC										
663441	30659-400	EASA;FAA;ANAC										
663441	30679-450	EASA;FAA;ANAC										
663441	30679-500	EASA;FAA;ANAC										
663441	30679-600	EASA;FAA;ANAC										
663441	30759-200	EASA;FAA;ANAC										
663441	30766-400	EASA;FAA;ANAC										
663441	31046-150	EASA;FAA;ANAC										
663441	31073-150	EASA;FAA;ANAC										
663441	34H40-600	EASA;FAA;ANAC										
663441	50U366	EASA;FAA;ANAC										
663441	50U367	EASA;FAA;ANAC										
663441	50U368	EASA;FAA;ANAC										
663441	50U370	EASA;FAA;ANAC										
663441	50U372	EASA;FAA;ANAC										
663441	50U373	EASA;FAA;ANAC										
663441	50U374	EASA;FAA;ANAC										
663441	51U749	EASA;FAA;ANAC										
663441	51U888	EASA;FAA;ANAC										
663441	56T561	EASA;FAA;ANAC										
663441	57T938	EASA;FAA;CAAC;ANAC										
663441	58T054	EASA;FAA;ANAC										
663441	58T886	EASA;FAA;ANAC										
663441	59T331	EASA;FAA;ANAC										
663441	728879-2	EASA;FAA;ANAC										
663891	J905P08A	EASA;FAA;CAAC;ANAC	4	0	72-09-04	BOLT INSPECTION CFM56 ENGINE	Package A	CLN/INSP	CLEANING & INSPECTION			150 SR Technics Switzerland
663891	J905P10A	EASA;FAA;CAAC;ANAC										

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B
valid until December 31, 2026**

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
664002	1895M53P01	EASA;FAA;CAAC;ANAC	6	21	72-XX_XX	CFM56 TL FOR MISCELLANEOUS CFM PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		70	SR Technics Switzerland
664002	338-007-401-0	EASA;FAA;ANAC										
664002	338-025-303-0	EASA;FAA;CAAC;ANAC										
664002	340-094-606-0	EASA;FAA;CAAC;ANAC										
664002	340-094-607-0	EASA;FAA;CAAC;ANAC										
664002	340-094-608-0	EASA;FAA;CAAC;ANAC										
664002	340-094-609-0	EASA;FAA;CAAC;ANAC										
664002	340-094-610-0	EASA;FAA;CAAC;ANAC										
664002	340-146-701-0	EASA;FAA;CAAC;ANAC										
664002	9993M72P01	EASA;FAA;CAAC;ANAC										
665444	336-056-201-0	EASA;FAA;ANAC	5	28	72-21-00	BALANCE WEIGHT	Package A	CLN	CLEANING & INSPECTION		75	SR Technics Switzerland
665444	336-056-202-0	EASA;FAA;ANAC										
665444	336-056-203-0	EASA;FAA;ANAC										
665444	336-056-204-0	EASA;FAA;ANAC										
667723	1834M53P01	EASA;FAA;CAAC;ANAC	12	28	72-31-20	CFM56 HPC HARDWARE BALANCE WEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		75	SR Technics Switzerland
667723	1834M53P02	EASA;FAA;CAAC;ANAC										
667723	1834M54P01	EASA;FAA;CAAC;ANAC										
667723	1993M73P01	EASA;FAA;CAAC;ANAC										
667723	1993M73P02	EASA;FAA;CAAC;ANAC										
667723	1993M74P01	EASA;FAA;CAAC;ANAC										
667723	1993M74P02	EASA;FAA;CAAC;ANAC										
671086	336-482-301-0	EASA;FAA;CAAC;ANAC	9	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	160	SR Technics Switzerland
671086	336-522-703-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		215	SR Technics Switzerland
671086	337-154-601-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	215	SR Technics Switzerland
671086	338-013-101-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS AND NUTS	SPM 70-42-XX	215	SR Technics Switzerland
671086	338-016-002-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		215	SR Technics Switzerland
671086	338-016-201-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		95	SR Technics Switzerland
671086	338-016-603-0	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		155	SR Technics Switzerland
671086	338-021-303-0	EASA;FAA;CAAC;ANAC										
671086	338-022-301-0	EASA;FAA;ANAC										
671086	338-027-302-0	EASA;FAA;CAAC;ANAC										
671086	338-028-301-0	EASA;FAA;CAAC;ANAC										
671086	338-028-601-0	EASA;FAA;CAAC;ANAC										
671086	338-029-702-0	EASA;FAA;CAAC;ANAC										
671086	338-030-803-0	EASA;FAA;CAAC;ANAC										
671086	338-031-003-0	EASA;FAA;CAAC;ANAC										
671086	338-031-702-0	EASA;FAA;CAAC;ANAC										
671086	338-032-502-0	EASA;FAA;ANAC										
671086	338-032-803-0	EASA;FAA;CAAC;ANAC										
671086	338-033-903-0	EASA;FAA;CAAC;ANAC										
671086	338-034-102-0	EASA;FAA;CAAC;ANAC										
671086	338-034-302-0	EASA;FAA;CAAC;ANAC										
671086	338-034-403-0	EASA;FAA;ANAC										
671086	338-034-703-0	EASA;FAA;ANAC										
671086	338-035-701-0	EASA;FAA;CAAC;ANAC										
671086	338-036-003-0	EASA;FAA;CAAC;ANAC										
671086	338-037-601-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671086	338-037-901-0	EASA;FAA;CAAC;ANAC										
671086	338-038-101-0	EASA;FAA;CAAC;ANAC										
671086	338-040-201-0	EASA;FAA;ANAC										
671086	338-041-201-0	EASA;FAA;CAAC;ANAC										
671086	338-041-602-0	EASA;FAA;CAAC;ANAC										
671086	338-041-802-0	EASA;FAA;CAAC;ANAC										
671086	338-042-001-0	EASA;FAA;CAAC;ANAC										
671086	338-042-401-0	EASA;FAA;ANAC										
671086	338-042-602-0	EASA;FAA;CAAC;ANAC										
671086	338-043-201-0	EASA;FAA;CAAC;ANAC										
671086	338-043-202-0	EASA;FAA;CAAC;ANAC										
671086	338-043-401-0	EASA;FAA;CAAC;ANAC										
671086	338-043-601-0	EASA;FAA;CAAC;ANAC										
671086	338-043-801-0	EASA;FAA;ANAC										
671086	338-044-001-0	EASA;FAA;CAAC;ANAC										
671086	338-046-401-0	EASA;FAA;ANAC										
671086	338-050-301-0	EASA;FAA;CAAC;ANAC										
671086	338-057-301-0	EASA;FAA;CAAC;ANAC										
671086	338-059-501-0	EASA;FAA;CAAC;ANAC										
671086	338-059-601-0	EASA;FAA;CAAC;ANAC										
671086	338-088-701-0	EASA;FAA;ANAC										
671086	338-130-102-0	EASA;FAA;CAAC;ANAC										
671086	340-019-002-0	EASA;FAA;CAAC;ANAC										
671086	340-143-701-0	EASA;FAA;CAAC;ANAC										
671086	VTF02460	EASA;FAA;CAAC;ANAC										
671089	1348M59P01	EASA;FAA;CAAC;ANAC	6	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	265	SR Technics Switzerland
671089	1467M96G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		80	SR Technics Switzerland
671089	1527M36G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP-001	REPLACE INSERT SPM	70-42-XX	210	SR Technics Switzerland
671089	1870M22G01	EASA;FAA;CAAC;ANAC			72-09-04		Package D	INSP-001	REPLACE RIVETED PART'S		185	SR Technics Switzerland
671089	1892M84G01	EASA;FAA;CAAC;ANAC			72-09-04		Package E	INSP-001	WELDING HINGED BRACKETS		265	SR Technics Switzerland
671089	1892M98G01	EASA;FAA;CAAC;ANAC			72-09-04		Package F	INSP-001	REPLACE INSERT ANTI SIPHON	SPM 70-42-11	200	SR Technics Switzerland
671089	1894M28G01	EASA;FAA;CAAC;ANAC			72-09-04		Package G	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	80	SR Technics Switzerland
671089	1894M80G01	EASA;FAA;CAAC;ANAC			72-09-04		Package L	011	REPLACE KEY LOCKED INSERT		110	SR Technics Switzerland
671089	1895M89G01	EASA;FAA;CAAC;ANAC			72-09-04		Package M	051	BRACKET PIN REPLACE		165	SR Technics Switzerland
671089	1896M53G01	EASA;FAA;CAAC;ANAC			72-09-04		Package N	REPAIR	SPM SHOCK-MOUNT REPLACE ELASTOMER		95	SR Technics Switzerland
671089	1898M66G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	SB 75-0044	INTRO OF A NEW INLET AIRSCOOP ASSY AND REWORK OF THE OLD ONE		655	SR Technics Switzerland
671089	1958M12G01	EASA;FAA;CAAC;ANAC										
671089	1958M64G01	EASA;FAA;CAAC;ANAC										
671089	1970M27G01	EASA;FAA;CAAC;ANAC										
671089	2046M34G01	EASA;FAA;CAAC;ANAC										
671089	2174M20P01	EASA;FAA;CAAC;ANAC										
671089	2174M25G01	EASA;FAA;CAAC;ANAC										
671089	2174M35G01	EASA;FAA;CAAC;ANAC										
671089	2174M37G01	EASA;FAA;CAAC;ANAC										
671089	2174M38G01	EASA;FAA;CAAC;ANAC										
671089	2174M44G01	EASA;FAA;CAAC;ANAC										
671089	2174M49G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	2175M13G01	EASA;FAA;CAAC;ANAC										
671089	238-0505-503	EASA;FAA;CAAC;ANAC										
671089	238-0607-503	EASA;FAA;CAAC;ANAC										
671089	238-0608-503	EASA;FAA;CAAC;ANAC										
671089	238-0610-511	EASA;FAA;CAAC;ANAC										
671089	24765-01	EASA;FAA;CAAC;ANAC										
671089	321-450-701-6	EASA;FAA;CAAC;ANAC										
671089	321-450-802-0	EASA;FAA;CAAC;ANAC										
671089	321-451-100-0	EASA;FAA;CAAC;ANAC										
671089	321-451-452-0	EASA;FAA;CAAC;ANAC;CAA UK										
671089	332A2910-101	EASA;FAA;CAAC;ANAC										
671089	332A2910-106	EASA;FAA;CAAC;ANAC										
671089	332A2910-111	EASA;FAA;CAAC;ANAC										
671089	332A2910-113	EASA;FAA;CAAC;ANAC										
671089	332A2910-130	EASA;FAA;CAAC;ANAC										
671089	332A2910-132	EASA;FAA;CAAC;ANAC										
671089	332A2910-134	EASA;FAA;CAAC;ANAC										
671089	332A2910-136	EASA;FAA;CAAC;ANAC										
671089	332A2910-143	EASA;FAA;CAAC;ANAC										
671089	332A2910-147	EASA;FAA;ANAC										
671089	332A2910-149	EASA;FAA;ANAC										
671089	332A2910-24	EASA;FAA;CAAC;ANAC										
671089	332A2910-41	EASA;FAA;CAAC;ANAC										
671089	332A2910-74	EASA;FAA;CAAC;ANAC										
671089	332A2911-9	EASA;FAA;CAAC;ANAC										
671089	332A2920-157	EASA;FAA;CAAC;ANAC										
671089	332A2920-185	EASA;FAA;CAAC;ANAC										
671089	332A2920-187	EASA;FAA;ANAC										
671089	332A2920-193	EASA;FAA;ANAC										
671089	332A2920-197	EASA;FAA;CAAC;ANAC										
671089	332A2920-199	EASA;FAA;CAAC;ANAC										
671089	332A2920-224	EASA;FAA;CAAC;ANAC										
671089	332A2920-225	EASA;FAA;ANAC										
671089	332A2920-229	EASA;FAA;CAAC;ANAC;CAA UK										
671089	332A2920-230	EASA;FAA;CAAC;ANAC										
671089	332A2920-236	EASA;FAA;ANAC										
671089	332A2920-245	EASA;FAA;CAAC;ANAC										
671089	332A2920-55	EASA;FAA;CAAC;ANAC										
671089	332A2921-1	EASA;FAA;CAAC;ANAC										
671089	332A2930-104	EASA;FAA;CAAC;ANAC										
671089	332A2930-11	EASA;FAA;CAAC;ANAC										
671089	332A2930-50	EASA;FAA;ANAC										
671089	332A2930-83	EASA;FAA;CAAC;ANAC										
671089	332A2930-88	EASA;FAA;ANAC										
671089	332A2930-90	EASA;FAA;CAAC;ANAC										
671089	336-512-905-0	EASA;FAA;CAAC;ANAC										
671089	336-512-906-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	338-018-302-0	EASA;FAA;CAAC;ANAC										
671089	338-021-402-0	EASA;FAA;CAAC;ANAC										
671089	338-023-003-0	EASA;FAA;CAAC;ANAC										
671089	338-024-802-0	EASA;FAA;CAAC;ANAC										
671089	338-027-501-0	EASA;FAA;CAAC;ANAC										
671089	338-027-502-0	EASA;FAA;CAAC;ANAC										
671089	338-028-704-0	EASA;FAA;CAAC;ANAC										
671089	338-038-604-0	EASA;FAA;CAAC;ANAC										
671089	338-045-901-0	EASA;CAAC										
671089	338-046-101-0	EASA;FAA;CAAC;ANAC										
671089	338-055-401-0	EASA;FAA;CAAC;ANAC										
671089	338-163-505-0	EASA;FAA;CAAC;ANAC										
671089	340-017-402-0	EASA;FAA;CAAC;ANAC										
671089	340-097-304-0	EASA;FAA;CAAC;ANAC										
671089	340-097-802-0	EASA;FAA;CAAC;ANAC										
671089	340-114-301-0	EASA;FAA;CAAC;ANAC										
671089	340-140-503-0	EASA;FAA;CAAC;ANAC										
671089	642-3031-501	EASA;FAA;CAAC;ANAC										
671089	642-5651-501	EASA;FAA;CAAC;ANAC										
671089	642-5656-501	EASA;FAA;CAAC;ANAC										
671089	642-5675-501	EASA;FAA;CAAC;ANAC										
671089	642-5677-501	EASA;FAA;CAAC;ANAC										
671089	642-5681-501	EASA;FAA;CAAC;ANAC										
671089	642-5681-503	EASA;FAA;CAAC;ANAC										
671089	642-5715-507	EASA;FAA;CAAC;ANAC										
671089	642-5752-501	EASA;FAA;CAAC;ANAC										
671089	642-5753-501	EASA;FAA;CAAC;ANAC										
671089	642-5927-502	EASA;FAA;CAAC;ANAC										
671089	642-9826-501	EASA;FAA;CAAC;ANAC										
671089	642-9828-503	EASA;FAA;CAAC;ANAC										
671089	642-9829-501	EASA;FAA;CAAC;ANAC										
671089	642-9833-501	EASA;FAA;CAAC;ANAC										
671089	642-9837-501	EASA;FAA;CAAC;ANAC										
671089	642-9843-501	EASA;FAA;CAAC;ANAC										
671089	642-9845-501	EASA;FAA;CAAC;ANAC										
671089	642-9850-501	EASA;FAA;CAAC;ANAC										
671089	642-9863-501	EASA;FAA;CAAC;ANAC										
671089	642-9870-503	EASA;FAA;CAAC;ANAC										
671089	642-9889-501	EASA;FAA;CAAC;ANAC										
671089	642-9893-501	EASA;FAA;CAAC;ANAC										
671089	642-9913-501	EASA;FAA;CAAC;ANAC										
671089	642-9916-501	EASA;FAA;CAAC;ANAC										
671089	642-9918-501	EASA;FAA;CAAC;ANAC										
671089	642-9922-501	EASA;FAA;CAAC;ANAC										
671089	642-9951-503	EASA;FAA;CAAC;ANAC										
671095	301-534-311-0	EASA;FAA;CAAC;ANAC	9	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	115	SR Technics Switzerland
671095	336-480-401-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	85	SR Technics Switzerland

**Capabilities and Fixed Prices Catalogue 2026 for
CFM56-5B**
valid until December 31, 2026

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671095	336-486-001-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	85	SR Technics Switzerland
671095	337-138-303-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP-001	REPLACE RIVETED PART'S		85	SR Technics Switzerland
671095	338-015-302-0	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		85	SR Technics Switzerland
671095	338-027-201-0	EASA;FAA;ANAC										
671095	338-028-001-0	EASA;FAA;CAAC;ANAC										
671095	338-030-504-0	EASA;FAA;CAAC;ANAC										
671095	338-033-504-0	EASA;FAA;CAAC;ANAC										
671095	338-035-201-0	EASA;FAA;ANAC										
671095	338-040-801-0	EASA;FAA;ANAC										
671095	338-041-002-0	EASA;FAA;CAAC;ANAC										
671095	338-045-401-0	EASA;FAA;CAAC;ANAC										
671095	338-045-601-0	EASA;FAA;ANAC										
671095	338-050-801-0	EASA;FAA;CAAC;ANAC										
671095	338-057-401-0	EASA;FAA;CAAC;ANAC										
671095	340-002-202-0	EASA;FAA;CAAC;ANAC										
671095	340-116-001-0	EASA;FAA;CAAC;ANAC										
671095	340-131-301-0	EASA;FAA;CAAC;ANAC										
671095	340-132-201-0	EASA;FAA;CAAC;ANAC										
671095	340-143-501-0	EASA;FAA;CAAC;ANAC										
671095	340-143-702-0	EASA;FAA;ANAC										
671095	642-5828-501	EASA;FAA;CAAC;ANAC										
671175	340-031-802-0	EASA;FAA;CAAC;ANAC	9	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	70	SR Technics Switzerland
671175	340-088-701-0	EASA;FAA;CAAC;ANAC										
672453	1870M26P01	EASA;FAA;CAAC;ANAC	5	21	72-09-04	CFM56 ENGINE HARDWARE INSPECTION MOD.82	Package A	CLN/INSP	CLEANING & INSPECTION		105	SR Technics Switzerland
672453	1898M50G01	EASA;FAA;CAAC;ANAC										
672453	340-078-202-0	EASA;FAA;ANAC										
672453	649-791-260-0	EASA;FAA;CAAC;ANAC										
672775	1348M88G05	EASA;FAA;CAAC;ANAC	12	28	72-41-04	CFM56 MANIFOLD-FUEL SUPPLY/DRAIN	Package A	CLN/INSP	CLEANING AND INSPECTION	FOR SHOP VISITS ONLY	570	SR Technics Switzerland
672775	1348M88G07	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	BLENDING DRAIN TUBE		1,030	SR Technics Switzerland
672775	1348M88G08	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	BLENDING SUPPLY TUB		1,030	SR Technics Switzerland
672775	1444M50G11	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST DRAIN		1,030	SR Technics Switzerland
672775	1444M50G13	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST SUPPLY		1,030	SR Technics Switzerland
672775	1444M51G17	EASA;FAA;CAAC;ANAC			72-41-04		Package D	002	TUBE FITTING NUT		505	SR Technics Switzerland
672775	1444M51G18	EASA;FAA;CAAC;ANAC			72-41-04		Package E		REPLACE DEFECTIVE FUEL NOZZLE SHROUD		375	SR Technics Switzerland
672775	1605M65G01	EASA;FAA;CAAC;ANAC			72-41-04		Package SB00	73-0044	DELETION AT THE FUEL NOZZLE DRAIN SHROUDS		925	SR Technics Switzerland
672775	1621M82G01	EASA;FAA;CAAC;ANAC			72-41-04		Package SB01	73-0052	FIELD REWORK OF SAC INNER AND OUTER FUEL MAIFOLDS		3,580	SR Technics Switzerland
672775	1813M58G02	EASA;FAA;CAAC;ANAC										
672775	1867M63G01	EASA;FAA;CAAC;ANAC										
672775	1867M64G01	EASA;FAA;CAAC;ANAC										
672775	1867M68G01	EASA;FAA;CAAC;ANAC										
672775	1870M11G01	EASA;FAA;CAAC;ANAC										
672775	1871M74G01	EASA;FAA;CAAC;ANAC										
672775	1882M60G03	EASA;FAA;CAAC;ANAC										
672775	1882M60G04	EASA;FAA;CAAC;ANAC										
672775	1882M61G03	EASA;FAA;CAAC;ANAC										
672775	1882M61G04	EASA;FAA;CAAC;ANAC										
672775	1882M62G03	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672775	1882M62G04	EASA;FAA;CAAC;ANAC										
672775	1882M63G03	EASA;FAA;CAAC;ANAC										
672775	1882M63G04	EASA;FAA;CAAC;ANAC										
672775	1892M95G01	EASA;FAA;CAAC;ANAC										
672775	1895M12G01	EASA;FAA;CAAC;ANAC										
672775	1895M12G02	EASA;FAA;CAAC;ANAC										
672775	1895M19G01	EASA;FAA;CAAC;ANAC										
672775	1895M44G01	EASA;FAA;CAAC;ANAC										
672775	1895M45G01	EASA;FAA;CAAC;ANAC										
672775	1895M80G06	EASA;FAA;CAAC;ANAC										
672775	1895M80G08	EASA;FAA;CAAC;ANAC										
672775	1895M81G06	EASA;FAA;CAAC;ANAC										
672775	1895M81G11	EASA;FAA;CAAC;ANAC										
672775	1895M82G06	EASA;FAA;CAAC;ANAC										
672775	1895M82G08	EASA;FAA;CAAC;ANAC										
672775	1895M83G06	EASA;FAA;CAAC;ANAC										
672775	1895M83G13	EASA;FAA;CAAC;ANAC										
672775	1895M83G14	EASA;FAA;CAAC;ANAC										
672775	1958M81G01	EASA;FAA;CAAC;ANAC										
672775	1958M82G01	EASA;FAA;CAAC;ANAC										
672775	1958M86G01	EASA;FAA;CAAC;ANAC										
672775	1971M10G01	EASA;FAA;CAAC;ANAC										
672775	1971M17G01	EASA;FAA;CAAC;ANAC										
672775	1971M18G01	EASA;FAA;CAAC;ANAC										
672775	1971M63G01	EASA;FAA;CAAC;ANAC										
672775	1971M63G02	EASA;FAA;CAAC;ANAC										
672775	1971M95G01	EASA;FAA;CAAC;ANAC										
672775	1971M96G01	EASA;FAA;CAAC;ANAC										
672775	2046M62G01	EASA;FAA;CAAC;ANAC										
672775	2046M63G01	EASA;FAA;CAAC;ANAC										
672775	9393M59G05	EASA;FAA;CAAC;ANAC										
672775	9393M60G07	EASA;FAA;CAAC;ANAC										
672775	9394M34G01	EASA;FAA;CAAC;ANAC										
672783	1871M49G03	EASA;FAA;CAAC;ANAC	9	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	195	SR Technics Switzerland
672783	1892M63P01	EASA			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		80	SR Technics Switzerland
672783	1895M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP/CHK	REPLACE INSERT	SPM 70-42-XY	210	SR Technics Switzerland
672783	1895M35G01	EASA;FAA;CAAC;ANAC										
672783	2174M29G01	EASA;FAA;ANAC										
672783	2175M14G01	EASA;FAA;CAAC;ANAC										
672783	340-201-003-0	EASA;EASA/ANAC BRAZIL DUAL R										
672788	1443M74G02	EASA;FAA;CAAC;ANAC	5	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	160	SR Technics Switzerland
672788	1443M77G02	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		215	SR Technics Switzerland
672788	1645M33G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERTS		215	SR Technics Switzerland
672788	1645M33G03	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS OR NUTS		215	SR Technics Switzerland
672788	1867M33G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		215	SR Technics Switzerland
672788	1867M33G02	EASA;FAA;CAAC;ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		95	SR Technics Switzerland
672788	1867M35G01	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		155	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672788	1867M35G02	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	73-0044	DELETION AT THE FUEL NOZZLE DRAIN SHROUD		160	SR Technics Switzerland
672788	1867M45G01	EASA;FAA;CAAC;ANAC										
672788	1867M62G01	EASA;FAA;CAAC;ANAC										
672788	1868M21G01	EASA;FAA;CAAC;ANAC										
672788	1868M22G01	EASA;FAA;CAAC;ANAC										
672788	1869M28G01	EASA;FAA;CAAC;ANAC										
672788	1869M29G01	EASA;FAA;CAAC;ANAC										
672788	1870M37G01	EASA;FAA;CAAC;ANAC										
672788	1871M23G01	EASA;FAA;CAAC;ANAC										
672788	1871M80G01	EASA;FAA;CAAC;ANAC										
672788	1892M72G01	EASA;FAA;CAAC;ANAC										
672788	1892M81G01	EASA;FAA;CAAC;ANAC										
672788	1892M85G01	EASA;FAA;CAAC;ANAC										
672788	1892M86G01	EASA;FAA;CAAC;ANAC										
672788	1892M94G01	EASA;FAA;CAAC;ANAC										
672788	1894M19G01	EASA;FAA;CAAC;ANAC										
672788	1894M50G01	EASA;FAA;CAAC;ANAC										
672788	1894M76G01	EASA;FAA;CAAC;ANAC										
672788	1895M20G01	EASA;FAA;CAAC;ANAC										
672788	1895M23G01	EASA;FAA;CAAC;ANAC										
672788	1895M36G01	EASA;FAA;CAAC;ANAC										
672788	1895M37G01	EASA;FAA;CAAC;ANAC										
672788	1896M66G01	EASA;FAA;CAAC;ANAC										
672788	1896M70G01	EASA;FAA;CAAC;ANAC										
672788	1898M61G01	EASA;FAA;CAAC;ANAC										
672788	1958M54G01	EASA;FAA;CAAC;ANAC										
672788	1969M24G01	EASA;FAA;CAAC;ANAC										
672788	2174M30G01	EASA;FAA;CAAC;ANAC										
672788	2174M36G01	EASA;FAA;CAAC;ANAC										
672788	2174M53G01	EASA;FAA;ANAC										
672788	2175M38G01	EASA;FAA;CAAC;ANAC										
672788	2175M84G01	EASA;FAA;CAAC;ANAC										
672788	336-044-801-0	EASA;FAA;CAAC;ANAC										
672788	338-039-002-0	EASA;FAA;CAAC;ANAC										
672788	338-057-803-0	EASA;FAA;CAAC;ANAC										
672788	340-180-401-0	EASA;FAA;CAAC;ANAC										
672788	340-180-601-0	EASA;FAA;CAAC;ANAC										
672793	1869M44G01	EASA;FAA;CAAC;ANAC	6	21	72-09-04	SPM 70-42-XX	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	115	SR Technics Switzerland
672793	1898M82G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELOCOIL INSERT		85	SR Technics Switzerland
672793	1958M37G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	85	SR Technics Switzerland
672793	2046M76G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		85	SR Technics Switzerland
672793	338-056-901-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	SPM	SHOCK-MOUNT REPLACE ELASTOMER		85	SR Technics Switzerland
672793	338-122-301-0	EASA;FAA;CAAC;ANAC										
672793	340-097-202-0	EASA;FAA;CAAC;ANAC										
672801	1871M51G01	EASA;FAA;CAAC;ANAC	8	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	75	SR Technics Switzerland
672801	1894M72P001A	EASA;FAA;CAAC;ANAC										
672807	337-114-052-0	EASA;FAA;CAAC;ANAC	8	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	355	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672807	338-012-303-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR AND PRESSURE TEST		1,280	SR Technics Switzerland
672807	649-430-111-0	EASA;FAA;CAAC;ANAC										
672818	338-082-101-0	EASA;FAA;CAAC;ANAC	10	21	72-23-18	CFM56 N0.3 BEARING TUBE-DRAIN/SUPPLY	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	690	SR Technics Switzerland
672818	338-082-201-0	EASA;FAA;CAAC;ANAC			72-23-18		Package B	01	REPLACE SELF-LOCKING NUTS		345	SR Technics Switzerland
672818	340-026-402-0	EASA;FAA;CAAC;ANAC										
672818	340-030-601-0	EASA;FAA;CAAC;ANAC										
672818	340-032-102-0	EASA;FAA;CAAC;ANAC										
672818	340-034-402-0	EASA;FAA;CAAC;ANAC										
672819	1898M65G01	EASA;FAA;CAAC;ANAC	8	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	440	SR Technics Switzerland
672819	340-026-602-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		1,075	SR Technics Switzerland
672819	340-034-202-0	EASA;FAA;CAAC;ANAC										
672820	337-036-917-0	EASA;FAA;CAAC;ANAC	9	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	440	SR Technics Switzerland
672820	340-023-202-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		1,075	SR Technics Switzerland
672820	649-430-021-0	EASA;FAA;CAAC;ANAC										
672820	649-432-111-0	EASA;FAA;CAAC;ANAC										
672820	649-434-051-0	EASA;FAA;CAAC;ANAC										
672822	340-026-502-0	EASA;FAA;CAAC;ANAC	10	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSES	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	325	SR Technics Switzerland
672822	340-200-002-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		680	SR Technics Switzerland
672822	J1238P04	EASA;FAA;CAAC;ANAC										
673122	238-0226-507	EASA;FAA;CAAC;ANAC	6	28	72-23-02	CFM56-5B FWD MOUNT SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION	FOR SHOP VISITS ONLY	155	SR Technics Switzerland
673122	238-0226-508	EASA;FAA;CAAC;ANAC										
673677	321-450-603-0	EASA;FAA;CAAC;ANAC	10	28	71-00-01	INNER FLANGE ASSY	Package A	CLN/INSP	PREREQUISIT INSPECTION AND REPAIR	FOR SHOP VISITS ONLY	690	SR Technics Switzerland
673677	321-456-602-0	EASA;CAAC;EASA/ANAC BRAZIL D			71-00-01		Package B	SPM 70-43-11	REPLACE RIVETS		240	SR Technics Switzerland
673762			4	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package B		REPLACE INSERTS ENGINE		320	SR Technics Switzerland
673762					72-00-00		Package C		REPLACE INSERTS MODULE		320	SR Technics Switzerland
673762					72-00-00		Package D		REPLACE INSERTS TEST CELL		350	SR Technics Switzerland
673762					72-00-00		Package E		REPLACE INSERTS QTL		320	SR Technics Switzerland
140213	LPT MAJOR MODUL		30	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION	-	435	SR Technics Switzerland
140213					72-00-03		Package AE	051	REPLACEMENT OF BROKEN STUDS OF T49.5 EGT SENSOR FIXATION ASSEMBLY P-		21,050	SR Technics Switzerland
140213					72-00-03		Package B	001	REPLACEMENT/REWORK OF RIVETED PARTS	72-54-07	760	SR Technics Switzerland
140213					72-00-03		Package D	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR	-	525	SR Technics Switzerland
140213					72-00-03		Package F	001	STUD REPLACEMENT	72-00-03	1,405	SR Technics Switzerland
140213					72-00-03		Package K	010	RECONDITIONING OF THE LPT SHAFT PAINT AT MAJOR MODULE 3	-	505	SR Technics Switzerland
140213					72-00-03		Package O	014	BLENDING ANTI-ROTATION-LUG	-	545	SR Technics Switzerland
140213					72-00-03		Package SB01	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD	-	1,115	SR Technics Switzerland
140213					72-00-03		Package SB02	72-0473	REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR BRACKET ASSY AND RET-		1,435	SR Technics Switzerland
140213					72-00-03		Package SB03	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL S-		330	SR Technics Switzerland
140213					72-00-03		Package SB04	72-0589	REIDENTIFICATION OF LPT CASE IN FIELD		255	SR Technics Switzerland
140213					72-00-03		Package SB05	EASA-2014-0130	TIME LIMITS INSPECTIONS		310	SR Technics Switzerland
9017	HPT ROTOR ASSY		23	28	72-52-00	HIGH PRESSURE TURBINE ROTOR - ASSEMBLY	Package B	ASSEMBLY	HIGH SPEED GRINDING BLADE RADIUS K AND MACHINE NOTCHES ON HPT BLADES TIP		3,260	SR Technics Switzerland
9017					72-52-00		Package C	SPEC.PROC-002	PREGROUNDING BLADE SET		4,385	SR Technics Switzerland
9017					72-52-00		Package SB00	72-0171	HPC ROTOR, MOD FROM -5B/2 TO -5B/2P	HIGH SPEED GRINDING BLADE RADIUS K A	4,385	SR Technics Switzerland
9017					72-52-00		Package SB01	72-0263	CONVERSION OF 5BN TO 5BN/P N =1,2,4,5,6	HIGH SPEED GRINDING BLADE RADIUS K A	4,385	SR Technics Switzerland
139963	COMPRESSOR ROTOR ASS		23	28	72-31-00	COMPRESSOR ROTOR - ASSEMBLY	Package B	ASSEMBLY-001	HIGH SPEED GRINDING OF BLADE TIP		10,855	SR Technics Switzerland
139963					72-31-00		Package SB00	72-0171	HPC ROTOR, MOD FROM -5B/2 TO -5B/2P	HIGH SPEED GRINDING OF BLADE TIP ONL'	10,855	SR Technics Switzerland
139963					72-31-00		Package SB01	72-0263	CONVERSION OF 5BN TO 5BN/P N =1,2,4,5,6	HIGH SPEED GRINDING OF BLADE TIP ONLY	10,855	SR Technics Switzerland
648803	SCREW-NUT-SPACER-SETB		10	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - SCREWS, NUTS AND SPACERS REFURBISHMENT	Package B	LIGHT	REFURBISHMENT OF REMOVED SET OF PARTS	3 OR LESS OF FOLLOW. ENG. MODULS PARTIALLY/FULLY DISASS. (21,22,23,41,42,51,52,53,54,55,56,61,62,63)	4,080	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2026 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2026

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648803					72-09-04		Package C	MEDIUM	REFURBISHMENT OF REMOVED SET OF PARTS	TOP CASE REPAIR OR NOT LIGHT CONDITION	20,455	SR Technics Switzerland
648803					72-09-04		Package D	HEAVY	REFURBISHMENT OF REMOVED SET OF PARTS	L FLANGE (MOD.23 TO MOD.32) COMPLETE SPLITTED	40,570	SR Technics Switzerland