



CAPABILITIES AND FIXED PRICES CATALOGUE



ENGINE PARTS REPAIR SERVICES

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

valid until December 31, 2024

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
212	340-059-815-0	EASA,FAA,CAAC,ANAC	73	35	72-23-02	FAN FRAME ASSEMBLY - FAN INLET / CONTAINMENT CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		2400.00	SR Technics Switzerland
212	340-059-816-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AD	029	RECONDITIONING OF THE ATTACHMENT HOLES ON THE FLANGE B6		4270.00	SR Technics Switzerland
212	340-059-817-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AE	040	REMOVAL OF CORROSION		1030.00	SR Technics Switzerland
212	340-059-818-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-02		Package AI	035	RECONDITIONING OF THE ATTACHMENT HOLES ON THE FLANGE A1 BY BUSHING		3685.00	SR Technics Switzerland
212	340-059-819-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AI	035	RECONDITIONING OF THE ATTACHMENT HOLES ON FLANGE A1(MOBILE MILL)		3225.00	SR Technics Switzerland
212	340-059-820-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AK	036	RECONDITIONING OF THE ATTACHMENT HOLES ON THE FLANGE A1 BY DRILLING		860.00	SR Technics Switzerland
212	340-059-821-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-02		Package AL	041	BLEND REPAIR OF LUG 87 ON FLANGE B1		1235.00	SR Technics Switzerland
212	340-059-822-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AM	042	REPAIR OF A1 FLANGE AREA G BY BLENDING		615.00	SR Technics Switzerland
212	340-059-823-0	EASA,FAA,CAAC,ANAC			72-23-02		Package AN	037	REPAIR OF FLANGES A1,B1,B2,B3,B4,B5&B6 BY BLENDING		810.00	SR Technics Switzerland
212	340-059-824-0	EASA,FAA,CAAC,ANAC			72-23-02		Package C	INSP-001	REMOVAL OF HIGHMETAL		305.00	SR Technics Switzerland
212	340-059-825-0	EASA,FAA,CAAC,ANAC			72-23-02		Package D	003	REPLACEMENT OF THE HI-LITE BOLTS AND HI-LITE NUTS		1515.00	SR Technics Switzerland
212	340-059-826-0	EASA,FAA,CAAC,ANAC			72-23-02		Package F	005	RECONDITIONING OF FAN INLET CASE SURFACE		2420.00	SR Technics Switzerland
212	340-059-827-0	EASA,FAA,CAAC,ANAC			72-23-02		Package I	008	REPLACEMENT OF THE RIVETED NUTS AND GANG CHANNEL NUTS		1515.00	SR Technics Switzerland
212	340-059-830-0	EASA,FAA,ANAC			72-23-02		Package K	010	REPLACEMENT OF THE AGB RESILIENT MOUNT DAMPER ASSEMBLIES		1385.00	SR Technics Switzerland
212	340-059-833-0	EASA,FAA,CAAC,ANAC			72-23-02		Package L	011	FULL OR PARTIAL REPAIR OF THE ABRADABLE EPOXY LINER		21815.00	SR Technics Switzerland
212	340-059-836-0	EASA,FAA,CAAC,ANAC			72-23-02		Package P	015	REPLACEMENT OF THE HANDLING BRACKETS		2515.00	SR Technics Switzerland
212	340-059-839-0	EASA,FAA,CAAC,ANAC			72-23-02		Package QI	016	FULL OR PARTIAL RECONDITIONING OF THE ANTI EROSION PAINT		5025.00	SR Technics Switzerland
212	340-059-840-0	EASA,FAA,CAAC,ANAC			72-23-02		Package SB00	72-0580	REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION		9410.00	SR Technics Switzerland
212	340-059-841-0	EASA,FAA,ANAC			72-23-02		Package SB01	72-0553	INTRODUCTION OF AN ANTI EROSION PAINT ON THE FAN FRAME ASSEMBLY		5395.00	SR Technics Switzerland
212	340-059-842-0	EASA,FAA,CAAC,ANAC			72-23-02		Package SB02	72-0730	REIDENTIFICATION OF THE CONTAINMENT CASE	340-059-813-0 AND 340-059-814-0	150.00	SR Technics Switzerland
212	340-059-846-0	EASA,FAA,CAAC,ANAC			72-23-02		Package SB03	72-0858	INSPECTION OF SUSPECT FAN CONTAINMENT CASE FOR MISSING OR MISLOCATED ANODIZATION		375.00	SR Technics Switzerland
212	340-059-847-0	EASA,FAA,CAAC,ANAC			72-23-02		Package SB04	72-0780	REWORK IN FIELD OF CONTAINMENT CASE B1 FLANGE AT HOLE 84 AND 85	REQUIRES REP-024	8160.00	SR Technics Switzerland
212					72-23-02		Package SB05	72-0829	MARK NAMEPLATE		170.00	SR Technics Switzerland
212					72-23-02		Package T	019	REPAIR OF THE ATTACHMENT HOLES ON B1, B4 AND/OR B5 FLANGES OF CONTAINMENT CASE		3570.00	SR Technics Switzerland
212					72-23-02		Package U	020	REPLACE ATTACHMENT HOLES 89A AND 89B ON B4 FLANGE		3365.00	SR Technics Switzerland
212					72-23-02		Package V	021	SPOT TOUCH-UP OF MISSING SULFURIC ANODIZING		720.00	SR Technics Switzerland
212					72-23-02		Package W	022	REMOVAL OF CORROSION IN THE RIVETED SELF LOCKING NUTS HOLES		2945.00	SR Technics Switzerland
212					72-23-02		Package X	023	REMOVAL OF CORROSION IN OGV ATTACHMENT HOLES ON CONTAINMENT CASE BY BUSHING INSTALLATION		4525.00	SR Technics Switzerland
212					72-23-02		Package Y	024	REPAIR OF FORWARD FLANGE BY REINFORCEMENT PLATE		4920.00	SR Technics Switzerland
251	336-095-401-0	EASA,FAA,CAAC,ANAC	33	28	72-55-04	LOW PRESSURE TURBINE SHAFT - REAR ROTATING AIR/OIL SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		720.00	SR Technics Switzerland
251	336-095-402-0	EASA,FAA,CAAC,ANAC			72-55-04		Package B	001	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR/OIL SEAL WHICH DIA A		2765.00	SR Technics Switzerland
251					72-55-04		Package E	004	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR SEAL WHICH ALI DIA X		1680.00	SR Technics Switzerland
251					72-55-04		Package U	INSP-001	BLENDING REAR ROTATING AIR SEAL TEETH		430.00	SR Technics Switzerland
1291	335-006-414-0	EASA,FAA,CAAC,ANAC	34	28	72-22-01	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		915.00	SR Technics Switzerland
1291	335-006-416-0	EASA,FAA,CAAC,ANAC			72-22-01		Package B	001	REPLACEMENT OF THE ALUMINIUM PAINT		3900.00	SR Technics Switzerland
1291					72-22-01		Package B	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING SHANK NUTS		3900.00	SR Technics Switzerland
1291					72-22-01		Package D	INSP-001	SPOT TOUCH UP PAINT		1200.00	SR Technics Switzerland
1291					72-22-01		Package G	006	REPAIR OF THE LPT SHAFT AFT LOCATING DIAMETER		3415.00	SR Technics Switzerland
1291					72-22-01		Package O	014	REPAIR OF THE AREA WHICH ADJUSTS THE FAN DISK ON THE FAN SHAFT	DIA C	3215.00	SR Technics Switzerland
1291					72-22-01		Package R	17	BLEND REPAIR OF THREADS		1125.00	SR Technics Switzerland
1291					72-22-01		Package SB00	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI)	IN CONJUNCTION WITH PACKAGE A	375.00	SR Technics Switzerland
1459	301-298-909-0	EASA,FAA,CAAC,ANAC,CAA UK	30	28	72-55-17	LOW PRESSURE TURBINE SHAFT - SLOTTED NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		220.00	SR Technics Switzerland
1459	337-112-901-0	EASA,FAA,CAAC,ANAC			72-55-17		Package B	001	REPAIR OF THE MATING FACE		1895.00	SR Technics Switzerland
1459					72-55-17		Package C	002	REPAIR OF THE SILVER PLATING		660.00	SR Technics Switzerland
1788			19	28	72-41-04	COMBUSTION CASE - FUEL MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
1788					72-41-04		Package B	INSP-001	PRESSURE TEST		915.00	SR Technics Switzerland
1788					72-41-04		Package D	002	REPAIR THE SILVER PLATE ON THE TUBE FITTING NUTS		445.00	SR Technics Switzerland
1879	340-047-601-0	EASA,FAA,CAAC,ANAC	4	21	72-63-09	HANDCRANKING COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		335.00	SR Technics Switzerland
1879	340-047-603-0	EASA,FAA,CAAC,ANAC			72-63-09		Package B		HANDCRANKING COVER REPLACE CABLE		110.00	SR Technics Switzerland
1879					72-63-09		Package SB00	72-A0140	INTRODUCTION OF A BONDED CAUTION PLATE ON HANDCRANKING COVER		55.00	SR Technics Switzerland
2055	336-009-801-0	EASA,FAA,CAAC,ANAC,CAA UK	28	28	72-55-14	LOW PRESSURE TURBINE SHAFT - NO.4 BEARING FORWARD ROTATING OIL SEA	Package A	CLN/INSP	CLEANING AND INSPECTION		590.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2055					72-55-14		Package B	001	RECONDITIONING OF THE 5 PERCENT NI-AL UNDERCOAT AND THE AL-SI-POLYESTER ABRADABLE COATING		2600.00	SR Technics Switzerland
2055					72-55-14		Package C	002	REPAIR OF RABBIT DIAMETER A		2200.00	SR Technics Switzerland
2055					72-55-14		Package E	004	REPAIR MATING SURFACE		2000.00	SR Technics Switzerland
2153	340-001-804-0	EASA,FAA,CAAC,ANAC	22	28	72-21-20	FAN AND BOOSTER - FAN BLADES PLATFORM	Package A		BASIC REPAIR		175.00	SR Technics Switzerland
2153	340-001-805-0	EASA,FAA,CAAC,ANAC			72-21-20		Package A	CLN/INSP	CLEANING AND INSPECTION		175.00	SR Technics Switzerland
2153	340-001-806-0	EASA,FAA,CAAC,ANAC			72-21-20		Package B		FULL REPAIR		775.00	SR Technics Switzerland
2153	340-001-809-0	EASA,FAA,CAAC,ANAC			72-21-20		Package B	003	FULL OR PARTIAL RECONDITIONING OF PROTECTIVE COATINGS		775.00	SR Technics Switzerland
2153	340-001-814-0	EASA,FAA,CAAC,ANAC			72-21-20		Package B	006	WEIGHT ADJUSTMENT OF THE FAN BLADE PLATFORM		775.00	SR Technics Switzerland
2153	340-001-816-0	EASA,FAA,CAAC,ANAC			72-21-20		Package B	007	REPAIR THE FORWARD END CONCAVE SIDE		775.00	SR Technics Switzerland
2153	340-001-817-0	EASA,FAA,CAAC,ANAC			72-21-20		Package B	008	REPAIR OF CORROSION DAMAGE		775.00	SR Technics Switzerland
2153					72-21-20		Package B	009	BLENDING REPAIR OF THE BACK SIDE CORNER OF FORWARD LUG		775.00	SR Technics Switzerland
2153					72-21-20		Package B	010	BLENDING REPAIR OF THE AFT AND CONCAVE SIDE		775.00	SR Technics Switzerland
2153					72-21-20		Package D		ADDITIONAL WORK SCOPE		430.00	SR Technics Switzerland
2153					72-21-20		Package D	002	REPLACEMENT AND BONDING OF ELASTOMER SEALS	IN CONJUNCTION WITH PACKAGES A AND B	430.00	SR Technics Switzerland
2153					72-21-20		Package SB00		ADDITIONAL WORK SCOPE		345.00	SR Technics Switzerland
2153					72-21-20		Package SB00	72-0586	INTRODUCTION OF A NEW FAN BLADE PLATFORM WITH A NEW ELASTOMER SEAL		345.00	SR Technics Switzerland
2200	1523M40G02	EASA,FAA,CAAC,ANAC	34	28	72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		550.00	SR Technics Switzerland
2200	1808M56G01	EASA,FAA,CAAC,ANAC			72-41-03		Package A	INSP-001	BLENDING SURFACE A ID		550.00	SR Technics Switzerland
2200					72-41-03		Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		340.00	SR Technics Switzerland
2200					72-41-03		Package D	003	REPLACEMENT OF HONEYCOMB SEAL		5105.00	SR Technics Switzerland
2200					72-41-03		Package E	004	INNER STATIONARY SEAL HEAT SHIELD REPLACEMENT		5105.00	SR Technics Switzerland
2200					72-41-03		Package SB03	72-1054-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	480.00	SR Technics Switzerland
2200					72-41-03		Package SB03	72-1054-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	480.00	SR Technics Switzerland
2200					72-41-03		Package SB03	72-1054-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	480.00	SR Technics Switzerland
2200					72-41-03		Package SB03	72-1054-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	480.00	SR Technics Switzerland
2586	340-079-603-0	EASA,FAA,CAAC,ANAC	25	28	72-21-23	FAN AND BOOSTER - VARIABLE BLEED VALVE GUIDE PADS	Package A	CLN/INSP	CLEANING AND INSPECTION		375.00	SR Technics Switzerland
2586	340-079-604-0	EASA,FAA,CAAC,ANAC			72-21-23		Package B	001	REPLACEMENT OF THE PTFE FRICTION PAD		440.00	SR Technics Switzerland
2586					72-21-23		Package C	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS OR SWAGED SELF-LOCKING INSERTS		345.00	SR Technics Switzerland
2591	1559M40G02	EASA,FAA,CAAC,ANAC	47	28	72-33-01	COMPRESSOR REAR STATOR - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1140.00	SR Technics Switzerland
2591	1559M40G03	EASA,FAA,CAAC,ANAC			72-33-01		Package B	INSP-001	REMOVAL OF HIGH METAL		1420.00	SR Technics Switzerland
2591					72-33-01		Package B	INSP-001	BLEND PATH PICK-UP		1420.00	SR Technics Switzerland
2591					72-33-01		Package C	002	LEADING/TRAILING EDGES	72-33-02	835.00	SR Technics Switzerland
2591					72-33-01		Package F	005	REPAIR OF DAMAGED FLOW PATH SURFACES		6780.00	SR Technics Switzerland
2591					72-33-01		Package G	006	REPAIR OF FORWARD LIP OUTER DIAMETER (DIAMETER D)		5895.00	SR Technics Switzerland
2591					72-33-01		Package J	009	REPAIR OF FLOW PATH RUB LAND CRACKS IN THE INCOLOY 909 COMPRESSOR REAR STATOR CASE		6275.00	SR Technics Switzerland
2742	340-000-410-0	EASA,FAA,CAAC,ANAC	48	28	72-21-03	FAN AND BOOSTER - FAN DISK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	4955.00	SR Technics Switzerland
2742	340-000-415-0	EASA,FAA,CAAC,ANAC			72-21-03		Package B	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS		610.00	SR Technics Switzerland
2742	340-000-420-0	EASA,FAA,CAAC,ANAC			72-21-03		Package C	SPEC PROC-001	ULTRASONIC INSPECTION	SPM 70-35-13	2100.00	SR Technics Switzerland
2742	340-000-471-0	EASA,FAA,CAAC,ANAC			72-21-03		Package D	016	REPLACEMENT OF THE CRIMPED SPACERS		470.00	SR Technics Switzerland
2742	340-000-472-0	EASA,FAA,CAAC,ANAC			72-21-03		Package M	012	BLENDING OF THE FAN DISK		4175.00	SR Technics Switzerland
2742	340-000-473-0	EASA,FAA,CAAC,ANAC			72-21-03		Package N	013	REPAIR OF THE FACE THAT MATES WITH THE SEALING FLANGE OF THE BOOSTER SPOOL		2120.00	SR Technics Switzerland
2742	340-000-474-0	EASA,FAA,CAAC,ANAC			72-21-03		Package R	017	REPAIR OF PAINT MARKING		935.00	SR Technics Switzerland
2742	340-000-475-0	EASA,FAA,CAAC,ANAC			72-21-03		Package S	018	REPAIR OF LOCKS BY PLASMA SPRAYING		4780.00	SR Technics Switzerland
2742	340-000-485-0	EASA,FAA,CAAC,ANAC			72-21-03		Package SB00	AD 2002-13-03	DISK FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE AND DOVETAIL EDDY CURRENT INSPECTION (ECI)		2170.00	SR Technics Switzerland
2742	340-000-486-0	EASA,FAA,CAAC,ANAC			72-21-03		Package SB02	72-0525	FAN DISK PRESSURE FACES INSPECTIO N		735.00	SR Technics Switzerland
2742	340-000-490-0	EASA,FAA,CAAC,ANAC			72-21-03		Package SB03	72-0534	FAN DISK FORWARD FLANGE LUG INSPECTION		480.00	SR Technics Switzerland
2742					72-21-03		Package SB04	72-0545	FAN DISK LIFE LIMIT INCREASE		560.00	SR Technics Switzerland
2742					72-21-03		Package U	020	REPAIR OF THE FAN DISK MID-LUG FORWARD MATING FACE		3215.00	SR Technics Switzerland
2882	1795M36P01	EASA,FAA,CAAC,ANAC	39	28	72-52-03	HIGH PRESSURE TURBINE ROTOR - FRONT AIR ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	3370.00	SR Technics Switzerland
2882	1795M36P02	EASA,FAA,CAAC,ANAC			72-52-03		Package B	INSP-001	REMOVAL OF HIGH METAL		190.00	SR Technics Switzerland
2882	2116M20P02	EASA,FAA,CAAC,ANAC			72-52-03		Package C	002	REPAIR OF DIAMETER R		1325.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2882	2410M50P02	EASA,FAA,CAAC,ANAC			72-52-03		Package E	001	REPLACEMENT OF SEAL TEETH COATING		4435.00	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBIT THERMAL SPRAY REPAIR	DIA B	4695.00	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA C	4695.00	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBIT THERMAL SPRAY REPAIR	DIA C	4695.00	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA B	4695.00	SR Technics Switzerland
2882					72-52-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND EDDY CURRENT INSPECTION (ECI) IN CONJUNCTION WITH PACKAGE A		570.00	SR Technics Switzerland
2882					72-52-03		Package SB02	72-1042	REPL. OF ROTATING AIR HPT FRONT SEAL PN 1795M36P02	AD EASA-2019-0146	380.00	SR Technics Switzerland
2882					72-52-03		Package SB05	72-1054-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	480.00	SR Technics Switzerland
2882					72-52-03		Package SB05	72-1054-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	480.00	SR Technics Switzerland
2882					72-52-03		Package SB06	72-EO-52905	REPLACEMENT OF AFFECTED ROTATING AIR HPT	FAA-2021-16-08	480.00	SR Technics Switzerland
3021	1853M56P06	EASA,FAA,CAAC,ANAC,CAA MALAYSIA,DGCA CI	9	21	73-21-76	MODEL CH-T1 HYDROMECHANICAL UNIT	Package G		OVERHAUL		12185.00	SR Technics Switzerland
3021	442098	EASA,FAA,CAAC,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF INDOI			73-21-76		Package SB00	73-0007	IDENTIFICATION NUMBER vin 442098 UPGRADE TO VIN 442124 TO IMPROVE MAN GEAE VIN 1853M56P06 TO 1853M56P07		3985.00	SR Technics Switzerland
3021					73-21-76		Package SB01	73-0009	INSPECTION OF HMU MAIN BODY FOR HPT2 THIN WALL CASTING		480.00	SR Technics Switzerland
3021					73-21-76		Package SB02	73-0020	INTRO IMPROVED TBV EHSV		480.00	SR Technics Switzerland
3021					73-21-76		Package SB03	73-0021	INTRO IMPR METERING VALVE RESOLVER		480.00	SR Technics Switzerland
3021					73-21-76		Package SB04	73-0022	INTRO IMPROVED BURNER STAGING VALVE		480.00	SR Technics Switzerland
3044	217780-1	EASA,FAA,ANAC	9	21	73-11-13	MAIN GEAR HOUSING ASSEMBLY	Package B		TEST AND INSPECTION		265.00	SR Technics Switzerland
3044	219822-1	EASA,FAA,ANAC			73-11-13		Package E		REPLACEMENT OF DAMAGED STUDS		920.00	SR Technics Switzerland
3044					73-11-13		Package E		REWORK MAIN GEAR HOUSING		920.00	SR Technics Switzerland
3207	338-010-103-0	EASA,FAA,CAAC,ANAC	25	28	72-53-06	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 1	Package AA	22	OVERCOATING OF APVS PROTECTION		1010.00	SRTAS
3207	338-010-104-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AB	12	AIRFLOW RESTORATION BY DIFFUSION BRAZING		3600.00	SRTAS
3207	338-010-106-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AC		BASIC REPAIR	TYPE 2	255.00	SRTAS
3207	338-010-107-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AC	INSP-001	VISUAL / DIMENSIONAL		255.00	SRTAS
3207	338-010-108-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AD		MINOR REPAIR		580.00	SRTAS
3207	338-010-203-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AD	1	AIRFOIL BLEND REPAIR		580.00	SRTAS
3207	338-010-204-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AD	5	REPAIR OF APVS COATING		580.00	SRTAS
3207	338-010-206-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AD	55	OVERCOATING OF APVS PROTECTION		580.00	SRTAS
3207	338-010-207-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AD	INSP-001	VISUAL / DIMENSIONAL		580.00	SRTAS
3207	338-010-208-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE		MEDIUM REPAIR		5505.00	SRTAS
3207	338-108-606-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE	1	AIRFOIL BLEND REPAIR		5505.00	SRTAS
3207	338-108-607-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE	27	FULL BRAZING REPAIR	CRACK REPAIR ONLY	5505.00	SRTAS
3207	338-108-608-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		5505.00	SRTAS
3207	338-108-609-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE	5	REPAIR OF APVS COATING		5505.00	SRTAS
3207	338-108-614-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AE	INSP-001	VISUAL / DIMENSIONAL		5505.00	SRTAS
3207	338-108-706-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF		FULL REPAIR		5630.00	SRTAS
3207	338-108-707-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	1	AIRFOIL BLEND REPAIR		5630.00	SRTAS
3207	338-108-708-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		5630.00	SRTAS
3207	338-108-709-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	27	FULL BRAZING REPAIR	CRACK REPAIR ONLY	5630.00	SRTAS
3207	338-108-714-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		5630.00	SRTAS
3207	340-256-251-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	5	REPAIR OF APVS COATING		5630.00	SRTAS
3207	340-256-252-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AF	INSP-001	VISUAL / DIMENSIONAL		5630.00	SRTAS
3207	340-256-254-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AG	22	OVERCOATING OF APVS PROTECTION		1010.00	SRTAS
3207	340-256-351-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AH		GLOBAL AIRFLOW REPAIR BY DICA		9785.00	SRTAS
3207	340-256-352-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AI	12	AIRFLOW RESTORATION BY DIFFUSION BRAZING		3600.00	SRTAS
3207	340-256-354-0	EASA,FAA,CAAC,ANAC			72-53-06		Package AI		BASIC REPAIR	TYPE 3	255.00	SRTAS
3207					72-53-06		Package AJ	INSP-001	VISUAL / DIMENSIONAL		255.00	SRTAS
3207					72-53-06		Package AK		MINOR REPAIR		580.00	SRTAS
3207					72-53-06		Package AK	5	REPAIR OF APVS COATING		580.00	SRTAS
3207					72-53-06		Package AK	55	OVERCOATING OF APVS PROTECTION		580.00	SRTAS
3207					72-53-06		Package AK	INSP-001	VISUAL / DIMENSIONAL		580.00	SRTAS
3207					72-53-06		Package AL		MEDIUM REPAIR		5505.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3207					72-53-06		Package AL	1	AIRFOIL BLEND REPAIR		5505.00	SRTAS
3207					72-53-06		Package AL	27	FULL BRAZING REPAIR	CRACK REPAIR ONLY	5505.00	SRTAS
3207					72-53-06		Package AL	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		5505.00	SRTAS
3207					72-53-06		Package AL	5	REPAIR OF APVS COATING		5505.00	SRTAS
3207					72-53-06		Package AL	INSP-001	VISUAL / DIMENSIONAL		5505.00	SRTAS
3207					72-53-06		Package AM		FULL REPAIR		5630.00	SRTAS
3207					72-53-06		Package AM	1	AIRFOIL BLEND REPAIR		5630.00	SRTAS
3207					72-53-06		Package AM	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		5630.00	SRTAS
3207					72-53-06		Package AM	27	FULL BRAZING REPAIR	INCLUDING ANY COMBINATION OF ASPECT	5630.00	SRTAS
3207					72-53-06		Package AM	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		5630.00	SRTAS
3207					72-53-06		Package AM	5	REPAIR OF APVS COATING		5630.00	SRTAS
3207					72-53-06		Package AM	INSP-001	VISUAL / DIMENSIONAL		5630.00	SRTAS
3207					72-53-06		Package AN	22	OVERCOATING OF APVS PROTECTION		1010.00	SRTAS
3207					72-53-06		Package AO	12	AIRFLOW RESTORATION BY DIFFUSION BRAZING		3600.00	SRTAS
3207					72-53-06		Package SB00		GLOBAL AIRFLOW REPAIR BY DICA		9785.00	SRTAS
3207					72-53-06		Package V		BASIC REPAIR	TYPE 1	255.00	SRTAS
3207					72-53-06		Package V	INSP-001	VISUAL / DIMENSIONAL		255.00	SRTAS
3207					72-53-06		Package W		MINOR REPAIR		580.00	SRTAS
3207					72-53-06		Package W	1	AIRFOIL BLEND REPAIR		580.00	SRTAS
3207					72-53-06		Package W	5	REPAIR OF APVS COATING		580.00	SRTAS
3207					72-53-06		Package W	55	OVERCOATING OF APVS PROTECTION		580.00	SRTAS
3207					72-53-06		Package W	INSP-001	VISUAL / DIMENSIONAL		580.00	SRTAS
3207					72-53-06		Package X		MEDIUM REPAIR		5505.00	SRTAS
3207					72-53-06		Package X	1	AIRFOIL BLEND REPAIR		5505.00	SRTAS
3207					72-53-06		Package X	17	FULL BRAZING REPAIR		5505.00	SRTAS
3207					72-53-06		Package X	5	REPAIR OF APVS COATING		5505.00	SRTAS
3207					72-53-06		Package X	INSP-001	VISUAL / DIMENSIONAL		5505.00	SRTAS
3207					72-53-06		Package Y		FULL REPAIR		5630.00	SRTAS
3207					72-53-06		Package Y	1	AIRFOIL BLEND REPAIR		5630.00	SRTAS
3207					72-53-06		Package Y	17	FULL BRAZING REPAIR		5630.00	SRTAS
3207					72-53-06		Package Y	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		5630.00	SRTAS
3207					72-53-06		Package Y	5	REPAIR OF APVS COATING		5630.00	SRTAS
3207					72-53-06		Package Y	INSP-001	VISUAL / DIMENSIONAL		5630.00	SRTAS
3207					72-53-06		Package Z		ADDITIONAL WORKSCOPE		740.00	SRTAS
3207					72-53-06		Package Z	72-0229	NEW PART RELEASE OR REWORK OLD PART. EDM HOLES IN AFT FLANGE & SEALING PLATES		740.00	SRTAS
3302	340-091-804-0	EASA,FAA,CAAC,ANAC	24	28	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - HOUSING-PROBE	Package A	CLN/INSP	CLEANING AND INSPECTION		235.00	SR Technics Switzerland
3302	340-091-805-0	EASA,FAA,CAAC,ANAC			72-09-04		Package C	002	REPLACE INSERTS PROBE HOUSING		370.00	SR Technics Switzerland
3302	340-091-806-0	EASA,FAA,CAAC,ANAC			72-09-04		Package SB00	72-0298	INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS OR REWORK OF THE OLD ONE		950.00	SR Technics Switzerland
3473	336-024-704-0	EASA,FAA,CAAC,ANAC	45	28	72-56-06	LOW PRESSURE TURBINE REAR FRAME - OIL INLET COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		1585.00	SR Technics Switzerland
3473	336-024-705-0	EASA,FAA,CAAC,ANAC			72-56-06		Package B	001	REPLACEMENT OF THE COATED RING OR REPLACEMENT OF THE ORIGINAL COATING BY A COATED RING		4670.00	SR Technics Switzerland
3473	336-024-706-0	EASA,FAA,CAAC,ANAC			72-56-06		Package C	002	REPAIR OF THE CRIMPED SELF LOCKING NUTS		805.00	SR Technics Switzerland
3473	336-024-707-0	EASA,FAA,CAAC,ANAC			72-56-06		Package E	004	REPAIR OF SEAL TEETH BY WELD UP		2760.00	SR Technics Switzerland
3473	336-024-708-0	EASA,FAA,CAAC,ANAC			72-56-06		Package G	006	REMOVE DEFECTS FROM REAR CONTACT FACE		665.00	SR Technics Switzerland
3473					72-56-06		Package SB00	72-0221	INTRODUCTION OF NEW OIL INLET COVER ASSY		1135.00	SR Technics Switzerland
3473					72-56-06		Package SB01	79-0017	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1135.00	SR Technics Switzerland
3643	340-001-108-0	EASA,FAA,CAAC,ANAC	28	28	72-21-18	FAN AND BOOSTER - FAN RETAINING FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		265.00	SR Technics Switzerland
3643	340-001-110-0	EASA,FAA,CAAC,ANAC			72-21-18		Package C	002	REPAIR OF THE MATING FACE		2075.00	SR Technics Switzerland
3643	340-001-111-0	EASA,FAA,CAAC,ANAC			72-21-18		Package SB00	72-0366	REPLACEMENT OF THE FAN RETAINING FLANGE OR REWORK OF THE OLD ONE		3285.00	SR Technics Switzerland
3643					72-21-18		Package SB01	72-0318	APPLICATION OF ROOM TEMPERATURE VULCANIZING (RTV) ON THE FAN BLADE RETAINING FLANGE		630.00	SR Technics Switzerland
3975	1358M80P04	EASA,FAA,CAAC,ANAC	27	28	72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SEAL RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		475.00	SR Technics Switzerland
3975					72-51-10		Package B	001	REPAIR WEAR ON THE HPT NOZZLE EXTERNAL PRESSURE SEAL RETAINER		3400.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
7808	301-546-107-0	EASA,FAA,CAAC,ANAC	24	28	72-55-16	LOW PRESSURE TURBINE SHAFT - PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		340.00	SR Technics Switzerland
7808	337-124-601-0	EASA,FAA,CAAC,ANAC			72-55-16		Package B	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAFT BY PLASMA S DIA A		1505.00	SR Technics Switzerland
7808	337-124-620-0	EASA,FAA,CAAC,ANAC			72-55-16		Package C	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAFT BY PLASMA S DIA B		1505.00	SR Technics Switzerland
7808	338-072-102-0	EASA,FAA,CAAC,ANAC			72-55-16		Package D	002	RECONDITIONING OF THE INNER LOCATING DIAMETER (DIA C) WITH THE CENTER VENT TUBE BY PLASMA SPRAYING		1510.00	SR Technics Switzerland
7808	338-072-103-0	EASA,FAA,CAAC,ANAC			72-55-16		Package E	003	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		1085.00	SR Technics Switzerland
7808	340-310-501-0	EASA,FAA,CAAC,ANAC			72-55-16		Package F	004	CLEANING AND PACKAGING		205.00	SR Technics Switzerland
8521	1358M35G02	EASA,FAA,CAAC,ANAC	33	28	72-51-08	HIGH PRESSURE TURBINE NOZZLE - AFT INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		995.00	SR Technics Switzerland
8521	1522M46G02	EASA,FAA,CAAC,ANAC			72-51-08		Package B	003	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY	WASPALLOY CONFIGURATION	6445.00	SR Technics Switzerland
8521					72-51-08		Package B	004	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY		6445.00	SR Technics Switzerland
8521					72-51-08		Package C	001	REPAIR FOR THE HPT AFT INNER NOZZLE SUPPORT PIN REPLACEMENT		1830.00	SR Technics Switzerland
8527	301-297-812-0	EASA,FAA,CAAC,ANAC	7	28	72-22-12	CFM56 NO.1 BEARING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		735.00	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLECTOR AND OPPI AREA G		1100.00	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLECTOR AND OPPI AREA L		1100.00	SR Technics Switzerland
8881	310A2033-3	EASA,FAA,CAAC,ANAC	23	21	71-21-37	AFT ENGINE MOUNT - LEFT LINK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		940.00	SR Technics Switzerland
8881	310A2033-5	EASA,FAA,CAAC,ANAC			71-21-37		Package B	9-1	BEARING REPLACEMENT	FOR P/N 310A2033-3	660.00	SR Technics Switzerland
8881	310A2033-7	EASA,FAA,CAAC,ANAC			71-21-37		Package B	9-3	BEARING REPLACEMENT	FOR P/N 310A2033-5	660.00	SR Technics Switzerland
8881	310A2033-8	EASA,FAA,CAAC,ANAC			71-21-37		Package B	9-5	BEARING REPLACEMENT	FOR P/N 310A2033-7, -8	660.00	SR Technics Switzerland
8881					71-21-37		Package D	SRM 54-70-90	ENGINE BLEND THRUST-LINK		380.00	SR Technics Switzerland
8891	310A2034-13	EASA,FAA,CAAC,ANAC	22	21	71-21-37	AFT ENGINE MOUNT - CENTER LINK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		980.00	SR Technics Switzerland
8891	310A2034-14	EASA,FAA,CAAC,ANAC			71-21-37		Package B	10-1	BEARING REPLACEMENT	FOR P/N 310A2034-3	760.00	SR Technics Switzerland
8891	310A2034-3	EASA,FAA,CAAC,ANAC			71-21-37		Package B	10-3	BEARING REPLACEMENT	FOR P/N 310A2034-7, -8, -13, -14	760.00	SR Technics Switzerland
8891	310A2034-7	EASA,FAA,CAAC,ANAC			71-21-37		Package C	SRM 54-70-90	ALLOWABLE DAMAGE 12 BLENDING		380.00	SR Technics Switzerland
8891	310A2034-8	EASA,FAA,CAAC,ANAC			71-21-37		Package SB00	737-71A1462	AFT ENGINE MOUNT, LINK ASSEMBLY, HANGER FITTING, INSPECTION, CORRECTION AND IDENTIFICATION OF PARTS		330.00	SR Technics Switzerland
8897	310A2035-3	EASA,FAA,CAAC,ANAC	22	21	71-21-37	AFT ENGINE MOUNT - RIGHT LINK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		980.00	SR Technics Switzerland
8897	310A2035-5	EASA,FAA,CAAC,ANAC			71-21-37		Package B	11-1	BEARING REPLACEMENT	FOR P/N 310A2035-3	885.00	SR Technics Switzerland
8897	310A2035-7	EASA,FAA,CAAC,ANAC			71-21-37		Package B	11-3	BEARING REPLACEMENT	FOR P/N 310A2035-5	885.00	SR Technics Switzerland
8897	310A2035-8	EASA,FAA,CAAC,ANAC			71-21-37		Package B	11-5	BEARING REPLACEMENT	FOR P/N 310A2035-7, -8	885.00	SR Technics Switzerland
8897					71-21-37		Package D	SRM 54-70-90	ENGINE BLEND THRUST-LINK		700.00	SR Technics Switzerland
9941	340-059-917-0	EASA,FAA,CAAC,ANAC	53	28	72-23-31	FAN FRAME ASSEMBLY - FAN FRAME SHROUD	Package A	CLN/INSP	CLEANING AND INSPECTION		3800.00	SR Technics Switzerland
9941	340-059-918-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AA	50	BUSHING OF THE FAN FRAME STRUTS ATTACHMENT HOLES		8030.00	SR Technics Switzerland
9941	340-059-921-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AB	42	REPAIR OF HOLES FLANGE B7		4985.00	SR Technics Switzerland
9941	340-059-923-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AC	43	REMOVAL OF CORROSION IN THE RIVETED SELF LOCKING NUTS HOLES		3145.00	SR Technics Switzerland
9941	340-059-925-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AD	29	REPLACEMENT OF THE HI-LITE BOLTS AND HI-LITE NUTS		525.00	SR Technics Switzerland
9941	340-059-926-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AL	53	REPL. OF WEAR STRIPS IN V-GROOVE		4720.00	SR Technics Switzerland
9941	340-059-927-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AM	52	REMOVE CORROSION IN STRUT FAIRING ATTACHMENT HOLES		3145.00	SR Technics Switzerland
9941	340-059-928-0	EASA,FAA,CAAC,ANAC			72-23-31		Package AN	51	APPLICATION LUBRICANT VARNISH ON V-GROOVE		820.00	SR Technics Switzerland
9941	340-059-929-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-31		Package AN	51	REPLACE LUBRICANT VARNISH ON V-GROOVE		820.00	SR Technics Switzerland
9941	340-059-930-0	EASA,FAA,CAAC,ANAC			72-23-31		Package B	INSP-001	CASE V-GROOVE SEAL TOUCH UP		1270.00	SR Technics Switzerland
9941	340-059-931-0	EASA,FAA,CAAC,ANAC			72-23-31		Package B	INSP-001	REMOVAL OF HIGH METAL		1270.00	SR Technics Switzerland
9941	340-059-932-0	EASA,FAA,CAAC,ANAC			72-23-31		Package B	INSP-001	CASE INNER/OUTER TOUCH UP		1270.00	SR Technics Switzerland
9941	340-059-933-0	EASA,FAA,CAAC,ANAC			72-23-31		Package C	1	REPLACEMENT OF THE RIVETED SELF LOCKING NUTS, ANGLE PLATE, BOSS, FITTING, BRACKET, AND COVER PLATES		2520.00	SR Technics Switzerland
9941	340-059-934-0	EASA,FAA,CAAC,ANAC			72-23-31		Package D	2	SPOT TOUCH UP MISSING ANODIZING		695.00	SR Technics Switzerland
9941	340-059-935-0	EASA,FAA,CAAC,ANAC			72-23-31		Package E	3	REPLACEMENT OF THE KEY-LOCKED INSERTS		1385.00	SR Technics Switzerland
9941	340-059-936-0	EASA,FAA,CAAC,ANAC			72-23-31		Package F	4	REPLACEMENT OF BUSHING		1385.00	SR Technics Switzerland
9941	340-059-937-0	EASA,FAA,CAAC,ANAC			72-23-31		Package G	5	REPAIR OF THE FAN FRAME SHROUD BY TIG WELDING		14720.00	SR Technics Switzerland
9941	340-059-938-0	EASA,FAA,CAAC,ANAC			72-23-31		Package H	7	REPAIR OF ENGINE HANDLING BOSSES		865.00	SR Technics Switzerland
9941	340-059-939-0	EASA,FAA,CAAC,ANAC			72-23-31		Package I	8	REPAIR OF IDG COOLER INNER SKIN AREAS		1130.00	SR Technics Switzerland
9941	340-059-940-0	EASA,FAA,CAAC,ANAC			72-23-31		Package P	15	REPAIR OF THE FAN FRAME SHROUD MATING SURFACE WITH CONTAINMENT CASE		3495.00	SR Technics Switzerland
9941	340-059-941-0	EASA,FAA,CAAC,ANAC			72-23-31		Package Q	16	REMOVE CORROSION FROM STRUT		1355.00	SR Technics Switzerland
9941	340-059-942-0	EASA,FAA,CAAC,ANAC			72-23-31		Package S	18	REAM IDG COOLER ATTACHEMENT HOLES		1900.00	SR Technics Switzerland
9941	340-059-943-0	EASA,FAA,CAAC,ANAC			72-23-31		Package S	18	BUSHING REPAIR IDG COOLER ATTACHEMENT HOLES		1900.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
9941	340-059-944-0	EASA,FAA,CAAC,ANAC			72-23-31		Package SB00	72-0440	IDG AIR/OIL COOLEER ACOUSTICAL PANLE REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD		820.00	SR Technics Switzerland
9941					72-23-31		Package SB01	72-0495	REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINIUM DOUBLER		7780.00	SR Technics Switzerland
9941					72-23-31		Package SB02	72-0531	NEW INSPECTION OF FAN FRAME SHROUD		2520.00	SR Technics Switzerland
9941					72-23-31		Package SB03	72-0512	INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLE PA OF THE PREVIOUS CONFIGURATION		2520.00	SR Technics Switzerland
9941					72-23-31		Package SB04	72-0975	WEAR STRIP REWORK OF THE FAN FRAME SHROUD		6845.00	SR Technics Switzerland
9941					72-23-31		Package SB05	72-0996	APPLICATION OF PTFE LUBRICANT VARNISH ON V-GROOVE OUTER RING		755.00	SR Technics Switzerland
9941					72-23-31		Package SB06		ENGINE IDENTIFICATION PLATE RTV106 SEALANT APPLICATION		165.00	SR Technics Switzerland
9941					72-23-31		Package U	44	REPAIR OF THE CORROSIN IN ACOUSTIC PANELS BOLT HOLES BY BUSHING		5210.00	SR Technics Switzerland
9941					72-23-31		Package V	45	BLEND REPAIR OF WEARS		490.00	SR Technics Switzerland
9941					72-23-31		Package W	46	RECONDITIONING OF THE ATTACHMENT HOLES ON THE FLANG B6		5525.00	SR Technics Switzerland
9941					72-23-31		Package X	47	COLD REFORMING REPAIR OF THE FAN FRAME SHROUD AFT LIP		2765.00	SR Technics Switzerland
9941					72-23-31		Package Y	48	BLEND REPAIR OF THE FAN FRAME SHROUD AFT LIP		1080.00	SR Technics Switzerland
9941					72-23-31		Package Z	49	REMOVAL OF CORROSION UNDER THE ANCHOR NUTS OF THE FAN FRAME SHROUD OUTER SKIN		1225.00	SR Technics Switzerland
13445	340-050-201-0	EASA,FAA,CAAC,ANAC	6	28	72-23-06	CFM56-7B TGB INNER RADIAL DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		340.00	SR Technics Switzerland
13445	340-050-202-0	EASA,FAA,CAAC,ANAC			72-23-06		Package SB00	SB 72-0291	INSP/RWK OUTER RADIAL DRIVE SHAFT - TGB		155.00	SR Technics Switzerland
15175	2616M78G01	EASA,FAA,CAAC,ANAC	44	28	72-31-11	COMPRESSOR ROTOR - AIR DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		815.00	SR Technics Switzerland
15175	9514M54G05	EASA,FAA,CAAC,ANAC			72-31-11		Package C	002	REPAIR ILLEGIBLE PART IDENTIFICATION NUMBERS		175.00	SR Technics Switzerland
15175					72-31-11		Package G	006	REPLACEMENT OF COMPRESSOR ROTOR AIR DUCT SLEEVE		3070.00	SR Technics Switzerland
16715	1559M30G05	EASA,FAA,CAAC,ANAC	81	28	72-32-01	COMPRESSOR FRONT STATOR - CASE	Package A	ASSEMBLY-001	RE-MEASURE FLOW PATH		3270.00	SR Technics Switzerland
16715	1559M30G06	EASA,FAA,CAAC,ANAC			72-32-01		Package A	CLN/INSP	CLEANING AND INSPECTION		3270.00	SR Technics Switzerland
16715	1559M30G09	EASA,FAA,CAAC,ANAC			72-32-01		Package AB	027	REPAIR OF THE AFT FLANGE PITTING AND CORROSION		5885.00	SR Technics Switzerland
16715	1559M30G10	EASA,FAA,CAAC,ANAC			72-32-01		Package AD	029	WEAR REPAIR ON THE BELLCRANK FORWARD BOSS OF THE VARIABLE STATOR VANE		5000.00	SR Technics Switzerland
16715	1559M30G11	EASA,FAA,CAAC,ANAC			72-32-01		Package AG	032	BLEND CORROSION/PITTING NON-FLOWPATH AREA		1210.00	SR Technics Switzerland
16715	1559M30G12	EASA,FAA,CAAC,ANAC			72-32-01		Package AH	033	ONLY COATING IN THE FWD FLANGE BOLTHOLES		6445.00	SR Technics Switzerland
16715	1559M30G13	EASA,FAA,CAAC,ANAC			72-32-01		Package AJ	035	WELD REPAIR MID FLANGE BOLT HOLES AND FACES		2420.00	SR Technics Switzerland
16715	1559M30G14	EASA,FAA,CAAC,ANAC			72-32-01		Package AK		MEASURE NEW - / OVHLD PARTS		175.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH	ATA 72-00-32	2100.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND CASE SURFACE		2100.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH PICKUP		2100.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND HOT SPOTS		2100.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLENDING FLOW, NICKS, ETC.		2100.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	REMOVE CORROSION BY BLEND		2100.00	SR Technics Switzerland
16715					72-32-01		Package B	SPM	REMOVE BROKEN BOLTS		2100.00	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS		3105.00	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS	RETAP THREADS	3105.00	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABDET DIAMETERS OF THE COMPRESSOR FRONT DIA C		3615.00	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABDET DIAMETERS OF THE COMPRESSOR FRONT DIA B		3615.00	SR Technics Switzerland
16715					72-32-01		Package G	002	LEADING/TRAILING EDGES	72-32-03	835.00	SR Technics Switzerland
16715					72-32-01		Package M	012	TEMPERATURE HEAT TREAT REPAIR		6535.00	SR Technics Switzerland
16715					72-32-01		Package O	014	REPAIR OF THREADED BOSSES AND PADS		2145.00	SR Technics Switzerland
16715					72-32-01		Package P	015	FLOW PATH REPAIR		11210.00	SR Technics Switzerland
16715					72-32-01		Package Q	016	WELD REPAIR OF LINEAR INDICATIONS AT THE HORIZONTAL SPLIT LINE		8405.00	SR Technics Switzerland
16715					72-32-01		Package Q	016	CRACK WELDING REPAIR OF STATOR CASE		8405.00	SR Technics Switzerland
16715					72-32-01		Package R	017	INTRGRAL PILOT BRACKET (IPB) DIAMETER D REPAIR	DIA D	8025.00	SR Technics Switzerland
16715					72-32-01		Package V	021	REAMING OF THE AFT FLANGE BOLT HOLES		11285.00	SR Technics Switzerland
16715					72-32-01		Package X	023	WELD REPAIR OF LINEAR INDICATIONS AT SPLITLINE BOLT HOLES AND BUSHING HOLES		11075.00	SR Technics Switzerland
18900	305-025-408-0	EASA,FAA,CAAC,ANAC	51	28	72-55-15	LOW PRESSURE TURBINE SHAFT - AIR/OIL SEPARATOR AND COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		470.00	SR Technics Switzerland
18900	305-044-506-0	EASA,FAA,CAAC,ANAC			72-55-15		Package B	001	TOUCH-UP OF THE SURFACE PROTECTION ON THE AIR/OIL SEPARATOR		555.00	SR Technics Switzerland
18900	337-108-502-0	EASA,FAA,CAAC,ANAC			72-55-15		Package C	002	TOUCHUP OF SURFACE PROTECTION ON AIR/OIL SEPARATOR COVER		885.00	SR Technics Switzerland
18900	337-108-510-0	EASA,FAA,CAAC,ANAC,CAA UK			72-55-15		Package D	003	AIR/OIL SEPARATOR AND COVER REPAIR		2025.00	SR Technics Switzerland
18900	337-108-520-0	EASA,FAA,CAAC,ANAC,CAA UK			72-55-15		Package E	004	REPAIR OF THE LOCATING DIAMETER WITH LPT SHAFT		3600.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
18900	337-108-551-0	EASA,FAA,CAAC,ANAC			72-55-15		Package F	005	REPAIR OF THE LOCATING DIAMETER (DIA C) ON THE AIR/OIL SEPARATOR BY PLASMA SPRAYING		1520.00	SR Technics Switzerland
18900					72-55-15		Package G	006	REPAIR OF THREE WELD BEADS ON AIR/OIL SEPARATOR		1145.00	SR Technics Switzerland
18900					72-55-15		Package H	007	REPLACEMENT OF THE COVER OF THE AIR/OIL SEPARATOR		1295.00	SR Technics Switzerland
18900					72-55-15		Package I	008	FINAL CLEANING AND PACKAGING OF THE AIR/OIL SEPARATOR		170.00	SR Technics Switzerland
18900					72-55-15		Package SB00	72-0897	REPETITIVE REPAIR OF THE AIR OIL SEPARATOR		1065.00	SR Technics Switzerland
18900					72-55-15		Package SB01	72-0904	INTRODUCTION OF A NEW AIR/OIL SEPARATOR AND REWORK OF THE OLD ONE		1200.00	SR Technics Switzerland
18900					72-55-15		Package SB04	72-0971	REPETITIVE REPAIR OF THE 6 AIR/OIL SEPARATOR WELD BEADS IN SHOP		1200.00	SR Technics Switzerland
21511	1558M31G03	EASA,FAA,CAAC,ANAC	49	28	72-31-04	COMPRESSOR ROTOR - SPOOL	Package A	CLN/INSP	CLEANING, FLUORESCENT PENETRANT INSPECTION (FPI) AND INSPECTION		2285.00	SR Technics Switzerland
21511	1558M31G04	EASA,FAA,CAAC,ANAC			72-31-04		Package B	INSP-001	BLENDING FWD SEAL DIA DZ		2275.00	SR Technics Switzerland
21511	1558M31G05	EASA,FAA,CAAC,ANAC			72-31-04		Package B	INSP-001	BLENDING RETAINER HOOKS		2275.00	SR Technics Switzerland
21511	1558M31G07	EASA,FAA,CAAC,ANAC			72-31-04		Package B	INSP-001	BLENDING STAGE 1 AREA M		2275.00	SR Technics Switzerland
21511	1834M5SG01	EASA,FAA,CAAC,ANAC			72-31-04		Package B	INSP-001	REMOVAL OF HIGHMETAL		2275.00	SR Technics Switzerland
21511					72-31-04		Package C	002	REPAIR OF ILLEGIBLE PART MARKINGS		110.00	SR Technics Switzerland
21511					72-31-04		Package E	004	REPAIR DIAMETER B		4205.00	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA E	6290.00	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA F	6290.00	SR Technics Switzerland
21511					72-31-04		Package G	006	APPLICATION OF MOLYDAG 254 COATING ON STAGES 1 AND 2 DOVETAILS		3050.00	SR Technics Switzerland
21511					72-31-04		Package H	007	REPAIR OF FRETTED SURFACE G		5255.00	SR Technics Switzerland
21511					72-31-04		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)		1460.00	SR Technics Switzerland
21512	1590M59P01	EASA,FAA,CAAC,ANAC	39	28	72-31-05	COMPRESSOR ROTOR - DISK STAGE 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1490.00	SR Technics Switzerland
21512	2116M23P01	EASA,FAA,CAAC,ANAC			72-31-05		Package B	INSP-001	DISK BLENDING PAD AREA E		790.00	SR Technics Switzerland
21512	9940M55P18	EASA,FAA,CAAC,ANAC			72-31-05		Package C	002	REPAIR OF THE RABBIT DIAMETERS		4050.00	SR Technics Switzerland
21512					72-31-05		Package L	INSP-001	REMOVE HIGHMETAL		790.00	SR Technics Switzerland
21512					72-31-05		Package M	INSP-001	DISK BLEND RETAINER HOOK		790.00	SR Technics Switzerland
21512					72-31-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	850.00	SR Technics Switzerland
24630	336-026-101-0	EASA,FAA,CAAC,ANAC	20	28	72-53-09	STAGE 1 LPT NOZZLE - BORESCOPE PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		190.00	SR Technics Switzerland
24630					72-53-09		Package B	INSP-001	BLENDING THREAD HIGH METAL		415.00	SR Technics Switzerland
44969	9531M11G02	EASA,FAA,CAAC,ANAC	22	28	72-42-01	COMBUSTION CHAMBER (SAC) - INNER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		905.00	SR Technics Switzerland
44969					72-42-01		Package C	002	WELD REPAIR AND RESIZING OF THE INNER COWL		1460.00	SR Technics Switzerland
64526	335-192-202-0	EASA,FAA,CAAC,ANAC	41	28	72-21-09	FAN AND BOOSTER - BOOSTER VANE ASSMELBY, STAGE 1 - 4	Package A	CLN/INSP	CLEANING AND INSPECTION		810.00	SR Technics Switzerland
64526	340-001-307-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AM	038	PLASMA SPRAY OF STAGE 4 INNER SHROUD AFT FACE		3145.00	SR Technics Switzerland
64526	340-001-308-0	EASA,FAA,CAAC,ANAC			72-21-09		Package B	INSP-001	REMOVE OXIDATION / CORROSION		1335.00	SR Technics Switzerland
64526	340-058-302-0	EASA,FAA,CAAC,ANAC			72-21-09		Package C	001	BLEND REPAIR OF THE VANE AIRFOILS		1355.00	SR Technics Switzerland
64526	340-058-402-0	EASA,FAA,CAAC,ANAC			72-21-09		Package D	003	REPAIR ABRADABLE COATING IN THE OUTER SHROUD OF THE BOOSTER IGV AND STG. 3 AND 4 VANE ASSEMBLIES		4395.00	SR Technics Switzerland
64526	340-058-403-0	EASA,FAA,CAAC,ANAC			72-21-09		Package E	004	REPLACEMENT OF THE RIVETED SELF LOCKING NUTS		645.00	SR Technics Switzerland
64526	340-058-404-0	EASA,FAA,CAAC,ANAC			72-21-09		Package F	002	REPLACEMENT OF THE ABRADABLE COATING ON THE INNER SHROUDS		3275.00	SR Technics Switzerland
64526					72-21-09		Package QI	060	REMOVAL OF CORROSION ON OUTER SHROUD		2395.00	SR Technics Switzerland
64526					72-21-09		Package SB00	72-0454	ANTI CORROSION PAINT		4880.00	SR Technics Switzerland
72531	9523M11G03	EASA,FAA,CAAC,ANAC	9	28	72-31-09	CFM56 COMPRESSOR ROTOR BLADE RETAINERS	Package A	CLN/INSP	CLEANING AND INSPECTION		360.00	SR Technics Switzerland
72531	9523M12G01	EASA,FAA,CAAC,ANAC			72-31-09		Package B	INSP-001	BLENDING		290.00	SR Technics Switzerland
135131	1324M04P03	EASA,FAA,CAAC,ANAC	16	21	73-21-77	FUEL - HPTCC THERMOCOUPLE	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	855.00	SR Technics Switzerland
135131	8TC19AAH1	EASA,FAA,CAAC,ANAC			73-21-77		Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE REPAIR	145.00	SR Technics Switzerland
138562	310A2031-22	EASA,FAA,CAAC,ANAC	26	21	71-21-37	AFT ENGINE MOUNT - HANGER ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		930.00	SR Technics Switzerland
138562	310A2031-24	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package B	6-1	BUSHING REPLACEMENT	FOR P/N 310A2031-9	1755.00	SR Technics Switzerland
138562	310A2031-26	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package D	SRM 54-70-90	BLENDING HANGER DAMAGES		1560.00	SR Technics Switzerland
138562	310A2031-9	EASA,FAA,CAAC,ANAC			71-21-37		Package F	6-3	BUSHING REPLACEMENT	FOR P/N 310A2031-22, -24	1050.00	SR Technics Switzerland
138562					71-21-37		Package SB00	737-71A1462	AFT ENGINE MOUNT, LINK ASSEMBLY, HANGER FITTING, INSPECTION, CORRECTION AND IDENTIFICATION OF PARTS		155.00	SR Technics Switzerland
138566	310A2036-5	EASA,FAA,CAAC,CAAC,ANAC	21	21	71-21-37	AFT ENGINE MOUNT - BAR ASSY EVENER	Package A	CLN/INSP	CLEANING AND INSPECTION		940.00	SR Technics Switzerland
138566	310A2036-8	EASA,FAA,CAAC,CAAC,CAA UK			71-21-37		Package B	7-1	BEARING REPLACEMENT	FOR P/N 310A2036-5	1095.00	SR Technics Switzerland
138566					71-21-37		Package C	7-3	BEARING REPLACEMENT	FOR P/N 310A2036-8	1335.00	SR Technics Switzerland
138566					71-21-37		Package D	7-2	BORE REPAIR	FOR P/N 310A2036-6	1255.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138566					71-21-37		Package F	7-4	BORE REPAIR	FOR P/N 310A2036-9	1055.00	SR Technics Switzerland
138950	1559M27G01	EASA,FAA,CAAC,ANAC	10	28	72-32-05	CFM-56 SEAL-STATIONARY ASSY STG 4-5	Package A		BASIC REPAIR	STG 4/5	100.00	SRTAS
138950	1559M27G02	EASA,FAA,CAAC,ANAC			72-32-05		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		100.00	SRTAS
138950	1559M27G06	EASA,FAA,CAAC,ANAC			72-32-05		Package B		FULL REPAIR	STG 4/5	405.00	SRTAS
138950					72-32-05		Package B	2	HONEYCOMB REPLACEMENT		405.00	SRTAS
138952	1559M27G03	EASA,FAA,CAAC,ANAC	10	28	72-33-03	CFM56 COMPR.REAR STAT.SEAL STG.6-8	Package A		BASIC REPAIR	STG 6/7/8	130.00	SRTAS
138952	1559M27G04	EASA,FAA,CAAC,ANAC			72-33-03		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		130.00	SRTAS
138952					72-33-03		Package B		BASIC REPAIR	STG 6/7/8	350.00	SRTAS
138952					72-33-03		Package B	1	HONEYCOMB REPLACEMENT		350.00	SRTAS
138952					72-33-03		Package D		FULL REPAIR	STG 7	350.00	SRTAS
138952					72-33-03		Package D	1	HONEYCOMB REPLACEMENT		350.00	SRTAS
138952					72-33-03		Package F		FULL REPAIR	STG 8	350.00	SRTAS
138952					72-33-03		Package F	1	HONEYCOMB REPLACEMENT		350.00	SRTAS
138955	1275M27P04	EASA,FAA,CAAC,ANAC	16	28	72-42-02	COMBUSTION CHAMBER - PRIMARY SWIRL NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		55.00	SR Technics Switzerland
138955					72-42-02		Package C	02	PRIMARY SWIRL NOZZLE REPAIR		170.00	SR Technics Switzerland
138955					72-42-02		Package D	03	WELD ANTI-ROTATION TANG		120.00	SR Technics Switzerland
138977	9972M46G05	EASA,FAA,CAAC,ANAC	23	28	72-61-05	INLET GEARBOX & NO.3 BEARING - BEARING NO.3 LOCKING NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		990.00	SR Technics Switzerland
138977					72-61-05		Package C	002	REPAIR OF DAMAGED WRENCH SLOTS		1035.00	SR Technics Switzerland
138977					72-61-05		Package D	003	REPLACEMENT OF FIBER WASHER		780.00	SR Technics Switzerland
138977					72-61-05		Package E	004	REPAIR 004 - REPAIR OF 4.6875-12 OR 5.300-16 THREADS		840.00	SR Technics Switzerland
138977					72-61-05		Package F	005	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		750.00	SR Technics Switzerland
138977					72-61-05		Package G	006	REPAIR OF GALLING ON DIA B		1555.00	SR Technics Switzerland
138977					72-61-05		Package H	007	MACHINING REPAIR OF DIAMETER C		1335.00	SR Technics Switzerland
138977					72-61-05		Package SB00	72-0582	SPARE PARTS RELEASE FOR CFM56-7B ENGINES		730.00	SR Technics Switzerland
139054	9992M86G07	EASA,FAA,CAAC,ANAC	28	28	72-32-20	COMPRESSOR FRONT STATOR - PLUG ASSY-BOREScope	Package A	CLN/INSP	CLEANING AND INSPECTION		355.00	SR Technics Switzerland
139054	9992M86G08	EASA,FAA,CAAC,ANAC			72-32-20		Package B	001	REPLACEMENT OF DAMAGED PARTS ON THE STAGE 6-8 BORESCOPE PLUG ASSEMBLIES		535.00	SR Technics Switzerland
139334	1319M17P01	EASA,FAA,CAAC,ANAC	36	28	72-52-10	HIGH PRESSURE TURBINE ROTOR - REAR ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		590.00	SR Technics Switzerland
139334	1319M17P02	EASA,FAA,CAAC,ANAC			72-52-10		Package A	INSP-001	ROTATION SEAL SERRATIONS DEFECT REMOVAL		590.00	SR Technics Switzerland
139334					72-52-10		Package C	001	REPLACEMENT OF SEAL TEETH COATING		4120.00	SR Technics Switzerland
139334					72-52-10		Package F	004	REPAIR OF ILLEGIBLE PART MARKINGS		330.00	SR Technics Switzerland
139335	1360M70G01	EASA,FAA,CAAC,ANAC	23	28	72-61-01	INLET GEARBOX & NO.3 BEARING - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		525.00	SR Technics Switzerland
139335	1360M70G02	EASA,FAA,ANAC			72-61-01		Package B	001	REPLACEMENT OF THE OIL NOZZLES AND PLUGS		1205.00	SR Technics Switzerland
139335					72-61-01		Package C	002	REPLACEMENT OF DAMAGED STUDS		920.00	SR Technics Switzerland
139335					72-61-01		Package E	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR WEAR AND FRE SURFACE A		1565.00	SR Technics Switzerland
139335					72-61-01		Package F	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR WEAR AND FRE DIAMETER C		3295.00	SR Technics Switzerland
139335					72-61-01		Package H	007	REPAIR OF THE LOCATING HOLE AV		3070.00	SR Technics Switzerland
139335					72-61-01		Package SB00	SB 72-1069	IGB BOLTED JOINT IMPROVEMENT AND REWORK		925.00	SR Technics Switzerland
139336	1361M13P01	EASA,FAA,CAAC,ANAC	26	28	72-61-04	INLET GEARBOX & NO.3 BEARING - ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		835.00	SR Technics Switzerland
139336					72-61-04		Package A	INSP-001	HAND LAP SEAL SURFACE D		835.00	SR Technics Switzerland
139336					72-61-04		Package B	001	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		1200.00	SR Technics Switzerland
139339	1475M30G03	EASA,FAA,CAAC,ANAC	41	28	72-32-06	COMPRESSOR FRONT STATOR - SHROUD, INLET GUIDE VANES	Package A	CLN/INSP	CLEANING AND INSPECTION		790.00	SR Technics Switzerland
139339					72-32-06		Package B	001	REPLACEMENT OF THE ABRADABLE SEAL ON THE HPC FRONT STATOR IGV SHROUD		3425.00	SR Technics Switzerland
139339					72-32-06		Package C	002	TRUNNION HOLE WEAR REPAIR	SINGLE	3070.00	SR Technics Switzerland
139339					72-32-06		Package D	INSP-001	REMOVE HIGH METAL		175.00	SR Technics Switzerland
139339					72-32-06		Package E	002	2ND TRUNNION HOLE WEAR REPAIR		2795.00	SR Technics Switzerland
139339					72-32-06		Package G	002	TRUNNION HOLE WEAR REPAIR	ALL	5830.00	SR Technics Switzerland
139341	1498M40P03	EASA,FAA,CAAC,ANAC	36	28	72-52-04	HIGH PRESSURE TURBINE ROTOR - FRONT SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1400.00	SR Technics Switzerland
139341	1498M40P05	EASA,FAA,CAAC,ANAC			72-52-04		Package A	INSP	MEASUREMENT SHAFT CONCENTRICITY DIA B AND C	TECHNICAL INSTRUCTION	1400.00	SR Technics Switzerland
139341	1498M40P06	EASA,FAA,CAAC,ANAC			72-52-04		Package B	INSP-001	REMOVE HIGH METAL		425.00	SR Technics Switzerland
139341	1873M73P01	EASA,FAA,CAAC,ANAC			72-52-04		Package C	001	THERMAL SPRAY RABBIT REPAIR	EQUILIZE DIA H AND K	4875.00	SR Technics Switzerland
139341	2048M21P03	EASA,FAA,CAAC,ANAC			72-52-04		Package E	003	THERMAL SPRAY RABBIT REPAIR		3025.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139341					72-52-04		Package F	005	MACHINING REPAIR OF RIB CORNER FRETTING		1085.00	SR Technics Switzerland
139341					72-52-04		Package SB01	72-0946	REPLACE FWD DAMPER SLEEVE		1130.00	SR Technics Switzerland
139342	1498M43P04	EASA,FAA,CAAC,ANAC	56	28	72-52-02	HIGH PRESSURE TURBINE ROTOR - DISK	Package A	CLN/INSP	CLEANING AND INSPECTION		4155.00	SR Technics Switzerland
139342	1498M43P05	EASA,FAA,CAAC,ANAC			72-52-02		Package B	INSP-001	BLENDING OF RIM OD		3145.00	SR Technics Switzerland
139342	1498M43P06	EASA,FAA,CAAC,ANAC			72-52-02		Package B	INSP-001	REMOVAL OF HIGH METAL		3145.00	SR Technics Switzerland
139342	1498M43P07	EASA,FAA,CAAC,ANAC			72-52-02		Package B	INSP-001	BLENDING OF WEB AND HUB FACES		3145.00	SR Technics Switzerland
139342	2410M49P01	EASA,FAA,CAAC,ANAC			72-52-02		Package B	INSP-001	BLENDING OF DISK BORE EDGE RADIUS		3145.00	SR Technics Switzerland
139342	2410M49P02	EASA,FAA,CAAC,ANAC			72-52-02		Package D	1	REPLACEMENT OF THE DISK CLUNCH NUTS		3175.00	SR Technics Switzerland
139342					72-52-02		Package F	5	THERMAL SPRAY REPAIR OF THE FORWARD FLANGE RABBIT		3165.00	SR Technics Switzerland
139342					72-52-02		Package G	INSP-002	REMOVAL OF HIGH METAL		985.00	SR Technics Switzerland
139342					72-52-02		Package I	8	SHOTPEENING REPAIR OF SURFACE		840.00	SR Technics Switzerland
139342					72-52-02		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE EDDY CURRENT INSPECTION (ECI)		3780.00	SR Technics Switzerland
139349	1523M35P01	EASA,FAA,CAAC,ANAC	31	28	72-31-08	COMPRESSOR ROTOR - REAR ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1380.00	SR Technics Switzerland
139349	2116M25P01	EASA,FAA,CAAC,ANAC			72-31-08		Package B	INSP-001	BLENDING SEAL TEETH		1110.00	SR Technics Switzerland
139349					72-31-08		Package B	INSP-001	REMOVAL OF HIGH METAL BY BLENDING		1110.00	SR Technics Switzerland
139349					72-31-08		Package C	001	REPAIR OF THE SEAL TEETH COATING		3925.00	SR Technics Switzerland
139349					72-31-08		Package D	003	REPAIR THE FORWARD AND AFT RABBIT	DIAMETER B+C	3715.00	SR Technics Switzerland
139349					72-31-08		Package E		MEASURE NEW - / OVHLD PARTS		105.00	SR Technics Switzerland
139349					72-31-08		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	630.00	SR Technics Switzerland
139350	1523M37P01	EASA,FAA,CAAC,ANAC	38	28	72-41-05	COMBUSTION CASE - HPT NOZZLE SUPPORT BOLT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		770.00	SR Technics Switzerland
139350	1523M37P02	EASA,FAA,CAAC,ANAC			72-41-05		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		1940.00	SR Technics Switzerland
139350					72-41-05		Package SB01	72-0540	REWORK OF THE BOLT SHIELD OUTSIDE DIAMETER		845.00	SR Technics Switzerland
139353	1523M43P01	EASA,FAA,CAAC,ANAC	29	28	72-51-11	HIGH PRESSURE TURBINE NOZZLE - SUPPORT NUT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		515.00	SR Technics Switzerland
139353	2071M15P01	EASA,FAA,CAAC,ANAC			72-51-11		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		3945.00	SR Technics Switzerland
139354	1523M59G01	EASA,FAA,CAAC,ANAC	25	28	72-53-04	HPT SHROUD - SUPPORT HANGER	Package A	INSP-001	INSPECTION/CHECK	7B, 7BE	225.00	SRTAS
139354	1523M59G05	EASA,FAA,CAAC,ANAC			72-53-04		Package B		FULL REPAIR (Pre SB 72-0909/0962)	7B, 7BE	1830.00	SRTAS
139354	1808M61G01	EASA,FAA,CAAC,ANAC			72-53-04		Package B	008	STRAIGHT PIN REPLACEMENT		1830.00	SRTAS
139354	1808M61G02	EASA,FAA,CAAC,ANAC			72-53-04		Package B	009	PIN HOLE AND AXIAL CRACKS ON FORWARD INNER RAIL WELD REPAIR		1830.00	SRTAS
139354	1808M61G04	EASA,FAA,CAAC,ANAC			72-53-04		Package B	013	SEAL SLOT BREAKOUT WELD REPAIR		1830.00	SRTAS
139354	1808M61G05	EASA,FAA,CAAC,ANAC			72-53-04		Package B	014	REPAIR USING RBD	alternative to Repairs 002, 003, 005, 007, 0	1830.00	SRTAS
139354	1808M61G06	EASA,FAA,CAAC,ANAC			72-53-04		Package B	015	AFT RAIL WELD REPAIR		1830.00	SRTAS
139354	1808M61G07	EASA,FAA,CAAC,ANAC			72-53-04		Package B	016	FORM REPAIR (CHECK SHAPE & TRUE UP)		1830.00	SRTAS
139354	1808M61G08	EASA,FAA,CAAC,ANAC			72-53-04		Package B	018	AFT RAIL WELD REPAIR		1830.00	SRTAS
139354	1808M61G09	EASA,FAA,CAAC,ANAC			72-53-04		Package B	INSP-001	INSPECTION/CHECK		1830.00	SRTAS
139354	1808M61G10	EASA,FAA,CAAC,ANAC			72-53-04		Package C		FULL REPAIR (Post SB 72-0909/0962)		2415.00	SRTAS
139354	1808M61G11	EASA,FAA,CAAC,ANAC			72-53-04		Package C	008	STRAIGHT PIN REPLACEMENT		2415.00	SRTAS
139354	1808M61G12	EASA,FAA,CAAC,ANAC			72-53-04		Package C	009	PIN HOLE AND AXIAL CRACKS ON FORWARD INNER RAIL WELD REPAIR.		2415.00	SRTAS
139354	1893M42G01	EASA,FAA,CAAC,ANAC			72-53-04		Package C	013	SEAL SLOT BREAKOUT WELD REPAIR		2415.00	SRTAS
139354	1893M42G02	EASA,FAA,CAAC,ANAC			72-53-04		Package C	014	REPAIR UNDER CDR USING RBD	alternative to Repairs 002, 005, 007, 011, 0	2415.00	SRTAS
139354	1893M42G03	EASA,FAA,CAAC,ANAC			72-53-04		Package C	015	AFT RAIL WELD REPAIR		2415.00	SRTAS
139354	1893M42G04	EASA,FAA,CAAC,ANAC			72-53-04		Package C	016	FORM REPAIR (CHECK SHAPE & TRUE UP)		2415.00	SRTAS
139354	1957M74G01	EASA,FAA,CAAC,ANAC			72-53-04		Package C	018	AFT RAIL WELD REPAIR		2415.00	SRTAS
139354	1957M74G02	EASA,FAA,CAAC,ANAC			72-53-04		Package D		ADDITIONAL WORKSCOPE	7B, 7BE	485.00	SRTAS
139354	1957M86G01	EASA,FAA,CAAC,ANAC			72-53-04		Package D	017	BRAZE REPAIR FOR WEAR ON HANGER RAILS.		485.00	SRTAS
139354					72-53-04		Package E		ADDITIONAL WORKSCOPE	(WITH FULL REPAIR WORKSCOPE)	715.00	SRTAS
139354					72-53-04		Package E	72-0079	ENLARGE COOLING HOLES, INCREASE FORWARD LIP HEIGHT AND ALTER PIN POSIT	7B, 7BE	715.00	SRTAS
139354					72-53-04		Package F		ADDITIONAL WORKSCOPE	(WITH ANY OF THE PACKAGED WORKSCOPE)	820.00	SRTAS
139354					72-53-04		Package F	72-0962	REWORK TO ADD AIR FILTER	7B, 7BE	820.00	SRTAS
139354					72-53-04		Package H		ADDITIONAL WORKSCOPE	7B, 7BE	1190.00	SRTAS
139354					72-53-04		Package H	020	AIRFILTER REMOVAL AND REPLACEMENT	1893M42G03 / 1893M42G04 / 1808M61G	1190.00	SRTAS
139354					72-53-04		Package I		ADDITIONAL WORKSCOPE	7B, 7BE	955.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139354					72-53-04		Package I	021	WELD OF THE PIN HOLE AND AXIAL AND RADIAL CRACK		955.00	SRTAS
139381	301-475-207-6	EASA,FAA,CAAC,ANAC	34	28	72-22-14	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING OIL BAFFLE	Package A	CLN/INSP	CLEANING AND INSPECTION		560.00	SR Technics Switzerland
139381					72-22-14		Package B	002	RESTORATION OF THE SHIMMING FUNCTION		4170.00	SR Technics Switzerland
139381					72-22-14		Package C	ASSEMBLY-001	BAFFLE THICKNESS GRINDING		795.00	SR Technics Switzerland
139388	305-135-904-0	EASA,FAA,CAAC,ANAC	39	28	72-63-01	ACCESSORY GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1275.00	SR Technics Switzerland
139388	305-135-905-0	EASA,FAA,CAAC,ANAC			72-63-01		Package C	002	REPLACEMENT OF THE KEY-LOCKED STUDS		1020.00	SR Technics Switzerland
139388	340-046-602-0	EASA,FAA,CAAC,ANAC			72-63-01		Package D	003	REPLACEMENT OF THE KEY-LOCKED SELF-LOCKING INSERTS		890.00	SR Technics Switzerland
139388	340-046-603-0	EASA,FAA,CAAC,ANAC			72-63-01		Package H	006	REPLACEMENT OF THE AXIAL OIL NOZZEL		1500.00	SR Technics Switzerland
139388	340-046-604-0	EASA,FAA,CAAC,ANAC			72-63-01		Package I	009	SPOT TOUCH UP OF NON-MACHINED SURFACES BY OXIDE FILM COATING		470.00	SR Technics Switzerland
139388	340-046-605-0	EASA,FAA,CAAC,ANAC			72-63-01		Package K	007	REPLACEMENT OF SWAGED SELF-LOCKING INSERTS		875.00	SR Technics Switzerland
139388					72-63-01		Package L	011	REPAIR OF MACHINED SURFACES BY PLASMA SPRAYING		9805.00	SR Technics Switzerland
139388					72-63-01		Package M	012	REPAIR OF DIAMETERS BY PLASMA SPRAY		9805.00	SR Technics Switzerland
139388					72-63-01		Package N	013	MACHINING OF BEARING SEATING SURFACES		9350.00	SR Technics Switzerland
139388					72-63-01		Package O	014	BLEND REPAIR OF MOUNT CLEVIS		445.00	SR Technics Switzerland
139388					72-63-01		Package SB00	72-0879	INTRODUCTION OF A NEW ASSY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSY		7670.00	SR Technics Switzerland
139389	305-136-503-0	EASA,FAA,CAAC,ANAC	30	28	72-62-01	TRANSFER GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1050.00	SR Technics Switzerland
139389	335-300-403-0	EASA,FAA,CAAC,ANAC			72-62-01		Package AA	006	REPAIR OF MACHINED FACES	SURFACE H	855.00	SR Technics Switzerland
139389	338-089-601-0	EASA,FAA,CAAC,ANAC,CAA UK			72-62-01		Package AK	006	REPAIR OF MACHINED FACES	SURFACE J	855.00	SR Technics Switzerland
139389	340-050-704-0	EASA,FAA,CAAC,ANAC			72-62-01		Package E	004	SPOT TOUCH-UP OF NON-MACHINED SURFACES BY OXIDE FILM COATING		855.00	SR Technics Switzerland
139389	340-050-705-0	EASA,FAA,CAAC,ANAC			72-62-01		Package F	005	REPAIR OF BEARING SUPPORT LOCATING DIAMETERS	DIA E	855.00	SR Technics Switzerland
139389					72-62-01		Package G	006	REPAIR OF MACHINED FACES	SURFACE A	855.00	SR Technics Switzerland
139389					72-62-01		Package K	003	ID PLATE NAILS		855.00	SR Technics Switzerland
139389					72-62-01		Package P	005	REPAIR OF BEARING SUPPORT LOCATING DIAMETERS	DIA H	855.00	SR Technics Switzerland
139389					72-62-01		Package Q	006	REPAIR OF MACHINED FACES	SURFACE E	855.00	SR Technics Switzerland
139389					72-62-01		Package Z	005	REPAIR OF BEARING SUPPORT LOCATING DIAMETERS	DIA J	855.00	SR Technics Switzerland
139422	305-148-801-0	EASA,FAA,CAAC,ANAC	22	28	72-62-04	TRANSFER GEARBOX - HOUSING ASSY-HORIZONTAL BEVEL	Package A	CLN/INSP	CLEANING AND INSPECTION		270.00	SR Technics Switzerland
139422	335-305-000-0	EASA,FAA,CAAC,ANAC			72-62-04		Package B	001	REPLACEMENT OF KEY-LOCKED INSERTS		1480.00	SR Technics Switzerland
139429	305-396-303-0	EASA,FAA,CAAC,ANAC	33	28	72-22-05	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT ROTOR AIR/OIL SEPARATOR	Package A	CLN/INSP	CLEANING AND INSPECTION		355.00	SR Technics Switzerland
139429	305-396-306-0	EASA,FAA,CAAC,ANAC			72-22-05		Package B	001	RECONDITIONING THE RABBIT DIAMETER WITH THE FAN SHAFT BY THERMAL SPRAYING		2570.00	SR Technics Switzerland
139430	305-408-301-0	EASA,FAA,CAAC,ANAC	43	21	72-55-10	LOW PRESSURE TURBINE SHAFT - CENTER VENT TUBE REAR EXTENSION DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		695.00	SR Technics Switzerland
139430	338-180-101-0	EASA,FAA,CAAC,ANAC			72-55-10		Package A	INSP-001	REMOVAL OF HIGH METAL/DAMAGED THREADST		695.00	SR Technics Switzerland
139430	338-180-401-0	EASA,FAA,CAAC,ANAC			72-55-10		Package B	001	REPLACEMENT OF ONE OR SEVERAL LOCATING PIN		920.00	SR Technics Switzerland
139430	340-170-401-0	EASA,FAA,CAAC,ANAC			72-55-10		Package C	002	REPAIR OF THE SLOTS BY WELD BUILDUP		2935.00	SR Technics Switzerland
139430	340-170-402-0	EASA,FAA,CAAC,ANAC			72-55-10		Package D	004	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4425.00	SR Technics Switzerland
139430					72-55-10		Package E	005	REPAIR THE FRONT LOCATING DIAMETER OF THE VENT TUBE REAR EXTENSION DUCT BY PLASMA SPRAYING		5025.00	SR Technics Switzerland
139430					72-55-10		Package H	007	REPAIR OF REAR VENT TUBE BY DRILLING OF THE THREE NEW HOLES		2520.00	SR Technics Switzerland
139430					72-55-10		Package I	008	RESHAPING SEAL TEETH		1015.00	SR Technics Switzerland
139431	335-070-301-6	EASA,FAA,CAAC,ANAC	20	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE - ADJUSTING SLEEVE BE	Package B	ASSEMBLY-001	GRIND-ADJUST SLEEVE	FOR SHOP VISITS ONLY	1105.00	SR Technics Switzerland
139432	336-001-804-0	EASA,FAA,CAAC,ANAC,CAA UK	48	28	72-54-03	LOW PRESSURE TURBINE - DISKS, STG 1-4 (CFM56-5B/7B)	Package A	CLN/INSP	CLEANING AND INSPECTION		1110.00	SR Technics Switzerland
139432	336-001-909-0	EASA,FAA,CAAC,ANAC,CAA UK			72-54-03		Package B	INSP 001	BLENDING SURFACE		3005.00	SR Technics Switzerland
139432	336-002-006-0	EASA,FAA,CAAC,ANAC,CAA UK			72-54-03		Package C	INSP	INSPECTION OF THE DISKS (AFTER OVERTEMPERATURE AND/OR OVERSPEED) FOR: HARDNESS AND GROWTH CHECK		620.00	SR Technics Switzerland
139432	336-002-105-0	EASA,FAA,CAAC,ANAC,CAA UK			72-54-03		Package D	INSP 001	REMOVE HIGHMETAL ON WEB		1595.00	SR Technics Switzerland
139432	337-001-404-0	EASA,FAA,CAAC,ANAC			72-54-03		Package F	001	REPAIR OF STAGE 1 LPT DISKS FORWARD FLANGE BY MACHING		3865.00	SR Technics Switzerland
139432	337-001-605-0	EASA,FAA,CAAC,ANAC			72-54-03		Package G	001	REPAIR OF STAGE 2 LPT DISKS FORWARD FLANGE BY MACHING		5040.00	SR Technics Switzerland
139432	337-001-705-0	EASA,FAA,CAAC,ANAC			72-54-03		Package J	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 1	1840.00	SR Technics Switzerland
139432	337-001-802-0	EASA,FAA,CAAC,ANAC			72-54-03		Package K	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 2	1840.00	SR Technics Switzerland
139432	340-301-001-0	EASA,FAA,CAAC,ANAC			72-54-03		Package L	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 3	1840.00	SR Technics Switzerland
139432	340-301-101-0	EASA,FAA,CAAC,ANAC			72-54-03		Package M	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 4	1840.00	SR Technics Switzerland
139432	340-301-201-0	EASA,FAA,CAAC,ANAC			72-54-03		Package O	005	MACHINING OF MARKS ON FLANGES STG.1		7940.00	SR Technics Switzerland
139432	340-301-301-0	EASA,FAA,CAAC,ANAC			72-54-03		Package P	005	MACHINING OF MARKS ON FLANGES STG.2		7940.00	SR Technics Switzerland
139432					72-54-03		Package Q	005	MACHINING OF MARKS ON FLANGES STG.3		7940.00	SR Technics Switzerland

For new capability, please refer to our homepage <https://cpc.srtechnics.com>

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139432					72-54-03		Package R	005	MACHINING OF MARKS ON FLANGES STG.4		7940.00	SR Technics Switzerland
139432					72-54-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG1	IN CONJUNCTION WITH PACKAGE A	435.00	SR Technics Switzerland
139432					72-54-03		Package SB01	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG2	IN CONJUNCTION WITH PACKAGE A	435.00	SR Technics Switzerland
139432					72-54-03		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG3	IN CONJUNCTION WITH PACKAGE A	435.00	SR Technics Switzerland
139432					72-54-03		Package SB03	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG4	IN CONJUNCTION WITH PACKAGE A	435.00	SR Technics Switzerland
139432					72-54-03		Package SB04	72-EO-521902	WORKSCOPE LPT OVERTEMP ANALYSE		435.00	SR Technics Switzerland
139432					72-54-03		Package T	006	RECONDITIONING BY PLASMA SPRAYING OF THE LPT ROTATING AIR SEAL LOCATIN STAGE 3		7940.00	SR Technics Switzerland
139443	336-013-101-0	EASA,FAA,CAAC,ANAC	23	28	72-54-17	LOW PRESSURE TURBINE - SEAL-ROTATING OIL FORWARD	Package A	CLN/INSP	CLEANING AND INSPECTION		830.00	SR Technics Switzerland
139443					72-54-17		Package B	001	REPAIR OF THE ALUMINUM-SILICIUM-POLYESTER ABRADABLE COATING		2510.00	SR Technics Switzerland
139443					72-54-17		Package C	002	LOCATING DIAMETER		2520.00	SR Technics Switzerland
139448	338-000-405-0	EASA,FAA,CAAC,ANAC	28	28	72-54-01	LOW PRESSURE TURBINE - BLADES STG 1	Package B		FULL REPAIR		300.00	SRTAS
139448	338-000-461-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	11	WELD REPAIR RUB BETWEEN SEAL TEETH		300.00	SRTAS
139448	338-000-481-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	2	AIRFOIL BLEND REPAIR		300.00	SRTAS
139448	338-000-482-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	3	RE-SETTING THE PRE-TWIST ANGLE		300.00	SRTAS
139448	338-108-204-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	4	REPAIR OF SEAL TEETH BY PLASMA SPRAYING		300.00	SRTAS
139448	338-108-206-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	40	LASER CLADDING OF HARD FACING AND MATING FACES OF THE TIP SHROUD		300.00	SRTAS
139448	338-108-207-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	5	REPAIR OF THE SEAL TEETH ON THE BLADE TIP SHROUD BY WELD BUILD-UP WITH COAST METAL 64		300.00	SRTAS
139448	338-108-208-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	55	OVER-COATING OF APVS COATING		300.00	SRTAS
139448	338-108-210-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	7	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS, BY WELD BUILD-UP WITH COAST METAL 64		300.00	SRTAS
139448	338-115-703-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	8	REPAIR OF VAPOUR PHASE ALUMINAZATION		300.00	SRTAS
139448	338-115-705-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	9	CORROSION REMOVAL ON ROOT BY BLENDING		300.00	SRTAS
139448	338-115-706-0	EASA,FAA,CAAC,ANAC			72-54-01		Package B	INSP 001	VISUAL & DIMENSIONAL INSPECTION		300.00	SRTAS
139448	338-115-707-0	EASA,FAA,CAAC,ANAC			72-54-01		Package C		ADDITIONAL REPAIR	7B, 7BE	135.00	SRTAS
139448	338-115-709-0	EASA,FAA,CAAC,ANAC			72-54-01		Package C	5A	DIMESIONAL RESTORATION OF THE SEAL TEETH		135.00	SRTAS
139448	340-302-001-0	EASA,FAA,CAAC,ANAC			72-54-01		Package D		FULL REPAIR	7BE	300.00	SRTAS
139448	340-310-001-0	EASA,FAA,CAAC,ANAC			72-54-01		Package D	18	REPAIR OF VAPOUR PHASE ALUMINISATION. (INCLUDES OXIDE & OXYSULPHIDE CLEANING)		300.00	SRTAS
139448					72-54-01		Package D	3	RE-SETTING THE PRE-TWIST ANGLE		300.00	SRTAS
139448					72-54-01		Package D	32	AIRFOIL BLEND REPAIR		300.00	SRTAS
139448					72-54-01		Package D	34	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTRIUM		300.00	SRTAS
139448					72-54-01		Package D	5	REPAIR OF THE SEAL TEETH ON THE BLADE TIP SHROUD BY WELD BUILD-UP WITH COAST METAL 64		300.00	SRTAS
139448					72-54-01		Package D	55	OVER-COATING OF APVS COATING		300.00	SRTAS
139448					72-54-01		Package D	7	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS, BY WELD BUILD-UP WITH COAST METAL 64		300.00	SRTAS
139448					72-54-01		Package D	9	CORROSION REMOVAL ON ROOT BY BLENDING		300.00	SRTAS
139448					72-54-01		Package D	INSP 001	VISUAL & DIMENSIONAL INSPECTION		300.00	SRTAS
139490	338-075-801-0	EASA,FAA,CAAC,ANAC	27	28	72-54-02	LOW PRESSURE TURBINE - BLADES STG 2 - 4	Package AH		STG 4 - ADDITIONAL WORK SCOPE	7B, 7BE	125.00	SRTAS
139490	338-082-802-0	EASA,FAA,CAAC,ANAC			72-54-02		Package AH	17A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS BY REQUEST		125.00	SRTAS
139490	338-082-803-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B		STG 2 - FULL REPAIR		430.00	SRTAS
139490	338-082-804-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	11	BLEND TO REMOVE ROOT SULPHIDATION/ CORROSION		430.00	SRTAS
139490	338-082-852-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	18	REPAIR APVS COATING		430.00	SRTAS
139490	338-082-853-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	2	PLASMA SPRAY SEAL TEETH ZIRCONIUM OXIDE-YTRIUM (3 PARTS PER SET)		430.00	SRTAS
139490	338-082-854-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	20	WELD REPAIR SEAL TEETH WITH CM 64		430.00	SRTAS
139490	338-084-003-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	3	RESET PRE TWIST ANGLE		430.00	SRTAS
139490	338-084-023-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	4	AIRFOIL BLEND REPAIR		430.00	SRTAS
139490	338-084-052-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	41	LASER CLADDING OF HARDFACING AND MATING FACES OF BLADE TIP SHROUDS WITH COAST METAL 64.		430.00	SRTAS
139490	338-084-072-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	55	OVER COATING OF VAPOUR PHASE ALUMINAZATION		430.00	SRTAS
139490	338-086-203-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	6	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS		430.00	SRTAS
139490	338-086-228-0	EASA,FAA,CAAC,ANAC			72-54-02		Package B	INSP-001	VISUAL / DIMENSIONAL INSPECTION		430.00	SRTAS
139490	338-086-253-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C		STG 3 - FULL REPAIR		270.00	SRTAS
139490	338-086-278-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	17	WELD REPAIR SEAL TEETH WITH CM 64		270.00	SRTAS
139490	338-108-304-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	2	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTRIUM.		270.00	SRTAS
139490	338-108-305-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	28	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		270.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139490	338-108-403-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	3	RESET PRE TWIST ANGLE		270.00	SRTAS
139490	338-108-503-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	39	CORROSION REMOVAL FROM BLADE ROOT SURFACES		270.00	SRTAS
139490	338-108-504-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	5	AIRFOIL BLEND REPAIR		270.00	SRTAS
139490	338-108-553-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	7	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH CM64		270.00	SRTAS
139490	338-108-554-0	EASA,FAA,CAAC,ANAC			72-54-02		Package C	INSP-001	VISUAL / DIMENSIONAL		270.00	SRTAS
139490	338-115-902-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D		STG 4 - FULL REPAIR		280.00	SRTAS
139490	338-116-102-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	17	WELD REPAIR SEAL TEETH WITH CM 64		280.00	SRTAS
139490	338-116-103-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	2	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTRIUM		280.00	SRTAS
139490	338-116-152-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	28	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		280.00	SRTAS
139490	338-116-153-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	3	RESET PRE TWIST ANGLE		280.00	SRTAS
139490	338-116-303-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	39	CORROSION REMOVAL FROM BLADE ROOT SURFACES		280.00	SRTAS
139490	338-116-304-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	5	AIRFOIL BLEND REPAIR		280.00	SRTAS
139490	340-302-101-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	8	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH T800		280.00	SRTAS
139490	340-302-201-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	9	REPLACE RBD 191 WITH T800 ON TIP SHROUDS		280.00	SRTAS
139490	340-302-202-0	EASA,FAA,CAAC,ANAC			72-54-02		Package D	INSP-001	VISUAL / DIMENSIONAL		280.00	SRTAS
139490	340-302-301-0	EASA,FAA,CAAC,ANAC			72-54-02		Package L		STG 2 - FULL REPAIR	7BE	430.00	SRTAS
139490	340-310-101-0	EASA,FAA,CAAC,ANAC			72-54-02		Package L	11	BLEND TO REMOVE ROOT SULPHIDATION/ CORROSION		430.00	SRTAS
139490	340-310-202-0	EASA,FAA,CAAC,ANAC			72-54-02		Package L	20	WELD REPAIR SEAL TEETH WITH CM 64		430.00	SRTAS
139490	340-310-301-0	EASA,FAA,CAAC,ANAC			72-54-02		Package L	3	RESET PRE TWIST ANGLE		430.00	SRTAS
139490					72-54-02		Package L	32	REPAIR OF THE COATING ON THE SEAL TEETH BY PLASMA SPRAYING		430.00	SRTAS
139490					72-54-02		Package L	34	AIRFOIL BLEND REPAIR		430.00	SRTAS
139490					72-54-02		Package L	38	REPAIR OF THE VAPOR PHASE ALUMINIZATION		430.00	SRTAS
139490					72-54-02		Package L	55	OVER COATING OF VAPOUR PHASE ALUMINAZATION		430.00	SRTAS
139490					72-54-02		Package L	6	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS		430.00	SRTAS
139490					72-54-02		Package M		STG 3 - FULL REPAIR	7BE	270.00	SRTAS
139490					72-54-02		Package M	17	WELD REPAIR SEAL TEETH WITH CM 64		270.00	SRTAS
139490					72-54-02		Package M	28	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		270.00	SRTAS
139490					72-54-02		Package M	3	RESET PRE TWIST ANGLE		270.00	SRTAS
139490					72-54-02		Package M	32	AIRFOIL BLEND REPAIR		270.00	SRTAS
139490					72-54-02		Package M	35	REPAIR OF THE COATING ON THE SEAL TEETH BY PLASMA SPRAYING		270.00	SRTAS
139490					72-54-02		Package M	39	CORROSION REMOVAL FROM BLADE ROOT SURFACES		270.00	SRTAS
139490					72-54-02		Package M	7	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH CM64		270.00	SRTAS
139490					72-54-02		Package M	INSP-001	VISUAL / DIMENSIONAL		270.00	SRTAS
139490					72-54-02		Package N		STG 2 - ADDITIONAL WORK SCOPE	7B, 7BE	125.00	SRTAS
139490					72-54-02		Package N	20A	DIMENSIONAL RESTORATION OF THE SEAL TEETH ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS BY REQUEST		125.00	SRTAS
139490					72-54-02		Package O		STG 4 - FULL REPAIR	7BE	280.00	SRTAS
139490					72-54-02		Package O	17	WELD REPAIR SEAL TEETH WITH CM 64		280.00	SRTAS
139490					72-54-02		Package O	28	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		280.00	SRTAS
139490					72-54-02		Package O	3	RESET PRE TWIST ANGLE		280.00	SRTAS
139490					72-54-02		Package O	32	REPAIR OF THE COATING ON THE SEAL TEETH BY PLASMA SPRAYING		280.00	SRTAS
139490					72-54-02		Package O	35	AIRFOIL BLEND REPAIR		280.00	SRTAS
139490					72-54-02		Package O	39	CORROSION REMOVAL FROM BLADE ROOT SURFACES		280.00	SRTAS
139490					72-54-02		Package O	8	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH T800		280.00	SRTAS
139490					72-54-02		Package O	INSP-001	VISUAL / DIMENSIONAL		280.00	SRTAS
139490					72-54-02		Package X		STG 3 - ADDITIONAL WORK SCOPE	7B, 7BE	125.00	SRTAS
139490					72-54-02		Package X	17A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS BY REQUEST		125.00	SRTAS
139515	9542M67P01	EASA,FAA,CAAC,ANAC	18	28	72-61-02	INLET GEARBOX & NO.3 BEARING - GEAR-BEVEL HORIZOTAL 47 TOOTH	Package A	CLN/INSP	CLEANING AND INSPECTION		1065.00	SR Technics Switzerland
139515					72-61-02		Package B	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA E	2865.00	SR Technics Switzerland
139515					72-61-02		Package C	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA F	2865.00	SR Technics Switzerland
139515					72-61-02		Package D	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA G	2865.00	SR Technics Switzerland
139515					72-61-02		Package E	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA J	2865.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139515					72-61-02		Package F	002	REPAIR OF THE LOCKING PIN HOLES	DIA H	1020.00	SR Technics Switzerland
139517	9972M31G03	EASA,FAA,CAAC,ANAC	25	28	72-61-03	INLET GEARBOX & NO.3 BEARING - RADIAL BEVEL GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		780.00	SR Technics Switzerland
139517					72-61-03		Package B	001	REPLACEMENT OF OIL SEAL		1230.00	SR Technics Switzerland
139520	9972M49G02	EASA,FAA,CAAC,ANAC	25	28	72-61-07	INLET GEARBOX & NO.3 BEARING - PULLER RING	Package A	CLN/INSP	CLEANING AND INSPECTION		1000.00	SR Technics Switzerland
139520					72-61-07		Package B	001	REPLACEMENT OF FIBER WASHER		1055.00	SR Technics Switzerland
139520					72-61-07		Package SB00	72-0582	INTRODUCTION OF A NEW LPT ROTOR SUPPORT		465.00	SR Technics Switzerland
139541	1588M89G02	EASA,FAA,CAAC,ANAC	49	28	72-31-06	COMPRESSOR ROTOR - SPOOL STG 4-9	Package A	CLN/INSP	CLEANING AND INSPECTION		2505.00	SR Technics Switzerland
139541	1588M89G03	EASA,FAA,CAAC,ANAC			72-31-06		Package B	INSP-001	BLEND BORES STG. 4-9		1495.00	SR Technics Switzerland
139541	2048M20G03	EASA,FAA,CAAC,ANAC			72-31-06		Package B	INSP-001	REMOVE HIGH METAL		1495.00	SR Technics Switzerland
139541	2048M20G04	EASA,FAA,CAAC,ANAC			72-31-06		Package C	INSP-001	BLEND PLATFORM RAIL OUTER DIA.		1545.00	SR Technics Switzerland
139541	2048M20G05	EASA,FAA,ANAC,TCCA			72-31-06		Package D	INSP-001	BLEND FWD SIDE PLATFORM STG 4		1200.00	SR Technics Switzerland
139541					72-31-06		Package E	001	REPAIR OF THE SEAL TEETH COATINGS		7090.00	SR Technics Switzerland
139541					72-31-06		Package G	003	REPAIR OF THE FORWARD AND AFT RABBIT DIAMETERS		3880.00	SR Technics Switzerland
139541					72-31-06		Package I	006	REPAIR OF THE FORWARD AND AFT RABBIT DIAMETERS		5165.00	SR Technics Switzerland
139541					72-31-06		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1745.00	SR Technics Switzerland
139576	2423M70G01	EASA,FAA,CAAC,ANAC,CAA UK	35	28	72-23-04	FAN FRAME ASSEMBLY - OUTLET GUIDE VANE INNER SHROUD ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		835.00	SR Technics Switzerland
139576	338-007-203-0	EASA,FAA,CAAC,ANAC			72-23-04		Package B	001	TOUCH UP OR TOTAL REPAIR OF SULVURIC ANODIZING		820.00	SR Technics Switzerland
139576	338-007-205-0	EASA,FAA,CAAC,ANAC			72-23-04		Package C	002	REPLACEMENT OF CRIMPED NUTS		810.00	SR Technics Switzerland
139576	340-002-408-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-04		Package E	004	REPAIR OF THE HOLES ON THE REAR FLANGE OF THE FAN OUTLET GUIDE VANE INNER SHROUD BY BUSHING		3055.00	SR Technics Switzerland
139576					72-23-04		Package F	005	REPAIR OF THE HOLES ON THE FORWARD FLANGE ON THE FAN OUTLET GUIDE VANE INNER SHROUD BY WELD BUILD UP		2605.00	SR Technics Switzerland
139576					72-23-04		Package G	006	REMOVAL OF THE CORROSION OF THE HOLE ON THE RIVETED SELF LOCKING NUTS		1490.00	SR Technics Switzerland
139576					72-23-04		Package H	007	REPLACE CAPTIVE NUTS		790.00	SR Technics Switzerland
139576					72-23-04		Package I	008	REMOVAL OF CORROSION IN FAN DUCT PANELS ATTACHMENT HOLES BY BLENDING		1950.00	SR Technics Switzerland
139576					72-23-04		Package J	009	WASHER REPAIR OF THE CORROSION IN FAN DUCT PANELS ATTACHMENT HOLES		3055.00	SR Technics Switzerland
139576					72-23-04		Package N	013	REPAIR OF THE INNER SHROUD ATTACHEMENT HOLES BY BUSHING		595.00	SR Technics Switzerland
139576					72-23-04		Package P	015-94525	HOLES STRUT NR.5 AND NR.6 CASE A		1305.00	SR Technics Switzerland
139996	2406M74G01	EASA,FAA,CAAC,ANAC	61	28	72-21-05	FAN AND BOOSTER - SPINNER FRONT CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		590.00	SR Technics Switzerland
139996	2406M74G02	EASA,FAA,CAAC,ANAC			72-21-05		Package AA	026	REPLACEMENT OF DEFECTIVE SWAGED SELF-LOCKING INSERTS ON THE SPINNER FRONT CONE ASSEMBLY		840.00	SR Technics Switzerland
139996	337-005-118-0	EASA,FAA,CAAC,ANAC			72-21-05		Package AC	028	REPAIR BOLT HOLES BY BUSHING		1950.00	SR Technics Switzerland
139996	338-001-204-0	EASA,FAA,CAAC,ANAC			72-21-05		Package AI	034	BLEND ON ATTACHMENT SURFACE		595.00	SR Technics Switzerland
139996	338-085-202-0	EASA,FAA,CAAC,ANAC			72-21-05		Package G	006	REPAIR OF THE REAR OUTER DIAMETER BY BLENDING		565.00	SR Technics Switzerland
139996	338-085-203-0	EASA,FAA,CAAC,ANAC			72-21-05		Package O	014	REMOVE SURFACE DEFECTS AND REPAIR SULPHURIC ANODIZING, ANTI-EROSION PAINT AND WHITE SPIRAL MARK		2250.00	SR Technics Switzerland
139996	338-085-204-0	EASA,FAA,CAAC,ANAC			72-21-05		Package QI	016	REPAIR OF THE LOCATING DIAMETER ON THE SPINNER FRONT CONE BY PLASMA SPRAYING		1300.00	SR Technics Switzerland
139996					72-21-05		Package W	022	REPAIR BOLT HOLES		1145.00	SR Technics Switzerland
139998			17	21	72-23-18	FAN FRAME ASSEMBLY - OIL SUPPLY MAINFOLD AND NO.3 BEARING DRAIN TUE	Package A	CLN/INSP	CLEANING AND INSPECTION		470.00	SR Technics Switzerland
140019	1795M66P01	EASA,FAA,CAAC,ANAC	34	28	72-52-06	HIGH PRESSURE TURBINE ROTOR - BLADE RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		940.00	SR Technics Switzerland
140019	2002M15P01	EASA,FAA,CAAC,ANAC			72-52-06		Package B	INSP-001	BLENDING OF SEAL		305.00	SR Technics Switzerland
140019	2410M51P01	EASA,FAA,CAAC,ANAC			72-52-06		Package B	INSP-001	REMOVE HIGHMETAL		305.00	SR Technics Switzerland
140019					72-52-06		Package C	001	REPAIR OF PART/SERIAL NUMBERS THAT CANNOT BE READ ON BLADE RETAINER.		340.00	SR Technics Switzerland
140019					72-52-06		Package D	003	THERMAL SPRAY REPAIR OF DIAMETER E		7200.00	SR Technics Switzerland
140037	338-083-003-0	EASA,FAA,CAAC,ANAC	21	28	72-54-08	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 2	Package A		BASIC REPAIR		250.00	SRTAS
140037	338-083-004-0	EASA,FAA,CAAC,ANAC			72-54-08		Package A	INSP-001	VISUAL / DIMENSIONAL		250.00	SRTAS
140037	338-083-053-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C		MINOR REPAIR		1460.00	SRTAS
140037	338-083-054-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	1	AIRFOIL BLEND REPAIR		1460.00	SRTAS
140037	338-083-104-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1460.00	SRTAS
140037	338-083-105-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	32	RD 15-94412 - OVERCOATING OF APVS PROTECTION		1460.00	SRTAS
140037	338-083-154-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	4	REPAIR OF APVS COATING		1460.00	SRTAS
140037	338-083-155-0	EASA,FAA,CAAC,ANAC			72-54-08		Package C	INSP-001	VISUAL / DIMENSIONAL		1460.00	SRTAS
140037	338-083-204-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D		FULL REPAIR		3060.00	SRTAS
140037	338-083-205-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	1	AIRFOIL BLEND REPAIR.		3060.00	SRTAS
140037	338-083-254-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	15	RD 15-94438 - RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3060.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140037	338-083-255-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3060.00	SRTAS
140037	338-109-104-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	20	FULL BRAZING REPAIR		3060.00	SRTAS
140037	338-109-105-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	4	REPAIR OF APVS COATING.		3060.00	SRTAS
140037	338-109-106-0	EASA,FAA,CAAC,ANAC			72-54-08		Package D	INSP-001	VISUAL / DIMENSIONAL		3060.00	SRTAS
140037	338-109-107-0	EASA,FAA,CAAC,ANAC			72-54-08		Package E		ADDITIONAL WORKSCOPE		775.00	SRTAS
140037	338-109-108-0	EASA,FAA,CAAC,ANAC			72-54-08		Package E	19	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.		775.00	SRTAS
140037	338-109-109-0	EASA,FAA,CAAC,ANAC			72-54-08		Package F	72-0241	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB REPLACEMENT (WHEN PERFORMED INDEPENDENTLY)		770.00	SRTAS
140037	338-109-150-0	EASA,FAA,CAAC,ANAC			72-54-08		Package G	72-0241	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB REPLACEMENT (WHEN PERFORMED AS PART OF MINOR OI		645.00	SRTAS
140037	338-109-151-0	EASA,FAA,CAAC,ANAC			72-54-08		Package H	29	REPLACEMENT OF THE HONEYCOMB LINER		885.00	SRTAS
140037	338-109-204-0	EASA,FAA,CAAC,ANAC			72-54-08		Package I		BASIC REPAIR	7BE	630.00	SRTAS
140037	338-109-205-0	EASA,FAA,CAAC,ANAC			72-54-08		Package I	CLN-001	CLEANING	7BE	630.00	SRTAS
140037	338-109-206-0	EASA,FAA,CAAC,ANAC			72-54-08		Package I	INSP-001	VISUAL / DIMENSIONAL	7BE	630.00	SRTAS
140037	338-109-207-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J		MINOR REPAIR	7BE	1710.00	SRTAS
140037	338-109-208-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)	7BE	1710.00	SRTAS
140037	338-109-209-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J	31	BLEND REPAIR OF AIRFOILS	7BE	1710.00	SRTAS
140037	338-109-250-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J	32	OVERCOATING OF APVS PROTECTION	7BE	1710.00	SRTAS
140037	338-109-251-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J	CLN-001	CLEANING	7BE	1710.00	SRTAS
140037	338-109-304-0	EASA,FAA,CAAC,ANAC			72-54-08		Package J	INSP-001	VISUAL / DIMENSIONAL	7BE	1710.00	SRTAS
140037	338-109-305-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L		FULL REPAIR	7BE	3485.00	SRTAS
140037	338-109-306-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)	7BE	3485.00	SRTAS
140037	338-109-307-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L	31	BLEND REPAIR OF AIRFOILS	7BE	3485.00	SRTAS
140037	338-109-308-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L	4	REPAIR OF APVS COATING.	7BE	3485.00	SRTAS
140037	338-109-309-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L	CLN-001	CLEANING	7BE	3485.00	SRTAS
140037	338-109-350-0	EASA,FAA,CAAC,ANAC			72-54-08		Package L	INSP-001	VISUAL / DIMENSIONAL	7BE	3485.00	SRTAS
140037	338-109-351-0	EASA,FAA,CAAC,ANAC			72-54-08		Package M		ADDITIONAL WORKSCOPE	7BE	955.00	SRTAS
140037	340-303-001-0	EASA,FAA,CAAC,ANAC			72-54-08		Package M	19	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.	7BE	955.00	SRTAS
140037	340-303-101-0	EASA,FAA,CAAC,ANAC			72-54-08		Package N		ADDITIONAL WORKSCOPE	7BE	1470.00	SRTAS
140037	340-303-201-0	EASA,FAA,CAAC,ANAC			72-54-08		Package N	30	REPLACEMENT OF THE HONEYCOMB LINER	7BE	1470.00	SRTAS
140104			18	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - TGB BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
140131	1851M59P01	EASA,FAA,CAAC,ANAC	29	28	72-52-08	HIGH PRESSURE TURBINE ROTOR - NO. 4 BEARING RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		600.00	SR Technics Switzerland
140131	9339M45P03	EASA,FAA,CAAC,ANAC			72-52-08		Package B	INSP-001	RECONDITION OF SILVER PLATE		4045.00	SR Technics Switzerland
140131					72-52-08		Package C	INSP-001	BLENDING NUT WRENCH SLOTS		815.00	SR Technics Switzerland
140138	325-027-303-0	EASA,FAA,CAAC,ANAC	10	21	26-11-01	FIRE DETECTION HARNESSES MW0316 & MW0315	Package B	TEST	PRE TEST		370.00	SR Technics Switzerland
140138	325-027-403-0	EASA,FAA,CAAC,ANAC			26-11-01		Package D	LIGHT	LIGHT REPAIR		1230.00	SR Technics Switzerland
140138	325-027-404-0	EASA,FAA,CAAC,ANAC			26-11-01		Package E	MEDIUM	MEDIUM REPAIR		3900.00	SR Technics Switzerland
140138					26-11-01		Package F	HEAVY	HEAVY REPAIR		5480.00	SR Technics Switzerland
140138					26-11-01		Package G		OVERHAUL		8030.00	SR Technics Switzerland
140150	338-007-103-0	EASA,FAA,CAAC,ANAC,CAA UK	28	28	72-23-23	FAN FRAME ASSEMBLY - FAN SPLITTER FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		1010.00	SR Technics Switzerland
140150	340-002-602-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-23		Package C	INSP-001	SPOT AND TOUCH-UP REPAIR		1820.00	SR Technics Switzerland
140150					72-23-23		Package D	002	REPAIR OF DEFECTS ON THE LEADING EDGE		2080.00	SR Technics Switzerland
140150					72-23-23		Package F	005	REPAIR OF THE CONNECTING GROOVE		5400.00	SR Technics Switzerland
140150					72-23-23		Package G	006	REPAIR OF ATTACHMENT HOLE BY BUSHING		4005.00	SR Technics Switzerland
140151	340-002-805-0	EASA,FAA,CAAC,ANAC	21	28	72-23-01	FAN FRAME ASSEMBLY - HUB-12 STRUT	Package A	CLN/INSP	CLEANING AND INSPECTION		3795.00	SR Technics Switzerland
140151	340-002-851-0	EASA,FAA,CAAC,ANAC			72-23-01		Package AI	034	REPLACEMENT OF CENTERING PIN		805.00	SR Technics Switzerland
140151					72-23-01		Package B	002	REPLACEMENT OF RING LOCK STUDS		765.00	SR Technics Switzerland
140151					72-23-01		Package D	003	REPLACEMENT OF KEY LOCKED INSERTS		885.00	SR Technics Switzerland
140151					72-23-01		Package K	010	BLENDING OF FAN DUCT PANEL LUGS		1055.00	SR Technics Switzerland
140253	310A2020-10	EASA,FAA,CAAC,ANAC,CAA UK	21	21	71-21-37	FWD ENGINE MOUNT - ASSY	Package C		PREINSPECTION OF FORWARD ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, M	1890.00	SR Technics Switzerland
140253	310A2020-11	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS EXAMPLE: LINK ASSY REPLACEMENT (1 EA)		1015.00	SR Technics Switzerland
140253	310A2020-12	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS		2765.00	SR Technics Switzerland
140253	310A2020-5	EASA,FAA,CAAC,ANAC			71-21-37		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS EXAMPLE: MOUNT FITTING ASSY REPLACEN		4015.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140253					71-21-37		Package G		OVERHAUL	DISASSEMBLY, CLEANING, INSPECTION, ASS	5150.00	SR Technics Switzerland
140254	310A2021-4	EASA,FAA,CAAC,ANAC,CAA UK	24	21	71-21-37	FWD ENGINE MOUNT - FITTING ASSY - HANGER	Package A	CLN/INSP	CLEANING AND INSPECTION		955.00	SR Technics Switzerland
140254	310A2021-5	EASA,FAA,CAAC,ANAC			71-21-37		Package B	2-1	BUSHING REPLACEMENT	ITEM 245	850.00	SR Technics Switzerland
140254	310A2021-6	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package C	2-1	BUSHING REPLACEMENT	ITEM 240	685.00	SR Technics Switzerland
140254					71-21-37		Package D	2-1	SHEARPIN REPLACEMENT	ITEM 250	360.00	SR Technics Switzerland
140254					71-21-37		Package E	2-2	REPAIR BORE	ITEM 245A	4710.00	SR Technics Switzerland
140254					71-21-37		Package F	SRM 54-70-90	ALLOWABLE DAMAGE 3 FORWARD	WITH BUSHING	570.00	SR Technics Switzerland
140254					71-21-37		Package G	SRM 54-70-90	ALLOWABLE DAMAGE 7 FORWARD	WITH BUSHING	1125.00	SR Technics Switzerland
140254					71-21-37		Package H	SRM 54-70-90	ALLOWABLE DAMAGE 3, 7	WITHOUT BUSHING	1340.00	SR Technics Switzerland
140254					71-21-37		Package I	71-EO-528794-00	HANGER FITTING ASSY ADAPTION	P/N 310A2021-4 ONLY	4865.00	SR Technics Switzerland
140254					71-21-37		Package J	2-2	DECONTAMINATION IN BATH		545.00	SR Technics Switzerland
140261	310A2042-2	EASA,FAA,CAAC,ANAC	15	21	71-04-26	AFT ENGINE MOUNT - PIN-PAWL THRUST LINK	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
140261	310A2042-3	EASA,FAA,ANAC			71-04-26		Package D	3-1	THRUST LINK PIN		940.00	SR Technics Switzerland
140261					71-04-26		Package F	5-1	PAWL/LINK PIN		940.00	SR Technics Switzerland
140262	314A2610-1	EASA,FAA,CAAC,ANAC	20	35	78-11-37	EXHAUST - PRIMARY NOZZLE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3270.00	SR Technics Switzerland
140262	314A2610-62	EASA,FAA,CAAC,ANAC,CAA UK			78-11-37		Package B		DISASSEMBLY AND ASSEMBLY PRIMARY NOZZLE		4885.00	SR Technics Switzerland
140262	314A2610-68	EASA,FAA,CAAC,ANAC,CAA UK			78-11-37		Package H	1-1	FENCE REPLACEMENT		4770.00	SR Technics Switzerland
140262					78-11-37		Package I	1-2	WELD REPAIR OF A CRACKED NOZZLE ASSEMBLY		4770.00	SR Technics Switzerland
140262					78-11-37		Package J	1-2	WELD REPAIR OF HOLE AND PUNCTURE		7030.00	SR Technics Switzerland
140262					78-11-37		Package K	1-2	PATCH REPAIR OF HOLE AND PUNCTURE		7030.00	SR Technics Switzerland
140262					78-11-37		Package L	737-SL-78-060-A	PRIMARY EXHAUST NOZZLE FENCE REPLACEMENT PROCEDURE		435.00	SR Technics Switzerland
140262					78-11-37		Package M		REPAIR SHEETMETAL		1140.00	SR Technics Switzerland
140263	314A2620-1	EASA,FAA,CAAC,ANAC,CAA UK	9	21	78-11-38	CFM56-7B PLUG ASSEMBLY-PRIMARY	Package B	1-1	REPAIR OF CRACKED PLUG		1515.00	SR Technics Switzerland
140290	338-061-004-0	EASA,FAA,CAAC,ANAC	21	28	72-54-12	LOW PRESSURE TURBINE - OUTER STATIONARY AIR SEAL STG 1 - 4	Package A		STG 1 - BASIC REPAIR	7B, 7BE	220.00	SRTAS
140290	338-061-005-0	EASA,FAA,CAAC,ANAC			72-54-12		Package A	CLN-001	CLEANING		220.00	SRTAS
140290	338-061-104-0	EASA,FAA,CAAC,ANAC			72-54-12		Package A	INSP-001	VISUAL / DIMENSIONAL		220.00	SRTAS
140290	338-082-401-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B		STG 1 - FULL REPAIR	7B, 7BE	1070.00	SRTAS
140290	338-112-603-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1070.00	SRTAS
140290	338-112-604-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	003	WELD REPAIR OF CRACKS		1070.00	SRTAS
140290	338-112-605-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	006	APPLICATION OF APV5 COATING		1070.00	SRTAS
140290	338-112-606-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	007	REPAIR OF WEAR ON LOCATING DOWEL		1070.00	SRTAS
140290	338-112-607-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	CLN-001	CLEANING		1070.00	SRTAS
140290	338-112-650-0	EASA,FAA,CAAC,ANAC			72-54-12		Package B	INSP-001	VISUAL / DIMENSIONAL		1070.00	SRTAS
140290	338-112-651-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C		STG 1 - FULL REPAIR	7B, 7BE	1580.00	SRTAS
140290	338-112-704-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1580.00	SRTAS
140290	338-112-705-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	003	WELD REPAIR OF CRACKS		1580.00	SRTAS
140290	338-112-706-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	005	REMOVAL AND REPLACEMENT OF THRUST	REPAIR 005 OR SB 72-0567	1580.00	SRTAS
140290	338-112-707-0	EASA,FAA,CAAC			72-54-12		Package C	006	APPLICATION OF APV5 COATING		1580.00	SRTAS
140290	338-112-708-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	72-0567	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	REPAIR 005 OR SB 72-0567	1580.00	SRTAS
140290	338-112-709-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	CLN-001	CLEANING		1580.00	SRTAS
140290	338-112-803-0	EASA,FAA,CAAC,ANAC			72-54-12		Package C	INSP-001	VISUAL / DIMENSIONAL		1580.00	SRTAS
140290	338-112-804-0	EASA,FAA,CAAC,ANAC			72-54-12		Package D		STG 1 - ADDITIONAL WORKSCOPE	7B, 7BE	100.00	SRTAS
140290	338-112-805-0	EASA,FAA,CAAC			72-54-12		Package D	72-0249	CHAMFER HOOD TO PREVENT INTERFERENCE WITH CASE		100.00	SRTAS
140290	338-121-602-0	EASA,FAA,CAAC			72-54-12		Package E		STG 1 - ADDITIONAL WORKSCOPE	7B, 7BE	2260.00	SRTAS
140290					72-54-12		Package E	72-0567	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	STAND ALONE	2260.00	SRTAS
140290					72-54-12		Package F		STG 1 - ADDITIONAL WORKSCOPE	7B, 7BE	120.00	SRTAS
140290					72-54-12		Package F	011	REPLACEMENT OF COVER STRIP		120.00	SRTAS
140290					72-54-12		Package G		STG-2 - BASIC REPAIR	7B, 7BE	225.00	SRTAS
140290					72-54-12		Package G	CLN-001	CLEANING		225.00	SRTAS
140290					72-54-12		Package G	INSP-001	VISUAL / DIMENSIONAL		225.00	SRTAS
140290					72-54-12		Package H		STG 2 - FULL REPAIR	7B, 7BE	1060.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140290					72-54-12		Package H	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1060.00	SRTAS
140290					72-54-12		Package H	003	WELD REPAIR OF CRACKS		1060.00	SRTAS
140290					72-54-12		Package H	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1060.00	SRTAS
140290					72-54-12		Package H	009	WELD BUILD UP OF ANTI ROTATION SLOT		1060.00	SRTAS
140290					72-54-12		Package H	INSP-001	VISUAL / DIMENSIONAL		1060.00	SRTAS
140290					72-54-12		Package I		STG 2 - ADDITIONAL WORKSCOPE	7B, 7BE	160.00	SRTAS
140290					72-54-12		Package I	72-0197	CHAMFER LOCK TO PREVENT INTERFERENCE WITH NGV		160.00	SRTAS
140290					72-54-12		Package J		STG 2 - ADDITIONAL WORKSCOPE	7B, 7BE	255.00	SRTAS
140290					72-54-12		Package J	72-0249	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		255.00	SRTAS
140290					72-54-12		Package K		STG-3 - BASIC REPAIR	7B	225.00	SRTAS
140290					72-54-12		Package K	CLN-001	CLEANING		225.00	SRTAS
140290					72-54-12		Package K	INSP-001	VISUAL / DIMENSIONAL		225.00	SRTAS
140290					72-54-12		Package L		STG 3 - FULL REPAIR	7B	1130.00	SRTAS
140290					72-54-12		Package L	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1130.00	SRTAS
140290					72-54-12		Package L	003	WELD REPAIR OF CRACKS		1130.00	SRTAS
140290					72-54-12		Package L	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1130.00	SRTAS
140290					72-54-12		Package L	009	REPLACEMENT OF THE ANTI ROTATION LOCK		1130.00	SRTAS
140290					72-54-12		Package L	INSP-001	VISUAL / DIMENSIONAL		1130.00	SRTAS
140290					72-54-12		Package M		STG 3 - ADDITIONAL WORKSCOPE	7B	255.00	SRTAS
140290					72-54-12		Package M	72-0249	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		255.00	SRTAS
140290					72-54-12		Package N		STG 4 - FULL REPAIR	7B	815.00	SRTAS
140290					72-54-12		Package N	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		815.00	SRTAS
140290					72-54-12		Package N	003	WELD REPAIR OF CRACKS		815.00	SRTAS
140290					72-54-12		Package N	004	REPLACE ANTI ROTATION LOCK		815.00	SRTAS
140290					72-54-12		Package N	INSP-001	VISUAL / DIMENSIONAL		815.00	SRTAS
140290					72-54-12		Package O		STG 4 - ADDITIONAL WORKSCOPE	7B	185.00	SRTAS
140290					72-54-12		Package O	002	REPLACEMENT OF RETAINING HOOK		185.00	SRTAS
140290					72-54-12		Package Q		STG 3 - FULL REPAIR	7BE	1430.00	SRTAS
140290					72-54-12		Package Q	001	REPLACE HONEYCOMB LINER		1430.00	SRTAS
140290					72-54-12		Package Q	003	WELD REPAIR OF CRACKS		1430.00	SRTAS
140290					72-54-12		Package Q	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1430.00	SRTAS
140290					72-54-12		Package Q	009	WELD BUILD UP OF ANTI ROTATION SLOT		1430.00	SRTAS
140290					72-54-12		Package Q	CLN-001	CLEANING		1430.00	SRTAS
140290					72-54-12		Package Q	INSP-001	VISUAL / DIMENSIONAL		1430.00	SRTAS
140290					72-54-12		Package R		STG 4 - FULL REPAIR	7BE	1430.00	SRTAS
140290					72-54-12		Package R	001	REPLACE HONEYCOMB LINER		1430.00	SRTAS
140290					72-54-12		Package R	002	REPLACEMENT OF BRAZED PARTS (RETAINING HOOK)		1430.00	SRTAS
140290					72-54-12		Package R	003	WELD REPAIR OF CRACKS		1430.00	SRTAS
140290					72-54-12		Package R	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1430.00	SRTAS
140290					72-54-12		Package R	CLN-001	CLEANING		1430.00	SRTAS
140290					72-54-12		Package R	INSP-001	VISUAL / DIMENSIONAL		1430.00	SRTAS
140303	310A2022-3	EASA,FAA,CAAC,ANAC	14	21	71-21-37	FWD ENGINE MOUNT - LINK ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1125.00	SR Technics Switzerland
140303	310A2022-4	EASA,FAA,CAAC,ANAC			71-21-37		Package B	3-1	LINK ASSEMBLY		530.00	SR Technics Switzerland
140303					71-21-37		Package C	3-2	REPAIR AND REFINISH THE LINK		1490.00	SR Technics Switzerland
140303					71-21-37		Package I	3-2	REPAIR DECONTAMINATION IN BATH		545.00	SR Technics Switzerland
140303					71-21-37		Package K	54-70-90	FORWARD MOUNT HANGER BLEND AND SPOTFACE REPAIR		530.00	SR Technics Switzerland
140303					71-21-37		Package L	54-70-90	ALLOWABLE DAMAGE 8 DECONTAMINATION IN BATH		535.00	SR Technics Switzerland
140319	325-016-801-0	EASA,FAA,CAAC,ANAC	3	21	79-21-53	BOX-DMS	Package B	TEST	INSPECTION AND TESTING		340.00	SR Technics Switzerland
140319					79-21-53		Package C		REPAIR		380.00	SR Technics Switzerland
140762	310A2024-2	EASA,FAA,CAAC,ANAC	2	21	71-21-37	CFM56-7B PIN-SHEAR MOUNT ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		125.00	SR Technics Switzerland
140763	310A2028-11	EASA,FAA,CAAC,ANAC	23	21	71-21-37	FWD ENGINE MOUNT - FITTING ASSY - FAN CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1075.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140763	310A2028-12	EASA,FAA,CAAC,ANAC			71-21-37		Package B	4-1	BUSHING REPLACEMENT	ITEM 45	820.00	SR Technics Switzerland
140763	310A2028-13	EASA,FAA,CAAC,ANAC			71-21-37		Package C	4-1	BUSHING REPLACEMENT	ITEM 40	645.00	SR Technics Switzerland
140763	310A2028-15	EASA,FAA,CAAC,ANAC			71-21-37		Package D	4-1	SHEAR PIN REPLACEMENT		350.00	SR Technics Switzerland
140763					71-21-37		Package E	4-2	REPAIR GROUNDBORE	ITEM (45A)	3185.00	SR Technics Switzerland
140763					71-21-37		Package F	4-2	REPAIR GROUNDBORE DECONTAMINATION IN BATH		535.00	SR Technics Switzerland
140763					71-21-37		Package G	SRM 54-70-90	BLENDING FAN CASE FITTING		1700.00	SR Technics Switzerland
140763					71-21-37		Package H	SRM 54-70-90	ALLOWABLE DAMAGE 4, 6 DECONTAMINATION IN BATH		540.00	SR Technics Switzerland
144730	338-077-501-0	EASA,FAA,CAAC,ANAC	31	28	72-54-05	LOW PRESSURE TURBINE - ROTOR SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
144730	338-077-502-0	EASA,FAA,CAAC,ANAC,CAA UK			72-54-05		Package B	INSP-001	REMOVAL OF HIGH MEATAL		660.00	SR Technics Switzerland
144730	340-301-702-0	EASA,FAA,CAAC,ANAC			72-54-05		Package H	007	REPAIR OF THE NEAR DIAMETER MATING THE LPT FORWARD ROTATING AIR SEAL BY PLASMA SPRAYING		2850.00	SR Technics Switzerland
144730					72-54-05		Package I	008	REPAIR OF THE DIAMETER LOCATING THE LPT FORWARD ROTATING OIL SEAL	DIA G	2815.00	SR Technics Switzerland
144730					72-54-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	845.00	SR Technics Switzerland
144739	2406M75G01	EASA,FAA,CAAC,ANAC	43	28	72-21-05	FAN AND BOOSTER - SPINNER REAR CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		705.00	SR Technics Switzerland
144739	338-001-304-0	EASA,FAA,CAAC,ANAC			72-21-05		Package AE	030	REPAIR OF THE FRONT FLANGE OF THE REAR CONE BY BLENDING		1480.00	SR Technics Switzerland
144739	338-001-305-0	EASA,FAA,CAAC,ANAC			72-21-05		Package AG	032	REPAIR OF SPINNER REAR CONE AFT FLANGE BOLT HOLES		2450.00	SR Technics Switzerland
144739	340-000-205-0	EASA,FAA,CAAC,ANAC,CAA UK			72-21-05		Package B	001	REMOVAL OF SURFACE DEFECTS AND SPOT TOUCH-UP OF OXIDE FILM COATING		1230.00	SR Technics Switzerland
144739					72-21-05		Package C	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE REAR CONE		1225.00	SR Technics Switzerland
144739					72-21-05		Package R	017	REPAIR OF THE SPINNER REAR CONE DIAMETERS THAT LOCATES THE SPINNER FRONT CONE AND THE FAN DISK		3425.00	SR Technics Switzerland
144739					72-21-05		Package Z	025	REPAIR OF THE SPINNER REAR CONE SURFACES THAT MATES WITH THE FAN BLADES, THE FAN DISK AND THE SPINNE		4190.00	SR Technics Switzerland
144755	338-001-905-0	EASA,FAA,CAAC,ANAC	36	28	72-21-04	FAN AND BOOSTER - BOOSTER SPOOL	Package A	CLN/INSP	CLEANING AND INSPECTION		1905.00	SR Technics Switzerland
144755	338-001-906-0	EASA,FAA,CAAC,ANAC			72-21-04		Package B	001	REPLACEMENT OF THE HI-LOCK FASTENERS AND/OR THE SEALING FLANGE		2375.00	SR Technics Switzerland
144755	340-000-814-0	EASA,FAA,CAAC,ANAC			72-21-04		Package C	002	SPOT TOUCH-UP OR FULL RECONDITIONING OF THE CHROMIC OR SULFURIC ANOD THE BOOSTER SPOOL SEALING FLANGE		410.00	SR Technics Switzerland
144755	340-000-815-0	EASA,FAA,CAAC,ANAC			72-21-04		Package D	003	REPAIR OF ILLEGIBLE PART MARKINGS		370.00	SR Technics Switzerland
144755	340-000-816-0	EASA,FAA,CAAC,ANAC			72-21-04		Package E		REMOVAL OF THE THREADED PINS/COUNTERWEIGHTS		410.00	SR Technics Switzerland
144755	340-000-824-0	EASA,FAA,CAAC,ANAC			72-21-04		Package E		REMOVE BOOSTER SPOOL FWD FLANGE PLUG		410.00	SR Technics Switzerland
144755	340-000-825-0	EASA,FAA,CAAC,ANAC			72-21-04		Package J	009	REPLACEMENT OF LUBRICANT COATING		1185.00	SR Technics Switzerland
144755	340-000-826-0	EASA,FAA,CAAC,ANAC			72-21-04		Package K	010	TOUCH UP OF SEAL TEETH		2445.00	SR Technics Switzerland
144755					72-21-04		Package SB00	72-0295	INSPECTION OF THE BOOSTER SPOOL		2130.00	SR Technics Switzerland
144755					72-21-04		Package SB01	72-0296	INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL		535.00	SR Technics Switzerland
144755					72-21-04		Package SB02	72-0632	BOOSTER SPOOL FORWARD FLANGE INSPECTION		400.00	SR Technics Switzerland
144755					72-21-04		Package SB03	72-0634	BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD		400.00	SR Technics Switzerland
144759	338-010-502-0	EASA,FAA,CAAC,ANAC	32	28	72-22-02	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
144759	340-033-005-0	EASA,FAA,CAAC,ANAC			72-22-02		Package B	001	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE NO. 1 BEARING SUPPORT ASSEMBLY		595.00	SR Technics Switzerland
144759					72-22-02		Package L	011	FINAL CLEANING AND CONDITIONING		165.00	SR Technics Switzerland
144776	1968M59G01	EASA,FAA,CAAC,ANAC	33	28	72-42-01	COMBUSTION CHAMBER (SAC) - OUTER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		770.00	SR Technics Switzerland
144776	9531M61G06	EASA,FAA,CAAC,ANAC			72-42-01		Package B	001	WELD REPAIR AND RESIZE OF THE HS188 OUTER COWL		1595.00	SR Technics Switzerland
144778	336-026-302-0	EASA,FAA,CAAC,ANAC	39	28	72-54-16	LOW PRESSURE TURBINE - FWD ROTATING AIR SEAL ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		940.00	SR Technics Switzerland
144778					72-54-16		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINERS		4525.00	SR Technics Switzerland
144778					72-54-16		Package C	002	REPAIR OF THE ABRADABLE COATING	DIA H	1960.00	SR Technics Switzerland
144778					72-54-16		Package D	003	REPAIR OF THE OUTER DIAMETER MATING THE LPT ROTOR SUPPORT BY PLASMA SPRAYING		1960.00	SR Technics Switzerland
144778					72-54-16		Package E	004	REPAIR OF THE INNER DIAMETER MATING THE LPT ROTOR SUPPORT, BY PLASMA S DIA B		2025.00	SR Technics Switzerland
144795	338-010-302-0	EASA,FAA,CAAC,ANAC	55	28	72-53-07	STAGE 1 LPT NOZZLE - INNER AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		605.00	SR Technics Switzerland
144795	338-111-002-0	EASA,FAA,CAAC,ANAC			72-53-07		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINER		5625.00	SR Technics Switzerland
144795	338-111-003-0	EASA,FAA,CAAC,ANAC			72-53-07		Package C	002	REPLACEMENT OF THE PLASMA THERMAL COATING ON THE FACE MATING WITH THE STAGE 1 LPT NOZZLE SEGMENT		2330.00	SR Technics Switzerland
144795	338-111-050-0	EASA,FAA,CAAC,ANAC			72-53-07		Package E	004	REPAIR OF THE COOLING AIR DUCT BORES		3570.00	SR Technics Switzerland
144795	338-111-051-0	EASA,FAA,CAAC,ANAC			72-53-07		Package G	006	REPAIR OF THE DIAMETER LOCATING THE STAGE 1 LPT NOZZLE STATIONARY AIR SEAL		2900.00	SR Technics Switzerland
144795	340-311-001-0	EASA,FAA,CAAC,ANAC			72-53-07		Package H	007	REPLACEMENT OR RESTORE OF THE KEYING PIN		935.00	SR Technics Switzerland
144795					72-53-07		Package L	011	BLENDING OR BRAZING OF CRACKS BTW FRONT FLANGE AND REAR FLANGE		2025.00	SR Technics Switzerland
144795					72-53-07		Package SB00	72-0801	INTRODUCTION OF A NEW FRONT FLANGE WITH 6 VENTILATION HOLES AND REWORK OF THE OLD PART		745.00	SR Technics Switzerland
144800	338-085-402-0	EASA,FAA,CAAC,ANAC	25	28	72-54-13	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 3 - 4	Package A		STG 3/4 - BASIC REPAIR		250.00	SRTAS
144800	338-085-403-0	EASA,FAA,CAAC,ANAC			72-54-13		Package A	INSP-001	VISUAL / DIMENSIONAL		250.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144800	338-085-404-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AA		STG 3 - ADDITIONAL	7BE, AS PART OF FULL REPAIR	1320.00	SRTAS
144800	338-085-405-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AA		STG 3 - ADDITIONAL	AS PART OF FULL REPAIR	1320.00	SRTAS
144800	338-085-452-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AA	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS PART OF FULL REPAIR		1320.00	SRTAS
144800	338-085-502-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AA	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS PART OF FULL REPA	7BE	1320.00	SRTAS
144800	338-085-503-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AB		STG 3 - ADDITIONAL		2850.00	SRTAS
144800	338-085-504-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AB		STG 3 - ADDITIONAL	7BE	2850.00	SRTAS
144800	338-109-702-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AB	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS STAND ALONE REPA	WHEN PERFORMED INDEPENDENTLY	2850.00	SRTAS
144800	338-109-704-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AC		STG 3 - ADDITIONAL	7BE	390.00	SRTAS
144800	338-109-705-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AC	033	OXIDES REMOVAL	7BE	390.00	SRTAS
144800	338-109-802-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AD		STG 3 - ADDITIONAL		1000.00	SRTAS
144800	338-109-804-0	EASA,FAA,CAAC,ANAC			72-54-13		Package AD	021	REPLACEMENT OF THE HONEYCOMB LINER	(HONEYCOMB,HONEYCOMB SUPPORT SHIE	1000.00	SRTAS
144800	338-109-805-0	EASA,FAA,CAAC,ANAC			72-54-13		Package C		STG 3 - MINOR REPAIR		1460.00	SRTAS
144800	338-110-102-0	EASA,FAA,CAAC,ANAC			72-54-13		Package C	001	AIRFOIL BLEND REPAIR		1460.00	SRTAS
144800	338-110-103-0	EASA,FAA,CAAC,ANAC			72-54-13		Package C	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1460.00	SRTAS
144800	338-110-202-0	EASA,FAA,CAAC,ANAC			72-54-13		Package C	INSP-001	VISUAL / DIMENSIONAL		1460.00	SRTAS
144800	338-110-203-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E		STG 3 - FULL REPAIR		3020.00	SRTAS
144800	338-161-604-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	001	AIRFOIL BLEND REPAIR		3020.00	SRTAS
144800	338-161-605-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	003	REPAIR CRACKS BY DIFFUSION BRAZING.		3020.00	SRTAS
144800	338-161-607-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	005	RECONDITIONING OF THE VAPOUR PHASE ALUMINISATION		3020.00	SRTAS
144800	338-161-608-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3020.00	SRTAS
144800	338-161-704-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3020.00	SRTAS
144800	338-161-705-0	EASA,FAA,CAAC,ANAC			72-54-13		Package E	INSP-001	VISUAL / DIMENSIONAL		3020.00	SRTAS
144800	338-161-707-0	EASA,FAA,CAAC,ANAC			72-54-13		Package F		STG 3 - ADDITIONAL WORKSCOPE		700.00	SRTAS
144800	338-161-708-0	EASA,FAA,CAAC,ANAC			72-54-13		Package F	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.		700.00	SRTAS
144800	340-303-301-0	EASA,FAA,CAAC,ANAC			72-54-13		Package G		STG 3 - ADDITIONAL WORKSCOPE		740.00	SRTAS
144800	340-303-401-0	EASA,FAA,CAAC,ANAC			72-54-13		Package G	72-0241	REWORK FOR OVERSPEED IMPROVEMENT	(WHEN PERFORMED INDEPENDENTLY)	740.00	SRTAS
144800	340-303-501-0	EASA,FAA,CAAC,ANAC			72-54-13		Package H		STG 3 - ADDITIONAL WORKSCOPE		635.00	SRTAS
144800	340-303-601-0	EASA,FAA,CAAC,ANAC			72-54-13		Package H	72-0241	REWORK FOR OVERSPEED IMPROVEMENT	(PART OF MINOR OR FULL REPAIR)	635.00	SRTAS
144800					72-54-13		Package I		STG 4 - ADDITIONAL WORKSCOPE		1570.00	SRTAS
144800					72-54-13		Package I	021	REPLACE HONEYCOMB LINER		1570.00	SRTAS
144800					72-54-13		Package J		STG 4 - MINOR REPAIR		310.00	SRTAS
144800					72-54-13		Package J	001	AIRFOIL BLEND REPAIR.		310.00	SRTAS
144800					72-54-13		Package J	INSP-001	VISUAL / DIMENSIONAL		310.00	SRTAS
144800					72-54-13		Package K		STG 4 - MEDIUM REPAIR		1460.00	SRTAS
144800					72-54-13		Package K	001	AIRFOIL BLEND REPAIR.		1460.00	SRTAS
144800					72-54-13		Package K	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		1460.00	SRTAS
144800					72-54-13		Package K	INSP-001	VISUAL / DIMENSIONAL		1460.00	SRTAS
144800					72-54-13		Package L		STG 4 - FULL REPAIR		3020.00	SRTAS
144800					72-54-13		Package L	001	AIRFOIL BLEND REPAIR		3020.00	SRTAS
144800					72-54-13		Package L	003	REPAIR CRACKS BY DIFFUSION BRAZING.		3020.00	SRTAS
144800					72-54-13		Package L	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		3020.00	SRTAS
144800					72-54-13		Package L	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3020.00	SRTAS
144800					72-54-13		Package L	INSP-001	VISUAL / DIMENSIONAL		3020.00	SRTAS
144800					72-54-13		Package M		STG 4 - ADDITIONAL WORKSCOPE		620.00	SRTAS
144800					72-54-13		Package M	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.		620.00	SRTAS
144800					72-54-13		Package O		STG 3 - MINOR REPAIR	7BE	965.00	SRTAS
144800					72-54-13		Package O	031	BLEND REPAIR OF AIRFOILS		965.00	SRTAS
144800					72-54-13		Package O	CLN-001	CLEANING		965.00	SRTAS
144800					72-54-13		Package O	INSP-001	VISUAL / DIMENSIONAL		965.00	SRTAS
144800					72-54-13		Package P		STG 3 - FULL REPAIR	7BE	2125.00	SRTAS
144800					72-54-13		Package P	009	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINER		2125.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144800					72-54-13		Package P	031	AIRFOIL BLEND REPAIR		2125.00	SRTAS
144800					72-54-13		Package P	CLN-001	CLEANING		2125.00	SRTAS
144800					72-54-13		Package P	INSP-001	VISUAL / DIMENSIONAL		2125.00	SRTAS
144800					72-54-13		Package Q		STG 3 - ADDITIONAL	7BE	1090.00	SRTAS
144800					72-54-13		Package Q	012	RECONDITIONING OF THE AR SLOT, LUG AND HARD FACE MATING BY WELDING		1090.00	SRTAS
144800					72-54-13		Package R		STG 3 - ADDITIONAL	7BE	1320.00	SRTAS
144800					72-54-13		Package R	015	BRAZING REPAIR OF THE OSAS MATING SURFACE		1320.00	SRTAS
144800					72-54-13		Package S		STG 3/4 BASIC REPAIR	7BE	510.00	SRTAS
144800					72-54-13		Package S	CLN-001	CLEANING 001		510.00	SRTAS
144800					72-54-13		Package S	INSP-001	VISUAL / DIMENSIONAL		510.00	SRTAS
144800					72-54-13		Package T		STG 4 - MINOR REPAIR	7BE	965.00	SRTAS
144800					72-54-13		Package T	031	BLEND REPAIR OF AIRFOILS		965.00	SRTAS
144800					72-54-13		Package T	CLN-001	CLEANING		965.00	SRTAS
144800					72-54-13		Package T	INSP-001	VISUAL / DIMENSIONAL		965.00	SRTAS
144800					72-54-13		Package U		STG 4 - FULL REPAIR	7BE	2125.00	SRTAS
144800					72-54-13		Package U	009	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINER		2125.00	SRTAS
144800					72-54-13		Package U	031	AIRFOIL BLEND REPAIR		2125.00	SRTAS
144800					72-54-13		Package U	CLN-001	CLEANING		2125.00	SRTAS
144800					72-54-13		Package U	INSP-001	VISUAL / DIMENSIONAL		2125.00	SRTAS
144800					72-54-13		Package V		STG 4 - ADDITIONAL	7BE	1090.00	SRTAS
144800					72-54-13		Package V	012	RECONDITIONING OF THE AR SLOT, LUG AND HARD FACE MATING BY WELDING		1090.00	SRTAS
144800					72-54-13		Package W		STG 4 - ADDITIONAL	7BE	1320.00	SRTAS
144800					72-54-13		Package W	015	BRAZING REPAIR OF THE OSAS MATING SURFACE		1320.00	SRTAS
144800					72-54-13		Package X		STG 4 - ADDITIONAL		1320.00	SRTAS
144800					72-54-13		Package X		STG 4 - ADDITIONAL	7BE	1320.00	SRTAS
144800					72-54-13		Package X	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS PART OF FULL REPA AS PART OF FULL REPAIR		1320.00	SRTAS
144800					72-54-13		Package Y		STG 4 - ADDITIONAL	7BE	2850.00	SRTAS
144800					72-54-13		Package Y		STG 4 - ADDITIONAL		2850.00	SRTAS
144800					72-54-13		Package Y	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE STAND ALONE REPAIR	WHEN PERFORMED INDEPENDENTLY	2850.00	SRTAS
144800					72-54-13		Package Z		STG 4 - ADDITIONAL	7BE	390.00	SRTAS
144800					72-54-13		Package Z	033	OXIDES REMOVAL	7BE	390.00	SRTAS
601631	340-160-402-0	EASA,FAA,CAAC,ANAC	18	28	72-21-21	FAN AND BOOSTER - FAN RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		660.00	SR Technics Switzerland
603670	301-475-904-6	EASA,FAA,CAAC,ANAC	18	28	72-22-00	NO.1 AND NO.2 BEARING SUPPORT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		75.00	SR Technics Switzerland
603670	337-011-702-6	EASA,FAA,CAAC,ANAC			72-22-00		Package B	ASSEMBLY-001	SHIM WIDTH GRINDING		210.00	SR Technics Switzerland
607353	325-026-701-0	EASA,FAA,CAAC,ANAC	22	21	71-51-01	NACELLE HARNESS - MW0312	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607353	325-045-301-0	EASA,FAA,CAAC,ANAC			71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1655.00	SR Technics Switzerland
607353					71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	3725.00	SR Technics Switzerland
607353					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	5105.00	SR Technics Switzerland
607353					71-51-01		Package SB00	72-0462	INTRODUCTION OF A NEW MW0312 HARNESS WITH A NEW DP1204 CONNECTOR / IN CONIUNCTION WITH PACKAGE MEDIUM		150.00	SR Technics Switzerland
607354	325-035-501-0	EASA,FAA,CAAC,ANAC	21	21	71-51-01	NACELLE HARNESS - MW0301	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607354	325-035-502-0	EASA,FAA,CAAC,ANAC			71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1135.00	SR Technics Switzerland
607354	325-035-503-0	EASA,FAA,CAAC,ANAC			71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1780.00	SR Technics Switzerland
607354					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	2025.00	SR Technics Switzerland
607354					71-51-01		Package SB00	72-0560	INTRODUCTION OF A NEW MW0301 HARNESS WITH A NEW ROUTING	IN CONIUNCTION WITH PACKAGE LIGHT, M	360.00	SR Technics Switzerland
607355	325-026-901-0	EASA,FAA,CAAC,ANAC	20	21	71-51-01	NACELLE HARNESS - MW0302	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	380.00	SR Technics Switzerland
607355	325-026-902-0	EASA,FAA,CAAC,ANAC			71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1110.00	SR Technics Switzerland
607355					71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1510.00	SR Technics Switzerland
607355					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	1960.00	SR Technics Switzerland
607356	325-015-001-0	EASA,FAA,CAAC,ANAC	20	21	71-51-01	NACELLE HARNESS - MW0303	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607356					71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
607356					71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1510.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
607356					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	2965.00	SR Technics Switzerland
607357	325-035-201-0	EASA,FAA,CAAC,ANAC	20	21	71-51-01	NACELLE HARNESS - MW0304	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607357					71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
607357					71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1510.00	SR Technics Switzerland
607357					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	2965.00	SR Technics Switzerland
607358	325-026-801-0	EASA,FAA,CAAC,ANAC	20	21	71-51-01	NACELLE HARNESS - MW0313	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607358					71-51-01		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
607358					71-51-01		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1510.00	SR Technics Switzerland
607358					71-51-01		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	2965.00	SR Technics Switzerland
609461	325-034-901-0	EASA,FAA,CAAC,ANAC	22	21	73-24-03	ELECTRICAL HARNESS J5	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	395.00	SR Technics Switzerland
609461	325-034-902-0	EASA,FAA,CAAC,ANAC			73-24-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
609461	325-101-102-0	EASA,FAA,CAAC,ANAC			73-24-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	3785.00	SR Technics Switzerland
609461					73-24-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	5260.00	SR Technics Switzerland
609461					73-24-03		Package SB00	72-0101	NEW ROUTING OF J5 AND J6 HARNESSES	IN CONJUNCTION WITH PACKAGE LIGHT, M	270.00	SR Technics Switzerland
609462	325-035-001-0	EASA,FAA,CAAC,ANAC	22	21	73-24-03	ELECTRICAL HARNESS J6	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
609462	325-035-002-0	EASA,FAA,CAAC,ANAC			73-24-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1190.00	SR Technics Switzerland
609462	325-035-003-0	EASA,FAA,CAAC,ANAC			73-24-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	3800.00	SR Technics Switzerland
609462					73-24-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	5100.00	SR Technics Switzerland
609462					73-24-03		Package SB00	72-0101	NEW ROUTING OF J5 AND J6 HARNESSES	IN CONJUNCTION WITH PACKAGE LIGHT, M	270.00	SR Technics Switzerland
609463	325-025-701-0	EASA,FAA,CAAC,ANAC	20	21	73-24-03	ELECTRICAL HARNESS J7	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	395.00	SR Technics Switzerland
609463	325-025-702-0	EASA,FAA,CAAC,ANAC			73-24-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
609463	325-042-801-0	EASA,FAA,ANAC			73-24-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	3785.00	SR Technics Switzerland
609463					73-24-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	5015.00	SR Technics Switzerland
609489	325-025-201-0	EASA,FAA,CAAC,ANAC	23	21	73-24-04	ELECTRICAL HARNESS J9	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	330.00	SR Technics Switzerland
609489	325-025-202-0	EASA,FAA,CAAC,ANAC			73-24-04		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
609489	325-043-401-0	EASA,FAA,CAAC,ANAC			73-24-04		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	5395.00	SR Technics Switzerland
609489	325-043-402-0	EASA,FAA,CAAC,ANAC			73-24-04		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	7890.00	SR Technics Switzerland
609489					73-24-04		Package SB00	73-0058	HARNESSES WITH IMPROVED OR REWORKED DESIGN	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609489					73-24-04		Package SB01	73-0198	INTRODUCTION OF NEW CONNECTORS FOR ELECTRICAL HARNESSES	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609491	325-027-701-0	EASA,FAA,CAAC,ANAC	22	21	73-24-05	ELECTRICAL HARNESS CJ9	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	330.00	SR Technics Switzerland
609491	325-027-702-0	EASA,FAA,CAAC,ANAC			73-24-05		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
609491	325-045-201-0	EASA,FAA,CAAC,ANAC			73-24-05		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1890.00	SR Technics Switzerland
609491	325-045-202-0	EASA,FAA,CAAC,ANAC			73-24-05		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	3765.00	SR Technics Switzerland
609491	325-045-501-0	EASA,FAA,CAAC,ANAC			73-24-05		Package SB00	73-0089	REWORK OF THE CJ9 HARNESS AND DELETION OF THE DUMMY PECEPTACLE BRACH	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609491	325-045-502-0	EASA,FAA,CAAC,ANAC			73-24-05		Package SB01	73-0142	DELETION OF CJ9 WIRING HARNESS TS BRANCH FOR NON-PMUX ENGINE IN THE FI	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609491					73-24-05		Package SB02	73-0198	INTRODUCTION OF NEW CONNECTIONS FOR ELECTRICAL HARNESSES	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609492	325-025-401-0	EASA,FAA,CAAC,ANAC	20	21	73-24-05	ELECTRICAL HARNESS CJ10	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	270.00	SR Technics Switzerland
609492	325-025-402-0	EASA,FAA,CAAC,ANAC			73-24-05		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
609492					73-24-05		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1550.00	SR Technics Switzerland
609492					73-24-05		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	3325.00	SR Technics Switzerland
609492					73-24-05		Package SB00	73-0198	INTRODUCTION OF NEW CONNECTORS	IN CONJUNCTION WITH PACKAGE MEDIUM	270.00	SR Technics Switzerland
609503	325-034-801-0	EASA,FAA,CAAC,ANAC	22	21	73-24-04	ELECTRICAL HARNESS J10	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	315.00	SR Technics Switzerland
609503	325-034-802-0	EASA,FAA,CAAC,ANAC			73-24-04		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1045.00	SR Technics Switzerland
609503	325-043-501-0	EASA,FAA,CAAC,ANAC			73-24-04		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	5240.00	SR Technics Switzerland
609503	325-043-502-0	EASA,FAA,CAAC,ANAC			73-24-04		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	7670.00	SR Technics Switzerland
609503	325-043-503-0	EASA,FAA,CAAC,ANAC			73-24-04		Package SB00	73-0058	J9 AND J10 HARNESSES WITH IMPROVED OR REWORKED DESIGN	IN CONJUNCTION WITH PACKAGE MEDIUM	920.00	SR Technics Switzerland
609503	325-043-505-0	EASA,FAA,CAAC,ANAC			73-24-04		Package SB01	73-0085	INTRODUCTION OF NEW J10 HARNESSES OR REWORK OF THE OLD ONES	IN CONJUNCTION WITH PACKAGE MEDIUM	920.00	SR Technics Switzerland
609503					73-24-04		Package SB02	73-0198	INTRODUCTION OF NEW CONNECTORS FOR ELECTRICAL HARNESSES	IN CONJUNCTION WITH PACKAGE MEDIUM	520.00	SR Technics Switzerland
610379	340-051-301-0	EASA,FAA,CAAC,ANAC	3	28	72-62-08	TRANSFER GEAR BOX TUBE SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
610972	056-000-217-0	EASA,FAA,CAAC,ANAC	3	21	72-56-01	CFM56 OIL SCAVENGE ELBOW	Package S	018	ADJUSTMENT NEW ELBOW		150.00	SR Technics Switzerland
610972					72-56-01		Package S	018	ADJUSTMENT OLD ELBOW		150.00	SR Technics Switzerland

For new capability, please refer to our homepage <https://cpc.srtechnics.com>

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
610972					72-56-01		Package S	018	PREREQUISIT ELBOW ADJUST		150.00	SR Technics Switzerland
610972					72-56-01		Package S	018	REPLACE ELBOW NUT		150.00	SR Technics Switzerland
613126	1523M69P01	EASA,FAA,CAAC,ANAC	23	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		420.00	SR Technics Switzerland
613126	1523M71G06	EASA,FAA,CAAC,ANAC,CAA UK			72-53-02		Package B	INSP-001	BLENDING THE MID HEAT SHIELD WORN AREA		350.00	SR Technics Switzerland
613126	1523M71G07	EASA,FAA,CAAC,ANAC,CAA UK			72-53-02		Package Z	25	BRAZE REPAIR OF THE FORWARD HEAT SHIELD		650.00	SR Technics Switzerland
614086	337-089-901-0	EASA,FAA,CAAC,ANAC	19	28	72-56-04	LOW PRESSURE TURBINE REAR FRAME - STREAM FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		715.00	SR Technics Switzerland
614086	340-165-503-0	EASA,FAA,CAAC,ANAC			72-56-04		Package B	001	REPLACEMENT OF ANCHOR NUTS		465.00	SR Technics Switzerland
618233	9972M48P01	EASA,FAA,CAAC,ANAC	3	28	72-61-06	CFM56-ALL NO.3 BEARING PULLER NUT	Package A	CLN/INSP	CLEANING & INSPECTION		170.00	SR Technics Switzerland
618234	9542M68P02	EASA,FAA,CAAC,ANAC	19	28	72-61-12	INLET GEARBOX & NO.3 BEARING - OUTER SPANNER NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		975.00	SR Technics Switzerland
618701	336-026-806-0	EASA,FAA,CAAC,ANAC	40	35	72-56-02	LOW PRESSURE TURBINE REAR FRAME - NO.5 BEARING SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		850.00	SR Technics Switzerland
618701	336-026-807-0	EASA,FAA,CAAC,ANAC			72-56-02		Package C	002	RECONDITIONING OF THE ABRADABLE COATING		3055.00	SR Technics Switzerland
618701	340-165-901-0	EASA,FAA,CAAC,ANAC			72-56-02		Package G	006	RECONDITIONING OF RABBIT DIAMETER G		2700.00	SR Technics Switzerland
618701	340-165-903-0	EASA,FAA,CAAC,ANAC			72-56-02		Package H	007	REPLACEMENT OR CRACKS REPAIR OF OIL SCAVENGE TUBE NIPPLE BY WELD BUILD-UP		4645.00	SR Technics Switzerland
618701	340-165-904-0	EASA,FAA,CAAC,ANAC			72-56-02		Package I	008	RECONDITIONING OF THE LOCATING DIAMETER OF THE RING BY PLASMA SPRAYING		3055.00	SR Technics Switzerland
618701					72-56-02		Package J	009	CRACKS REPAIR OF NO. 5 BEARING SUPPORT BY WELD BUILD-UP		4770.00	SR Technics Switzerland
618701					72-56-02		Package N	013	REPAIR OF SAFETY WIRE HOLES ON THE OIL SCAVENGE TUBE NIPPLE		1840.00	SR Technics Switzerland
618701					72-56-02		Package R	017	RECONDITIONING OF THE LOCATING DIAMETER WITH THE TURBINE REAR FRAME		3055.00	SR Technics Switzerland
618701					72-56-02		Package SB00	72-0178	INTRODUCTION OF NEW NO.5 BEARING SUPPORT		1110.00	SR Technics Switzerland
618701					72-56-02		Package SB02	72-0499	INTRODUCTION OF NEW N°5 BEARING SUPPORT NIPPLE DESIGN OR REWORK OF THE OLD ONE		4710.00	SR Technics Switzerland
618701					72-56-02		Package SB03	72-0477	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		1270.00	SR Technics Switzerland
618701					72-56-02		Package U	014	REPAIR OF TAPPED HOLE WITH LOCALLY MANUFACTURED THREADED INSERT		2395.00	SR Technics Switzerland
623552	337-111-302-0	EASA,FAA,CAAC,ANAC	19	28	72-55-13	LOW PRESSURE TURBINE SHAFT - BEARING NO.4 RING-RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		350.00	SR Technics Switzerland
630864	1561M26G01	EASA,FAA,CAAC,ANAC	39	28	72-42-02	COMBUSTION CHAMBER (SAC) - DOME	Package A	CLN/INSP	CLEANING AND INSPECTION,		875.00	SR Technics Switzerland
630864	1561M26G03	EASA,FAA,CAAC,ANAC			72-42-02		Package B	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE COMBUSTION CHAMBER DOME		2160.00	SR Technics Switzerland
630864	1561M26G05	EASA,FAA,CAAC,ANAC			72-42-02		Package F	006	APPLICATION OF THERMAL BARRIER COATING ON COMBUSTION CHAMBER DOME		10495.00	SR Technics Switzerland
630864	1561M26G06	EASA,FAA,CAAC,ANAC			72-42-02		Package F	008	REPLACEMENT OF THE PRIMARY SWIRL NOZZLE RETAINER		10495.00	SR Technics Switzerland
630864	2255M24G06	EASA,FAA,CAAC,ANAC			72-42-02		Package F	009	PLUG WELDING AND DRILLING OF THE BOLT HOLES IN THE COMBUSTION CHAMBER DOME		10495.00	SR Technics Switzerland
630864	2255M24G07	EASA,FAA,CAAC,ANAC			72-42-02		Package F	013	SPECIAL SIZING TECHNIQUE, VENTURI DIAMETER SIZING AND WELD REPAIR		10495.00	SR Technics Switzerland
630864	2255M77G01	EASA,FAA,CAAC,ANAC			72-42-02		Package G	004	COMBUSTOR DOME DEFLECTOR PLATE REPLACEMENT		5400.00	SR Technics Switzerland
630864	2255M77G02	EASA,FAA,ANAC			72-42-02		Package K	010	SLEEVE AND DEFLECTOR REPLACEMENT		5330.00	SR Technics Switzerland
630864	2255M77G03	EASA,FAA,ANAC			72-42-02		Package M	012	SECONDARY SWIRL NOZZLE REPLACEMENT		5965.00	SR Technics Switzerland
630864	2813M78G01	EASA,FAA,CAAC,ANAC			72-42-02		Package O	014	THICK BELLMOUNT REPLACEMENT REPAIR		7300.00	SR Technics Switzerland
630864					72-42-02		Package Q	016	CC DOME-REPLACEMENT OF SECONDARY SWIRLER NOZZLE		4140.00	SR Technics Switzerland
630864					72-42-02		Package R	017	CC DOME-REPLACEMENT OF SLEEVE AN DEFLECTOR		2285.00	SR Technics Switzerland
630864					72-42-02		Package S	018	RETAINERLESS PRIMARY SWIRLER REPLACEMENT		3180.00	SR Technics Switzerland
630864					72-42-02		Package SB00	72-0455	SWIRLERS - THICK FLANGE		7300.00	SR Technics Switzerland
630864					72-42-02		Package SB02	72-0941	DOME THICK BELLMOUTH MODIFICATION		9655.00	SR Technics Switzerland
630864					72-42-02		Package SB03	SB 72-1055	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL	REPLACEMENT OF BELMOUTH FLANGES	7815.00	SR Technics Switzerland
630864					72-42-02		Package SB04	SB 72-1055	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL	REPLACEMENT OF SECONDARY NOZZLE	7815.00	SR Technics Switzerland
631027	335-306-301-0	EASA,FAA,CAAC,ANAC	16	28	72-62-12	TRANSFER GEARBOX - BRACKET ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		390.00	SR Technics Switzerland
631146	1317M57G02	EASA,FAA,CAAC,ANAC	43	28	72-42-03	COMBUSTION CHAMBER (SAC) - INNER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		475.00	SR Technics Switzerland
631146	1317M57G03	EASA,FAA,CAAC,ANAC			72-42-03		Package AN	OS 255084	AIRFLOW TEST OF LARGE DIA. MULTI HOLES ON INNER LINER		3055.00	SR Technics Switzerland
631146	1317M57G05	EASA,FAA,CAAC,ANAC			72-42-03		Package C	002	PULSE WELD REPAIR OF THE COMBUSTION CHAMBER INNER LINER SEAL		3880.00	SR Technics Switzerland
631146	1968M64G01	EASA,FAA,CAAC,ANAC			72-42-03		Package I	008	WELDED PATCH REPAIR		3055.00	SR Technics Switzerland
631146	1968M64G02	EASA,FAA,CAAC,ANAC			72-42-03		Package K	001	WELD REPAIR AND RESIZING OF THE COMBUSTION CHAMBER INNER LINER		13125.00	SR Technics Switzerland
631146	1968M64G04	EASA,FAA,CAAC,ANAC			72-42-03		Package K	003	REMOVAL OF THE NUT PLATES IN THE COMBUSTION CHAMBERINNER LINER		13125.00	SR Technics Switzerland
631146	2256M23G02	EASA,FAA,CAAC,ANAC			72-42-03		Package K	004	INSTALLATION OF THE NUT PLATES IN THE COMBUSTION CHAMBER INNER LINER		13125.00	SR Technics Switzerland
631146	2256M23G03	EASA,FAA,CAAC,ANAC			72-42-03		Package K	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE COMBUSTION CHAMBER INNER LINER		13125.00	SR Technics Switzerland
631146	2256M23G04	EASA,FAA,CAAC,ANAC			72-42-03		Package K	006	APPLICATION OF THE THERMAL BARRIER COATING ON THE COMBUSTION CHAMBER INNER LINER		13125.00	SR Technics Switzerland
631146	2257M42G01	EASA,FAA,CAAC,ANAC			72-42-03		Package K	007	COMBUSTION CHAMBER INNER LINER BOLT HOLE DRILLING REPAIR		13125.00	SR Technics Switzerland
631146	2257M42G02	EASA,FAA,CAAC,ANAC			72-42-03		Package K	009	BRAZED DOUBLER WELD REPAIR OF THE INNER LINER AFT SUPPORT RING		13125.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
631146	2480M43G02	EASA,FAA,CAAC,ANAC			72-42-03		Package K	017	WELDING AND RESIZING REPAIR FOR THE INNER LINER WITH IMPROVED GEOMETRY AND MATERIAL AFT SUPPORT		13125.00	SR Technics Switzerland
631146					72-42-03		Package M	012	(THICK) THERMAL BARRIER COATING REPLACEMENT		1270.00	SR Technics Switzerland
631146					72-42-03		Package N	013	INNER LINER AFT FLANGE REPLACEMENT		8325.00	SR Technics Switzerland
631146					72-42-03		Package P	015	APPLICATION OF TBC ON INNER LINER WITH LARGE DIA MULTI HOLE	additional TAT +9, in cork	4135.00	SR Technics Switzerland
631146					72-42-03		Package SB01	72-0769	INTRODUCTION OF INNER AND OUTER SEGMENT LINER SPARE PARTS		305.00	SR Technics Switzerland
631146					72-42-03		Package SB02	72-0229	INNER AND OUTER LINER THICKER TBC FIELD REWORK		2360.00	SR Technics Switzerland
631146					72-42-03		Package SB03	72-0521	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE K	360.00	SR Technics Switzerland
631146					72-42-03		Package SB05	72-0694	REWORK OF THE INNER COMBUSTION CHAMBER LINER		9545.00	SR Technics Switzerland
631146					72-42-03		Package SB06	72-0812	REWORK OF PRE_TECH INSERTION COMBUSTION CHAMBER INNER LINER WITH THIN TBC		1950.00	SR Technics Switzerland
631146					72-42-03		Package SB07	72-0880	REWORK OF TECH INSERTION INNER LINER INTO MULTI-HOLE COOLING PATCH WITH THIN TBC CONFIGURATION		4135.00	SR Technics Switzerland
631146					72-42-03		Package SB10	72-0547	ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS		465.00	SR Technics Switzerland
631146					72-42-03		Package T	019	REPAIR OF THE BRAZE JOINT OF THE COMBUSTION CHAMBER INNER LINER AFT FLANGE DOUBLER		1950.00	SR Technics Switzerland
631146					72-42-03		Package U	020	PLUG-WELD INNER LINER HOLE		7055.00	SR Technics Switzerland
631146					72-42-03		Package U	020	WELD AND RESIZE REPAIR OF THE INNER NON-MULTIHOLE AREAS		7055.00	SR Technics Switzerland
631146					72-42-03		Package V	021	APPLICATION OF THIN THERMAL BARRIER COATING ON INNER LINERS WITH LARGE DIAMETER MULTI-HOLES		4135.00	SR Technics Switzerland
631146					72-42-03		Package W	022	CRACK WELD/RESIZE	additional TAT +9, in cork	8580.00	SR Technics Switzerland
631393	1498M58P01	EASA,FAA,CAAC,ANAC	19	28	72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package A	CLN/INSP	CLEANING & INSPECTION		55.00	SR Technics Switzerland
631393	1498M58P04	EASA,FAA,CAAC,ANAC			72-41-03		Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		120.00	SR Technics Switzerland
634072	338-065-603-0	EASA,FAA,CAAC,ANAC	48	35	72-54-07	LOW PRESSURE TURBINE - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1325.00	SR Technics Switzerland
634072	338-117-404-0	EASA,FAA,CAAC,ANAC			72-54-07		Package B	001	REPLACEMENT OF RIVETED PARTS AND RIVETS		2090.00	SR Technics Switzerland
634072	338-117-406-0	EASA,FAA,CAAC,ANAC			72-54-07		Package C	002	REPAIR OF THE OUTER DIAMETER LOCATING THE HPT SHROUD SUPPORT	FRONT OUTER DIAMETER	4270.00	SR Technics Switzerland
634072	338-117-407-0	EASA,FAA,CAAC,ANAC			72-54-07		Package D	003	REPLACEMENT OF THE BORESCOPE BOSSES		1565.00	SR Technics Switzerland
634072	338-117-450-0	EASA,FAA,CAAC,ANAC			72-54-07		Package H	007	REPAIR OF THE OUTER DIAMETER LOCATING THE LPT FRAME		5815.00	SR Technics Switzerland
634072	338-117-451-0	EASA,FAA,CAAC,ANAC			72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (BARE)		5815.00	SR Technics Switzerland
634072	338-117-452-0	EASA,FAA,CAAC,ANAC			72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (PLASMA)		5815.00	SR Technics Switzerland
634072	338-117-453-0	EASA,FAA,CAAC,ANAC			72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLASMA SPRAYING (E RAIL 1 TO 7		6230.00	SR Technics Switzerland
634072	338-117-454-0	EASA,FAA,CAAC,ANAC			72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLASMA SPRAYING (F RAIL 1 TO 7		6230.00	SR Technics Switzerland
634072	338-117-455-0	EASA,FAA,CAAC,ANAC			72-54-07		Package P	15-94761	BLENDED OF CRACKS ON RAIL 6 ANTI-ROTATION SLOTS		420.00	SR Technics Switzerland
634072	340-305-003-0	EASA,FAA,CAAC,ANAC			72-54-07		Package P	15-94762	BLENDED OF CRACKS ON RAIL 6 ANTI-ROTATION SLOTS	7BE	420.00	SR Technics Switzerland
634072					72-54-07		Package Q	016	WELD BUILD UP OF CRAKS ON RAILS 1,3,5 AND 7 NOZZLE SUPPORT RING	RAIL 1/3/5	15635.00	SR Technics Switzerland
634072					72-54-07		Package R	017	REPLACEMENT OF ANTI ROTATION PINS	RD 15-93532	1685.00	SR Technics Switzerland
634072					72-54-07		Package S	018	REPAIR OF PAR RAILS NOZZLES SUPPORT RING BY WELD BUILD UP	RAILS 2/4/6/8	20700.00	SR Technics Switzerland
634072					72-54-07		Package SB00	72-0552	REIDENTIFICATION OF LPT CASE IN FIELD		230.00	SR Technics Switzerland
634072					72-54-07		Package SB01	72-0718	REWORK OF THE LPT CASE RAIL "0" SUPPORT RING AND REIDENTIFICATION OF THE LPT CASE		5000.00	SR Technics Switzerland
634072					72-54-07		Package SB02	EASA-2014-0130	CHECK LIFE LIMITS		465.00	SR Technics Switzerland
634072					72-54-07		Package SB03	72-0608	INSPECTION OF THE LOW PRESSURE TURBINE (LPT) CASE		465.00	SR Technics Switzerland
634072					72-54-07		Package T	019	REPAIR OF ODD RAILS NOZZLES SUPPORT RING BY WELD BUILD UP	RAIL 1/3/5/7	13815.00	SR Technics Switzerland
634072					72-54-07		Package V	021	REPAIR OF WEAR MARKS ON RAIL 0 SUPPORT RING BY PLASMA SPRAYING		6230.00	SR Technics Switzerland
634151	1523M29G04	EASA,FAA,CAAC,ANAC	49	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1155.00	SR Technics Switzerland
634151	1784M36G01	EASA,FAA,CAAC,ANAC			72-53-02		Package AC	015	AFT FLANGE HEADLESS STRAIGHT PIN REPLACEMENT		850.00	SR Technics Switzerland
634151	1784M36G02	EASA,FAA,CAAC,ANAC			72-53-02		Package AM	017	HANGER ANTI-ROTATION PIN REPLACEMENT		570.00	SR Technics Switzerland
634151	2002M69G02	EASA,FAA,CAAC,ANAC			72-53-02		Package AN	022	THERMAL SPRAY REPAIR OF THE SHROUD HANGER RAIL INNER DIAMETER FACE	DIM. L / DIM. K	7620.00	SR Technics Switzerland
634151	2002M69G03	EASA,FAA,CAAC,ANAC			72-53-02		Package B	INSP-001	BLENDED WEAR INSIDE DIA.		2015.00	SR Technics Switzerland
634151	2002M69G05	EASA,FAA,CAAC,ANAC			72-53-02		Package B	INSP-001	TACK-WELD BOSS		2015.00	SR Technics Switzerland
634151	2002M90G01	EASA,FAA,CAAC,ANAC			72-53-02		Package B	INSP-001	TACK-WELD BUSHING		2015.00	SR Technics Switzerland
634151	2063M40G01	EASA,FAA,CAAC,ANAC			72-53-02		Package B	INSP-001	BLEND TO REMOVE HIGH METAL		2015.00	SR Technics Switzerland
634151					72-53-02		Package C	004	FORWARD FLANGE WEAR REPAIR		4230.00	SR Technics Switzerland
634151					72-53-02		Package E	018	REPAIR FOR LOCAL WEAR ON THE VANE MOUNT AFT FACE		3215.00	SR Technics Switzerland
634151					72-53-02		Package G	012	(EFFECT N) REPLACEMENT OF SUPPORT BUSHINGS		2645.00	SR Technics Switzerland
634151					72-53-02		Package H	013	(EFFECT N) REPLACEMENT OF THE BORESCOPE BOSS		445.00	SR Technics Switzerland
634151					72-53-02		Package M	023	FORWARD RAIL EROSION REPAIR		410.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634151					72-53-02		Package O	014	SELF RETAINING SLABBED HEAD BOLT REPLACEMENT		580.00	SR Technics Switzerland
634151					72-53-02		Package SB00	72-0203	INTRODUCTION OF A STRAIGHT HEADLESS PIN TO THE SPARE PARTS LIST		435.00	SR Technics Switzerland
634151					72-53-02		Package SB01	72-0156	HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01		4425.00	SR Technics Switzerland
634151					72-53-02		Package SB03	72-0930	REWORK FWD FLANGE SHROUD NOZZLE SUPPORT		4425.00	SR Technics Switzerland
634151					72-53-02		Package T	019	FORWARD FLANGE DIMENSIONAL REPAIR		5900.00	SR Technics Switzerland
634151					72-53-02		Package V	021	PLASMA SPRAY REPAIR OF SURFACE AM		2485.00	SR Technics Switzerland
634151					72-53-02		Package W	021	PLASMA SPRAY REPAIR OF DIAMETER FM		2485.00	SR Technics Switzerland
634151					72-53-02		Package X	022	REPAIR SHROUD ID DIM.M		7580.00	SR Technics Switzerland
635241	301-547-905-0	EASA,FAA,CAAC,ANAC,CAA UK	23	28	72-55-07	LOW PRESSURE TURBINE SHAFT - RETAINER NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
635241	64ECR101	EASA,FAA,CAAC,ANAC			72-55-07		Package N	001	REPAIR OF THE MATING FACES	ITEM 1	505.00	SR Technics Switzerland
635241	650-784-016-0	EASA,FAA,CAAC,ANAC,CAA UK			72-55-07		Package O	001	REPAIR OF THE MATING FACES	ITEM 2	505.00	SR Technics Switzerland
635241	650-784-037-0	EASA,FAA,CAAC,ANAC,CAA UK			72-55-07		Package P	001	REPAIR OF THE MATING FACES	ITEM 3	505.00	SR Technics Switzerland
635241	650-784-038-0	EASA,FAA,CAAC,ANAC			72-55-07		Package Q	001	REPAIR OF THE MATING FACES	ITEM 4	505.00	SR Technics Switzerland
635241	650-784-075-0	EASA,FAA,CAAC,ANAC			72-55-07		Package U	002	REPAIR OF THE SILVER PLATING	ITEM 1-3	1350.00	SR Technics Switzerland
635241					72-55-07		Package X	002	REPAIR OF THE SILVER PLATING	ITEM 4	1350.00	SR Technics Switzerland
635499	340-034-302-0	EASA,FAA,CAAC,ANAC	18	28	72-22-03	NO.1 AND NO.2 BEARING SUPPORT - NO. 2 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		930.00	SR Technics Switzerland
635499					72-22-03		Package C	001	REPLACEMENT OF THE SWAGED SELF-LOCKING INSERTS OF THE NO 2 BEARING SUPPORT		1355.00	SR Technics Switzerland
635521	9324M22G01	EASA,FAA,CAAC,ANAC	15	28	72-00-53	ENGINE MODULES/ASSEMBLIES - HPT SHROUD & STAGE 1 LPT NOZZLE ASSEMB	Package A	CLN/INSP	CLEANING AND INSPECTION		455.00	SR Technics Switzerland
635521	9324M62G01	EASA,FAA,CAAC,ANAC			72-00-53		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		815.00	SR Technics Switzerland
636114	337-006-168-0	EASA,FAA,CAAC,ANAC	11	28	72-23-03	CFM56 OUTLET GUIDE VANE SET	Package A	CLN/INSP	CLEANING AND INSPECTION		90.00	SRTAS
636114	337-006-181-0	EASA,FAA,CAAC,ANAC			72-23-03		Package B		FULL REPAIR		555.00	SRTAS
636114	338-067-007-0	EASA,FAA,CAAC,ANAC			72-23-03		Package B	1	AIRFOIL AND PLATFORM BLEND REPAIR		555.00	SRTAS
636114	338-067-009-0	EASA,FAA,CAAC,ANAC			72-23-03		Package B	2	RECONDITIONING OF PROTECTIVE COATING		555.00	SRTAS
636114	338-067-014-0	EASA,FAA,CAAC,ANAC			72-23-03		Package C	8	REMOVAL OF CORROSION IN OGV ATTACHMENT HOLE		125.00	SRTAS
636114	340-002-305-0	EASA,FAA,CAAC,ANAC			72-23-03		Package D	11	REMOVAL OF CORROSION IN OGV ATTACHMENT HOLES BY BUSHING INSTALLATION		230.00	SRTAS
636114					72-23-03		Package E	13	EPOXY BUILD UP OF OGV ATTACHMENT HOLES		255.00	SRTAS
636114					72-23-03		Package F	9	REPAIR OF THE VANE ROOT FACES CONVEX SIDE BY PLASMA		360.00	SRTAS
636431	338-071-201-0	EASA,FAA,CAAC,ANAC	21	28	72-00-54	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION		455.00	SR Technics Switzerland
636431	338-092-301-0	EASA,FAA,CAAC,ANAC			72-00-54		Package B	INSP-001	MINOR MODUL MEASUREMENT RAIL "O"		155.00	SR Technics Switzerland
636431	338-092-319-0	EASA,FAA,CAAC,ANAC			72-00-54		Package C	002	TEMPORARY REPLACEMENT OF BROKEN STUD OF T 49.5 EGT SENSOR ASSEMBLY PLATE		1230.00	SR Technics Switzerland
636431					72-00-54		Package D	003	REPLACEMENT OF RIVETED PARTS OR RIVETS OF LPT CASE		1150.00	SR Technics Switzerland
636431					72-00-54		Package SB00	051	REPLACEMENT OF BROKEN STUDS OF T49.5 EGT SENSOR FIXATION ASSEMBLY PLATE		1780.00	SR Technics Switzerland
636431					72-00-54		Package SB00	72-0423	REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR REATINING PLATE		1780.00	SR Technics Switzerland
636431					72-00-54		Package SB01	EASA-2014-0130	TIME LIMITS - ENGINE STATIONARY PARTS - LIFE LIMITS		480.00	SR Technics Switzerland
637104	340-170-501-0	EASA,FAA,CAAC,ANAC	17	28	72-55-18	LOW PRESSURE TURBINE SHAFT - SPACER	Package A	CLN/INSP	CLEANING AND INSPECTION		285.00	SR Technics Switzerland
642808	9968M26P02	EASA,FAA,CAAC,ANAC	16	28	72-42-04	COMBUSTION CHAMBER - IGNITER FERRULE	Package A	CLN/INSP	CLEANING AND INSPECTION		95.00	SR Technics Switzerland
642808					72-42-04		Package W	022	IGNITER FERRULE BORE WELD REPAIR		395.00	SR Technics Switzerland
643129			30	28	72-55-06	LOW PRESSURE TURBINE SHAFT - CENTER VENT TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION	PN337-111-603-0 FOR SHOP VISIT ONLY	480.00	SR Technics Switzerland
643129					72-55-06		Package AN	SPM 70-41-11	REMOVE HIGH METAL		180.00	SR Technics Switzerland
643129					72-55-06		Package B	001	REPAIR OF THE FRONT AND/OR MID JOURNALS		1940.00	SR Technics Switzerland
643129					72-55-06		Package C	002	REPAIR OF THE AFT JOURNAL		2440.00	SR Technics Switzerland
643129					72-55-06		Package D	003	CENTRAL SECTION REPLACEMENT		3395.00	SR Technics Switzerland
643129					72-55-06		Package E	004	REPLACEMENT OF ONE OR TWO MID JOURNAL SECTIONS		3655.00	SR Technics Switzerland
643129					72-55-06		Package F	005	REPLACEMENT OF THE FORWARD SECTION		2565.00	SR Technics Switzerland
643129					72-55-06		Package G	006	REPAIR OF THE LOCATING HOLES		1225.00	SR Technics Switzerland
643129					72-55-06		Package H	007	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		3870.00	SR Technics Switzerland
643129					72-55-06		Package I	008	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		3615.00	SR Technics Switzerland
643129					72-55-06		Package J	009	LAST CLEANING AND CONDITIONING OF THE CENTER VENT TUBE		410.00	SR Technics Switzerland
643129					72-55-06		Package K	010	WELD BUILD UP OF THE REAR SLOT FACES		1775.00	SR Technics Switzerland
643129					72-55-06		Package L	011	REPAIR OF CRACK IN THE CENTRAL SECTION BY WELD BUILD-UP		2205.00	SR Technics Switzerland
643129					72-55-06		Package O	014	REPAIR OF ILLEGIBLE PART MARKINGS		110.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
643129					72-55-06		Package P	015	REPLACE FORWARD JOURNAL		2805.00	SR Technics Switzerland
647987 1522M10G01	EASA,FAA,CAAC,ANAC		20	28	72-53-05	HPT SHROUD - AIR IMPINGEMENT MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		875.00	SR Technics Switzerland
647987 1668M93G01	EASA,FAA,CAAC,ANAC				72-53-05		Package B	001	WELD REPAIR OF AXIAL CRACKS NEXT TO THE AIR IMPINGEMENT MANIFOLD NUT		715.00	SR Technics Switzerland
647987 1668M93G02	EASA,FAA,CAAC,ANAC,CAA UK				72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL B	2725.00	SR Technics Switzerland
647987 1668M93G03	EASA,FAA,CAAC,ANAC				72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL C	2725.00	SR Technics Switzerland
647987 2071M29G01	EASA,FAA,CAAC,ANAC				72-53-05		Package F	005	SPLASH PLATE AND SPLASH PLATE SUPPORT WELD REPAIR		715.00	SR Technics Switzerland
647987 2071M29G02	EASA,FAA,CAAC,ANAC				72-53-05		Package G	006	WELD REPAIR OF THE SPLASH PLATE AND SPLASH PLATE SUPPORT		715.00	SR Technics Switzerland
647987 2071M29G03	EASA,FAA,CAAC,ANAC				72-53-05		Package I	008	BRAZE JOINT REPAIR		2750.00	SR Technics Switzerland
647987					72-53-05		Package J	009	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		815.00	SR Technics Switzerland
647987					72-53-05		Package M	012	FORWARD TABS PLASMA SPRAY REPAIR		1440.00	SR Technics Switzerland
647987					72-53-05		Package N	013	BOLT LUG BRAZE JOINT REPAIR		1935.00	SR Technics Switzerland
647987					72-53-05		Package Q	016	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		1960.00	SR Technics Switzerland
647987					72-53-05		Package SB04	72-0350	INTRODUCTION OF FIELD REWORK FOR HPT AIR MANIFOLD		3500.00	SR Technics Switzerland
648501 335-070-401-0	EASA,FAA,CAAC,ANAC		12	28	72-56-12	LOW PRESSURE TURBINE REAR FRAME - REAR INSULATION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		230.00	SR Technics Switzerland
648693 336-031-802-0	EASA,FAA,CAAC,ANAC		11	28	72-56-09	LOW PRESSURE TURBINE REAR FRAME - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		295.00	SR Technics Switzerland
648704 338-072-151-0	EASA,FAA,CAAC,ANAC		12	28	72-55-20	LOW PRESSURE TURBINE SHAFT - PIN-SHOULDER	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
648717 1864M97P01	EASA,FAA,CAAC,ANAC		12	28	72-52-11	COMPRESSOR FRONT STATOR - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		205.00	SR Technics Switzerland
648724			5	28	72-31-10	CFM56 COMPRESSOR ROTOR BLADE LOCKS	Package A	CLN/INSP	CLEANING AND INSPECTION		210.00	SR Technics Switzerland
648724					72-31-10		Package SB01	SB 72-0874	SUSPECT HPC BLADE LOCKS		480.00	SR Technics Switzerland
648726 1663M70P02	EASA,FAA,CAAC,ANAC		12	28	72-31-14	COMPRESSOR ROTOR - COMPRESSOR SHAFT RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		190.00	SR Technics Switzerland
648727 9125M42P03	EASA,FAA,CAAC,ANAC		12	28	72-31-12	COMPRESSOR ROTOR - SEAL RING	Package A	CLN/INSP	CLEANING AND INSPECTION		155.00	SR Technics Switzerland
648728 1499M47P02	EASA,FAA,CAAC,ANAC		4	28	72-31-15	CFM56 COMPRESSOR ROTOR DAMPER RING, STAG	Package A	CLN/INSP	CLEANING & INSPECTION		100.00	SR Technics Switzerland
654796 9321M97P02	EASA,FAA,CAAC,ANAC		4	28	72-33-20	CFM56 STOP, STATOR SECTOR	Package A	CLN/INSP	CLEANING & INSPECTION		90.00	SR Technics Switzerland
654828 9971M82P02	EASA,FAA,CAAC,ANAC		4	28	72-52-09	CFM56 RING-RETAINING	Package A	CLN/INSP	CLEANING AND INSPECTION		360.00	SR Technics Switzerland
655109 1207P0250	EASA,FAA,CAAC,ANAC		11	28	72-55-20	LOW PRESSURE TURBINE SHAFT - RING	Package A	CLN/INSP	CLEANING AND INSPECTION		460.00	SR Technics Switzerland
655153 1358M93P01	EASA,FAA,CAAC,ANAC		3	28	72-52-09	CFM56 HPT Seal-Blade	Package A	CLN/INSP	CLEANING & INSPECTION		35.00	SR Technics Switzerland
655176 301-298-208-0	EASA,FAA,CAAC,ANAC		12	28	72-22-06	NO.1 AND NO.2 BEARING SUPPORT - REAR ROTATING AIR/OIL SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		770.00	SR Technics Switzerland
655176 301-298-211-0	EASA,FAA,CAAC,ANAC,CAA UK				72-22-06		Package B	001	RECONDITIONING OF SILVER PLATING ON THE FORWARD MATING FACE AND/OR THREADS		435.00	SR Technics Switzerland
655179 301-298-006-0	EASA,FAA,CAAC,ANAC		15	28	72-22-13	NO.1 AND NO.2 BEARING SUPPORT - RETAINING NUT'S	Package A	CLN/INSP	CLEANING AND INSPECTION		705.00	SR Technics Switzerland
655179					72-22-13		Package B	001	REPLACEMENT OF SILVER PLATING ON NO. 1 BEARING INNER RACE RETAINING NUT		1135.00	SR Technics Switzerland
655179					72-22-13		Package C	002	REPAIR OF THE SILVER PLATE MATING FACES OF THE RETAINING NUTS		715.00	SR Technics Switzerland
655311 340-116-931-0	EASA,FAA,ANAC		3	28	72-21-26	CFM56-7B ELASTOMER SPACER	Package A	CLN/INSP	CLEANING & INSPECTION		30.00	SR Technics Switzerland
656214 301-436-804-0	EASA,FAA,CAAC,ANAC		14	28	72-22-13	NO.1 AND NO.2 BEARING SUPPORT - RETAINING NUT'S	Package A	CLN/INSP	CLEANING AND INSPECTION		715.00	SR Technics Switzerland
656214 337-011-902-0	EASA,FAA,CAAC,ANAC				72-22-13		Package D	003	EQUAL. SURF.		520.00	SR Technics Switzerland
663264 1853M56P07	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DG		11	21	73-21-79	HYDROMECHANICAL UNIT MODEL CH-T1	Package B		BENCH-TEST	READJUSTMENT AND TESTING	3425.00	SR Technics Switzerland
663264 1853M56P08	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		3900.00	SR Technics Switzerland
663264 1853M56P09	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		6155.00	SR Technics Switzerland
663264 1853M56P10	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		8160.00	SR Technics Switzerland
663264 1853M56P11	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package G		OVERHAUL	DISASSEMBLY,CLEANING, INSPECTION, ASSI	10410.00	SR Technics Switzerland
663264 1853M56P12	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB00	CHT1-73-0015	CONVERSION FROM HONEYWELL PN 442238 (GEAE PN 1853M56P08) TO HONEYW	IN CONJUNCTION WITH BENCH-TEST	465.00	SR Technics Switzerland
663264 1853M56P13	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB00	CHT1-73-0021	INTRODUCTION OF MODIFIED METERING VALVE RESOLVER BODY ASSEMBLY	WARRANTY BY DEFINED FAULT CODES	465.00	SR Technics Switzerland
663264 1853M56P14	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB00	CHT1-73-0022	INTRODUCTION OF IMPROVED BURNER STAGING VALVE SOLENOID ANDVALVE ASS	WARRANTY BY DEFINED FAULT CODES	465.00	SR Technics Switzerland
663264 1853M56P15	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB00	CHT1-73-0024	INTRODUCTION OF HONEYWELL HYDROMECHANICAL UNIT (HMU) PN442317 (GEA	PL ISS STATUS NO. -8- REQUIRED	465.00	SR Technics Switzerland
663264 1853M56P16	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	73-EO-525077	INTEGRATOR SPRING ASSY INSPECTION	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442124	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0008	REPLACEMENT OF AFSS SWITCH ASSEMBLY TO INCREASE HMU RELIABILITY AND	IN IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442238	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0011	ON-WINGAFSS SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTIO	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442317	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0012	REMOVAL AND REPLACEMENT OF SPEED SERVO (MATCHED) VALVE AND SLEEVE A	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442326	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0014	INTRODUCTION OF HONEYWELL HMU WITH NEW AIRFRAME SHUTOFF (AFSS) SWI	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442355	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0018	INSPECTION OF SHUTOFF SPACER PN 2687048 FOR PROPER INSTALLATION.	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442369	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0019	REPLACEMENT OF SHUTOFF SPACER PN 2687048 WITH NEW DESIGN	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264 442597	EASA,FAA,CAAC,ICAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF				73-21-79		Package SB01	CHT1-73-0020	INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SER	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
663264	442598	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-21-79				Package SB01	CHT1-73-0025	INTRODUCTION OF IMPROVED ADJUSTMENT SCREW (PN 2689127)	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264	442652	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-21-79				Package SB01	CHT1-73-0026	LOW PRESSURE LEAK CHECK	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264	442653	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-21-79				Package SB01	CHT1-73-0028	REMOVAL OF BURNER STAGING VALVE (BSV) SOLENOID AND VALVE ASSEMBLY FRI	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB01	CHT1-73-0030	NEW AIRFRAME SHUTOFF SOLENOID AND VALVE	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB01	CHT1-73-0033	INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERV	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB01	CHT1-73-0037	INSPECTION OF MAIN BODY ASSEMBLY	IN CONJUNCTION WITH LIGHT REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0010	IMPROVED ELECTRICAL WIRE RETENTION	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0013	REPLACEMENT OF SHUTTLE VALVE (MATCHED) PISTON AND SLEEVE ASSEMBLY	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0016	INTRODUCTION OF IMPROVED FUEL METERING VALVE (FMV) VALVE EXTENSION AI	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0034	OVER-FUEL THRESHOLD MARGIN INCREASE	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0039	INTRODUCTION OF MODIFIED MEETERING VALVE RESOLVER BODY ASSEMBLY	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0041	INTRODUCTION OF FUEL METRING VALVE RESOLVER MODIFICATION	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0042	INSPECTION OF MAIN BODY ASSEMBLY - EHSV WIRE BUNDLE	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0043	HYDROMECHANICAL UNIT (HMU) BODY NON-FERROUS RING CHIP CONTAMINATIC	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0044	INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION O	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0045	HYDROMECHANICAL UNIT (HMU) BYPASS VALVE ROTATION	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0046	INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE THREE WAY TWO STAGE I	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB02	CHT1-73-0047	INCORPORATION OF NEW INTEGRATOR SPRINGASSEMBLY FOR ANTI-ROTATION OF	IN CONJUNCTION WITH MEDIUM REPAIR	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0009	INSPECTION OF HMU MAIN BODY FOR HPT2 THIN WALL CASTING	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0017	REMOVAL ANDTEST OF ELECTROHYDRAULIC SERVO VALVE FOR TEMPERATURE SEN	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0023	REPLACEMENT OF FLUOROSILICONE PREFORMED PACKINGS WITH FLUOROCARBO	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0049	HMU ELECTROHYDRAULIC SERVO VALVE (EHSV) PINS CRIMPED WITH INSULATION	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0130	INSPECTION OF HYDROMECHANICAL UNIT FOR NON-HYDROCARBON CONTAMINA	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0138	USE OF CIS, FUEL ADDITIVES FOR 7B ENGINES	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB03	CHT1-73-0148	NEW SOFTWARE VERSION 7.B.S1	IN CONJUNCTION WITH HEAVY/ OV	465.00	SR Technics Switzerland
663264					73-21-79		Package SB05	CHT1-73-0040	MANUFACTURABILITY IMPROVEMENTS	IN CONJUNCTION WITH MEDIUM REPAIR	2395.00	SR Technics Switzerland
664893	340-091-109-0	EASA,FAA,CAAC,ANAC	2	21	72-09-04	CFM56 GEARBOX BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		105.00	SR Technics Switzerland
667972	340-027-110-0	EASA,FAA,CAAC,ANAC	21	35	72-56-01	CFM56-7B TURBINE REAR FRAME	Package A	CLN/INSP	CLEANING AND INSPECTION		1700.00	SR Technics Switzerland
667972	340-027-113-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AA	51	RADIUS OF DIA K POLISHING PROCEDURE		1325.00	SR Technics Switzerland
667972	340-027-115-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AC	INSP-001	ENGAGE DISENGAGE BUSHING		1515.00	SR Technics Switzerland
667972	340-027-116-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AC	INSP-001	REMOVE HIGH METAL		1515.00	SR Technics Switzerland
667972	340-027-118-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AC	INSP-001	REWELD STOP WELD ON STUDS		1515.00	SR Technics Switzerland
667972	340-027-119-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AD	29	REPLACEMENT OF INSULATION ASSEMBLY OF THE INNER HUB		1460.00	SR Technics Switzerland
667972	340-027-120-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AF	31	RECONDITIONING OF THE DIAMETER OIL SCAVENGE TUBE		2230.00	SR Technics Switzerland
667972	340-027-121-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AI	34	REPLACEMENT OF SUMP FLOODING TUBE		1245.00	SR Technics Switzerland
667972	340-166-205-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AJ	44	CRIMPED TRAIN TUBE REPLACEMENT		885.00	SR Technics Switzerland
667972	340-166-206-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AK	47	LOCALLY WELD BUILD-UP OF THE CLEVIS MOUNTS EXTERNAL FACES		3755.00	SR Technics Switzerland
667972	340-166-207-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AL	46	REPAIR OF CRACKS IN WELD BEAD OF THE INSULATION BLANKET		1690.00	SR Technics Switzerland
667972	340-166-208-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AM	38	REPAIR OF THE BRACKET CENTERING DIAMETER OF THE OIL SCAVENGE TUBE ASSEMBLY BY WELD BUILD UP		5300.00	SR Technics Switzerland
667972	340-166-209-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AN	43	REPAIR OF CLEVIS MOUNT AREA		1690.00	SR Technics Switzerland
667972	340-166-210-0	EASA,FAA,CAAC,ANAC			72-56-01		Package B	01	REPLACEMENT OF THE DEFECTIVE STUDS ON THE AFT FACE OF THE INNER HUB.		2645.00	SR Technics Switzerland
667972	340-166-211-0	EASA,FAA,CAAC,ANAC			72-56-01		Package C	02	REPLACEMENT OF THE DEFECTIVE STUDS ON THE AFT FACE OF THE INNER HUB		1135.00	SR Technics Switzerland
667972	340-166-254-0	EASA,FAA,CAAC,ANAC			72-56-01		Package D	03	REPLACEMENT OF BUSHINGS IN THE CLEVIS MOUNTS		2425.00	SR Technics Switzerland
667972	340-166-255-0	EASA,FAA,CAAC,ANAC			72-56-01		Package E	04	REPLACEMENT OF DEFECTIVE FASTENERS AND/ OR DEFECTIVE ASSOCIATED PARTS		1400.00	SR Technics Switzerland
667972	340-166-256-0	EASA,FAA,CAAC,ANAC			72-56-01		Package F	05	REPLACE THE DEFECTIVE BUSHINGS IN THE HANDLING BRACKETS ON THE TURBINE FRAME		2790.00	SR Technics Switzerland
667972	340-166-257-0	EASA,FAA,CAAC,ANAC			72-56-01		Package G	01	STUD REPLACEMENT	72-00-03	1250.00	SR Technics Switzerland
667972	340-166-258-0	EASA,FAA,CAAC,ANAC			72-56-01		Package H	07	REPAIR OF THE DIAMETER MATING WITH THE LPT CASE		3775.00	SR Technics Switzerland
667972	340-166-259-0	EASA,FAA,CAAC,ANAC			72-56-01		Package K	10	REPAIR DIAMETER K		2590.00	SR Technics Switzerland
667972	340-177-502-0	EASA,FAA,CAAC,ANAC			72-56-01		Package R	17	REPLACEMENT OF THE OIL SUPPLY TUBE ASSEMBLY		1515.00	SR Technics Switzerland
667972	340-177-503-0	EASA,FAA,CAAC,ANAC			72-56-01		Package S	18	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY	SAME WITH REP 033	3145.00	SR Technics Switzerland
667972	340-177-504-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB01	72-0527	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENAGE TUBE		2520.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
667972	340-177-505-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB02	72-0568	INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES		2305.00	SR Technics Switzerland
667972	340-177-506-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB02	72-0579	INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES		2305.00	SR Technics Switzerland
667972	340-177-507-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB02	72-0732	INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES		2305.00	SR Technics Switzerland
667972	340-177-551-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB03	72-0339	REPLACEMENT OF THE CURRENT OIL SUPPLY TUBE BY A REMOVABLE TUBE		1690.00	SR Technics Switzerland
667972	340-177-552-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB06	79-0017	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1690.00	SR Technics Switzerland
667972	340-177-553-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB08	EASA 2009-0009	INSPECTION OF TURBINE REAR FRAME ON DAC ENGINE	SB 72-558 EC	2305.00	SR Technics Switzerland
667972	340-177-554-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB10	EASA 2007-0104	TURBINE REAR FRAME, TIME LIMITS AND LIFE REDUCTION		1045.00	SR Technics Switzerland
667972	340-177-555-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB10	EASA-2014-0130	TIME LIMIT AND MANDATORY INSPECTION		1045.00	SR Technics Switzerland
667972	340-177-556-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB10	FAA 2008-03-09	MANDATORY INSPECTIONS LIFE LIMITS		1045.00	SR Technics Switzerland
667972	340-256-801-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB10	FAA 2010-01-05	TIME LIMIT AND MANDATORY INSPECTIONCRACKS		1045.00	SR Technics Switzerland
667972					72-56-01		Package SB11	737-71A1462	AFT ENGINE MOUNT, LINK ASSEMBLY, HANGAR FITTING, INSPECTION, CORRECTION AD 2011-18-10		395.00	SR Technics Switzerland
667972					72-56-01		Package SB12	72-0558	NOZZLES - ADDITIONAL COOLING HOLES - REWORK		1330.00	SR Technics Switzerland
667972					72-56-01		Package SB13	72-1077	INSPECTION OF TURBINE REAR FRAME AT RADIUS DIAMETAR K	PPR LEVEL	5515.00	SR Technics Switzerland
667972					72-56-01		Package SB14	72-1077	INSPECTION OF TURBINE REAR FRAME AT RADIUS DIAMETAR K	MODUL LEVEL	550.00	SR Technics Switzerland
667972					72-56-01		Package T	19	REPLACEMENT OF THE TUBE BOSS CONNECTION NIPPLE		2015.00	SR Technics Switzerland
667972					72-56-01		Package U	20	WELD REPAIR OF CRACKS FOR WELDED ASSEMBLY FRAME		4835.00	SR Technics Switzerland
667972					72-56-01		Package Z	25	INSTALLATION OF NEW BUSHINGS		3775.00	SR Technics Switzerland
668014	8960-01-002	EASA,FAA,CAAC,ANAC	9	21	26-11-04	FIRE DETECTION HARNESSSES MW0325&MW0326	Package B	TEST	PRE TEST		530.00	SR Technics Switzerland
668014	8960-02-002	EASA,FAA,CAAC,ANAC			26-11-04		Package C	TEST	TEST		885.00	SR Technics Switzerland
668014					26-11-04		Package E		REPAIR		1225.00	SR Technics Switzerland
668014					26-11-04		Package G		OVERHAUL		1495.00	SR Technics Switzerland
668056	8960-01-001	EASA,FAA,CAAC,ANAC	1	28	26-10-23	FIRE DETECTION HARNESSSES; SEMI RIGID ASSEMBLY	Package B	TEST	PRE TEST		530.00	SR Technics Switzerland
668056	8960-02-001	EASA,FAA,CAAC,ANAC			26-10-23		Package C	TEST	TEST		885.00	SR Technics Switzerland
668056					26-10-23		Package E		REPAIR		1225.00	SR Technics Switzerland
668056					26-10-23		Package G		OVERHAUL		1495.00	SR Technics Switzerland
668143	335-192-203-0	EASA,FAA,CAAC,ANAC	13	28	72-21-09	CFM56-7B STG 1-4 VANE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		735.00	SR Technics Switzerland
668143	340-001-309-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AE	038	PLASMA SPRAY OF STAGE 4 INNER SHROUD AFT FACE		2755.00	SR Technics Switzerland
668143	340-001-310-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AF	040	RECONDITION PAINTING STG.1	PER STAGE	5100.00	SR Technics Switzerland
668143	340-058-303-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AG	040	RECONDITION PAINTING STG.2	PER STAGE	4880.00	SR Technics Switzerland
668143	340-058-405-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AH	040	RECONDITION PAINTING STG.3	PER STAGE	4880.00	SR Technics Switzerland
668143	340-058-406-0	EASA,FAA,CAAC,ANAC			72-21-09		Package AI	040	RECONDITION PAINTING STG.4	PER STAGE	4880.00	SR Technics Switzerland
668143					72-21-09		Package B	INSP-001	REMOVE OXIDATION / CORROSION		1355.00	SR Technics Switzerland
668143					72-21-09		Package C	001	BLEND REPAIR OF THE VANE AIRFOILS		1370.00	SR Technics Switzerland
668143					72-21-09		Package D	003	REPAIR ABRADABLE COATING IN THE OUTER SHROUD OF THE BOOSTER IGV AND STG. 3 AND 4 VANE ASSEMBLIES		4465.00	SR Technics Switzerland
668143					72-21-09		Package E	004	REPLACEMENT OF THE RIVETED SELF LOCKING NUTS		680.00	SR Technics Switzerland
668143					72-21-09		Package F	002	REAPPLY ON THE INNERSHROUDS		3355.00	SR Technics Switzerland
668143					72-21-09		Package F	002	REPLACEMENT OF THE ABRADABLE COATING ON THE INNER SHROUDS		3355.00	SR Technics Switzerland
668143					72-21-09		Package Q	060	REMOVAL OF CORROSION ON OUTER SHROUD		1225.00	SR Technics Switzerland
668720	9324M68G02	EASA,FAA,CAAC,ANAC	6	28	72-XX-XX	CFM56-7B COMPRESSOR ROTOR ASSY MODULE 31	Package A	CLN/INSP	CLEANING & INSPECTION		3165.00	SR Technics Switzerland
668720					72-XX-XX		Package B	001	BLEND STAGE 1 BLADES	72-00-31	820.00	SR Technics Switzerland
668720					72-XX-XX		Package C	002	BLEND STAGE 2-3 BLADES	72-00-31	820.00	SR Technics Switzerland
668720					72-XX-XX		Package D	003	BLEND STAGE 4-9 BLADES	72-00-31	820.00	SR Technics Switzerland
668720					72-XX-XX		Package G	006	LUBRICANT DOVETAIL	72-31-04	820.00	SR Technics Switzerland
668720					72-XX-XX		Package N	INSP-001	BLEND STG.2 RETAINER HOOK	72-00-31	500.00	SR Technics Switzerland
668720					72-XX-XX		Package O	INSP-001	BLEND STG.4 DOVETAIL FWD	72-00-31	500.00	SR Technics Switzerland
668720					72-XX-XX		Package P	INSP-001	BLEND STG.1-2 SEAL TEETH	72-00-31	500.00	SR Technics Switzerland
668720					72-XX-XX		Package Q	INSP-001	BLEND STG.4-9 SEAL TEETH	72-00-31	500.00	SR Technics Switzerland
668720					72-XX-XX		Package R	INSP-001	LUBRICANT THREAD	72-31-07	500.00	SR Technics Switzerland
668720					72-XX-XX		Package S	INSP-001	LOCKING LUG SLOT; COMP. SHAFT	72-00-31	500.00	SR Technics Switzerland
668918	340-002-305-0	EASA,FAA,CAAC,ANAC	11	28	72-23-03	CFM56-7B OUTLET GUIDE VANE PIECE	Package A	CLN/INSP	CLEANING AND INSPECTION		90.00	SRTAS
668928	9324M61G02	EASA,FAA,CAAC,ANAC	2	28	72-XX-XX	CFM56-7B HPT ROTOR ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		3500.00	SR Technics Switzerland

For new capability, please refer to our homepage <https://cpc.srtechnics.com>

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
668928	9324M61G08	EASA,FAA,ANAC			72-XX-XX		Package A	SPEC PROC-005	EDDY CURRENT INSPECTION (ECI)	72-00-52	3500.00	SR Technics Switzerland
668928					72-XX-XX		Package B		REPLACE MARKED CLINCH NUTS	72-52-02	270.00	SR Technics Switzerland
672596	1386M56P02	EASA,FAA,CAAC,ANAC	6	28	72-31-07	CFM56 COMPRESSOR ROTOR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		910.00	SR Technics Switzerland
672596	1386M56P03	EASA,FAA,CAAC,ANAC			72-31-07		Package B	INSP-001	APPLY DRY FILM LUBRICANT		1515.00	SR Technics Switzerland
672596	1590M28G01	EASA,FAA,CAAC,ANAC			72-31-07		Package B	INSP-001	BLENDING REPAIR		1515.00	SR Technics Switzerland
672596	1590M28G02	EASA,FAA,CAAC,ANAC			72-31-07		Package E	004	REPAIR ROTOR LOCK SLOT		3145.00	SR Technics Switzerland
672596	1590M28G04	EASA,FAA,CAAC,ANAC			72-31-07		Package F	005	REPAIR ROTOR SHAFT		5780.00	SR Technics Switzerland
672596	1590M28G05	EASA,FAA,CAAC,ANAC			72-31-07		Package G	006	ROTOR SHAFT DAMAGED THREADS		1645.00	SR Technics Switzerland
672596					72-31-07		Package SB00	AD 2002-13-03	ENHANCED LLP INSP	AD 2002-13-03_007	760.00	SR Technics Switzerland
672596					72-31-07		Package SB01	72-0500	REWK HPC SHAFT PART NUMBERS TO THE IPC		270.00	SR Technics Switzerland
673759	314A2630-100	EASA,FAA,CAAC,ANAC	2	35	78-11-39	TURBINE EXHAUST PRIMARY NOZZLE ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		3400.00	SR Technics Switzerland
673759	314A2630-101	EASA,FAA,ANAC			78-11-39		Package B	INSP	FLUORESCENT PENETRANT INSPECTION		325.00	SR Technics Switzerland
673759	314A2630-102	EASA,FAA,CAAC,ANAC			78-11-39		Package C		REPAIR UNSCHEDULED		930.00	SR Technics Switzerland
673781	301-319-724-0	EASA,FAA,CAAC,ANAC	6	28	72-55-06	CFM56 LP TURBINE CENTER VENT TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		480.00	SR Technics Switzerland
673781	340-170-301-0	EASA,FAA,CAAC,ANAC,CAA UK			72-55-06		Package AN		REMOVE HIGH METAL	SPM 70-41-11	180.00	SR Technics Switzerland
673781					72-55-06		Package B	01	REPAIR OF THE FRONT AND/OR MID JOURNALS		1940.00	SR Technics Switzerland
673781					72-55-06		Package C	02	REPAIR OF THE AFT JOURNAL		2440.00	SR Technics Switzerland
673781					72-55-06		Package D	03	CENTRAL SECTION REPLACEMENT		3395.00	SR Technics Switzerland
673781					72-55-06		Package E	04	REPLACEMENT OF ONE OR TWO MID JOURNAL SECTIONS		3655.00	SR Technics Switzerland
673781					72-55-06		Package F	05	REPLACEMENT OF THE FORWARD SECTION		2565.00	SR Technics Switzerland
673781					72-55-06		Package G	06	REPAIR OF THE LOCATING HOLES		1225.00	SR Technics Switzerland
673781					72-55-06		Package H	07	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		3870.00	SR Technics Switzerland
673781					72-55-06		Package I	08	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		3615.00	SR Technics Switzerland
673781					72-55-06		Package J	09	LAST CLEANING AND CONDITIONING OF THE CENTER VENT TUBE		410.00	SR Technics Switzerland
673781					72-55-06		Package K	10	WELD BUILD UP OF THE REAR SLOTS FACES		1775.00	SR Technics Switzerland
673781					72-55-06		Package L	11	REPAIR OF CRACK IN THE CENTRAL SECTION BY WELD BUILD-UP		2205.00	SR Technics Switzerland
673781					72-55-06		Package M	12	REPLACEMENT OF AFT SECTION		2120.00	SR Technics Switzerland
673781					72-55-06		Package O	14	REPAIR OF ILLEGIBLE PART MARKINGS		110.00	SR Technics Switzerland
673781					72-55-06		Package P	15	REPLACE FORWARD JOURNAL		2805.00	SR Technics Switzerland
453	338-111-303-0	EASA,FAA,CAAC,ANAC	36	28	72-53-08	STAGE 1 LPT NOZZLE - REAR FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		1035.00	SR Technics Switzerland
453	338-111-304-0	EASA,FAA,CAAC,ANAC			72-53-08		Package B	2	REPAIR OF THE PLASMA THERMAL COATING ON THE FACE MATING WITH THE STAGE 1 LPT NOZZLE SEGMENTS		2520.00	SR Technics Switzerland
453	338-111-305-0	EASA,FAA,CAAC,ANAC			72-53-08		Package D	4	REPAIR OF THE MATING FACE BY PLASMA SPRAYING		2650.00	SR Technics Switzerland
1518	1559M16G01	EASA,FAA,CAAC,ANAC	41	28	72-33-02	COMPRESSOR REAR STATOR - VANE SECTORS	Package A	CLN/INSP	CLEANING AND INSPECTION		210.00	SRTAS
1518	1559M16G02	EASA,FAA,CAAC,ANAC			72-33-02		Package B		FULL REPAIR STAGE 6/7/8		485.00	SRTAS
1518	1559M16G03	EASA,FAA,CAAC,ANAC			72-33-02		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		485.00	SRTAS
1518	1559M16G04	EASA,FAA,CAAC,ANAC			72-33-02		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		485.00	SRTAS
1518	1559M17G01	EASA,FAA,CAAC,ANAC			72-33-02		Package C		ADDITIONAL WORK SCOPE STAGE 6		870.00	SRTAS
1518	1559M17G02	EASA,FAA,CAAC,ANAC			72-33-02		Package C	004	REBRAZE REPAIR WITHOUT AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	870.00	SRTAS
1518	1559M17G03	EASA,FAA,CAAC,ANAC			72-33-02		Package D		ADDITIONAL WORK SCOPE STAGE 6		1165.00	SRTAS
1518	1559M17G04	EASA,FAA,CAAC,ANAC			72-33-02		Package D	004	REBRAZE WITH SINGLE AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	1165.00	SRTAS
1518	1559M18G01	EASA,FAA,CAAC,ANAC			72-33-02		Package D	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTO	INCLUDES PACKAGE B	1165.00	SRTAS
1518	1559M18G02	EASA,FAA,CAAC,ANAC			72-33-02		Package E		FOR EACH ADDITIONAL AIRFOIL REPLACEMENT		355.00	SRTAS
1518	1559M18G03	EASA,FAA,CAAC,ANAC			72-33-02		Package E		ADDITIONAL WORK SCOPE STAGE 6		355.00	SRTAS
1518	1559M18G04	EASA,FAA,CAAC,ANAC			72-33-02		Package F		ADDITIONAL WORK SCOPE STAGE 6		70.00	SRTAS
1518	P206G05	EASA,FAA,CAAC,ANAC			72-33-02		Package F	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONIUNCTION WITH REPAIR 001,002 OR	70.00	SRTAS
1518	P206G06	EASA,FAA,CAAC,ANAC			72-33-02		Package G		ADDITIONAL WORK SCOPE STAGE 6		115.00	SRTAS
1518	P206G07	EASA,FAA,CAAC,ANAC			72-33-02		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONIUNCTION WITH PACKAGE A	115.00	SRTAS
1518	P206G08	EASA,FAA,CAAC,ANAC			72-33-02		Package H		ADDITIONAL WORK SCOPE STAGE 6		880.00	SRTAS
1518	P207G01	EASA,FAA,CAAC,ANAC			72-33-02		Package H	008	INNER PLATFORM J-HOOK		880.00	SRTAS
1518	P207G02	EASA,FAA,CAAC,ANAC			72-33-02		Package J		ADDITIONAL WORK SCOPE STAGE 7		875.00	SRTAS
1518	P207G03	EASA,FAA,CAAC,ANAC			72-33-02		Package J	004	REBRAZE REPAIR WITHOUT AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	875.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1518	P207G04	EASA,FAA,CAAC,ANAC			72-33-02		Package K		ADDITIONAL WORK SCOPE STAGE 7		1120.00	SRTAS
1518	P207G05	EASA,FAA,CAAC,ANAC			72-33-02		Package K	004	REBRAZE WITH SINGLE AIRFOIL REPLACEMENT	INCLUDES PACKAGE I	1120.00	SRTAS
1518	P207G06	EASA,FAA,CAAC,ANAC			72-33-02		Package K	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTO	INCLUDES PACKAGE I	1120.00	SRTAS
1518	P207G07	EASA,FAA,CAAC,ANAC			72-33-02		Package L		ADDITIONAL WORK SCOPE STAGE 7		360.00	SRTAS
1518	P207G08	EASA,FAA,CAAC,ANAC			72-33-02		Package L		FOR EACH ADDITIONAL AIRFOIL REPLACEMENT		360.00	SRTAS
1518	P208G01	EASA,FAA,CAAC,ANAC			72-33-02		Package M		ADDITIONAL WORK SCOPE STAGE 7		70.00	SRTAS
1518	P208G02	EASA,FAA,CAAC,ANAC			72-33-02		Package M	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH REPAIR 001,002 OR	70.00	SRTAS
1518	P208G03	EASA,FAA,CAAC,ANAC			72-33-02		Package N		ADDITIONAL WORK SCOPE STAGE 7		115.00	SRTAS
1518	P208G04	EASA,FAA,CAAC,ANAC			72-33-02		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	115.00	SRTAS
1518	P208G05	EASA,FAA,CAAC,ANAC			72-33-02		Package O		ADDITIONAL WORK SCOPE STAGE 7		880.00	SRTAS
1518	P208G06	EASA,FAA,CAAC,ANAC			72-33-02		Package O	008	INNER PLATFORM J-HOOK		880.00	SRTAS
1518	P246G01	EASA,FAA,CAAC,ANAC			72-33-02		Package Q		ADDITIONAL WORKS COPE STAGE 8		880.00	SRTAS
1518	P246G02	EASA,FAA,CAAC,ANAC			72-33-02		Package Q	004	REBRAZE REPAIR WITHOUT AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	880.00	SRTAS
1518	P246G03	EASA,FAA,CAAC,ANAC			72-33-02		Package R		ADDITIONAL WORK SCOPE STAGE 8		1145.00	SRTAS
1518	P246G04	EASA,FAA,CAAC,ANAC			72-33-02		Package R	004	REBRAZE WITH SINGLE AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	1145.00	SRTAS
1518	P246G09	EASA,FAA,CAAC,ANAC			72-33-02		Package R	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTO	INCLUDES PACKAGE B	1145.00	SRTAS
1518	P247G01	EASA,FAA,CAAC,ANAC			72-33-02		Package S		FOR EACH ADDITIONAL AIRFOIL REPLACEMENT		355.00	SRTAS
1518	P247G02	EASA,FAA,CAAC,ANAC			72-33-02		Package S		ADDITIONAL WORK SCOPE STAGE 8		355.00	SRTAS
1518	P247G03	EASA,FAA,CAAC,ANAC			72-33-02		Package T		ADDITIONAL WORKS COPE STAGE 8		70.00	SRTAS
1518	P247G04	EASA,FAA,CAAC,ANAC			72-33-02		Package T	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH REPAIR 001,002 OR	70.00	SRTAS
1518	P247G09	EASA,FAA,CAAC,ANAC			72-33-02		Package U		ADDITIONAL WORK SCOPE STAGE 8		115.00	SRTAS
1518	P248G01	EASA,FAA,CAAC,ANAC			72-33-02		Package U	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	115.00	SRTAS
1518	P248G02	EASA,FAA,CAAC,ANAC			72-33-02		Package V		ADDITIONAL WORKS COPE STAGE 8		895.00	SRTAS
1518	P248G03	EASA,FAA,CAAC,ANAC			72-33-02		Package V	008	INNER PLATFORM J-HOOK		895.00	SRTAS
1518	P248G04	EASA,FAA,CAAC,ANAC			72-33-02		Package W		ADDITIONAL WORK SCOPE STAGE 7/8/9		840.00	SRTAS
1518	P256G01	EASA,FAA,CAAC,ANAC			72-33-02		Package W	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTORS		840.00	SRTAS
1518	P256G02	EASA,FAA,CAAC,ANAC										
1518	P256G03	EASA,FAA,CAAC,ANAC										
1518	P256G04	EASA,FAA,CAAC,ANAC										
1518	P256G05	EASA,FAA,CAAC,ANAC										
1518	P256G06	EASA,FAA,CAAC,ANAC										
1518	P256G07	EASA,FAA,CAAC,ANAC										
1518	P256G08	EASA,FAA,CAAC,ANAC										
1518	P257G01	EASA,FAA,CAAC,ANAC										
1518	P257G02	EASA,FAA,CAAC,ANAC										
1518	P257G03	EASA,FAA,CAAC,ANAC										
1518	P257G04	EASA,FAA,CAAC,ANAC										
1518	P258G01	EASA,FAA,CAAC,ANAC										
1518	P258G02	EASA,FAA,CAAC,ANAC										
1518	P258G03	EASA,FAA,CAAC,ANAC										
1524	390-660-001-0	EASA,FAA,CAAC,ANAC	3	21	73-24-06	IDENTIFICATION PLUG CFM56-7B	Package A	TEST	TESTING AND TROUBLESHOOTING		335.00	SR Technics Switzerland
1524	390-660-101-0	EASA,FAA,CAAC,ANAC			73-24-06		Package B		REPAIR		880.00	SR Technics Switzerland
1524	390-660-201-0	EASA,FAA,CAAC,ANAC			73-24-06		Package C		OVERHAUL		1155.00	SR Technics Switzerland
1524	390-660-301-0	EASA,FAA,CAAC,ANAC			73-24-06		Package SB00	72-0106	INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS		305.00	SR Technics Switzerland
1524	390-660-401-0	EASA,FAA,CAAC,ANAC			73-24-06		Package SB01	73-0181	INTRODUCTION OF NEW CODING COMBINATIONS FOR -7B LPT HARDWARE		305.00	SR Technics Switzerland
1524	390-660-501-0	EASA,FAA,CAAC,ANAC										
1524	390-660-801-0	EASA,FAA,CAAC,ANAC										
1524	390-661-201-0	EASA,FAA,CAAC,ANAC										
1524	390-661-301-0	EASA,FAA,CAAC,ANAC										
1524	390-661-401-0	EASA,FAA,CAAC,ANAC										
1524	390-661-501-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1524	390-663-501-0	EASA,FAA,CAAC,ANAC										
1548	1476M51P01	EASA,FAA,CAAC,ANAC,CAA UK	31	28	72-32-13	COMPRESSOR FRONT STATOR - VSV ACTUATION HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION	PRICE PER STAGE	250.00	SR Technics Switzerland
1548	1476M80P01	EASA,FAA,CAAC,ANAC			72-32-13		Package B	002	REPAIR FOR THE STAGE 1, STAGE 2 AND STAGE 3 BELLCRANK BORES	PRICE PER STAGE	1015.00	SR Technics Switzerland
1548	1558M35G01	EASA,FAA,CAAC,ANAC										
1548	1559M91P01	EASA,FAA,CAAC,ANAC										
1548	9511M24P04	EASA,FAA,CAAC,ANAC										
1548	9511M24P07	EASA,FAA,CAAC,ANAC										
1548	9511M26P02	EASA,FAA,CAAC,ANAC										
1820	1523M42G02	EASA,FAA,CAAC,ANAC	33	28	72-51-05	HIGH PRESSURE TURBINE NOZZLE - OUTER STATIONARY SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
1820	1523M42G04	EASA,FAA,CAAC,ANAC			72-51-05		Package A	INSP-001	TI 315026 CRACKS IN SCALLOPS		820.00	SR Technics Switzerland
1820	1784M84G01	EASA,FAA,CAAC,ANAC			72-51-05		Package D	003	HONEYCOMB REPLACEMENT		7615.00	SR Technics Switzerland
1820	1784M84G02	EASA,FAA,CAAC,ANAC			72-51-05		Package E	004	DIAMETER B DIMENSIONAL RESTORATION		2495.00	SR Technics Switzerland
1820	1784M84G05	EASA,FAA,CAAC,ANAC			72-51-05		Package G	006	DIAMETER F MACHINING REPAIR		855.00	SR Technics Switzerland
1820	1808M58G01	EASA,FAA,CAAC,ANAC			72-51-05		Package S800	72-0092	INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL		1115.00	SR Technics Switzerland
1820	1808M58G03	EASA,FAA,CAAC,ANAC										
1820	1808M58G05	EASA,FAA,CAAC,ANAC										
1820	1808M58G07	EASA,FAA,CAAC,ANAC										
1820	1808M58G08	EASA,FAA,CAAC,ANAC										
1820	2091M57G01	EASA,FAA,CAAC,ANAC										
1820	2091M57G02	EASA,FAA,CAAC,ANAC										
1820	2091M57G03	EASA,FAA,CAAC,ANAC										
1920	332A2310-1	EASA,FAA,CAAC,ANAC	9	21	36-10-03	CFM56-7B PNEUMATIC DUCT	Package A	CLN/INSP	CLEANING INSPECTION AND TEST		595.00	SR Technics Switzerland
1920	332A2310-4	EASA,FAA,CAAC,ANAC			36-10-03		Package D	LIGHT	MINOR REPAIR		1125.00	SR Technics Switzerland
1920	332A2313-1	EASA,FAA,CAAC,ANAC			36-10-03		Package F	HEAVY	MAJOR REPAIR		2790.00	SR Technics Switzerland
1920	332A2321-10	EASA,FAA,CAAC,ANAC										
1920	332A2322-47	EASA,FAA,CAAC,ANAC										
1920	332A2322-54	EASA,FAA,CAAC,ANAC										
1920	332A2323-10	EASA,FAA,CAAC,ANAC										
1920	332A2323-14	EASA,FAA,CAAC,ANAC										
1920	332A2326-30	EASA,FAA,CAAC,ANAC										
1920	332A2326-45	EASA,FAA,CAAC,ANAC										
1920	332A2390-12	EASA,FAA,CAAC,ANAC										
1920	332A2390-3	EASA,FAA,CAAC,ANAC										
1920	332A2390-43	EASA,FAA,CAAC,ANAC										
1920	332A2390-45	EASA,FAA,CAAC,ANAC										
1920	332A2390-48	EASA,FAA,CAAC,ANAC										
2009	1498M45P03	EASA,FAA,CAAC,ANAC	47	28	72-52-05	HIGH PRESSURE TURBINE ROTOR - REAR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1400.00	SR Technics Switzerland
2009	1498M45P04	EASA,FAA,CAAC,ANAC,TCCA			72-52-05		Package B	INSP-001	REMOVE HIGH METAL		280.00	SR Technics Switzerland
2009	1498M45P05	EASA,FAA,CAAC,ANAC			72-52-05		Package B	INSP-001	BLENDING AIRSEAL		280.00	SR Technics Switzerland
2009	1498M45P06	EASA,FAA,CAAC,ANAC			72-52-05		Package C	001	REPLACEMENT OF SEAL TEETH WEAR COATING		5690.00	SR Technics Switzerland
2009	1498M45P07	EASA,FAA,CAAC,ANAC			72-52-05		Package F	005	THERMAL SPRAY REPAIR OF THE BEARING JOURNAL		7090.00	SR Technics Switzerland
2009	1498M45P08	EASA,FAA,CAAC,ANAC			72-52-05		Package G	006	HPT AFT SHAFT THERMAL SPRAY REPAIR OF AREA M		6945.00	SR Technics Switzerland
2009	1864M90P04	EASA,FAA,CAAC,ANAC			72-52-05		Package M	012	BLEND ANTI-ROTATION SLOTS		625.00	SR Technics Switzerland
2009	1864M90P05	EASA,FAA,CAAC,ANAC										
2009	1864M90P06	EASA,FAA,CAAC,ANAC										
2009	1864M90P07	EASA,FAA,CAAC,ANAC										
2009	1873M62G02	EASA,FAA,CAAC,ANAC										
2009	1873M62G03	EASA,FAA,CAAC,ANAC										
2009	1873M62G04	EASA,FAA,CAAC,ANAC										
2009	1873M62G05	EASA,FAA,CAAC,ANAC										
2082	1493M73G04	EASA,FAA,CAAC,ANAC	27	28	72-42-00	COMBUSTION CHAMBER (SAC)	Package A	CLN/INSP	CLEANING AND INSPECTION		4140.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2082	1493M73G06	EASA,FAA,CAAC,ANAC			72-42-00		Package F		DISASSEMBLY AND ASSEMBLY	EXCLUDED PIECE PART REPAIRS	3425.00	SR Technics Switzerland
2082	1493M73G08	EASA,FAA,CAAC,ANAC			72-42-00		Package I	INSP-001	WELD TAB ENDS		330.00	SR Technics Switzerland
2082	1968M41G01	EASA,FAA,CAAC,ANAC			72-42-00		Package SB00	72-0227	INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M41G02	EASA,FAA,CAAC,ANAC			72-42-00		Package SB04	72-0110	BIRD BUMPER (SWIRLER) ELIMINATION AND INTRODUCTION OF COMBUSTION CH/	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M41G03	EASA,FAA,CAAC,ANAC			72-42-00		Package SB05	72-0547	ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M41G04	EASA,FAA,CAAC,ANAC			72-42-00		Package SB06	72-0103	INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M46G08	EASA,FAA,CAAC,ANAC			72-42-00		Package SB09	72-0795	NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M46G10	EASA,FAA,CAAC,ANAC			72-42-00		Package SB12	72-0786	NEW OUTER LINER FOR HARSH ENVIROMENT OPERATORS	IN CONJUNCTION WITH PACKAGE F	250.00	SR Technics Switzerland
2082	1968M65G01	EASA,FAA,CAAC,ANAC										
2082	1968M65G03	EASA,FAA,CAAC,ANAC										
2082	1968M68G04	EASA,FAA,CAAC,ANAC										
2082	1968M68G06	EASA,FAA,CAAC,ANAC										
2082	1968M68G07	EASA,FAA,CAAC,ANAC										
2082	1968M68G08	EASA,FAA,CAAC,ANAC										
2082	1968M68G16	EASA,FAA,CAAC,ANAC										
2082	1968M68G17	EASA,FAA,CAAC,ANAC										
2082	1968M68G19	EASA,FAA,CAAC,ANAC										
2082	1968M68G20	EASA,FAA,CAAC,ANAC										
2082	1968M68G22	EASA,FAA,CAAC,ANAC										
2082	1968M68G41	EASA,FAA,CAAC,ANAC										
2082	2256M26G03	EASA,FAA,CAAC,ANAC										
2082	2256M26G04	EASA,FAA,CAAC,ANAC										
2082	2480M46G01	EASA,FAA,CAAC,CAAC,ANAC										
2187	305-136-803-0	EASA,FAA,CAAC,ANAC,CAA UK	20	28	72-62-06	TRANSFER GEARBOX - HORIZONTAL DRIVE SHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1085.00	SR Technics Switzerland
2187	305-136-804-0	EASA,ANAC,CAA UK			72-62-06		Package SB00	72-0291	FOLLOWING THE INSPECTION REWORK OR/AND REIDENTIFICATION OF A SPECIFIC	OUTER RADIAL DRIVE SHAFT REPLACEMENT	415.00	SR Technics Switzerland
2187	305-136-805-0	EASA,FAA,CAAC,ANAC,CAA UK										
2187	340-050-101-0	EASA,FAA,CAAC,ANAC										
2187	340-050-102-0	EASA,FAA,CAAC,ANAC										
2187	340-050-103-0	EASA,FAA,CAAC,ANAC										
2187	340-051-101-0	EASA,FAA,CAAC,ANAC										
2425	762246	EASA,FAA,CAAC,ANAC	3	21	24-19-15	CFM56-7B QUICK ATTACH-DETACH ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		800.00	SR Technics Switzerland
2425	S281A001-501	EASA,FAA,CAAC,ANAC										
3016	9324M67G01	EASA,FAA,ANAC	21	28	72-33-00	COMPRESSOR REAR STATOR - ASSEMBLY	Package B	ASSEMBLY	HONEY COMB GRINDING	PN9324M67G01 9324M77G01 FOR SHOP V	1780.00	SR Technics Switzerland
3461	301-480-220-0	EASA,FAA,CAAC,ANAC	19	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BI REWORK/	Package A	CLN/INSP	CLEANING AND INSPECTION		1320.00	SR Technics Switzerland
3461	301-480-221-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB00	72-0368	Replacement of Ball Bearing 340-052-602-0		465.00	SR Technics Switzerland
3461	301-480-225-0	EASA,FAA,CAAC,ANAC										
3461	301-480-320-0	EASA,FAA,CAAC,ANAC										
3461	301-480-326-0	EASA,FAA,CAAC,ANAC										
3461	301-480-720-0	EASA,FAA,CAAC,ANAC										
3461	301-480-724-0	EASA,FAA,CAAC,ANAC										
3461	301-480-726-0	EASA,FAA,CAAC,ANAC										
3461	301-480-920-0	EASA,FAA,CAAC,ANAC										
3461	301-480-923-0	EASA,FAA,CAAC,ANAC										
3461	301-480-926-0	EASA,FAA,CAAC,ANAC										
3461	301-481-220-0	EASA,FAA,CAAC,ANAC										
3461	301-481-223-0	EASA,FAA,CAAC,ANAC										
3461	301-481-225-0	EASA,FAA,CAAC,ANAC										
3461	305-100-410-0	EASA,FAA,CAAC,ANAC										
3461	305-100-415-0	EASA,FAA,CAAC,ANAC										
3461	305-115-100-0	EASA,FAA,CAAC,ANAC										
3461	305-115-104-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	305-115-200-0	EASA,FAA,CAAC,ANAC										
3461	305-115-201-0	EASA,FAA,CAAC,ANAC										
3461	305-115-205-0	ANAC										
3461	305-115-306-0	EASA,FAA,CAAC,ANAC										
3461	305-132-701-0	EASA,FAA,CAAC,ANAC										
3461	305-132-702-0	EASA,FAA,CAAC,ANAC										
3461	305-148-201-0	EASA,FAA,CAAC,ANAC										
3461	305-148-202-0	EASA,FAA,CAAC,ANAC										
3461	335-304-101-0	EASA,FAA,CAAC,ANAC										
3461	335-304-102-0	EASA,FAA,CAAC,ANAC										
3461	335-304-103-0	EASA,FAA,CAAC,ANAC										
3461	335-304-201-0	EASA,FAA,CAAC,ANAC										
3461	335-304-202-0	EASA,FAA,CAAC,ANAC										
3461	335-304-203-0	EASA,FAA,CAAC,ANAC										
3461	335-304-401-0	EASA,FAA,CAAC,ANAC										
3461	335-304-402-0	EASA,FAA,CAAC,ANAC										
3461	335-304-501-0	EASA,FAA,CAAC,ANAC										
3461	335-304-503-0	EASA,FAA,CAAC,ANAC										
3461	335-304-601-0	EASA,FAA,CAAC,ANAC										
3461	335-304-602-0	EASA,FAA,CAAC,ANAC										
3461	335-304-603-0	EASA,FAA,CAAC,ANAC										
3461	335-304-901-0	EASA,FAA,CAAC,ANAC										
3461	335-304-902-0	EASA,FAA,CAAC,ANAC										
3461	335-304-903-0	EASA,FAA,CAAC,ANAC										
3461	340-050-401-0	EASA,FAA,CAAC,ANAC										
3461	340-050-402-0	EASA,FAA,CAAC,ANAC										
3461	340-050-404-0	EASA,FAA,ANAC										
3461	340-050-901-0	EASA,FAA,CAAC,ANAC										
3461	340-050-902-0	EASA,FAA,CAAC,ANAC										
3461	340-051-001-0	EASA,FAA,CAAC,ANAC										
3461	340-051-002-0	EASA,FAA,CAAC,ANAC										
3461	340-052-502-0	EASA,FAA,CAAC,ANAC										
3461	340-052-503-0	EASA,FAA,CAAC,ANAC										
3461	340-052-602-0	EASA,FAA,CAAC,ANAC										
3461	340-052-603-0	EASA,FAA,CAAC,ANAC										
3461	340-054-502-0	EASA,FAA,CAAC,ANAC										
3461	340-054-503-0	EASA,FAA,CAAC,ANAC										
3461	340-055-801-0	EASA,FAA,CAAC,ANAC										
3461	340-055-901-0	EASA,FAA,CAAC,ANAC										
3461	340-056-001-0	EASA,FAA,CAAC,ANAC										
3461	340-056-101-0	EASA,FAA,CAAC,ANAC										
3461	340-056-102-0	EASA,FAA,ANAC,CAA UK										
3461	340-056-202-0	EASA,FAA,CAAC,ANAC										
3461	340-056-302-0	EASA,FAA,CAAC,ANAC										
3461	340-056-401-0	EASA,FAA,CAAC,ANAC										
3461	340-154-101-0	EASA,FAA,CAAC,ANAC										
3461	340-154-201-0	EASA,FAA,CAAC,ANAC										
3461	340-155-101-0	EASA,FAA,CAAC,ANAC										
3461	9541M89P01	EASA,FAA,CAAC,ANAC										
3461	9725M84P08	EASA,FAA,CAAC,ANAC										
3461	9725M84P09	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	9972M33P06	EASA,FAA,CAAC,ANAC										
3461	9972M33P07	EASA,FAA,CAAC,ANAC										
3461	9972M33P08	EASA,FAA,CAAC,ANAC										
3461	9972M34P08	EASA,FAA,CAAC,ANAC										
3461	9972M34P09	EASA,FAA,CAAC,ANAC										
3461	9972M34P10	EASA,FAA,CAAC,ANAC										
3941	J818P050A	EASA,FAA,CAAC,ANAC	5	28	72-21-11	CFM56 BOLT-SHEAR DBL HEX HD FAN AND BOOS	Package A	CLN/INSP	CLEANING AND INSPECTION		35.00	SR Technics Switzerland
3941	J818P060A	EASA,FAA,CAAC,ANAC										
8127	310A2037-11	EASA,FAA,CAAC,ANAC	13	21	71-21-37	FWD AND AFT ENGINE MOUNT- PIN-PAWL THRUST LINK PIN	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
8127	310A2037-12	EASA,FAA,CAAC,ANAC			71-21-37		Package D	8-1	LINK PIN OD CHROMING REPAIR		820.00	SR Technics Switzerland
8127	310A2037-13	EASA,FAA,CAAC,ANAC										
8127	310A2037-14	EASA,FAA,CAAC,ANAC										
8127	310A2037-15	EASA,FAA,CAAC,ANAC										
8127	310A2037-16	EASA,FAA,CAAC,ANAC										
8127	310A2037-4	EASA,FAA,CAAC,ANAC										
8127	310A2037-5	EASA,FAA,CAAC,ANAC										
8127	310A2037-6	EASA,FAA,CAAC,ANAC										
8127	310A2037-7	EASA,FAA,CAAC,ANAC										
8127	310A2037-9	EASA,FAA,CAAC,ANAC										
9003	307-020-601-0	EASA,FAA,CAAC,ANAC	17	28	72-23-11	FAN FRAME ASSEMBLY - RADIAL DRIVE SHAFT VESPEL NUT	Package A	CLN/INSP	CLEANING AND INSPECTION	SELFLOCKING QUALITY CHECK	260.00	SR Technics Switzerland
9003	340-050-502-0	EASA,FAA,CAAC,ANAC										
9003	340-050-503-0	EASA,FAA,CAAC,ANAC										
11542	301-792-202-0	EASA,FAA,CAAC,ANAC	42	28	72-23-35	FAN FRAME ASSEMBLY - FAN FRAME HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		70.00	SR Technics Switzerland
11542	301-792-302-0	EASA,FAA,CAAC,ANAC			72-23-35		Package B	001	REPLACEMENT OF BLIND BOLTS AND RESILIENT MOUNTS		50.00	SR Technics Switzerland
11542	305-355-901-0	EASA,FAA,ANAC			72-23-35		Package SB00	72-0475	INTRODUCTION OF NEW AIR TUBE, A NEW BRACKET ASSY WITH SAFETY WIRDE HO REWORK OF THE PREVIOUS CONFIGURATIC		190.00	SR Technics Switzerland
11542	337-060-801-0	EASA,FAA,ANAC			72-23-35		Package SB01	72-0570	IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD		785.00	SR Technics Switzerland
11542	338-077-001-0	EASA,FAA,ANAC			72-23-35		Package SB02	72-0248	REPLACEMENT OR REWORK OF BRACKET ASSY ATTACHING THE MW0301 ELECTRICAL HARNESS ON FLANGE B4		500.00	SR Technics Switzerland
11542	340-005-202-0	EASA,FAA,CAAC,ANAC			72-23-35		Package SB03	72-0754	INTRODUCTION OF BRACKETS WITH NEW DESIGN		165.00	SR Technics Switzerland
11542	340-005-301-0	EASA,FAA,CAAC,ANAC										
11542	340-005-302-0	EASA,FAA,CAAC,ANAC										
11542	340-005-401-0	EASA,FAA,CAAC,ANAC										
11542	340-005-402-0	EASA,FAA,CAAC,ANAC										
11542	340-005-502-0	EASA,FAA,CAAC,ANAC										
11542	340-005-602-0	EASA,FAA,CAAC,ANAC										
11542	340-005-801-0	EASA,FAA,CAAC,ANAC										
11542	340-005-802-0	EASA,FAA,CAAC,ANAC										
11542	340-006-202-0	EASA,FAA,CAAC,ANAC										
11542	340-006-301-0	EASA,FAA,CAAC,ANAC										
11542	340-006-502-0	EASA,FAA,CAAC,ANAC										
11542	340-006-503-0	EASA,FAA,CAAC,ANAC										
11542	340-006-504-0	EASA,FAA,CAAC,ANAC										
11542	340-006-602-0	EASA,FAA,CAAC,ANAC										
11542	340-006-603-0	EASA,FAA,CAAC,ANAC										
11542	340-006-604-0	EASA,FAA,CAAC,ANAC										
11542	340-006-702-0	EASA,FAA,CAAC,ANAC										
11542	340-006-703-0	EASA,FAA,CAAC,ANAC										
11542	340-006-802-0	EASA,FAA,CAAC,ANAC										
11542	340-006-803-0	EASA,FAA,CAAC,ANAC										
11542	340-007-304-0	EASA,FAA,CAAC,ANAC										
11542	340-007-404-0	EASA,FAA,CAAC,ANAC										
11542	340-008-703-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-008-801-0	EASA,FAA,CAAC,ANAC										
11542	340-008-902-0	EASA,FAA,CAAC,ANAC										
11542	340-008-903-0	EASA,FAA,CAAC,ANAC										
11542	340-008-904-0	EASA,FAA,CAAC,ANAC										
11542	340-009-003-0	EASA,FAA,CAAC,ANAC										
11542	340-009-004-0	EASA,FAA,CAAC,ANAC										
11542	340-013-703-0	EASA,FAA,CAAC,ANAC										
11542	340-015-003-0	EASA,FAA,CAAC,ANAC										
11542	340-015-004-0	EASA,FAA,CAAC,ANAC										
11542	340-017-002-0	EASA,FAA,CAAC,ANAC										
11542	340-017-305-0	EASA,FAA,CAAC,ANAC										
11542	340-017-306-0	EASA,FAA,CAAC,ANAC										
11542	340-017-502-0	EASA,FAA,CAAC,ANAC										
11542	340-017-601-0	EASA,FAA,CAAC,ANAC										
11542	340-017-602-0	EASA,FAA,CAAC,ANAC										
11542	340-017-804-0	EASA,FAA,CAAC,ANAC										
11542	340-017-805-0	EASA,FAA,CAAC,ANAC										
11542	340-017-806-0	EASA,FAA,CAAC,ANAC										
11542	340-019-903-0	EASA,FAA,CAAC,ANAC										
11542	340-020-001-0	EASA,FAA,CAAC,ANAC										
11542	340-020-105-0	EASA,FAA,CAAC,ANAC										
11542	340-020-203-0	EASA,FAA,CAAC,ANAC										
11542	340-020-303-0	EASA,FAA,CAAC,ANAC										
11542	340-020-403-0	EASA,FAA,CAAC,ANAC										
11542	340-020-404-0	EASA,FAA,CAAC,ANAC										
11542	340-022-501-0	EASA,FAA,CAAC,ANAC										
11542	340-022-502-0	EASA,FAA,CAAC,ANAC										
11542	340-022-901-0	EASA,FAA,CAAC,ANAC										
11542	340-023-301-0	EASA,FAA,CAAC,ANAC										
11542	340-023-302-0	EASA,FAA,CAAC,ANAC										
11542	340-023-404-0	EASA,FAA,CAAC,ANAC										
11542	340-023-405-0	EASA,FAA,CAAC,ANAC										
11542	340-025-402-0	EASA,FAA,CAAC,ANAC										
11542	340-025-503-0	EASA,FAA,CAAC,ANAC										
11542	340-067-504-0	EASA,FAA,CAAC,ANAC										
11542	340-067-505-0	EASA,FAA,CAAC,ANAC										
11542	340-067-506-0	EASA,FAA,CAAC,ANAC										
11542	340-087-804-0	EASA,FAA,CAAC,ANAC										
11542	340-088-503-0	EASA,FAA,CAAC,ANAC										
11542	340-088-602-0	EASA,FAA,CAAC,ANAC										
11542	340-088-901-0	EASA,FAA,CAAC,ANAC										
11542	340-089-001-0	EASA,FAA,CAAC,ANAC										
11542	340-090-301-0	EASA,FAA,CAAC,ANAC										
11542	340-090-402-0	EASA,FAA,CAAC,ANAC										
11542	340-090-501-0	EASA,FAA,CAAC,ANAC										
11542	340-090-601-0	EASA,FAA,CAAC,ANAC										
11542	340-090-602-0	EASA,FAA,CAAC,ANAC										
11542	340-090-603-0	EASA,FAA,CAAC,ANAC										
11542	340-090-701-0	EASA,FAA,CAAC,ANAC										
11542	340-090-902-0	EASA,FAA,CAAC,ANAC										
11542	340-091-001-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-091-403-0	EASA,FAA,CAAC,ANAC										
11542	340-093-701-0	EASA,FAA,CAAC,ANAC										
11542	340-095-501-0	EASA,FAA,CAAC,ANAC										
11542	340-095-602-0	EASA,FAA,CAAC,ANAC										
11542	340-095-603-0	EASA,FAA,CAAC,ANAC										
11542	340-095-703-0	EASA,FAA,CAAC,ANAC										
11542	340-096-003-0	EASA,FAA,CAAC,ANAC										
11542	340-096-004-0	EASA,FAA,CAAC,ANAC										
11542	340-096-005-0	EASA,FAA,ANAC										
11542	340-096-006-0	EASA,FAA,CAAC,ANAC										
11542	340-099-001-0	EASA,FAA,CAAC,ANAC										
11542	340-099-101-0	EASA,FAA,CAAC,ANAC										
11542	340-099-902-0	EASA,FAA,CAAC,ANAC										
11542	340-099-903-0	EASA,FAA,CAAC,ANAC										
11542	340-103-902-0	EASA,FAA,CAAC,ANAC										
11542	340-103-903-0	EASA,FAA,CAAC,ANAC										
11542	340-104-301-0	EASA,FAA,CAAC,ANAC										
11542	340-104-601-0	EASA,FAA,CAAC,ANAC										
11542	340-105-903-0	EASA,FAA,CAAC,ANAC										
11542	340-106-005-0	EASA,FAA,CAAC,ANAC										
11542	340-106-006-0	EASA,FAA,CAAC,ANAC										
11542	340-106-007-0	EASA,FAA,CAAC,ANAC										
11542	340-106-203-0	EASA,FAA,CAAC,ANAC										
11542	340-106-302-0	EASA,FAA,CAAC,ANAC										
11542	340-106-504-0	EASA,FAA,CAAC,ANAC										
11542	340-106-602-0	EASA,FAA,CAAC,ANAC										
11542	340-106-704-0	EASA,FAA,CAAC,ANAC										
11542	340-109-601-0	EASA,FAA,CAAC,ANAC										
11542	340-109-602-0	EASA,FAA,CAAC,ANAC										
11542	340-112-113-0	EASA,FAA,CAAC,ANAC										
11542	340-115-302-0	EASA,FAA,CAAC,ANAC										
11542	340-115-303-0	EASA,FAA,CAAC,ANAC										
11542	340-118-303-0	EASA,FAA,CAAC,ANAC										
11542	340-118-702-0	EASA,FAA,CAAC,ANAC										
11542	340-118-704-0	EASA,FAA,CAAC,ANAC										
11542	340-120-501-0	EASA,FAA,CAAC,ANAC										
11542	340-120-601-0	EASA,FAA,CAAC,ANAC										
11542	340-120-702-0	EASA,FAA,CAAC,ANAC										
11542	340-120-803-0	EASA,FAA,CAAC,ANAC										
11542	340-120-901-0	EASA,FAA,CAAC,ANAC										
11542	340-121-001-0	EASA,FAA,CAAC,ANAC										
11542	340-121-101-0	EASA,FAA,CAAC,ANAC										
11542	340-121-201-0	EASA,FAA,CAAC,ANAC										
11542	340-121-401-0	EASA,FAA,CAAC,ANAC										
11542	340-121-502-0	EASA,FAA,CAAC,ANAC										
11542	340-121-602-0	EASA,FAA,CAAC,ANAC										
11542	340-121-702-0	EASA,FAA,CAAC,ANAC										
11542	340-121-802-0	EASA,FAA,CAAC,ANAC										
11542	340-122-501-0	EASA,FAA,CAAC,ANAC										
11542	340-122-502-0	EASA,FAA,CAAC,ANAC										
11542	340-122-503-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-122-504-0	EASA,FAA,CAAC,ANAC										
11542	340-123-401-0	EASA,FAA,CAAC,ANAC										
11542	340-123-703-0	EASA,FAA,CAAC,ANAC										
11542	340-123-704-0	EASA,FAA,CAAC,ANAC										
11542	340-123-803-0	EASA,FAA,CAAC,ANAC										
11542	340-123-902-0	EASA,FAA,CAAC,ANAC										
11542	340-124-001-0	EASA,FAA,CAAC,ANAC										
11542	340-124-101-0	EASA,FAA,CAAC,ANAC										
11542	340-124-202-0	EASA,FAA,CAAC,ANAC										
11542	340-124-302-0	EASA,FAA,CAAC,ANAC										
11542	340-124-402-0	EASA,FAA,CAAC,ANAC										
11542	340-124-501-0	EASA,FAA,CAAC,ANAC										
11542	340-124-502-0	EASA,FAA,CAAC,ANAC										
11542	340-124-604-0	EASA,FAA,CAAC,ANAC										
11542	340-124-605-0	EASA,FAA,CAAC,ANAC										
11542	340-124-701-0	EASA,FAA,CAAC,ANAC										
11542	340-124-801-0	EASA,FAA,CAAC,ANAC										
11542	340-124-802-0	EASA,FAA,CAAC,ANAC										
11542	340-124-803-0	EASA,FAA,ANAC										
11542	340-125-702-0	EASA,FAA,CAAC,ANAC										
11542	340-125-703-0	EASA,FAA,CAAC,ANAC										
11542	340-126-102-0	EASA,FAA,CAAC,ANAC										
11542	340-126-104-0	EASA,FAA,CAAC,ANAC										
11542	340-126-107-0	EASA,FAA,ANAC										
11542	340-126-701-0	EASA,FAA,CAAC,ANAC										
11542	340-126-702-0	EASA,FAA,CAAC,ANAC										
11542	340-126-802-0	EASA,FAA,CAAC,ANAC										
11542	340-128-302-0	EASA,FAA,CAAC,ANAC										
11542	340-128-303-0	EASA,FAA,CAAC,ANAC										
11542	340-130-001-0	EASA,FAA,CAAC,ANAC										
11542	340-130-701-0	EASA,FAA,CAAC,ANAC										
11542	340-131-208-0	EASA,FAA,CAAC,ANAC										
11542	340-134-302-0	EASA,FAA,CAAC,ANAC										
11542	340-150-702-0	EASA,FAA,CAAC,ANAC										
11542	340-159-301-0	EASA,FAA,CAAC,ANAC										
11542	649-002-265-0	EASA,FAA,CAAC,ANAC										
11542	649-771-090-0	EASA,FAA,CAAC,ANAC										
11542	649-771-092-0	EASA,FAA,CAAC,ANAC										
11542	649-771-093-0	EASA,FAA,CAAC,ANAC										
11542	649-786-799-0	EASA,FAA,CAAC,ANAC										
11542	J534P04	EASA,FAA,CAAC,ANAC										
11542	J534P08	EASA,FAA,CAAC,ANAC										
11542	J534P54	EASA,FAA,CAAC,ANAC										
13450	340-082-602-0	EASA,FAA,CAAC,ANAC	12	28	72-23-09	FAN FRAME ASSEMBLY - STRUT PROFILE	Package A	CLN/INSP	CLEANING AND INSPECTION		205.00	SR Technics Switzerland
13450	340-082-702-0	EASA,FAA,CAAC,ANAC										
13450	340-082-802-0	EASA,FAA,CAAC,ANAC										
13450	340-082-902-0	EASA,FAA,CAAC,ANAC										
13450	340-083-002-0	EASA,FAA,CAAC,ANAC										
13450	340-083-102-0	EASA,FAA,CAAC,ANAC										
13450	340-083-202-0	EASA,FAA,CAAC,ANAC										
13450	340-083-203-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
13450	340-083-302-0	EASA,FAA,CAAC,ANAC										
13450	340-083-402-0	EASA,FAA,CAAC,ANAC										
13451	301-566-807-0	EASA,FAA,CAAC,ANAC	21	28	72-23-10	FAN FRAME ASSEMBLY - AGB STRAIGHT MOUNT PIN	Package A	CLN/INSP	CLEANING AND INSPECTION		135.00	SR Technics Switzerland
13451	336-030-701-0	EASA,FAA,CAAC,ANAC										
13451	J626P09	EASA,FAA,ANAC										
13451	J626P10	EASA,FAA,ANAC										
13451	J626P11	EASA,FAA,ANAC										
13459	301-417-104-0	EASA,FAA,CAAC,ANAC	19	28	72-23-12	FAN FRAME STRUTS INTERNAL TUBING	Package A	CLN/INSP	CLEANING AND INSPECTION		570.00	SR Technics Switzerland
13459	301-464-713-0	EASA,FAA,CAAC,ANAC			72-23-12		Package B	INSP-001	REPLACEMENT OF SWAGED THIN WALL SELF-LOCKING INSERTS		540.00	SR Technics Switzerland
13459	336-009-504-0	EASA,FAA,CAAC,ANAC										
13459	336-009-505-0	EASA,FAA,CAAC,ANAC										
13459	336-028-701-0	EASA,FAA,CAAC,ANAC										
13459	337-113-201-0	EASA,FAA,CAAC,ANAC										
13459	337-114-602-0	EASA,FAA,CAAC,ANAC										
13459	337-115-002-0	EASA,FAA,CAAC,ANAC										
13459	337-115-052-0	EASA,FAA,CAAC,ANAC										
13459	340-029-901-0	EASA,FAA,CAAC,ANAC										
13459	340-030-202-0	EASA,FAA,CAAC,ANAC										
13459	340-030-702-0	EASA,FAA,CAAC,ANAC										
13459	340-031-101-0	EASA,FAA,CAAC,ANAC										
13459	340-031-401-0	EASA,FAA,CAAC,ANAC										
13459	340-031-901-0	EASA,FAA,CAAC,ANAC										
13471	337-100-804-0	EASA,FAA,CAAC,ANAC	18	28	72-23-15	FAN FRAME ASSEMBLY - ACCESSORY DRIVE REAR CLEVIS MOUNT ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		515.00	SR Technics Switzerland
13471	338-075-402-0	EASA,FAA,CAAC,ANAC			72-23-15		Package C	003	REPLACEMENT OF BUSHING		1105.00	SR Technics Switzerland
13471	340-077-601-0	EASA,FAA,CAAC,ANAC										
13473	336-053-701-0	EASA,FAA,CAAC,ANAC	24	28	72-23-16	FAN FRAME ASSEMBLY - VARIABLE BLEED VALVE FEEDBACK ROD AND CLEVIS	Package A	CLN/INSP	CLEANING AND INSPECTION		245.00	SR Technics Switzerland
13473	336-057-802-0	EASA,FAA,CAAC,ANAC			72-23-16		Package B	INSP-001	SPOT TOUCH-UP VSV PART		430.00	SR Technics Switzerland
13473	340-056-804-0	EASA,FAA,CAAC,ANAC			72-23-16		Package B	INSP-001	REMOVE OXIDATION VBV PART		430.00	SR Technics Switzerland
13473	340-074-402-0	EASA,FAA,CAAC,ANAC			72-23-16		Package B	INSP-001	BLENDING/TOUCH-UP PARTS		430.00	SR Technics Switzerland
13473	340-074-505-0	EASA,FAA,CAAC,ANAC			72-23-16		Package B	INSP-001	BLENDING DAMAGED PARTS		430.00	SR Technics Switzerland
13473	340-079-204-0	EASA,FAA,CAAC,ANAC			72-23-16		Package C	001	VBV DOOR REPAIR		315.00	SR Technics Switzerland
13473	340-079-303-0	EASA,FAA,CAAC,ANAC			72-23-16		Package D	003	REPLACEMENT OF THE BUSHING ON THE VBV DOOR		615.00	SR Technics Switzerland
13473	340-079-403-0	EASA,FAA,CAAC,ANAC			72-23-16		Package E	004	REPLACEMENT OF THE SLEEVES ON THE VBV ACTUATING RING		3080.00	SR Technics Switzerland
13473	340-085-202-0	EASA,FAA,CAAC,ANAC			72-23-16		Package F	005	REMOVAL OF CORROSION ON VBV SYSTEM		655.00	SR Technics Switzerland
13473	340-085-302-0	EASA,FAA,CAAC,ANAC			72-23-16		Package G	006	REPLACEMENT OF SPHERICAL BEARING ON VBV TURNBUCKLES		330.00	SR Technics Switzerland
13473	340-085-401-0	EASA,FAA,CAAC,ANAC			72-23-16		Package H	007	REPLACEMENT OF THE SPHERICAL BEARINGS ON THE VBV BELLCRANKS		510.00	SR Technics Switzerland
13473	340-085-402-0	EASA,FAA,CAAC,ANAC			72-23-16		Package K	002	REPLACEMENT OF SPD SEAL		330.00	SR Technics Switzerland
13473	340-168-301-0	EASA,FAA,CAAC,ANAC										
13473	340-168-601-0	EASA,FAA,CAAC,ANAC										
13473	340-168-701-0	EASA,FAA,CAAC,ANAC										
13903	336-042-501-0	EASA,FAA,CAAC,ANAC	17	28	72-54-10	LOW PRESSURE TURBINE - THERMAL INSULATION BLANKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		115.00	SR Technics Switzerland
13903	336-042-540-0	EASA,FAA,CAAC,ANAC			72-54-10		Package B	001	PATCH REPAIR OF INSULATION BLANKETS		215.00	SR Technics Switzerland
13903	336-042-560-0	EASA,FAA,CAAC,ANAC										
13903	336-042-640-0	EASA,FAA,CAAC,ANAC										
13903	336-042-680-0	EASA,FAA,CAAC,ANAC										
13903	336-042-701-0	EASA,FAA,CAAC,ANAC										
13903	336-042-740-0	EASA,FAA,CAAC,ANAC										
13903	338-072-002-0	EASA,FAA,CAAC,ANAC										
13903	338-072-021-0	EASA,FAA,CAAC,ANAC										
13903	338-072-042-0	EASA,FAA,CAAC,ANAC										
13903	338-072-061-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
13903	338-072-081-0	EASA,FAA,CAAC,ANAC										
13903	338-086-702-0	EASA,FAA,CAAC,ANAC										
13903	338-086-752-0	EASA,FAA,CAAC,ANAC										
14164	340-064-501-0	EASA,FAA,CAAC,ANAC	29	28	72-23-33	FAN FRAME ASSEMBLY - FAIRINGS,SUPPORT,PLATES ETC	Package A	CLN/INSP	CLEANING AND INSPECTION		455.00	SR Technics Switzerland
14164	340-065-003-0	EASA,FAA,CAAC,ANAC			72-23-33		Package B	INSP-001	ATTACH. CLAMP BLEND DAMAGED AREA		745.00	SR Technics Switzerland
14164	340-065-004-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-33		Package B	INSP-001	APPLY ALODINE BLEND/BLANK AREA		745.00	SR Technics Switzerland
14164	340-065-604-0	EASA,FAA,CAAC,ANAC			72-23-33		Package B	INSP-001	ATTACH. CLAMP REPLACEMENT RIVET/PART		745.00	SR Technics Switzerland
14164	340-065-605-0	EASA,FAA,ANAC,CAA UK			72-23-33		Package B	INSP-001	MATING PADS BLEND DAMAGED AREA		745.00	SR Technics Switzerland
14164	340-065-803-0	EASA,FAA,CAAC,ANAC			72-23-33		Package B	INSP-001	FAIRING PLATE REPLACEMENT RIVET/PART		745.00	SR Technics Switzerland
14164	340-066-302-0	EASA,FAA,CAAC,ANAC			72-23-33		Package B	INSP-001	FAIRING SUPP. REPLACEMENT RIVET/PART		745.00	SR Technics Switzerland
14164	340-066-906-0	EASA,FAA,CAAC,ANAC			72-23-33		Package B	INSP-001	FAIRING BLEND DAMAGED AREA		745.00	SR Technics Switzerland
14164	340-066-907-0	EASA,FAA,CAAC,ANAC			72-23-33		Package C	001	REPLACEMENT OF THE BONDED SEALS ON STRUT NO. 4 FAIRING		790.00	SR Technics Switzerland
14164	340-066-908-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-33		Package D	003	REPLACEMENT OF SWAGED SELF-LOCKING INSERT ON STRUTS NO.4 AND 10 FAIRING		255.00	SR Technics Switzerland
14164	340-066-909-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-33		Package F	005	REPAIR OF ATTACHEMENT HOLES ON THE FAIRING STRUTS 4 AND 10 BY BUSHING INSTALLATION		1945.00	SR Technics Switzerland
14164	340-067-404-0	EASA,FAA,CAAC,ANAC			72-23-33		Package G	004	FULL REPAIR OR SPOT TOUCH-UP OF THE SULFURIC ANODIZATION ON THE FAIRING STRUTS 4 AND 10		1145.00	SR Technics Switzerland
14164	340-067-405-0	EASA,FAA,CAAC,ANAC			72-23-33		Package G	006	REPAIR OF THE N°10 STRUT FAIRING WELD JOINT		1145.00	SR Technics Switzerland
14164	340-067-406-0	EASA,FAA,CAAC,ANAC,CAA UK										
14164	340-067-702-0	EASA,FAA,CAAC,ANAC										
14164	340-068-101-0	EASA,FAA,CAAC,ANAC										
14164	340-068-302-0	EASA,FAA,CAAC,ANAC										
14164	340-068-402-0	EASA,FAA,CAAC,ANAC										
14164	340-068-503-0	EASA,FAA,CAAC,ANAC										
14164	340-068-603-0	EASA,FAA,CAAC,ANAC										
14164	340-068-702-0	EASA,FAA,CAAC,ANAC,CAA UK										
14164	340-068-802-0	EASA,FAA,CAAC,ANAC,CAA UK										
14164	649-411-951-0	EASA,FAA,CAAC,ANAC										
15015	340-064-701-0	EASA,FAA,CAAC,ANAC	34	21	72-23-21	FAN FRAME ASSEMBLY - HARNESS SUPPORT FRIS PLATE	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
15015	340-066-604-0	EASA,FAA,CAAC,ANAC			72-23-21		Package B	SPM	REPLACEMENT OF SWAGED THIN WALL SELF-LOCKING INSERTS		275.00	SR Technics Switzerland
15015	340-066-704-0	EASA,FAA,CAAC,ANAC										
15015	340-066-802-0	EASA,FAA,ANAC										
15379	336-043-302-0	EASA,FAA,CAAC,ANAC	4	28	72-56-01	CFM56-5B/7B INSULTION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		360.00	SR Technics Switzerland
15379	338-107-002-0	EASA,FAA,CAAC,ANAC			72-56-01		Package AD	029	REPLACEMENT OF INSULATION ASSEMBLY		225.00	SR Technics Switzerland
15379	338-107-003-0	EASA,FAA,CAAC,ANAC										
15379	338-107-102-0	EASA,FAA,CAAC,ANAC										
15379	338-107-103-0	EASA,FAA,CAAC,ANAC										
15379	338-107-202-0	EASA,FAA,CAAC,ANAC										
15379	338-107-203-0	EASA,FAA,CAAC,ANAC										
15379	340-101-604-0	EASA,FAA,CAAC,ANAC										
15379	340-101-704-0	EASA,FAA,CAAC,ANAC										
15379	340-156-503-0	EASA,FAA,CAAC,ANAC										
15379	340-156-603-0	EASA,FAA,CAAC,ANAC										
15379	340-156-703-0	EASA,FAA,CAAC,ANAC										
17535	340-032-901-0	EASA,FAA,CAAC,ANAC	19	28	72-23-22	FAN FRAME ASSEMBLY - THRUST MOUNTS	Package A	CLN/INSP	CLEANING AND INSPECTION		815.00	SR Technics Switzerland
17535	340-060-001-0	EASA,FAA,CAAC,ANAC			72-23-22		Package B	001	SPHERICAL BEARING REPLACEMENT		4500.00	SR Technics Switzerland
17535	340-182-701-0	EASA,FAA,CAAC,ANAC										
17535	340-182-801-0	EASA,FAA,CAAC,ANAC										
18941	340-402-101-0	EASA,FAA,CAAC,JCAB,ANAC,CAA UK	13	21	73-11-15	FUEL PUMP	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	1890.00	SR Technics Switzerland
18941	340-402-102-0	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE LIGHT, M	290.00	SR Technics Switzerland
18941	340-402-103-0	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS		2015.00	SR Technics Switzerland
18941	340-402-104-0	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS		3520.00	SR Technics Switzerland
18941	340-402-105-0	EASA,FAA,CAAC,JCAB,ANAC,TCCA,CAA MALAYSIA,DGCA CIVIL AVIATIC	73-11-15				Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS		5025.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
18941	340-402-106-0	EASA,FAA,CAAC,JCAB,ANAC,TCOA,CAA MALAYSIA,DGCA CIVIL AVIATIC	73-11-15				Package G		OVERHAUL		8705.00	SR Technics Switzerland
18941	340-402-107-0	EASA,FAA,CAAC,JCAB,ANAC,TCOA,CAA MALAYSIA,DGCA CIVIL AVIATIC	73-11-15				Package SB00	828300-73-101	INTRODUCTION OF NEW FUEL PUMP WITH NEW FILTER COVER ATTACHMENT		2160.00	SR Technics Switzerland
18941	340-402-108-0	EASA,FAA,CAAC,JCAB,ANAC,TCOA,CAA MALAYSIA,DGCA CIVIL AVIATIC	73-11-15				Package SB01	828300-73-102	INTRODUCTION OF A NEW IMPELLER DRIVE SHAFT AND IMPELLER DRIVE SHAFT PREFORMED PACKING		5630.00	SR Technics Switzerland
18941	340-402-109-0	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB02	828300-73-103	INTRODUCTION OF A NEW FUEL FILTER		2090.00	SR Technics Switzerland
18941	340-402-110-0	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB03	828300-73-104	INSPECTION OF PUMP COVER		5100.00	SR Technics Switzerland
18941	340-402-111-0	EASA,FAA,CAAC,JCAB,ANAC,TCOA,CAA MALAYSIA,DGCA CIVIL AVIATIC	73-11-15				Package SB04	828300-73-107	SHAFT SEAL IMPROVEMENT		5100.00	SR Technics Switzerland
18941	828300-1	EASA,FAA,CAAC,JCAB,ANAC,CAA UK	73-11-15				Package SB05	828300-73-105	INTRODUCTION OF NEW FUEL PUMP WITH NEW PUMP COVER		5100.00	SR Technics Switzerland
18941	828300-10	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB06	AD 2006-26-01	REPLACING THE FUEL FILTERS ON ENGINE		150.00	SR Technics Switzerland
18941	828300-11	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB08	828300-73-108	INTRODUCTION OF A NEW FUEL PUMP WITH A NEW SHAFT SEAL		150.00	SR Technics Switzerland
18941	828300-2	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB09	828300-73-110	MFP - NEW RETAINING RING		5100.00	SR Technics Switzerland
18941	828300-3	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB10	828300-73-109	MFP - FILTER BYPASS VALVE RETAINING RING		5100.00	SR Technics Switzerland
18941	828300-4	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB11	828300-73-111	MFP - INTRODUCTION OF NEW SHAFT SEAL		5100.00	SR Technics Switzerland
18941	828300-5	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB12	73-0234	INTRODUCTION OF A HIGH TIME SCHEDULED OVERHAUL ON THE MAIN FUEL PUMP		4715.00	SR Technics Switzerland
18941	828300-6	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF	73-11-15				Package SB13	73-0235	INTRODUCTION OF A SCHEDULED OVERHAUL ON THE MAIN FUEL PUMP		4715.00	SR Technics Switzerland
18941	828300-7	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF INDONESIA										
18941	828300-8	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF INDONESIA,CAA UK										
18941	828300-9	EASA,FAA,CAAC,JCAB,ANAC,CAA MALAYSIA,DGCA CIVIL AVIATION OF INDONESIA,CAA UK										
19228	056-000-221-0	EASA,FAA,CAAC,ANAC	27	21	72-56-01	LOW PRESSURE TURBINE REAR FRAME - BEARING NO.5 OIL SCAVENGE/SUPPLY	Package A	CLN/INSP	CLEANING AND INSPECTION		610.00	SR Technics Switzerland
19228	056-000-302-6	EASA,FAA,CAAC,ANAC			72-56-01		Package AK	036	REPAIR OF CRACKS TACK WELDING OF THE OIL SUPPLY TUBE BY WELD BUILD UP		935.00	SR Technics Switzerland
19228	334-007-367-0	EASA,FAA,CAAC,ANAC			72-56-01		Package S	018	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY		1120.00	SR Technics Switzerland
19228	336-052-111-0	EASA,FAA,CAAC,ANAC			72-56-01		Package SB00	72-0527	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE		325.00	SR Technics Switzerland
19228	338-103-405-0	EASA,FAA,CAAC,ANAC										
19228	340-166-101-0	EASA,FAA,CAAC,ANAC										
21823	338-063-602-0	EASA,FAA,CAAC,ANAC	31	28	72-54-04	LOW PRESSURE TURBINE - SHROUD SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		660.00	SR Technics Switzerland
21823	338-122-202-0	EASA,FAA,CAAC,ANAC										
23002	301-581-006-0	EASA,FAA,CAAC,ANAC	19	28	72-54-20	LOW PRESSURE TURBINE - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		300.00	SR Technics Switzerland
23002	301-581-007-0	EASA,FAA,CAAC,ANAC										
23002	305-074-104-0	EASA,FAA,CAAC,ANAC										
23002	336-026-002-0	EASA,FAA,CAAC,ANAC										
23002	336-026-052-0	EASA,FAA,CAAC,ANAC										
23002	336-031-201-0	EASA,FAA,CAAC,ANAC										
23002	336-031-301-0	EASA,FAA,CAAC,ANAC										
23002	336-031-401-0	EASA,FAA,CAAC,ANAC										
23002	336-031-501-0	EASA,FAA,CAAC,ANAC										
23002	336-044-102-0	EASA,FAA,CAAC,ANAC										
23002	336-044-202-0	EASA,FAA,CAAC,ANAC										
23002	336-049-301-0	EASA,FAA,CAAC,ANAC										
23002	336-049-603-0	EASA,FAA,CAAC,ANAC										
23002	336-053-602-0	EASA,FAA,CAAC,ANAC										
23002	336-055-106-0	EASA,FAA,CAAC,ANAC										
23002	336-063-001-0	EASA,FAA,CAAC,ANAC										
23002	338-063-501-0	EASA,FAA,CAAC,ANAC										
23002	338-065-501-0	EASA,FAA,CAAC,ANAC										
23002	338-069-901-0	EASA,FAA,CAAC,ANAC										
23002	338-069-951-0	EASA,FAA,CAAC,ANAC										
23002	338-086-101-0	EASA,FAA,CAAC,ANAC										
23002	338-111-801-0	EASA,FAA,CAAC,ANAC										
23002	338-111-901-0	EASA,FAA,CAAC,ANAC										
23002	338-116-402-0	EASA,FAA,CAAC,ANAC										
23002	338-116-502-0	EASA,FAA,CAAC,ANAC										
23002	338-116-503-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
23002	338-116-602-0	EASA,FAA,CAAC,ANAC										
23002	338-116-603-0	EASA,FAA,CAAC,ANAC										
23002	338-116-702-0	EASA,FAA,CAAC,ANAC										
23002	338-121-701-0	EASA,FAA,CAAC,ANAC										
23002	338-121-702-0	EASA,FAA,CAAC,ANAC										
23002	338-180-201-0	EASA,FAA,CAAC,ANAC										
23002	340-306-301-0	EASA,FAA,CAAC,ANAC										
23002	649-051-001-0	EASA,FAA,CAAC,ANAC										
45002	340-252-305-0	EASA,FAA,CAAC,ANAC	20	28	72-21-22	FAN AND BOOSTER - FAN BLADE SHIM	Package A	CLN/INSP	CLEANING AND INSPECTION		115.00	SR Technics Switzerland
45002	340-252-306-0	EASA,FAA,CAAC,ANAC			72-21-22		Package B	001	REPLACEMENT OF THE LUBRICANT COATING		175.00	SR Technics Switzerland
45002	340-252-307-0	EASA,FAA,CAAC,ANAC										
62444	301-298-111-0	EASA,FAA,CAAC,ANAC	18	28	72-22-15	NO.1 AND NO.2 BEARING SUPPORT - PHONIC WHEEL	Package A	CLN/INSP	CLEANING AND INSPECTION		350.00	SR Technics Switzerland
62444	301-298-113-0	EASA,FAA,CAAC,ANAC										
62444	340-034-701-0	EASA,FAA,CAAC,ANAC										
65986	1318M20G03	EASA,FAA,CAAC,ANAC	24	28	72-32-11	COMPRESSOR FRONT STATOR - VARIABLE VANE ACTUATION RINGS	Package A	CLN/INSP	CLEANING AND INSPECTION		470.00	SR Technics Switzerland
65986	1318M20G04	EASA,FAA,CAAC,ANAC			72-32-11		Package A	INSP-001	ISPECTION FOR SUSPECTED CRACKS		470.00	SR Technics Switzerland
65986	1318M21G03	EASA,FAA,CAAC,ANAC			72-32-11		Package A	INSP-001	REPLACE FLANGED BUSHINGS		470.00	SR Technics Switzerland
65986	1318M22G03	EASA,FAA,CAAC,ANAC			72-32-11		Package A	INSP-001	SECURE LOOSE STRAIGHT PIN		470.00	SR Technics Switzerland
65986	1318M23G03	EASA,FAA,CAAC,ANAC										
65986	1318M50G03	EASA,FAA,CAAC,ANAC										
65986	1318M51G01	EASA,FAA,CAAC,ANAC										
65986	1318M51G03	EASA,FAA,CAAC,ANAC										
65986	1318M52G01	EASA,FAA,CAAC,ANAC										
65986	1318M52G03	EASA,FAA,CAAC,ANAC										
65986	1318M53G03	EASA,FAA,CAAC,ANAC										
65986	9524M85P02	EASA,FAA,CAAC,ANAC										
72544	305-165-501-0	EASA,FAA,CAAC,ANAC	12	28	72-63-05	ACCESSORY GEARBOX - LUBRICATION UNIT DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		175.00	SR Technics Switzerland
72544	335-312-603-0	EASA,FAA,CAAC,ANAC										
125455	P201P05M1	EASA,FAA,CAAC,ANAC	17	28	72-32-02	COMPRESSOR FRONT STATOR - VARIABLE VANES	Package SB01	72-0581	STG 2 AND STG 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS		155.00	SR Technics Switzerland
125455	P201P06	EASA,FAA,CAAC,ANAC			72-32-02		Package SB02	72-0665	INTRODUCTION OF NEW METALIC-COMPOSITE VSV BUSHING		155.00	SR Technics Switzerland
125455	P201P06M1	EASA,FAA,CAAC,ANAC										
125455	P201P15	EASA,FAA,CAAC,ANAC										
125455	P201P16	EASA,FAA,CAAC,ANAC										
125455	P202P01	EASA,FAA,CAAC,ANAC										
125455	P202P01M1	EASA,FAA,CAAC,ANAC										
125455	P202P02	EASA,FAA,CAAC,ANAC										
125455	P202P09	EASA,FAA,CAAC,ANAC										
125455	P202P10	EASA,FAA,CAAC,ANAC										
125455	P210P02	EASA,FAA,CAAC,ANAC										
125455	P210P02M1	EASA,FAA,CAAC,ANAC										
125455	P210P04	EASA,FAA,CAAC,ANAC										
125455	P223P01	EASA,FAA,CAAC,ANAC										
125455	P223P02	EASA,FAA,CAAC,ANAC										
125455	P223P07	EASA,FAA,CAAC,ANAC										
125455	P223P08	EASA,FAA,CAAC,ANAC										
125455	P241P01	EASA,FAA,CAAC,ANAC										
125455	P241P02	EASA,FAA,CAAC,ANAC										
125455	P242P01	EASA,FAA,CAAC,ANAC										
125455	P242P02	EASA,FAA,CAAC,ANAC										
125455	P242P04	EASA,FAA,CAAC,ANAC										
125455	P243P01	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
125455	P243P02	EASA,FAA,CAAC,ANAC										
125455	P251P09	EASA,FAA,CAAC,ANAC										
125455	P262G01	EASA,FAA,CAAC,ANAC										
125455	P262G02	EASA,FAA,CAAC,ANAC										
125455	P263G01	EASA,FAA,CAAC,ANAC										
125455	P263G02	EASA,FAA,CAAC,ANAC										
135150	1348M21P01	EASA,FAA,CAAC,ANAC	9	21	77-23-10	T3 SENSOR, COMPRESSOR OUTLET TEMPERATURE	Package C	TEST	INSPECTION AND TEST		955.00	SR Technics Switzerland
135150	1348M21P04	EASA,FAA,CAAC,ANAC										
135150	1348M21P05	EASA,FAA,CAAC,ANAC										
135150	1853M47P02	EASA,FAA,CAAC,ANAC										
135150	8TC19AAJ1	EASA,FAA,CAAC,ANAC										
135150	8TC19AAK1	EASA,FAA,CAAC,ANAC										
135150	8TC19AAP1	EASA,FAA,CAAC,ANAC										
135150	8TC19AAR1	EASA,FAA,CAAC,ANAC										
138941	335-190-201-0	EASA,FAA,CAAC,ANAC	32	28	72-21-07	FAN AND BOOSTER - BOOSTER BLADES LOCK ASSEMBLY, STAGE 2-5	Package A	CLN/INSP	CLEANING AND INSPECTION		255.00	SR Technics Switzerland
138941	335-190-202-0	EASA,FAA,CAAC,ANAC			72-21-07		Package B	001	REPLACEMENT OF THE SELF-LOCKING THREADED INSERTS		155.00	SR Technics Switzerland
138941	335-190-301-0	EASA,FAA,CAAC,ANAC										
138941	335-190-302-0	EASA,FAA,CAAC,ANAC										
138941	335-190-401-0	EASA,FAA,CAAC,ANAC										
138941	335-190-402-0	EASA,FAA,CAAC,ANAC										
138941	338-006-201-0	EASA,FAA,CAAC,ANAC										
138941	338-006-202-0	EASA,FAA,CAAC,ANAC										
138941	338-006-301-0	EASA,FAA,CAAC,ANAC										
138941	338-006-302-0	EASA,FAA,CAAC,ANAC										
138941	338-006-401-0	EASA,FAA,CAAC,ANAC										
138941	338-006-402-0	EASA,FAA,CAAC,ANAC										
138941	338-006-501-0	EASA,FAA,CAAC,ANAC										
138941	338-006-502-0	EASA,FAA,CAAC,ANAC										
138945	1523M39P06	EASA,FAA,CAAC,ANAC	21	28	72-31-20	COMPRESSOR ROTOR - SELF-WRENCHING HOOK BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION	TECHNICAL INSTRUCTION (TI)	40.00	SR Technics Switzerland
138945	1523M39P07	EASA,FAA,CAAC,ANAC										
138945	2116M22P01	EASA,FAA,CAAC,ANAC										
138945	9115M80P06	EASA,FAA,CAAC,ANAC										
138945	9977M25P01	EASA,FAA,CAAC,ANAC										
138947	1385M33G02	EASA,FAA,CAAC,ANAC	4	28	72-32-10	CFM56 ARM ASSY-VANE ACTUATION	Package A	CLN/INSP	CLEANING & INSPECTION		50.00	SR Technics Switzerland
138947	1385M33G03	EASA,FAA,CAAC,ANAC										
138947	1385M34G01	EASA,FAA,CAAC,ANAC										
138947	1385M34G02	EASA,FAA,CAAC,ANAC										
138947	1834M58G01	EASA,FAA,CAAC,ANAC										
138947	1834M58G02	EASA,FAA,CAAC,ANAC										
138947	1834M59G01	EASA,FAA,CAAC,ANAC										
138947	1834M59G02	EASA,FAA,CAAC,ANAC										
138947	9511M79G01	EASA,FAA,CAAC,ANAC										
138947	9511M79G02	EASA,FAA,CAAC,ANAC										
138947	9523M35G01	EASA,FAA,CAAC,ANAC										
138947	9523M35G03	EASA,FAA,CAAC,ANAC										
138947	9938M48G05	EASA,FAA,CAAC,ANAC										
138947	9938M48G06	EASA,FAA,CAAC,ANAC										
138953	1316M84G01	EASA,FAA,CAAC,ANAC	26	28	72-42-06	COMBUSTION CHAMBER - SELFLOCKING GANG CHANNEL NUT ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		100.00	SR Technics Switzerland
138953	9945M19G03	EASA,FAA,CAAC,ANAC			72-42-06		Package B	001	REPLACEMENT OF SELFLOCKING GANG CHANNEL NUT ASSY NUTS		565.00	SR Technics Switzerland
138953	9945M19G04	EASA,FAA,CAAC,ANAC										
138962	305-158-701-0	EASA,FAA,CAAC,ANAC	16	28	72-62-05	TRANSFER GEARBOX - VESPEL NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		390.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2024



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138962	305-158-801-0	EASA,FAA,CAAC,ANAC										
138962	335-322-201-0	EASA,FAA,CAAC,ANAC										
138962	335-322-501-0	EASA,FAA,CAAC,ANAC										
138962	SL40703M45-15FG	EASA,FAA,CAAC,ANAC										
138980	301-297-909-0	EASA,FAA,CAAC,ANAC	22	28	72-22-16	NO.1 AND NO.2 BEARING SUPPORT - KEYWASHERS	Package A	CLN/INSP	CLEANING AND INSPECTION		420.00	SR Technics Switzerland
138980	301-298-408-0	EASA,FAA,CAAC,ANAC			72-22-16		Package B	INSP-001	BLEND RING KEYWASHER		155.00	SR Technics Switzerland
138980	301-537-803-0	EASA,FAA,CAAC,ANAC			72-22-16		Package D	INSP-001	REPLACE ANTI ROTAIN PIN		550.00	SR Technics Switzerland
138980	301-544-203-0	EASA,FAA,CAAC,ANAC										
138980	305-398-901-0	EASA,FAA,CAAC,ANAC										
139002	SL4081CA10	EASA,FAA,CAAC,JCAB,ANAC	3	21	71-21-37	CFM56-7B ENGINE MOUNT NUT-BARREL	Package A	CLN/INSP	CLEANING & INSPECTION		80.00	SR Technics Switzerland
139002	SL4081CA14SP1	EASA,FAA,CAAC,JCAB,ANAC										
139002	SL4147CA10A	EASA,FAA,CAAC,JCAB,ANAC										
139002	SL4147CA14EBSP1	EASA,FAA,CAAC,ANAC										
139002	SLR4124C10	EASA,FAA,CAAC,ANAC										
139002	SLR4124C14EB	EASA,FAA,CAAC,ANAC										
139012	301-298-802-6	EASA,FAA,CAAC,ANAC	17	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE - SHIM	Package B		GRINDING SPACER THICKNESS		170.00	SR Technics Switzerland
139012	301-298-803-0	EASA,FAA,CAAC,ANAC										
139012	301-298-804-0	EASA,FAA,CAAC,ANAC										
139012	301-298-805-0	EASA,FAA,CAAC,ANAC										
139012	301-298-806-0	EASA,FAA,CAAC,ANAC										
139012	301-298-807-0	EASA,FAA,CAAC,ANAC										
139012	301-298-808-0	EASA,FAA,CAAC,ANAC										
139012	301-298-809-0	EASA,FAA,ANAC										
139012	301-298-810-0	EASA,FAA,CAAC,ANAC										
139012	301-298-811-0	EASA,FAA,CAAC,ANAC										
139012	301-298-812-0	EASA,FAA,CAAC,ANAC										
139012	301-298-813-0	EASA,FAA,CAAC,ANAC										
139012	301-298-814-0	EASA,FAA,CAAC,ANAC										
139012	301-298-815-0	EASA,FAA,CAAC,ANAC										
139012	301-298-816-0	EASA,FAA,CAAC,ANAC										
139012	301-298-817-0	EASA,FAA,CAAC,ANAC										
139012	301-298-818-0	EASA,FAA,CAAC,ANAC										
139012	301-298-819-0	EASA,FAA,CAAC,ANAC										
139015	305-115-704-0	EASA,FAA,CAAC,ANAC	24	28	72-63-21	ACCESSORY GEARBOX - SEALOL SEALS	Package A	CLN/INSP	CLEANING AND INSPECTION		120.00	SR Technics Switzerland
139015	305-115-709-0	EASA,FAA,CAAC,ANAC			72-63-21		Package B	001	ATA 72-63-08	LAPPING OF SURFACES OF MATING RING AT	410.00	SR Technics Switzerland
139015	305-140-801-0	EASA,FAA,CAAC,ANAC			72-63-21		Package C	002	ATA 72-63-08	REPLACEMENT OF SEALOL SEAL HOUSING E	190.00	SR Technics Switzerland
139015	335-310-706-0	EASA,FAA,CAAC,ANAC			72-63-21		Package SB00	72-0652	INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-RIN REWORK OF OLD SEALOL SEAL TO THE NEW		350.00	SR Technics Switzerland
139015	335-310-707-0	EASA,FAA,CAAC,ANAC										
139015	335-310-708-0	EASA,FAA,CAAC,ANAC										
139015	335-320-304-0	EASA,FAA,CAAC,ANAC										
139015	335-320-305-0	EASA,FAA,CAAC,ANAC										
139015	340-155-304-0	EASA,FAA,CAAC,ANAC										
139015	340-155-305-0	EASA,FAA,CAAC,ANAC										
139015	340-190-001-0	EASA,FAA,CAAC,ANAC										
139015	340-194-201-0	EASA,FAA,CAAC,ANAC										
139020	305-415-401-0	EASA,FAA,CAAC,ANAC	18	28	72-63-18	ACCESSORY GEARBOX - PIN-STRAIGHT	Package A	CLN/INSP	CLEANING AND INSPECTION		345.00	SR Technics Switzerland
139020	340-077-702-0	EASA,FAA,CAAC,ANAC										
139020	340-077-903-0	EASA,FAA,CAAC,ANAC										
139020	340-078-002-0	EASA,FAA,CAAC,ANAC										
139020	340-085-902-0	EASA,FAA,CAAC,ANAC										
139021	301-495-102-0	EASA,FAA,CAAC,ANAC	19	28	72-63-14	ACCESSORY GEARBOX - QAD RING ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		470.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139021	305-126-601-0	EASA,FAA,CAAC,ANAC			72-63-14		Package B	001	RECONDITIONING OF LUBRICANT VARNISH ON SPHERICAL SEATING SURFACES		695.00	SR Technics Switzerland
139021	335-311-700-0	EASA,FAA,CAAC,ANAC			72-63-14		Package C	002	RECONDITIONING OF THE SOLID-FILM LUBRICANT COATING		875.00	SR Technics Switzerland
139021	335-311-701-0	EASA,FAA,CAAC,ANAC										
139021	9009M29P01	EASA,FAA,CAAC,ANAC										
139023	301-367-605-0	EASA,FAA,CAAC,ANAC	17	28	72-55-11	LOW PRESSURE TURBINE SHAFT - ASSEMBLY BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION		150.00	SR Technics Switzerland
139023	J952P22A	EASA,FAA,CAAC,ANAC										
139024	338-072-601-0	EASA,FAA,CAAC,ANAC	36	21	72-54-14	LOW PRESSURE TURBINE - SUPPORT BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION		115.00	SR Technics Switzerland
139024	338-072-801-0	EASA,FAA,CAAC,ANAC			72-54-14		Package E	003	REPAIR OF CRACKS		145.00	SR Technics Switzerland
139024	338-119-202-0	EASA,FAA,CAAC,ANAC			72-54-14		Package SB00	75-0043	REWORK OF THE AIR MANIFOLD AND THE BRACKET OF THE COOLING MANIFOLD IN FIELD		120.00	SR Technics Switzerland
139024	338-119-204-0	EASA,FAA,CAAC,ANAC										
139024	340-029-703-0	EASA,FAA,CAAC,ANAC										
139024	340-029-706-0	EASA,FAA,CAAC,ANAC										
139024	340-029-707-0	EASA,FAA,CAAC,ANAC										
139024	340-029-708-0	EASA,FAA,CAAC,ANAC										
139024	340-084-102-0	EASA,FAA,CAAC,ANAC										
139024	340-084-104-0	EASA,FAA,CAAC,ANAC										
139024	340-084-152-0	EASA,FAA,CAAC,ANAC										
139030	338-011-201-0	EASA,FAA,CAAC,ANAC	24	28	72-23-17	FAN FRAME ASSEMBLY - OIL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		200.00	SR Technics Switzerland
139030	338-011-402-0	EASA,FAA,CAAC,ANAC			72-23-17		Package N	052	REPLACEMENT OF WORN SPHERICAL BEARING ON OIL TANK LINK ROD	EASA / FAA APPROVED SRT DESIGN	1380.00	SR Technics Switzerland
139030	338-014-801-0	EASA,FAA,CAAC,ANAC										
139030	338-015-101-0	EASA,FAA,CAAC,ANAC,CAA UK										
139030	338-045-001-0	EASA,FAA,CAAC,ANAC										
139030	338-079-901-0	EASA,FAA,CAAC,ANAC										
139030	338-079-951-0	EASA,FAA,CAAC,ANAC										
139030	340-086-003-0	EASA,FAA,CAAC,ANAC										
139030	340-086-004-0	EASA,FAA,CAAC,ANAC										
139030	340-086-201-0	EASA,FAA,CAAC,ANAC										
139030	340-086-202-0	EASA,FAA,CAAC,ANAC										
139030	340-086-302-0	EASA,FAA,CAAC,ANAC										
139030	340-086-303-0	EASA,FAA,CAAC,ANAC										
139030	340-168-401-0	EASA,FAA,CAAC,ANAC										
139035	338-068-007-0	EASA,FAA,CAAC,ANAC	53	28	72-23-08	FAN FRAME ASSEMBLY - FAN CASE ACOUSTICAL PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION		265.00	SR Technics Switzerland
139035	338-068-008-0	EASA,FAA,CAAC,ANAC			72-23-08		Package C	002	REPAIR OF THE PROTECTIVE COATING ON THE FAN CASE ACOUSTICAL PANELS		1190.00	SR Technics Switzerland
139035	338-068-010-0	EASA,FAA,CAAC,ANAC			72-23-08		Package C	003	REPLACE THE COMPONENTS AT THE ATTACHMENT POINTS OF THE ACOUSTICAL PANELS		1190.00	SR Technics Switzerland
139035	338-068-108-0	EASA,FAA,CAAC,ANAC			72-23-08		Package C	003	REPLACEMENT OF THE COMPONENTS AT THE ATTACHMENT POINTS		1190.00	SR Technics Switzerland
139035	338-068-109-0	EASA,FAA,CAAC,ANAC			72-23-08		Package C	006	EROSION REPAIR BY EPOXY RESIN		1190.00	SR Technics Switzerland
139035	338-068-111-0	EASA,FAA,CAAC,ANAC			72-23-08		Package C	010	REPAIR OF THE FORWARD MIDDLE AND AFT ACCUSTICAL PANELS BY RESING INJECTION		1190.00	SR Technics Switzerland
139035	338-068-208-0	EASA,FAA,CAAC,ANAC			72-23-08		Package L	011	RECONDITIONING OF FWD, MID, AFT ACC. PANELS BY WET LAY-UP PROCESS		2800.00	SR Technics Switzerland
139035	338-068-209-0	EASA,FAA,CAAC,ANAC										
139035	338-068-211-0	EASA,FAA,CAAC,ANAC										
139035	338-068-307-0	EASA,FAA,CAAC,ANAC										
139035	338-068-308-0	EASA,FAA,CAAC,ANAC										
139035	338-068-310-0	EASA,FAA,CAAC,ANAC										
139035	338-068-408-0	EASA,FAA,CAAC,ANAC										
139035	338-068-409-0	EASA,FAA,CAAC,ANAC										
139035	338-068-411-0	EASA,FAA,CAAC,ANAC										
139035	338-073-008-0	EASA,FAA,CAAC,ANAC										
139035	338-073-009-0	EASA,FAA,CAAC,ANAC										
139035	338-073-010-0	EASA,FAA,CAAC,ANAC										
139035	338-073-011-0	EASA,FAA,CAAC,ANAC										
139035	338-073-012-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139035	338-073-013-0	EASA,FAA,CAAC,ANAC										
139035	338-078-804-0	EASA,FAA,CAAC,ANAC										
139035	338-078-806-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	338-078-807-0	EASA,FAA,CAAC,ANAC										
139035	338-078-808-0	EASA,FAA,CAAC,ANAC										
139035	338-079-504-0	EASA,FAA,CAAC,ANAC										
139035	338-079-506-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	338-079-507-0	EASA,FAA,CAAC,ANAC										
139035	338-079-508-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	338-079-705-0	EASA,FAA,CAAC,ANAC										
139035	338-079-706-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	338-079-707-0	EASA,FAA,CAAC,ANAC										
139035	338-079-708-0	EASA,FAA,CAAC,ANAC										
139035	340-082-501-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	340-082-504-0	EASA,FAA,CAAC,ANAC										
139035	340-082-506-0	EASA,FAA,CAAC,ANAC										
139035	340-084-201-0	EASA,FAA,CAAC,ANAC										
139035	340-084-302-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	340-085-101-0	EASA,FAA,CAAC,ANAC										
139035	340-085-103-0	EASA,FAA,CAAC,ANAC										
139035	340-085-120-0	EASA,FAA,CAAC,ANAC,CAA UK										
139035	340-085-150-0	EASA,FAA,CAAC,ANAC										
139035	340-116-401-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	338-070-102-0	EASA,FAA,CAAC,ANAC	43	28	72-23-07	FAN FRAME ASSEMBLY - FAN DUCT PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION		435.00	SR Technics Switzerland
139040	338-070-202-0	EASA,FAA,CAAC,ANAC			72-23-07		Package B	001	CRACK REPAIR BY WELD BUILDUP		1175.00	SR Technics Switzerland
139040	338-070-302-0	EASA,FAA,CAAC,ANAC			72-23-07		Package E	004	REPAIR OF THE ATTACHMENT HOLE		660.00	SR Technics Switzerland
139040	338-070-402-0	EASA,FAA,CAAC,ANAC			72-23-07		Package F	003	SILICONE SEAL REPLACEMENT		765.00	SR Technics Switzerland
139040	338-070-502-0	EASA,FAA,CAAC,ANAC			72-23-07		Package F	005	REPLACEMENT OF THE SEAL RING		765.00	SR Technics Switzerland
139040	340-075-702-0	EASA,FAA,CAAC,ANAC			72-23-07		Package F	006	CRACK REPAIR ON LPT ACC STRUT PANEL		765.00	SR Technics Switzerland
139040	340-075-703-0	EASA,FAA,CAAC,ANAC			72-23-07		Package H	007	REPLACEMENT OF CUPS		760.00	SR Technics Switzerland
139040	340-075-705-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-07		Package H	007	REPLACEMENT OF INSERT		760.00	SR Technics Switzerland
139040	340-075-802-0	EASA,FAA,CAAC,ANAC			72-23-07		Package SB00	72-0202	REMOVAL OF SILICONE ELASTOMER SEALS FROM FAN DUCT PANELS		400.00	SR Technics Switzerland
139040	340-075-803-0	EASA,FAA,CAAC,ANAC			72-23-07		Package SB01	72-0334	INTRODUCTION OF A 4-5 O'CLOCK LPTACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED		305.00	SR Technics Switzerland
139040	340-075-805-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-075-902-0	EASA,FAA,CAAC,ANAC										
139040	340-075-903-0	EASA,FAA,CAAC,ANAC										
139040	340-075-905-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-075-953-0	EASA,FAA,CAAC,ANAC										
139040	340-076-002-0	EASA,FAA,CAAC,ANAC										
139040	340-076-003-0	EASA,FAA,CAAC,ANAC										
139040	340-076-005-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-102-0	EASA,FAA,CAAC,ANAC										
139040	340-076-103-0	EASA,FAA,CAAC,ANAC										
139040	340-076-105-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-153-0	EASA,FAA,CAAC,ANAC										
139040	340-076-202-0	EASA,FAA,CAAC,ANAC										
139040	340-076-203-0	EASA,FAA,CAAC,ANAC										
139040	340-076-205-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-253-0	EASA,FAA,CAAC,ANAC										
139040	340-076-302-0	EASA,FAA,CAAC,ANAC										
139040	340-076-303-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139040	340-076-305-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-402-0	EASA,FAA,CAAC,ANAC										
139040	340-076-403-0	EASA,FAA,CAAC,ANAC										
139040	340-076-405-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-502-0	EASA,FAA,CAAC,ANAC										
139040	340-076-503-0	EASA,FAA,CAAC,ANAC										
139040	340-076-505-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-553-0	EASA,FAA,CAAC,ANAC										
139040	340-076-602-0	EASA,FAA,CAAC,ANAC										
139040	340-076-603-0	EASA,FAA,CAAC,ANAC										
139040	340-076-605-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-076-702-0	EASA,FAA,CAAC,ANAC										
139040	340-076-703-0	EASA,FAA,CAAC,ANAC										
139040	340-076-705-0	EASA,FAA,CAAC,ANAC,CAA UK										
139040	340-084-002-0	EASA,FAA,CAAC,ANAC										
139040	340-084-003-0	EASA,FAA,CAAC,ANAC,CAA UK										
139055	338-006-102-0	EASA,FAA,CAAC,ANAC	27	28	72-21-10	FAN AND BOOSTER - FAN BLADES SPACERS	Package A	CLN/INSP	CLEANING AND INSPECTION		80.00	SR Technics Switzerland
139055	340-001-215-0	EASA,FAA,CAAC,ANAC			72-21-10		Package S800	72-0344	INTRODUCTION OF A NEW FAN BLADE SPACER OR REWORK OF THE OLD ONE		150.00	SR Technics Switzerland
139055	340-001-216-0	EASA,FAA,CAAC,ANAC										
139055	340-001-217-0	EASA,FAA,CAAC,ANAC										
139055	340-001-261-0	EASA,FAA,CAAC,ANAC										
139055	340-001-262-0	EASA,FAA,CAAC,ANAC										
139056	301-295-106-0	EASA,FAA,CAAC,ANAC	23	28	72-23-05	FAN FRAME ASSEMBLY - INNER/OUTER HOUSING/SUPPORT RDS	Package A	CLN/INSP	CLEANING AND INSPECTION		760.00	SR Technics Switzerland
139056	301-295-909-0	EASA,FAA,CAAC,ANAC			72-23-05		Package F	005	REPLACEMENT OF THE LOCATING PINS IN THE GUIDE SUPPORT		1480.00	SR Technics Switzerland
139056	340-029-803-0	EASA,FAA,CAAC,ANAC			72-23-05		Package G	006	RADIDAL SHAFT GUID TUBE AND GUIDID SUPPORT REPAIR		2080.00	SR Technics Switzerland
139056	340-032-604-0	EASA,FAA,CAAC,ANAC			72-23-05		Package H	007	REPAIR THE INNER LOCATION DIAMETER OF THE OUTER RADIAL DRIVER SHAFT BY PLASMA SPARYING		2080.00	SR Technics Switzerland
139056	340-032-606-0	EASA,FAA,CAAC,ANAC										
139056	340-050-004-0	EASA,FAA,CAAC,ANAC										
139056	340-050-005-0	EASA,FAA,CAAC,ANAC										
139340	1476M79P01	EASA,FAA,CAAC,ANAC	4	28	72-52-07	CFM56 HPT ROTOR FR. SHAFT DAMPER SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		450.00	SR Technics Switzerland
139340	1476M79P02	EASA,FAA,CAAC,ANAC										
139340	1476M79P03	EASA,FAA,CAAC,ANAC										
139344	1385M91P01	EASA,FAA,CAAC,ANAC	20	28	72-52-09	HIGH PRESSURE TURBINE ROTOR - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		355.00	SR Technics Switzerland
139344	1498M46P01	EASA,FAA,CAAC,ANAC										
139344	1522M86P01	EASA,FAA,CAAC,ANAC										
139344	1847M57P01	EASA,FAA,CAAC,ANAC										
139344	1847M57P02	EASA,FAA,CAAC,ANAC										
139344	2410M52P01	EASA,FAA,CAAC,ANAC										
139360	1559M14G05	EASA,FAA,CAAC,ANAC	41	28	72-32-03	COMPRESSOR FRONT STATOR - VANE SECTORS	Package A		BASIC REPAIR		195.00	SRTAS
139360	1559M14G06	EASA,FAA,CAAC,ANAC			72-32-03		Package A	CLN/INSP	CLEANING AND INSPECTION		195.00	SRTAS
139360	1559M14G07	EASA,FAA,CAAC,ANAC			72-32-03		Package A	INSP 001	INSPECTION		195.00	SRTAS
139360	1559M14G08	EASA,FAA,CAAC,ANAC			72-32-03		Package B		FULL REPAIR STAGE 4		495.00	SRTAS
139360	1559M15G01	EASA,FAA,CAAC,ANAC			72-32-03		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		495.00	SRTAS
139360	1559M15G02	EASA,FAA,CAAC,ANAC			72-32-03		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		495.00	SRTAS
139360	1559M15G03	EASA,FAA,CAAC,ANAC			72-32-03		Package C		ADDITIONAL WORKSCOPE STAGE 4		855.00	SRTAS
139360	1559M15G04	EASA,FAA,CAAC,ANAC			72-32-03		Package C	004	REBRAZE WITHOUT AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	855.00	SRTAS
139360	1834M94G01	EASA,FAA,CAAC,ANAC			72-32-03		Package D		ADDITIONAL WORKSCOPE STAGE 4		1660.00	SRTAS
139360	1834M94G02	EASA,FAA,CAAC,ANAC			72-32-03		Package D	004	REBRAZE REPAIR WITH SINGLE AIRFOIL REPLACEMENT	INCLUDES PACKAGE B	1660.00	SRTAS
139360	1834M94G03	EASA,FAA,CAAC,ANAC			72-32-03		Package D	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTO	INCLUDES PACKAGE B	1660.00	SRTAS
139360	1834M94G04	EASA,FAA,CAAC,ANAC			72-32-03		Package E		ADDITIONAL WORKSCOPE STAGE 4		350.00	SRTAS
139360	2031M14G05	EASA,FAA,CAAC,ANAC			72-32-03		Package E		FOR EACH ADDITIONAL AIRFOIL REPLACEMENT		350.00	SRTAS

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139360	2031M14G06	EASA,FAA,CAAC,ANAC			72-32-03		Package F		ADDITIONAL WORKSCOPE STAGE 4		70.00	SRTAS
139360	2031M14G07	EASA,FAA,CAAC,ANAC			72-32-03		Package F	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A B AND	70.00	SRTAS
139360	2031M14G08	EASA,FAA,CAAC,ANAC			72-32-03		Package G		ADDITIONAL WORKSCOPE STAGE 4		160.00	SRTAS
139360	P244G05	EASA,FAA,CAAC,ANAC			72-32-03		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	160.00	SRTAS
139360	P244G06	EASA,FAA,CAAC,ANAC			72-32-03		Package H		ADDITIONAL WORKSCOPE STAGE 4		850.00	SRTAS
139360	P244G07	EASA,FAA,CAAC,ANAC			72-32-03		Package H	006	INNER PLATFORM J-HOOK REPAIR		850.00	SRTAS
139360	P244G08	EASA,FAA,CAAC,ANAC			72-32-03		Package I		FULL REPAIR STAGE 5		510.00	SRTAS
139360	P245G01	EASA,FAA,CAAC,ANAC			72-32-03		Package I	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		510.00	SRTAS
139360	P245G02	EASA,FAA,CAAC,ANAC			72-32-03		Package I	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		510.00	SRTAS
139360	P245G03	EASA,FAA,CAAC,ANAC			72-32-03		Package J		ADDITIONAL WORKSCOPE STAGE 5		875.00	SRTAS
139360	P245G04	EASA,FAA,CAAC,ANAC			72-32-03		Package J	004	REBRAZE WITHOUT AIRFOIL REPLACEMENT	INCLUDES PACKAGE I	875.00	SRTAS
139360	P264G01	EASA,FAA,CAAC,ANAC			72-32-03		Package K		ADDITIONAL WORKSCOPE STAGE 5		1365.00	SRTAS
139360	P264G02	EASA,FAA,CAAC,ANAC			72-32-03		Package K	004	REBRAZE REPAIR WITH SINGLE AIRFOIL REPLACEMENT	INCLUDES PACKAGE I	1365.00	SRTAS
139360	P264G03	EASA,FAA,CAAC,ANAC			72-32-03		Package K	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTO	INCLUDES PACKAGE I	1365.00	SRTAS
139360	P264G04	EASA,FAA,CAAC,ANAC			72-32-03		Package L		ADDITIONAL WORKSCOPE STAGE 5		485.00	SRTAS
139360	P264G05	EASA,FAA,CAAC,ANAC			72-32-03		Package L		FOR EACH ADDITIONAL AIRFOIL REPLACEMENT		485.00	SRTAS
139360	P264G06	EASA,FAA,CAAC,ANAC			72-32-03		Package M		ADDITIONAL WORKSCOPE STAGE 5		75.00	SRTAS
139360	P264G07	EASA,FAA,CAAC,ANAC			72-32-03		Package M	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH REPAIRS 001, 002, I	75.00	SRTAS
139360	P264G08	EASA,FAA,CAAC,ANAC			72-32-03		Package N		ADDITIONAL WORKSCOPE STAGE 5		90.00	SRTAS
139360	P265G01	EASA,FAA,CAAC,ANAC			72-32-03		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	90.00	SRTAS
139360	P265G02	EASA,FAA,CAAC,ANAC			72-32-03		Package O		ADDITIONAL WORKSCOPE STAGE 5		880.00	SRTAS
139360	P265G03	EASA,FAA,CAAC,ANAC			72-32-03		Package O	006	INNER PLATFORM J-HOOK REPAIR		880.00	SRTAS
139360	P265G04	EASA,FAA,CAAC,ANAC			72-32-03		Package P		ADDITIONAL WORKSCOPE STAGE 4		505.00	SRTAS
139360	P265G05	EASA,FAA,CAAC,ANAC			72-32-03		Package P	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTORS		505.00	SRTAS
139360	P265G06	EASA,FAA,CAAC,ANAC			72-32-03		Package Q		ADDITIONAL WORKSCOPE STAGE 5		505.00	SRTAS
139360	P265G07	EASA,FAA,CAAC,ANAC			72-32-03		Package Q	007	AIRFOIL REPLACEMENT ON THE 3D AERO AND SEMI-3D AERO DESIGN VANE SECTORS		505.00	SRTAS
139360	P265G08	EASA,FAA,CAAC,ANAC										
139378	301-333-307-0	EASA,FAA,CAAC,ANAC	31	28	72-55-20	LOW PRESSURE TURBINE SHAFT - LOCATING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		340.00	SR Technics Switzerland
139378	301-333-404-0	EASA,FAA,CAAC,ANAC,CAA UK										
139378	305-415-103-0	EASA,FAA,CAAC,ANAC										
139378	337-111-801-0	EASA,FAA,CAAC,ANAC										
139378	337-111-802-0	EASA,FAA,CAAC,ANAC										
139378	337-111-803-0	EASA,FAA,CAAC,ANAC										
139378	337-111-901-0	EASA,FAA,CAAC,ANAC										
139378	337-111-902-0	EASA,FAA,CAAC,ANAC										
139378	337-111-903-0	EASA,FAA,CAAC,ANAC										
139378	340-161-101-0	EASA,FAA,CAAC,ANAC										
139378	340-161-103-0	EASA,FAA,CAAC,ANAC										
139378	340-161-201-0	EASA,FAA,CAAC,ANAC										
139378	340-161-203-0	EASA,FAA,CAAC,ANAC										
139390	305-136-605-0	EASA,FAA,CAAC,ANAC	18	28	72-62-02	TRANSFER GEARBOX - BEVEL GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1125.00	SR Technics Switzerland
139390	305-136-704-0	EASA,FAA,CAAC,ANAC			72-62-02		Package F	005	REPLACEMENT OF THE RING SEAL		820.00	SR Technics Switzerland
139390	305-163-301-0	EASA,FAA,CAAC,ANAC			72-62-02		Package I	008	REPLACEMENT OF DISTRIBUTOR		1690.00	SR Technics Switzerland
139390	305-163-401-0	EASA,FAA,CAAC,ANAC										
139390	340-049-501-0	EASA,FAA,CAAC,ANAC										
139390	340-049-601-0	EASA,FAA,CAAC,ANAC										
139401	305-138-805-0	EASA,FAA,CAAC,ANAC	22	28	72-63-02	ACCESSORY GEARBOX - MOUNTING DRIVE PADS	Package A	CLN/INSP	CLEANING AND INSPECTION		475.00	SR Technics Switzerland
139401	305-138-807-0	EASA,FAA,CAAC,ANAC			72-63-02		Package C	02	REPLACEMENT OF KEY-LOCKED STUDS		990.00	SR Technics Switzerland
139401	305-139-002-0	EASA,FAA,CAAC,ANAC			72-63-02		Package SB00	72-0689	INTRODUCTION OF NEW AGB WITH NEW ROLLER BEARING AND REWORK OF OLD / DRIVE PAD		810.00	SR Technics Switzerland
139401	305-139-003-0	EASA,FAA,CAAC,ANAC										
139401	305-139-203-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139401	305-139-204-0	EASA,FAA,CAAC,ANAC										
139401	305-139-406-0	EASA,FAA,CAAC,ANAC										
139401	305-139-407-0	EASA,FAA,CAAC,ANAC										
139401	305-139-602-0	EASA,FAA,CAAC,ANAC										
139401	305-139-603-0	EASA,FAA,CAAC,ANAC										
139401	305-139-701-0	EASA,FAA,CAAC,ANAC										
139401	305-139-801-0	EASA,FAA,CAAC,ANAC										
139401	305-140-001-0	EASA,FAA,CAAC,ANAC										
139401	305-142-601-0	EASA,FAA,CAAC,ANAC										
139401	335-301-000-0	EASA,FAA,CAAC,ANAC										
139401	335-301-200-0	EASA,FAA,CAAC,ANAC										
139401	340-047-802-0	EASA,FAA,CAAC,ANAC										
139401	340-047-804-0	EASA,FAA,CAAC,ANAC										
139401	340-047-805-0	EASA,FAA,CAAC,ANAC										
139401	340-047-807-0	EASA,FAA,CAAC,ANAC										
139401	340-048-102-0	EASA,FAA,CAAC,ANAC										
139401	340-048-103-0	EASA,FAA,CAAC,ANAC										
139401	340-048-104-0	EASA,FAA,CAAC,ANAC										
139401	340-048-602-0	EASA,FAA,CAAC,ANAC										
139401	340-048-802-0	EASA,FAA,CAAC,ANAC										
139401	340-055-602-0	EASA,FAA,CAAC,ANAC										
139423	305-137-101-0	EASA,FAA,CAAC,ANAC	34	28	72-63-03	ACCESSORY GEARBOX - GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1140.00	SR Technics Switzerland
139423	305-137-203-0	EASA,FAA,CAAC,ANAC			72-63-03		Package B	INSP-001	MPI INSPECTION TEETH FOOT AREA		275.00	SR Technics Switzerland
139423	305-137-501-0	EASA,FAA,CAAC,ANAC			72-63-03		Package D	003	REPLACEMENT OF THE OIL RETAINING RING ON THE 47-TOOTH GEARSHAFT ASSEMBLY		2270.00	SR Technics Switzerland
139423	305-137-602-0	EASA,FAA,CAAC,ANAC			72-63-03		Package F	005	REPAIR DIA OF TOOTH GEARSHAFT		1375.00	SR Technics Switzerland
139423	305-137-701-0	EASA,FAA,CAAC,ANAC			72-63-03		Package I	008	EFF.D OF TOOTH GEARSHAFT		940.00	SR Technics Switzerland
139423	305-137-802-0	EASA,FAA,CAAC,ANAC			72-63-03		Package SB00	72-0689	INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND BEARING PART		435.00	SR Technics Switzerland
139423	305-137-902-0	EASA,FAA,CAAC,ANAC			72-63-03		Package SB01	72-0130	STARTER GEARSHAFT REPLACEMENT		500.00	SR Technics Switzerland
139423	305-138-202-0	EASA,FAA,CAAC,ANAC										
139423	305-146-302-0	EASA,FAA,CAAC,ANAC										
139423	305-146-402-0	EASA,FAA,CAAC,ANAC										
139423	305-151-501-0	EASA,FAA,CAAC,ANAC										
139423	305-163-501-0	EASA,FAA,CAAC,ANAC										
139423	305-165-301-0	EASA,FAA,CAAC,ANAC										
139423	305-165-401-0	EASA,FAA,CAAC,ANAC										
139423	305-165-601-0	EASA,FAA,CAAC,ANAC										
139423	305-167-001-0	EASA,FAA,CAAC,ANAC										
139423	335-302-902-0	EASA,FAA,CAAC,ANAC										
139423	335-303-002-0	EASA,FAA,CAAC,ANAC										
139423	335-303-201-0	EASA,FAA,CAAC,ANAC										
139423	335-303-502-0	EASA,FAA,CAAC,ANAC										
139423	335-303-503-0	EASA,FAA,CAAC,ANAC										
139423	335-303-506-0	EASA,FAA,CAAC,ANAC										
139423	335-303-601-0	EASA,FAA,CAAC,ANAC										
139423	335-324-101-0	EASA,FAA,CAAC,ANAC										
139423	340-048-301-0	EASA,FAA,CAAC,ANAC										
139423	340-051-602-0	EASA,FAA,CAAC,ANAC										
139423	340-051-801-0	EASA,FAA,CAAC,ANAC										
139423	340-051-901-0	EASA,FAA,CAAC,ANAC										
139423	340-052-802-0	EASA,FAA,CAAC,ANAC										
139423	340-055-202-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139423	340-151-101-0	EASA,FAA,CAAC,ANAC										
139423	340-151-501-0	EASA,FAA,CAAC,ANAC										
139423	340-154-301-0	EASA,FAA,CAAC,ANAC										
139424	305-140-501-0	EASA,FAA,CAAC,ANAC	4	28	72-63-25	ACCESSORY GEARBOX HARDWARE MODUL 63	Package A	CLN/INSP	CLEANING & INSPECTION		340.00	SR Technics Switzerland
139424	305-147-001-0	EASA,FAA,CAAC,ANAC										
139424	305-159-001-0	EASA,FAA,CAAC,ANAC										
139440	336-002-203-0	EASA,FAA,CAAC,ANAC	47	28	72-54-06	LOW PRESSURE TURBINE - ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		560.00	SR Technics Switzerland
139440	336-002-302-0	EASA,FAA,CAAC,ANAC,TCOA			72-54-06		Package AN	SPM 70-41-11	REMOVE HIGH METAL		245.00	SR Technics Switzerland
139440	336-003-002-0	EASA,FAA,CAAC,ANAC			72-54-06		Package C	001	RECONDITIONING OF THE TITANIUM/ALUMINUM OXIDE COATING ON THE SEAL TE PRICE PER STAGE		3095.00	SR Technics Switzerland
139440	336-003-102-0	EASA,FAA,CAAC,ANAC			72-54-06		Package D	002	RECONDITIONING OF THE FACE MATING WITH THE RETAINING RING BY PLASMA SPRAYING		2695.00	SR Technics Switzerland
139440	338-111-502-0	EASA,FAA,CAAC,ANAC			72-54-06		Package E	003	TOUCH-UP OF SEAL TEETH		985.00	SR Technics Switzerland
139440	338-111-603-0	EASA,FAA,CAAC,ANAC										
139440	338-111-701-0	EASA,FAA,CAAC,ANAC										
139440	338-111-703-0	EASA,FAA,CAAC,ANAC										
139440	340-304-002-0	EASA,FAA,ANAC										
139440	340-304-101-0	EASA,FAA,CAAC,ANAC										
139440	340-304-301-0	EASA,FAA,CAAC,ANAC										
139447	337-123-301-0	EASA,FAA,CAAC,ANAC	14	28	72-23-27	NO.1 AND NO.2 BEARING SUPPORT - RETAINER WASHER	Package A	CLN/INSP	CLEANING AND INSPECTION		95.00	SR Technics Switzerland
139447	340-032-501-0	EASA,FAA,ANAC										
139483	337-011-001-0	EASA,FAA,CAAC,ANAC	20	28	72-22-11	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT - STATIONARY AIR/OIL SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		755.00	SR Technics Switzerland
139483	337-011-002-0	EASA,FAA,CAAC,ANAC										
139483	338-063-702-0	EASA,FAA,CAAC,ANAC										
139483	338-063-703-0	EASA,FAA,CAAC,ANAC										
139483	338-063-704-0	EASA,FAA,CAAC,ANAC										
139483	338-063-705-0	EASA,FAA,CAAC,ANAC										
139483	338-063-751-0	EASA,FAA,CAAC,ANAC										
139483	338-156-002-0	EASA,FAA,CAAC,ANAC										
139483	338-156-003-0	EASA,FAA,CAAC,ANAC										
139485	1585M80G01	EASA,FAA,CAAC,ANAC	4	28	72-09-02	CFM56-ALL MGB/IGB/TGB GEARBOX NOZZLE	Package A	CLN/INSP	CLEANING AND INSPECTION		430.00	SR Technics Switzerland
139485	305-142-702-0	EASA,FAA,CAAC,ANAC										
139485	305-142-802-0	EASA,FAA,CAAC,ANAC										
139485	305-142-901-0	EASA,FAA,CAAC,ANAC										
139485	305-143-002-0	EASA,FAA,CAAC,ANAC										
139485	305-143-102-0	EASA,FAA,CAAC,ANAC										
139485	305-143-201-0	EASA,FAA,CAAC,ANAC										
139485	305-143-301-0	EASA,FAA,CAAC,ANAC										
139485	305-143-401-0	EASA,FAA,CAAC,ANAC										
139485	305-143-502-0	EASA,FAA,CAAC,ANAC										
139485	305-146-802-0	EASA,FAA,CAAC,ANAC										
139485	305-147-102-0	EASA,FAA,CAAC,ANAC										
139485	9542M72G03	EASA,FAA,CAAC,ANAC										
139485	9973M28G02	EASA,FAA,CAAC,ANAC										
139550	335-191-202-0	EASA,FAA,CAAC,ANAC	36	28	72-21-02	FAN AND BOOSTER - BOOSTER BLADES, STAGES 2-4	Package A	CLN/INSP	CLEANING AND INSPECTION		40.00	SR Technics Switzerland
139550	335-191-203-0	EASA,FAA,CAAC,ANAC			72-21-02		Package E		WEIGH AND MATCH BLADE		40.00	SR Technics Switzerland
139550	335-191-204-0	EASA,FAA,CAAC,ANAC										
139550	335-191-205-0	EASA,FAA,CAAC,ANAC										
139550	335-191-302-0	EASA,FAA,CAAC,ANAC										
139550	335-191-303-0	EASA,FAA,CAAC,ANAC										
139550	335-191-304-0	EASA,FAA,CAAC,ANAC										
139550	335-191-305-0	EASA,FAA,CAAC,ANAC										
139550	338-002-206-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139550	338-002-207-0	EASA,FAA,CAAC,ANAC										
139550	338-002-208-0	EASA,FAA,CAAC,ANAC										
139550	338-002-209-0	EASA,FAA,CAAC,ANAC										
139550	338-002-218-0	EASA,FAA,CAAC,ANAC										
139550	338-002-219-0	EASA,FAA,CAAC,ANAC										
139550	338-002-220-0	EASA,FAA,CAAC,ANAC										
139550	338-002-221-0	EASA,FAA,CAAC,ANAC										
139550	338-002-306-0	EASA,FAA,CAAC,ANAC										
139550	338-002-307-0	EASA,FAA,CAAC,ANAC										
139550	338-002-308-0	EASA,FAA,CAAC,ANAC										
139550	338-002-309-0	EASA,FAA,CAAC,ANAC										
139550	338-002-318-0	EASA,FAA,CAAC,ANAC										
139550	338-002-319-0	EASA,FAA,CAAC,ANAC										
139550	338-002-320-0	EASA,FAA,CAAC,ANAC										
139550	338-002-321-0	EASA,FAA,CAAC,ANAC										
139550	338-002-406-0	EASA,FAA,CAAC,ANAC										
139550	338-002-407-0	EASA,FAA,CAAC,ANAC										
139550	338-002-408-0	EASA,FAA,CAAC,ANAC										
139550	338-002-409-0	EASA,FAA,CAAC,ANAC										
139550	338-002-418-0	EASA,FAA,CAAC,ANAC										
139550	338-002-419-0	EASA,FAA,CAAC,ANAC										
139550	338-002-420-0	EASA,FAA,CAAC,ANAC										
139550	338-002-421-0	EASA,FAA,CAAC,ANAC										
139550	338-002-518-0	EASA,FAA,CAAC,ANAC										
139550	338-002-519-0	EASA,FAA,CAAC,ANAC										
139550	338-002-520-0	EASA,FAA,CAAC,ANAC										
139550	338-002-521-0	EASA,FAA,CAAC,ANAC										
139550	338-002-534-0	EASA,FAA,CAAC,ANAC										
139550	338-002-535-0	EASA,FAA,CAAC,ANAC										
139550	338-002-536-0	EASA,FAA,CAAC,ANAC										
139550	338-002-537-0	EASA,FAA,CAAC,ANAC										
139550	338-002-542-0	EASA,FAA,CAAC,ANAC										
139550	338-002-543-0	EASA,FAA,CAAC,ANAC										
139550	338-002-544-0	EASA,FAA,CAAC,ANAC										
139550	338-002-545-0	EASA,FAA,CAAC,ANAC										
139550	340-057-201-0	EASA,FAA,CAAC,ANAC										
139550	340-057-202-0	EASA,FAA,CAAC,ANAC										
139550	340-057-203-0	EASA,FAA,CAAC,ANAC										
139550	340-057-204-0	EASA,FAA,CAAC,ANAC										
139550	340-057-301-0	EASA,FAA,CAAC,ANAC										
139550	340-057-302-0	EASA,FAA,CAAC,ANAC										
139550	340-057-303-0	EASA,FAA,CAAC,ANAC										
139550	340-057-304-0	EASA,FAA,CAAC,ANAC										
139550	340-057-401-0	EASA,FAA,CAAC,ANAC										
139550	340-057-402-0	EASA,FAA,CAAC,ANAC										
139550	340-057-403-0	EASA,FAA,CAAC,ANAC										
139550	340-057-404-0	EASA,FAA,CAAC,ANAC										
139550	340-057-409-0	EASA,FAA,CAAC,ANAC										
139550	340-057-410-0	EASA,FAA,CAAC,ANAC										
140121	1276M85P05	EASA,FAA,CAAC,ANAC	18	28	72-32-15	COMPRESSOR STATOR SUPPORT PLATE AND LINK	Package A	CLN/INSP	CLEANING AND INSPECTION		675.00	SR Technics Switzerland
140121	1276M86P05	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140121	1591M23P02	EASA,FAA,CAAC,ANAC										
140121	1591M24G01	EASA,FAA,CAAC,ANAC										
140121	9511M34P01	EASA,FAA,CAAC,ANAC										
140140	325-027-503-0	EASA,FAA,CAAC,ANAC	12	21	26-11-02	FIRE DETECTION HARNESSES MW0325 & MW0326	Package C		PRE-TEST	TESTING AND FAULT ISOLATION	495.00	SR Technics Switzerland
140140	325-027-504-0	EASA,FAA,CAAC,ANAC			26-11-02		Package C		TEST	TESTING AND FAULT ISOLATION	495.00	SR Technics Switzerland
140140	325-027-505-0	EASA,FAA,CAAC,ANAC			26-11-02		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
140140	325-027-506-0	EASA,FAA,CAAC,ANAC			26-11-02		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1780.00	SR Technics Switzerland
140140	325-027-603-0	EASA,FAA,CAAC,ANAC			26-11-02		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	3390.00	SR Technics Switzerland
140140	325-027-604-0	EASA,FAA,CAAC,ANAC			26-11-02		Package SB00	72-0136	IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNE	IN CONJUNCTION WITH PACKAGE MEDIUM	170.00	SR Technics Switzerland
140140	325-027-605-0	EASA,FAA,CAAC,ANAC			26-11-02		Package SB01	72-0269	FIRE DETECTION HARNESSES MW0325 AND MW0326 TERMINAL LUG REPLACEMENT	IN CONJUNCTION WITH PACKAGE MEDIUM	170.00	SR Technics Switzerland
140140	325-027-606-0	EASA,FAA,CAAC,ANAC										
140140	325-102-502-0	EASA,FAA,CAAC,ANAC										
140140	325-102-503-0	EASA,FAA,CAAC,ANAC										
140152	340-003-206-0	EASA,FAA,CAAC,ANAC	18	28	72-21-19	FAN AND BOOSTER - THREADED PIN	Package A	CLN/INSP	CLEANING AND INSPECTION		60.00	SR Technics Switzerland
140152	340-046-106-0	EASA,FAA,CAAC,ANAC										
140152	340-046-206-0	EASA,FAA,CAAC,ANAC										
140152	649-781-790-0	EASA,FAA,CAAC,ANAC										
140152	649-781-791-0	EASA,FAA,CAAC,ANAC										
140152	649-781-793-0	EASA,FAA,CAAC,ANAC										
140152	649-782-300-0	EASA,FAA,CAAC,ANAC										
140152	649-782-304-0	EASA,FAA,CAAC,ANAC										
140152	649-782-309-0	EASA,FAA,CAAC,ANAC										
140170	340-063-804-0	EASA,FAA,CAAC,ANAC,CAA UK	26	28	72-23-32	FAN FRAME ASSEMBLY - SHROUD SEGMENTS AND SHROUD PADS	Package A	CLN/INSP	CLEANING AND INSPECTION		560.00	SR Technics Switzerland
140170	340-063-902-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-32		Package B	INSP-001	SHROUD APPLICATION ALODINE		1020.00	SR Technics Switzerland
140170	340-064-102-0	EASA,FAA,CAAC,ANAC			72-23-32		Package B	INSP-001	SHROUD REPLACE RIVETED PART		1020.00	SR Technics Switzerland
140170	340-064-203-0	EASA,FAA,CAAC,ANAC			72-23-32		Package B	INSP-001	SHROUD REPLACE SWAGED INSERT		1020.00	SR Technics Switzerland
140170	340-064-205-0	EASA,FAA,CAAC,ANAC,CAA UK			72-23-32		Package B	INSP-001	SHROUD SEGMENT BLEND OTHER AREA		1020.00	SR Technics Switzerland
140170	340-064-206-0	EASA,FAA,CAAC,ANAC			72-23-32		Package B	INSP-001	SHROUD V-GROOVE APPLY VARNISH		1020.00	SR Technics Switzerland
140170	340-064-303-0	EASA,FAA,CAAC,ANAC			72-23-32		Package B	INSP-001	SHROUD V-GROOVE BLEND AREA A+B		1020.00	SR Technics Switzerland
140170	340-064-305-0	EASA,FAA,CAAC,ANAC			72-23-32		Package C	001	REPLACEMENT OF DAMAGED SEAL FITTING ON SHROUD PAD 4,7 AND 10		1105.00	SR Technics Switzerland
140170	340-064-306-0	EASA,FAA,CAAC,ANAC			72-23-32		Package D	002	BLEND REPAIR		360.00	SR Technics Switzerland
140170	340-064-307-0	EASA,FAA,CAAC,ANAC										
140170	340-066-104-0	EASA,FAA,CAAC,ANAC										
140170	340-066-105-0	EASA,FAA,CAAC,ANAC										
140170	340-066-106-0	EASA,FAA,CAAC,ANAC										
140170	340-067-806-0	EASA,FAA,CAAC,ANAC										
140170	340-073-001-0	EASA,FAA,CAAC,ANAC,CAA UK										
140170	340-073-201-0	EASA,FAA,CAAC,ANAC										
140170	340-073-401-0	EASA,FAA,CAAC,ANAC										
140170	340-073-601-0	EASA,FAA,CAAC,ANAC										
140170	340-073-801-0	EASA,FAA,CAAC,ANAC										
140182	340-402-503-0	EASA,FAA,CAAC,ANAC	10	21	77-21-17	CFM56-7B T495 THERMOCOUPLE WIRING HARNESS	Package B	TEST	PRE TEST		460.00	SR Technics Switzerland
140182	TC296-02	EASA,FAA,CAAC,ANAC										
140182	TC296-03	EASA,FAA,CAAC,ANAC										
140182	TC296-04	EASA,FAA,CAAC,ANAC										
140245	338-061-302-0	EASA,FAA,CAAC,ANAC	46	28	72-54-11	LOW PRESSURE TURBINE - COOLING MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		570.00	SR Technics Switzerland
140245	338-061-352-0	EASA,FAA,CAAC,ANAC			72-54-11		Package B	1	REPLACEMENT OF ONE OR SEVERAL COOLING AIR TUBES		1065.00	SR Technics Switzerland
140245	338-119-301-0	EASA,FAA,CAAC,ANAC			72-54-11		Package F	5	REPLACEMENT OF THE FORWARD AND / OR REAR LUGS		795.00	SR Technics Switzerland
140245	340-027-505-0	EASA,FAA,CAAC,ANAC			72-54-11		Package H	7	SMOOTHING OF BRAZE		550.00	SR Technics Switzerland
140245	340-027-506-0	EASA,FAA,CAAC,ANAC			72-54-11		Package K	6	REPAIR OF CRACKS ON LUG BY TIG WELDING		430.00	SR Technics Switzerland
140245	340-027-507-0	EASA,FAA,CAAC,ANAC			72-54-11		Package L	4	REPLACEMENT OF SLEEVE		3055.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140245	340-027-508-0	EASA,FAA,CAAC,ANAC										
140245	340-027-555-0	EASA,FAA,CAAC,ANAC										
140245	340-027-556-0	EASA,FAA,CAAC,ANAC										
140245	340-027-557-0	EASA,FAA,CAAC,ANAC										
140245	340-038-251-0	EASA,FAA,CAAC,ANAC,CAA UK										
140245	340-038-307-0	EASA,FAA,CAAC,ANAC										
140245	340-038-351-0	EASA,FAA,CAAC,ANAC,CAA UK										
140245	340-311-401-0	EASA,FAA,CAAC,ANAC										
140245	340-311-402-0	EASA,FAA,CAAC,ANAC										
140255	310A2030-11	EASA,FAA,CAAC,ANAC	20	21	71-21-37	AFT ENGINE MOUNT - ASSY	Package C		PREINSPECTION OF AFT ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LIGHT, M	2355.00	SR Technics Switzerland
140255	310A2030-12	EASA,FAA,CAAC,ANAC			71-21-37		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS		510.00	SR Technics Switzerland
140255	310A2030-15	EASA,FAA,CAAC,ANAC			71-21-37		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS EXAMPLE: BAR EVENER REPLACEMENT		1015.00	SR Technics Switzerland
140255	310A2030-16	EASA,FAA,CAAC,ANAC			71-21-37		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIECE PART REPAIRS EXAMPLE: HANGER ASSY REPLACEMENT		1530.00	SR Technics Switzerland
140255	310A2030-17	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package G		OVERHAUL	DISASSEMBLY, CLEANING, INSPECTION, ASS	1615.00	SR Technics Switzerland
140255	310A2030-19	EASA,FAA,CAAC,ANAC,CAA UK			71-21-37		Package SB00	737-71A1462	AFT ENGINE MOUNT, LINK ASSEMBLY, HANGER FITTING, INSPECTION, CORRECTION IN CONJUNCTION WITH PACKAGE HEAVY O		465.00	SR Technics Switzerland
140255	310A2030-4	EASA,FAA,CAAC,ANAC										
140255	310A2030-6	EASA,FAA,CAAC,ANAC										
140257	310A2041-10	EASA,FAA,CAAC,ANAC,CAA UK	25	21	71-04-26	AFT ENGINE MOUNT - THRUST LINK ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		835.00	SR Technics Switzerland
140257	310A2041-12	EASA,FAA,CAAC,ANAC			71-04-26		Package B	2-1	BUSHING REPLACEMENT		1685.00	SR Technics Switzerland
140257	310A2041-5	EASA,FAA,CAAC,ANAC			71-04-26		Package C	2-2	REPAIR GROUND-BORES		1460.00	SR Technics Switzerland
140257	310A2041-6	EASA,FAA,CAAC,ANAC			71-04-26		Package D	SRM 54-70-90	ALLOWABLE DAMAGE 1 BLEND THRUST LINK		2055.00	SR Technics Switzerland
140257	310A2041-9	EASA,FAA,CAAC,ANAC,CAA UK										
144718	1498M53G01	EASA,FAA,CAAC,ANAC	26	28	72-41-07	COMBUSTION CASE - COMPRESSOR STATOR SUPPORT CDP BULKHEAD	Package A	CLN/INSP	CLEANING AND INSPECTION		1000.00	SR Technics Switzerland
144718	1834M52P01	EASA,FAA,CAAC,ANAC			72-41-07		Package B	001	DIMENSIONAL RESTORATION		4340.00	SR Technics Switzerland
144718	1834M52P02	EASA,FAA,CAAC,ANAC			72-41-07		Package C		MEASURE NEW - / OVHLD PARTS		110.00	SR Technics Switzerland
144718	1993M20G01	EASA,FAA,CAAC,ANAC										
144718	2428M60G01	EASA,FAA,CAAC,ANAC										
144741	305-397-203-0	EASA,FAA,CAAC,ANAC	20	21	72-23-26	FAN FRAME ASSEMBLY - AIR TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		650.00	SR Technics Switzerland
144741	338-171-501-0	EASA,FAA,CAAC,ANAC										
144741	340-032-401-0	EASA,FAA,CAAC,ANAC										
144756	338-002-701-0	EASA,FAA,CAAC,ANAC	24	28	72-21-04	FAN AND BOOSTER - SEALING FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		570.00	SR Technics Switzerland
144756	338-002-702-0	EASA,FAA,CAAC,ANAC			72-21-04		Package C	002	SPOT TOUCH-UP FULL OR RECONDITIONING OF THE CHROMIC OR SULFURIC ANODIZING		790.00	SR Technics Switzerland
144756	338-002-703-0	EASA,FAA,CAAC,ANAC										
144756	340-003-103-0	EASA,FAA,CAAC,ANAC										
144787	337-002-910-0	EASA,FAA,CAAC,ANAC	59	28	72-55-01	LOW PRESSURE TURBINE SHAFT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1225.00	SR Technics Switzerland
144787	338-010-003-0	EASA,FAA,CAAC,ANAC			72-55-01		Package A	INSP	BORESCOPE INSPECTION (BSI)		1225.00	SR Technics Switzerland
144787	338-010-004-0	EASA,FAA,CAAC,ANAC			72-55-01		Package B	INSP-001	OUTER PAINTED SURFACE - CORROSION	BLENDING AND TOUCHUP REPAIR	980.00	SR Technics Switzerland
144787	338-010-005-0	EASA,FAA,CAAC,ANAC			72-55-01		Package C	INSP-001	INNER SURFACE - CORROSION	BLASTING AND TOUCHUP REPAIR	1230.00	SR Technics Switzerland
144787	338-010-006-0	EASA,FAA,CAAC,ANAC			72-55-01		Package D	001	FULL REPAIR OF THE ALUMINUM PAINT		3725.00	SR Technics Switzerland
144787	340-074-703-0	EASA,FAA,CAAC,ANAC			72-55-01		Package H	014	BLENDING OF THE FORWARD ANTI-ROTATION LUGS		925.00	SR Technics Switzerland
144787	340-074-705-0	EASA,FAA,CAAC,ANAC			72-55-01		Package QI	016	CLEANING AND PACKAGING		410.00	SR Technics Switzerland
144787	340-074-706-0	EASA,FAA,CAAC,ANAC			72-55-01		Package S	018	REPAIR OF THE LOCATING DIAMETER WITH AIR/OIL SEPARATOR		2410.00	SR Technics Switzerland
144787	340-074-707-0	EASA,FAA,CAAC,ANAC			72-55-01		Package SB00	72-0520	INSPECTION OF THE FORWARD LPT SHAFT FOR MISSING PAINT	IN CONJUNCTION WITH PACKAGE A	970.00	SR Technics Switzerland
144787	340-074-720-0	EASA,FAA,CAAC,ANAC			72-55-01		Package SB01	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI)	IN CONJUNCTION WITH PACKAGE A	715.00	SR Technics Switzerland
144787	340-074-721-0	EASA,FAA,CAAC,ANAC			72-55-01		Package SB02	72-0526	INSPECTION OF THE LPT SHAFT IN SHOP	IN CONJUNCTION WITH PACKAGE A	1685.00	SR Technics Switzerland
144787	340-074-722-0	EASA,FAA,CAAC,ANAC			72-55-01		Package SB03	72-0104	INTRODUCTION OF A NEW PAINT ON LPT SHAFT		3570.00	SR Technics Switzerland
144787	340-074-723-0	EASA,FAA,CAAC,ANAC,CAA UK										
144788	336-025-102-0	EASA,FAA,CAAC,ANAC	26	28	72-56-03	LOW PRESSURE TURBINE REAR FRAME - OIL COLLECTOR	Package A	CLN/INSP	CLEANING AND INSPECTION		570.00	SR Technics Switzerland
144788	338-170-601-0	EASA,FAA,CAAC,ANAC										
144788	340-175-802-0	EASA,FAA,CAAC,ANAC										
144788	340-175-803-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144793	336-065-403-0	EASA,FAA,CAAC,ANAC	51	21	72-54-18	LOW PRESSURE TURBINE - AIR SUPPLY TUBE AND MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		475.00	SR Technics Switzerland
144793	336-504-604-0	EASA,FAA,CAAC,ANAC			72-54-18		Package C	002	REPLACEMENT OF THE CLIP BY BRAZING		670.00	SR Technics Switzerland
144793	337-110-303-0	EASA,FAA,CAAC,ANAC			72-54-18		Package D	003	REPLACEMENT OF THE INLET FITTING AND/OR THE END FITTING BY WELDING		2840.00	SR Technics Switzerland
144793	338-118-602-0	EASA,FAA,CAAC,ANAC			72-54-18		Package E	004	REPLACEMENT OF THE END FITTING ON THE AIR SUPPLY DUCT		2695.00	SR Technics Switzerland
144793	340-027-602-0	EASA,FAA,CAAC,ANAC			72-54-18		Package O	014	HOSE AND TUBE ASSEMBLIES REPAIR 014 - EXTERNAL TUBE ASSEMBLIES BRACKETS GENERAL EXTERNAL TUBING REPAIR REF. E		945.00	SR Technics Switzerland
144793	340-027-603-0	EASA,FAA,CAAC,ANAC			72-54-18		Package SB00	75-0043	REWORK OF THE AIR MANIFOLD AND THE BRACKET OF THE COOLING MANIFOLD IN FIELD		650.00	SR Technics Switzerland
144793	340-027-604-0	EASA,FAA,CAAC,ANAC										
144793	340-091-603-0	EASA,FAA,CAAC,ANAC										
144793	340-091-604-0	EASA,FAA,CAAC,ANAC										
144793	340-091-605-0	EASA,FAA,CAAC,ANAC										
144794	336-009-602-0	EASA,FAA,CAAC,ANAC	36	28	72-53-11	STAGE 1 LPT NOZZLE - INTERMEDIATE FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		725.00	SR Technics Switzerland
144794	338-111-201-0	EASA,FAA,CAAC,ANAC			72-53-11		Package B	001	REPAIR OF THERMAL COATING ON MATING FACE & RABBIT DIA WITH STG 1 LPT N AREA A		3475.00	SR Technics Switzerland
144794	338-111-202-0	EASA,FAA,CAAC,ANAC										
601859	219316-1	EASA,FAA,ANAC	2	21	73-11-15	CFM56-7B PLATE BEARING ASSY	Package B	05	REWORK BEARING PLATE		1040.00	SR Technics Switzerland
603519	310A2037-10	EASA,FAA,CAAC,ANAC	5	21	71-21-37	CFM56-7B PIN-PAWL THRUST LINK PIN	Package A	CLN/INSP	CLEANING & INSPECTION		340.00	SR Technics Switzerland
603519	310A2037-8	EASA,FAA,CAAC,ANAC										
607350	325-029-901-0	EASA,FAA,CAAC,ANAC	21	21	71-51-02	NACELLE HARNESS - MW0311	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
607350	325-029-902-0	EASA,FAA,CAAC,ANAC			71-51-02		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1075.00	SR Technics Switzerland
607350	325-029-903-0	EASA,FAA,CAAC,ANAC			71-51-02		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	1510.00	SR Technics Switzerland
607350	325-029-904-0	EASA,FAA,CAAC,ANAC			71-51-02		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	2965.00	SR Technics Switzerland
607350	325-029-905-0	EASA,FAA,CAAC,ANAC			71-51-02		Package SB00	72-0262	NEW MW0311 ELECTRICAL HARNESS	IN CONIUNCTION WITH PACKAGE MEDIUM	500.00	SR Technics Switzerland
607350	325-029-906-0	EASA,FAA,CAAC,ANAC			71-51-02		Package SB01	72-0779	INTRODUCTION OF NEW MW0311 ELEC. HARNESS AND IN FILED REWORK OF THE C IN CONIUNCTION WITH PACKAGE MEDIUM		500.00	SR Technics Switzerland
607350	325-029-907-0	EASA,FAA,CAAC,ANAC										
607350	325-029-908-0	EASA,FAA,CAAC,ANAC										
609488	325-025-801-0	EASA,FAA,CAAC,ANAC	22	21	73-24-03	ELECTRICAL HARNESS J8	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	360.00	SR Technics Switzerland
609488	325-025-803-0	EASA,FAA,CAAC,ANAC			73-24-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1190.00	SR Technics Switzerland
609488	325-025-804-0	EASA,FAA,CAAC,ANAC			73-24-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF THE CONI	4135.00	SR Technics Switzerland
609488	325-100-703-0	EASA,FAA,ANAC			73-24-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS ARE AF	5015.00	SR Technics Switzerland
609488	325-100-802-0	EASA,FAA,ANAC			73-24-03		Package SB00	73-0202	INTRODUCTION OF A NEW J8 ELECTRICAL HARNESS AND REWORK OF THE OLD ONE IN CONIUNCTION WITH PACKAGE MEDIUM		3020.00	SR Technics Switzerland
609488	325-100-803-0	EASA,FAA,ANAC										
614157	9542M62P02	EASA,FAA,CAAC,ANAC	11	28	72-61-13	INLET GEARBOX & NO.3 BEARING - REAR INSULATION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		1050.00	SR Technics Switzerland
614157	9542M62P03	EASA,FAA,CAAC,ANAC										
614382	340-251-201-0	EASA,FAA,CAAC,ANAC	18	28	72-21-24	FAN AND BOOSTER - BOOSTER SPOOL COUNTERWEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		345.00	SR Technics Switzerland
614382	340-251-202-0	EASA,FAA,CAAC,ANAC										
618231	9725M81P02	EASA,FAA,CAAC,ANAC	4	28	72-61-15	CFM56 INLET GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		340.00	SR Technics Switzerland
618231	9972M39P01	EASA,FAA,CAAC,ANAC										
619936	336-031-901-0	EASA,FAA,CAAC,ANAC	28	28	72-56-07	LOW PRESSURE TURBINE REAR FRAME - FLANGE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		695.00	SR Technics Switzerland
619936	337-087-302-0	EASA,FAA,CAAC,ANAC			72-56-07		Package B	001	REPLACEMENT OF THE EQUIPMENT		925.00	SR Technics Switzerland
619936	338-171-801-0	EASA,FAA,CAAC,ANAC			72-56-07		Package C	002	REAR COVER, FILER WELDING OF CRACKS		3310.00	SR Technics Switzerland
619936	338-171-802-0	EASA,FAA,CAAC,ANAC			72-56-07		Package E	004	CONFIG.1 CIRCULAR STAMP ON THE FLANGE		440.00	SR Technics Switzerland
619936	338-171-902-0	EASA,FAA,CAAC,ANAC			72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.1	480.00	SR Technics Switzerland
619936	340-157-501-0	EASA,FAA,CAAC,ANAC			72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.2/3	480.00	SR Technics Switzerland
619936	340-157-502-0	EASA,FAA,CAAC,ANAC			72-56-07		Package G		REPAIR ILLEGIBLE PART IDENTIFICATION NUMBERS		175.00	SR Technics Switzerland
619936	340-165-601-0	EASA,FAA,CAAC,ANAC										
619936	340-168-802-0	EASA,FAA,CAAC,ANAC										
619936	340-168-803-0	EASA,FAA,CAAC,ANAC										
622278	337-004-103-0	EASA,FAA,CAAC,ANAC	29	28	72-00-63	ENGINE MODULES/ASSEMBLIES - ACCESSORY GEARBOX MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION	INCLUDING CONSERVATION	4560.00	SR Technics Switzerland
622278	337-004-104-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB01	72-0564	INTRODUCTION OF NEW AGB ASSY WITH NEW STARTER DRIVE PAD AND HANDCRANKING COVER AND REWORK OLD AGB		2580.00	SR Technics Switzerland
622278	337-004-105-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB02	72-0689	INTRODUCTION OF NEW AGB ASSY WITH NEW ROLLER BEARING AND REWORK OF OLD AGB ASSY TO THE NEW ONE		465.00	SR Technics Switzerland
622278	338-089-701-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB03	72-0927	DELETION OF BALL BEARING 335-304-401-0 ALTERNATIVE FOR HANDVRANKING LINE		2580.00	SR Technics Switzerland
622278	338-089-702-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB04	72-0965	TOOTH GEARSHAFT AND 41 TOOTH GEARSHAFT MANAGEMENT	AD EASA-2015-0133	465.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
622278	338-089-703-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB05	72-0879	INTRODUCTION OF A NEW ASSY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSY		7670.00	SR Technics Switzerland
622278	340-046-503-0	EASA,FAA,CAAC,ANAC			72-00-63		Package SB06	72-0617	REPETITIVE CLEANING OF CONTROL ALTERNATOR AND INSP. OF KEY LOCKED STUDS ATTACHING LINE NO.1 BEARING		1550.00	SR Technics Switzerland
622278	340-046-504-0	EASA,FAA,CAAC,ANAC										
622278	340-046-505-0	EASA,FAA,CAAC,ANAC										
622278	340-046-508-0	EASA,FAA,CAAC,JCAB,ANAC										
622278	340-046-509-0	EASA,FAA,CAAC,JCAB,ANAC										
622278	340-046-528-0	EASA,FAA,JCAB,ANAC										
622278	340-188-601-0	EASA,FAA,CAAC,ANAC										
622278	340-188-603-0	EASA,FAA,CAAC,ANAC										
624071	301-360-006-0	EASA,FAA,CAAC,ANAC	21	28	72-23-14	FAN FRAME ASSEMBLY - ACCESSORY DRIVE MOUNT LINK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
624071	301-360-020-0	EASA,FAA,CAAC,ANAC			72-23-14		Package K	010	REPLACEMENT OF SPHERICAL BEARING ONMOUNT LINKS	72-09-04	905.00	SR Technics Switzerland
624071	305-356-606-0	EASA,FAA,CAAC,ANAC										
624071	305-356-620-0	EASA,FAA,CAAC,ANAC										
624071	336-042-801-0	EASA,FAA,CAAC,ANAC										
624071	336-042-810-0	EASA,FAA,CAAC,ANAC										
624071	338-077-601-0	EASA,FAA,CAAC,ANAC										
624071	338-077-651-0	EASA,FAA,CAAC,ANAC										
624071	340-029-401-0	EASA,FAA,CAAC,ANAC										
624071	340-029-501-0	EASA,FAA,CAAC,ANAC										
624071	340-029-502-0	EASA,FAA,CAAC,ANAC										
624071	340-032-801-0	EASA,FAA,CAAC,ANAC										
624071	340-103-701-0	EASA,FAA,CAAC,ANAC										
624071	340-103-801-0	EASA,FAA,CAAC,ANAC										
624071	340-103-802-0	EASA,FAA,CAAC,ANAC										
624071	340-168-001-0	EASA,FAA,CAAC,ANAC										
624071	340-168-101-0	EASA,FAA,CAAC,ANAC										
624071	340-168-201-0	EASA,FAA,CAAC,ANAC										
624071	340-168-501-0	EASA,FAA,CAAC,ANAC										
624218	332A2341-2	EASA,FAA,ANAC	17	21	36-12-07	PRECOOLER INSTALLATION COMPONENTS - INLET ASSY-12 O'CLOCK STRUT	Package A	CLN/INSP	CLEANING AND INSPECTION		870.00	SR Technics Switzerland
624218	332A2371-1	EASA,FAA,CAAC,ANAC			36-12-07		Package B	2-1	REPLACE THE PARTS OF THE INLET ASSEMBLY		1220.00	SR Technics Switzerland
624218	332A2371-3	EASA,FAA,CAAC,ANAC			36-12-07		Package C	2-2	REPAIR AND REFINISH THE INLET CASTING		2270.00	SR Technics Switzerland
624218	332A2371-4	EASA,FAA,ANAC										
629621	1522M71P01	EASA,FAA,CAAC,ANAC	19	28	72-53-05	HPT SHROUD - MISCELLANEOUS	Package A	CLN/INSP	CLEANING AND INSPECTION		125.00	SR Technics Switzerland
629621	1667M72P01	EASA,FAA,CAAC,ANAC										
629938	1318M40G02	EASA,FAA,CAAC,ANAC	24	28	72-32-14	COMPRESSOR FRONT STATOR - VANE ACTUATOR TIE RODS	Package A	CLN/INSP	CLEANING AND INSPECTION		155.00	SR Technics Switzerland
629938	1318M40G03	EASA,FAA,CAAC,ANAC			72-32-14		Package B	001	INLET GUIDE VANE STAGE 1 AND STAGE 2 LINK SPHERICAL BEARING REPLACEMENT		315.00	SR Technics Switzerland
629938	1318M40G06	EASA,FAA,CAAC,ANAC			72-32-14		Package C	002	STAGE 3 LINK SPHERICAL BEARING REPLACEMENT		525.00	SR Technics Switzerland
629938	1318M41G02	EASA,FAA,CAAC,ANAC										
629938	1590M22P03	EASA,FAA,CAAC,ANAC										
629938	1590M22P04	EASA,FAA,CAAC,ANAC										
629938	1590M22P09	EASA,FAA,CAAC,ANAC										
629938	1590M33P01	EASA,FAA,CAAC,ANAC,CAA UK										
634090	1317M56G06	EASA,FAA,CAAC,ANAC	48	28	72-42-04	COMBUSTION CHAMBER (SAC) - OUTER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		920.00	SR Technics Switzerland
634090	1317M56G07	EASA,FAA,CAAC,ANAC			72-42-04		Package AA	026	APPL. OF THIN TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		3765.00	SR Technics Switzerland
634090	1317M56G08	EASA,FAA,CAAC,ANAC			72-42-04		Package AB	027	CRACK WELD/RESIZE REPAIR	+9 days TAT	6455.00	SR Technics Switzerland
634090	1317M56G09	EASA,FAA,CAAC,ANAC			72-42-04		Package AE	OS 255085	AIRFLOW TEST OF LARGE DIAMETER MULTI-HOLES ON OUTER LINER PANEL		2820.00	SR Technics Switzerland
634090	1317M56G10	EASA,FAA,CAAC,ANAC			72-42-04		Package C	002	REPAIR OF THE PLASMA SPRAY WEAR COATING ON THE COMBUSTION CHAMBER OUTER LINER SEAL		12250.00	SR Technics Switzerland
634090	1317M56G11	EASA,FAA,CAAC,ANAC			72-42-04		Package C	003	REMOVAL OF THE THERMAL BARRIER COATING		12250.00	SR Technics Switzerland
634090	1317M56G12	EASA,FAA,CAAC,ANAC			72-42-04		Package C	004	(THIN) APPLICATION OF THE THERMAL BARRIER COATING ON THE COMBUSTION CHAMBER OUTER LINER		12250.00	SR Technics Switzerland
634090	1317M56G13	EASA,FAA,CAAC,ANAC			72-42-04		Package C	005	REMOVAL OF THE COMBUSTION CHAMBER OUTER LINER LUG RING		12250.00	SR Technics Switzerland
634090	1317M56G14	EASA,FAA,ANAC			72-42-04		Package C	007	BOLT HOLE DRILLING REPAIR		12250.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634090	1968M44G02	EASA,FAA,CAAC,ANAC			72-42-04		Package C	008	WELD REPAIR AND RESIZING OF COMBUSTION CHAMBER OUTER LINERS THAT HAVE I718 LUG RINGS		12250.00	SR Technics Switzerland
634090	1968M44G03	EASA,FAA,CAAC,ANAC			72-42-04		Package C	009	IGNITER SLEEVE, IGNITER FERRULE RETAINER AND IGNITER FERRULE REPAIR/REPLACEMENT		12250.00	SR Technics Switzerland
634090	1968M44G04	EASA,FAA,CAAC,ANAC			72-42-04		Package C	016	(THICK) THERMAL BARRIER COATING REPLACEMENT		12250.00	SR Technics Switzerland
634090	1968M44G05	EASA,FAA,CAAC,ANAC			72-42-04		Package C	017	IGNITER PORT LOCALIZED SIZING REPAIR AND INSPECTION		12250.00	SR Technics Switzerland
634090	1968M44G06	EASA,FAA,CAAC,ANAC			72-42-04		Package C	020	WELD REPAIR AND RESIZING OF THE OUTER LINER WITHOUT LUG RING REMOVAL		12250.00	SR Technics Switzerland
634090	1968M44G08	EASA,FAA,CAAC,ANAC			72-42-04		Package F	012	WELDED PATCH REPAIR		2825.00	SR Technics Switzerland
634090	1968M44G09	EASA,FAA,ANAC			72-42-04		Package G	013	INCO 718 PLASMA SPRAY REPAIR OF THE LUG RING AFT SURFACE		2335.00	SR Technics Switzerland
634090	1968M45G03	EASA,FAA,CAAC,ANAC			72-42-04		Package I	015	AFT SEAL FLANGE WELD REPAIR		4210.00	SR Technics Switzerland
634090	1968M45G04	EASA,FAA,CAAC,ANAC			72-42-04		Package S	018	AFT SUPPORT RING REPLACEMENT		4395.00	SR Technics Switzerland
634090	1968M63G05	EASA,FAA,CAAC,ANAC			72-42-04		Package SB00	72-0521	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE C	360.00	SR Technics Switzerland
634090	1968M63G06	EASA,FAA,CAAC,ANAC			72-42-04		Package SB01	72-0647	COMBUSTION CHAMBER OUTER LINER REWORK	RECOATING WITH THICK THERMAL BARRIER	5370.00	SR Technics Switzerland
634090	1968M63G07	EASA,FAA,CAAC,ANAC			72-42-04		Package SB02	72-0229	INNER AND OUTER LINER THICKER TBC FIELD REWORK		2475.00	SR Technics Switzerland
634090	1968M63G08	EASA,FAA,CAAC,ANAC			72-42-04		Package SB04	72-0868	ALTERATION / THIN THERMAL BARRIER COATING APPLICATION		2560.00	SR Technics Switzerland
634090	1968M63G09	EASA,FAA,CAAC,ANAC			72-42-04		Package SB05	72-0817	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING P THICK TBC, +9 days TAT		9435.00	SR Technics Switzerland
634090	1968M63G11	EASA,FAA,CAAC,ANAC			72-42-04		Package SB06	72-0861	REWORK OF PRE-TECH INSERTION OUTER CC LINER WITH MULTI-HOLE COOLING P, +9 days TAT		3765.00	SR Technics Switzerland
634090	1968M63G12	EASA,FAA,CAAC,ANAC			72-42-04		Package SB07	72-0862	REWORK OF PRE-TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITHOUT IN CONJUNCTION WITH PACKAGE C		3765.00	SR Technics Switzerland
634090	1968M63G15	EASA,FAA,CAAC,ANAC			72-42-04		Package SB08	72-0817	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING P THIN TBC, +9 days TAT		9435.00	SR Technics Switzerland
634090	1968M63G16	EASA,FAA,CAAC,ANAC			72-42-04		Package SB09	72-1056	OUTER COMBUSTION CHAMBER LINER REMARKING		465.00	SR Technics Switzerland
634090	1968M63G19	EASA,FAA,CAAC,ANAC			72-42-04		Package SB10	72-0547	ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS	1317M56G09, 1317M57G02	465.00	SR Technics Switzerland
634090	2256M22G01	EASA,FAA,CAAC,ANAC			72-42-04		Package V	021	AFT SEAL FLANGE WELD REPAIR		6550.00	SR Technics Switzerland
634090	2256M22G02	EASA,FAA,CAAC,ANAC			72-42-04		Package X	023	INSTALLATION OF A LUG RING WITH HIGH TEMPERATURE BRAZE ALLOY		8315.00	SR Technics Switzerland
634090	2256M22G03	EASA,FAA,ANAC			72-42-04		Package Y	024	WELD PATCH REPAIR FOR THE TECH INSERTION OUTER LINER		2955.00	SR Technics Switzerland
634090	2256M22G04	EASA,FAA,CAAC,ANAC			72-42-04		Package Z	025	APPL. OF THICK TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		3765.00	SR Technics Switzerland
634090	2414M75G02	EASA,FAA,CAAC,ANAC										
634090	2414M75G03	EASA,FAA,CAAC,ANAC										
634090	2414M75G04	EASA,FAA,CAAC,ANAC										
634090	2414M75G06	EASA,FAA,CAAC,ANAC										
634090	2414M75G07	EASA,FAA,CAAC,ANAC										
634090	2414M75G08	EASA,FAA,CAAC,ANAC										
634090	2480M42G01	EASA,FAA,ANAC										
634090	2480M42G02	EASA,FAA,ANAC										
635513	336-092-208-0	EASA,FAA,CAAC,ANAC	17	28	72-00-56	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE REAR FRAME ASSEMBLY	Package A	INSP-001	CLEANING COXING SUPPL/SCAV. TUBES	PN340-035-901-0 FOR SHOP VISIT ONLY	240.00	SR Technics Switzerland
635513	338-071-401-0	EASA,FAA,CAAC,ANAC			72-00-56		Package C	SPEC-PROC	REPLACE THE TURBINE FRAM MODULE		2035.00	SR Technics Switzerland
635513	340-035-901-0	EASA,FAA,ANAC			72-00-56		Package SB00	72-0477	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		820.00	SR Technics Switzerland
635513	340-035-903-0	EASA,FAA,ANAC			72-00-56		Package SB01	EASA-2014-0130	TIME LIMITS - ENGINE STATIONARY PARTS - LIFE LIMITS		255.00	SR Technics Switzerland
635513	340-035-904-0	EASA,FAA,ANAC										
635513	340-035-905-0	EASA,FAA,ANAC										
635513	340-035-906-0	EASA,FAA,ANAC										
635513	340-035-907-0	EASA,FAA,ANAC										
635513	340-035-908-0	EASA,FAA,ANAC										
635520	1887M16G01	EASA,FAA,CAAC,ANAC	17	28	72-00-32	ENGINE MODULES/ASSEMBLIES - COMPRESSOR FRONT STATOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	PN9324M76G02 FOR SHOP VISIT ONLY	455.00	SR Technics Switzerland
635520	1887M16G02	EASA,FAA,CAAC,ANAC			72-00-32		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		815.00	SR Technics Switzerland
635520	9324M66G01	EASA,FAA,ANAC			72-00-32		Package M	ASSEMBLY	GRINDING STAGE 1-5 HONEYCOMBS		4570.00	SR Technics Switzerland
635520	9324M66G02	EASA,FAA,ANAC										
635520	9324M76G01	EASA,FAA,CAAC,ANAC										
635520	9324M76G02	EASA,FAA,CAAC,ANAC										
636432	338-071-301-0	EASA,FAA,CAAC,ANAC	3	28	72-00-55	CFM56 LPT SHAFT MINOR MODUL	Package A	CLN/INSP	CLEANING & INSPECTION		385.00	SR Technics Switzerland
636432	338-071-302-0	EASA,FAA,ANAC			72-00-55		Package B	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR		465.00	SR Technics Switzerland
636432	338-071-305-0	EASA,FAA,ANAC			72-00-55		Package K	010	RECONDITIONING OF SHAFT PAINT	72-00-03	305.00	SR Technics Switzerland
636432	338-071-306-0	EASA,FAA,ANAC			72-00-55		Package O	014	BLENDED ANTI-ROTATION-LUG	72-55-01	480.00	SR Technics Switzerland
636432	340-035-801-0	EASA,FAA,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
636432	340-035-804-0	EASA,FAA,CAAC,ANAC										
636432	340-035-805-0	EASA,FAA,CAAC,ANAC										
636616	338-118-004-0	EASA,FAA,CAAC,ANAC	4	28	72-54-07	CFM56 LPT CASE RING SECTOR SEGMENTS	Package A	CLN/INSP	CLEANING AND INSPECTION		390.00	SR Technics Switzerland
636616	338-118-104-0	EASA,FAA,CAAC,ANAC			72-54-07		Package B	025	CRACK REPAIR ON SHIELD SHROUD SECTOR		1015.00	SR Technics Switzerland
636616	338-118-204-0	EASA,FAA,CAAC,ANAC										
636616	338-118-304-0	EASA,FAA,CAAC,ANAC										
640894	1444M33G02	EASA,FAA,CAAC,ANAC	21	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	PN1969M83G01 340-021-801-0 FOR SHOP	315.00	SR Technics Switzerland
640894	1467M24G01	EASA,FAA,CAAC,ANAC			72-09-03		Package A	TEST	PRESSURE TEST		315.00	SR Technics Switzerland
640894	1605M78G03	EASA,FAA,CAAC,ANAC			72-09-03		Package B	001	BLENDING		225.00	SR Technics Switzerland
640894	1813M50G01	EASA,FAA,CAAC,ANAC			72-09-03		Package G	006	REFACE SPHERICAL SEATINGS		380.00	SR Technics Switzerland
640894	1817M21G02	EASA,FAA,CAAC,ANAC			72-09-03		Package H	007	REFACE INTERNAL SEATING FACE		380.00	SR Technics Switzerland
640894	1817M38G01	EASA,FAA,CAAC,ANAC			72-09-03		Package SB00	79-0017	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES	IN CONJUNCTION WITH PACKAGE A	135.00	SR Technics Switzerland
640894	1867M25G01	EASA,FAA,CAAC,ANAC			72-09-03		Package SB01	72-0333	INSPECTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY - WIRE HOLES		215.00	SR Technics Switzerland
640894	1867M50G01	EASA,FAA,CAAC,ANAC										
640894	1870M60G01	EASA,FAA,CAAC,ANAC										
640894	1882M92G01	EASA,FAA,CAAC,ANAC										
640894	1892M13G01	EASA,FAA,CAAC,ANAC										
640894	1895M76G01	EASA,FAA,CAAC,ANAC										
640894	1896M60G01	EASA,FAA,CAAC,ANAC										
640894	1958M29G01	EASA,FAA,CAAC,ANAC										
640894	1958M69G01	EASA,FAA,CAAC,ANAC										
640894	1958M71G01	EASA,FAA,CAAC,ANAC										
640894	1971M27G01	EASA,FAA,CAAC,ANAC										
640894	2283M19G01	EASA,FAA,CAAC,ANAC										
640894	2283M20G01	EASA,FAA,CAAC,ANAC										
640894	2283M26G01	EASA,FAA,CAAC,ANAC										
640894	305-872-701-0	EASA,FAA,CAAC,ANAC										
640894	335-104-308-0	EASA,FAA,CAAC,ANAC										
640894	335-104-309-0	EASA,FAA,CAAC,ANAC										
640894	336-098-601-0	EASA,FAA,CAAC,ANAC										
640894	337-153-101-0	EASA,FAA,CAAC,ANAC										
640894	337-153-901-0	EASA,FAA,CAAC,ANAC										
640894	337-153-903-0	EASA,FAA,CAAC,ANAC										
640894	338-012-403-0	EASA,FAA,CAAC,ANAC										
640894	338-025-104-0	EASA,FAA,CAAC,ANAC										
640894	338-047-802-0	EASA,FAA,CAAC,ANAC										
640894	338-049-602-0	EASA,FAA,CAAC,ANAC										
640894	338-049-802-0	EASA,FAA,CAAC,ANAC										
640894	338-052-602-0	EASA,FAA,CAAC,ANAC										
640894	338-059-901-0	EASA,FAA,CAAC,ANAC										
640894	338-106-602-0	EASA,FAA,CAAC,ANAC										
640894	338-106-603-0	EASA,FAA,CAAC,ANAC										
640894	340-005-103-0	EASA,FAA,CAAC,ANAC										
640894	340-010-201-0	EASA,FAA,CAAC,ANAC										
640894	340-010-801-0	EASA,FAA,CAAC,ANAC										
640894	340-011-402-0	EASA,FAA,CAAC,ANAC										
640894	340-134-002-0	EASA,FAA,CAAC,ANAC										
640894	340-134-052-0	EASA,FAA,CAAC,ANAC										
640894	340-177-801-0	EASA,FAA,CAAC,ANAC										
640894	340-178-001-0	EASA,FAA,CAAC,ANAC,CAA UK										
640894	649-430-000-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640894	649-430-030-0	EASA,FAA,CAAC,ANAC										
640894	649-430-070-0	EASA,FAA,CAAC,ANAC										
640894	649-430-073-0	EASA,FAA,CAAC,ANAC										
640894	649-430-212-0	EASA,FAA,CAAC,ANAC										
640894	649-430-242-0	EASA,FAA,CAAC,ANAC										
640894	649-433-150-0	EASA,FAA,CAAC,ANAC										
640894	649-433-253-0	EASA,FAA,CAAC,ANAC										
640894	649-433-404-0	EASA,FAA,CAAC,ANAC										
640894	649-434-030-0	EASA,FAA,CAAC,ANAC										
640894	649-434-093-0	EASA,FAA,CAAC,ANAC										
640894	649-434-095-0	EASA,FAA,CAAC,ANAC										
640894	649-434-220-0	EASA,FAA,ANAC										
640894	649-434-231-0	EASA,FAA,CAAC,ANAC										
640894	649-434-242-0	EASA,FAA,CAAC,ANAC										
640894	649-434-254-0	EASA,FAA,CAAC,ANAC										
640894	649-434-404-0	EASA,FAA,CAAC,ANAC										
640894	649-438-013-0	EASA,FAA,CAAC,ANAC										
640894	649-438-014-0	EASA,FAA,CAAC,ANAC										
640894	649-439-013-0	EASA,FAA,CAAC,ANAC										
640894	9393M48G01	EASA,FAA,CAAC,ANAC										
640894	J534P10	EASA,FAA,CAAC,ANAC										
640894	R287P06	EASA,FAA,ANAC										
640894	R287P08	EASA,FAA,ANAC										
640895	1324M91G01	EASA,FAA,CAAC,ANAC	28	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		315.00	SR Technics Switzerland
640895	1443M92G01	EASA,FAA,CAAC,ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		1135.00	SR Technics Switzerland
640895	1527M69G02	EASA,FAA,CAAC,ANAC			72-09-03		Package SB00	72-0333	INSPECTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY - WIRE HOLES		750.00	SR Technics Switzerland
640895	1605M38G02	EASA,FAA,CAAC,ANAC			72-09-03		Package SB01	72-0475	INTRO/RWK TUBE, BRACKET SAFETY WIRE HOLE		480.00	SR Technics Switzerland
640895	1605M94G01	EASA,FAA,CAAC,ANAC										
640895	1621M50G01	EASA,FAA,CAAC,ANAC										
640895	1645M19G01	EASA,FAA,CAAC,ANAC										
640895	1645M43G02	EASA,FAA,CAAC,ANAC										
640895	1677M61G01	EASA,FAA,CAAC,ANAC										
640895	1787M42G02	EASA,FAA,CAAC,ANAC										
640895	1788M44G01	EASA,FAA,CAAC,ANAC										
640895	1813M94G01	EASA,FAA,CAAC,ANAC										
640895	1817M21G01	EASA,FAA,CAAC,ANAC										
640895	1817M35G01	EASA,FAA,CAAC,ANAC										
640895	1867M38G01	EASA,FAA,CAAC,ANAC										
640895	1867M57G01	EASA,FAA,CAAC,ANAC										
640895	1867M69G01	EASA,FAA,CAAC,ANAC										
640895	1869M33G01	EASA,FAA,CAAC,ANAC										
640895	1870M53G01	EASA,FAA,CAAC,ANAC										
640895	1870M61G01	EASA,FAA,CAAC,ANAC										
640895	1870M97G01	EASA,FAA,CAAC,ANAC										
640895	1871M15G01	EASA,FAA,CAAC,ANAC										
640895	1871M35G01	EASA,FAA,CAAC,ANAC										
640895	1882M86G01	EASA,FAA,CAAC,ANAC										
640895	1892M61G01	EASA,FAA,CAAC,ANAC										
640895	1892M62G01	EASA,FAA,CAAC,ANAC										
640895	1892M80G01	EASA,FAA,CAAC,ANAC										
640895	1896M46G01	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	1896M47G01	EASA,FAA,CAAC,ANAC										
640895	1898M42G01	EASA,FAA,CAAC,ANAC										
640895	1898M58G01	EASA,FAA,CAAC,ANAC										
640895	1958M58G01	EASA,FAA,CAAC,ANAC										
640895	1970M21G01	EASA,FAA,CAAC,ANAC										
640895	1970M89G01	EASA,FAA,CAAC,ANAC										
640895	1971M28G01	EASA,FAA,CAAC,ANAC										
640895	1971M49G01	EASA,FAA,CAAC,ANAC										
640895	1971M74G01	EASA,FAA,CAAC,ANAC										
640895	2046M13G01	EASA,FAA,CAAC,ANAC										
640895	2046M41G01	EASA,FAA,CAAC,ANAC										
640895	2283M22G01	EASA,FAA,CAAC,ANAC										
640895	2283M23G01	EASA,FAA,CAAC,ANAC										
640895	2283M38G01	EASA,FAA,CAAC,TCCA										
640895	2497M71G01	EASA,FAA,ANAC										
640895	305-397-001-0	EASA,FAA,CAAC,ANAC										
640895	336-451-005-0	EASA,FAA,CAAC,ANAC										
640895	336-451-205-0	EASA,FAA,CAAC,ANAC										
640895	336-455-405-0	EASA,FAA,CAAC,ANAC										
640895	336-457-407-0	EASA,FAA,CAAC,ANAC										
640895	336-457-606-0	EASA,FAA,CAAC,ANAC										
640895	336-489-402-0	EASA,FAA,CAAC,ANAC										
640895	336-489-604-0	EASA,FAA,CAAC,ANAC										
640895	337-026-804-0	EASA,FAA,CAAC,ANAC										
640895	337-027-203-0	EASA,FAA,CAAC,ANAC										
640895	337-029-705-0	EASA,FAA,CAAC,ANAC										
640895	337-029-902-0	EASA,FAA,CAAC,ANAC										
640895	337-152-702-0	EASA,FAA,CAAC,ANAC										
640895	337-153-503-0	EASA,FAA,CAAC,ANAC										
640895	337-154-101-0	EASA,FAA,CAAC,ANAC										
640895	338-011-706-0	EASA,FAA,CAAC,ANAC										
640895	338-011-809-0	EASA,FAA,CAAC,ANAC										
640895	338-011-908-0	EASA,FAA,CAAC,ANAC										
640895	338-012-006-0	EASA,FAA,CAAC,ANAC										
640895	338-023-402-0	EASA,FAA,CAAC,ANAC										
640895	338-023-603-0	EASA,FAA,CAAC,ANAC										
640895	338-023-803-0	EASA,FAA,CAAC,ANAC										
640895	338-026-403-0	EASA,FAA,CAAC,ANAC										
640895	338-026-607-0	EASA,FAA,CAAC,ANAC										
640895	338-029-204-0	EASA,FAA,CAAC,ANAC										
640895	338-029-407-0	EASA,FAA,CAAC,ANAC										
640895	338-047-204-0	EASA,FAA,CAAC,ANAC										
640895	338-047-402-0	EASA,FAA,CAAC,ANAC										
640895	338-048-002-0	EASA,FAA,CAAC,ANAC										
640895	338-048-204-0	EASA,FAA,CAAC,ANAC										
640895	338-048-403-0	EASA,FAA,CAAC,ANAC										
640895	338-048-604-0	EASA,FAA,CAAC,ANAC										
640895	338-048-802-0	EASA,FAA,CAAC,ANAC										
640895	338-052-202-0	EASA,FAA,CAAC,ANAC										
640895	338-052-203-0	EASA,FAA,CAAC,ANAC										
640895	338-052-802-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	338-052-803-0	EASA,FAA,CAAC,ANAC										
640895	338-053-002-0	EASA,FAA,CAAC,ANAC										
640895	338-056-502-0	EASA,FAA,CAAC,ANAC										
640895	338-057-601-0	EASA,FAA,ANAC										
640895	338-057-651-0	EASA,FAA,CAAC,ANAC										
640895	338-057-701-0	EASA,FAA,CAAC,ANAC										
640895	338-057-751-0	EASA,FAA,CAAC,ANAC										
640895	338-057-753-0	EASA,FAA,CAAC,ANAC										
640895	338-059-951-0	EASA,FAA,CAAC,ANAC										
640895	338-125-003-0	EASA,FAA,CAAC,ANAC										
640895	338-126-004-0	EASA,FAA,CAAC,ANAC										
640895	338-126-103-0	EASA,FAA,CAAC,ANAC										
640895	338-126-153-0	EASA,FAA,CAAC,ANAC										
640895	338-129-101-0	EASA,FAA,CAAC,ANAC										
640895	338-129-251-0	EASA,FAA,CAAC,ANAC										
640895	338-130-801-0	EASA,FAA,CAAC,ANAC										
640895	340-005-104-0	EASA,FAA,CAAC,ANAC										
640895	340-005-105-0	EASA,FAA,CAAC,ANAC										
640895	340-006-103-0	EASA,FAA,CAAC,ANAC										
640895	340-007-005-0	EASA,FAA,CAAC,ANAC										
640895	340-007-102-0	EASA,FAA,CAAC,ANAC										
640895	340-007-203-0	EASA,FAA,CAAC,ANAC										
640895	340-008-504-0	EASA,FAA,CAAC,ANAC										
640895	340-009-303-0	EASA,FAA,CAAC,ANAC										
640895	340-010-401-0	EASA,FAA,CAAC,ANAC										
640895	340-010-402-0	EASA,FAA,CAAC,ANAC										
640895	340-010-603-0	EASA,FAA,CAAC,ANAC										
640895	340-011-001-0	EASA,FAA,CAAC,ANAC										
640895	340-011-202-0	EASA,FAA,CAAC,ANAC										
640895	340-011-601-0	EASA,FAA,CAAC,ANAC										
640895	340-011-804-0	EASA,FAA,CAAC,ANAC										
640895	340-012-402-0	EASA,FAA,CAAC,ANAC										
640895	340-014-203-0	EASA,FAA,CAAC,ANAC										
640895	340-014-406-0	EASA,FAA,CAAC,ANAC										
640895	340-014-602-0	EASA,FAA,CAAC,ANAC										
640895	340-015-103-0	EASA,FAA,CAAC,ANAC										
640895	340-016-101-0	EASA,FAA,CAAC,ANAC										
640895	340-016-151-0	EASA,FAA,CAAC,ANAC										
640895	340-016-201-0	EASA,FAA,CAAC,ANAC										
640895	340-016-251-0	EASA,FAA,CAAC,ANAC										
640895	340-016-452-0	EASA,FAA,CAAC,ANAC										
640895	340-016-602-0	EASA,FAA,CAAC,ANAC										
640895	340-016-652-0	EASA,FAA,CAAC,ANAC										
640895	340-016-701-0	EASA,FAA,CAAC,ANAC										
640895	340-016-751-0	EASA,FAA,CAAC,ANAC										
640895	340-018-103-0	EASA,FAA,CAAC,ANAC										
640895	340-021-002-0	EASA,FAA,CAAC,ANAC										
640895	340-021-003-0	EASA,FAA,CAAC,ANAC										
640895	340-021-802-0	EASA,FAA,CAAC,ANAC										
640895	340-021-803-0	EASA,FAA,CAAC,ANAC										
640895	340-021-852-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	340-021-853-0	EASA,FAA,CAAC,ANAC										
640895	340-022-003-0	EASA,FAA,CAAC,ANAC										
640895	340-022-201-0	EASA,FAA,CAAC,ANAC										
640895	340-023-507-0	EASA,FAA,CAAC,ANAC										
640895	340-088-803-0	EASA,FAA,CAAC,ANAC										
640895	340-138-401-0	EASA,FAA,CAAC,ANAC										
640895	340-138-901-0	EASA,FAA,CAAC,ANAC										
640895	340-138-951-0	EASA,FAA,CAAC,ANAC										
640895	340-8801-515	EASA,FAA,CAAC,ANAC										
640895	649-430-004-0	EASA,FAA,CAAC,ANAC										
640895	649-430-006-0	EASA,FAA,ANAC										
640895	649-430-036-0	EASA,FAA,ANAC										
640895	649-430-069-0	EASA,FAA,CAAC,ANAC										
640895	649-430-201-0	EASA,FAA,CAAC,ANAC										
640895	649-430-203-0	EASA,FAA,CAAC,ANAC										
640895	649-430-219-0	EASA,FAA,CAAC,ANAC										
640895	649-430-233-0	EASA,FAA,CAAC,ANAC										
640895	649-433-030-0	EASA,FAA,CAAC,ANAC										
640895	649-433-034-0	EASA,FAA,CAAC,ANAC										
640895	649-433-036-0	EASA,FAA,CAAC,ANAC										
640895	649-433-047-0	EASA,FAA,CAAC,ANAC										
640895	649-433-051-0	EASA,FAA,CAAC,ANAC										
640895	649-433-086-0	EASA,FAA,CAAC,ANAC										
640895	649-433-087-0	EASA,FAA,CAAC,ANAC										
640895	649-433-093-0	EASA,FAA,CAAC,ANAC										
640895	649-433-094-0	EASA,FAA,CAAC,ANAC										
640895	649-433-095-0	EASA,FAA,CAAC,ANAC										
640895	649-433-147-0	EASA,FAA,CAAC,ANAC										
640895	649-433-219-0	EASA,FAA,CAAC,ANAC										
640895	649-433-220-0	EASA,FAA,ANAC										
640895	649-433-231-0	EASA,FAA,CAAC,ANAC										
640895	649-433-233-0	EASA,FAA,CAAC,ANAC										
640895	649-433-254-0	EASA,FAA,CAAC,ANAC										
640895	649-434-034-0	EASA,FAA,CAAC,ANAC										
640895	649-434-036-0	EASA,FAA,CAAC,ANAC										
640895	649-434-087-0	EASA,FAA,CAAC,ANAC										
640895	649-434-091-0	EASA,FAA,CAAC,ANAC										
640895	649-434-094-0	EASA,FAA,CAAC,ANAC										
640895	649-434-147-0	EASA,FAA,CAAC,ANAC										
640895	649-434-219-0	EASA,FAA,CAAC,ANAC										
640895	649-434-233-0	EASA,FAA,CAAC,ANAC										
640895	649-434-251-0	EASA,FAA,CAAC,ANAC										
640895	649-434-253-0	EASA,FAA,CAAC,ANAC										
640895	649-438-000-0	EASA,FAA,CAAC,ANAC										
640895	649-438-002-0	EASA,FAA,CAAC,ANAC										
640895	649-438-004-0	EASA,FAA,CAAC,ANAC										
640895	649-438-005-0	EASA,FAA,CAAC,ANAC										
640895	649-438-011-0	EASA,FAA,CAAC,ANAC										
640895	649-438-012-0	EASA,FAA,CAAC,ANAC										
640895	649-438-101-0	EASA,FAA,CAAC,ANAC										
640895	649-438-102-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2024



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	649-438-200-0	EASA,FAA,CAAC,ANAC										
640895	649-438-201-0	EASA,FAA,CAAC,ANAC										
640895	649-439-005-0	EASA,FAA,CAAC,ANAC										
640895	649-439-012-0	EASA,FAA,CAAC,ANAC										
640895	649-439-102-0	EASA,FAA,CAAC,ANAC										
640895	649-439-200-0	EASA,FAA,CAAC,ANAC										
640895	9393M42G03	EASA,FAA,CAAC,ANAC										
640895	9393M46G08	EASA,FAA,CAAC,ANAC										
640896	1605M10G02	EASA,FAA,CAAC,ANAC	32	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		315.00	SR Technics Switzerland
640896	1605M63G01	EASA,FAA,CAAC,ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		2095.00	SR Technics Switzerland
640896	1645M11G01	EASA,FAA,CAAC,ANAC										
640896	1645M31G03	EASA,FAA,CAAC,ANAC										
640896	1677M12G02	EASA,FAA,CAAC,ANAC										
640896	1677M20G01	EASA,FAA,CAAC,ANAC										
640896	1677M89G01	EASA,FAA,CAAC,ANAC										
640896	1677M91G01	EASA,FAA,CAAC,ANAC										
640896	1788M40G01	EASA,FAA,CAAC,ANAC										
640896	1813M24G01	EASA,FAA,CAAC,ANAC										
640896	1813M96G01	EASA,FAA,CAAC,ANAC										
640896	1817M52G01	EASA,FAA,CAAC,ANAC										
640896	1817M66G01	EASA,FAA,CAAC,ANAC										
640896	1867M39G01	EASA,FAA,CAAC,ANAC										
640896	1867M67G01	EASA,FAA,CAAC,ANAC										
640896	1870M24G01	EASA,FAA,CAAC,ANAC										
640896	1870M28G01	EASA,FAA,CAAC,ANAC										
640896	1870M45G01	EASA,FAA,CAAC,ANAC										
640896	1870M46G01	EASA,FAA,CAAC,ANAC										
640896	1870M57G01	EASA,FAA,CAAC,ANAC										
640896	1870M70G01	EASA,FAA,CAAC,ANAC										
640896	1870M71G01	EASA,FAA,CAAC,ANAC										
640896	1870M72G01	EASA,FAA,CAAC,ANAC										
640896	1870M73G01	EASA,FAA,CAAC,ANAC										
640896	1870M75G01	EASA,FAA,CAAC,ANAC										
640896	1882M68G01	EASA,FAA,CAAC,ANAC										
640896	1882M70G01	EASA,FAA,CAAC,ANAC										
640896	1882M72G01	EASA,FAA,CAAC,ANAC										
640896	1882M74G01	EASA,FAA,CAAC,ANAC										
640896	1892M16G01	EASA,FAA,CAAC,ANAC										
640896	1892M18G01	EASA,FAA,CAAC,ANAC										
640896	1892M47G01	EASA,FAA,CAAC,ANAC										
640896	1892M89G01	EASA,FAA,CAAC,ANAC										
640896	1895M58G01	EASA,FAA,CAAC,ANAC										
640896	1897M24G01	EASA,FAA,CAAC,ANAC										
640896	1897M68G01	EASA,FAA,CAAC,ANAC										
640896	1897M72G01	EASA,FAA,CAAC,ANAC										
640896	1897M74G01	EASA,FAA,CAAC,ANAC										
640896	1897M76G01	EASA,FAA,CAAC,ANAC										
640896	1898M13G01	EASA,FAA,CAAC,ANAC										
640896	1958M57G01	EASA,FAA,CAAC,ANAC										
640896	1971M75G01	EASA,FAA,CAAC,ANAC										
640896	2046M11G01	EASA,FAA,CAAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640896	2046M12G01	EASA,FAA,CAAC,ANAC										
640896	2046M16G01	EASA,FAA,ANAC										
640896	2046M30G01	EASA,FAA,CAAC,ANAC										
640896	2046M59G01	EASA,FAA,CAAC,ANAC										
640896	2046M71G01	EASA,FAA,CAAC,ANAC										
640896	2046M77G01	EASA,FAA,CAAC,ANAC										
640896	2283M24G01	EASA,FAA,CAAC,ANAC										
640896	2557M32G01	EASA,FAA,CAAC,ANAC										
640896	336-401-402-0	EASA,FAA,CAAC,ANAC										
640896	336-401-403-0	EASA,FAA,CAAC,ANAC										
640896	336-493-204-0	EASA,FAA,CAAC,ANAC										
640896	337-153-702-0	EASA,FAA,CAAC,ANAC										
640896	338-012-104-0	EASA,FAA,CAAC,ANAC										
640896	338-012-206-0	EASA,FAA,CAAC,ANAC										
640896	338-015-604-0	EASA,FAA,CAAC,ANAC										
640896	338-015-803-0	EASA,FAA,CAAC,ANAC										
640896	338-019-505-0	EASA,FAA,CAAC,JCAB,ANAC										
640896	338-019-703-0	EASA,FAA,CAAC,ANAC										
640896	338-024-004-0	EASA,FAA,CAAC,ANAC										
640896	338-037-202-0	EASA,FAA,CAAC,ANAC										
640896	338-039-603-0	EASA,FAA,CAAC,ANAC										
640896	338-047-002-0	EASA,FAA,CAAC,ANAC										
640896	338-128-501-0	EASA,FAA,CAAC,ANAC										
640896	340-006-004-0	EASA,FAA,CAAC,ANAC										
640896	340-006-005-0	EASA,FAA,CAAC,ANAC										
640896	340-006-104-0	EASA,FAA,CAAC,ANAC										
640896	340-009-202-0	EASA,FAA,CAAC,ANAC										
640896	340-009-401-0	EASA,FAA,CAAC,ANAC										
640896	340-012-802-0	EASA,FAA,CAAC,ANAC										
640896	340-014-007-0	EASA,FAA,CAAC,ANAC										
640896	340-015-801-0	EASA,FAA,CAAC,ANAC										
640896	340-015-852-0	EASA,FAA,CAAC,ANAC										
640896	340-015-906-0	EASA,FAA,CAAC,ANAC										
640896	340-015-956-0	EASA,FAA,CAAC,ANAC										
640896	340-016-002-0	EASA,FAA,CAAC,ANAC										
640896	340-016-003-0	EASA,FAA,CAAC,ANAC										
640896	340-016-052-0	EASA,FAA,CAAC,ANAC										
640896	340-016-053-0	EASA,FAA,CAAC,ANAC										
640896	340-016-802-0	EASA,FAA,CAAC,ANAC										
640896	340-016-852-0	EASA,FAA,CAAC,ANAC										
640896	340-020-501-0	EASA,FAA,CAAC,ANAC										
640896	340-020-502-0	EASA,FAA,CAAC,ANAC										
640896	340-130-401-0	EASA,FAA,CAAC,ANAC										
640896	642-9848-501	EASA,FAA,CAAC,ANAC										
640896	649-430-071-0	EASA,FAA,ANAC										
640896	649-433-091-0	EASA,FAA,CAAC,ANAC										
640896	649-433-146-0	EASA,FAA,CAAC,ANAC										
640896	649-433-242-0	EASA,FAA,CAAC,ANAC										
640896	649-434-252-0	EASA,FAA,CAAC,ANAC										
640897	1645M25G03	EASA,FAA,CAAC,ANAC	31	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		305.00	SR Technics Switzerland
640897	1677M55G01	EASA,FAA,CAAC,ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		4760.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640897	1716M87G01	EASA,FAA,CAAC,ANAC			72-09-03		Package SB00	73-0047	INTRO LOWER DRAIN MANIFOLD & ID PLATE		465.00	SR Technics Switzerland
640897	1788M85G03	EASA,FAA,CAAC,ANAC			72-09-03		Package T		REPLACE OF RIVETED PARTS DRAIN MANIFOLD		175.00	SR Technics Switzerland
640897	1813M52G01	EASA,FAA,CAAC,ANAC			72-09-03		Package U		RE-ETCH PART NUMBER		135.00	SR Technics Switzerland
640897	1813M60G01	EASA,FAA,CAAC,ANAC										
640897	1817M67G01	EASA,FAA,CAAC,ANAC										
640897	1867M43G01	EASA,FAA,CAAC,ANAC										
640897	1867M71G01	EASA,FAA,CAAC,ANAC										
640897	1869M45G01	EASA,FAA,CAAC,ANAC										
640897	1870M27G01	EASA,FAA,CAAC,ANAC										
640897	1870M44G01	EASA,FAA,CAAC,ANAC										
640897	1870M86G01	EASA,FAA,CAAC,ANAC										
640897	1870M90G01	EASA,FAA,CAAC,ANAC										
640897	1870M98G01	EASA,FAA,CAAC,ANAC										
640897	1871M46G01	EASA,FAA,CAAC,ANAC										
640897	1882M76G01	EASA,FAA,CAAC,ANAC										
640897	1882M94G01	EASA,FAA,CAAC,ANAC										
640897	1888M49G01	EASA,FAA,CAAC,ANAC										
640897	1888M52G01	EASA,FAA,CAAC,ANAC										
640897	1895M60G01	EASA,FAA,CAAC,ANAC										
640897	1895M65G01	EASA,FAA,ANAC										
640897	1896M69G01	EASA,FAA,CAAC,ANAC										
640897	1897M39G01	EASA,FAA,CAAC,ANAC										
640897	1897M51G01	EASA,FAA,CAAC,ANAC										
640897	1897M69G01	EASA,FAA,CAAC,ANAC										
640897	1898M20G01	EASA,FAA,CAAC,ANAC										
640897	1898M35G01	EASA,FAA,CAAC,ANAC										
640897	1898M38G01	EASA,FAA,CAAC,ANAC										
640897	1958M70G01	EASA,FAA,CAAC,ANAC										
640897	1970M36G01	EASA,FAA,CAAC,ANAC										
640897	1971M90G01	EASA,FAA,CAAC,ANAC										
640897	2046M55G01	EASA,FAA,CAAC,ANAC										
640897	2046M79G01	EASA,FAA,CAAC,ANAC										
640897	2174M16G01	EASA,FAA,CAAC,ANAC										
640897	2174M17G01	EASA,FAA,CAAC,ANAC										
640897	2174M18G01	EASA,FAA,ANAC										
640897	2174M19G01	EASA,FAA,CAAC,ANAC										
640897	2175M39G01	EASA,FAA,CAAC,ANAC										
640897	2175M40G01	EASA,FAA,CAAC,ANAC										
640897	2175M41G01	EASA,FAA,CAAC,ANAC										
640897	2175M42G01	EASA,FAA,CAAC,ANAC										
640897	2175M45G01	EASA,FAA,ANAC										
640897	2175M48G01	EASA,FAA,CAAC,ANAC										
640897	2480M87G01	EASA,FAA,CAAC,ANAC										
640897	2497M63G01	EASA,FAA,CAAC,ANAC										
640897	2497M70G01	EASA,FAA,ANAC										
640897	336-462-002-0	EASA,FAA,CAAC,ANAC										
640897	336-462-003-0	EASA,FAA,CAAC,ANAC										
640897	336-462-051-0	EASA,FAA,CAAC,ANAC										
640897	336-462-052-0	EASA,FAA,CAAC,ANAC										
640897	336-462-071-0	EASA,FAA,CAAC,ANAC										
640897	338-025-003-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640897	338-166-604-0	EASA,FAA,CAAC,ANAC										
640897	338-166-804-0	EASA,FAA,CAAC,ANAC										
640897	338-166-904-0	EASA,FAA,CAAC,ANAC										
640897	338-169-302-0	EASA,FAA,CAAC,ANAC										
640897	340-105-302-0	EASA,FAA,CAAC,ANAC										
640897	340-105-352-0	EASA,FAA,CAAC,ANAC										
640897	649-431-650-0	EASA,FAA,CAAC,ANAC										
640897	649-433-251-0	EASA,FAA,CAAC,ANAC										
640897	649-433-252-0	EASA,FAA,CAAC,ANAC										
640897	649-433-330-0	EASA,FAA,CAAC,ANAC										
640897	649-434-330-0	EASA,FAA,CAAC,ANAC										
640897	649-438-302-0	EASA,FAA,CAAC,ANAC										
640950	305-364-002-0	EASA,FAA,CAAC,ANAC	16	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARING NO	Package A	CLN/INSP	CLEANING AND INSPECTION		995.00	SR Technics Switzerland
640950	305-364-103-0	EASA,FAA,CAAC,ANAC										
640950	337-108-201-0	EASA,FAA,CAAC,ANAC										
640950	340-257-001-0	EASA,FAA,CAAC,ANAC										
640951	305-365-702-0	EASA,FAA,CAAC,ANAC	15	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARING NO	Package A	CLN/INSP	CLEANING AND INSPECTION		995.00	SR Technics Switzerland
640951	305-365-704-0	EASA,FAA,CAAC,ANAC										
640951	305-366-203-0	EASA,FAA,CAAC,ANAC										
640951	305-366-204-0	EASA,FAA,CAAC,ANAC										
640951	337-010-702-0	EASA,FAA,CAAC,ANAC										
640951	337-010-703-0	EASA,FAA,CAAC,ANAC										
640951	337-010-761-0	EASA,FAA,CAAC,ANAC										
640951	337-108-301-0	EASA,FAA,CAAC,ANAC										
640951	337-108-302-0	EASA,FAA,CAAC,ANAC										
640951	337-108-351-0	EASA,FAA,CAAC,ANAC										
640951	337-205-401-0	EASA,FAA,CAAC,ANAC										
640951	337-205-501-0	EASA,FAA,CAAC,ANAC										
640951	337-205-601-0	EASA,FAA,CAAC,ANAC										
640951	340-257-101-0	EASA,FAA,CAAC,ANAC										
640952	1361M71P02	EASA,FAA,CAAC,ANAC	16	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARING NO	Package A	CLN/INSP	CLEANING AND INSPECTION		1000.00	SR Technics Switzerland
640952	1361M71P05	EASA,FAA,CAAC,ANAC			72-09-01		Package SB02	EASA-2020-004	SB 72-1054-001		480.00	SR Technics Switzerland
640952	1364M91P01	EASA,FAA,CAAC,ANAC			72-09-01		Package SB02	FAA 2021-10-0	SB 72-1054-001		480.00	SR Technics Switzerland
640952	1364M91P02	EASA,FAA,CAAC,ANAC										
640952	1364M91P05	EASA,FAA,CAAC,ANAC										
640952	1460M51P05	EASA,FAA,CAAC,ANAC										
640952	1460M52P01	EASA,FAA,CAAC,ANAC										
640952	1460M52P03	EASA,FAA,CAAC,ANAC										
640952	1460M52P05	EASA,FAA,CAAC,ANAC										
640952	1665M98P02	EASA,FAA,CAAC,ANAC										
640952	2124M95P01	EASA,FAA,CAAC,ANAC										
640952	2124M95P02	EASA,FAA,CAAC,ANAC										
640952	2411M39P01	EASA,FAA,CAAC,ANAC										
640952	2411M39P02	EASA,FAA,ANAC										
640952	9542M61P03	EASA,FAA,CAAC,ANAC										
640953	305-351-905-0	EASA,FAA,CAAC,ANAC	16	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARING NO	Package A	CLN/INSP	CLEANING AND INSPECTION		1220.00	SR Technics Switzerland
640953	305-352-004-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB00	72-0382	NEW/RWK NO.5 BRG (OUTER RACE MODI)		465.00	SR Technics Switzerland
640953	337-108-401-0	EASA,FAA,CAAC,ANAC										
640953	337-220-301-0	EASA,FAA,CAAC,ANAC										
640953	337-220-351-0	EASA,FAA,CAAC,ANAC										
640953	340-252-801-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640953	340-252-802-0	EASA,FAA,CAAC,ANAC										
640953	340-252-901-0	EASA,FAA,CAAC,ANAC										
640953	340-252-902-0	EASA,FAA,CAAC,ANAC										
640953	340-253-001-0	EASA,FAA,CAAC,ANAC										
640953	340-253-002-0	EASA,FAA,CAAC,ANAC										
640953	340-257-201-0	EASA,FAA,CAAC,ANAC										
640954	305-355-717-0	EASA,FAA,CAAC,ANAC	18	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARINGS - BEARING NO	Package A	CLN/INSP	CLEANING AND INSPECTION		1125.00	SR Technics Switzerland
640954	305-355-718-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB01	72-0192	REPL. OF NO.4 ROLLER BEARING 335-352-301-0		255.00	SR Technics Switzerland
640954	305-355-720-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB02	72-A0392	RED. INTERVAL EL MASTER CHIP DETEC. INSP		255.00	SR Technics Switzerland
640954	335-352-301-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB07	72-0207	RETURN No.4 BRG 335-352-301-0 TO CFMI		255.00	SR Technics Switzerland
640954	335-352-302-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB08	72-0400	BRG NO. 4, INTR OUTER RACE (MAT 32CDV13)		255.00	SR Technics Switzerland
640954	335-352-303-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB09	72-0395	REPL OF NO.4 ROLLER BRG PN 340-167-901-0		255.00	SR Technics Switzerland
640954	335-352-304-0	EASA,FAA,CAAC,ANAC			72-09-01		Package SB11	72-0685	BRG NO.4, DELETION OF P/N'S 717/-302/-901-0		255.00	SR Technics Switzerland
640954	335-352-305-0	EASA,FAA,CAAC,ANAC										
640954	340-167-901-0	EASA,FAA,CAAC,ANAC										
640954	340-167-902-0	EASA,FAA,CAAC,ANAC										
640954	340-167-904-0	EASA,FAA,CAAC,ANAC										
640954	340-167-906-0	EASA,FAA,CAAC,ANAC										
641535	1523M41G02	EASA,FAA,CAAC,ANAC	26	28	72-51-07	HIGH PRESSURE TURBINE NOZZLE - FWD INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1565.00	SR Technics Switzerland
641535	1668M61G01	EASA,FAA,CAAC,ANAC			72-51-07		Package C	2	HONEYCOMB REPAIR		9470.00	SR Technics Switzerland
641535	1668M61G03	EASA,FAA,CAAC,ANAC			72-51-07		Package E	4	REPAIR THE DIMENSIONS OF THE AFT FLANGE AND INDUCER DIAMETER SEAL SURFACE		3430.00	SR Technics Switzerland
641535	1668M61G05	EASA,FAA,CAAC,ANAC			72-51-07		Package H	7	DIMENSIONAL RESTORATION OF DIAMETER B		2505.00	SR Technics Switzerland
641535	1808M15G01	EASA,FAA,CAAC,ANAC			72-51-07		Package M	12	CHROME CARBIDE EROSION COATING REPAIR		2505.00	SR Technics Switzerland
641535	1808M15G03	EASA,FAA,CAAC,ANAC			72-51-07		Package O	14	REMOVAL OF A CRACKED AIR DEFLECTOR		1020.00	SR Technics Switzerland
641535	1808M15G04	EASA,FAA,CAAC,ANAC			72-51-07		Package R	17	REPAIR OF CRACKS ON THE CAST INDUCER AFT SURFACE		2865.00	SR Technics Switzerland
641535	1808M15G05	EASA,FAA,CAAC,ANAC			72-51-07		Package SB01	72-0556	WITH IMPROVED EROSION COATING		2405.00	SR Technics Switzerland
641535	1808M15G06	EASA,FAA,CAAC,ANAC			72-51-07		Package SB03	72-0940	FORWARD INNER NOZZLE SUPPORT REWORK	2131M81G06	9470.00	SR Technics Switzerland
641535	1808M15G08	EASA,FAA,CAAC,ANAC										
641535	1808M15G12	EASA,FAA,CAAC,ANAC										
641535	1808M15G13	EASA,FAA,CAAC,ANAC										
641535	1808M15G16	EASA,FAA,CAAC,ANAC										
641535	1873M94G05	EASA,FAA,CAAC,ANAC										
641535	1893M96G02	EASA,FAA,ANAC										
641535	2071M27G02	EASA,FAA,CAAC,ANAC										
641535	2071M28G01	EASA,FAA,CAAC,ANAC										
641535	2071M28G02	EASA,FAA,CAAC,ANAC										
641535	2071M28G04	EASA,FAA,CAAC,ANAC										
641535	2071M28G05	EASA,FAA,CAAC,ANAC										
641535	2071M28G07	EASA,FAA,CAAC,ANAC										
641535	2071M28G10	EASA,FAA,CAAC,ANAC										
641535	2131M81G05	EASA,FAA,CAAC,ANAC										
641535	2131M81G06	EASA,FAA,CAAC,ANAC										
641535	2131M82G01	EASA,FAA,CAAC,ANAC										
642820	1498M52G03	EASA,FAA,CAAC,ANAC	28	28	72-41-01	COMBUSTION CASE - ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	PN1784M91G02 FOR SHOP VISIT ONLY	4395.00	SR Technics Switzerland
642820	1498M52G05	EASA,FAA,CAAC,ANAC			72-41-01		Package AA	026	INNER WALL BLEND REPAIR		3915.00	SR Technics Switzerland
642820	1498M52G06	EASA,FAA,CAAC,ANAC			72-41-01		Package B	INSP-001	BLENDING REPAIR		2610.00	SR Technics Switzerland
642820	1498M52G08	EASA,FAA,CAAC,ANAC			72-41-01		Package C	002	OUTLET GUIDE VANES BLENDING REPAIR	BLENDING OF L/E OR T/E	4220.00	SR Technics Switzerland
642820	1498M52G10	EASA,FAA,CAAC,ANAC			72-41-01		Package D	INSP-001	REMOVAL OF BROKEN BOLT(S)		1630.00	SR Technics Switzerland
642820	1498M52G11	EASA,FAA,CAAC,ANAC			72-41-01		Package E	003	DIMENSIONAL RESTORATION OF COMBUSTION CASE FLANGES AND DIAMETERS		5610.00	SR Technics Switzerland
642820	1498M52G12	EASA,FAA,CAAC,ANAC			72-41-01		Package F	001	COMBUSTION CASE.REPAIR OF THREADED HOLES		3005.00	SR Technics Switzerland
642820	1668M39G02	EASA,FAA,CAAC,ANAC			72-41-01		Package I	008	REPAIR OF FRETTING ON THE HIGH PRESSURE TURBINE COOLING DUCT PAD		8720.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
642820	1668M39G03	EASA,FAA,CAAC,ANAC			72-41-01		Package P	015	REPAIR OF THE AFT CASE INNER DIAMETER		7475.00	SR Technics Switzerland
642820	1668M39G04	EASA,FAA,CAAC,ANAC			72-41-01		Package Q	016	DIAMETER M AND DIAMETER S REPAIR WITH T800 COATING		7475.00	SR Technics Switzerland
642820	1668M39G05	EASA,FAA,CAAC,ANAC			72-41-01		Package X	023	THERMAL SPRAY REPAIR FOR THE INNER BAND WALL OF THE OUTLET GUIDE VANE		6745.00	SR Technics Switzerland
642820	1784M18G01	EASA,FAA,CAAC,ANAC										
642820	1784M18G02	EASA,FAA,CAAC,ANAC										
642820	1784M82G04	EASA,FAA,CAAC,ANAC										
642820	1784M82G07	EASA,FAA,CAAC,ANAC										
642820	1784M82G08	EASA,FAA,CAAC,ANAC										
642820	1784M82G09	EASA,FAA,CAAC,ANAC										
642820	1784M91G01	EASA,FAA,CAAC,ANAC										
642820	1784M91G02	EASA,FAA,CAAC,ANAC										
642820	1784M91G03	EASA,FAA,CAAC,ANAC										
642820	1784M91G04	EASA,FAA,CAAC,ANAC										
642820	1784M91G05	EASA,FAA,CAAC,ANAC										
642820	1784M91G06	EASA,FAA,CAAC,ANAC										
642820	1784M91G07	EASA,FAA,CAAC,ANAC										
642820	1784M91G08	EASA,FAA,CAAC,ANAC										
642820	1784M91G11	EASA,FAA,CAAC,ANAC										
642820	1784M91G12	EASA,FAA,CAAC,ANAC										
642820	1784M91G13	EASA,FAA,CAAC,ANAC										
642820	1784M91G16	EASA,FAA,CAAC,ANAC										
642820	1784M91G17	EASA,FAA,ANAC										
642820	2002M81G01	EASA,FAA,CAAC,ANAC										
642820	2002M81G02	EASA,FAA,CAAC,ANAC										
642820	2002M81G03	EASA,FAA,CAAC,ANAC										
642820	2002M81G04	EASA,FAA,CAAC,ANAC										
642820	2002M81G05	EASA,FAA,CAAC,ANAC										
642820	2002M81G06	EASA,FAA,CAAC,ANAC										
642820	2002M81G07	EASA,FAA,CAAC,ANAC										
642820	2002M81G08	EASA,FAA,CAAC,ANAC										
642820	2002M81G09	EASA,FAA,CAAC,ANAC										
642820	2002M92G01	EASA,FAA,CAAC,ANAC										
642820	2002M92G02	EASA,FAA,CAAC,ANAC										
642820	2002M92G03	EASA,FAA,CAAC,ANAC										
642820	2002M92G05	EASA,FAA,CAAC,ANAC										
642820	2002M92G06	EASA,FAA,CAAC,ANAC										
642820	2002M92G07	EASA,FAA,CAAC,ANAC										
642820	2002M92G08	EASA,FAA,CAAC,ANAC										
648090	332A2920-108	EASA,FAA,CAAC,ANAC	3	21	72-09-04	CFM56-7B BOEING EBU / QEC BRACKETS (PPBU)	Package A	CLN/INSP	CLEANING & INSPECTION		225.00	SR Technics Switzerland
648090	332A2920-150	EASA,FAA,CAAC,ANAC			72-09-04		Package SB00	SB 737-71-1608	INSP. AND REP. OF ENG. BUILD UP BRACKETS		350.00	SR Technics Switzerland
648090	332A2920-161	EASA,FAA,CAAC,ANAC										
648090	332A2920-222	EASA,FAA,CAAC,ANAC										
648090	332A2920-223	EASA,FAA,CAAC,ANAC										
648090	332A2920-232	EASA,FAA,CAAC,ANAC										
648090	332A2920-4	EASA,FAA,CAAC,ANAC										
648090	AS1895-1-350	EASA,FAA,CAAC,ANAC										
648090	AS1895-4-350	EASA,FAA,CAAC,ANAC										
648440	301-544-407-0	EASA,FAA,CAAC,ANAC	6	21	72-22-07	NO.1 AND NO.2 BEARING SUPPORT OIL TUBES	Package A	CLN/INSP	CLEANING & INSPECTION		285.00	SR Technics Switzerland
648440	337-010-901-0	EASA,FAA,CAAC,ANAC			72-22-07		Package A	CLN/INSP	PRESSURE TEST		285.00	SR Technics Switzerland
648440	337-010-902-0	EASA,FAA,CAAC,ANAC			72-22-07		Package B	001	BLENDING		290.00	SR Technics Switzerland
648440	337-011-202-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648440	337-011-303-0	EASA,FAA,CAAC,ANAC										
648440	338-062-501-0	EASA,FAA,CAAC,ANAC										
648440	338-067-302-0	EASA,FAA,CAAC,ANAC										
648440	338-067-351-0	EASA,FAA,CAAC,ANAC										
648440	340-026-302-0	EASA,FAA,CAAC,ANAC										
648459	301-348-412-0	EASA,FAA,CAAC,ANAC	13	28	72-22-17	NO.1 AND NO.2 BEARING SUPPORT - PROBE SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		230.00	SR Technics Switzerland
648459	337-011-802-0	EASA,FAA,CAAC,ANAC										
648459	340-027-051-0	EASA,FAA,CAAC,ANAC										
648461	305-047-401-0	EASA,FAA,CAAC,ANAC	2	28	72-22-20	CFM56 NO. 1 AND NO. 2 BEARING SUPPORT HA	Package A	CLN/INSP	CLEANING & INSPECTION		135.00	SR Technics Switzerland
648461	AS3217-207	EASA,FAA,CAAC,ANAC										
648461	AS3217-253	EASA,FAA,CAAC,ANAC										
648461	AS3218-247	EASA,FAA,CAAC,ANAC										
648461	J204P0475	EASA,FAA,CAAC,ANAC										
648461	J204P0925	EASA,FAA,CAAC,ANAC										
648461	J205P1100	EASA,FAA,CAAC,ANAC										
648494	305-367-103-0	EASA,FAA,CAAC,ANAC	4	28	72-22-10	CFM56 OIL SEPARATOR DUCT	Package A	CLN/INSP	CLEANING & INSPECTION		90.00	SR Technics Switzerland
648494	305-367-104-0	EASA,FAA,CAAC,ANAC										
648512	340-077-802-0	EASA,FAA,CAAC,ANAC	4	28	72-09-04	CFM56-7B ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		45.00	SR Technics Switzerland
648512	340-102-403-0	EASA,FAA,CAAC,ANAC										
648512	340-103-201-0	EASA,FAA,CAAC,ANAC										
648512	340-103-402-0	EASA,FAA,CAAC,ANAC										
648512	340-103-502-0	EASA,FAA,CAAC,ANAC										
648512	340-157-001-0	EASA,FAA,CAAC,ANAC										
648512	649-781-495-0	EASA,FAA,CAAC,ANAC										
648512	649-781-787-0	EASA,FAA,CAAC,ANAC										
648697	305-371-802-0	EASA,FAA,CAAC,ANAC	5	28	72-56-08	CFM56 FLAME ARRESTOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		370.00	SR Technics Switzerland
648697	305-371-803-0	EASA,FAA,CAAC,ANAC										
648698	336-049-702-0	EASA,FAA,CAAC,ANAC	3	21	72-56-05	CFM56 BEARING 5 DRAIN TUBE / OVERBOARD S	Package A	CLN/INSP	CLEANING & INSPECTION		80.00	SR Technics Switzerland
648698	338-107-801-0	EASA,FAA,CAAC,ANAC										
648714	1359M84P06	EASA,FAA,CAAC,ANAC	11	28	72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SEAL RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		500.00	SR Technics Switzerland
648714	1359M84P08	EASA,FAA,CAAC,ANAC										
648731	1476M52P01	EASA,FAA,CAAC,ANAC	4	28	72-32-13	CFM56 BUSHING, COMPR. STATOR ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		55.00	SR Technics Switzerland
648731	1476M52P02	EASA,FAA,CAAC,ANAC										
648731	1476M52P04	EASA,FAA,CAAC,ANAC										
648731	9131M66P03	EASA,FAA,CAAC,ANAC										
648731	9131M68P02	EASA,FAA,CAAC,ANAC										
648731	9513M97P01	EASA,FAA,CAAC,ANAC										
648731	9513M98P01	EASA,FAA,CAAC,ANAC										
648731	9513M99P01	EASA,FAA,CAAC,ANAC										
648731	9944M24P01	EASA,FAA,CAAC,ANAC										
648731	9945M71P02	EASA,FAA,CAAC,ANAC										
648731	9945M74P06	EASA,FAA,CAAC,ANAC										
648731	9955M10P01	EASA,FAA,CAAC,ANAC										
652060	2050M55P01	EASA,FAA,CAAC,ANAC	4	28	72-32-09	CFM56 COMPRESSOR STATOR VSV TRUNNION BUS	Package A	CLN/INSP	CLEANING & INSPECTION		30.00	SR Technics Switzerland
652060	2050M55P02	EASA,FAA,CAAC,ANAC										
652060	2102M23P04	EASA,FAA,CAAC,ANAC										
652060	2102M23P08	EASA,FAA,CAAC,ANAC										
653329	340-406-801-0	EASA,FAA,CAAC,ANAC	9	21	26-11-03	FIRE DETECTION HARNESSES MW0325&MW0326	Package B	TEST	PRE TEST		530.00	SR Technics Switzerland
653329	340-406-901-0	EASA,FAA,CAAC,ANAC			26-11-03		Package C	TEST	TEST		885.00	SR Technics Switzerland
653329	CA243-01	EASA,FAA,CAAC,ANAC			26-11-03		Package E		REPAIR		1225.00	SR Technics Switzerland
653329	CA243-02	EASA,FAA,CAAC,ANAC			26-11-03		Package G		OVERHAUL		1495.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
653329	CA244-01	EASA,FAA,CAAC,ANAC										
653329	CA244-02	EASA,FAA,CAAC,ANAC										
653347	336-472-901-0	EASA,FAA,CAAC,ANAC	13	28	72-23-17	FAN FRAME ASSEMBLY - OEL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
653347	337-040-403-0	EASA,FAA,CAAC,ANAC										
653347	337-043-001-0	EASA,FAA,CAAC,ANAC										
653347	338-011-603-0	EASA,FAA,CAAC,ANAC										
653347	649-148-149-0	EASA,FAA,CAAC,ANAC										
653347	649-781-842-0	EASA,FAA,CAAC,ANAC										
656317	9513M60P02	EASA,FAA,CAAC,ANAC	10	28	72-52-09	CFM56 COUNTER WEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		155.00	SR Technics Switzerland
656317	9513M61P03	EASA,FAA,CAAC,ANAC										
656317	9513M61P04	EASA,FAA,CAAC,ANAC										
656317	9513M62P04	EASA,FAA,CAAC,ANAC										
656317	9513M62P05	EASA,FAA,CAAC,ANAC										
656317	9513M62P06	EASA,FAA,CAAC,ANAC										
656317	9524M49P04	EASA,FAA,CAAC,ANAC										
656317	9524M49P05	EASA,FAA,CAAC,ANAC										
656317	9524M49P06	EASA,FAA,CAAC,ANAC										
656317	9524M50P06	EASA,FAA,CAAC,ANAC										
656317	9524M50P07	EASA,FAA,CAAC,ANAC										
656317	9524M50P08	EASA,FAA,CAAC,ANAC										
656317	9524M50P09	EASA,FAA,CAAC,ANAC										
656380	340-049-001-0	EASA,FAA,CAAC,ANAC	3	21	72-63-12	ACCESSORY GEARBOX FORKS	Package A	CLN/INSP	CLEANING & INSPECTION		390.00	SR Technics Switzerland
656380	340-049-101-0	EASA,FAA,CAAC,ANAC										
656383	305-147-501-0	EASA,FAA,CAAC,ANAC	2	21	72-62-1	TRANSFER GEARBOX OIL NOZZLE PLUGS	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
656384	301-301-600-0	EASA,FAA,CAAC,ANAC	4	28	72-62-20	TRANSFER GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		360.00	SR Technics Switzerland
656384	305-120-700-0	EASA,FAA,CAAC,ANAC										
656384	305-158-401-6	EASA,FAA,CAAC,ANAC										
656384	305-158-412-0	EASA,FAA,CAAC,ANAC										
656384	305-158-506-0	EASA,FAA,CAAC,ANAC										
656384	335-319-501-0	EASA,FAA,CAAC,ANAC										
656384	335-321-801-6	EASA,FAA,CAAC,ANAC										
656384	649-363-131-0	EASA,FAA,CAAC,ANAC										
657873	1605M68P001A	EASA,FAA,CAAC,ANAC	13	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		55.00	SR Technics Switzerland
657873	1867M59G01	EASA,FAA,CAAC,ANAC										
657873	1867M73G01	EASA,FAA,CAAC,ANAC										
657873	1867M78G01	EASA,FAA,CAAC,ANAC										
657873	1868M20P001A	EASA,FAA,CAAC,ANAC										
657873	1870M31P001A	EASA,FAA,CAAC,ANAC										
657873	1894M47P001A	EASA,FAA,CAAC,ANAC										
657873	1894M63P001A	EASA,FAA,CAAC,ANAC										
657873	1958M27G01	EASA,FAA,CAAC,ANAC										
657873	1958M30G01	EASA,FAA,CAAC,ANAC										
657873	1969M92G01	EASA,FAA,CAAC,ANAC										
657873	1970M94G01	EASA,FAA,CAAC,ANAC										
657873	2174M42P01	EASA,FAA,CAAC,ANAC										
657873	238-0910-19	EASA,FAA,CAAC,ANAC										
657873	238-0910-37	EASA,FAA,CAAC,ANAC										
657873	238-0910-5	EASA,FAA,CAAC,ANAC										
657873	238-0950-15	EASA,FAA,CAAC,ANAC										
657873	238-0950-285	EASA,FAA,CAAC,ANAC										
657873	238-0950-63	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657873	642-5671-501	EASA,FAA,CAAC,ANAC										
657873	642-5672-501	EASA,FAA,CAAC,ANAC										
657873	642-5673-501	EASA,FAA,CAAC,ANAC										
657873	642-5829-501	EASA,FAA,CAAC,ANAC										
657873	642-9831-503	EASA,FAA,ANAC										
657873	642-9878-501	EASA,FAA,CAAC,ANAC										
657873	642-9928-501	EASA,FAA,CAAC,ANAC										
657873	642-9936-501	EASA,FAA,CAAC,ANAC										
657874	1621M35G01	EASA,FAA,ANAC	13	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		80.00	SR Technics Switzerland
657874	1677M98G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	110.00	SR Technics Switzerland
657874	1813M14G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		110.00	SR Technics Switzerland
657874	1813M15G01	EASA,FAA,CAAC,ANAC										
657874	1867M32G01	EASA,FAA,CAAC,ANAC										
657874	1867M44G01	EASA,FAA,CAAC,ANAC										
657874	1867M58G01	EASA,FAA,CAAC,ANAC										
657874	1867M60G01	EASA,FAA,CAAC,ANAC										
657874	1867M79G01	EASA,FAA,CAAC,ANAC										
657874	1867M81G01	EASA,FAA,CAAC,ANAC										
657874	1867M83G01	EASA,FAA,CAAC,ANAC										
657874	1867M84G01	EASA,FAA,CAAC,ANAC										
657874	1867M87G01	EASA,FAA,CAAC,ANAC										
657874	1869M13G01	EASA,FAA,CAAC,ANAC										
657874	1870M16G01	EASA,FAA,CAAC,ANAC										
657874	1870M33G01	EASA,FAA,CAAC,ANAC										
657874	1870M64G01	EASA,FAA,CAAC,ANAC										
657874	1870M78G01	EASA,FAA,CAAC,ANAC										
657874	1870M82G01	EASA,FAA,CAAC,ANAC										
657874	1892M21G01	EASA,FAA,CAAC,ANAC										
657874	1892M43G01	EASA,FAA,CAAC,ANAC										
657874	1894M44G01	EASA,FAA,CAAC,ANAC										
657874	1894M86G01	EASA,FAA,CAAC,ANAC										
657874	1894M88G01	EASA,FAA,CAAC,ANAC										
657874	1894M91G01	EASA,FAA,CAAC,ANAC										
657874	1894M94G01	EASA,FAA,CAAC,ANAC										
657874	1895M59G01	EASA,FAA,CAAC,ANAC										
657874	1958M55G01	EASA,FAA,CAAC,ANAC										
657874	1970M99G01	EASA,FAA,CAAC,ANAC										
657874	2174M33P01	EASA,FAA,CAAC,ANAC										
657874	2174M45G01	EASA,FAA,CAAC,ANAC										
657874	2174M46G01	EASA,FAA,CAAC,ANAC										
657874	2174M59G01	EASA,FAA,CAAC,ANAC										
657874	2175M12G01	EASA,FAA,CAAC,ANAC										
657874	2283M76G01	EASA,FAA,CAAC,ANAC										
657874	238-0660-501	EASA,FAA,CAAC,ANAC										
657874	238-0823-503	EASA,FAA,CAAC,ANAC										
657874	238-0856-159	EASA,FAA,CAAC,ANAC										
657874	238-0950-351	EASA,FAA,CAAC,ANAC										
657874	2423M79G01	EASA,FAA,ANAC,CAA UK										
657874	2468M14G01	EASA,FAA,ANAC										
657874	305-070-901-0	EASA,FAA,CAAC,ANAC										
657874	336-480-505-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657874	336-544-204-0	EASA,FAA,CAAC,ANAC										
657874	336-545-002-0	EASA,FAA,CAAC,ANAC										
657874	336-547-902-0	EASA,FAA,CAAC,ANAC										
657874	338-025-402-0	EASA,FAA,CAAC,ANAC										
657874	338-038-402-0	EASA,FAA,CAAC,ANAC										
657874	340-090-804-0	EASA,FAA,CAAC,ANAC										
657874	340-097-102-0	EASA,FAA,CAAC,ANAC										
657874	340-097-201-0	EASA,FAA,CAAC,ANAC										
657874	340-097-203-0	EASA,FAA,CAAC,ANAC										
657874	340-097-501-0	EASA,FAA,CAAC,ANAC										
657874	642-5613-501	EASA,FAA,CAAC,ANAC										
657874	642-5676-501	EASA,FAA,CAAC,ANAC										
657874	642-5702-501	EASA,FAA,CAAC,ANAC										
657874	642-5705-501	EASA,FAA,CAAC,ANAC										
657874	642-9830-501	EASA,FAA,CAAC,ANAC										
657874	642-9831-501	EASA,FAA,CAAC,ANAC										
657874	642-9831-505	EASA,FAA,CAAC,ANAC										
657874	642-9834-501	EASA,FAA,CAAC,ANAC										
657874	642-9849-503	EASA,FAA,CAAC,ANAC										
657874	642-9851-503	EASA,FAA,CAAC,ANAC										
657874	642-9857-503	EASA,FAA,CAAC,ANAC										
657874	642-9868-501	EASA,FAA,CAAC,ANAC										
657874	642-9892-501	EASA,FAA,CAAC,ANAC										
657874	642-9896-501	EASA,FAA,CAAC,ANAC										
657874	642-9897-501	EASA,FAA,CAAC,ANAC										
657874	642-9898-503	EASA,FAA,CAAC,ANAC										
657874	642-9920-501	EASA,FAA,CAAC,ANAC										
657874	642-9921-501	EASA,FAA,CAAC,ANAC										
657874	642-9924-501	EASA,FAA,CAAC,ANAC										
657874	642-9925-501	EASA,FAA,CAAC,ANAC										
657874	642-9927-501	EASA,FAA,CAAC,ANAC										
657874	642-9929-501	EASA,FAA,CAAC,ANAC										
657874	642-9945-501	EASA,FAA,CAAC,ANAC										
657875	1444M20G03	EASA,FAA,CAAC,ANAC	14	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		75.00	SR Technics Switzerland
657875	1677M30G03	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	145.00	SR Technics Switzerland
657875	1677M48G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		145.00	SR Technics Switzerland
657875	1788M89G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		145.00	SR Technics Switzerland
657875	1817M25G01	EASA,FAA,CAAC,ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		50.00	SR Technics Switzerland
657875	1867M19G01	EASA,FAA,CAAC,ANAC										
657875	1867M34G01	EASA,FAA,CAAC,ANAC										
657875	1867M82G01	EASA,FAA,CAAC,ANAC										
657875	1869M14G01	EASA,FAA,CAAC,ANAC										
657875	1869M31G01	EASA,FAA,CAAC,ANAC										
657875	1869M32G01	EASA,FAA,CAAC,ANAC										
657875	1870M12G01	EASA,FAA,CAAC,ANAC										
657875	1870M29G01	EASA,FAA,CAAC,ANAC										
657875	1870M30G01	EASA,FAA,CAAC,ANAC										
657875	1870M34G01	EASA,FAA,CAAC,ANAC										
657875	1870M49G01	EASA,FAA,CAAC,ANAC										
657875	1870MS8G01	EASA,FAA,CAAC,ANAC										
657875	1870M65G01	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	1870M69G01	EASA,FAA,CAAC,ANAC										
657875	1870M76G01	EASA,FAA,CAAC,ANAC										
657875	1870M77G01	EASA,FAA,CAAC,ANAC										
657875	1870M83G01	EASA,FAA,CAAC,ANAC										
657875	1870M91G01	EASA,FAA,CAAC,ANAC										
657875	1871M72G01	EASA,FAA,CAAC,ANAC										
657875	1892M27G01	EASA,FAA,CAAC,ANAC										
657875	1892M42G01	EASA,FAA,CAAC,ANAC										
657875	1892M46G01	EASA,FAA,CAAC,ANAC										
657875	1892M54G01	EASA,FAA,CAAC,ANAC										
657875	1892M68G01	EASA,FAA,CAAC,ANAC										
657875	1892M75G01	EASA,FAA,CAAC,ANAC										
657875	1892M82G01	EASA,FAA,CAAC,ANAC										
657875	1892M97G01	EASA,FAA,CAAC,ANAC										
657875	1894M12G01	EASA,FAA,CAAC,ANAC										
657875	1894M16G01	EASA,FAA,CAAC,ANAC										
657875	1894M21G01	EASA,FAA,CAAC,ANAC										
657875	1894M39G01	EASA,FAA,CAAC,ANAC										
657875	1894M42G01	EASA,FAA,CAAC,ANAC										
657875	1894M54G01	EASA,FAA,CAAC,ANAC										
657875	1894M55G01	EASA,FAA,CAAC,ANAC										
657875	1894M60G01	EASA,FAA,CAAC,ANAC										
657875	1894M66G01	EASA,FAA,CAAC,ANAC										
657875	1894M67G01	EASA,FAA,CAAC,ANAC										
657875	1894M84G01	EASA,FAA,CAAC,ANAC										
657875	1894M87G01	EASA,FAA,CAAC,ANAC										
657875	1894M90G01	EASA,FAA,CAAC,ANAC										
657875	1894M92G01	EASA,FAA,CAAC,ANAC										
657875	1895M79G01	EASA,FAA,CAAC,ANAC										
657875	1895M84G01	EASA,FAA,CAAC,ANAC										
657875	1895M85G01	EASA,FAA,CAAC,ANAC										
657875	1895M90G01	EASA,FAA,CAAC,ANAC										
657875	1896M38G01	EASA,FAA,CAAC,ANAC										
657875	1896M90G01	EASA,FAA,CAAC,ANAC										
657875	1897M49G01	EASA,FAA,CAAC,ANAC										
657875	1897M50G01	EASA,FAA,CAAC,ANAC										
657875	1897M57G01	EASA,FAA,CAAC,ANAC										
657875	1897M70G01	EASA,FAA,CAAC,ANAC										
657875	1898M64G01	EASA,FAA,CAAC,ANAC										
657875	1898M80G01	EASA,FAA,CAAC,ANAC										
657875	1898M86G01	EASA,FAA,CAAC,ANAC										
657875	1958M11G01	EASA,FAA,CAAC,ANAC										
657875	1958M13G01	EASA,FAA,CAAC,ANAC										
657875	1958M24G01	EASA,FAA,CAAC,ANAC										
657875	1958M31G01	EASA,FAA,CAAC,ANAC										
657875	1958M34G01	EASA,FAA,CAAC,ANAC										
657875	1958M40G01	EASA,FAA,CAAC,ANAC										
657875	1958M44G01	EASA,FAA,CAAC,ANAC										
657875	1958M45G01	EASA,FAA,CAAC,ANAC										
657875	1958M53G01	EASA,FAA,CAAC,ANAC										
657875	1958M76G01	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	1969M26G01	EASA,FAA,CAAC,ANAC										
657875	1969M93G01	EASA,FAA,CAAC,ANAC										
657875	1970M10G01	EASA,FAA,CAAC,ANAC										
657875	1970M28G01	EASA,FAA,CAAC,ANAC										
657875	1970M38G01	EASA,FAA,CAAC,ANAC										
657875	1970M68G01	EASA,FAA,CAAC,ANAC										
657875	1970M98G01	EASA,FAA,CAAC,ANAC										
657875	1971M11G01	EASA,FAA,CAAC,ANAC										
657875	1971M12G01	EASA,FAA,CAAC,ANAC										
657875	1971M14P01	EASA,FAA,CAAC,ANAC										
657875	1971M78G01	EASA,FAA,CAAC,ANAC										
657875	1971M79G01	EASA,FAA,CAAC,ANAC										
657875	1971M86G01	EASA,FAA,CAAC,ANAC										
657875	1971M98G01	EASA,FAA,CAAC,ANAC										
657875	2046M73G01	EASA,FAA,CAAC,ANAC										
657875	2174M26G01	EASA,FAA,CAAC,ANAC										
657875	2174M31G01	EASA,FAA,CAAC,ANAC										
657875	2174M32G01	EASA,FAA,CAAC,ANAC										
657875	2174M39G01	EASA,FAA,CAAC,ANAC										
657875	2174M41G01	EASA,FAA,CAAC,ANAC										
657875	2174M43G01	EASA,FAA,CAAC,ANAC										
657875	2174M47G01	EASA,FAA,CAAC,ANAC										
657875	2174M51G01	EASA,FAA,CAAC,ANAC										
657875	2174M52G01	EASA,FAA,CAAC,ANAC										
657875	2174M54G01	EASA,FAA,CAAC,ANAC										
657875	2174M58G01	EASA,FAA,CAAC,ANAC										
657875	2175M10G01	EASA,FAA,CAAC,ANAC										
657875	2175M11G01	EASA,FAA,CAAC,ANAC										
657875	2175M15G01	EASA,FAA,CAAC,ANAC										
657875	2175M63G01	EASA,FAA,CAAC,ANAC										
657875	2283M10G01	EASA,FAA,ANAC										
657875	2283M65G01	EASA,FAA,CAAC,ANAC										
657875	238-0557-501	EASA,FAA,CAAC,ANAC										
657875	238-0654-503	EASA,FAA,CAAC,ANAC										
657875	238-0655-503	EASA,FAA,CAAC,ANAC										
657875	238-0704-505	EASA,FAA,CAAC,ANAC										
657875	238-0708-507	EASA,FAA,CAAC,ANAC										
657875	238-0825-503	EASA,FAA,CAAC,ANAC										
657875	238-0856-139	EASA,FAA,CAAC,ANAC										
657875	238-0856-3	EASA,FAA,CAAC,ANAC										
657875	238-0910-35	EASA,FAA,CAAC,ANAC										
657875	238-0950-237	EASA,FAA,CAAC,ANAC										
657875	238-0950-311	EASA,FAA,CAAC,ANAC										
657875	2464M87G01	EASA,ANAC,TCCA,CAA UK										
657875	2678M59G01	EASA,FAA,ANAC										
657875	332A2911-1	EASA,FAA,CAAC,ANAC										
657875	332A2920-142	EASA,FAA,CAAC,ANAC										
657875	332A2920-92	EASA,FAA,CAAC,ANAC										
657875	332A2930-89	EASA,FAA,CAAC,ANAC										
657875	332A2931-3	EASA,FAA,CAAC,ANAC										
657875	336-479-603-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	336-515-803-0	EASA,FAA,CAAC,ANAC										
657875	336-523-002-0	EASA,FAA,CAAC,ANAC										
657875	336-544-303-0	EASA,FAA,CAAC,ANAC										
657875	336-544-406-0	EASA,FAA,CAAC,ANAC										
657875	336-544-503-0	EASA,FAA,CAAC,ANAC										
657875	336-544-603-0	EASA,FAA,CAAC,ANAC										
657875	336-544-706-0	EASA,FAA,CAAC,ANAC										
657875	336-544-707-0	EASA,FAA,CAAC,ANAC										
657875	336-544-902-0	EASA,FAA,CAAC,ANAC										
657875	338-014-504-0	EASA,FAA,CAAC,ANAC										
657875	338-014-601-0	EASA,FAA,CAAC,ANAC										
657875	338-017-301-0	EASA,FAA,CAAC,ANAC										
657875	338-017-502-0	EASA,FAA,CAAC,ANAC										
657875	338-022-101-0	EASA,FAA,CAAC,ANAC										
657875	338-023-203-0	EASA,FAA,CAAC,ANAC										
657875	338-024-404-0	EASA,FAA,CAAC,ANAC										
657875	338-024-405-0	EASA,FAA,ANAC										
657875	338-024-601-0	EASA,FAA,CAAC,ANAC										
657875	338-027-801-0	EASA,FAA,CAAC,ANAC										
657875	338-038-601-0	EASA,FAA,CAAC,ANAC										
657875	338-039-402-0	EASA,FAA,CAAC,ANAC										
657875	338-055-202-0	EASA,FAA,CAAC,ANAC										
657875	338-056-201-0	EASA,FAA,CAAC,ANAC										
657875	338-126-605-0	EASA,FAA,CAAC,ANAC										
657875	338-168-604-0	EASA,FAA,CAAC,ANAC										
657875	340-019-106-0	EASA,FAA,CAAC,ANAC										
657875	340-097-002-0	EASA,FAA,CAAC,ANAC										
657875	340-097-405-0	EASA,FAA,CAAC,ANAC										
657875	340-097-502-0	EASA,FAA,CAAC,ANAC										
657875	340-097-601-0	EASA,FAA,CAAC,ANAC										
657875	340-097-701-0	EASA,FAA,CAAC,ANAC										
657875	340-119-303-0	EASA,FAA,CAAC,ANAC										
657875	340-119-501-0	EASA,FAA,CAAC,ANAC										
657875	340-119-602-0	EASA,FAA,CAAC,ANAC										
657875	340-119-701-0	EASA,FAA,CAAC,ANAC										
657875	340-139-102-0	EASA,FAA,CAAC,ANAC										
657875	340-8134-523	EASA,FAA,CAAC,ANAC										
657875	642-5652-501	EASA,FAA,CAAC,ANAC										
657875	642-5653-501	EASA,FAA,CAAC,ANAC										
657875	642-5657-503	EASA,FAA,CAAC,ANAC										
657875	642-5657-505	EASA,FAA,CAAC,ANAC										
657875	642-5663-501	EASA,FAA,CAAC,ANAC										
657875	642-5664-503	EASA,FAA,CAAC,ANAC										
657875	642-5665-501	EASA,FAA,CAAC,ANAC										
657875	642-5703-501	EASA,FAA,CAAC,ANAC										
657875	642-5826-501	EASA,FAA,CAAC,ANAC										
657875	642-5827-501	EASA,FAA,CAAC,ANAC										
657875	642-5856-501	EASA,FAA,CAAC,ANAC										
657875	642-5862-501	EASA,FAA,CAAC,ANAC										
657875	642-9825-501	EASA,FAA,CAAC,ANAC										
657875	642-9835-501	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	642-9836-501	EASA,FAA,CAAC,ANAC										
657875	642-9838-505	EASA,FAA,CAAC,ANAC										
657875	642-9840-501	EASA,FAA,CAAC,ANAC										
657875	642-9841-501	EASA,FAA,CAAC,ANAC										
657875	642-9844-501	EASA,FAA,CAAC,ANAC										
657875	642-9846-501	EASA,FAA,CAAC,ANAC										
657875	642-9847-501	EASA,FAA,CAAC,ANAC										
657875	642-9855-501	EASA,FAA,CAAC,ANAC										
657875	642-9855-502	EASA,FAA,CAAC,ANAC										
657875	642-9855-503	EASA,FAA,CAAC,ANAC										
657875	642-9856-501	EASA,FAA,CAAC,ANAC										
657875	642-9857-505	EASA,FAA,CAAC,ANAC										
657875	642-9858-502	EASA,FAA,CAAC,ANAC										
657875	642-9869-501	EASA,FAA,CAAC,ANAC										
657875	642-9871-503	EASA,FAA,CAAC,ANAC										
657875	642-9877-503	EASA,FAA,CAAC,ANAC										
657875	642-9879-501	EASA,FAA,CAAC,ANAC										
657875	642-9887-501	EASA,FAA,CAAC,ANAC										
657875	642-9890-501	EASA,FAA,CAAC,ANAC										
657875	642-9894-501	EASA,FAA,CAAC,ANAC										
657875	642-9895-501	EASA,FAA,CAAC,ANAC										
657875	642-9899-503	EASA,FAA,CAAC,ANAC										
657875	642-9912-501	EASA,FAA,CAAC,ANAC										
657875	642-9915-501	EASA,FAA,CAAC,ANAC										
657875	642-9917-501	EASA,FAA,CAAC,ANAC										
657875	642-9919-501	EASA,FAA,CAAC,ANAC										
657875	642-9923-501	EASA,FAA,CAAC,ANAC										
657875	642-9926-501	EASA,FAA,CAAC,ANAC										
657875	642-9930-501	EASA,FAA,CAAC,ANAC										
657875	642-9934-501	EASA,FAA,CAAC,ANAC										
657875	642-9943-501	EASA,FAA,CAAC,ANAC										
657875	642-9944-501	EASA,FAA,CAAC,ANAC										
657875	642-9950-503	EASA,FAA,CAAC,ANAC										
657875	642-9971-501	EASA,FAA,CAAC,ANAC										
657875	9134M25P121	EASA,FAA,CAAC,ANAC										
657875	9134M25P125	EASA,FAA,CAAC,ANAC										
657876	1677M58G01	EASA,FAA,CAAC,ANAC	18	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND EBU BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		250.00	SR Technics Switzerland
657876	1677M63G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	400.00	SR Technics Switzerland
657876	1716M29G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		400.00	SR Technics Switzerland
657876	1817M10G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		400.00	SR Technics Switzerland
657876	1817M53G01	EASA,FAA,CAAC,ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		155.00	SR Technics Switzerland
657876	1867M49G01	EASA,FAA,CAAC,ANAC			72-09-04		Package SB00	72-0188	FAN FRAME ASSEMBLY - DISCONNECTION AND RECONNECTION OF MW0301 (J01) AND MW0302 (J02) HARNESSES AT TH		255.00	SR Technics Switzerland
657876	1871M24G03	EASA,FAA,CAAC,ANAC										
657876	1871M34G01	EASA,FAA,CAAC,ANAC										
657876	1871M48G01	EASA,FAA,CAAC,ANAC										
657876	1871M48G03	EASA,FAA,CAAC,ANAC										
657876	1871M75G03	EASA,FAA,CAAC,ANAC										
657876	1892M37G01	EASA,FAA,CAAC,ANAC										
657876	1892M63P01	EASA,FAA,CAAC,ANAC										
657876	1894M15G01	EASA,FAA,CAAC,ANAC										
657876	1894M95G01	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	1894M9EG01	EASA,FAA,CAAC,ANAC										
657876	1895M16G01	EASA,FAA,CAAC,ANAC										
657876	1895M91G01	EASA,FAA,CAAC,ANAC										
657876	1898M98G01	EASA,FAA,CAAC,ANAC										
657876	1958M60G01	EASA,FAA,CAAC,ANAC										
657876	1970M76G01	EASA,FAA,CAAC,ANAC										
657876	1970M90G01	EASA,FAA,CAAC,ANAC										
657876	1971M25G01	EASA,FAA,CAAC,ANAC										
657876	2174M34G01	EASA,FAA,CAAC,ANAC										
657876	2174M40G01	EASA,FAA,CAAC,ANAC										
657876	2175M34G01	EASA,FAA,CAAC,ANAC										
657876	2283M34G01	EASA,FAA,CAAC,ANAC										
657876	238-0513-505	EASA,FAA,CAAC,ANAC										
657876	238-0553-501	EASA,FAA,CAAC,ANAC										
657876	238-0554-501	EASA,FAA,CAAC,ANAC										
657876	238-0556-501	EASA,FAA,CAAC,ANAC										
657876	238-0856-121	EASA,FAA,CAAC,ANAC										
657876	238-0856-127	EASA,FAA,CAAC,ANAC										
657876	238-0856-131	EASA,FAA,CAAC,ANAC										
657876	238-0856-135	EASA,FAA,CAAC,ANAC										
657876	238-0856-143	EASA,FAA,CAAC,ANAC										
657876	238-0856-147	EASA,FAA,CAAC,ANAC										
657876	238-0856-151	EASA,FAA,CAAC,ANAC										
657876	238-0856-173	EASA,FAA,CAAC,ANAC										
657876	238-0856-179	EASA,FAA,CAAC,ANAC										
657876	321-455-302-0	EASA,FAA,CAAC,ANAC										
657876	321-455-654-0	EASA,FAA,CAAC,ANAC										
657876	336-084-701-0	EASA,FAA,CAAC,ANAC										
657876	336-084-751-0	EASA,FAA,CAAC,ANAC										
657876	336-091-201-0	EASA,FAA,CAAC,ANAC										
657876	336-469-605-0	EASA,FAA,CAAC,ANAC										
657876	336-477-901-0	EASA,FAA,CAAC,ANAC										
657876	336-495-706-0	EASA,FAA,CAAC,ANAC										
657876	338-011-002-0	EASA,FAA,CAAC,ANAC										
657876	338-011-101-0	EASA,FAA,CAAC,ANAC										
657876	338-012-601-0	EASA,FAA,CAAC,ANAC										
657876	338-012-602-0	EASA,FAA,CAAC,ANAC										
657876	338-012-701-0	EASA,FAA,CAAC,ANAC										
657876	338-012-702-0	EASA,FAA,CAAC,ANAC										
657876	338-012-902-0	EASA,FAA,CAAC,ANAC										
657876	338-013-302-0	EASA,FAA,CAAC,ANAC										
657876	338-013-402-0	EASA,FAA,CAAC,ANAC										
657876	338-013-901-0	EASA,FAA,CAAC,ANAC										
657876	338-014-104-0	EASA,FAA,CAAC,ANAC										
657876	338-014-106-0	EASA,FAA,CAAC,ANAC										
657876	338-014-203-0	EASA,FAA,CAAC,ANAC										
657876	338-015-202-0	EASA,FAA,CAAC,ANAC										
657876	338-016-403-0	EASA,FAA,CAAC,ANAC										
657876	338-016-902-0	EASA,FAA,CAAC,ANAC										
657876	338-021-604-0	EASA,FAA,CAAC,ANAC										
657876	338-021-605-0	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	338-027-402-0	EASA,FAA,CAAC,ANAC										
657876	338-032-002-0	EASA,FAA,ANAC										
657876	338-032-702-0	EASA,FAA,CAAC,ANAC										
657876	338-033-104-0	EASA,FAA,CAAC,ANAC										
657876	338-033-602-0	EASA,FAA,CAAC,ANAC										
657876	338-037-003-0	EASA,FAA,CAAC,ANAC										
657876	338-039-802-0	EASA,FAA,CAAC,ANAC										
657876	338-040-003-0	EASA,FAA,CAAC,ANAC										
657876	338-041-402-0	EASA,FAA,ANAC										
657876	338-042-202-0	EASA,FAA,CAAC,ANAC										
657876	338-042-802-0	EASA,FAA,CAAC,ANAC										
657876	338-053-204-0	EASA,FAA,CAAC,ANAC										
657876	338-054-001-0	EASA,FAA,CAAC,ANAC										
657876	338-054-303-0	EASA,FAA,CAAC,ANAC										
657876	338-056-701-0	EASA,FAA,CAAC,ANAC										
657876	338-058-401-0	EASA,FAA,CAAC,ANAC										
657876	338-058-601-0	EASA,FAA,CAAC,ANAC										
657876	338-059-402-0	EASA,FAA,CAAC,ANAC										
657876	338-059-403-0	EASA,FAA,CAAC,ANAC										
657876	338-122-903-0	EASA,FAA,CAAC,ANAC										
657876	338-125-503-0	EASA,FAA,CAAC,ANAC										
657876	338-125-603-0	EASA,FAA,CAAC,ANAC										
657876	340-006-704-0	EASA,FAA,CAAC,ANAC										
657876	340-006-804-0	EASA,FAA,CAAC,ANAC										
657876	340-007-303-0	EASA,FAA,CAAC,ANAC										
657876	340-013-004-0	EASA,FAA,CAAC,ANAC										
657876	340-017-201-0	EASA,FAA,CAAC,ANAC										
657876	340-019-802-0	EASA,FAA,CAAC,ANAC										
657876	340-020-205-0	EASA,FAA,CAAC,ANAC										
657876	340-025-405-0	EASA,FAA,CAAC,ANAC										
657876	340-069-703-0	EASA,FAA,CAAC,ANAC,CAA UK										
657876	340-069-704-0	EASA,FAA,CAAC,ANAC										
657876	340-075-203-0	EASA,FAA,CAAC,ANAC										
657876	340-075-303-0	EASA,FAA,CAAC,ANAC										
657876	340-086-103-0	EASA,FAA,CAAC,ANAC										
657876	340-087-904-0	EASA,FAA,CAAC,ANAC										
657876	340-087-905-0	EASA,FAA,CAAC,ANAC										
657876	340-088-903-0	EASA,FAA,CAAC,ANAC										
657876	340-090-304-0	EASA,FAA,CAAC,ANAC										
657876	340-095-705-0	EASA,FAA,CAAC,ANAC										
657876	340-106-402-0	EASA,FAA,CAAC,ANAC										
657876	340-118-101-0	EASA,FAA,CAAC,ANAC										
657876	340-119-803-0	EASA,FAA,CAAC,ANAC										
657876	340-120-602-0	EASA,FAA,CAAC,ANAC										
657876	340-120-902-0	EASA,FAA,CAAC,ANAC										
657876	340-121-202-0	EASA,FAA,CAAC,ANAC										
657876	340-140-102-0	EASA,FAA,CAAC,ANAC										
657876	340-140-902-0	EASA,FAA,CAAC,ANAC										
657876	340-159-501-0	EASA,FAA,CAAC,ANAC										
657876	642-3031-503	EASA,FAA,CAAC,ANAC										
657876	642-9827-501	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	642-9829-502	EASA,FAA,CAAC,ANAC										
657876	642-9829-503	EASA,FAA,CAAC,ANAC										
657876	642-9866-503	EASA,FAA,CAAC,ANAC										
657876	642-9867-505	EASA,FAA,CAAC,ANAC										
657876	642-9876-503	EASA,FAA,CAAC,ANAC										
657876	649-400-055-0	EASA,FAA,CAAC,ANAC										
657876	649-400-056-0	EASA,FAA,CAAC,ANAC										
657876	AMBK4-4014	EASA,FAA,CAAC,ANAC										
657876	P40560	EASA,FAA,CAAC,ANAC										
657939	155006-06-16	EASA,FAA,CAAC,ANAC	9	21	72-30-01	HOSE ASSEMBLIES - HYDRAULIC	Package A	CLN/INSP	CLEANING AND INSPECTION		1225.00	SR Technics Switzerland
657939	155006-06-18	EASA,FAA,CAAC,ANAC										
657939	155006-06-23	EASA,FAA,CAAC,ANAC										
657939	155006-06-9	EASA,FAA,ANAC										
657939	155012-12-19	EASA,FAA,CAAC,ANAC										
657939	155012-12-21	EASA,FAA,CAAC,ANAC										
657939	155012-73-20	EASA,FAA,CAAC,ANAC										
657939	S332A210-11	EASA,FAA,CAAC,ANAC										
657939	S332A210-16	EASA,FAA,CAAC,ANAC										
657939	S332A210-18	EASA,FAA,CAAC,ANAC										
657939	S332A210-19	EASA,FAA,CAAC,ANAC										
657939	S332A210-20	EASA,FAA,CAAC,ANAC										
657939	S332A210-21	EASA,FAA,CAAC,ANAC										
658137	8970-01	EASA,FAA,CAAC,ANAC	4	21	26-10-93	FIRE / OVERHEAT DETECTOR	Package A	CLN/INSP	CLEANING & INSPECTION		200.00	SR Technics Switzerland
658137	8970-02	EASA,FAA,CAAC,ANAC			26-10-93		Package B	TEST	TESTING AND FAULT ISOLATION		720.00	SR Technics Switzerland
658137	8970-03	EASA,FAA,CAAC,ANAC										
658137	8970-04	EASA,FAA,CAAC,ANAC										
658151	902015-01	EASA,FAA,CAAC,ANAC	11	21	26-10-87	FIRE/OVERHEAT DETECTOR ASSY	Package A	CLN/INSP	CLEANING, INSPECTION AND TEST		1140.00	SR Technics Switzerland
658151	902016-01	EASA,FAA,CAAC,ANAC			26-10-87		Package E		REPAIR		1765.00	SR Technics Switzerland
658151	902018-01	EASA,FAA,CAAC,ANAC										
658151	902018-02	EASA,FAA,CAAC,ANAC										
658151	902862	EASA,FAA,CAAC,ANAC										
658151	902862-01	EASA,FAA,CAAC,ANAC										
658151	902864	EASA,FAA,CAAC,ANAC										
658151	S332T100-29	EASA,FAA,CAAC,ANAC										
658151	S332T100-30	EASA,FAA,CAAC,ANAC										
658151	S332T100-38	EASA,FAA,CAAC,ANAC										
658151	S332T100-43	EASA,FAA,CAAC,ANAC										
658151	S332T100-44	EASA,FAA,CAAC,ANAC										
663891	J905P08A	EASA,FAA,CAAC,ANAC	2	0	72-09-04	BOLT INSPECTION CFM56 ENGINE	Package A	CLN/INSP	CLEANING & INSPECTION		130.00	SR Technics Switzerland
663891	J905P10A	EASA,FAA,CAAC,ANAC										
664002	1895M3P01	EASA,FAA,CAAC,ANAC	4	21	72-XX_XX	CFM56 TL FOR MISCELLANEOUS CFM PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
664002	338-007-401-0	EASA,FAA,ANAC										
664002	338-025-303-0	EASA,FAA,CAAC,ANAC										
664002	340-094-606-0	EASA,FAA,CAAC,ANAC										
664002	340-094-607-0	EASA,FAA,CAAC,ANAC										
664002	340-094-608-0	EASA,FAA,CAAC,ANAC										
664002	340-094-609-0	EASA,FAA,CAAC,ANAC										
664002	340-094-610-0	EASA,FAA,CAAC,ANAC										
664002	340-146-701-0	EASA,FAA,CAAC,ANAC										
664002	9993M72P01	EASA,FAA,CAAC,ANAC										
665121	BACB30PN10-19	EASA,FAA,CAAC,ANAC	3	21	71-21-37	BOLTS	Package A	CLN/INSP	CLEANING & INSPECTION		120.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2024



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
665121	BACB30PN10-19M	EASA,FAA,CAAC,ANAC										
665121	BACB30PN14-32M	EASA,FAA,CAAC,ANAC										
667723	1834M53P01	EASA,FAA,CAAC,ANAC	9	28	72-31-20	CFM56 HPC HARDWARE BALANCE WEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		65.00	SR Technics Switzerland
667723	1834M53P02	EASA,FAA,CAAC,ANAC										
667723	1834M54P01	EASA,FAA,CAAC,ANAC										
667723	1993M73P01	EASA,FAA,CAAC,ANAC										
667723	1993M73P02	EASA,FAA,CAAC,ANAC										
667723	1993M74P01	EASA,FAA,CAAC,ANAC										
667723	1993M74P02	EASA,FAA,CAAC,ANAC										
671086	336-482-301-0	EASA,FAA,CAAC,ANAC	6	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		140.00	SR Technics Switzerland
671086	336-522-703-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		185.00	SR Technics Switzerland
671086	337-154-601-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	185.00	SR Technics Switzerland
671086	338-013-101-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS AND NUTS	SPM 70-42-XX	185.00	SR Technics Switzerland
671086	338-016-002-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		185.00	SR Technics Switzerland
671086	338-016-201-0	EASA,FAA,CAAC,ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		80.00	SR Technics Switzerland
671086	338-016-603-0	EASA,FAA,CAAC,ANAC										
671086	338-021-303-0	EASA,FAA,CAAC,ANAC										
671086	338-022-301-0	EASA,FAA,ANAC										
671086	338-027-302-0	EASA,FAA,CAAC,ANAC										
671086	338-028-301-0	EASA,FAA,CAAC,ANAC										
671086	338-028-601-0	EASA,FAA,CAAC,ANAC										
671086	338-029-702-0	EASA,FAA,CAAC,ANAC										
671086	338-030-803-0	EASA,FAA,CAAC,ANAC										
671086	338-031-003-0	EASA,FAA,CAAC,ANAC										
671086	338-031-702-0	EASA,FAA,CAAC,ANAC										
671086	338-032-502-0	EASA,FAA,ANAC										
671086	338-032-803-0	EASA,FAA,CAAC,ANAC										
671086	338-033-903-0	EASA,FAA,CAAC,ANAC										
671086	338-034-102-0	EASA,FAA,CAAC,ANAC										
671086	338-034-302-0	EASA,FAA,CAAC,ANAC										
671086	338-034-403-0	EASA,FAA,ANAC										
671086	338-034-703-0	EASA,FAA,ANAC										
671086	338-035-701-0	EASA,FAA,CAAC,ANAC										
671086	338-036-003-0	EASA,FAA,CAAC,ANAC										
671086	338-037-601-0	EASA,FAA,CAAC,ANAC										
671086	338-037-901-0	EASA,FAA,CAAC,ANAC										
671086	338-038-101-0	EASA,FAA,CAAC,ANAC										
671086	338-040-201-0	EASA,FAA,ANAC										
671086	338-041-201-0	EASA,FAA,CAAC,ANAC										
671086	338-041-602-0	EASA,FAA,CAAC,ANAC										
671086	338-041-802-0	EASA,FAA,CAAC,ANAC										
671086	338-042-001-0	EASA,FAA,CAAC,ANAC										
671086	338-042-401-0	EASA,FAA,ANAC										
671086	338-042-602-0	EASA,FAA,CAAC,ANAC										
671086	338-043-201-0	EASA,FAA,CAAC,ANAC										
671086	338-043-202-0	EASA,FAA,CAAC,ANAC										
671086	338-043-401-0	EASA,FAA,CAAC,ANAC										
671086	338-043-601-0	EASA,FAA,CAAC,ANAC										
671086	338-043-801-0	EASA,FAA,ANAC										
671086	338-044-001-0	EASA,FAA,CAAC,ANAC										
671086	338-046-401-0	EASA,FAA,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671086	338-050-301-0	EASA,FAA,CAAC,ANAC										
671086	338-057-301-0	EASA,FAA,CAAC,ANAC										
671086	338-059-501-0	EASA,FAA,CAAC,ANAC										
671086	338-059-601-0	EASA,FAA,CAAC,ANAC										
671086	338-088-701-0	EASA,FAA,ANAC										
671086	338-130-102-0	EASA,FAA,CAAC,ANAC										
671086	340-019-002-0	EASA,FAA,CAAC,ANAC										
671086	340-143-701-0	EASA,FAA,CAAC,ANAC										
671086	VTF02460	EASA,FAA,CAAC,ANAC										
671089	1348M59P01	EASA,FAA,CAAC,ANAC	3	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		165.00	SR Technics Switzerland
671089	1467M96G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		70.00	SR Technics Switzerland
671089	1527M36G01	EASA,FAA,CAAC,ANAC			72-09-04		Package C	INSP-001	REPLACE INSERT SPM	70-42-XX	180.00	SR Technics Switzerland
671089	1870M22G01	EASA,FAA,CAAC,ANAC			72-09-04		Package D	INSP-001	REPLACE RIVETED PART'S		160.00	SR Technics Switzerland
671089	1892M84G01	EASA,FAA,CAAC,ANAC			72-09-04		Package E	INSP-001	WELDING HINGED BRACKETS		235.00	SR Technics Switzerland
671089	1892M98G01	EASA,FAA,CAAC,ANAC			72-09-04		Package G	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	70.00	SR Technics Switzerland
671089	1894M28G01	EASA,FAA,CAAC,ANAC										
671089	1894M80G01	EASA,FAA,CAAC,ANAC										
671089	1895M89G01	EASA,FAA,CAAC,ANAC										
671089	1896M53G01	EASA,FAA,CAAC,ANAC										
671089	1898M66G01	EASA,FAA,CAAC,ANAC										
671089	1958M12G01	EASA,FAA,CAAC,ANAC										
671089	1958M64G01	EASA,FAA,CAAC,ANAC										
671089	1970M27G01	EASA,FAA,CAAC,ANAC										
671089	2046M34G01	EASA,FAA,CAAC,ANAC										
671089	2174M25G01	EASA,FAA,ANAC										
671089	2174M35G01	EASA,FAA,CAAC,ANAC										
671089	2174M37G01	EASA,FAA,CAAC,ANAC										
671089	2174M38G01	EASA,FAA,ANAC										
671089	2174M44G01	EASA,FAA,CAAC,ANAC										
671089	2174M49G01	EASA,FAA,CAAC,ANAC										
671089	2175M13G01	EASA,FAA,CAAC,ANAC										
671089	238-0505-503	EASA,FAA,CAAC,ANAC										
671089	238-0607-503	EASA,FAA,CAAC,ANAC										
671089	238-0608-503	EASA,FAA,CAAC,ANAC										
671089	238-0610-511	EASA,FAA,CAAC,ANAC										
671089	24765-01	EASA,FAA,CAAC,ANAC										
671089	321-450-701-6	EASA,FAA,CAAC,ANAC										
671089	321-450-802-0	EASA,FAA,CAAC,ANAC										
671089	321-451-100-0	EASA,FAA,CAAC,ANAC										
671089	321-451-452-0	EASA,FAA,CAAC,ANAC										
671089	332A2910-101	EASA,FAA,CAAC,ANAC										
671089	332A2910-106	EASA,FAA,CAAC,ANAC										
671089	332A2910-111	EASA,FAA,CAAC,ANAC										
671089	332A2910-113	EASA,FAA,CAAC,ANAC										
671089	332A2910-130	EASA,FAA,CAAC,ANAC										
671089	332A2910-132	EASA,FAA,CAAC,ANAC										
671089	332A2910-134	EASA,FAA,CAAC,ANAC										
671089	332A2910-136	EASA,FAA,CAAC,ANAC										
671089	332A2910-143	EASA,FAA,CAAC,ANAC										
671089	332A2910-147	EASA,FAA,ANAC										
671089	332A2910-149	EASA,FAA,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	332A2910-24	EASA,FAA,CAAC,ANAC										
671089	332A2910-41	EASA,FAA,CAAC,ANAC										
671089	332A2910-74	EASA,FAA,CAAC,ANAC										
671089	332A2911-9	EASA,FAA,CAAC,ANAC										
671089	332A2920-157	EASA,FAA,CAAC,ANAC										
671089	332A2920-185	EASA,FAA,CAAC,ANAC										
671089	332A2920-187	EASA,FAA,ANAC										
671089	332A2920-193	EASA,FAA,ANAC										
671089	332A2920-197	EASA,FAA,CAAC,ANAC										
671089	332A2920-199	EASA,FAA,CAAC,ANAC										
671089	332A2920-224	EASA,FAA,CAAC,ANAC										
671089	332A2920-225	EASA,FAA,ANAC										
671089	332A2920-229	EASA,FAA,CAAC,ANAC										
671089	332A2920-230	EASA,FAA,CAAC,ANAC										
671089	332A2920-236	EASA,FAA,ANAC										
671089	332A2920-245	EASA,FAA,CAAC,ANAC										
671089	332A2920-55	EASA,FAA,CAAC,ANAC										
671089	332A2921-1	EASA,FAA,CAAC,ANAC										
671089	332A2930-104	EASA,FAA,CAAC,ANAC										
671089	332A2930-11	EASA,FAA,CAAC,ANAC										
671089	332A2930-50	EASA,FAA,ANAC										
671089	332A2930-83	EASA,FAA,CAAC,ANAC										
671089	332A2930-88	EASA,FAA,ANAC										
671089	332A2930-90	EASA,FAA,CAAC,ANAC										
671089	336-512-905-0	EASA,FAA,CAAC,ANAC										
671089	336-512-906-0	EASA,FAA,CAAC,ANAC										
671089	338-018-302-0	EASA,FAA,CAAC,ANAC										
671089	338-021-402-0	EASA,FAA,CAAC,ANAC										
671089	338-023-003-0	EASA,FAA,CAAC,ANAC										
671089	338-024-802-0	EASA,FAA,CAAC,ANAC										
671089	338-027-501-0	EASA,FAA,CAAC,ANAC										
671089	338-027-502-0	EASA,FAA,CAAC,ANAC										
671089	338-028-704-0	EASA,FAA,CAAC,ANAC										
671089	338-038-604-0	EASA,FAA,CAAC,ANAC										
671089	338-046-101-0	EASA,FAA,CAAC,ANAC										
671089	338-055-401-0	EASA,FAA,CAAC,ANAC										
671089	338-163-505-0	EASA,FAA,CAAC,ANAC										
671089	340-017-402-0	EASA,FAA,CAAC,ANAC										
671089	340-097-304-0	EASA,FAA,CAAC,ANAC										
671089	340-097-802-0	EASA,FAA,CAAC,ANAC										
671089	340-114-301-0	EASA,FAA,CAAC,ANAC										
671089	340-140-503-0	EASA,FAA,CAAC,ANAC										
671089	642-3031-501	EASA,FAA,CAAC,ANAC										
671089	642-5651-501	EASA,FAA,CAAC,ANAC										
671089	642-5656-501	EASA,FAA,CAAC,ANAC										
671089	642-5675-501	EASA,FAA,CAAC,ANAC										
671089	642-5677-501	EASA,FAA,CAAC,ANAC										
671089	642-5681-501	EASA,FAA,CAAC,ANAC										
671089	642-5681-503	EASA,FAA,CAAC,ANAC										
671089	642-5715-507	EASA,FAA,CAAC,ANAC										
671089	642-5752-501	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	642-5753-501	EASA,FAA,CAAC,ANAC										
671089	642-5927-502	EASA,FAA,CAAC,ANAC										
671089	642-9826-501	EASA,FAA,CAAC,ANAC										
671089	642-9828-503	EASA,FAA,CAAC,ANAC										
671089	642-9829-501	EASA,FAA,CAAC,ANAC										
671089	642-9833-501	EASA,FAA,CAAC,ANAC										
671089	642-9837-501	EASA,FAA,CAAC,ANAC										
671089	642-9843-501	EASA,FAA,CAAC,ANAC										
671089	642-9845-501	EASA,FAA,CAAC,ANAC										
671089	642-9850-501	EASA,FAA,CAAC,ANAC										
671089	642-9863-501	EASA,FAA,CAAC,ANAC										
671089	642-9870-503	EASA,FAA,CAAC,ANAC										
671089	642-9889-501	EASA,FAA,CAAC,ANAC										
671089	642-9893-501	EASA,FAA,CAAC,ANAC										
671089	642-9913-501	EASA,FAA,CAAC,ANAC										
671089	642-9916-501	EASA,FAA,CAAC,ANAC										
671089	642-9918-501	EASA,FAA,CAAC,ANAC										
671089	642-9922-501	EASA,FAA,CAAC,ANAC										
671089	642-9951-503	EASA,FAA,CAAC,ANAC										
671095	301-534-311-0	EASA,FAA,CAAC,ANAC	6	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		95.00	SR Technics Switzerland
671095	336-480-401-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	75.00	SR Technics Switzerland
671095	336-486-001-0	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	75.00	SR Technics Switzerland
671095	337-138-303-0	EASA,FAA,CAAC,ANAC			72-09-04		Package C	INSP-001	REPLACE RIVETED PART'S		75.00	SR Technics Switzerland
671095	338-015-302-0	EASA,FAA,CAAC,ANAC										
671095	338-027-201-0	EASA,FAA,ANAC										
671095	338-028-001-0	EASA,FAA,CAAC,ANAC										
671095	338-030-504-0	EASA,FAA,CAAC,ANAC										
671095	338-033-504-0	EASA,FAA,CAAC,ANAC										
671095	338-035-201-0	EASA,FAA,ANAC										
671095	338-040-801-0	EASA,FAA,ANAC										
671095	338-041-002-0	EASA,FAA,CAAC,ANAC										
671095	338-045-401-0	EASA,FAA,CAAC,ANAC										
671095	338-045-601-0	EASA,FAA,ANAC										
671095	338-050-801-0	EASA,FAA,CAAC,ANAC										
671095	338-057-401-0	EASA,FAA,CAAC,ANAC										
671095	340-002-202-0	EASA,FAA,CAAC,ANAC										
671095	340-116-001-0	EASA,FAA,CAAC,ANAC										
671095	340-131-301-0	EASA,FAA,CAAC,ANAC										
671095	340-132-201-0	EASA,FAA,CAAC,ANAC										
671095	340-143-501-0	EASA,FAA,CAAC,ANAC										
671095	642-5828-501	EASA,FAA,CAAC,ANAC										
671175	340-031-802-0	EASA,FAA,CAAC,ANAC	6	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		60.00	SR Technics Switzerland
671175	340-088-701-0	EASA,FAA,CAAC,ANAC										
672453	1324M95P01	EASA,FAA,CAAC,ANAC	3	21	72-09-04	CFM56 ENGINE HARDWARE INSPECTION MOD.82	Package A	CLN/INSP	CLEANING & INSPECTION		90.00	SR Technics Switzerland
672453	1870M26P01	EASA,FAA,CAAC,ANAC										
672453	1898M50G01	EASA,FAA,CAAC,ANAC										
672453	340-078-202-0	EASA,FAA,ANAC										
672453	649-791-260-0	EASA,FAA,CAAC,ANAC										
672775	1348M88G05	EASA,FAA,CAAC,ANAC	8	28	72-41-04	CFM56 MANIFOLD-FUEL SUPPLY/DRAIN	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
672775	1348M88G07	EASA,FAA,CAAC,ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST DRAIN		915.00	SR Technics Switzerland
672775	1348M88G08	EASA,FAA,CAAC,ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST SUPPLY		915.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672775	1444M50G11	EASA,FAA,CAAC,ANAC			72-41-04		Package D	002	REPAIR THE SILVER PLATE ON THE TUBE FITTING NUTS		445.00	SR Technics Switzerland
672775	1444M50G13	EASA,FAA,CAAC,ANAC			72-41-04		Package E		REPLACE DEFECTIVE FUEL NOZZLE SHROUD		330.00	SR Technics Switzerland
672775	1444M51G17	EASA,FAA,CAAC,ANAC			72-41-04		Package SB01	73-0005	INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS		3180.00	SR Technics Switzerland
672775	1444M51G18	EASA,FAA,CAAC,ANAC			72-41-04		Package SB01	73-0077	FIELD REOWRK SAC FUEL MANIFOLDS TO ELIMINATE DEAD-END TONE		3180.00	SR Technics Switzerland
672775	1605M65G01	EASA,FAA,CAAC,ANAC										
672775	1621M82G01	EASA,FAA,CAAC,ANAC										
672775	1813M58G02	EASA,FAA,CAAC,ANAC										
672775	1867M63G01	EASA,FAA,CAAC,ANAC										
672775	1867M64G01	EASA,FAA,CAAC,ANAC										
672775	1867M68G01	EASA,FAA,CAAC,ANAC										
672775	1870M11G01	EASA,FAA,CAAC,ANAC										
672775	1871M74G01	EASA,FAA,CAAC,ANAC										
672775	1882M60G03	EASA,FAA,CAAC,ANAC										
672775	1882M60G04	EASA,FAA,CAAC,ANAC										
672775	1882M61G03	EASA,FAA,CAAC,ANAC										
672775	1882M61G04	EASA,FAA,CAAC,ANAC										
672775	1882M62G03	EASA,FAA,CAAC,ANAC										
672775	1882M62G04	EASA,FAA,CAAC,ANAC										
672775	1882M63G03	EASA,FAA,CAAC,ANAC										
672775	1882M63G04	EASA,FAA,CAAC,ANAC										
672775	1892M95G01	EASA,FAA,CAAC,ANAC										
672775	1895M12G01	EASA,FAA,CAAC,ANAC										
672775	1895M12G02	EASA,FAA,CAAC,ANAC										
672775	1895M19G01	EASA,FAA,CAAC,ANAC										
672775	1895M44G01	EASA,FAA,CAAC,ANAC										
672775	1895M45G01	EASA,FAA,CAAC,ANAC										
672775	1895M80G06	EASA,FAA,CAAC,ANAC										
672775	1895M80G08	EASA,FAA,CAAC,ANAC										
672775	1895M81G06	EASA,FAA,CAAC,ANAC										
672775	1895M81G11	EASA,FAA,CAAC,ANAC										
672775	1895M82G06	EASA,FAA,CAAC,ANAC										
672775	1895M82G08	EASA,FAA,CAAC,ANAC										
672775	1895M83G06	EASA,FAA,CAAC,ANAC										
672775	1895M83G13	EASA,FAA,CAAC,ANAC										
672775	1895M83G14	EASA,FAA,CAAC,ANAC										
672775	1958M81G01	EASA,FAA,CAAC,ANAC										
672775	1958M82G01	EASA,FAA,CAAC,ANAC										
672775	1958M86G01	EASA,FAA,CAAC,ANAC										
672775	1971M10G01	EASA,FAA,CAAC,ANAC										
672775	1971M17G01	EASA,FAA,CAAC,ANAC										
672775	1971M18G01	EASA,FAA,CAAC,ANAC										
672775	1971M63G01	EASA,FAA,CAAC,ANAC										
672775	1971M63G02	EASA,FAA,CAAC,ANAC										
672775	1971M95G01	EASA,FAA,CAAC,ANAC										
672775	1971M96G01	EASA,FAA,CAAC,ANAC										
672775	2046M62G01	EASA,FAA,CAAC,ANAC										
672775	2046M63G01	EASA,FAA,CAAC,ANAC										
672775	2283M70G01	EASA,FAA,CAAC,ANAC										
672775	2283M73G01	EASA,FAA,CAAC,ANAC										
672775	9393M59G05	EASA,FAA,CAAC,ANAC										
672775	9393M60G07	EASA,FAA,CAAC,ANAC										

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672775	9394M34G01	EASA,FAA,CAAC,ANAC										
672783	1871M49G03	EASA,FAA,CAAC,ANAC	5	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		170.00	SR Technics Switzerland
672783	1895M34G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		70.00	SR Technics Switzerland
672783	1895M35G01	EASA,FAA,CAAC,ANAC			72-09-04		Package C	INSP/CHK	REPLACE INSERT	SPM 70-42-XY	180.00	SR Technics Switzerland
672783	2174M29G01	EASA,FAA,ANAC										
672783	2175M14G01	EASA,FAA,CAAC,ANAC										
672788	1443M74G02	EASA,FAA,CAAC,ANAC	2	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		140.00	SR Technics Switzerland
672788	1443M77G02	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		185.00	SR Technics Switzerland
672788	1645M33G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERTS		185.00	SR Technics Switzerland
672788	1645M33G03	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS OR NUTS		185.00	SR Technics Switzerland
672788	1867M33G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		185.00	SR Technics Switzerland
672788	1867M33G02	EASA,FAA,CAAC,ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		80.00	SR Technics Switzerland
672788	1867M35G01	EASA,FAA,CAAC,ANAC			72-09-04		Package SB01	75-0038	INTRODUCTION OF PS3 SIGNAL TUBE BRACKET		90.00	SR Technics Switzerland
672788	1867M35G02	EASA,FAA,CAAC,ANAC										
672788	1867M45G01	EASA,FAA,CAAC,ANAC										
672788	1867M62G01	EASA,FAA,CAAC,ANAC										
672788	1868M21G01	EASA,FAA,CAAC,ANAC										
672788	1868M22G01	EASA,FAA,CAAC,ANAC										
672788	1869M28G01	EASA,FAA,CAAC,ANAC										
672788	1869M29G01	EASA,FAA,CAAC,ANAC										
672788	1870M37G01	EASA,FAA,CAAC,ANAC										
672788	1871M23G01	EASA,FAA,CAAC,ANAC										
672788	1871M80G01	EASA,FAA,CAAC,ANAC										
672788	1892M72G01	EASA,FAA,CAAC,ANAC										
672788	1892M81G01	EASA,FAA,CAAC,ANAC										
672788	1892M85G01	EASA,FAA,CAAC,ANAC										
672788	1892M86G01	EASA,FAA,CAAC,ANAC										
672788	1892M94G01	EASA,FAA,CAAC,ANAC										
672788	1894M19G01	EASA,FAA,CAAC,ANAC										
672788	1894M50G01	EASA,FAA,CAAC,ANAC										
672788	1894M76G01	EASA,FAA,CAAC,ANAC										
672788	1895M20G01	EASA,FAA,CAAC,ANAC										
672788	1895M23G01	EASA,FAA,CAAC,ANAC										
672788	1895M36G01	EASA,FAA,CAAC,ANAC										
672788	1895M37G01	EASA,FAA,CAAC,ANAC										
672788	1896M66G01	EASA,FAA,CAAC,ANAC										
672788	1896M70G01	EASA,FAA,CAAC,ANAC										
672788	1898M61G01	EASA,FAA,CAAC,ANAC										
672788	1958M54G01	EASA,FAA,CAAC,ANAC										
672788	1969M24G01	EASA,FAA,CAAC,ANAC										
672788	2174M30G01	EASA,FAA,CAAC,ANAC										
672788	2174M36G01	EASA,FAA,CAAC,ANAC										
672788	2174M53G01	EASA,FAA,ANAC										
672788	2175M38G01	EASA,FAA,CAAC,ANAC										
672788	2175M84G01	EASA,FAA,CAAC,ANAC										
672788	336-044-801-0	EASA,FAA,CAAC,ANAC										
672788	338-039-002-0	EASA,FAA,CAAC,ANAC										
672788	338-057-803-0	EASA,FAA,CAAC,ANAC										
672788	340-180-401-0	EASA,FAA,CAAC,ANAC										
672788	340-180-601-0	EASA,FAA,CAAC,ANAC										
672793	1869M44G01	EASA,FAA,CAAC,ANAC	3	21	72-09-04	SPM 70-42-XX	Package A	CLN/INSP	CLEANING & INSPECTION		95.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672793	1898M82G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE HELOCOIL INSERT		75.00	SR Technics Switzerland
672793	1958M37G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	75.00	SR Technics Switzerland
672793	2046M76G01	EASA,FAA,CAAC,ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		75.00	SR Technics Switzerland
672793	338-056-901-0	EASA,FAA,CAAC,ANAC										
672793	338-122-301-0	EASA,FAA,CAAC,ANAC										
672793	340-097-202-0	EASA,FAA,CAAC,ANAC										
672801	1871M51G01	EASA,FAA,CAAC,ANAC	5	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		65.00	SR Technics Switzerland
672801	1894M72P001A	EASA,FAA,CAAC,ANAC										
672818	338-082-101-0	EASA,FAA,CAAC,ANAC	6	21	72-23-18	PW4 TUBES (REPAIR MEDIUM)	Package A	00	CLEANING & INSPECTION		615.00	SR Technics Switzerland
672818	338-082-201-0	EASA,FAA,CAAC,ANAC										
672818	340-026-402-0	EASA,FAA,CAAC,ANAC										
672818	340-030-601-0	EASA,FAA,CAAC,ANAC										
672818	340-032-102-0	EASA,FAA,CAAC,ANAC										
672818	340-034-402-0	EASA,FAA,CAAC,ANAC										
672819	1898M65G01	EASA,FAA,CAAC,ANAC	5	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION		390.00	SR Technics Switzerland
672819	340-026-602-0	EASA,FAA,CAAC,ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		950.00	SR Technics Switzerland
672819	340-034-202-0	EASA,FAA,CAAC,ANAC										
672820	337-036-917-0	EASA,FAA,CAAC,ANAC	6	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION		390.00	SR Technics Switzerland
672820	340-023-202-0	EASA,FAA,CAAC,ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		950.00	SR Technics Switzerland
672820	649-430-021-0	EASA,FAA,CAAC,ANAC										
672820	649-432-111-0	EASA,FAA,CAAC,ANAC										
672820	649-434-051-0	EASA,FAA,CAAC,ANAC										
672822	340-026-502-0	EASA,FAA,CAAC,ANAC	6	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSES	Package A	CLN/INSP	CLEANING & INSPECTION		285.00	SR Technics Switzerland
672822	340-200-002-0	EASA,FAA,CAAC,ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		600.00	SR Technics Switzerland
672822	J1238P04	EASA,FAA,CAAC,ANAC										
668262	FAN FRAME ASSEMBLY		13	35		CFM56-7B FAN FRAME MINOR MODULE	Package A	CLN/INSP	CLEANING & INSPECTION	-	1140.00	SR Technics Switzerland
668262							Package AA	024	CCA FORWARD FLANGE REPAIR BY REINFORCEMENT PLATE	72-23-02	4920.00	SR Technics Switzerland
668262							Package AB	035	CCA ATTACHMENT HOLES FLANGE A1 RECONDITIONING (MACHINE)	72-23-02	22430.00	SR Technics Switzerland
668262							Package AC	035	CCA ATTACHMENT HOLES FLANGE A1 RECONDITIONING (MOBILE MILL)	72-23-02	22430.00	SR Technics Switzerland
668262							Package AD	018	REAM IDG ATTACHEMENT HOLES BUSHING REPLACEMENT	-	1285.00	SR Technics Switzerland
668262							Package AE	043	FFS REMOVAL OF CORROSION IN THE RIVETED SELF LOCKING NUTS HOLES	72-23-31	3145.00	SR Technics Switzerland
668262							Package AF	044	FFS REMOVAL OF CORROSION IN ACOUSTIC PANEL BOLT HOLES BY BUSHING	72-23-31	5210.00	SR Technics Switzerland
668262							Package AG	045	FFS BLEND REPAIRS OF WEARS	72-23-31	490.00	SR Technics Switzerland
668262							Package AH	046	FFS RECONDITIONING OF THE ATTACHMENT HOLES ON THE FLANG B6	72-23-31	5525.00	SR Technics Switzerland
668262							Package AI	047	FFS COLD REFORMING REPAIR AFT LIP	72-23-31	2765.00	SR Technics Switzerland
668262							Package AJ	048	FFS BLEND REPAIR OF AFT LIP	72-23-31	1080.00	SR Technics Switzerland
668262							Package AK	049	FFS REMOVAL OF CORROSION UNDER ANCHOR NUTS	72-23-31	1225.00	SR Technics Switzerland
668262							Package AL	051	FFS V-GROOVE VARNISH AND LUBRICANT APPLICATION	72-23-31	820.00	SR Technics Switzerland
668262							Package AM	037	CCA BLEND FLANGES A1,B1,B2,B3,B4,B5&B6	72-23-02	810.00	SR Technics Switzerland
668262							Package AM	15-94732	CCA BLEND FLANGES A1,B1,B2,B3,B4,B5&B6	72-23-02	810.00	SR Technics Switzerland
668262							Package AN	042	CCA BLEND A1 FLANGE AREA G	72-23-02	615.00	SR Technics Switzerland
668262							Package AN	15-94733	CCA BLEND A1 FLANGE AREA G	72-23-02	615.00	SR Technics Switzerland
668262							Package AO	016	LOCAL APPLICATION OF ANTI EROSION PAINT	72-23-02	5025.00	SR Technics Switzerland
668262							Package AP	052	REMOVE CORROSION IN STRUT FAIRING ATTACHMENT HOLES	-	3145.00	SR Technics Switzerland
668262							Package AQ	006	FCC HOLES FLANGE A1 BUSHING	AMM 72-24-01	1200.00	SR Technics Switzerland
668262							Package AR	007	FCC HOLES FLANGE A1 DRILLING	AMM 72-24-01	850.00	SR Technics Switzerland
668262							Package AT	053	REPL. WEAR STRIPS IN V-GROOVE	72-23-31	4,720.00	SR Technics Switzerland
668262							Package B	INSP-001	CCA CLEANING CASE	72-00-23	1865.00	SR Technics Switzerland
668262							Package B	INSP-001	CCA REMOVAL HIGH METAL	72-23-02	1865.00	SR Technics Switzerland
668262							Package D	INSP-001	VBV ACTUATING RING BLEND AND FPI	72-23-16	430.00	SR Technics Switzerland
668262							Package D	INSP-001	VBV ACTUATING RING GENERAL WORK	72-23-16	430.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2024

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
668262							Package D	INSP-001	VBV ACTUATING RING TOUCH UP	72-23-16	430.00	SR Technics Switzerland
668262							Package E	INSP-001	SPLITTER FAIRING GENERAL WORK	72-23-33	1065.00	SR Technics Switzerland
668262							Package E	INSP-001	SPLITTER FAIRING TOUCH UP	72-23-33	1065.00	SR Technics Switzerland
668262							Package F	INSP-001	V-GROOVE DRY FILM LUBRICANTS	72-00-23	365.00	SR Technics Switzerland
668262							Package F	INSP-001	V-GROOVE SEGMENTS GENERAL WORK	72-23-23	365.00	SR Technics Switzerland
668262							Package F	INSP-001	V-GROOVE SEGMENTS TOUCH UP	72-23-32	365.00	SR Technics Switzerland
668262							Package G	001	FFS RIVETED PARTS PS13 BOSS	72-23-31	2520.00	SR Technics Switzerland
668262							Package H	002	OGVS REPLACEMENT NUTS	72-23-04	810.00	SR Technics Switzerland
668262							Package I	002	SPOT TOUCH UP MISSING ANODIZING	72-23-31	695.00	SR Technics Switzerland
668262							Package J	002	OGV RECONDITIONING OF PROTECTIVE COATING	72-23-03	540.00	SR Technics Switzerland
668262							Package K	003	FFS REPLACEMENT OF THE KEY-LOCKED INSERTS	72-23-31	1385.00	SR Technics Switzerland
668262							Package L	003	CCA REPLACEMENT OF HI-LITE BOLTS AND NUTS	72-23-02	1515.00	SR Technics Switzerland
668262							Package M	003	REPLACEMENT OF KEY LOCKED INSERTS	72-23-01	885.00	SR Technics Switzerland
668262							Package N	007	FFS DAMAGE ON ENGINE HANDLING BOSSES	72-23-31	865.00	SR Technics Switzerland
668262							Package O	008	CCA REPLACEMENT OF RIVETED NUTS, GANG CHANNEL NUTS	-	1515.00	SR Technics Switzerland
668262							Package P	008	OGVS CORROSION REMOVAL IN ATTACHMENT HOLES	72-23-04	1950.00	SR Technics Switzerland
668262							Package QI	008	REPAIR OF IDG COOLER INNER SKIN AREAS	72-23-31	1130.00	SR Technics Switzerland
668262							Package R	010	CCA REPLACEMENT OF THE AGB RESILIENT MOUNT DAMPER ASSEMBLIES	72-23-02	1385.00	SR Technics Switzerland
668262							Package S	010	FF BLENDING OF FAN DUCT PANEL LUGS	72-23-01	1055.00	SR Technics Switzerland
668262							Package SB00	72-0440	FFS IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND UN WING OR IN SHOP INSPECTION	-	820.00	SR Technics Switzerland
668262							Package SB01	72-0512	INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLER PANEL IN TWO PARTS AND REWORK	OF THE PREVIOUS CONFIGURATION	2520.00	SR Technics Switzerland
668262							Package SB02	72-0531	FFS NDT INSPECTION IDG AIR-OIL COOLER	-	2520.00	SR Technics Switzerland
668262							Package SB03	72-0924	FFS INTRODUCTION OF NEW BRACKET ASSEMBLIES	-	465.00	SR Technics Switzerland
668262							Package SB04	72-0975	WEAR STRIP REWORK OF THE FAN FRAME SHROUD	-	6845.00	SR Technics Switzerland
668262							Package SB05	72-0996	FFS APPLICATION OF PTFE LUBRICANT VARNISH ON V-GROOVE OUTER RING	-	755.00	SR Technics Switzerland
668262							Package SB06	72-0553	FFA CASE LOCAL REPAIR ANTI EROSION PAINT	-	5395.00	SR Technics Switzerland
668262							Package SB07	72-0580	REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION	-	9410.00	SR Technics Switzerland
668262							Package SB11	72-0744	FFS INTRODUCTION OF THREE BRACKETS ASSY WITH A NEW DESIGN	-	465.00	SR Technics Switzerland
668262							Package SB14	72-0780	REWORK IN FIELD OF CONTAINMENT CASE B1 FLANGE AT HOLE 84 AND 85	REQUIRES REP-024	8,160.00	SR Technics Switzerland
668262							Package SB15	72-0495	REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINIUM FINISH FR	-	7,780.00	SR Technics Switzerland
668262							Package SB18	M-20-172-00618	ENGINE IDENTIFICATION PLATE RTV106 SEALANT APPLICATION	-	160.00	SR Technics Switzerland
668262							Package T	011	CCA FULL OR PARTIAL REPLACEMENT OF ABRADABLE LINER	72-23-02	16,295.00	SR Technics Switzerland
668262							Package U	013	OGVS CASE B BUSHING REPLACEMENT	72-23-04	595.00	SR Technics Switzerland
668262							Package V	015	CCA REPLACEMENT OF HANDLING BRACKETS	72-23-02	2,515.00	SR Technics Switzerland
668262							Package W	019	CCA REPAIR OF THE ATTACHMENT HOLES ON B1, B4 AND/OR B5 FLANGES	72-23-02	3,570.00	SR Technics Switzerland
668262							Package X	021	CCA SPOT TOUCH UP SULFRIC ANODIZING	72-23-02	720.00	SR Technics Switzerland
668262							Package Y	022	CCA REMOVAL OF CORROSION IN RIV. SELF LOCKING NUTS HOLES	72-23-02	2,945.00	SR Technics Switzerland
668262							Package Z	023	CCA REMOVAL OF CORROSION OGV ATTACHMENT HOLES	72-23-02	4,525.00	SR Technics Switzerland
673762	REPLACEMENT OF HELICOIL ON ENGINE/MODULE		2	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package B	-	REPLACE INSERTS ENGINE	-	280.00	SR Technics Switzerland
673762					72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package C	-	REPLACE INSERTS MODULE	-	280.00	SR Technics Switzerland
673762					72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package D	-	REPLACE INSERTS TEST CELL	-	310.00	SR Technics Switzerland
673762					72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package E	-	REPLACE INSERTS QTL	-	280.00	SR Technics Switzerland
140213	LPT MAJOR MODUL		24	21	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION		385.00	
140213					72-00-03		Package AE	051	REPLACEMENT OF BROKEN STUDS OF 149.5 EG1 SENSOR FIXATION ASSEMBLY PLATE	-	18,730.00	
140213					72-00-03		Package B	001	REPLACEMENT OF RIVETED PARTS ON LPT	-	670.00	
140213					72-00-03		Package C	002	TEMPORARY REPLACEMENT OF BROKEN STUD ON 149.5 EG1 SENSOR FIXATION ASSEMBLY PLATE	-	1,155.00	
140213					72-00-03		Package D	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR	-	465.00	
140213					72-00-03		Package F	001	STUD REPLACEMENT	72-00-03	1,250.00	
140213					72-00-03		Package K	010	RECONDITIONING OF THE LPT SHAFT PAINT AT MAJOR MODULE 3	-	305.00	
140213					72-00-03		Package O	014	BLENDING ANTI-ROTATION-LUG	-	480.00	
140213					72-00-03		Package P	-	STORAGE 002 PRESERVATION 30 TO 365 D	-	625.00	

Capabilities and Fixed Prices Catalogue 2024 for

CFM56-7B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply

valid until December 31, 2024



Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140213					72-00-03		Package SB01	72-0477	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD	-	990.00	
140213					72-00-03		Package SB02	72-0423	REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR RETAINING PLATE	-	1,270.00	
140213					72-00-03		Package SB03	72-0527	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL	-	465.00	
140213					72-00-03		Package SB04	72-0552	REIDENTIFICATION OF LPT CASE IN FIELD	-	465.00	
140213					72-00-03		Package SB05	EASA-2014-0130	TIME LIMITS INSPECTIONS	-	465.00	
9017	HPT ROTOR ASSY		20	21	72-52-00	HIGH PRESSURE TURBINE ROTOR - ASSEMBLY	Package B	ASSEMBLY-002	HIGH SPEED GRINDING BLADE RADIUS K AND MACHINE NOTCHES ON HPT BLADES TIP		2900.00	SR Technics Switzerland
9017					72-52-00		Package C	SPEC.PROC-002	PREGROUNDING BLADE SET		3900.00	SR Technics Switzerland
139963	COMPRESSOR ROTOR ASSY		20	21	72-31-00	COMPRESSOR ROTOR - ASSEMBLY	Package B	ASSEMBLY-005	HIGH SPEED GRINDING OF BLADE TIP		9660.00	SR Technics Switzerland
139963					72-31-00		Package SB02	72-0583	IMPROVED STAGE 1 THROUGH STAGE 9 COMPRESSOR BLADES AND STAGE 4 VANE SECTROS		465.00	SR Technics Switzerland
139963					72-31-00		Package SB02	72-0688	IMPROVED STAGE 1 THROUGH STAGE 9 COMPRESSOR BLADES AND STAGE 4 VANE SECTROS		465.00	SR Technics Switzerland
648805	SCREW-NUT-SPACER-SETB		10	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - SCREWS, NUTS AND SPACERS REFURBISHMENT	Package B	LIGHT	REFURBISHMENT OF REMOVED SET OF PARTS	3 OR LESS OF FOLLOW. ENG. MODULS PARTIALLY/FULLY DISSASS. (21,22,23,41,42,51,52,53,54,55,56,61,62,63)	3625.00	SR Technics Switzerland
648805					72-09-04		Package C	MEDIUM	REFURBISHMENT OF REMOVED SET OF PARTS	TOP CASE REPAIR OR NOT LIGHT CONDITION	18200.00	SR Technics Switzerland
648805					72-09-04		Package D	HEAVY	REFURBISHMENT OF REMOVED SET OF PARTS	1.FLANGE (MOD.23 TO MOD.32) COMPLETE SPLITTED	36100.00	SR Technics Switzerland